

NYSDEC

Central Office

Division of Environmental Remediation

Site: Dunlop Tire and Rubber

Phase: Management

Site No.: 915018

Contractor PM:

NYSDEC PM: Bradley Demo

Construction Manager:

Project Engineers:

Remedial Contractor: GHD

Air Monitoring:

Health &amp; Safety:

**Weather Conditions**

General Description	Cloudy	am	pm
Temperature	60°F	am	pm
Wind Direction	NW	am	pm

**HEALTH & SAFETY:**

(\*If any box(s) below are checked "Yes", list the deviation under the "Items for Concern" section of this report).

Were there any changes to the Health & Safety Plan?	*Yes ( )	No ( )	NA (x)
Were there any exceedances at the perimeter action level reported on this date?	Air: *Yes ( )	No ( )	NA (x)
Were there any Noise /Vibration exceedances reported on this date?	Noise: *Yes ( )	No ( )	NA (x)
	Vibration: *Yes ( )	No ( )	NA (x)
Were there any breaches to the tent structure or silt fence reported/observed on this date?	*Yes ( )	No ( )	NA (x)
Were there any dust/odor issues reported or observed on this date?	*Yes ( )	No (x)	NA ( )

**WASTE HAULING :**

(\*If any box(s) below are checked "Yes", list the deviation under the "Items of Concern" section of this report).

Were there any vehicles which did not display proper D.O.T numbers and placards?	*Yes ( )	No ( )	NA (x)
Were there any vehicles which were not lined or tarped?	*Yes ( )	No ( )	NA (x)
Were there any vehicles which were not decontaminated prior to exiting the work site?	* Yes ( )	No ( )	NA (x)

**Materials Removed From Site: N/A****Disposal Facility:**

Total Loads: (on this date)

Total Loads: (to date)

Total Daily Weight: (est.)

Total Weight: (\*approx.)

**\*Actual (total weight) adjusted periodically based on weight tickets submitted by the disposal facilities.****Summary of Events:**

- NYSDEC onsite 8:45 am to 9:50 am to conduct annual inspection with Sumitomo.
- Site cover in good condition. 1 small area (2 x 2 feet) in area B will need to be repaired with topsoil. Christine Barton aware of import request requirement.
- All observed monitoring wells were locked and in good condition.

**VISITORS TO SITE:**

NAME	Representing	Entered Exclusion/CRZ Zone	
Chrstine Barton	Sumitomo Rubber	Yes (x)	No ()
		Yes ()	No ()
		Yes ()	No ()
		Yes ()	No ()

**PROJECT SCHEDULE:**

- 

**ISSUES PENDING:**

- 

**ITEMS OF CONCERN:**

-

Inspector: Bradley Demo

Signature: *Bradley W. Demo*

Date: 05/28/2025



Oil boom (precautionary measure) leading to settling pond between Areas A and B.





Site cover, Area A, looking NE.



Settling pond, looking SW.





Monitoring well, Area A.





Small patch of cover needing repair in Area B.





Asphalt cover conditions, Area B.





Area A cover facing SW.





Area A cover facing N.





MW-C5.





Area C cover facing E.