NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

		Class:	4 Nur	n ber: 915031
O&M Funding Source: State Superior	erfund 🛛	Federal Superfund	Municipal	Responsible Par
O&M Information: O&M Start: January,	, 2000 End	t:	Annual Cost: R	efer Site #915063
 ■ Groundwater Recovery/Treatment ■ Leach □ Air Sparging/Stripper System ■ Treatr 			 □ Tank Removal ■ Fence/Security □ Vapor Extraction/Treatment □ Potable Water Supply/System 	
Other: Other: Other: Other: Other: Other:	ction m	Discharge Permit	Departme	ent of Health Sampling
O&M Review Information: Reports: Annual Report Inspection: Quarterly Sampling: Semi-annual for groundwater p	oumping wells, an	d collection trench		
Other: Monthly sampling of pre-treatm	ent plant influent	/effluent per Town of T	onawanda discha	irae permit
Conclusions:	ere provident and office			
Remedy Effective? III Yes 🗆 No				
ROD Compliance? 🔳 Yes 🗆 No:				
Consent Order Compliance? 🔳 Yes	🗆 No:			
Other:				
Recommendations:		<u> </u>		
Repair minor erosion caused by burrowing Continue animal control to remove unwante		nals (muskrat, woodch	uck etc.)	
	Yes (per above)	Reclassify the	Site? M No	□ Yes → Class:
Comments: Parsons Engineering Science performing C Obrien & Gere performing semi-annual gro O&M activity at this site is tied to the Niaga	undwater samplin	ng		
Brion Ladenals		Reviewer:		