

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

*Entered 7/10/03 by [signature]*

<b>Site Name:</b> River Road		<b>Class:</b> 4	<b>Number:</b> 915031
<b>O&amp;M Funding Source:</b> <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party			
<b>O&amp;M Information:</b> June 1997		<b>End:</b> Continuing	<b>Annual Cost:</b> Not Available
<b>Interim Remedial Measures/Operable Units in O&amp;M Phase:</b>			
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil/Sediment Removal	<input type="checkbox"/> Tank Removal	
<input checked="" type="checkbox"/> Cap/Cover	<input type="checkbox"/> Containment Structure	<input checked="" type="checkbox"/> Fence/Security	
<input checked="" type="checkbox"/> Groundwater Recovery/Treatment	<input checked="" type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment	
<input type="checkbox"/> Air Sparging/Stripper System	<input checked="" type="checkbox"/> Treatment/Filtration Plant	<input type="checkbox"/> Potable Water Supply/System	
<input type="checkbox"/> Other:			
<b>Institutional Controls:</b> <input type="checkbox"/> Deed Restriction <input checked="" type="checkbox"/> Discharge Permit <input type="checkbox"/> DOH Sampling <input type="checkbox"/> Other:			
<b>O&amp;M Review Information:</b>			
<b>Reports:</b> 2002 Annual Report dated March 2003.			
<b>Site Inspection:</b> Quarterly by Parsons. Last DEC and Parsons inspection; 5/8/03			
<b>Monitoring Activity:</b> Semi-Annually for monitoring wells.			
<b>Other:</b> Monthly sampling of pre-treatment plant influent/effluent according to Town of Tonawanda discharge permit.			
<b>Conclusions:</b>			
<b>Remedy Effective?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown.			
<b>ROD Compliance?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Applicable.			
<b>Consent Order Compliance?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Applicable.			
<b>Other:</b> None.			
<b>Recommendations:</b>			
Continue OM&M activities by approved OM&M Plan.			
Repair ruts caused by USCG post 9/11/01.			
<b>ROD/Consent Order Modifications?</b> <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above) <b>Reclassify the Site?</b> <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class: 4			
<b>Comments:</b> Parsons Engineering Science is doing the O&M activity at the site. The treatment plant is effectively running as designed. The OM&M log is up to date. Fencing and gate integrity is good. O'Brien and Gere are performing the semi-annual groundwater sampling. The cap is in good condition. Erosion was not observed. Woodchuck burrows were not observed. O&M activity at this site is tied to the Niagara Mohawk Cherry Farm Site #915063. Town of Tonawanda Police make rounds on the site when the gate is open.			
<b>OM&amp;M R9 North Coordinator:</b> Brian P. Sadowski <i>Brian P. Sadowski 6/12/03</i>			
<b>Project Manager:</b> Michael J. Hinton <i>Michael J. Hinton</i> <b>Reviewer:</b> Daniel K. King <i>Daniel K. King</i>			
<b>Date:</b> June 13, 2003 <b>Date:</b> 6/13/03			
<b>Region or Bureau</b> 9		<b>Telephone</b> 716/851-7220	<b>Region or Bureau</b> 9 <b>Telephone</b> 716/851-7220