## NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

## Inactive Hazardous Waste Site Operations and Maintenance Review Report

JEW \_\_\_ file

<b>/</b>	<del></del>				Form Date 98.10.0
Site Name: Lancaster Sanitary Landfill		Class:	4	Number:	915068
O&M Funding Source:   State Supering	erfund	eral Superfund	☐ Municipal	□ Res	onsible Party
O&M Information: O&M Start: 1991	End:	2015	Annual Cost:	\$ 21,000	☐ Estimated
Interim Remedial Measures/Operable Units in O&M Phase:					
☐ Drum Removal	☐ Soil Removal		□ Tank Re	emoval	
	☐ Containment S		☐ Fence/S	Security	
☐ Groundwater Recovery/Treatment			☐ Vapor E		
		ation Plant/System	□ Potable	Water Sup	ply/System
tx Other: Landfill gas extraction and electrical limitational Controls: □ Deed Restrict		ischarge Permit	— Dene	rtment of H	ealth Sampling
Other: Part 360 permit - LFG Energy,		ecies de Latitif	и обра	idiletik Of 11	calul Saniping
O&M Review Information:				-	_
Reports: Quarterly groundwater monitoring	g reports submitted	to Department.			
Inspection: Site last inspected by Region 1				<del></del>	
Sampling: Most recent groundwater monit Other:	oring event comple	eted on August 17, 2	<u>000</u> .		
Conclusions:					
Remedy Effective? Ef Yes   No:					_
ROD Compliance?					
Consent Order Compliance?					
Other:					
	<u> </u>				
Recommendations: Continue routine mo	nitoring and inspec	ction of site.			
-	<u> </u>				-
<del></del>					
			<del>-</del> -		
	<del></del> _	<u> </u>			
·				<u> </u>	
			<u> </u>		
ROD/Consent Order Modifications?	Yes (per above)	Reclassify the	Site? S'No	☐ Yes	→ Class:
Comments: The landfill is closed and cap	ped. Routine mail	ntenance and monito	oring is conduc	ted by resp	oonsible parties.
A new state-of-the-art LFG to energy facilit	y has been constr	ucted, which include	s upgraded LF	G collectio	n and
condensate handling facilities. 12 replacement LFG extraction wells were will also installed. Access control gates are in					
place at the entrances from Gunville Road					t of upgrade.
A post-closure trust fund is in place to cover 25 years of post-closure operation and maintenance costs.					
			<u>:</u>		
Project Manager:	doub	Reviewer L	1 Hans		u la dro
Signature Cultura	Dete	Signature	7 May C	<u> </u>	Dete
	16/851-7220 elephone	Mark J. Hans P.E Name	. 9 Region or Bure		/851-7220 slephone

**FOIL** Releasable Non-Heleasable