

ecology and environment engineering, p.c.

BUFFALO CORPORATE CENTER 368 Pleasantview Drive, Lancaster, New York 14086 Tel: 716/684-8060, Fax: 716/684-0844

October 8, 2010

Mr. William Welling PE, Project Manager New York State Department of Environmental Conservation Division of Environmental Remediation 625 Broadway, 12th Floor Albany, New York 12233 - 7013

Re: Mr. C's Dry Cleaners Site, Contract # D004442.DC13, Site # 9-15-157 September 2010 Operations, Maintenance, and Monitoring Report

Dear Mr. Welling:

Ecology and Environment Engineering, P.C. (EEEPC) is pleased to provide the September 2010 Operations, Maintenance, and Monitoring (OM&M) Report for the Mr. C's Dry Cleaners Site, NYSDEC Site # 9-15-157, located in East Aurora, New York. Copies of weekly inspection reports prepared by EEEPC's subcontractor, Iyer Environmental Group, PLLC (IEG) are provided in Attachment A. Selected pages from the individual analytical data package prepared by Mitkem Laboratories, Inc. (MLI) on September 17, 2010 are provided as Attachment B. The full analytical report along with QA/QC information will be retained by EEEPC. Remedial treatment system utility costs for the Mr. C's and Agway sites are provided as Attachment C.

In review of the on-site treatment system operations, monitoring and maintenance for September 2010, EEEPC offers the following comments and highlights:

Operational Summary

Mr. C's Site - Remedial Operations Information

- Checklists for weekly system inspections from IEG are provided as <u>Attachment A</u> for 9/7, 9/13, 9/21, and 9/28.
- Based on the weekly inspection results performed by IEG, the remedial treatment system had a 100.00% operational up-time (<u>Table 1</u>) for September 2010 and the treatment of contaminated groundwater totaling of 297,308 gallons (<u>Table 2</u>).
- The analytical samples for the monthly compliance were taken on September 13, 2010. The sampling results were received by EEEPC on September 17, 2010.
- Excerpts from the Analytical Data package for the August 10, 2010 sampling event are presented in <u>Attachment B</u>.
- A review of the analytical data revealed the influent concentration to be 913.9 ug/L or 913.9 ppb, and 1.3 ug/L or 1.3 ppb of treated effluent. The summary of influent and effluent contaminant concentrations for the September 13, 2010 sampling event is presented in Table 4.

Mr. William Welling PE, Project Manager October 8, 2010 Page 2 of 3

- Overall cleanup efficiency for the contaminants of concern at the site during the reporting period 9/7/10 to 9/28/10 was 99.86%. The air stripper unit on the Mr. C's property is in compliance and MLI continues to provide analytical data to sub-ppb accuracy, supporting the accurate determination of effluent contaminant levels. The summary of Effluent Discharge Criteria & Analytical Compliance Results for September 2010 is presented in Table 3.
- The Mr. C's treatment system based on the total monthly flows has effectively removed 2.26 lbs of targeted contaminants from the groundwater below the site in the month of September 2010. The calculations and data for the month and entire year of 2010 are presented in <u>Table 5</u>.

The air stripper unit on Mr. C's property is in compliance and analytical data is provided to sub-ppb accuracy, supporting the accurate determination of effluent contaminant levels. IEG took corrective action to teardown and clean the individual trays of the air stripper unit on October 6th and 7th, 2010. IEG plans to examine the effluent pipe for buildup that will also be cleaned if present. After cleaning and repair another sampling event is planned for October.

Agway Site Remedial Information

No current operational issues.

Subslab Depressurization Systems (SSDS) – First Presbyterian Church and 27 Whaley Ave. sites

No current operational issues.

Mr. C's and Agway Energy Usage Information

A copy of the site utility costs from the Mr. C's and Agway remedial operations for September 2010 and year to date are provided as <u>Attachment C.</u>

If you have questions regarding the September 2010 OM&M report summary, please do not hesitate to contact me at 716-684-8060.

Very Truly Yours,

Ecology and Environment Engineering, P. C.

Michael G. Steffan Project Manager

cc: D. Szymanski, Region 9, NYSDEC - Buffalo w/ attachments

D. Iyer, IEG – w/attachments CTF- 002700.DC13.02.01.01

Michael B. Steffan

Table 1 Mr. C's Dry Cleaners Site Remediation Site #9-15-157 System Operational Time

Month	Reporting Hours	Operational Up- time
(Up-time from inception to 1/5/10)	61,992.50	95.99%
January 5, 2010 - February 1, 2010	648	100.00%
February 1, 2010 - March 2, 2010	696	100.00%
March 2, 2010 - March 30, 2010	672	100.00%
March 30, 2010 - April 27, 2010	672	100.00%
April 27, 2010 - June 2, 2010	816	94.44%
June 2, 2010 - July 6, 2010	816	100.00%
July 6, 2010 - August 4, 2010	696	100.00%
August 4, 2010 - September 7, 2010	816	100.00%
September 7, 2010 - September 28, 2010	504	100.00%
October 2010		,
November 2010		
December 2010		
Total Hours from System Startup '2/02'	68,328.50	

Average Operational Up-time from startup =

Average Operational Up-time for 2010 =

96.28% 99.25%

NOTES:

- 1. Up-time based as percentage of total reporting hours
- 2. Treatment system operated by the Tyree Organization Ltd. from 9/02-9/03.
- 3. Treatment system operated by O&M Enterprises Inc. from 10/03 7/07.
- 4. Treatment system operated by Iyer Environmental Group from 7/07 to present

Mr. C's Dry Cleaners Site Remediation **Monthly Process Water Volumes** Site #9-15-157 Table 2

112,892,647	Hotal Gallons Treated To Date:	Tiotal(Gallo
3,883,490	Total Gallons Treated in 2010	Total (
		December 2010 ³
		November 2010 ³
		October 2010 ³
297,308	9/7/10 - 9/28/10	September 2010 ³
503,999	8/4/10 - 9/7/10	August 2010 ³
450,503	7/6/10 - 8/4/10	July 2010 ³
268,627	6/2/10 - 7/6/10	June 2010 ³
322,174	4/27/10 - 6/2/2010	May 2010 ³
228,188	3/30/10 - 4/27/10	April 2010 ³
491,152	3/2/10 - 3/30/10	March 2010 ³
672,687	2/1/10 - 3/2/10	February 2010 ³
648,852	1/5/10 - 2/1/10	January 2010 ³
109,009,157	9/5/02 - 1/5/10	Total - Inception to December 2009
Gallons - S	Actual Period	Month,

NOTES:

- System operated by Tyree Organization Ltd. From 9/02 9/03
 System operated by O&M Enterprises from 10/03 7/07
 System operated by IEG PLLC from 7/07 present

Effluent Discharge Criteria & Analytical Compliance Results Mr. C's Dry Cleaners Site Remediation Site #9-15-157

Table 3

NAS CONTRACTOR		- 01str	Cyanide Free Constant Landing
490	mg/l	N/A	Hardness
世紀では、 一般の では、 では、 では、 では、 では、 では、 では、 では、	家是是我们g/DXX来来	20	Total Suspended/Solids
はいません。 はいない人。 ない人。 ないないない。 ないないない。 ないないない。 ないないない。 ないないない。 ないないない。 ないないない。 ないないないない。 ないないないない。 ないないないないない。 ないないないないないない。 ないないないないないないない。 ないないないないないないないない。 ないないないないないないないないないないない。 ないないないないないないないないないないないないないないないない。 ないないないないないないないないないないないないないないないないないないない	mg/Ls - s.J. mg/Ls	850	Hotal Dissolved Solids
「「「「」」「「」」「「」」「NAW」「NAW」「NAW」「NAW」「NAW」「	λίους	250	Zinc Parket Service Table 17
TO THE PROPERTY OF THE PARTY OF		数据"是"28 是第5条	Vanadium: Vanadium
NASS TELESTICATION OF THE PROPERTY OF THE PROP	a μg/L	(100 mg/4)	Silverin
TO SELECTION OF THE SECOND		2,000 -	Mangariesca
中国 THE TRANSPORT TO THE PROPERTY OF THE PROPE	事等等 μg/Bディーマラ		Lead To Make Control of the American
La	ing/E-α. γε	## ## ## ## ## ## ## ## ## ## ## ## ##	Copper
これに という こうしゅう アンスター・アー・アー・アー・アー・アー・アー・アー・アー・アー・アー・アー・アー・アー	ho dL	第一条 1000 25 15 19	Alluminum
NA ²	$\mu_{\mu} = \mu_{\mu} \mu_{\mu} \mu_{\mu}$	600	Iron, tofal
ND(<1.0)	.l/gu	NA	Total Xylenes
NA NA	µg/L	10	m, p-Xylene ³
NA	1/gu	J.S.	o-Xylene ³
ND(<1.0)	ug/L	NA	Methyl-t-Butyl Ether (MTBE)
ND(<1.0)	Т/Вт/	5	Toluene
ND(<1.0)	Т/Вт	10	1,1,1 Trichloroethane
ND(<1.0)	μg/L	10	Methylene Chloride
ND(<1.0)	T/Bri	5	Ethylbenzene
ND(<1.0)	T/Bri		Benzene
ND(<1.0)	μg/L	10	Vinyl Chloride
1,3	π8/L	10	Tetrachloroethene
ND(<1.0)	J/βπ	10	Trichloroethene
ND(<1.0)	J/gμ	01	cis-1,2-dichloroethene
ND(<1.0)	μg/L	10	1,2 Dichloroethane
ND(<1.0)	μg/L	01	1,1 Dichloroethene
8.10	standard units	0.0 - 0.0	pH_
14,157.52	gpd		Flow
September 2010 Efficient Analytical Values Compliance	Units	Daily Maximum	Parameter/Analyte

NOTES:

- 2. Analytical report did not differentiate between o-Xylene and m, p-Xylene. Total Xylene value reported is given in each line. 1. "Daily Maximum" excerpted from Attachment E of Addendum 1 to the Construction Contract Documents dated October 2000.
- Shaded cells indicate that analytical value exceeds the "Daily Maximum"
- 4. "ND" indicates that the compound was not detected and lists the practical quantitation limit in parentheses
- "NA" indicates that analyses were not performed and data is unavailable.
- days (504 actual operating hours). 6. Average flows based on effluent readings taken September 7, 2010 through September 28, 2010. Total gallons: 297,308 divided by 21 operating
- 7. "J" indicates an estimated value below the detection limit.
- 8. "B" indicates analyte found in the associated blank
- 9. Removed from the required analysis list by NYSDEC Region 9 in February 2005.

Indicates non-compliance with the NYSDEC effluent discharge requirements indicates Not Reported by Lab

Mr. C's Dry Cleaners Site Remediation
NYSDEC Site #9-15-157
September 2010 VOC Analytical Summary

NA NA		1.30		913.9	September 2010 TOTALs (in ug/L) =
1.1.4	U	ND (<1.0)	U	ND (<10.0)	Total Xylenes
AN	U	ND (<1.0)	U	ND (<10.0)	Methyl acetate
NA	U	ND (<1.0)	U	ND (<10.0)	Methylcyclohexane
NA	U	ND (<1.0)	U	ND (<10.0)	trans-1,2-dichloroethene
NA	U	ND (<1.0)	U	ND (<10.0)	Cyclohexane
NA	U	ND (<1.0)	U	ND (<10.0)	1,1,2 Trichloro-1,2,2-trifluororethane
NA	U	ND (<1.0)	U	ND (<10.0)	Carbon Disulfide
100.00%	Ü	ND (<1.0)		45.0	Trichloroethene
NA	U	ND (<1.0)	U	ND (<10.0)	Toluene
99.85%		1.3		840.0	Tetrachloroethene
100.00%	U	ND (<1.0)	J	8.9	Methyl tert-butyl ether (MTBE)
AN	U	ND (<1.0)	U	ND (<10.0)	Methylene chloride
100.00%	U	ND (<1.0)	-	20.0	cis-1, 2-Dichloroethene
. NA	U	ND (<5.0)	U	ND (<50.0)	2-Butanone
AN	u _	ND (<1.0)	U	ND (<10.0)	Benzene
AN	n	ND (<5.0)	U	ND (<50.0)	Acetone
(%)	(ug/L)	(ug	[₂)	(ug/L)	
on* Cleanup Efficiency**	ncentration*	Effluent Concen	entration*	Influent Concentration*	Compound
Sampling Results		Based on the 9/13/10 Effluent	Based on ti		

Notes

- 1. "NA" = Not applicable
- 2. "ND" or "U" = Compound analyzed, but was not detected. Detection limit in parentheses
- 3. "J" indicates an estimated value below the practical quantitation limit but above the method detection limit.
- 4. Non-detect values are assumed to be equal to zero for calculation of monthly average concentrations.
- 5. "D" = Compounds identified in analysis required secondary dilution factoring.
- 6. "B" indicates analyte found in the associated blank.
- * (<50) Detection Limit
- ** Contaminants of Concern only

Table 5 Mr. C's Dry Cleaners Site Remediation Site #9-15-157

Monthly VOCs Removed From Groundwater

Month	Actual Period	Influent VOCs (μg/L)	Effluent VOCs (μg/L)	VOCs Removed (lbs.)
Total pounds o	of VOCs removed from			######################################
January 2010	1/5/2010 - 2/1/2010	1420	0.00	7.69
February 2010	2/1/2010 - 3/2/2010	992	3.90	5.55
March 2010	3/2/2010 - 3/30/2010	1098	26.80	4.39
April 2010	3/30/2010 - 4/27/2010	1547	7.20	2.93
May 2010	4/27/2010 - 6/2/2010	434	0.00	1.17
June 2010	6/2/2010 - 7/6/2010	1530	0.73	3.43
July 2010	7/6/2010 - 8/4/2010	865	3.10	3.24
August 2010	8/4/2010 - 9/7/2010	858	129.90	3.06
September 2010	9/7/2010 - 9/28/2010	914	1.30	2.26
October 2010				
November 2010				
December 2010		1		The lander content plants of the first of the section of the secti

Total pounds of VOCs removed from inception to September 2010 =

1,469,02 33,72

Total pounds of VOCs removed in 2010 =

HISTORICAL NOTES:

- 1. Calculations are based on monthly water samples and assumes samples are representative of the entire reporting period.
- 2. Calculations assume that non-detect values = 0 ug/L.
- 3. Total VOCs summations include estimated "J" values.
- 4. Calculations are based on effluent totalizer readings.
- 5. "Influent VOCs" and "Effluent VOCs" values given above is the summation of values for individual compounds given in monthly analytical reports.
- 6. No samples were collected in September 2003. August 2003 values are used.
- 7. Treatment system operated by Tyree Organization, Ltd. from 9/02 to 9/03.
- 8. Treatment system operated by O&M Enterprises from 10/03 to 7/07.
- 9. Treatment system operated by IEG from 7/07 to present.

CONVERSIONS:

1 pound = 453.5924 grams

1 gallon = 3.785 liters

Based on the Analytical Results from Each Month:

Pounds of VOCs removed calculated by the following formula:

 $(VOCs_{\it Influent} - VOCs_{\it Effluent})(ug/L) \cdot (1g/10^{\,6}\,ug) \cdot (1\,\,lb/453.5924\,g) \cdot (Monthly\,process\,water)(gal) \cdot (3.785\,\,L/gallon)$

Attachment A IEG Weekly Inspection Reports September 2010

Including:

9/7/10

9/13/10

9/21/10

9/28/10

NYSDEC Site #9-15-157

OM&M: SITE INSPECTION FORM

DATE: 7-Sep-10 ACTIVITIES:	Site Inspection
INSPECTION PERSONNEL: R. Allen, D. lyer	OTHER PERSONNEL:
WEATHER CONDITIONS: Sunny, hot	OUTSIDE TEMPERATURE (° F): 85
ARE WELL PUMPS OPERATING IN AUTO: YES:	NO: If "NO", provide explanation below
PROVIDE WATER LE	VEL READINGS ON CONTROL PANEL
RW-1 ON: $\sqrt{}$ OFF: $\frac{7}{}$ ft	PW-5 ON: OFF: √ 6 ft
PW-2 ON: OFF: ft	PW-6 ON: OFF: V 4 ft
PW-3 ON: OFF: √ 5 ft	PW-7 ON: √ OFF: 11 ft
PW-4 ON: OFF: V 6 ft	PW-8 ON: √ OFF: 4 ft
EQUALIZATION TANK: 4 ft NOTES:	Last Alarm D/T/Condition: 8/30/10 Air Stripper Low Air Pressure
INFLUENT FLOW RATE: 35 gpm	INFLUENT TOTALIZER READING: 181,930.0 gallons
SEQUESTERING AGENT DRUM LEVEL: 28 inches	(x 1.7=) AMOUNT OF AGENT REMAINING: 47.5 gallons
SEQUESTERING AGENT FEED RATE: 5.0 ml/min	METERING PUMP PRESSURE: 3.0 psi
BAG FILTER PRESSURES: LEFT: 0	
INFLUENT FEED PUMP IN USE: #1 \\ #	2 INFLUENT PUMP PRESSURE: 14psi
AIR STRIPPER BLOWER IN USE: #1 #	12 √ AIR STRIPPER PRESSURE: 38.0 in. H₂O
AIR STRIPPER DIFFERENTIAL PRESSURE: 0.02	_ in. H₂O
EFFLUENT PUMP IN USE: #1 #2 V	EFFLUENT FEED PUMP PRESSURE:7.0 psi
EFFLUENT FLOW RATE: 110 gpm EFFLUEN	T TOTALIZER READING: 60,363,703 638300 gallons
ARE BUILDING HEATERS IN USE? YES:NO	o: INSIDE TEMPERATURE (° F):
IS SUMP PUMP IN USE: YES: NO:	ARE ANY LEAKS PRESENT? YES: NO:
WATER LEVEL IN SUMP: 6.0 in. TREATMENT	BUILDING CLEAN & ORGANIZED? YES: NO:

NYSDEC Site #90150157

SITE INSPECTION FORM

										7-Sep-1
SAMPLES COLLECT	ED? YES:	NO):					•		-
		Sample	ID Tim	e of Samplin	g	рН	Turbidity	Temp.	Sp. Cond.	
					1					
	ER INFLUENT:	<u> </u>			-					_
AIR STRIPPE	ER EFFLUENT:		-							_ ·
IS THERE E	VIDENCE OF TA	MPERING/VANI	DALISM OF	WELLS: ?	YES:		NO:	√		
		WERE MAN	IHOLES INS	PECTED?	YES:	√	NO:			
	WER	E ELECTRICAL	BOXES INS	PECTED?	YES:		NO:			
IS WATER PRE	SENT IN ANY N	IANHOLES OR E	LECTRICAL	BOXES?	YES:		NO:	1		•
	If yes, prov	ide manhole/elect	tric box ID an	d description	of any correc	ctive meas	ures below:	٠	4,	
·					_					
					-					
er Actions: Clear	ned Air Stripper	through access	ports.							
			· -		······		·			
				AGWAY						
SYS	TEM VACUUM:	-21	_in. H ₂ O			AIR P	RESSURE:		105	psi
SP-1: 8.	2 scfm	16.0 ps	si	SP-5_	0.0	scfm		29.0	psi	
SP-2: 0.	0 scfm	13.0 ps	si .	SP-6_	0.0	scfm		> 30	psi	
SP-3: 0	0 scfm	12.5 ps	si	SP-7_	0.0	scfm		> 30	psi	
SP-4:	scfm_		si	SP-8_	0.0	scfm	_	> 30	psi	
	CLUDE DEMAR	KS & DESCRIBE	ANY OTHE	 R SYSTEM M	AINTFNANC		ORMED ON	AGWAY S	 ITE	
marks:	CLODE REMAIN	NO B DESCRIBE	ART OTTE							
marks.										
hay Antions:									***	
ner Actions:				,						
									<u>:</u>	 -

NYSDEC Site #9-15-157

OM&M: SITE INSPECTION FORM

DATE: 13-Sep-10 ACTIVITIES:	Site Inspection	
INSPECTION PERSONNEL: R. Allen	OTHER PERSONNEL:	
WEATHER CONDITIONS: Partly cloudy, warm	OUTSIDE TEMPERATURE (° F):72
ARE WELL PUMPS OPERATING IN AUTO: YES: √ PW-7 is constantly ON while reading a steady 11.	NO: If "NO", provide explanation below	N
PROVIDE WATER LEV	VEL READINGS ON CONTROL PANEL	
RW-1 ON: OFF: √ 8 ft	PW-5 ON: OFF:	_ft
PW-2 ON: OFF: √ 6 ft	PW-6 ON: OFF: √ 3	ft
PW-3 ON: OFF:	PW-7 ON: √ OFF: 11	_ft
PW-4 ON: OFF: V 5 ft	PW-8 ON: OFF: 1	ft
EQUALIZATION TANK: 4 ft	Last Alarm D/T/Condition: 9/10/10 Air Stripper Low Level	
NOTES:		<u> </u>
INFLUENT FLOW RATE: 3 gpm	INFLUENT TOTALIZER READING: 318,144.0	gallons
SEQUESTERING AGENT DRUM LEVEL: 20 inches SEQUESTERING AGENT FEED RATE: 9.0 ml/min	(x 1.7=) AMOUNT OF AGENT REMAINING: 34 METERING PUMP PRESSURE: 3.0	galions psi
Top	Bottom Top Bottom	
BAG FILTER PRESSURES: LEFT: 0	0 psi RIGHT: 6 0	_psi
INFLUENT FEED PUMP IN USE: #1 #	2 INFLUENT PUMP PRESSURE: 13	psi
AIR STRIPPER BLOWER IN USE: #1 # AIR STRIPPER DIFFERENTIAL PRESSURE: 0.035	12 √ AIR STRIPPER PRESSURE: 12.0	in. H₂O
	in. H₂O DISCHARGE PRESSURE: 1.0	— in. H₂O
EFFLUENT PUMP IN USE: #1 #2 √ EFFLUENT FLOW RATE: 0.035 gpm EFFLUENT	in. H₂O DISCHARGE PRESSURE: 1.0 EFFLUENT FEED PUMP PRESSURE: 9.5 T TOTALIZER READING: 60,444,342 71962	psi
	EFFLUENT FEED PUMP PRESSURE: 9.5 T TOTALIZER READING: 60,444,342 71962	psi 0 gallons
EFFLUENT FLOW RATE: 0.035 gpm EFFLUENT	EFFLUENT FEED PUMP PRESSURE: 9.5 T TOTALIZER READING: 60,444,342 71962	psi 0 gallons : 77

NYSDEC Site #90150157

SITE INSPECTION FORM

										. 	13-	Sep-10
SAMPLES COLL	ECTED?	YES:	√	NO:								
			Sa	mple ID	Time of	Sampling	g ·	рН	Turbidity	Temp.	Sp. Cond.	
AIR STE	RIPPER INFI	LUENT;	<u>1N</u>	F	11:	30 AM	_	7.49	7.03	17.4	2720	
AIR STR	IPPER EFF	LUENT:	EF	F	11:	40 AM		8.67	8.94	17.9	2660	
 _					<u></u>							
IS THE	RE EVIDEN	CE OF TA	MPERING	/VANDALIS	SM OF WEL	.LS: ?	YES:_	<u> </u>	NO:			
			WERE	MANHOL	ES INSPEC	TED?	YES:_	<u> </u>	NO:			
					ES INSPEC		YES:	<u>\</u>	NO:			
IS WATER	PRESENT	•					YES:_		NO:		1	
	lf	yes, provi	de manhol	e/electric bo	ox ID and de	scription o	of any correc	tive meast	ires below:			:
		***			•••					•		
	INCLUDE	REMARK	(S & DES	CRIBE ANY	OTHER S	/STEM M/	AINTENANO	CE PERFO	RMED ON	MR. C's SI	TE .	÷
marks: <u>T</u>	urned Jesc	o pump d	own sligh	tly to: Left :	2.1; Right 1	.1						
her Actions:						,				· · · · · · · · · · · · · · · · · · ·		
ner Actions.			• .									
	· · · · · · · · · · · · · · · · · · ·		e male					1				
	:			-	. <u>-</u>							· ·
<u> </u>				• •								
· · · · · · · · · · · · · · · · · · ·				4	AG	SWAY						
	SYSTEM VA	сиии: _	-21	in.	H₂O			AIR PR	ESSURE:	1	10 p	si
SP-1:	10.0	scfm	5.0	psi .		SP-5	0.0	scfm		28.5 p	ısi	
SP-2:	0.0	scfm	25.0	psi	;	SP-6	0.0	scfm	_	> 30 p	osi	
 SP-3:	0.0	scfm		psi	•	SP-7	0.0	scfm	_	> 30 p	ısi	
SP-4:	0.0	scfm		psi		SP-8	0.0	scfm	_	> 30 p		
									-			
	INCLUDE	REMARK	S & DESC	RIBE ANY	OTHER SY	'STEN MA	AINTENANC	E PERFO	RMED ON A	AGWAY SIT	TE .	
emarks:											•	
. <u></u>												
ther Actions:												

NYSDEC Site #9-15-157

OM&M: SITE INSPECTION FORM

DATE:	21-Sep-	10	ACTIVITIES:	Site Inspection	on		· 	
INSPECT	ION PERSONNEL:	R. Allen		_OTHER PERSO	NNEL:	·		
WEATHE	R CONDITIONS:	Partly cloudy, wa	rm			OUTSIDE TEMPE	RATURE (° F):	59
	L PUMPS OPERA	TING IN AUTO: at a steady level 11.	YES:	NO:		f "NO", provide expl	anation below	
-		PRO	/IDE WATER LEV	EL READINGS C	N CONTROL PANE	 L	 	
RW-1	on: \	OFF:	ft	PW-5	ON:	off:√_	51	t
PW-2	ON:	off: √	6ft	PW-6	ON:	0FF:√	f	t
PW-3	ON:	0FF: <u>√</u>	6 tt	PW-7	on: <u>√</u>	OFF:	f	t
PW-4	ON:	off: √	7_ft	PW-8	ON:	0FF: <u>√</u>	f	t
	EQU	ALIZATION TANK: _	4 ft	Last A	larm D/T/Condition:	9/10/10 Air Stripper Lo	ow Level	
	NOTES:		1.44 ·					·
INFLU	ENT FLOW RATE:	3	gpm	INFLUENT TOT	ALIZER READING:	509,60	3.0	allons
	QUESTERING AGE	NT DRUM LEVEL:	8 inches	(x 1.7=	•	GENT REMAINING:	3.5	allons esi
	BAG FILTER PRE	SSURES:	Top	Bottom psi	RIGHT:	Тор 6	Bottom p	si
INFLU	ENT FEED PUMP I	N USE: #1	√ +#2		NFLUENT PUMP PR	ESSURE:	13 r	si
	TRIPPER BLOWE		#2 0.035	in. H₂O	AIR STRIPPER PRI			n. H₂O n. H₂O
	NT PUMP IN USE:		#2\ EFFLUENT	-	NT FEED PUMP PRI	-	10.5 p	
ARE BU	ILDING HEATERS	IN USE? YES:	NO:	<u> </u>	· — — — — — — — —	INSIDE TEMPE	RATURE (° F):	72
IS SUI	MP PUMP IN USE:	YES:	NO:	ARE ANY L	EAKS PRESENT?	YES:	NO:_	
WATER	LEVEL IN SUMP:	5.5 in.	TREATMENT E	BUILDING CLEAI	N & ORGANIZED?	YES:	NO:_	

NYSDEC Site #90150157

SITE INSPECTION FORM

SAMPLES COLLECTED? YES:	NO: <u>√</u>		
. Sa	imple ID Time of Sampling	pH Turbidity	Temp. Sp. Cond.
AIR STRIPPER INFLUENT:			
AIR STRIPPER EFFLUENT:			
IS THERE EVIDENCE OF TAMPERING	VANDALISM OF WELLS: ?	YES: NO:	
WERL	E MANHOLES INSPECTED?	YES: NO:	
WERE ELECTR	RICAL BOXES INSPECTED?	YES: NO:	
IS WATER PRESENT IN ANY MANHOLES	OR ELECTRICAL BOXES?	YES: NO:	
lf yes, provide manhol	le/electric box ID and description of a	ny corrective measures below:	
		-	
INCLUDE REMARKS & DES	CRIBE ANY OTHER SYSTEM MAIN	ITENANCE PERFORMED ON	MR, C's SITE
Remarks: Reduced Jesco pump slightly to			
Remarks. Reduced Jesco pump signify in	J. Left 2.0, Mg/ft 1.0.	· ·	· · · · · · · · · · · · · · · · · · ·
Other Actions: Drew As-Built sketch of Effluen	t Pipe		
			·
	AGWAY		
SYSTEM VACUUM:21	in. H₂O	AIR PRESSURE:	85 psi
SP-1: > 10 scfm 3.5	psi SP-5 0	.0 scfm	psi
SP-2: 0.0 scfm 21.0	psi SP-6 0	.0 scfm	<u>> 30</u> psi
SP-3: 0.0 scfm 20.0	psi SP-7 0	.0 scfm	> 30 psi
SP-4: 0.0 scfm 20.5	psi SP-8 <u>0</u>	.0 scfm	> 30 psi
INCLUDE REMARKS & DESC	CRIBE ANY OTHER SYSTEM MAIN	TENANCE PERFORMED ON	AGWAY SITE
Remarks: SVE drum is dry.			
Other Actions:			

NYSDEC Site #9-15-157

OM&M: SITE INSPECTION FORM

DATE: 28-Sep-10	ACTIVITIES:	Site Inspect	ion		<u></u>	
INSPECTION PERSONNEL: R. Allen	***	OTHER PERS	ONNEL:			
WEATHER CONDITIONS:			·	OUTSIDE TEMPE	RATURE (° F): 70	<u> </u>
ARE WELL PUMPS OPERATING IN AUTO: PW-7 remains ON at a steady level 12.	YES: \(\sqrt{1} \)	NO:		If "NO", provide exp	lanation below	
<u></u>				<u> </u>		<u>. </u>
PRO	VIDE WATER LEV	EL READINGS (ON CONTROL PAN	EL .		
RW-1 ON: √ OFF:	6 ft	PW-5	ON:	_ OFF:√	ft	
PW-2 ON: OFF:	6 ft	PW-6	ON:	_ OFF:√_	ft	
PW-3 ON: OFF:	7 ft	PW-7	on:√	OFF:	ft	1
PW-4 ON: OFF: √	6 ft	PW-8	on:√	OFF:	ft	
EQUALIZATION TANK:	4 ft	Last	Alarm D/T/Condition	: 9/10/10 Air Stripper L	ow Level	
NOTES:						
INFLUENT FLOW RATE: 23	gpm	INFLUENT TO	TALIZER READING	: 683,18	8.0 gallon	าร
SEQUESTERING AGENT DRUM LEVEL:	26 inches	(x 1.7	=) AMOUNT OF	AGENT REMAINING:	44 gallon	 15
SEQUESTERING AGENT DRUM LEVEL: SEQUESTERING AGENT FEED RATE:	26 inches	(x 1.7		AGENT REMAINING: G PUMP PRESSURE:		าร
_		(x 1.7				ns
_	7.0 ml/min			G PUMP PRESSURE:	3.0 psi	ns
SEQUESTERING AGENT FEED RATE:	7.0 ml/min	Bottom 0 psi	METERIN	G PUMP PRESSURE: Top .6	3.0 psi	ns
SEQUESTERING AGENT FEED RATE: BAG FILTER PRESSURES: INFLUENT FEED PUMP IN USE: #1	7.0 ml/min Top LEFT: 0	Bottom 0 psi	METERIN RIGHT: NFLUENT PUMP P	G PUMP PRESSURE: Top 6 RESSURE:	3.0 psi Bottom 0 psi 13 psi	
SEQUESTERING AGENT FEED RATE: BAG FILTER PRESSURES: INFLUENT FEED PUMP IN USE: #1 AIR STRIPPER BLOWER IN USE: #1	7.0 ml/min Top LEFT: 0 #2	Bottom 0 psi	METERIN RIGHT: NFLUENT PUMP P	G PUMP PRESSURE: Top 6 RESSURE:	3.0 psi Bottom 0 psi 13 psi 14.0 in. H ₂ (
SEQUESTERING AGENT FEED RATE: BAG FILTER PRESSURES: INFLUENT FEED PUMP IN USE: #1	7.0 ml/min Top LEFT: 0	Bottom 0 psi	METERIN RIGHT: NFLUENT PUMP P	G PUMP PRESSURE: Top 6 RESSURE:	3.0 psi Bottom 0 psi 13 psi	
SEQUESTERING AGENT FEED RATE: BAG FILTER PRESSURES: INFLUENT FEED PUMP IN USE: #1 AIR STRIPPER BLOWER IN USE: #1 AIR STRIPPER DIFFERENTIAL PRESSURE:	7.0 ml/min Top LEFT: 0 #2	Bottom O psi	METERIN RIGHT: NFLUENT PUMP P	Top 6 RESSURE: RESSURE:	3.0 psi Bottom 0 psi 13 psi 14.0 in. H ₂ (
SEQUESTERING AGENT FEED RATE: BAG FILTER PRESSURES: INFLUENT FEED PUMP IN USE: #1 AIR STRIPPER BLOWER IN USE: #1 AIR STRIPPER DIFFERENTIAL PRESSURE: EFFLUENT PUMP IN USE: #1	7.0 ml/min Top LEFT: 0 #2 0.033	Bottom O psi V in. H ₂ O	METERIN RIGHT: NFLUENT PUMP P AIR STRIPPER P DISCHARGE P	Top 6 RESSURE: RESSURE:	3.0 psi Bottom	0
SEQUESTERING AGENT FEED RATE: BAG FILTER PRESSURES: INFLUENT FEED PUMP IN USE: #1 AIR STRIPPER BLOWER IN USE: #1 AIR STRIPPER DIFFERENTIAL PRESSURE: EFFLUENT PUMP IN USE: #1 EFFLUENT FLOW RATE: 112 gpm	7.0 ml/min Top LEFT: 0 #2 0.033	Bottom O psi in. H ₂ O EFFLUI TOTALIZER RE	METERIN RIGHT: NFLUENT PUMP P AIR STRIPPER P DISCHARGE P	G PUMP PRESSURE: Top 6 RESSURE: RESSURE: RESSURE:	3.0 psi Bottom	0
SEQUESTERING AGENT FEED RATE: BAG FILTER PRESSURES: INFLUENT FEED PUMP IN USE: #1 AIR STRIPPER BLOWER IN USE: #1 AIR STRIPPER DIFFERENTIAL PRESSURE: EFFLUENT PUMP IN USE: #1 EFFLUENT FLOW RATE: 112 gpm	7.0 ml/min Top LEFT: 0	Bottom O psi in. H ₂ O EFFLUI TOTALIZER RE	RIGHT: NFLUENT PUMP P AIR STRIPPER P DISCHARGE P ENT FEED PUMP P EADING: 6	Top 6 RESSURE: RESSURE: RESSURE: 0,661,011	3.0 psi Bottom	00 00

NYSDEC Site #90150157

SITE INSPECTION FORM

	LLECTED?	YES:_		NO:	<u> </u>					_		
			Sam	ple ID	Time of \$	Sampling		рН	Turbidity	Temp.	Sp. Cond.	
AIR S	TRIPPER IN	FLUENT:					_					
AIR S	TRIPPER EF	FLUENT:		·			· · · -		· · · · · · · · · · · · · · · · · · ·			
 IS TH	ERE EVIDEI	ICE OF TA	MPERING/\	/ANDALIS	SM OF WELL	.s: ?	YES:		NO:	√		
10 111	_,,,,				.ES INSPECT		YES:		. NO:	.==	•	
		WER	E ELECTRIC	CAL BOX	ES INSPECT	ED?	YES:	√ √	NO:			
IS WATE	R PRESENT	'IN ANY M	ANHOLES (OR ELEC	TRICAL BOX	(ES?	YES:		NO:	√	_	
		if yes, provi	de manhole/	electric bo	ox ID and des	cription of	any correc	ctive meas	ures below:		•	
				•						_		
					<u> </u>							_
	Air Strippei			.	Vidth 34" x F			,				
				.				,				
				.	111'6" x Wi			,				
		onmental,		s: Length	111'6" x Wi	dth 34" x		AIR P	RESSURE:		105	osi
ther Actions:	Bisco Envi	onmental,	Inc. gasket	s: Length	111' 6" x Wi	dth 34" x		AIR P			105 _j	osi
emarks: ther Actions: SP-1:	SYSTEM V	onmental,	Inc. gasket	is: Length	111' 6" x Wi	dth 34" x	Heigth 1"			29.5	 -	osi
ther Actions:	SYSTEM V > 10 0.0	onmental,	-21 3.5	in.	111'6" x Wi	WAY	Heigth 1"	scfm	•	29.5	psi	osi
ther Actions: SP-1: SP-2:	SYSTEM V > 10 0.0 0.0	CACUUM: scfm	-21 3.5 18.5	in. psi	111'6" x Wi	WAY SP-5 SP-6	0.0 1.3	scfm scfm	•	29.5 > 30	psi psi	osi
sp-1: SP-2: SP-3:	SYSTEM V > 10 0.0 0.0	Scfm_scfm_scfm_scfm_scfm_scfm_scfm_scfm_s	-21 3.5 18.5 17.5 18.0	in. psi psi psi psi	11'6" x Wi	WAY SP-5 SP-6 SP-7 SP-8	0.0 1.3 0.0	scfm scfm scfm scfm		29.5 > 30 > 30 > 30	psi psi psi psi	osi
sp-1: SP-2: SP-3: SP-4	SYSTEM V > 10 0.0 0.0 INCLUE	Sofm_sofm_sofm_sefm_	-21 3.5 18.5 17.5 18.0	in. psi psi psi psi	111'6" x Wi	WAY SP-5 SP-6 SP-7 SP-8	0.0 1.3 0.0	scfm scfm scfm scfm		29.5 > 30 > 30 > 30	psi psi psi psi	osi
sp-1: SP-2: SP-3:	SYSTEM V > 10 0.0 0.0	Sofm_sofm_sofm_sefm_	-21 3.5 18.5 17.5 18.0	in. psi psi psi psi	11'6" x Wi	WAY SP-5 SP-6 SP-7 SP-8	0.0 1.3 0.0	scfm scfm scfm scfm		29.5 > 30 > 30 > 30	psi psi psi psi	osi

28-Sep-10

Mr. C's CLEANERS OM&M

SUMMARY OF FIELD ACTIVITIES BY IEG - 9/2010

DATE	ACTIVITY
3-Sep	Take delivery of Redux
7-Sep	OM&M Weekly Inspection and end of month summary
8-Sep	OM&M Piezometer Readings
9-Sep	Prepare for Air Stripper cleaning
10-Sep	Clean Air Stripper
13-Sep	OM&M Weekly Inspection and sampling
21-Sep	OM&M Weekly Inspection. Draw As-Built sketch of effluent pipe.
24-Sep	Switch Jesco pump. Clean out drum.
28-Sep	OM&M Weekly Inspection and office work

Mr. C's CLEANERS OM&M STATUS SUMMARY - FIELD ACTIVITIES BY IEG - 9/2010

ACTIVITY	DESCRIPTION	COMPLETION DATE/STATUS		
Restart System after May storm	Blower #2 causes breaker in Air Stripper Control Panel to trip. Switch system to Bloweer #1. Troubleshoot and repair Blower #2. Removed and repaired #2 motor.	Jul-10		
Troubleshoot electrical overload	Alarm calls repeatedly indicate an electrical power overload. System usually continues to run normally. Troubleshoot source of alarm and repair. Reset temperature alarm.	Jul-10		
Champion Compressor replace belts	Belts are loose and the adjustment is at end of tightening limit. Replace both belts.	Jul-10		
Champion Compressor repair belt guard	The belt guard is loose and wiggles during operation. Add braces to guard.	Jul-10		
Blower #1 - replace starter motor (contactor)	The contactor is defective for this motor. Replace the unit.	Jul-10		
Blower #2 - replace starter motor (contactor) .	The contactor is defective for this motor. Replace the unit.	Jul-10		
Influent Pump #2 - replace starter	The contactor is defective for this motor. Replace the unit.	Jul-10		
Fix Leak in Influent Pipe	A leak started in the Redux fitting in the Influent Pipe. Replace corroded fitting.	Jul-10 .		
Sump pump pipe disconnects The sump pump pipe was not cemented onto the fitting at the Equalization Tank. Cement the loose pipe back onto the fitting.				
Champion Compressor Maintenance	Change oil and air filter.	Jul-10		
Replace SVE Vacuum Drum	Present Vacuum Drum inside Agway Shed is corroded. Replace drum.	To be ordered		
AS / SVE System Evaluation	Agway Shed - test & evaluate air sparge system and Soil Vapor Extraction system. Installed fittings to measure pressure and flow. Tested air sparging and SVE lines.	in progress		
Service Compressor	iservice, including a valve kit.			
PW-4 Well Repair and Level	Asphalt around PW-4 well has sunk, due to collapse of corroded inner ring. Replace inner ring and bring parking lot up to level with asphalt patch.			
PW-4 UE Level	Asphalt around Underground Enclosure has sunk, leaving it vulnerable to damage. Bring parking lot up to level with asphalt patch.	in progress		
Install MW Ring	Piezimeter in Agway Site parking lot was damaged by the road repair crew. To instal new Monitoring Well Ring around damaged Piezometer for protection.	in progress		
Rebuild Automatic Tank Drain Valve (ATDV)	Factory recommends rebuilding the ATDV on a compressor of this age. Order rebuild kit and repair. Have purchased rebuild kit.	in progress		
Rebuild JAC Pump as needed	Jesco America Corp recommends rebuilding the Redux pump when needed. Purchased rebuild kit.	in progress		
Brace Effluent Pipe	David Saymanski (NYSDEC) inspected Treatment Room and said that the effuent pine			
Inspect and clean Manholes	Inspect manholes near operating pumps. Pump out water in manholes and clean out remaining sediment and other material.	in progress		
Purge PW-5	Inspect, purge well, clean pump, plastic pipe and transducer. Trouble shoot problems.	in progress		
Agway Shed Concrete Dump	Approximately 1/4 yard of concrete was washed out on the north side of the Agway Shed. Concrete should be removed.	in progress		
Trim Broken Piezometers	Many of the piezometers are broken. Measuring water levels is not precise when a pipe is broken. Identify and trim all broken piezometers.	in progress		
Repair Filter Basket	The handle loop on a filter basket broke. Weld handle back in place.	in progress		
Champion Compressor not running	Diagnose problem to the electric motor. Remove and take to S&S Electric for repair. Motor is burned up and not worth repairing. Replaced motor.	Aug-10		
Cool Treatment Room	Temperature in Treatment Room is well above 90 degrees during the summer months. Need to increase outside air inflow to the room.	in progress		
Air Stripper readings are high	Clean air stripper trays: Brushed trays through access ports, pressure washed trays through ports.	Sep-10		
Schedule Air Stripper Disassembly	Trays need to be periodically disassembled so that built up scale can be brushed off with power tools.	Sep-10		

Mr. C's CLEANERS OM&M

SUMMARY OF WATER PUMP MAINTENANCE BY IEG

9
Sep
ö
as

<u> </u>	REPLACED PUMP	REPAIR PUMP	PIPE & PITLESS ADAPTER	CLEAN & INSPECT TRANSDUCER	REPLACE TRANSDUCER	REPAIR TRANSDUCER	PUMP OUT WELL	CLEAN OUT & INSPECT ELECTRICAL BOX	ELECTRICAL BOX REPAIR
	Feb-08	May-10		May-10					
	Jul-08			Aug 09, May 10	Sep-09	• .	Aug-09		Sep-09
	Jul-08		Repair adapter	60-6nV			Aug-09		·
	Dec-07	NEED		May-10			Jul 09, Sep 09	Sep-09	Sep-09
	Jul-08			Sep-09		Sep-09			
	Jun 08, Jul 09		Replace pipe 8/09	Apr 09, Aug 09	Sep-09		Aug-09	Aug 09, Sep 09	Jul 09, Sep 09
	Nov 07, Jul 09		Replace pipe 8/09	Aug 09, May 10			Au 09, May 10		
	Aug 09, May 10 Jul 08, Sep 09		Replace pipe 8/09	Aug 09, May 10			Aug 09, May 10		

Mr. C's CLEANERS OM&M

SUMMARY OF WATER PUMP STATUS - 2010

			· · · · · · · · · · · · · · · · · · ·					ı	1
as of Sep 10	NEEDS REPAIR	YES - bolts	YES - bolts	ON	YES - Asphalt patch	ON	DONE	ON	ON
	NEEDS U.E. CLEANED	ON	ON	ON	DONE	ON	Ņ	ON	ON
	NEEDS ANEROID BELLOWS	YES	DONE 9/09	YES	DONE 9/09	DONE	DONE 9/09	DONE	YES
	CLEANED & INSPECTED U.E.	·			YES 9/09		YES 9/09		·
	NEEDS NEW TRANSDUCER	ON		ON		problems 1/09 and 11/09	NO .	ON	ON
	NEEDS TRANSDUCER INSPECTION	ON	ON	ON	NO	YES 7/09, Problem 11/09	YES 7/09	NO	ON
!	NEEDS WELL CLEAN-OUT	YES	YES	DONE 8/09	DONE 9/09	YES	DONE 8/09	ON	ON
	NEEDS P.A. OR PIPE			REPAIRED 8/09			Replaced pipe 8/09	Replaced pipe 8/09	Replaced pipe 8/09
	NEEDS NEW PUMP	ON	ON	ON	ON	ON	DONE 8/09	YES	DONE 9/09
	NEEDS CLEANING & INSPECTION	ON	ON	ON	ON	ON	ΟN	ON	ON .
·	(D	RW - 1	PW - 2	PW - 3	PW - 4	PW - 5	PW - 6	P.W 7	PW`-8

Attachment B Analytical Report from Mitkem Laboratories

Analytical Data Package Work Order ID: J1769

Sampled: September 13, 2010 Analyzed: September 14, 2010

Analytical Data Package for Ecology & Environment Engineering, P.C. (EEEPC)

Client Project No.: Mr. C's Dry Cleaners Site (Compliance)

Mitkem Work Order ID: J1769 September 17, 2010

Prepared For:

Ecology & Environment Engineering P.C.

368 Pleasantview Drive Lancaster, NY 14086 Attn: Mr. Michael Steffan

Prepared By:

Mitkem Laboratories

175 Metro Center Boulevard

Warwick, RI 02886 (401) 732-3400

Sample Transmittal Documentation

E		TECHNOLOGY
MITKEM	LABORATORIES	VIOLENCE CRECITOR & ANALYTICAL THE Barbarian DANIBAL TECHNOLOGY

CHAIN OF CUSTODY RECORD

jo

Page !

Special Handling:
TAT-Indicate Date Needed: Rush 72 hrs
All TATs subject to laboratory approval.
Min. 24-hour notification needed for rushes.
Samples disposed of after 30 days unless otherwise instructed.

ERE, Inc	Invoice To:	(I)	山	200			Project No.:				
2 Santa					-	1	Site Name:		Mrcs	アキアの	-
Lancaster N (TOB6					ļ		Location:	Eas	Aura	3 State:	e: \(\frac{\fir}{\fint}}}}}}}}{\frac}}}}}}}}}}{\frac{\fin}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\frac{\f
(716) 684-8060							Sampler(s).	ينر	R. Allen		
ا تا ا	P.O. No.:		1	RQN:			The state of the s	-	j		
$1=Na_2S2O_3$ $2=HC1$ $3=H_2SO_4$ $4=HNO_3$ $5=8=NaHSO_4$ $9=$	5=NaOH 6=	6=Ascorbic Acid	Acid	7=CH ₃ OH	НО	1	List preservative code below:	vative co	le below:	Notes	δ.
ter GW=Groundwater WW=Was	tewater A=Air			Conta	Containers:	2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	20.000	Analyses		QA/QC Reporting Level	rting Level
X2= X3=			slsi\				72.5		,	D Level III	□ Level IV
G=Grab C=Composite		-	/ AO			H	<u> </u>			A Other CAT	*
21769		egy] Tatrix	V 10	A To	of CI	4	\ \ \			State specific reporting standards:	rting standards:
ld: Sample Id: Date:	Time:	_	#	-	\dashv	_)				
11. (VELUENT 9/13/ (0 1:	1.00 PM	0 0	-		J	>				Note: Boyte	क्ष्रिक क्ष
TO INFLUENT /	:00 PM	G GW			_		>			said 500 m	w HNO,
) -	100 PM	6 60	2			<u> </u>	>			bottles	,
	15 PM	G 6W	1		_	>				We were sent	ient
OZ EFFLUENT / (:1	1:15 PM	Ø 6₩					>			250 m	HNO,
OZ EFFLUENT V	1:15 PM	S S S	ΛI				>	-		boffes.	3
										,	
# E-mail to Msteffan @ ene, com	123		kelingu	shed b	Relinquished by:	\$30 2548	R	Received by:		Date:	Time:
EDD Format PDF		5.2	harl	1	OC Allen Jr		3	MPS	,		
)	Urs			gruber	les	NS	9/14/10	12:ത
Condition upon receipt: 🖆 Iced 🗆 Ambient 🗹 🤨 🧳					-			Į			
						•					

MITKEM LABORATORIES

Sample Condition Form

(of Page Date 9/14 d Mitkem Work Order #: Reviewed By: CN Received By: ENE Comptance Client: MY C Client Project: Headspace or Preservation (pH) VOA Air Bubble ≥ HNO3 H2SO4 HCI NaOH H3PO4 1/4" Lab Sample ID Matrix 31769 01 H 42 1) Cooler Sealed Xes / No CZ J7769 02 1 2) Custody Seal(s) Present / Absent Coolers / Bottles Intact / Broken 3) Custody Seal Number(s) Present / Absent 4) Chain-of-Custody 5) Cooler Temperature IR Temp Gun ID **Coolant Condition** Fresent / Absent 6) Airbill(s) UPS Airbill Number(s) 1ZFR8725139193 4728 intast / Broken / Leaking 7) Samples Bottles 9/14/10 8) Date Received 12:00 9) Time Received Preservative Name/Lot No.: VOA Matrix Key: US = Unpreserved Soil A = AirUA = Unpreserved Aqueous H = HCl E = Encore M = MeOHF = Freeze N = NaHSO4See Sample Condition Notification/Corrective Action Form yes 7 fto Rad OK yes / no



* Volatiles *

1A - FORM I VOA-1 VOLATILE ORGANICS ANALYSIS DATA SHEET

CLIENT	SAMPLE	NO.
INFLUE	NT	

Lab Name: MITKEM LABOR	RATORIES	· .	Contract:	
Lab Code: MITKEM	Case No.:	J1769	Mod. Ref No.:	SDG No.: SJ1769
Matrix: (SOIL/SED/WATE)	R) WATER		Lab Sample ID:	J1769-01A
Sample wt/vol: 5	.00 (g/mL)	ML	Lab File ID:	V1L6543.D
Level: (TRACE/LOW/MED)	LOW		Date Received:	09/14/2010
% Moisture: not dec.	-	-	Date Analyzed:,	09/14/2010
GC Column: DB-624	ID:	0.25 (mm)	Dilution Factor:	10.0
Soil Extract Volume:		(uL)	Soil Aliquot Vol	ume: (uL)
	-	/mT.\	•	

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) µg/L	Q
75-71-8	Dichlorodifluoromethane	. 10	Ū
	Chloromethane	10	Ū
	Vinyl chloride	10	U ·····
	Bromomethane	10	U
	Chloroethane	10	Ū
	Trichlorofluoromethane	10	Ŭ
75-35-4	1,1-Dichloroethene	10	U
67-64-1	Acetone	50	Ū
75-15-0	Carbon disulfide	10	Ū
75-09-2	Methylene chloride	10	Ū
	trans-1,2-Dichloroethene	10	Ū
1634-04-4	Methyl tert-butyl ether	8.9	J
75-34-3	1,1-Dichloroethane	10	Ū
	2-Butanone	50	Ü
156-59-2	cis-1,2-Dichloroethene	20	
	Chloroform	10	Ū
71-55-6	1,1,1-Trichloroethane	10	Ū
56-23-5	Carbon tetrachloride	10	Ū
107-06-2	1,2-Dichloroethane	10	U
	Benzene	10	U
79-01-6	Trichloroethene	45	
78-87 - 5	1,2-Dichloropropane	10	บ
	Bromodichloromethane	.10	Ü
10061-01-5	cis-1,3-Dichloropropene	10	ซ
108-10-1	4-Methyl-2-pentanone	50	Ū
108-88-3		10	Ū
10061-02-6	trans-1,3-Dichloropropene	10	Ū
79-00-5	1,1,2-Trichloroethane	10	U.
	Tetrachloroethene	840	
591-78-6	2-Hexanone	50	U
124-48-1	Dibromochloromethane	10	ט
106-93-4	1,2-Dibromoethane	10	Ü
108-90-7	Chlorobenzene	10	Ü
100-41-4	Ethylbenzene	10	U
1330-20-7	Xylene (Total)	10	Ü

1B - FORM I VOA-2 VOLATILE ORGANICS ANALYSIS DATA SHEET

CLIENT	SAMPLE	NO.
INFLUE	NT .	

Lab Name: MITKEM LABOR	ATORIES -			Contract:		
Lab Code: MITKEM	Case No.:	J1769		Mod. Ref No.:	SDG No.: SJ1769	
Matrix: (SOIL/SED/WATER) WATER			Lab Sample ID:	J1769-01A	
Sample wt/vol: 5.	00 (g/mL)	ML		Lab File ID:	V1L6543.D	
Level: (TRACE/LOW/MED)	LOW			Date Received:	09/14/2010	
% Moisture: not dec.				Date Analyzed:	09/14/2010	
GC Column: DB-624	ID:	0.25	(mm)	Dilution Factor:	10.0	
Soil Extract Volume:			(uĹ)	Soil Aliquot Vol	ume:(uL)
Purge Volume: 5.0			(mL)			

CAS NO.	COMPOUND	CONCENTRATION UN (ug/L or ug/Kg)	ITS: μG/L	Q
100-42-5	Styrene		10	Ū
	Bromoform		10	Ū
98-82-8	Isopropylbenzene		10	U.
79-34 - 5	1,1,2,2-Tetrachloroethane		10	U
541-73-1	1,3-Dichlorobenzene		10	U
106-46-7	1,4-Dichlorobenzene		10	U
95-50-1	1,2-Dichlorobenzene		10	U
96-12-8	1,2-Dibromo-3-chloropropane		10	Ü
120-82-1	1,2,4-Trichlorobenzene		10	U
76-13-1	1,1,2-Trichloro-1,2,2-trifluoroethane		10	U
	Cyclohexane		10	Ū
79-20-9	Methyl acetate		10	Ū
108-87-2	Methylcyclohexane ·		10	Ū

1A - FORM I VOA-1 VOLATILE ORGANICS ANALYSIS DATA SHEET

CLIENT	SAMPLE	NO.
EFFLUE	NT	
Ì		

Lab Name: MITKEM LABORAT	ORIES			Contract:	
Lab Code: MITKEM	Case No.:	J1769		Mod. Ref No.:	SDG No.: SJ1769
Matrix: (SOIL/SED/WATER)	WATER			Lab Sample ID:	J1769-02A
Sample wt/vol: 5.00	(g/mL)	ML		Lab File ID:	V1L6538.D
Level: (TRACE/LOW/MED) I	¹OM̄ -			Date Received:	09/14/2010
% Moisture: not dec.				Date Analyzed:	09/14/2010
GC Column: DB-624	ID:	0.25	(mm)	Dilution Factor:	1.0
Soil Extract Volume:			(uL)	Soil Aliquot Vol	ume: (uL)
T			- /mT \		


CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) µg/L	Q
75-71-8	Dichlorodifluoromethane	1.0	ָ ט
74-87-3	Chloromethane	1.0	ט
75-01-4	Vinyl chloride	1.0	Ū
74-83-9	Bromomethane	1.0	Ū
75-00-3	Chloroethane	1.0	U
75-69-4	Trichlorofluoromethane	1.0	Ū
75-35-4	1,1-Dichloroethene	1.0	U
67-64-1	Acetone	5.0	Ū ·
75-15-0	Carbon disulfide	1.0	Ū
75-09-2	Methylene chloride	1.0	Ū
156-60-5	trans-1,2-Dichloroethene	1.0	U
1634-04-4	Methyl tert-butyl ether	1.0	Ū
	1,1-Dichloroethane	1.0	Ū
78-93-3	2-Butanone	5.0	U
156-59-2	cis-1,2-Dichloroethene	1.0	Ū
	Chloroform	1.0	Ū
71-55-6	1,1,1-Trichloroethane	1.0	Ū
	Carbon tetrachloride	1.0	Ū
107-06-2	2 1,2-Dichloroethane	1.0	Ū
71-43-2	Benzene	1.0	Ū
79-01-6	Trichloroethene	1.0	Ū
78-87-5	1,2-Dichloropropane	1.0	Ū
75-27-4	Bromodichloromethane	1.0	Ū
10061-01-5	cis-1,3-Dichloropropene	1.0	Ū
	4-Methyl-2-pentanone	5.0	Ū
	3 Toluene	1.0	U
10061-02-6	trans-1,3-Dichloropropene	1.0	Ū
	1,1,2-Trichloroethane	1.0	Ū ·
	Tetrachloroethene	1.3	
591-78-6	2-Hexanone	5.0	U
	Dibromochloromethane	1.0	Ū
	1,2-Dibromoethane	1.0	U
	Chlorobenzene	1.0	Ū
	Ethylbenzene	1.0	Ū
	Xylene (Total)	1.0	Ū

1B - FORM I VOA-2 VOLATILE ORGANICS ANALYSIS DATA SHEET

CLIENT	SAMPLE	NO.
EFFLUE	NT	

Lab Name: MITKEM LABORA	TORIES	-		Contract:	
Lab Code: MITKEM	Case No.:	J1769		Mod. Ref No.:	SDG No.: SJ1769
Matrix: (SOIL/SED/WATER)	WATER			Lab Sample ID:	J1769-02A
Sample wt/vol: 5.0)0 (g/mL)	ML		Lab File ID:	V1L6538.D
Level: (TRACE/LOW/MED)	LOW			Date Received:	09/14/2010
% Moisture: not dec.			·	Date Analyzed:	09/14/2010
GC Column: DB-624	ID:	0.25	(mm)	Dilution Factor:	1.0
Soil Extract Volume:			(uL)	Soil Aliquot Vol	ume:(uL)
Purge Volume: 5.0			(mL)		

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) µG/L	Q
100-42-5	Styrene	1.0	Ū
	· · · · · · · · · · · · · · · · · · ·	1.0	Ū
	Isopropylbenzene	1.0	U
79-34-5	1,1,2,2-Tetrachloroethane	1.0	U
	1,3-Dichlorobenzene	1.0	U
	1,4-Dichlorobenzene	1.0	Ū
	1,2-Dichlorobenzene	1.0	Ū
96-12-8	1,2-Dibromo-3-chloropropane	1.0	ט
120-82-1	1,2,4-Trichlorobenzene	1.0	Ū
76-13-1	1,1,2-Trichloro-1,2,2-trifluoroethane	1.0	Ū
		1.0	U
79-20-9	Methyl acetate	1.0	Ü
108-87-2	Methylcyclohexane	1.0	Ū



* Wet Chemistry *

Mitkem Laboratories

Date: 15-Sep-10

Client: Ecology and Environment Engineering P.C.

Client Sample ID: INFLUENT

Lab ID: J1769-01

Project: Mr. C's Dry Cleaning

Collection Date: 09/13/10 13:00

Analyses	Result Qual	RL Units	DF Date Analyzed	Batch ID
SM 2340 HARDNESS by Calculation				SM2340_W
Hardness, Ca/Mg (As CaCO3)	480	4.0 mg/L CaCO3	1 09/15/2010 10:02	54094
SM 4500 H+ B pH VALUE				SM4500_H+
рН	6,9	1.0 S.U.	1 09/14/2010 15:30	R52077

Qualifiers:

ND - Not Detected at the Reporting Limit

J - Analyte detected below quantitation limits

B - Analyte detected in the associated Method Blank

DF - Dilution Factor

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

RL - Reporting Limit

Mitkem Laboratories

Date: 15-Sep-10

Client: Ecology and Environment Engineering P.C.

Client Sample ID: EFFLUENT

Lab ID: J1769-02

Project: Mr. C's Dry Cleaning

Collection Date: 09/13/10 13:15

Analyses		Result Qual	RL Units	DF Date Analyzed	Batch ID
SM 2340 HARDNESS by Calculation					SM2340_W
Hardness, Ca/Mg (As CaCO3)		490	4.0 mg/L CaCO3	1 09/15/2010 10:05	54094
SM 4500 H+ B pH VALUE	٠.			•	SM4500_H+
pH .	•	8.1	1.0 S.U.	1 09/14/2010 16:00	R52077

Qualifiers:

ND - Not Detected at the Reporting Limit

J - Analyte detected below quantitation limits

B - Analyte detected in the associated Method Blank

DF - Dilution Factor

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

RL - Reporting Limit

Attachment C Summary of Site Utility Costs and Projections January to December 2010

										-		
				•								
										t		
							0,001.79	-	oullines to pare	Craire Cia Cilines		
					-		0 624 70	\dashv	ქ	Crand Total		
							215.82	i en	Grand Lotal - Verizon Costs to Date	Grand Lotal - V		
\$ 30.83								\$ 33.34				
Ave./Month			Dec-2010	Nov-2010	Oct-2010	Sep-2010	Aug-2010	Jul-2010				
												716 652 0094 416 26 2
												Account#
			\$ 31.55	\$ 30,29	\$ 30.22	\$ 30.19	\$ 30.19	\$ 30.04	Mr. C's Telephone Costs	002700.DC13.02.01	716-652-0094	Verizon
		非特殊	Jun-2010	Маў-2010	Apr-2010	Mar-2010	Feb-2010	Jan-2010	Location Description	E&E Cost Center	Phone #	Utility Provider
		,						*				Phone
f billing	in red -adjusted billing	\$ 333.44	ading	Estimated Reading			8,415.97	\$	Grand Total - NYSE&G/National Fuel Gas Costs To Date	SE&G/National F	Grand Total - NY	
		no charges	Overbilled natural gas costs - no charges	Overbilled natu	Livering to the control of the contr		\$ 519,40	1	Natural Gas			
				-			\$7,896.57		Electric			
\$ 1,290.88		Carlo	4	ť	1	\$ 25.19	c7.6c0'l. ¢	\$/03.94	iotais			
			•			ļ	,	,	T : 1 - 1			
						\$ 25.19	8	\$8.73	Mr. C's Natural Gas Costs			
\$ 459.22							\$367.86		Agway Electric			
\$ 757.46							49	\$755.21	Mr. C's Electric Costs			
Ave. /Month			Dec-2010	Nov-2010	Oct-2010	Sep-2010	Aug-2010	Jul-2010				
			\$ 1,368.00	\$ 1,071.91	\$ 1,324.48	\$ 707.62	\$ 1,255.00	\$ 840.58	Totals			
				\$ 75.26		\$ 107.95	\$ 115.66	\$168.02	Mr. C's Natural Gas Costs	002700.DC13.02.01.	5819628-05	National Fuel Gas
			\$497.79		\$445.56		\$ 525.65		Agway Site - Electric		76-311-11-015900-18	New York State E&G
).21	\$ 870.21	\$ 996.65	\$ 878.92	\$ 599.67	\$ 613.69	\$672.56	Mr. C's Electric Costs	002700.DC13.02.01.	06-311-11-002616-26	New York State E&G
		訓練	Jun-2010	May-2010	Apr-2010	Mar-2010	Feb-2010	Jan-2010	Description	E&E Cost Center	Account #	Utility Provider
	\$27,060.00	Total:	J									Gas, Telephone, and Electric
	\$720.00	Gas			-						010 Report	September 2010 Report
	\$540.00	Telephone:							12 Months of System Operation and Maintenance	eration and	f System Op	12 Months of
	\$25,800.00	Electric:		Utility Budget:					2.01.01	ent #DC13.0	rk Assignme	NYSDEC Work Assignment #DC13.02.01.01
ATTACHMENT C	ATTA						S	ity Costs	Remedial Treatment Othity	- Kemediai	C S Dry Cleaners Site -	WIT. CS DIY
								1	Tunnahunnah		Yannama Cita	

Mr. Cs Dry Clean	Dry Cleaners Site - Remedial	al Treatment Utility Cost		Budget Remaining: Electric:	\$17,903.43		ATTACHMENT C
NYSDEC Work Assignment #DC13	signment #DC13						
12 Months of System Operation and Maintenance	tem Operation and	d Maintenance		Gas			
September 2010 Report	Report			Total:	\$18,428.21		
			.				
January-10	648 648 696 696	100.00%					
		100.00%		ttle rain in March			
		100.00%	-	RW- 1 pump			
		100.00%				-	
	!	100.00%		Problem with Pump PW-7			
		100.00%		ess for teardown and cleani			
	:	#DIV/0!					
November-10		#DIV/0!				· ·	
	6384 6336	99.25%					
*Percent Capacity is based on initial operating groundwater flows from the eight installed pumps from 9/02. Evaluated on total gallonsdischargedfor monthly operating time. Maximum pump discharges calculated as an average of 78 gpm as the total for all 8 pumps at the site if all pumps operate 100%. With the exception of groundwater pump RW-1, all others run on a batch basis.	ial operating groundwater flows fro ated as an average of 78 gpm as t	om the eight installed pumps from the signal the signal for all 8 pumps at the signal for all 8 pumps at the signal for the si	m 9/02. Evaluated on total gal	lonsdischargedfor monthly o	perating time.	s run on a batch basis	
Monthly Average Co	Costs						Total Gallons
							1000
Ш	757.46						
Agway Electric \$	459.22				,		
Mr. C's Telephone \$	30.83						
Ave. Utility Cost Total \$	1,321.71 times	12 month Estimate	\$17,182.23		-		
				. *			
				·.			
			٠.				