



New York Department of Environmental Conservation
Division of Environmental Remediation
Region 9 Office-Buffalo

FIELD INSPECTION REPORT

Date/Time: August 20, 2013
Site Name: Vanadium Corp, OU3
Site Number: 932001
Location: Town of Niagara, Niagara County
Project Engineer: Michael Hinton, NYSDEC - Buffalo
Contractor/Engineer: Sevenson/CRA

Weather Conditions:

Purpose of Inspection: Inspect removal of Site Activities

Discussions/Comments:

- No site progress meeting today.
- Sevenson has stripped the top soil from the borrow source area and are pushing up cover soils into a pile.
- Sevenson is removing soils at the north end of excavation limits in the low area. They anticipate placing the cover soil in this area this week.
- Sevenson is addressing the site drainage issues opening up the path for water to migrate from the NW corner to the SW corner.

Respectfully submitted: K. Glaser

Distribution: Michael Hinton, Region 9 DEC



Figure 1 Dust emissions from TTU 8/22/13