

**New York State Department of Environmental Conservation**

**Division of Environmental Remediation, Region 9**

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • Fax: (716) 851-7226

Website: [www.dec.ny.gov](http://www.dec.ny.gov)



Joe Martens  
Commissioner

## **INSPECTION REPORT**

**Site Number:** 932110

**Date:** February 12, 2014

**Site Name:** Vanadium Corporation of America

**Location:** 4201 Witmer Rd, Town of Niagara, Niagara County

**Project Manager:** Michael Hinton

**Project Engineer:** Obrien and Gere – Al Farrell/ Jim Bryck

**Contractor:** Severson Environmental Services

**Job Phone:** NA

**HEALTH & SAFETY:** Level C in work zone

### **DESCRIPTION OF WORK PERFORMED:**

MJH on site at 1045 hrs

Weather – T~10<sup>0</sup>F, partly cloudy, wind calm

Mike Welch provided information for Emergency waste Haulers permit.

SES grading SW corner of site and ditch along south side of OU#2. Excavated material being placed in Area 3 for subsequent covering with final site cover.

Advised Severson and OB&G of OU#2 SPDES out fall in SW corner of OU#2 site. Flow must not be impeded from OU#2. Observed area on OU#2 outfall and it looks good. Snow cover is present that makes exact determination impossible. Will re-check after area is completed and snow melts.

MJH left site at 1130 hrs.

**Attachments:** meeting summary

**Inspector's Name (Print):** Michael J Hinton

**Inspector's Signature:**

**Date:** February 12, 2014