

New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • **Fax:** (716) 851-7226

Website: www.dec.ny.gov



Joe Martens
Commissioner

INSPECTION REPORT

Site Number: 932110

Date: March 11, 2014

Site Name: Vanadium Corporation of America

Location: 4201 Witmer Rd, Town of Niagara, Niagara County

Project Manager: Michael Hinton

Project Engineer: Obrien and Gere – Al Farrell/ Jim Bryck

Contractor: Severson Environmental Services

Job Phone: NA

HEALTH & SAFETY: Level C in work zone

DESCRIPTION OF WORK PERFORMED:

MJH on site at 1135 hrs

Weather – T~46⁰F partly cloudy, wind SW @ 3 mph

No Job Progress Meeting – rescheduled to Friday march 14 at 10:30 AM

SES constructing western area island.

SES completed excavation of slag in approved NAPA area waiting for approval from NYPA to extend excavation.

MJH left site at 1215 hrs.

Attachments: photo's

Inspector's Name (Print): Michael J Hinton

Inspector's Signature:

Date: March 11, 2014



3112014-01 West Wetland Island.jpg



3112014-02 West Wetland Island.jpg



3112014-03 West Wetland Island.jpg



3112014-04 West Wetland Island.jpg



3112014-05 West Wetland Island.jpg



3112014-06 West Wetland Island.jpg



3112014-07 West Wetland Island.jpg



3112014-08 West Wetland Island.jpg