


New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • Fax: (716) 851-7226

Website: www.dec.ny.gov



Joe Martens
Commissioner

INSPECTION REPORT

Site Number: 932110

Date: May 27, 2014

Site Name: Vanadium Corporation of America

Location: 4201 Witmer Rd, Town of Niagara, Niagara County

Project Manager: Michael Hinton

Project Engineer: Obrien and Gere – Al Farrell/ Jim Bryck

Contractor: Severson Environmental Services

Job Phone: NA

HEALTH & SAFETY: Level C in work zone

DESCRIPTION OF WORK PERFORMED:

MJH on site at 1020 hrs

Weather – T~75°F, mostly cloudy, wind SSW @ 9 mph

Job Progress Meeting #34

Refer meeting summary prepared by OB&G for attendees and summary

Meeting 33 Summary Notes no issues

H&S – No issues

CAMP – meters deployed daily, no issues, expecting drying conditions, water truck ready

SWWP – no problem, Glynn continuing weekly inspections

Security – continued ATV activity?

Work Completed – Refer summary notes

Upcoming Work – Refer summary notes

NYPA – No answer on slag excavation or permit.

Nat Grid - Towers south of OU#1, south conductor to be removed. Grid soliciting bids will provide schedule. No response to tower corrosion problem at SE corner of OU2

Fence Grounding – Nat. Grid details to govern. SES needs coordinates for grounding requirements (start and end locations).

RFI #14 – East wet land on hold pending tower resolution

Hydro-seed – areas seeded last fall are not germinating as expected. SES to re-seed as necessary.

Next meeting June 2, 2014

Toured site – took photo's. No issues

MJH left site at 1145 hrs.

Attachments: meeting summary, photo's
Inspector's Name (Print): Michael J Hinton
Inspector's Signature:

Date: May 28, 2014

