

New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • Fax: (716) 851-7226

Website: www.dec.ny.gov



Joe Martens
Commissioner

INSPECTION REPORT

Site Number: 932110

Date: November 4 & 12, 2014

Site Name: Vanadium Corporation of America

Location: 4201 Witmer Rd, Town of Niagara, Niagara County

Project Manager: Michael Hinton

Project Engineer: Obrien and Gere – Al Farrell/ Jim Bryck

Contractor: Severson Environmental Services

Job Phone: NA

HEALTH & SAFETY: Level C in work zone

DESCRIPTION OF WORK PERFORMED:

November 4, 2014

MJH on site at 1020 hrs

GPS on site at 1030 hrs

Weather – T~58°F, cloudy & windy, wind SSW @ 20

Substantial Completion - FINAL Inspection

Representatives of DEC, OB&G, SES and CBI toured completed remedial project. No significant issues observed. Some minor restoration work required by GRID tower contractor.

OB&G to submit SMP and FER. Grid working on easement.

MJH left site at 1200 hrs.

November 12, 2014

MJH on site ~1200 hrs

OB&G – Jim Bruck

SES – Jack Bruckl and two laborers

Support zone trailers all removed.

Fence to remain

SES loading out the last of the equipment.

Jim Bryck to monitor Grid tower contractor restoration work. Final inspection to be made of Grid work at a later date. If weather prevents satisfactory completion, OB&G to write final restoration work into SMP for completion next year.

Attachments:

Inspector's Name (Print): Michael J Hinton

Inspector's Signature:

Date: November 18, 2014