

New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • Fax: (716) 851-7226

Website: www.dec.ny.gov



Joe Martens
Commissioner

INSPECTION REPORT

Site Number: 932001

Date: May 29, 2015

Site Name: Vanadium Corporation of America

Location: 4201 Witmer Rd, Town of Niagara, Niagara County

Project Manager: Michael Hinton

Project Engineer: Obrien and Gere – Al Farrell/ Jim Bryck

Contractor: Severson Environmental

Services

Job Phone: NA

HEALTH & SAFETY: NA

DESCRIPTION OF WORK PERFORMED:

MJH on site at 0855 hrs

Weather – T~80°F, overcast, wind SW @ 10

Inspected site to evaluate how the wetland plantings are fairing

OB&G –Jim Bryck, Kyle _____ (wetland professional)

Severson – Frank Constiglione, Mike Welch

Kyle thoroughly inspected wetland plantings on all three Islands. The two eastern islands have problems with lack of growth. Very little of the wetlands plantings have sprouted. The button bushes have about a 75-80% survival. Area desperately needs rain to help the plants.

The western island is in good shape. Wetlands plantings are well established and the button bushes are >85% taken hold.

Recommend replanting of the eastern islands in late August and will reinspect in October 2015.

MJH left site at 1110 hrs.

Attachments: photos

Inspector's Name (Print): Michael J Hinton

Inspector's Signature:

Date: June 1, 2015



