



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

Site Name: Hyde Park Landfill		Class: 2	Number: 932021
O&M Funding Source: <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party			
O&M Information: O&M Start: 1979		End: Present	Annual Cost: \$ <input type="checkbox"/> Estimated
Interim Remedial Measures/Operable Units in O&M Phase:			
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal	
<input checked="" type="checkbox"/> Cap/Cover	<input checked="" type="checkbox"/> Containment Structure	<input checked="" type="checkbox"/> Fence/Security	
<input checked="" type="checkbox"/> Groundwater Recovery/Treatment	<input checked="" type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment	
<input type="checkbox"/> Air Sparging/Stripper System	<input checked="" type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System	
<input type="checkbox"/> Other:			
Institutional Controls: <input type="checkbox"/> Deed Restriction <input type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling			
<input type="checkbox"/> Other:			
O&M Review Information:			
Reports: 2 nd Quarter 2000 report by Glen Springs Holding Inc. 2/2000			
Inspection: 1/2001			
Sampling: 3/2001 all bedrock groundwater monitoring wells			
Other:			
Conclusions:			
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: explain: _____			
ROD Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: explain: N/A			
Consent Order Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: explain: _____			
Other:			
Recommendations: Continue O&M and refine bedrock groundwater control.			
ROD/Consent Order Modifications? <input type="checkbox"/> No <input type="checkbox"/> Yes (per above)		Reclassify the Site? <input type="checkbox"/> No <input type="checkbox"/> Yes → Class:	
Comments: Groundwater modeling recently done. Now in discussions with PRP on future activities at site.			
A Remedial Alternatives Report is due from the PRP in March 2001			
Project Manager:		Reviewer:	
			
Signature		Signature	
3/15/01		3/16/01	
Date		Date	
Gerald Pietraszek Region 9			
716/851-7220			
Name Region or Bureau Telephone		Name Region or Bureau Telephone	