## New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York, 14203-2999

Phone: (716) 851-7220 FAX: (716) 851-7226



## MEMORANDUM

Non-Releasable

To:

Will Welling - Albany

From:

Brian Sadowski - Buffalo Men Moderki Hooker 102<sup>nd</sup> St. Landfill - Registry #932022

Subject:

Olin 102<sup>nd</sup> St. Landfill - Registry #932031

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Date:

November 27, 2002

Please find attached, the initial O&M review report for the Hooker 102<sup>nd</sup> St. Landfill Site and Olin 102<sup>nd</sup> St. Landfill Site. Should you have any questions, contact Abul Barkat or me at (716) 851-7220. Thank you.

BPS/tml Attachment

cc:

Daniel King, Division of Environmental Remediation, Buffalo, w/o att. Abul Barkat, Division of Environmental Remediation, Buffalo, w/o att. Gerald Rider, Division of Environmental Remediation, Albany, w/o att.

## NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

## Inactive Hazardous Waste Site Operations and Maintenance Review Report

			Form Date 96.10.
Site Name: Hooker 102 St. Landfill/Olin 102 St.	Landfill Class: 4	Number:	932022/31
O&M Funding Source: ☐ State Superfu	nd D Federal Superfund	☐ Municipal ■ Res	sponsible Party
O&M Information: Start: March 9, 1999	End: Continuing	Annual	Cost: N/A
Interim Remedial Measures/Operable Units in	1 O&M Phase:		
□ Drum Removal	□ Soil Removal	☐ Tank f	Removal
■ Cap/Cover	■ Containment Structu		•
Groundwater Recovery/Treatment	☐ Leachate Collection	•	Extraction/Treatment
☐ Air Sparging/Stripper System ■ Other: DNAPL Recovery and extraction wells.	☐ Treatment/Filtration	•	e Water Supply/System
Institutional Controls: ■ Deed Restriction (U			pling □ Other:
management controls.	.0. 001150111 5001007 🗀 5100	margo r omme 🗀 🖰 om oan	pining 2 outlon
O&M Review Information:		•	
Reports: Quarterly monitoring well data. Weekl	v and monthly pumping data.	Annual embayment vegeta	tive habitat data.
Inspection: Conducted and reported as required	by approved O&M Plan.		{
Sampling: Quarterly for monitoring wells.			}
DNAPL Recovery Wells: Quarterly level monitor	ing.		1
Conclusions:		· · · · · · · · · · · · · · · · · · ·	
		,	'
Remedy Effective? ■ Yes □ No			
ROD Compliance? ■ Yes □ No □ Not A			
Consent Order Compliance? ■ Yes □ No □ Not Applicable.			
Other: None			
Recommendations:			
Continue monitoring of the groundwater recover			
subsequent treatment at the Love Canal Leacha			
from monitoring wells. Monitor quantity of DNAF cap, security fence, crib wall and other facilities			
ROD/Consent Order Modifications? ■ No □	Yes (per above)	classify the Site? ■ No	☐ Yes → Class:
Comments:			
Completion of the Remedial Action was certified	on January 14, 2002. Accord	dingly, the site officially wen	t into the O&M Phase.
Document co-written by Brian P. Sadowski and A	Abul Barkat	day 1/2 1/24/8	2
	~ was /- XI	Succession 1. 4.	
Project Manager:	1 Re	eviewer: Danger	
Date: 1/12/102	D	ate: 11/26/02	
Region or Bureau Telephone	- 1 - 7 - 7 - Besies -	or Burnou	elephone
BUFFALO Telephone 716/8	751- 7220 Hegion of Dec.		851-722C