

**New York State - Department of Environmental Conservation
Division of Environmental Remediation
Periodic Review Evaluation Report**

Period covered by -- 2006-07

Site Code: 932022	Site Name: Hooker-102nd Street Landfill	Class: 04
Program Lead: State Superfund Program	Site Management Funding Source: Responsible Party (RP)	
Start Date: 04/01/2004	ACT	
IC/EC Certification:	Received Date:	Accept Date:
DEC Inspection Date: 05/31/2006	--- Last Date of DEC Inspection	
Report Used for Evaluation: Site Management, Longterm Monitoring, Inspection		
ROD Complicance? Yes		
Long Term Monitoring (effectiveness of remedy): Yes	Frequency:	
Treatment System (Monitoring performance of remedy): No	Frequency:	Number of Wells: 13
Problem Status:		
Comments/Changes/Attachments:		
<p>This site was found in excellent condition during the walkover on May 31st 2006. All pumps, pump vaults, collection system and related PLC (process logic controls) units are operational and effective. Collected leachate continues to be automatically discharged and treated at Love Canal. The gallonage is approximately 400K/yr. The cap is in good condition. Habitat programs are in place w/delayed mowing, bat and bird houses and lancer pea and wildflower plantings. River debris continues to obstruct the outfall due to the embayment configuration, river water direction and prevailing winds. The debris is cleared by OXY as necessary. The integrity of the perimeter fence and gates, are good. There were no breaches. NAPL recovery well NR-2 continues to produce. The total gallonage recovered to date from 2001 is approxiametely 37K. Some site indicator chemicals are above GW stds. at wells PCM 03, 04 and 05. The trends are consistent and not increasing.</p>		
ROD/Consent Order Modifications? No		
Site reclassification recommended:		
Contaminant of concern	OU	Media/Receptor
ORGANIC PHOSPHITES, SODIUM	01	
HYPOPHOSPHITE, INORGANIC PHOSPHATES,	01	
BHC CAKE (INCLUDES LINDANE), CHLOROBENZENES,	01	
MISC. CHLORINATED ORGANICS, BRINE SLUDGE, AND	01	
GYPSUM	01	
Evaluation: The Remedy is performing properly and is effective.		

Next Review:	Priority: 01
Project Manager: BPSADOWS	Reviewer: Sutton, Greg
Signature: _____	Signature: _____
Date: _____	Date: _____
Name _____	Name _____
Region or Bureau _____	Region or Bureau _____
Telephone _____	Telephone _____

**New York State - Department of Environmental Conservation
 Division of Environmental Remediation
Periodic Review Evaluation Report**

Remedies	OU	Site of Treatment	Date in Place	Remedy Effective
6 NYCRR Part 360 Cap	01	XX		Ongoing
Slurry Wall	01	XX		Ongoing
Plume Management Monitoring	01	XX		Ongoing
Other	01	XX		Ongoing

Next Review:			Priority: 01		
Project Manager: BPSADOWS			Reviewer: Sutton, Greg		
Signature:		Date:	Signature:		Date:
Name	Region or Bureau	Telephone	Name	Region or Bureau	Telephone