

<b>Site Name:</b> Hooker 102 St. Landfill/Olin 102' St. Landfill		<b>Class:</b> 4	<b>Number:</b> 932022/31
<b>O&amp;M Funding Source:</b> <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party			
<b>O&amp;M Information:</b> Start: March 9, 1999		End: Continuing	Annual Cost: N/A
<b>Interim Remedial Measures/Operable Units in O&amp;M Phase:</b>			
<input type="checkbox"/> Drum Removal		<input type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal
<input checked="" type="checkbox"/> Cap/Cover		<input checked="" type="checkbox"/> Containment Structure	<input checked="" type="checkbox"/> Fence/Security
<input checked="" type="checkbox"/> Groundwater Recovery/Treatment		<input type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment
<input type="checkbox"/> Air Sparging/Stripper System		<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System
<input checked="" type="checkbox"/> Other: DNAPL Recovery and extraction wells. Manual pump out necessary.			
<b>Institutional Controls:</b> <input checked="" type="checkbox"/> Deed Restriction (U.S. Consent Decree) <input type="checkbox"/> Discharge Permit <input type="checkbox"/> DOH Sampling <input type="checkbox"/> Other:			
<b>O&amp;M Review Information:</b>			
<u>Reports: Quarterly monitoring well data. Weekly and monthly pumping data. Annual embayment vegetative habitat data.</u>			
<u>Inspection: Conducted and reported as required by approved O&amp;M Plan.</u>			
<u>Sampling: Quarterly for monitoring wells.</u>			
<u>DNAPL Recovery Wells: Quarterly level monitoring.</u>			
<b>Conclusions:</b>			
<u>Remedy Effective?</u> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
<u>ROD Compliance?</u> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Applicable			
<u>Consent Order Compliance?</u> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Applicable.			
<u>Other: None</u>			
<b>Recommendations:</b>			
<u>Continue monitoring of the groundwater recovery and discharge system to pump chamber 3 at the Love Canal site and subsequent treatment at the Love Canal Leachate Treatment Facility. Monitor groundwater levels and quarterly analytical results from monitoring wells. Monitor quantity of DNAPL collected and waste disposal practices from extraction wells. Inspect the landfill cap, security fence, crib wall and other facilities at the site. Monitor coverage of vegetation on the cap and embayment area.</u>			
<u>ROD/Consent Order Modifications?</u> <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above)		<u>Reclassify the Site?</u> <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class:	
<b>Comments:</b>			
<u>Completion of the Remedial Action was certified on January 14, 2002. Accordingly, the site officially went into the O&amp;M Phase.</u>			
Document co-written by Brian P. Sadowski and Abul Barkat <i>Brian P. Sadowski 11/26/02</i>			
<b>Project Manager:</b> <i>Cume Kent</i>		<b>Reviewer:</b> <i>Danting</i>	
<b>Date:</b> <i>11/26/02</i>		<b>Date:</b> <i>11/26/02</i>	
<b>Region or Bureau</b> BUFFALO	<b>Telephone</b> <i>(716) 851-7220</i>	<b>Region or Bureau</b> PER-9N	<b>Telephone</b> <i>716/851-7226</i>