

New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • **Fax:** (716) 851-7226

Website: www.dec.ny.gov



Joe Martens
Commissioner

INSPECTION REPORT

Site Number: 932043

Date: July 18, 2011

Site Name: Frontier Pendleton

Location: Townline Road, North Tonawada N.Y.

Project Engineer: Greg Sutton

Site Management: Brian Sadowski

RP: Olin **PM:** Curt Richards **Phone:** 423-336-4007

Environmental Consultant: Severson Environmental **PM:** Mike Walker

Phone: 716-583-4460

Site Operator: Mike Walker

Weather: Sunny, hot and dry.

Job Phone: N/A

HEALTH & SAFETY: Level D

PURPOSE OF VISIT: Annual Inspection

DESCRIPTION OF WORK PERFORMED:

Toured and inspected the site and treatment system. All Institutional and Engineering control components of the remedial system were in place and effective. There were no observations out of the ordinary or cause for concern.

Inspector's Name (Print): Brian Sadowski

Inspector's Signature:

Date: July 20, 2011

Attachments: Photos

ec: Gregory P. Sutton, RHWE, Buffalo
edocs



Bag&Carbon Filters



Cap Slope



Cap Vegetation



Cap-East



Cap-NE



Cap-SW



Flow Meters



MW-88-12D



Quarry Lake 1



Quarry Lake 2



Res. Proximity



Site Fence-typical



Treatment Electronics



Treatment Vault



Woodchuck Burrow