



## **SITE INSPECTION REPORT**

**Site Name:** Niagara Sanitation Company

**Site Number:** 932054

**Location:** Nash Road, Wheatfield, NY

**Inspection Date:** 1/2/2025

**NYSDEC Project Manager:** Glenn May

**Weather Conditions:** Sunny, 23°F

**Personnel Onsite:** 2 technicians (Texas Brine Company)

**Description of Work Performed:** Inspection

**Details:**

NYSDEC arrived in area between 50 Forbes Terrace North Tonawanda, NY and Site perimeter fence to find 2 technicians, transport van and a backhoe onsite. The 2 workers identified themselves as employees of Texas Brine Company and explained that they performed an excavation to repair associated Brine lines just outside of the site perimeter. Observed physical disturbance had been restored to grade. Four sections of chain-link fencing had been removed but no evidence of excavation inside the site was observed. The fence was being re-installed.

**Inspector:** Bradley Demo

**Signature:** *Bradley W. Demo*

**Attachments:** Photolog

## Site Inspection Report

Niagara Sanitation (Site No. 932054)

January 2, 2025

Page 2

### Photolog:



Ruts leading to work area.

## Site Inspection Report

Niagara Sanitation (Site No. 932054)

January 2, 2025

Page 3



Backhoe onsite.

## Site Inspection Report

Niagara Sanitation (Site No. 932054)

January 2, 2025

Page 4



Area of disturbance.

## Site Inspection Report

Niagara Sanitation (Site No. 932054)

January 2, 2025

Page 5



Area of disturbance, alt view.