

NYSDEC

Central Office

Division of Environmental Remediation

Site: Solvent Chemical

Phase: Management

Site No.: 932096

Contractor PM:

NYSDEC PM: Bradley Demo

Construction Manager:

Project Engineers:

Remedial Contractor: TRC/Camtech

Air Monitoring:

Health &amp; Safety:

**Weather Conditions**

General Description	Sunny	am	pm
Temperature		am	pm
Wind Direction		am	pm

**HEALTH & SAFETY:**

(\*If any box(s) below are checked "Yes", list the deviation under the "Items for Concern" section of this report).

Were there any changes to the Health & Safety Plan?	*Yes ( )	No ( )	NA (x)
Were there any exceedances at the perimeter action level reported on this date?	Air: *Yes ( )	No ( )	NA (x)
Were there any Noise /Vibration exceedances reported on this date?	Noise: *Yes ( )	No ( )	NA (x)
	Vibration: *Yes ( )	No ( )	NA (x)
Were there any breaches to the tent structure or silt fence reported/observed on this date?	*Yes ( )	No (x)	NA ( )
Were there any dust/odor issues reported or observed on this date?	*Yes ( )	No (x)	NA ( )

**WASTE HAULING :**

(\*If any box(s) below are checked "Yes", list the deviation under the "Items of Concern" section of this report).

Were there any vehicles which did not display proper D.O.T numbers and placards?	*Yes ( )	No ( )	NA (x)
Were there any vehicles which were not lined or tarped?	*Yes ( )	No ( )	NA (x)
Were there any vehicles which were not decontaminated prior to exiting the work site?	* Yes ( )	No ( )	NA (x)

**Materials Removed From Site: N/A****Disposal Facility:**

Total Loads: (on this date)

Total Loads: (to date)

Total Daily Weight: (est.)

Total Weight: (\*approx.)

**\*Actual (total weight) adjusted periodically based on weight tickets submitted by the disposal facilities.****Summary of Events:**

- NYSDEC onsite to observe semiannual sampling/inspection with Camtech and TRC.
- TRC noted wells are sampled via 6-month placement of passive diffusion bags (PDB) so those placed on this date will be removed in the fall. Noted all wells were gauged without issue except for obstruction or pinching in 18B.
- No deficiencies were noted with groundwater treatment system or SSDS although a manometer may still need to be installed. A couple bare spots were noted in southern end of cover system that should be monitored for revegetation during growing season.

**VISITORS TO SITE:**

NAME	Representing	Entered Exclusion/CRZ Zone	
Chris Rudzinski, John	TRC	Yes (x)	No ()
1 technician	Camtech	Yes (x)	No ()
		Yes ()	No ()
		Yes ()	No ()

**PROJECT SCHEDULE:**

- 

**ISSUES PENDING:**

- 

**ITEMS OF CONCERN:**

-

## DAILY OBSERVATION REPORT: 3/19/2025

---

Page 3 of 12

---

Inspector: Bradley Demo

Signature: *Bradley W. Demo*

Date: 03/19/2025



Inside of pumping well 7B (PW-7B).





Inside of trench well 1A (TW-1A).





Cover system facing S.





Collection trench/site cover conditions facing S.





Central site cover conditions facing S.





Manhole/central site cover conditions facing NE.





Ruts/bare spots in cover to be monitored for regrowth, view facing N/NW.





Ruts/bare spot in southern area of cover to be monitored for regrowth, facing NE.





Monitoring well cluster with probable decommissioned wells/cut off casings.