



August 12, 2008

Michael J. Hinton, P.E.
Division of Environmental Remediation
New York State Department of Environmental Conservation
270 Michigan Avenue
Buffalo, NY 14203-2999

**Subject: 2008 July Site Inspection Report
Booth Oil Site
North Tonawanda, New York
NYSDEC Site No. 9-32-100**

Dear Mr. Hinton:

On behalf of the Booth Oil Site Administrative Group (BOSAG), AMEC Earth and Environmental, Inc. (AMEC) presents this *Annual Site Inspection Report* for the above referenced site (**Figure 1**). The Site Inspection was performed on July 10, 2008. The following sections of this report discuss the observations and activities completed during the Inspection event.

SITE SURFACE CONDITIONS

A visual inspection of the site including surface conditions and its surroundings was conducted on July 10, 2008. No significant signs of erosion were noted, and the grass was well maintained. The drainage ditch that runs along the outskirts of the site has been cleaned and remains free of debris. There also weren't any neighboring encroachments noted at the time of the site inspection. There consistently have been no signs of extensive erosion during recent site inspections, therefore as of this current site visit new erosion control is not recommended. A photographic log of the site conditions is included as **Attachment 1**.

SUMMARY

In general, the Site appeared well maintained. Now that the wells have been decommissioned, the only site activities that will continue are mowing of the grass in the summer months, which is part of the site maintenance. The first of two annual site inspections has been completed; the next and final inspection will be conducted July 2009.

Should you have any questions or comments concerning this report, please contact Jeff LaRock or myself at (518) 372-0905 or by e-mail at Jeffrey.larock@amec.com or howard.miller@amec.com.

Sincerely,
AMEC Earth and Environmental Inc.




Howard G. Miller
Environmental Engineer



Jeffrey W. LaRock
Project Manager

cc: BOSAG Steering Committee
BOSAG Technical Committee
Paul J. Kurzanski, CSXT
Matthew J. Forcucci, NYSDOH

FIGURES



**Public Safety
& Environment**

**Booth Oil Site
88 Robinson Street
North Tonawanda, NY
Site Location Map**

Niagara County New York

LOCATOR



NOTES & SOURCES

Quadrangle Name: Tonawanda East NY
Map Source Date: 1 July 1995
Source: USGS
Projection: NAD 83 UTM Zone 17N
Map Created: 4 May 2005

0 2,000
Feet



AMEC Earth & Environmental, Inc.
Westford, Massachusetts

FIGURE

1

ATTACHMENTS



Photo 1

Facing northeast looking across the site.



Photo 2

Looking west along Robinson Street. A pile of removed ties was noted along Robinson Street.



155 Erie Blvd. Edison Plaza
Schenectady, New York 12305

W.O. 64300-8554
PROCESSED: HGM
DATE: July 2008
PAGE 1

Booth Oil Site
North Tonawanda, NY
CSX Transportation, Inc.
Jacksonville, FL



Photo 3

View of the drainage ditch looking east along the tracks.



Photo 4

View of the drainage ditch facing southwest following the tracks.



155 Erie Blvd. Edison Plaza
Schenectady, New York 12305

W.O. 64300-8554
PROCESSED: HGM
DATE: July 2008
PAGE 2

Booth Oil Site
North Tonawanda, NY
CSX Transportation, Inc.
Jacksonville, FL



Photo 5

Facing southwest
looking at drainage
area free of debris.



Photo 6

Facing west looking
across the site.



155 Erie Blvd. Edison Plaza
Schenectady, New York 12305

W.O. 64300-8554
PROCESSED: HGM
DATE: July 2008
PAGE 3

Booth Oil Site
North Tonawanda, NY
CSX Transportation, Inc.
Jacksonville, FL