

## PROFILE REPORT

APR 0 6 2007

# SOUTH NIAGARA STREET QUARRY SITE

## BY NIAGARA COUNTY HEALTH DEPARTMENT JUNE, 1993

## Site Description

The South Niagara Street Quarry Site is located in the City of Lockport. A site location map is found in Appendix A. The site is bounded by South Niagara Street on the north, junkyard property on the east and south, and Somerset Railroad tracks on the west.

The property is currently owned by the City of Lockport and is being used as a City of Lockport storage area for wood debris, fencing material and miscellaneous junk.

## Site Inspection

The site was initially discovered April 14, 1993 during a routine inspection of the Lockport City Landfill. Evidence of ash, glass debris is noted along the western side cut due to the Somerset Railroad. A visible leachate stain was flowing from the toe of the slope to an adjacent ditch which drained under the Somerset tracks and discharged into the Gulf Creek ravine.

#### Previous Investigations

This department is unaware of any previous investigations of this site. Due to the grading of the side slope along the Somerset tracks, it appears that the end of the landfill was excavated and graded during the construction of the Somerset Railroad in the mid 1980's.

Interpretation of aerial photographs is limited as site activity could be quarry activity or landfilling activity.

## **Exposure Potential**

Exposure to contaminants at the site are possible through contact with the exposed waste or leachate. The leachate discharges to Gulf Creek, a tributary of Eighteen Mile Creek. Odors were not evident at the site.

### Operation History

The site was reportedly first operated as a quarry. A rock cut is clearly visible along the southwest corner of the site. It appears the site was brought back to original grade through landfill of municipal debris. Industrial use is unknown. It is suspected that the City of Lockport operated the site in or around the time of operation of the Old Upper Mountain Road Site or the City of Lockport Landfill.

## Recommendations


The site is in need of a thorough investigation so that a better determination as to the significance of the site can be made. If operation of this site was similar to the City of Lockport Landfill, hazardous wastes might be expected.


As a minimum, the site is in need of a proper 360 closure to prevent offsite migration of leachate.


Recommended field activities should include surveying and mapping, waste samples, leachate samples, and a geophysical survey to help establish the extent of fill at the site.


# Appendix A Contents

<u>Page</u>	<u>Description</u>
A-1	U.S.G.S. Topographic Map
A-2	City of Lockport Tax Map
A-3	1991 Aerial Photograph
A-4	Niagara County Health Department sketch
A-5	Photographs
A-6	Photographs









PAGE A-4 SOUTH NIAGARA QUARRY SITE + SOMERSET RAIL ROA SITE SKETCH ENTRANCE NIAGARA COUNTY HEALTH DEPARTMENT TO CITY OF Lockfort Landfill TOP OF ESCARPMENT NIAGARA Street DEAD ASSORTED WOOD FENLE VISIBLE TE A PRINCHEMAN DEBRIS JUNY YARD ET #5005) ENGANKMENT PIZCH NOT AREA OF Dump scale DRAWN By Paul Dicky 5-7-93 NIAGARA C. J 11-1167-1

PAGE A-5 SOUTH NIAGARA QUARRY SITE SITE PHOTOGRAPHS

NIAGARA COUNTY HEALTH DEPARTMENT



DITCH - EXPOSED WASTE VISIBLE DUE TO ANIMAL BURROWING




BOTTOM OF DITCH STUREN GRATE - BOTTOM OF DITCH Schween LAND ELLEGAN

PAGE A-6 SOUTH NIAGARA QUARRY SITE SITE PHOTOGRAPHS

NIAGARA COUNTY HEALTH DEPARTMENT




TOP OF LANDFILL USED BY CITY OF LOCKPORT FOR STORAGE



VIEW OF BITCH RECEIVED

PAGE A-7 SOUTH NIAGARA ROAD QUARRY SITE SITE PHOTOGRAH

NIAGARA COUNTY HEALTH DEPARTMENT



STERM CRATING (IN OTHER PHOTO) DISCHARGES
HERE - WEST SIDE OF RAILROAD TRACKS-