

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF HAZARDOUS WASTE REMEDIATION  
INSPECTOR'S DAILY REPORT

Site Code No. ALBANY COUNTY (GENERAL FILE)

Date JULY 11, 1991 I.R. No. 2

Site Name: DELAWARE AND HUDSON RAILROAD

Sheet 1 of 2

Location: MAINTENANCE SHOP  
WATER VALLET (V), ALBANY CO.

Engineer: GUILFORD TRANSPORTATION INDUSTRIES

	AM	PM
Weather	<u>PARTLY CLOUDY</u>	<u>PARTLY CLOUDY</u>
Temperature	<u>60°F</u>	<u>80°F</u>
Wind (Dir. & Vel.)	<u>0-5 WNW</u>	<u>0-5 N-NW</u>

Contractor: WEST CENTRAL ENVIRONMENTAL

Job Phone: (518) 272-6891

Health & Safety:

Level of protective clothing used: CEO

Is the level of protection in conformance with the approved Health & Safety Plan?

Yes     No     If no, list the deviations under Items of Concern. - NO WORK PLAN SUBMITTED

Are atmospheric monitoring results at acceptable levels? Yes    No   

Attach a copy of the monitoring log.

Description of work performed during this report period:

A) PUMPING OIL FROM DRUMS AT NORTHEAST SIDE OF MAINTENANCE BUILDING (OUTSIDE) AND EXCAVATING OIL CONTAMINATED SOILS.

B.) OUCH PACKING AND SAMPLING ORANGE, YELLOW POWDERED CHEMICAL IN PAPER DRUMS FOUND OUTSIDE BY OIL DRUMS.

C.) FINISHING SAMPLING OF DRUMS INSIDE MAINTENANCE BUILDING.

Site Visitors \_\_\_\_\_ Representing \_\_\_\_\_ Entered exclusion zone \_\_\_\_\_

TIM CATELLA CHIEF ENGINEER - GUILFORD TRANSPORTATION,

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
 DIVISION OF HAZARDOUS WASTE REMEDIATION  
 INSPECTOR'S DAILY REPORT



Subcontractor A: \_\_\_\_\_ worked from \_\_\_\_\_ to \_\_\_\_\_  
 Subcontractor B: \_\_\_\_\_ worked from \_\_\_\_\_ to \_\_\_\_\_

Contractors' Equipment	Prime	A	B	Not Used		Work Force	Prime	A	B
TRACTOR - MACK	✓					FOREMAN	✓		
2- DUMP TRAILER	✓					OPERATOR	✓		
LOWBOY TRAILER	✓					TRUCK DRIVER	✓		
TRACKED EXCAVATOR	✓					2- TECHNICIANS	✓		
UTILITY TRUCK	✓								
2- PICKUPS	✓								

Prime Contractor worked from 8:00 AM to 5:00 PM

Comments:  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Items of concern: SOIL CONTAINING OIL SPILLED TAKEN DOWN TO 1' DEPTH WITH EXCAVATOR AND LACK PROBLEM WITH OIL IN SOIL FOUND. Russ SHAWER CONTACTED AL GIESENDORFER OF NYS DEU SPILL RESPONSE. AL TO MEET WITH WEST CENTRAL ON MONDAY JULY 15, 1991 TO DISCUSS FURTHER REMOVAL OPERATIONS.

Attachments to this report:  
 \_\_\_\_\_  
 \_\_\_\_\_

Inspector's Name (Print): RUSSELL R SHAWER  
 Inspector's Signature: Russell R Shawer Date: 7-11-91  
 Reviewed by: \_\_\_\_\_ Date: \_\_\_\_\_