



**Department of
Environmental
Conservation**

Division of Environmental Remediation
Central Office

DAILY INSPECTION REPORT

Site Code #: B-00-184	Date: 12/01/2015	Report #: 06
------------------------------	-------------------------	---------------------

Site Name: Fosters Refrigeration
Location: City of Hudson, Columbia Co.
DEC Proj. Mgr.: Michael Mason
Contractor: Precision Environmental
Contractor Proj. Mgr.: Steve Phelps

	AM	PM
Weather	Cloudy	Cloudy
Temperature	32	42
Wind Direction	West	West

Description of work performed by contractor this report period:

Dan's Hauling and Demolition (Sub):

- Building debris, primarily concrete block was loaded into 30yd trailers and disposed of at the Albany Landfill. All debris considered asbestos containing material. 2 trailer loads total, approximately 60 tons.

Ambient Environmental (Asbestos Monitor):

- Asbestos Monitor, Jim Edge on site during working hours

Discussions/comments regarding visitors, contractor and/or engineer:

- All onsite structures have been demolished

Change Orders:

Sampling and Analyses:

Major Issues	Description & Reason

Health & Safety:

Level of protection: C

Is the level of protection in conformance with the approved Health & Safety Plan? Yes

List deviations: None

Are atmospheric monitoring results acceptable? Yes

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Contractor Hours 7:00am – 3:30pm (estimated end time)

Subcontractor	Activity	Hours Worked
(1) Dan's	Building Demo	8

Equipment	P	1	2	3	4	Personnel	P	1	2	3	4
Excavator/Hyundai		1				Foreman/Operator		1			
Utility Truck		1				Operator		1			
Decon Trailer		1									
Semi w/trailer		1									

Site Representative: Kristopher Keenan

Date: 12/01/2015

Representative's Signature:



Photo Log



Loading trailer with building debris



Loading trailer with building debris