



**Department of  
Environmental  
Conservation**

Division of Environmental Remediation  
Central Office

### **DAILY INSPECTION REPORT**

<b>Site Code #:</b> B-00-184	<b>Date:</b> 12/17/2015	<b>Report #:</b> 07
------------------------------	-------------------------	---------------------

**Site Name:** Fosters Refrigeration  
**Location:** City of Hudson, Columbia Co.  
**DEC Proj. Mgr.:** Michael Mason  
**Contractor:** Precision Environmental  
**Contractor Proj. Mgr.:** Steve Phelps

	<b>AM</b>	<b>PM</b>
<b>Weather</b>	Rain	Rain
<b>Temperature</b>	40	45
<b>Wind Direction</b>	West	West

**Description of work performed by contractor this report period:**

Precision Environmental:

- Trees, brush and vines were cleared at the north end of the site between the concrete slab and perimeter fence. Trees, brush and vines were chipped and stockpiled at the north end of the slab.

**Discussions/comments regarding visitors, contractor and/or engineer:**

**Change Orders:**

**Sampling and Analyses:**

Major Issues	Description & Reason

**Health & Safety:**

Level of protection: D

Is the level of protection in conformance with the approved Health & Safety Plan? Yes

List deviations: None

Are atmospheric monitoring results acceptable? NA

Site Visitors	Representing	Entered Exclusion Zone

**Contractor's Information:**

Contractor Hours 7:00am – 3:30pm

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	4	Personnel	P	1	2	3	4
Excavator/Takeuchi TB153	1					Operator	1				
Chipper/Morebark	1					Laborer	2				
Pick Up/Ford F250	1										
						Operator	1 (2.5 hrs)				
						Laborer	1 (2.5 hrs)				

Site Representative: Kristopher Keenan

Date: 12/17/2015

Representative's Signature:



## Photo Log



**Transporting brush and vines to chipper**



**Running tree through chipper**



**Removing vines from NE corner of site**



**Cutting stump to ground level**