



**Department of
Environmental
Conservation**

Division of Environmental Remediation
Central Office

DAILY INSPECTION REPORT

Site Code #: B-00-184	Date: 12/21/2015	Report #: 08
------------------------------	-------------------------	---------------------

Site Name: Fosters Refrigeration
Location: City of Hudson, Columbia Co.
DEC Proj. Mgr.: Michael Mason
Contractor: Precision Environmental
Contractor Proj. Mgr.: Steve Phelps

	AM	PM
Weather	Cloudy	Cloudy
Temperature	30	40
Wind Direction	West	West

Description of work performed by contractor this report period:

Precision Environmental:

- Trees, brush and vines were cleared at the east end of the site between the concrete slab and perimeter fence. Trees, brush and vines were chipped and stockpiled at the north end of the slab.
- Wood chips were spread on the access road at the south end of the site

Discussions/comments regarding visitors, contractor and/or engineer:

- Two piles of wood chips remain on the concrete slab at the north end of the site.
Approximately 30-40 cy.

Change Orders:

Sampling and Analyses:

Major Issues	Description & Reason

Health & Safety:

Level of protection: D

Is the level of protection in conformance with the approved Health & Safety Plan? Yes

List deviations: None

Are atmospheric monitoring results acceptable? NA

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Contractor Hours 7:00am – 3:30pm

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	4	Personnel	P	1	2	3	4
Excavator/Takeuchi TB153	1					Operator	2				
Chipper/Morebark	1					Laborer					
Pick Up/Ford F250	1										
Skid Steer/Bobcat863	1										
Equip. Trailer	1										

Site Representative: Kristopher Keenan

Date: 12/21/2015

Representative's Signature:



Photo Log



Transporting trees to chipper



Spreading wood chips on access road



Chip pile remaining on concrete slab



Chip pile remaining on concrete slab