


**New York State Department of Environmental Conservation  
Division of Environmental Remediation**

**Remedial Bureau C, 11th Floor**

625 Broadway, Albany, New York 12233-7014

**Phone:** (518) 402-9662 • **FAX:** (518) 402-9679

**Website:** www.dec.ny.gov



**DAILY INSPECTION REPORT**

<b>Site Code #:</b> B00190	<b>Date:</b> May 7, 2010	<b>Report #:</b> 2010-05-07.JPC
----------------------------	--------------------------	---------------------------------

**Site Name:** Hudson River Waterfront/DeLaval Property  
**Location:** Pine Street & Rinaldi Blvd, City of Poughkeepsie, Dutchess Co.  
**DEC Proj. Mgr.:** Joshua Cook (Section A)  
**Muni. Proj. Mgr.:** Joseph Chenier (City of Poughkeepsie)  
**Consultant Proj. Mgr.:** Scott Smith (CHA), John Bazzoni (OCC)  
**Contractor Proj. Mgr.:** Greg Paquin (Stamford Wrecking Company)  
**Contractor Super.:** Dave (Stamford Wrecking Company)

	<b>AM</b>	<b>PM</b>
<b>Weather</b>		Sunny
<b>Temperature</b>		~70/75
<b>Wind Speed &amp; Direction</b>		S to N

**Description of work performed by contr. this report period:**

- Volvo EC460B track excavator at site. Idle. Used to remove boat from water at end of day.
- Fuel truck parked at northeast end of site. No secondary containment in place.
- G. Donaldson coating inside of Zone1 bulkhead
- City contractor installing sidewalk, Zone 4, along temporary parking lot. Placing stone along top of rip-rap. Item 4 installed up to top of jersey barrier. Silt fence not in place during work.
- 2 laborers worked on patching lifting eye holes in jersey barrier, south end of Zone 1.
- ~2:30 - J. Bazzoni & 1 worker & me in boat to inspect interlocks from water side.
  - Zone 1 – J. Bazzoni heard leak at southwest corner.
  - Zone 3- Leaks identified at the following locations. Labeling reflects labels on outside of sheets.
    - 133/132
    - 217/216
    - 309/308
    - 307/306
    - 314/315
    - 326/327
    - 331/330

**Discussions/comments regarding visitors, contractor and/or engineer:**

- 

**Sampling and Analyses:**

- 

Major Issues	Description & Reason
1)	1)

**Health & Safety:**

**Level of protection:** Level D, Boots, Hard Hat, Safety Glasses.

**Is the level of protection in conformance with the approved Health & Safety Plan?**

**List deviations:**

**Are atmospheric monitoring results acceptable?**

Site Visitors	Representing	Entered Exclusion Zone
J. Chenier J. Bazzoni Dave and workers J. Cook (2:00 P – 3:45 P)	City of Poughkeepsie OCC Stamford Wrecking Co. NYSDEC	

**Site Representative:** Joshua Cook

**Date:** May 7, 2009

**Representative's signature:** *Joshua P. Cook*