


**New York State Department of Environmental Conservation  
Division of Environmental Remediation**

**Remedial Bureau C, 11th Floor**

625 Broadway, Albany, New York 12233-7014

**Phone:** (518) 402-9662 • **FAX:** (518) 402-9679

**Website:** www.dec.ny.gov



**DAILY INSPECTION REPORT**

<b>Site Code #:</b> B00190	<b>Date:</b> May 28, 2010	<b>Report #:</b> 2010-05-28.JPC
----------------------------	---------------------------	---------------------------------

**Site Name:** Hudson River Waterfront/DeLaval Property  
**Location:** Pine Street & Rinaldi Blvd, City of Poughkeepsie, Dutchess Co.  
**DEC Proj. Mgr.:** Joshua Cook (Section A)  
**Muni. Proj. Mgr.:** Joseph Chenier (City of Poughkeepsie)  
**Consultant Proj. Mgr.:** Scott Smith (CHA), John Bazzoni (OCC)  
**Contractor Proj. Mgr.:** Greg Paquin (Stamford Wrecking Company)  
**Contractor Super.:** Walt (Stamford Wrecking Company)  
**Site Phone & Fax:** 845-473-1467 (Contractor's Trailer)  
845-473-4586 (Consultant's Trailer)

	<b>AM</b>	<b>PM</b>
<b>Weather</b>	Cloudy	
<b>Temperature</b>	~60oF	
<b>Wind Speed &amp; Direction</b>	SSW to NNE	

**Description of work performed by contr. this report period:**

- Crew of 2 laborers working on outside of Zone 3 bulkhead, just N of new outfall (~150/200' S of NW corner). 1 laborer on bulkhead guiding/steadying boat; 1 in boat using what appeared to be a reaming tool.
- 1 laborer assisting this crew part time
- Dave welding bucket of excavator (Volvo EC 400)
- 1 laborer in water truck.
- Ginsburg outfall trench topped-off with Item 4 (clean fill). Last 20' +/- (river side) of trench not topped-off yet. Historic fill in trench. Outfall pipe partially exposed. Gap between sections.
- 1 worker doing coating on inside of Zone 1 bulkhead. Said he was new superintendent (Walt).
- Crushed concrete and brick mixed into stockpile along E side of site. Near, but separate from stone from PURA project.

**Discussions/comments regarding visitors, contractor and/or engineer:**

- 

**Sampling and Analyses:**

•

Major Issues	Description & Reason
1)	1)

**Health & Safety:**

**Level of protection:** Level D, Boots, Hard Hat, Safety Glasses.

**Is the level of protection in conformance with the approved Health & Safety Plan?**

**List deviations:**

**Are atmospheric monitoring results acceptable?**

Site Visitors	Representing	Entered Exclusion Zone
Walt, 4 workers J. Cook (~10:30 – 12:00)	Stamford Wrecking NYSDEC	

**Site Representative:** Joshua Cook

**Date:** May 28, 2010

**Representative's signature:** *Joshua P. Cook*