


**New York State Department of Environmental Conservation
Division of Environmental Remediation**

Remedial Bureau C, 11th Floor

625 Broadway, Albany, New York 12233-7014

Phone: (518) 402-9662 • **FAX:** (518) 402-9679

Website: www.dec.ny.gov



DAILY INSPECTION REPORT

Site Code #: B00190	Date: June 29, 2010	Report #: 2010-06-29.JPC
----------------------------	----------------------------	---------------------------------

Site Name: Hudson River Waterfront/DeLaval Property
Location: Pine Street & Rinaldi Blvd, City of Poughkeepsie, Dutchess Co.
DEC Proj. Mgr.: Joshua Cook (Section A)
Muni. Proj. Mgr.: Joseph Chenier (City of Poughkeepsie)
Consultant Proj. Mgr.: Scott Smith (CHA), John Bazzoni (OCC)
City Cont. Proj. Mgr.: Greg Paquin (Stamford Wrecking Company)
City Contractor Super.: Walt (Stamford Wrecking Company)
Developer's Contractor: Village Construction
Site Phone & Fax:

	AM	PM
Weather	Mostly Sunny	
Temperature	~75	
Wind Speed & Direction		

Description of work performed by contr. this report period:

Developer's Work

- Village Construction working on northern "marina" parking lot.
- Imported Item 4 being spread by Komatsu PC 200 track excavator & Komatsu 39 EX dozer
- Topsoil placed around traffic islands. Mulch being placed on top of topsoil
- Trucks delivering loads of topsoil to main site area. Generated dust which left site. Worker from Village said that was "their site".
- Village said Item 4 was from Tilcon and topsoil from Taylor recycling.

City's Work

- SWC working on coating outside of Zone 3 bulkhead. 4 work platforms set up. Crew of 3 (subcontractor) working on coating above high water from platforms. Crew of 3 working on coating below high water from boat. 2 in boat, 1 on bulkhead.
- Crew of 3 working on coating outside of Zone 1 bulkhead above high water. Worker said they were waiting on paint and for map-cracking repairs to be completed, so just keeping busy with some touch-ups.

Discussions/comments regarding visitors, contractor and/or engineer:

-

Sampling and Analyses:

•

Major Issues	Description & Reason
1)	1)

Health & Safety:

Level of protection: Level D, Boots, Hard Hat, Safety Glasses.

Is the level of protection in conformance with the approved Health & Safety Plan?

List deviations:

Are atmospheric monitoring results acceptable?

Site Visitors	Representing	Entered Exclusion Zone
Walt, Dave, workers Workers J. Cook (10:10 – 11:00)	Stamford Wrecking Co. Village Construction NYSDEC	

Site Representative: Joshua Cook

Date: June 29, 2010

Representative's signature: *Joshua P. Cook*