



BUILDING
(FIRST FLOOR ELEVATION 22.00 FT)

PARKING
ASPHALT PAVEMENT

WARNING:
IT IS A VIOLATION OF THE NYS EDUCATION LAW ARTICLE 145 FOR ANY PERSON, UNLESS HE/SHE IS ACTING UNDER THE DIRECTION OF A LICENSED PROFESSIONAL ENGINEER, TO ALTER THIS ITEM IN ANY WAY.

SOURCE #1:
© 2010 JOSEPH NICOLETTI ASSOCIATES, PROFESSIONAL LAND SURVEYORS, P.C. - ALL RIGHTS RESERVED. REF. NO.: B2314-010.

SOURCE #2:
DONALD G. DEKENIPP L.S., P.C., PROFESSIONAL LAND SURVEYOR, 222 GREENE AVENUE, SAYVILLE, NY 11782 (631) 589-5350
PROJECT NO. 111027, SURVEYED: NOVEMBER 1, 2011, TITLE: MONITORING WELL SURVEY OF PROPERTY SITUATED AT MOTT HAVEN, BOROUGH OF THE BRONX CITY OF NEW YORK.

SOURCE #3:
ELEVATION DATA PROVIDED IN AUGUST 27, 2013 SURVEY PROVIDED BY JOSEPH NICOLETTI ASSOCIATES (SOURCE #1).



TITLE POST-EXCAVATION & POST-BACKFILL SURFACE ELEVATION DATA			
PREPARED FOR BORINQUEN COURT BRONX, NY			
ERM CONSULTING & ENGINEERING, INC. Melville, New York (631) 758-8900		FIGURE 1-3	
DRAWN BY JMC/BML	SCALE GRAPHIC	DATE 11/12/2013	JOB NO. 0168812



- LEGEND
- SETS OF POST-BACKFILL AND POST-EXCAVATION ELEVATION DATA REPRESENTING AT LEAST 2-FT OF SOIL COVER
 - ELEVATION OF DEMARCATION BARRIER (RESIDUALS MANAGEMENT ZONE)
 - POST BACKFILL ELEVATION IN FT
 - TEST PIT EXCAVATED TO EXPOSE DEMARCATION BARRIER AND SURVEY THE ELEVATION
 - PROPERTY OUTLINE
 - BUILDING OUTLINE
 - AFTER SURVEYS CONDUCTED, A TEST HOLE WAS EXCAVATED. BACKFILL DEPTH PHYSICALLY MEASURED AND MINIMUM 2' OF COVER CONFIRMED BY REMEDIAL ENGINEER (MEASUREMENT SHOWN IS DEPTH TO DEMARCATION BARRIER)
 - SURFACE ELEVATION OF ASPHALT PARKING LOT IN FT
 - AREA WAS PHYSICALLY MEASURED DUE TO NEED TO BACKFILL QUICKLY (E.G., TO PROTECT TREES, ADJACENT TO SOME FENCING). 2' OF COVER CONFIRMED BY REMEDIAL ENGINEER.