

SITE OBSERVATION REPORT

PROJECT No.: 140115301	CLIENT: Enclave on 241 Street, LLC	DATE: 2/21/2019
PROJECT: Enclave on 241st Street Development		WEATHER: Overcast, mid-20's
LOCATION: 714 East 241 st Street, Bronx, NY		TIME: 10:00 am – 11:00 pm
CONTRACTOR: None		LANGAN REP. : John Fitzpatrick
CONTRACTOR'S EQUIPMENT: None	PRESENT AT SITE: Langan: John Fitzpatrick	

OBSERVATIONS, DISCUSSIONS, TEST RESULTS, ETC.:

Langan is onsite to replace the absorbent sock that was placed in monitoring well MW-29R on 17 January 2019, which replaced the sock that was previously placed on 12 December 2018 following completion of the second LNAPL extraction event at the site.

SITE ACTIVITIES:

- 1) John Fitzpatrick arrived onsite at 10:00 am and removed the hydrophobic absorbent sock that was in MW-29R. Although some silt had accumulated on the sock, no measurable product was detected.
- 2) Gauging of the well was completed with a dual-phase interface probe in order to detect the potential presence of free product. Depth to water was measured at 8.54 feet btoc and depth to bottom was 19.37 feet btoc. No measurable product was detected.
- 3) Langan deployed a new hydrophobic absorbent sock at MW-29R.
- 4) Langan offsite at 11:00 am.

Cc:	Ryan J. Wohlstrom, Jamie P. Barr	By:	John Fitzpatrick
			LANGAN

SITE PHOTOGRAPHS:




Photo 1: Removal of sock in MW-29R (no product).



Photo 2: Bailed water from MW-29R (no product).

Cc: Ryan J. Wohlstrom, Jamie P. Barr

By: John Fitzpatrick

LANGAN



Photo 3: New sock placed in MW-29R.

Cc: Ryan J. Wohlstrom, Jamie P. Barr

By: John Fitzpatrick

LANGAN