

	Daily Activity Report	
PAK RF	820 East 182nd Street	
	Bronx, NY	
	BCP Site No. C203149	
	General Site Information	
Date:	Wednesday, March 1, 2023	
Weather:	Sunny, 35° F	
Wind Direction/Speed:	Coming from East @ 4 mph	
AKRF Personnel on Site:	Jack Kelleher-Ferguson and Shannon Donohue	
AKRF Equipment on Site:	Mini RAE 3000 Photoionization Detectors [(PID) x3] and DustTrak Aerosol Monitors (x3)	
Visitors:		None
	Contractor Information	
Subcontracto	or	Service
Island Pump & Tank Corp. (IPT)		Tank removal contractor
East Northport,	NY Tank removal contractor	
	Description and Location of Work Activities	Performed
	CAMP Air Maritaria - Davida	
	CAMP Air Monitoring Results	
CAMP Station	UPWIND	DOWNWIND
Odors:	None	None
VOC Action Level Exceedance(s):	None	None
Particulate Action Level Exceedance(s):	None	1
Maximum VOC Level (ppm) 15-min avg:	2.354	1.723
Maximum Particulate Level (mg/m³) 15-min avg:	0.0980	
		0.2570
CAMP Response Actions: The downwind particulate excee Particulate levels reduced shortly after dust suppression w		ump island. AKRF instructed IPT to use water as dust suppression.
· · · · · · · · · · · · · · · · · · ·		

Comments:

None





Site Photographs Mar 1, 2023 at 10:2 AKRI Photograph 1 - IPT removing the pumping dispensers. CAKRI Photograph 2 - IPT placing poly sheeting under the removed tanks. Photograph 3 - IPT excavating and pulling back soil to remove the USTs.