

	Daily Activity Report	
	820 East 182nd Street	
	Bronx, NY	
BCP Site No. C203149		
General Site Information		
Date:	Thursday, March 2, 2023	
Weather:	Cludy/AM Rain, 35-56° F	
Wind Direction/Speed:	NW @ 15-25 mph	
AKRF Personnel on Site:	Shannon Donohue	
AKRF Equipment on Site:	Mini RAE 3000 Photoionization Detectors [(PID) x3] and DustTrak Aerosol Monitors (x3)	
Visitors:	None	
Contractor Information		
Subcontractor		Service
Island Pump & Tank Corp. (IPT) East Northport, NY		Tank removal contractor
Description and Location of Work Activities Performed		
<p>IPT removed two 4,000-gallon gasoline USTs from the ground (both previously emptied). The tanks were placed on and covered with poly sheeting until they can be cleaned and removed off-site. Debris from aboveground portions of the pump island (lighting, steel features) was transported off-site by IPT. AKRF collected one sidewall endpoint sample within the tank excavaiton area.</p>		
CAMP Air Monitoring Results		
CAMP Station	UPWIND	DOWNWIND
Odors:	None	None
VOC Action Level Exceedance(s):	None	1
Particulate Action Level Exceedance(s):	None	None
Maximum VOC Level (ppm) 15-min avg:	3.549	5.937
Maximum Particulate Level (mg/m³) 15-min avg:	0.1191	0.0981
<p>CAMP Response Actions: CAMP monitoring began at 8:30 due to morning rain. A VOC exceedance occurred at the downwind station from 11:15-11:23 due to relocation of the waste oil tank. The VOC levels decreased after AKRF informed IPT and the tank was covered with plastic sheeting. Elevated particulate readings were detected at the upwind CAMP station during movement of machinery around the Site, and not during intrusive work.</p>		
Additional Information		
Planned Work Activity for Next Day/Week:	Removal/cleaning of gasoline and waste oil USTs, associated piping, and any grossly contaminated fill/soil (if encountered). Collection of post-excavation endpoint samples.	
Comments:	None	




© 2022 AKRF. W:\Projects\210138 - 820 East 182nd Street\Technical\GIS and Graphics\Map\210138 Fig 2 Site Plan.mxd 4/25/2022 10:58:39 AM iszslus

 440 Park Avenue South, New York, NY 10016	820 East 182nd Street Bronx, New York		DATE 4/25/2022
	SITE PLAN		PROJECT NO. 210138
			FIGURE 2

Upwind CAMP Station Data



Downwind CAMP Station Data



Site Photographs

Photograph 1 - 4,000-gallon gasoline USTs removed from ground and being covered with plastic, view facing southwest.



Photograph 2 - Tank excavation area, view facing west.



Photograph 3 - IPT transporting metal debris from pump island off-site, view facing east.

