		Daily Activity Report		
ØAK RF		820 East 182nd Street		
		Bronx, NY		
		BCP Site No. C203149		
		General Site Information		
Date:		Monday, March 27, 2023		
Weather:		Partly Cloudy, 46-56° F		
Wind Direction/Spee		NE @ 6 mph		
AKRF Personnel on S		J. Kelleher-Ferguson		
AKRF Equipment on Visitors:	Site:	Mini RAE 3000 Photoionization Detectors [(PID) x3] and DustTrak Aerosol Monitors (x3) None		
VISITORS:		Contractor Information	Nor	le
	Subcontrac		1	Service
Island Pump & Tank Corp				
East Northport, N			Tank removal contractor	
		Description and Location of Work Activities	s Performed	
		Site Soil Disposal Tracking Informa	tion	
CAMP Station		UPWIND		DOWNWIND
Odors:		None		None
VOC Action Level Exceedance(s):		None		None
Particulate Action Level Exceedance(s):		None		None
Maximum VOC Level (ppm) 15-min avg:		0.267		
				0.112
	e Level (mg/m³) 15-min avg:	0.0214		
				0.112
Maximum Particulat				0.112
Maximum Particulat	ions: None	0.0214 Additional Information		0.112





