	Daily Activity Report		
	100 East 149 th Street Site		
	100 East 149 th Street, Bronx, New York		
	BCP No. C203159		
General Site Information			
Date:	Wednesday, April 24, 2024		
Weather:	Overcast, 49-69°F		
Wind Direction/Speed:	S 1 to 7 mph		
Touchstone Personnel on Site:	Firat Ataman		
Touchstone Equipment on Site:	Interface Probe		
Visitors:	N/A		
Contractor Information			
Contracting Company	Main Personnel	Equipment	
Drilling Contractor: PG Environmental Services, Inc.	N/A	N/A	
Description and Location of Work Activities Performed			
<p>The Community Air Monitoring Program (CAMP) was not implemented throughout the workday as no drilling activities were conducted.</p> <p>Touchstone performed a supplemental groundwater elevation investigation at the Site on April 24, 2024 based upon a request by the NYSDEC in their April 19, 2024 letter which requested modifications be made to the Remedial Investigation Report (RIR). The depth to water was measured in all monitoring wells (23MW1 through 23MW10) with an interface probe. The depth to water in each well was recorded and a new groundwater contour map was generated for the RIR. No samples were collected.</p>			
CAMP Air Monitoring Results			
CAMP Station	Upwind CAMP Station	Downwind CAMP Station	Roving (PID)
Odors:	None	None	None
VOC Action Level Exceedance(s):	None	None	None
Particulate Action Level Exceedance(s):	None	None	None
Maximum VOC 15min Avg. Level (ppm):	None	None	None
Maximum Particulate 15min Avg. Level (mg/m ³):	None	None	None
CAMP Response Actions: None.			
Additional Information			
Planned Work Activity for Following Day/Week:	None.		
Comments:	None.		

100 East 149th Street Site Map

LEGEND

- Site Boundary
- Soil Probe Location/Monitoring Well Location
- Soil Vapor Probe


Notes:

Touchstone performed a supplemental groundwater elevation investigation at the Site based upon a request by the NYSDEC in their April 19, 2024 letter which requested modifications be made to the Remedial Investigation Report (RIR). The depth to water was measured in all monitoring wells (23MW1 through 23MW10) with an interface probe. The depth to water in each well was recorded and a new groundwater contour map was generated for the RIR. CAMP monitoring was not conducted at the Site.

Samples Collected:

No samples were collected.



	
100 East 149th Street Bronx, New York	PROPOSED REMEDIAL EXCAVATION PLAN
DATE 04/24/2024	
PROJECT NO. C203159	
ATTACHMENT A	

100 East 149th Upwind CAMP Station


No CAMP Monitoring Conducted

100 East 149th Downwind CAMP Station

No CAMP Monitoring Conducted

100 East 149th Street Photographic Log

Photograph 1 –
Monitoring Well and
Interface Probe



Photograph 2 –
Monitoring Well and
Interface Probe



Photograph 3 –
Monitoring Well and
Interface Probe

