

## Daily Status Report

Prepared by: C. Zaccheo

Date: 1/3/2022

Weather: 30 deg F., Overcast

**Project: 470 Kent Avenue - Brooklyn, NY - DEC Site #s C224053 and 224053**

|  |   |
|--|---|
| Engineer:<br>Matthew Carroll, P.E.<br>Tenen Environmental, LLC | Safety Manager:<br>Claire Zaccheo<br>Tenen Environmental, LLC |
| Demolition Contractor:<br>Alba                                 |   |

### Work Activities Performed:

1) Completed air monitoring and environmental oversight on former building slab and footings demolition.


**Samples Collected (Since Last Report):** None.

**Air Monitoring (Since Last Report):** CAMP graphs are included below.

**Problems Encountered:** None.

**Planned Work Activities for Next Day/Week:** Continue demolishing former building slab and footings.

## Site Layout Map



**Photo 1:**

Site conditions




**Photo 2:**

Stockpiling concrete debris from the building slab and footings demolition.




**CAMP:  
Downwind  
Particulates**




51735 Dust Trak TWA (0.01mg/m³) 51735 Dustrak 15 min Average (0.02mg/m³)

**CAMP:  
Downwind VOCs**



51735 MiniRae TWA (0ppm) VOC 15 min Average (0ppm)

**CAMP:  
Upwind Particulates**



51728 Dust Trak TWA (0.02mg/m³)

51728 Dusttrak 15 min average (0.03mg/m³)