

74 20th Street
74 20th Street
Brooklyn, NY 11232

Inquiry Number: 6012679.2s
March 17, 2020

The EDR Radius Map™ Report with GeoCheck®



6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	660
Government Records Searched/Data Currency Tracking	GR-1
 <u>GEOCHECK ADDENDUM</u>	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

74 20TH STREET
BROOKLYN, NY 11232

COORDINATES

Latitude (North):	40.6650570 - 40° 39' 54.20"
Longitude (West):	73.9986970 - 73° 59' 55.30"
Universal Transverse Mercator:	Zone 18
UTM X (Meters):	584638.9
UTM Y (Meters):	4501847.0
Elevation:	7 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5940597 BROOKLYN, NY
Version Date:	2013
Northwest Map:	6048959 JERSEY CITY, NJ
Version Date:	2014

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
74 20TH STREET
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	DEBEVOISE CO	74 20TH ST	CORRACTS, RCRA-TSDF, RCRA NonGen / NLR, ICIS,...		TP
A2	DECORATIVE NOVELTY	74 20TH ST - 1ST FLO	RCRA NonGen / NLR, FINDS, ECHO		TP
A3	CON EDISON	27 21 ST	NY MANIFEST	Lower	1 ft.
A4	INTERNATIONAL TRUCK	92 20TH STREET	NY AST	Higher	62, 0.012, ESE
A5	SUNSET INDUSTRIAL PA	50 21ST STREET	NY UST	Lower	90, 0.017, WSW
A6	VERIZON	60 21ST	NY Spills, NY MANIFEST	Lower	91, 0.017, WSW
A7	CON EDISON	64 21ST ST & 3RD AVE	NY MANIFEST	Lower	92, 0.017, WSW
A8	KAMPCO SUPPLY	80 21ST STREET	NY Spills	Lower	107, 0.020, SW
B9	MH 5578	3RD AVE/20TH ST	NY Spills	Higher	229, 0.043, ESE
B10	STARPOINT USA INC	668 3RD AVE	EDR Hist Auto	Higher	234, 0.044, ESE
B11	SUNSET MANAGEMENT, L	668 THIRD AVENUE	NY UST	Higher	234, 0.044, ESE
C12	NW CORNER OF	63RD ST AT 3RD AVE	NY Spills	Higher	286, 0.054, South
C13	CON EDISON - SERVICE	690 3RD AVE	NY MANIFEST	Higher	308, 0.058, SSE
C14	CON EDISON - SERVICE	690 3RD AVE	RCRA-LQG	Higher	308, 0.058, SSE
D15	CON EDISON	73-19 72 ST	NY MANIFEST	Higher	311, 0.059, NNE
E16	NYSDOT GOWANUS EXPWY	3RD AVE & HAMILTON	RCRA NonGen / NLR, NY MANIFEST	Higher	317, 0.060, ENE
F17	SUNSET INDUSTRIAL PA	50 20TH ST	NY Spills	Lower	333, 0.063, NNW
C18	PARTS EXPRESS INC	694-696 3RD AVE	NY SWF/LF	Higher	338, 0.064, SSE
C19	3RD AVENUE AUTO PART	694 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	338, 0.064, SSE
D20	DECORATIVE NOVELTY C	65 19TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	358, 0.068, NNE
B21	ATLAS GAS STATION	20TH ST & 3RD AVE	NY Spills	Higher	363, 0.069, ESE
F22	SHAMROCK CONTRACTING	95-99 19TH STREET	NY SWF/LF	Lower	371, 0.070, NNW
B23	GOWANUS EXPWY/65TH S	GOWANUS EXPWY/65TH S	NY Spills	Higher	376, 0.071, East
E24	SCRAP KING USA INC	99 19TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	380, 0.072, ENE
E25	CON EDISON	109 19 ST	NY MANIFEST	Higher	395, 0.075, ENE
G26	SPIILL NUMBER 0306006	3RD AVE & 21ST ST	NY Spills	Higher	398, 0.075, SE
G27	UNDER TRESSSEL	21ST & 3RD AVE	NY Spills	Higher	398, 0.075, SE
D28	18TH-19TH RELATY CO	79 19TH STREET	NY AST	Lower	401, 0.076, North
C29	95 22ND STREET	95 22ND ST & 3RD AVE	NY Spills	Higher	409, 0.077, South
C30	GOWANUS BAY	22ND ST & 3RD AVE	NY Spills	Higher	422, 0.080, SSE
G31	CON EDISON	64 21ST ST & 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	437, 0.083, SE
G32	LINSOM SERVICE CENTE	687 3RD AVENUE	NY AST	Higher	445, 0.084, SE
G33	LINSOM SERVICE CENTE	687 3RD AVE	EDR Hist Auto	Higher	445, 0.084, SE
G34	21 ST OFF 3RD AVENUE	21 ST OFF 3RD AVENUE	NY LTANKS	Higher	446, 0.084, SE
E35	CON EDISON MANHOLE:	19TH ST & 3RD AVE MH	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	449, 0.085, East
E36	CON EDISON - MANHOLE	19TH STREET & 3RD AV	RCRA-LQG, NJ MANIFEST	Higher	449, 0.085, East
E37	TRI-STATE TRUCK & TR	84 18TH STREET	NY AST	Higher	481, 0.091, NE
E38	CON EDISON MANHOLE:	84 18 TH ST OPPOSITE	RCRA NonGen / NLR	Higher	481, 0.091, NE
E39	CON EDISON - VAULT 6	82 18TH ST	RCRA-SQG	Higher	495, 0.094, NE

MAPPED SITES SUMMARY

Target Property Address:
74 20TH STREET
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
E40	MANHOLE 46454	OPPOSITE 82 18TH ST	NY Spills	Higher	495, 0.094, NE
E41	CON EDISON	82 18TH ST	NY MANIFEST	Higher	495, 0.094, NE
C42	MANHOLE 5580	3RD AVE IFO 702 22ND	NY Spills	Higher	508, 0.096, South
C43	MANHOLE 5580	3RD AVE/22ND ST	NY Spills	Higher	508, 0.096, South
C44	SPILL NUMBER 9807662	3RD AVENUE & 22ND ST	NY Spills	Higher	508, 0.096, South
H45	SB46706	133 20TH ST	NY Spills	Higher	526, 0.100, ESE
H46	CON EDISON	647 3 AVE	RCRA NonGen / NLR	Higher	535, 0.101, East
H47	CON EDISON	647 3 AVENUE	NY MANIFEST	Higher	535, 0.101, East
H48	CON ED	647 3RD AVE	NY MANIFEST	Higher	535, 0.101, East
H49	CON EDISON	647 3 AVE	NJ MANIFEST	Higher	535, 0.101, East
H50	20TH STREET COLLISIO	135 20TH STREET	NY AST	Higher	551, 0.104, ESE
E51	CON EDISON	100 18 ST	NY MANIFEST	Higher	572, 0.108, ENE
I52	73 20TH ST	73 20TH ST	NY Spills	Lower	574, 0.109, NW
G53	EDWARD T MINOR CO	133 22ND ST	NY Spills	Higher	577, 0.109, SSE
E54	TRANSFORMER VAULT -	18TH ST & HAMILTON A	NY Spills	Higher	580, 0.110, ENE
E55	SEWER	18TH ST AND HAMILTON	NY Spills	Higher	580, 0.110, ENE
E56	SPILL NUMBER 0304223	HAMILTON AVE & 18TH	NY Spills	Higher	580, 0.110, ENE
E57	CON EDISON - MANHOLE	HAMILTON AVE & 3RD A	RCRA-LQG, NJ MANIFEST, NY MANIFEST	Higher	580, 0.110, ENE
E58	CON EDISON	18TH ST & HAMILTON A	RCRA NonGen / NLR, NY MANIFEST	Higher	580, 0.110, ENE
J59	POWER PLANT - JOSEPH	3RD AVE 23 ST	NY Spills	Higher	606, 0.115, SSW
H60	CON EDISON	123-19 ST	NY MANIFEST	Higher	608, 0.115, East
J61	NYCDEP	27 23 16TH ST	NY MANIFEST	Higher	614, 0.116, SSW
K62	CON EDISON SPLICE BO	709 3RD AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	616, 0.117, South
G63	CON EDISON SERVICE B	137 22ND ST	RCRA NonGen / NLR	Higher	617, 0.117, SSE
G64	CON EDISON	137 22ND ST	NY MANIFEST	Higher	617, 0.117, SSE
L65	MANHOLE #55605	3RD AVE & 18TH ST	NY Spills	Higher	618, 0.117, ENE
L66	VS 6601 HAS 50 GAL D	3 AVENUE & 18 STREET	NY Spills	Higher	618, 0.117, ENE
L67	ROADWAY	18TH ST AND 3RD AVE	NY Spills	Higher	618, 0.117, ENE
I68	HAMILTON AVENUE PIER	18TH-19TH STREETS	SEMS-ARCHIVE	Lower	619, 0.117, NNW
K69	3RD AVE AUTO REPAIR	703 3RD AVE	NY AST	Higher	638, 0.121, South
K70	NYSDOT	703-709 THIRD AVE	NY MANIFEST	Higher	638, 0.121, South
K71	NYSDOT	HAMILTON AVE & 16TH	RCRA NonGen / NLR	Higher	638, 0.121, South
L72	NYSDOT D257588	3RD AVE & 18TH ST	RCRA NonGen / NLR	Higher	664, 0.126, NE
J73	NYCDEP	64 23RD AVE	NY MANIFEST	Higher	664, 0.126, South
H74	CON EDISON	146 20 ST	NY MANIFEST	Higher	668, 0.127, SE
L75	NYSDOT	3RD AVE & 19TH ST	RCRA NonGen / NLR	Higher	676, 0.128, East
K76	SASUN JEWELRY INC	134 22ND ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	685, 0.130, SSE
K77	CON EDISON	134 22 ST	NY MANIFEST	Higher	685, 0.130, SSE
L78	CON EDISON	637 3RD AVE	NY MANIFEST	Higher	693, 0.131, East

MAPPED SITES SUMMARY

Target Property Address:
74 20TH STREET
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
L79	CON EDISON	637 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	693, 0.131, East
L80	CON EDISON	637 3RD AVE	NJ MANIFEST	Higher	693, 0.131, East
J81	CON EDISON	3RD AVE & 23RD ST	RCRA NonGen / NLR, NY MANIFEST	Higher	699, 0.132, South
J82	FORMER MOORE MCCORMA	730 3RD AVENUE	NY SHWS, NY Spills	Lower	704, 0.133, SSW
J83	NEW YORK POWER AUTHO	730 3RD AVE AND 23RD	NY CBS, NY CBS AST, NY TANKS, NY Spills	Lower	704, 0.133, SSW
H84	I & J FINISHING CORP	149 20TH ST	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Higher	722, 0.137, ESE
I85	NORTHROP/US CUSTOMS	18 20TH ST	NY MANIFEST	Lower	763, 0.145, NW
M86	CON EDISON	24-17 64 ST	NY MANIFEST	Higher	765, 0.145, NE
N87	STEPHEN IMPORTS INC.	150 20TH STREET	NY AST	Higher	767, 0.145, SE
I88	FEDERAL EXPRESS - FB	51 20TH STREET	NY AST	Lower	771, 0.146, NW
I89	FEDERAL EXPRESS CORP	51 20TH ST	RCRA NonGen / NLR, RI MANIFEST	Lower	771, 0.146, NW
M90	CON EDISON - SERVICE	HAMILTON AVE & 17 ST	RCRA-LQG	Higher	778, 0.147, NE
M91	CON EDISON	HAMILTON AVE & 17TH	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	778, 0.147, NE
M92	CON EDISON - SERVICE	HAMILTON AVE & 17 ST	NJ MANIFEST	Higher	778, 0.147, NE
L93	CON EDISON	123 18TH ST	RCRA NonGen / NLR	Higher	781, 0.148, East
L94	CON EDISON	123 18TH ST	NY MANIFEST	Higher	781, 0.148, East
L95	CON EDISON	123 18TH ST	NJ MANIFEST	Higher	781, 0.148, East
L96	LINSOM SERVICE CENTE	629 3RD AVENUE	NY AST	Higher	790, 0.150, ENE
L97	LINSOM SERVICE CENTE	629 3RD AVENUE	NY UST	Higher	790, 0.150, ENE
O98	VELAZQUEZ AUTO REPAI	134 18TH STREET	NY AST	Higher	806, 0.153, East
I99	CONSOLIDATED EDISON	20 ST C32W 4TH AVE 2	NY MANIFEST	Lower	817, 0.155, NW
I100	CON EDISON - TRF 26	20 ST C32W 4TH AVE 2	RCRA NonGen / NLR	Lower	817, 0.155, NW
M101	CON EDISON	HAMILTON AVE & 17TH	NY MANIFEST	Higher	855, 0.162, NE
N102	CON EDISON	162 20 ST	NY MANIFEST	Higher	867, 0.164, SE
P103	CON EDISON	151 23 ST	NY MANIFEST	Higher	891, 0.169, SSE
Q104	CON EDISON	134 17TH ST	NJ MANIFEST	Higher	909, 0.172, ENE
Q105	CON EDISON	134 17TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	909, 0.172, ENE
P106	CONSOLIDATED EDISON	V4652 134 E 23RD ST	NY MANIFEST	Higher	913, 0.173, South
N107	COLONIAL MIRROR & GL	163 20TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	916, 0.173, ESE
O108	ADELE ROOTSTEIN USA	145 18TH ST	RCRA NonGen / NLR, US AIRS, FINDS, ECHO, NY...	Higher	916, 0.173, East
N109	HK AUTO REPAIR INC.	163 21ST STREET	NY AST	Higher	920, 0.174, SE
R110	JETRO CASH & CARRY	566 HAMILTON AVENUE	NY UST	Higher	922, 0.175, NE
S111	B B R CONTRACTING CO	163 22ND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	922, 0.175, SSE
P112	CON EDISON - SERVICE	144 23 ST	RCRA-LQG, NY MANIFEST	Higher	970, 0.184, South
T113	MOORE MCCORMACK BUIL	740 3RD AVE	RCRA-SQG	Higher	971, 0.184, SSW
P114	SPIILL NUMBER 0300252	160 22ND ST	NY LTANKS	Higher	972, 0.184, SSE
O115	GLADYS PEREZ	144 17TH STREET	NY AST	Higher	978, 0.185, East
N116	CON EDISON SERVICE B	678 4TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	985, 0.187, SE
N117	CON EDISON SERVICE B	668 4TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	995, 0.188, ESE

MAPPED SITES SUMMARY

Target Property Address:
74 20TH STREET
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
R118	HOME DEPOT U.S.A., I	550 HAMILTON AVENUE	NY UST	Higher	1016, 0.192, NNE
R119	HOME DEPOT USA INC H	550 HAMILTON AVE	RCRA-SQG, FINDS, ECHO, NY MANIFEST, NJ MANIFEST	Higher	1016, 0.192, NNE
T120	CON ED - MH 67496	F/O 117-119 25TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1038, 0.197, SSW
T121	CON ED - MH 46939	F/O #117 - 25 ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1038, 0.197, SSW
U122	652 4TH AVE	652 4TH AVE	NY LTANKS	Higher	1042, 0.197, ESE
T123	LOPEZ BYWAY SERVICE	739 3RD AVENUE	NY UST	Higher	1055, 0.200, South
T124	LOPEZ BYWAY SERVICE	739 3RD AVENUE	NY AST	Higher	1055, 0.200, South
U125	CON EDISON SERVICE B	642 4TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1068, 0.202, ESE
V126	CON EDISON SERVICE B	192 24TH ST	RCRA NonGen / NLR	Higher	1071, 0.203, South
V127	CON EDISON	192 24TH ST	NY MANIFEST	Higher	1071, 0.203, South
U128	CON EDISON SERVICE B	112-14 E 19TH ST & 4	RCRA NonGen / NLR, FINDS	Higher	1093, 0.207, ESE
U129	CON EDISON SERVICE B	235-37 4TH AVE & 19T	RCRA NonGen / NLR, FINDS	Higher	1093, 0.207, ESE
P130	CON EDISON - EXCAVAT	160 23RD ST	RCRA-LQG, NY MANIFEST	Higher	1104, 0.209, SSE
S131	PRIVATE HOME	720 4TH AVE	NY LTANKS	Higher	1106, 0.209, SSE
S132	NYNEX-MANHOLE	4TH AVE & 22ND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1110, 0.210, SSE
W133	BROOKLYN CULTURAL CE	675 4TH AVENUE	NY AST	Higher	1119, 0.212, SE
P134	CON EDISON	162 23RD ST	NJ MANIFEST	Higher	1123, 0.213, SSE
P135	CON EDISON	162 23RD ST	NY MANIFEST	Higher	1123, 0.213, SSE
P136	CON EDISON	162 23RD ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1123, 0.213, SSE
137	NYC PARKS & REC - CO	30-26 W 25TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1152, 0.218, SSW
U138	SLOPE ON 4TH LLC	647 4TH AVENUE	NY AST	Higher	1154, 0.219, ESE
T139	25TH ST STATION/R TR	25TH ST STATION	NY LTANKS	Higher	1161, 0.220, SSW
140	PARK SLOPE AUTO CENT	651 4TH AVENUE	NY AST	Higher	1164, 0.220, ESE
V141	CON EDISON	155 25 ST	NY MANIFEST	Higher	1170, 0.222, South
T142	CONSOLIDATED EDISON	3RD AVE & 25TH ST EX	NY MANIFEST	Higher	1181, 0.224, SSW
U143	639 4TH AVENUE	639 4TH AVENUE	NY UST	Higher	1184, 0.224, ESE
144	HAMILTON AVE PIERS	19TH & 18TH STREETS	NY HSWDS	Lower	1189, 0.225, NNW
X145	CON EDISON	174-23 ST	NY MANIFEST	Higher	1193, 0.226, SSE
W146	CON EDISON SERVICE B	683 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1194, 0.226, SE
U147	SUNOCO SERVICE STATI	623 FOURTH AVE	RCRA NonGen / NLR	Higher	1217, 0.230, ESE
U148	635 4TH AVENUE	635 4TH AVENUE	NY VCP	Higher	1219, 0.231, ESE
W149	691 4TH AVENUE	691 4TH AVENUE	NY VCP	Higher	1222, 0.231, SE
Y150	CON EDISON - MANHOLE	614 4 AVE	RCRA-LQG	Higher	1227, 0.232, East
Y151	CON EDISON - MANHOLE	614 4 AVE	NJ MANIFEST	Higher	1227, 0.232, East
Y152	CON ED	614 4 AVE	NY MANIFEST	Higher	1227, 0.232, East
W153	CON EDISON - 22ND ST	181 22ND STREET	PA MANIFEST	Higher	1232, 0.233, SE
Z154	CON EDISON	F/O 12 16 MCDONAL AV	NY MANIFEST	Higher	1232, 0.233, NE
X155	NYSDEC/SPILLS	734 4TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1236, 0.234, SSE
AA156	CON EDISON	139 PROSPECT AVE	NY MANIFEST	Higher	1238, 0.234, ENE

MAPPED SITES SUMMARY

Target Property Address:
74 20TH STREET
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Z157	NYS DOT	HAMILTON AVE & 16TH	RCRA NonGen / NLR, NY MANIFEST	Higher	1252, 0.237, NE
V158	CON EDISON SERVICE B	169 25TH ST	RCRA NonGen / NLR	Higher	1252, 0.237, South
V159	CON EDISON	F/O # 169 25TH STREE	NY MANIFEST	Higher	1252, 0.237, South
X160	CON EDISON SERVICE B	115-17 E 23RD ST & 4	RCRA NonGen / NLR, FINDS	Higher	1256, 0.238, SSE
X161	CON EDISON SERVICE B	127-29 E 23RD ST & 4	RCRA NonGen / NLR, FINDS	Higher	1256, 0.238, SSE
X162	CON EDISON SERVICE B	104 E 23RD ST & 4TH	RCRA NonGen / NLR, FINDS	Higher	1256, 0.238, SSE
X163	CON EDISON SERVICE B	313-21 4TH AVE & 23R	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1256, 0.238, SSE
AB164	NYC DEP HAZ MAT	HAMILTON & SECOND AV	NY MANIFEST	Higher	1263, 0.239, NNE
Z165	WHITE TOP	11-16 - 11-17	RCRA NonGen / NLR, FINDS, ECHO	Higher	1272, 0.241, NE
Z166	NYC DEP	16TH & HAMILTON AVE	NY MANIFEST	Higher	1274, 0.241, NNE
167	CONSOLIDATED EDISON	16TH ST & 3RD AVE	NY MANIFEST	Higher	1298, 0.246, NE
AA168	CON EDISON	60 16TH ST	NY MANIFEST	Higher	1301, 0.246, ENE
AA169	CON EDISON SERVICE B	60 16TH ST	RCRA NonGen / NLR	Higher	1301, 0.246, ENE
Y170	609-619 4TH AVENUE	609 4TH AVENUE	NY VCP	Higher	1360, 0.258, East
AB171	HAMILTON AVENUE INCI	555 HAMILTON AVE	SEMS-ARCHIVE, NY SWF/LF, NY Spills, NY MANIFEST	Higher	1411, 0.267, NNE
AC172	ANTON JUNCIC ENTERP	776 3RD AVENUE	NY SWF/LF, NY CBS, NY Spills	Higher	1503, 0.285, SSW
AD173	NYS DEC BUREAU OF SP	737 4TH AVE	NY LTANKS, NY MANIFEST	Higher	1551, 0.294, South
AD174	CITGO STATION	4TH AV & 25TH ST	NY LTANKS	Higher	1556, 0.295, South
AE175	MOBIL R/S #11775	586 4TH AVENUE	NY LTANKS, NY UST, NY AST, NY Spills	Higher	1560, 0.295, East
176	BARGE: ELECTRA II/GO	THIRD AVENUE & 27TH	NY MOSF	Lower	1571, 0.298, SW
AF177	BUCKEYE TERMINALS, L	722 COURT STREET	NY MOSF	Lower	1605, 0.304, NW
AF178	AMERADA HESS	722 COURT STREET	NY LTANKS, NY Spills	Lower	1605, 0.304, NW
AF179	BUCKEYE TERMINALS LL	722 COURT ST	RCRA-SQG, NY LTANKS, NY MOSF UST, NY MOSF AST, NY..	Lower	1605, 0.304, NW
AF180	HESS BROOKLYN TERMIN	722 COURT ST	NY LTANKS, NY Spills	Lower	1605, 0.304, NW
AF181	AMERADA HESS	722 COURT STREET	NY LTANKS	Lower	1605, 0.304, NW
AF182	AMERADA HESS	722 COURT STREET	NY LTANKS	Lower	1605, 0.304, NW
AF183	AMERADA HESS	722 COURT STREET	NY LTANKS	Lower	1605, 0.304, NW
AE184	573-581 4TH AVENUE	581 4TH AVENUE	NY VCP	Higher	1612, 0.305, East
AD185	GOLDEN MILLION	276-280 24TH ST	NY LTANKS, NY Spills	Higher	1637, 0.310, SSE
AD186	207 25TH STREET	207 25TH STREET	NY LTANKS	Higher	1639, 0.310, SSE
AG187	FORMER BARRETT MANUF	627 SMITH ST.	NY SHWS, NY BROWNFIELDS	Lower	1658, 0.314, NNW
AC188	HI-VOLTAGE TEST SET	3RD AVE YARD	NY LTANKS, NY Spills	Higher	1673, 0.317, SSW
AH189	643 COURT ST.	643 COURT ST.	NY SHWS	Lower	1699, 0.322, NNW
AI190	HESS TERMINAL RACK 1	764 COURT STREET	NY LTANKS	Lower	1701, 0.322, NW
AI191	HESS LOADING RACK	764 COURT STREET	NY LTANKS	Lower	1701, 0.322, NW
AF192	713 COURT STREET	713 COURT STREET	NY LTANKS	Lower	1707, 0.323, NW
AD193	25TH ST - 4TH AVE SU	25TH ST - 4TH AVE SU	NY LTANKS	Higher	1763, 0.334, SSE
AJ194	SPILL NUMBER 0207372	3RD AVE/14TH ST	NY LTANKS	Higher	1793, 0.340, NE
195	GRESCHLER HARDWARE S	660 5TH AVE	NY LTANKS	Higher	1829, 0.346, ESE

MAPPED SITES SUMMARY

Target Property Address:
74 20TH STREET
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AG196	610 SMITH STREET	610 SMITH STREET	NY AST, NY BROWNFIELDS, NY Spills	Lower	1867, 0.354, NNW
AH197	CHEMTURA 633 COURT S	633 COURT STREET	NY SHWS	Higher	1879, 0.356, NNW
AK198	GOWANUS QUICK ENERGY	420 SECOND AVENUE	NY MOSF, NY TANKS	Lower	1942, 0.368, SW
AJ199	SUNOCO	538 3RD AVE	NY LTANKS	Higher	1956, 0.370, NE
AL200	CHEM TURA	688-700 COURT ST	NY CBS UST, NY CBS, NY DEL SHWS, RCRA NonGen /...	Higher	1958, 0.371, NW
AL201	WITCO CORPORATION BR	633 AND 688-700 COUR	NY VCP	Higher	1958, 0.371, NW
202	GOUWANUS BAY	COURT ST- PIER 8	NY LTANKS	Lower	1979, 0.375, WNW
203	707 5TH AVENUE	707 5TH AVENUE	NY LTANKS	Higher	1982, 0.375, SE
AM204	182 SIGOURNEY ST	182 SIGOURNEY ST	NY SHWS	Higher	1986, 0.376, NNW
AN205	740 5TH AVE	740 5TH AVENUE	NY LTANKS, NY Spills	Higher	2048, 0.388, SSE
AO206	535 4TH AVENUE	535 4TH AVENUE	NY VCP	Higher	2056, 0.389, ENE
AN207	TEXACO SERVICE STATI	735 5TH AVENUE	NY LTANKS	Higher	2062, 0.391, SSE
AK208	SIMS METAL MUNICIPAL	472 2ND AVE	NY CBS, NY SWRCY	Lower	2073, 0.393, SW
AP209	US INFORMATION AGENC	29TH ST & 3RD AVE DO	SEMS-ARCHIVE, RCRA NonGen / NLR	Higher	2083, 0.395, SSW
AM210	FIRST BROOKLYN TRANS	611 COURT ST.	NY SWF/LF	Higher	2090, 0.396, NNW
AO211	FORMER STRAUSS AUTO	521-539 4TH AVENUE	NY BROWNFIELDS	Higher	2105, 0.399, ENE
AO212	FORMER STRAUSS AUTO	521-539 4TH AVENUE	NY BROWNFIELDS	Higher	2105, 0.399, ENE
AQ213	USPS GOWANUS SITE. F	2ND AVENUE AND 12TH	EDR MGP	Higher	2124, 0.402, NNE
AK214	BARGE: CLEAN ENERGY	SECOND AVENUE & 29TH	NY MOSF	Lower	2124, 0.402, SW
AK215	GOWANES GAS TURBINE	29TH STREET & 2ND AV	NY LTANKS, NY Spills	Lower	2124, 0.402, SW
216	CONSOLIDATED EDISON	258 23RD ST	NY LTANKS, NY Spills, NY MANIFEST	Higher	2129, 0.403, SSE
217	578 5TH AVENUE	578 5TH AVENUE	NY VCP	Higher	2211, 0.419, East
AQ218	BUG, METROPOLITAN WO	2ND AVE & 12TH STREE	NY HSWDS	Higher	2231, 0.423, NNE
AQ219	BKLYN UNION GAS /MET	2ND AVE & 12 ST /GOW	SEMS-ARCHIVE	Higher	2231, 0.423, NNE
AR220	187 15TH ST	187 15TH ST	NY LTANKS	Higher	2296, 0.435, East
AP221	US INFORMATION AGENC	830 3RD AVE	NY HSWDS	Higher	2296, 0.435, SSW
AS222	BROOKLYN WEST 06 DOS	127 2ND AVENUE	NY LTANKS, NY Spills	Higher	2362, 0.447, NNE
AT223	MIL MED SUPPLY NO. 1		FUDS	Higher	2367, 0.448, SSW
224	72 PRECINCT NYPD -DD	830 4TH AVENUE	NY LTANKS, NY Spills	Higher	2396, 0.454, SSW
AR225	GTO HOLDING CORP	550 FIFTH AVENUE	NY LTANKS	Higher	2466, 0.467, East
AU226	CITY OF NY PARKS DEP	155 BAY SY	NY LTANKS	Higher	2480, 0.470, NNW
AU227	RED HOOK PARK	155 BAY STREET	SEMS	Higher	2480, 0.470, NNW
AS228	US POSTAL SERVICE -	138 2ND AVE	RCRA-VSQG, NY LTANKS, NJ MANIFEST, NY MANIFEST	Higher	2487, 0.471, NNE
AS229	BROOKLYN NORTH 2	11 2ND AVE	NY LTANKS, NY Spills	Higher	2493, 0.472, NNE
230	244A 13TH STREET	244A 13TH STREET	NY LTANKS	Higher	2528, 0.479, ENE
AS231	MCIZ CORP.	1-25 2ND AVENUE	NY LTANKS, NY Spills	Higher	2550, 0.483, NNE
AT232	850 3RD AVE	850 3RD AVENUE	NY LTANKS, NY Spills	Higher	2553, 0.484, SSW
AT233	US GSA	850 3RD AVENUE (29TH	NY LTANKS, NY Spills	Higher	2553, 0.484, SSW
234	APARTMENT	555 5TH AVE	NY LTANKS	Higher	2565, 0.486, East

MAPPED SITES SUMMARY

Target Property Address:
74 20TH STREET
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
235	NYC DOT ASPHALT PLAN	448 HAMILTON AVE	NY LTANKS, NY Spills	Higher	2575, 0.488, North
236	498 3RD AVENUE	498 3RD AVENUE	NY LTANKS	Higher	2596, 0.492, NE
AV237	SPILL NUMBER 0300314	124 2ND AVE	NY LTANKS, NY Spills	Higher	2600, 0.492, NNE
AV238	K - METROPOLITAN MGP	124-136 SECOND AVE	NY SHWS, NY BROWNFIELDS	Higher	2600, 0.492, NNE
AV239	METROPOLITAN	124-136 SECOND AVE	NY VCP	Higher	2600, 0.492, NNE
AV240	BU-METROPOLITAN MGP	124-136 SECOND AVE	EDR MGP	Higher	2600, 0.492, NNE
241	FORMER COLUMBIA SMEL	98 LORRAINE STREET	NY SHWS	Higher	3479, 0.659, NNW
242	ROBINS DRYDOCK		FUDS	Higher	3546, 0.672, NW
243	FORMER CITIZEN GAS W	5TH STREET AND SMITH	EDR MGP	Higher	4075, 0.772, North
244	CARROLL GARDENS	CORNER OF 5TH STREET	NY DEL SHWS	Higher	4403, 0.834, North
245	PATTERSON CHEMICAL C	102 3RD ST	CORRACTS, RCRA NonGen / NLR, FINDS, ECHO	Higher	4572, 0.866, NNE
246	EVER NU METAL	471 20TH STREET	NY SHWS	Higher	4755, 0.901, SE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
DEBEVOISE CO 74 20TH ST BROOKLYN, NY 11232	CORRACTS EPA ID:: NYD091590471 RCRA-TSDF EPA ID:: NYD091590471 RCRA NonGen / NLR EPA ID:: NYD091590471 ICIS FRS ID:: 110004374114 FINDS Registry ID:: 110004374114 ECHO Registry ID: 110004374114 NY MANIFEST EPA ID: NYD091590471	NYD091590471
DECORATIVE NOVELTY 74 20TH ST - 1ST FLO BROOKLYN, NY 11232	RCRA NonGen / NLR EPA ID:: NYR000072587 FINDS Registry ID:: 110004553849 ECHO Registry ID: 110004553849	NYR000072587

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL..... National Priority List
Proposed NPL..... Proposed National Priority List Sites
NPL LIENS..... Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

EXECUTIVE SUMMARY

Federal CERCLIS list

FEDERAL FACILITY..... Federal Facility Site Information listing

Federal institutional controls / engineering controls registries

LUCIS..... Land Use Control Information System

US ENG CONTROLS..... Engineering Controls Sites List

US INST CONTROL..... Sites with Institutional Controls

Federal ERNS list

ERNS..... Emergency Response Notification System

State and tribal leaking storage tank lists

INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land

NY HIST LTANKS..... Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST..... Underground Storage Tank Listing

INDIAN UST..... Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

NY RES DECL..... Restrictive Declarations Listing

NY ENG CONTROLS..... Registry of Engineering Controls

NY INST CONTROL..... Registry of Institutional Controls

State and tribal voluntary cleanup sites

INDIAN VCP..... Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP..... Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE..... Registered Waste Tire Storage & Facility List

INDIAN ODI..... Report on the Status of Open Dumps on Indian Lands

ODI..... Open Dump Inventory

DEBRIS REGION 9..... Torres Martinez Reservation Illegal Dump Site Locations

IHS OPEN DUMPS..... Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL..... Delisted National Clandestine Laboratory Register

EXECUTIVE SUMMARY

US CDL..... National Clandestine Laboratory Register
NY PFAS..... PFAS Contamination Site Location Listing

Local Lists of Registered Storage Tanks

NY HIST UST..... Historical Petroleum Bulk Storage Database
NY HIST AST..... Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS..... Spill Liens Information
LIENS 2..... CERCLA Lien Information

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System
NY Hist Spills..... SPILLS Database
NY SPILLS 90..... SPILLS 90 data from FirstSearch
NY SPILLS 80..... SPILLS 80 data from FirstSearch

Other Ascertainable Records

DOD..... Department of Defense Sites
SCRD DRYCLEANERS..... State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR..... Financial Assurance Information
EPA WATCH LIST..... EPA WATCH LIST
2020 COR ACTION..... 2020 Corrective Action Program List
TSCA..... Toxic Substances Control Act
TRIS..... Toxic Chemical Release Inventory System
SSTS..... Section 7 Tracking Systems
ROD..... Records Of Decision
RMP..... Risk Management Plans
RAATS..... RCRA Administrative Action Tracking System
PRP..... Potentially Responsible Parties
PADS..... PCB Activity Database System
FTTS..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS..... Material Licensing Tracking System
COAL ASH DOE..... Steam-Electric Plant Operation Data
COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER..... PCB Transformer Registration Database
RADINFO..... Radiation Information Database
HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS..... Incident and Accident Data
CONSENT..... Superfund (CERCLA) Consent Decrees
INDIAN RESERV..... Indian Reservations
FUSRAP..... Formerly Utilized Sites Remedial Action Program
UMTRA..... Uranium Mill Tailings Sites
LEAD SMELTERS..... Lead Smelter Sites
US MINES..... Mines Master Index File
ABANDONED MINES..... Abandoned Mines
UXO..... Unexploded Ordnance Sites
DOCKET HWC..... Hazardous Waste Compliance Docket Listing
FUELS PROGRAM..... EPA Fuels Program Registered Listing
NY AIRS..... Air Emissions Data

EXECUTIVE SUMMARY

NY COAL ASH.....	Coal Ash Disposal Site Listing
NY DRYCLEANERS.....	Registered Drycleaners
NY E DESIGNATION.....	E DESIGNATION SITE LISTING
NY Financial Assurance.....	Financial Assurance Information Listing
NY SPDES.....	State Pollutant Discharge Elimination System
NY VAPOR REOPENED.....	Vapor Intrusion Legacy Site List
NY UIC.....	Underground Injection Control Wells
NY COOLING TOWERS.....	Registered Cooling Towers
MINES MRDS.....	Mineral Resources Data System

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Cleaner..... EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS..... Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF..... Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS list

SEMS: SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly known as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the SEMS list, as provided by EDR, and dated 01/30/2020 has revealed that there is 1 SEMS

EXECUTIVE SUMMARY

site within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
RED HOOK PARK	155 BAY STREET	NNW 1/4 - 1/2 (0.470 mi.)	AU227	596

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 01/30/2020 has revealed that there are 4 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HAMILTON AVENUE INCI Site ID: 0202241 EPA Id: NYD980768733	555 HAMILTON AVE	NNE 1/4 - 1/2 (0.267 mi.)	AB171	355
US INFORMATION AGENC Site ID: 0203254 EPA Id: NY4470000635	29TH ST & 3RD AVE DO	SSW 1/4 - 1/2 (0.395 mi.)	AP209	516
BKLYN UNION GAS /MET Site ID: 0201976 EPA Id: NYD980532006	2ND AVE & 12 ST /GOW	NNE 1/4 - 1/2 (0.423 mi.)	AQ219	558
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HAMILTON AVENUE PIER Site ID: 0203383 EPA Id: NYD986914554	18TH-19TH STREETS	NNW 0 - 1/8 (0.117 mi.)	I68	129

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 12/16/2019 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
PATTERSON CHEMICAL C	102 3RD ST	NNE 1/2 - 1 (0.866 mi.)	245	654

EXECUTIVE SUMMARY

EPA ID:: NYD980592471

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/16/2019 has revealed that there are 7 RCRA-LQG sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CON EDISON - SERVICE EPA ID:: NYP005026945	690 3RD AVE	SSE 0 - 1/8 (0.058 mi.)	C14	42
CON EDISON - MANHOLE EPA ID:: NYP004190898	19TH STREET & 3RD AV	E 0 - 1/8 (0.085 mi.)	E36	78
CON EDISON - MANHOLE EPA ID:: NYP004190906	HAMILTON AVE & 3RD A	ENE 0 - 1/8 (0.110 mi.)	E57	110
CON EDISON - SERVICE EPA ID:: NYP004733747	HAMILTON AVE & 17 ST	NE 1/8 - 1/4 (0.147 mi.)	M90	179
CON EDISON - SERVICE EPA ID:: NYP004399861	144 23 ST	S 1/8 - 1/4 (0.184 mi.)	P112	240
CON EDISON - EXCAVAT EPA ID:: NYP004324620	160 23RD ST	SSE 1/8 - 1/4 (0.209 mi.)	P130	286
CON EDISON - MANHOLE EPA ID:: NYP004860231	614 4 AVE	E 1/8 - 1/4 (0.232 mi.)	Y150	324

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/16/2019 has revealed that there are 3 RCRA-SQG sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CON EDISON - VAULT 6 EPA ID:: NYP005106366	82 18TH ST	NE 0 - 1/8 (0.094 mi.)	E39	84
MOORE MCCORMACK BUIL EPA ID:: NYR000147249	740 3RD AVE	SSW 1/8 - 1/4 (0.184 mi.)	T113	243
HOME DEPOT USA INC H EPA ID:: NYR000077016	550 HAMILTON AVE	NNE 1/8 - 1/4 (0.192 mi.)	R119	255

EXECUTIVE SUMMARY

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 12/16/2019 has revealed that there is 1 RCRA-VSQG site within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
I & J FINISHING CORP EPA ID:: NYD098843089	149 20TH ST	ESE 1/8 - 1/4 (0.137 mi.)	H84	162

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 11/11/2019 has revealed that there are 8 NY SHWS sites within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CHEMTURA 633 COURT S Class Code: Significant threat to the public health or environment - action required. Site Code: 443256	633 COURT STREET	NNW 1/4 - 1/2 (0.356 mi.)	AH197	489
182 SIGOURNEY ST Site Code: 499845	182 SIGOURNEY ST	NNW 1/4 - 1/2 (0.376 mi.)	AM204	507
K - METROPOLITAN MGP Class Code: Significant threat to the public health or environment - action required. Site Code: 372656	124-136 SECOND AVE	NNE 1/4 - 1/2 (0.492 mi.)	AV238	645
FORMER COLUMBIA SMEL Site Code: 520660	98 LORRAINE STREET	NNW 1/2 - 1 (0.659 mi.)	241	649
EVER NU METAL Site Code: 492522	471 20TH STREET	SE 1/2 - 1 (0.901 mi.)	246	658
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
FORMER MOORE MCCORMA Site Code: 439096	730 3RD AVENUE	SSW 1/8 - 1/4 (0.133 mi.)	J82	152
FORMER BARRETT MANUF Site Code: 466165	627 SMITH ST.	NNW 1/4 - 1/2 (0.314 mi.)	AG187	468
643 COURT ST. Site Code: 498440	643 COURT ST.	NNW 1/4 - 1/2 (0.322 mi.)	AH189	475

EXECUTIVE SUMMARY

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 10/09/2019 has revealed that there are 5 NY SWF/LF sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
PARTS EXPRESS INC	694-696 3RD AVE	SSE 0 - 1/8 (0.064 mi.)	C18	49
HAMILTON AVENUE INCI	555 HAMILTON AVE	NNE 1/4 - 1/2 (0.267 mi.)	AB171	355
ANTON JUNCIC ENTERP	776 3RD AVENUE	SSW 1/4 - 1/2 (0.285 mi.)	AC172	362
FIRST BROOKLYN TRANS	611 COURT ST.	NNW 1/4 - 1/2 (0.396 mi.)	AM210	518
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
SHAMROCK CONTRACTING	95-99 19TH STREET	NNW 0 - 1/8 (0.070 mi.)	F22	57

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 11/11/2019 has revealed that there are 45 NY LTANKS sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
21 ST OFF 3RD AVENUE Spill Number/Closed Date: 9312696 / 1994-01-28 Site ID: 125518 Spill Date: 1994-01-28	21 ST OFF 3RD AVENUE	SE 0 - 1/8 (0.084 mi.)	G34	74
SPILL NUMBER 0300252 Spill Number/Closed Date: 0300252 / 2003-04-08 Site ID: 295284 Spill Date: 2003-04-07	160 22ND ST	SSE 1/8 - 1/4 (0.184 mi.)	P114	244
652 4TH AVE Spill Number/Closed Date: 0803553 / 2008-10-09 Site ID: 400313 Spill Date: 2008-06-25	652 4TH AVE	ESE 1/8 - 1/4 (0.197 mi.)	U122	266
PRIVATE HOME Spill Number/Closed Date: 0704596 / 2013-07-31 Site ID: 384784 Spill Date: 2007-07-24	720 4TH AVE	SSE 1/8 - 1/4 (0.209 mi.)	S131	290
25TH ST STATION/R TR Spill Number/Closed Date: 8902919 / 2003-02-12 Site ID: 149988 Spill Date: 1989-06-21	25TH ST STATION	SSW 1/8 - 1/4 (0.220 mi.)	T139	306
NYS DEC BUREAU OF SP	737 4TH AVE	S 1/4 - 1/2 (0.294 mi.)	AD173	368

EXECUTIVE SUMMARY

Spill Number/Closed Date: 9402784 / 1994-05-26 Site ID: 315150 Spill Date: 1994-05-26				
CITGO STATION	4TH AV & 25TH ST	S 1/4 - 1/2 (0.295 mi.)	AD174	370
Spill Number/Closed Date: 9607556 / 2003-03-03 Site ID: 279274 Spill Date: 1996-09-16				
MOBIL R/S #11775	586 4TH AVENUE	E 1/4 - 1/2 (0.295 mi.)	AE175	371
Spill Number/Closed Date: 8900734 / 1991-05-06 Spill Number/Closed Date: 9210276 / 1993-08-02 Spill Number/Closed Date: 0301750 / 2003-10-02 Site ID: 77275 Site ID: 77277 Site ID: 154867 Spill Date: 1989-04-24 Spill Date: 1992-12-04 Spill Date: 2003-05-19				
GOLDEN MILLION	276-280 24TH ST	SSE 1/4 - 1/2 (0.310 mi.)	AD185	463
Spill Number/Closed Date: 0210214 / 2006-03-02 Site ID: 242528 Spill Date: 2003-01-09				
207 25TH STREET	207 25TH STREET	SSE 1/4 - 1/2 (0.310 mi.)	AD186	466
Spill Number/Closed Date: 1610374 / Not Reported Site ID: 541194 Spill Date: 1993-09-10				
HI-VOLTAGE TEST SET	3RD AVE YARD	SSW 1/4 - 1/2 (0.317 mi.)	AC188	473
Spill Number/Closed Date: 0303210 / 2003-07-03 Site ID: 148976 Spill Date: 2003-06-26				
25TH ST - 4TH AVE SU	25TH ST - 4TH AVE SU	SSE 1/4 - 1/2 (0.334 mi.)	AD193	480
Spill Number/Closed Date: 9505109 / 1995-08-11 Site ID: 213768 Spill Date: 1995-02-01				
SPILL NUMBER 0207372	3RD AVE/14TH ST	NE 1/4 - 1/2 (0.340 mi.)	AJ194	481
Spill Number/Closed Date: 0207372 / 2003-02-05 Site ID: 124766 Spill Date: 2002-10-17				
GRESCHLER HARDWARE S	660 5TH AVE	ESE 1/4 - 1/2 (0.346 mi.)	195	482
Spill Number/Closed Date: 9602471 / 1996-05-21 Site ID: 102393 Spill Date: 1996-05-21				
SUNOCO	538 3RD AVE	NE 1/4 - 1/2 (0.370 mi.)	AJ199	493
Spill Number/Closed Date: 1900028 / 2019-09-18 Site ID: 585843 Spill Date: 2019-04-01				
707 5TH AVENUE	707 5TH AVENUE	SE 1/4 - 1/2 (0.375 mi.)	203	506
Spill Number/Closed Date: 9304083 / 1993-06-30 Site ID: 132567 Spill Date: 1993-06-30				
740 5TH AVE	740 5TH AVENUE	SSE 1/4 - 1/2 (0.388 mi.)	AN205	509
Spill Number/Closed Date: 8703559 / Not Reported				

EXECUTIVE SUMMARY

Site ID: 126157 Spill Date: 1987-07-31				
TEXACO SERVICE STATI	735 5TH AVENUE	SSE 1/4 - 1/2 (0.391 mi.)	AN207	513
Spill Number/Closed Date: 9702464 / 2014-11-28				
Site ID: 161348				
Spill Date: 1997-05-28				
CONSOLIDATED EDISON	258 23RD ST	SSE 1/4 - 1/2 (0.403 mi.)	216	538
Spill Number/Closed Date: 0312353 / 2009-08-18				
Site ID: 188149				
Spill Date: 2004-02-05				
187 15TH ST	187 15TH ST	E 1/4 - 1/2 (0.435 mi.)	AR220	559
Spill Number/Closed Date: 9800504 / 1998-04-13				
Site ID: 173608				
Spill Date: 1998-04-10				
BROOKLYN WEST 06 DOS	127 2ND AVENUE	NNE 1/4 - 1/2 (0.447 mi.)	AS222	562
Spill Number/Closed Date: 0012497 / 2003-10-30				
Site ID: 154174				
Spill Date: 2001-02-22				
72 PRECINCT NYPD -DD	830 4TH AVENUE	SSW 1/4 - 1/2 (0.454 mi.)	224	577
Spill Number/Closed Date: 9514143 / 2003-10-31				
Spill Number/Closed Date: 9502759 / 2005-01-10				
Site ID: 317853				
Site ID: 95328				
Spill Date: 1996-02-05				
Spill Date: 1995-06-01				
GTO HOLDING CORP	550 FIFTH AVENUE	E 1/4 - 1/2 (0.467 mi.)	AR225	592
Spill Number/Closed Date: 9902100 / 2009-09-04				
Site ID: 60272				
Spill Date: 1999-05-24				
CITY OF NY PARKS DEP	155 BAY SY	NNW 1/4 - 1/2 (0.470 mi.)	AU226	594
Spill Number/Closed Date: 1201097 / 2015-02-04				
Site ID: 463765				
Spill Date: 2012-05-03				
US POSTAL SERVICE -	138 2ND AVE	NNE 1/4 - 1/2 (0.471 mi.)	AS228	597
Spill Number/Closed Date: 9201414 / 1992-05-20				
Spill Number/Closed Date: 9111199 / 1992-01-31				
Site ID: 294178				
Site ID: 202256				
Spill Date: 1992-05-05				
Spill Date: 1992-01-29				
BROOKLYN NORTH 2	11 2ND AVE	NNE 1/4 - 1/2 (0.472 mi.)	AS229	604
Spill Number/Closed Date: 9214380 / 2003-09-01				
Site ID: 296990				
Spill Date: 1993-03-30				
244A 13TH STREET	244A 13TH STREET	ENE 1/4 - 1/2 (0.479 mi.)	230	607
Spill Number/Closed Date: 9210439 / 1992-12-10				
Site ID: 131864				
Spill Date: 1992-12-09				
MCIZ CORP.	1-25 2ND AVENUE	NNE 1/4 - 1/2 (0.483 mi.)	AS231	608
Spill Number/Closed Date: 9603998 / 2013-07-30				
Site ID: 267560				

EXECUTIVE SUMMARY

Spill Date: 1996-06-24				
850 3RD AVE	850 3RD AVENUE	SSW 1/4 - 1/2 (0.484 mi.)	AT232	617
Spill Number/Closed Date: 9312153 / 1994-01-15				
Site ID: 161674				
Spill Date: 1994-01-15				
US GSA	850 3RD AVENUE (29TH	SSW 1/4 - 1/2 (0.484 mi.)	AT233	619
Spill Number/Closed Date: 9908767 / 2008-06-10				
Site ID: 239334				
Spill Date: 1999-10-19				
APARTMENT	555 5TH AVE	E 1/4 - 1/2 (0.486 mi.)	234	623
Spill Number/Closed Date: 0404519 / 2004-08-04				
Site ID: 106219				
Spill Date: 2004-07-27				
NYC DOT ASPHALT PLAN	448 HAMILTON AVE	N 1/4 - 1/2 (0.488 mi.)	235	624
Spill Number/Closed Date: 0302574 / Not Reported				
Spill Number/Closed Date: 9109766 / 2005-01-13				
Site ID: 209848				
Site ID: 209849				
Spill Date: 2003-06-10				
Spill Date: 1991-12-11				
498 3RD AVENUE	498 3RD AVENUE	NE 1/4 - 1/2 (0.492 mi.)	236	641
Spill Number/Closed Date: 8809911 / Not Reported				
Site ID: 66897				
Spill Date: 1989-03-14				
SPILL NUMBER 0300314	124 2ND AVE	NNE 1/4 - 1/2 (0.492 mi.)	AV237	643
Spill Number/Closed Date: 9704147 / 2003-09-01				
Site ID: 156078				
Spill Date: 1997-07-02				
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
AMERADA HESS	722 COURT STREET	NW 1/4 - 1/2 (0.304 mi.)	AF178	396
Spill Number/Closed Date: 9500858 / 2003-08-11				
Site ID: 246738				
Spill Date: 1995-04-20				
BUCKEYE TERMINALS LL	722 COURT ST	NW 1/4 - 1/2 (0.304 mi.)	AF179	399
Spill Number/Closed Date: 0107145 / 2003-08-11				
Spill Number/Closed Date: 0109487 / 2003-08-11				
Spill Number/Closed Date: 0109620 / 2003-08-11				
Spill Number/Closed Date: 0207992 / 2003-07-17				
Spill Number/Closed Date: 9102797 / 2003-08-11				
Site ID: 138969				
Site ID: 138971				
Site ID: 138972				
Site ID: 138978				
Site ID: 138981				
Spill Date: 2001-10-10				
Spill Date: 2001-12-27				
Spill Date: 2002-01-03				
Spill Date: 2002-11-01				
Spill Date: 1991-06-10				
HESS BROOKLYN TERMIN	722 COURT ST	NW 1/4 - 1/2 (0.304 mi.)	AF180	440

EXECUTIVE SUMMARY

Spill Number/Closed Date: 0310372 / 2003-12-10 Site ID: 246722 Spill Date: 2003-12-08				
AMERADA HESS	722 COURT STREET	NW 1/4 - 1/2 (0.304 mi.)	AF181	459
Spill Number/Closed Date: 9111290 / 1992-02-26 Site ID: 138982 Spill Date: 1992-02-01				
AMERADA HESS	722 COURT STREET	NW 1/4 - 1/2 (0.304 mi.)	AF182	461
Spill Number/Closed Date: 0109349 / 2003-08-11 Site ID: 138970 Spill Date: 2001-12-21				
AMERADA HESS	722 COURT STREET	NW 1/4 - 1/2 (0.304 mi.)	AF183	462
Spill Number/Closed Date: 0312168 / 2004-04-08 Site ID: 246724 Spill Date: 2004-02-02				
HESS TERMINAL RACK 1	764 COURT STREET	NW 1/4 - 1/2 (0.322 mi.)	AI190	476
Spill Number/Closed Date: 0110576 / 2002-03-04 Site ID: 253896 Spill Date: 2002-02-05				
HESS LOADING RACK	764 COURT STREET	NW 1/4 - 1/2 (0.322 mi.)	AI191	478
Spill Number/Closed Date: 0704424 / 2007-07-19 Site ID: 384569 Spill Date: 2007-07-19				
713 COURT STREET	713 COURT STREET	NW 1/4 - 1/2 (0.323 mi.)	AF192	479
Spill Number/Closed Date: 9207990 / 1995-03-22 Site ID: 280278 Spill Date: 1992-10-10				
GOUWANUS BAY	COURT ST- PIER 8	WNW 1/4 - 1/2 (0.375 mi.)	202	505
Spill Number/Closed Date: 9710375 / 1997-12-10 Site ID: 71263 Spill Date: 1997-12-10				
GOWANES GAS TURBINE	29TH STREET & 2ND AV	SW 1/4 - 1/2 (0.402 mi.)	AK215	525
Spill Number/Closed Date: 9806837 / 1998-09-03 Spill Number/Closed Date: 9705001 / 2002-03-21 Site ID: 119011 Site ID: 261797 Spill Date: 1998-09-03 Spill Date: 1997-07-25				

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 7 NY UST sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
SUNSET MANAGEMENT, L	668 THIRD AVENUE	ESE 0 - 1/8 (0.044 mi.)	B11	36
Database: UST, Date of Government Version: 12/18/2019				

EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
LINSOM SERVICE CENTE Database: UST, Date of Government Version: 12/18/2019	629 3RD AVENUE	ENE 1/8 - 1/4 (0.150 mi.)	L97	195
JETRO CASH & CARRY Database: UST, Date of Government Version: 12/18/2019	566 HAMILTON AVENUE	NE 1/8 - 1/4 (0.175 mi.)	R110	232
HOME DEPOT U.S.A., I Database: UST, Date of Government Version: 12/18/2019	550 HAMILTON AVENUE	NNE 1/8 - 1/4 (0.192 mi.)	R118	252
LOPEZ BYWAY SERVICE Database: UST, Date of Government Version: 12/18/2019	739 3RD AVENUE	S 1/8 - 1/4 (0.200 mi.)	T123	268
639 4TH AVENUE Database: UST, Date of Government Version: 12/18/2019	639 4TH AVENUE	ESE 1/8 - 1/4 (0.224 mi.)	U143	312
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
SUNSET INDUSTRIAL PA Database: UST, Date of Government Version: 12/18/2019	50 21ST STREET	WSW 0 - 1/8 (0.017 mi.)	A5	27

NY MOSF UST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF UST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY MOSF UST site within approximately 0.5 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
BUCKEYE TERMINALS LL	722 COURT ST	NW 1/4 - 1/2 (0.304 mi.)	AF179	399

NY MOSF: These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

A review of the NY MOSF list, as provided by EDR, and dated 12/18/2019 has revealed that there are 4 NY MOSF sites within approximately 0.5 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
BARGE: ELECTRA II/GO Tank Status: Unregulated/Closed Facility Id: 0-0772	THIRD AVENUE & 27TH	SW 1/4 - 1/2 (0.298 mi.)	176	395
BUCKEYE TERMINALS, L Tank Status: Active Facility Id: 2-1520	722 COURT STREET	NW 1/4 - 1/2 (0.304 mi.)	AF177	396
GOWANUS QUICK ENERGY Tank Status: Active Facility Id: 0-1069	420 SECOND AVENUE	SW 1/4 - 1/2 (0.368 mi.)	AK198	493
BARGE: CLEAN ENERGY Tank Status: Unregulated/Closed Tank Status: Inactive	SECOND AVENUE & 29TH	SW 1/4 - 1/2 (0.402 mi.)	AK214	524

EXECUTIVE SUMMARY

Facility Id: 0-0538

Facility Id: 0-0539

Facility Id: 0-0541

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 12/18/2019 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
NEW YORK POWER AUTHO Facility Status: Active CBS Number: 2-000378	730 3RD AVE AND 23RD	SSW 1/8 - 1/4 (0.133 mi.)	J83	159

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 16 NY AST sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
INTERNATIONAL TRUCK Database: AST, Date of Government Version: 12/18/2019 Facility Id: 2-609252	92 20TH STREET	ESE 0 - 1/8 (0.012 mi.)	A4	24
LINSOM SERVICE CENTE Database: AST, Date of Government Version: 12/18/2019 Facility Id: 2-610184	687 3RD AVENUE	SE 0 - 1/8 (0.084 mi.)	G32	71
TRI-STATE TRUCK & TR Database: AST, Date of Government Version: 12/18/2019 Facility Id: 2-612335	84 18TH STREET	NE 0 - 1/8 (0.091 mi.)	E37	81
20TH STREET COLLISIO Database: AST, Date of Government Version: 12/18/2019 Facility Id: 2-612181	135 20TH STREET	ESE 0 - 1/8 (0.104 mi.)	H50	98
3RD AVE AUTO REPAIR Database: AST, Date of Government Version: 12/18/2019 Facility Id: 2-611566	703 3RD AVE	S 0 - 1/8 (0.121 mi.)	K69	131
STEPHEN IMPORTS INC. Database: AST, Date of Government Version: 12/18/2019 Facility Id: 2-283584	150 20TH STREET	SE 1/8 - 1/4 (0.145 mi.)	N87	169
LINSOM SERVICE CENTE Database: AST, Date of Government Version: 12/18/2019 Facility Id: 2-157309	629 3RD AVENUE	ENE 1/8 - 1/4 (0.150 mi.)	L96	190
VELAZQUEZ AUTO REPAI Database: AST, Date of Government Version: 12/18/2019 Facility Id: 2-611397	134 18TH STREET	E 1/8 - 1/4 (0.153 mi.)	O98	207
HK AUTO REPAIR INC. Database: AST, Date of Government Version: 12/18/2019	163 21ST STREET	SE 1/8 - 1/4 (0.174 mi.)	N109	229

EXECUTIVE SUMMARY

Facility Id: 2-611323				
GLADYS PEREZ	144 17TH STREET	E 1/8 - 1/4 (0.185 mi.)	O115	245
Database: AST, Date of Government Version: 12/18/2019				
Facility Id: 2-611458				
LOPEZ BYWAY SERVICE	739 3RD AVENUE	S 1/8 - 1/4 (0.200 mi.)	T124	274
Database: AST, Date of Government Version: 12/18/2019				
Facility Id: 2-610177				
Facility Id: 2-608187				
BROOKLYN CULTURAL CE	675 4TH AVENUE	SE 1/8 - 1/4 (0.212 mi.)	W133	294
Database: AST, Date of Government Version: 12/18/2019				
Facility Id: 2-054666				
SLOPE ON 4TH LLC	647 4TH AVENUE	ESE 1/8 - 1/4 (0.219 mi.)	U138	304
Database: AST, Date of Government Version: 12/18/2019				
Facility Id: 2-212962				
PARK SLOPE AUTO CENT	651 4TH AVENUE	ESE 1/8 - 1/4 (0.220 mi.)	140	307
Database: AST, Date of Government Version: 12/18/2019				
Facility Id: 2-605798				

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
18TH-19TH RELATY CO	79 19TH STREET	N 0 - 1/8 (0.076 mi.)	D28	64
Database: AST, Date of Government Version: 12/18/2019				
Facility Id: 2-366013				
FEDERAL EXPRESS - FB	51 20TH STREET	NW 1/8 - 1/4 (0.146 mi.)	I88	172
Database: AST, Date of Government Version: 12/18/2019				
Facility Id: 2-610915				

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
NEW YORK POWER AUTHO	730 3RD AVE AND 23RD	SSW 1/8 - 1/4 (0.133 mi.)	J83	159
Facility Status: 1				
Facility Status: 1				
CBS Number: 2-000378				

NY MOSF AST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is

EXECUTIVE SUMMARY

1 NY MOSF AST site within approximately 0.5 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
BUCKEYE TERMINALS LL Facility Status: 1 Facility Status: 1 Facility Status: 2 Facility Status: 4	722 COURT ST	NW 1/4 - 1/2 (0.304 mi.)	AF179	399

NY TANKS: This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

A review of the NY TANKS list, as provided by EDR, has revealed that there is 1 NY TANKS site within approximately 0.25 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
NEW YORK POWER AUTHO Database: TANKS, Date of Government Version: 12/18/2019 Facility Id: 2-610581 Site Status: Active	730 3RD AVE AND 23RD	SSW 1/8 - 1/4 (0.133 mi.)	J83	159

State and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 8 NY VCP sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
635 4TH AVENUE Database: VCP NYC, Date of Government Version: 08/20/2019	635 4TH AVENUE	ESE 1/8 - 1/4 (0.231 mi.)	U148	324
691 4TH AVENUE Database: VCP NYC, Date of Government Version: 08/20/2019	691 4TH AVENUE	SE 1/8 - 1/4 (0.231 mi.)	W149	324
609-619 4TH AVENUE Database: VCP NYC, Date of Government Version: 08/20/2019	609 4TH AVENUE	E 1/4 - 1/2 (0.258 mi.)	Y170	354
573-581 4TH AVENUE Database: VCP NYC, Date of Government Version: 08/20/2019	581 4TH AVENUE	E 1/4 - 1/2 (0.305 mi.)	AE184	463
WITCO CORPORATION BR Database: VCP, Date of Government Version: 11/11/2019 Site Code: 58750	633 AND 688-700 COUR	NW 1/4 - 1/2 (0.371 mi.)	AL201	504
535 4TH AVENUE Database: VCP NYC, Date of Government Version: 08/20/2019	535 4TH AVENUE	ENE 1/4 - 1/2 (0.389 mi.)	AO206	513
578 5TH AVENUE Database: VCP NYC, Date of Government Version: 08/20/2019	578 5TH AVENUE	E 1/4 - 1/2 (0.419 mi.)	217	556
METROPOLITAN Database: VCP, Date of Government Version: 11/11/2019	124-136 SECOND AVE	NNE 1/4 - 1/2 (0.492 mi.)	AV239	648

EXECUTIVE SUMMARY

Site Code: 57308

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 11/11/2019 has revealed that there are 5 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
FORMER STRAUSS AUTO Site Code: 517274	521-539 4TH AVENUE	ENE 1/4 - 1/2 (0.399 mi.)	AO211	519
FORMER STRAUSS AUTO Site Code: 493274	521-539 4TH AVENUE	ENE 1/4 - 1/2 (0.399 mi.)	AO212	521
K - METROPOLITAN MGP Site Code: 57384	124-136 SECOND AVE	NNE 1/4 - 1/2 (0.492 mi.)	AV238	645
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
FORMER BARRETT MANUF Site Code: 476652	627 SMITH ST.	NNW 1/4 - 1/2 (0.314 mi.)	AG187	468
610 SMITH STREET Site Code: 507490	610 SMITH STREET	NNW 1/4 - 1/2 (0.354 mi.)	AG196	483

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

Registered Recycling Facility List from the Department of Environmental Conservation.

A review of the NY SWRCY list, as provided by EDR, and dated 10/09/2019 has revealed that there is 1 NY SWRCY site within approximately 0.5 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
SIMS METAL MUNICIPAL	472 2ND AVE	SW 1/4 - 1/2 (0.393 mi.)	AK208	515

Local Lists of Hazardous waste / Contaminated Sites

NY DEL SHWS: A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

A review of the NY DEL SHWS list, as provided by EDR, and dated 11/11/2019 has revealed that there are 2 NY DEL SHWS sites within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CHEM TURA	688-700 COURT ST	NW 1/4 - 1/2 (0.371 mi.)	AL200	495

EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CARROLL GARDENS Site Code Id: 224012	CORNER OF 5TH STREET	N 1/2 - 1 (0.834 mi.)	244	652

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 11/11/2019 has revealed that there are 25 NY Spills sites within approximately 0.125 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
MH 5578 Spill Number/Closed Date: 9901948 / 1999-07-20 Site ID: 105607 Spill Date: 1999-05-20	3RD AVE/20TH ST	ESE 0 - 1/8 (0.043 mi.)	B9	34
NW CORNER OF Spill Number/Closed Date: 9606647 / 1996-08-23 Site ID: 179247 Spill Date: 1996-08-23	63RD ST AT 3RD AVE	S 0 - 1/8 (0.054 mi.)	C12	40
ATLAS GAS STATION Spill Number/Closed Date: 0101052 / 2003-11-17 Site ID: 237012 Spill Date: 2001-04-27	20TH ST & 3RD AVE	ESE 0 - 1/8 (0.069 mi.)	B21	56
GOWANUS EXPWY/65TH S Spill Number/Closed Date: 9416534 / 1995-03-22 Spill Number/Closed Date: 9416541 / 1995-03-22 Site ID: 132556 Site ID: 132557 Spill Date: 1995-03-22	GOWANUS EXPWY/65TH S	E 0 - 1/8 (0.071 mi.)	B23	57
SPILL NUMBER 0306006 Spill Number/Closed Date: 0306006 / 2003-10-03 Site ID: 78565 Spill Date: 2003-09-06	3RD AVE & 21ST ST	SE 0 - 1/8 (0.075 mi.)	G26	62
UNDER TRESSEL Spill Number/Closed Date: 0402503 / 2004-06-09 Site ID: 263962 Spill Date: 2004-06-08	21ST & 3RD AVE	SE 0 - 1/8 (0.075 mi.)	G27	63
95 22ND STREET Spill Number/Closed Date: 9503163 / 1995-06-13 Site ID: 266690 Spill Date: 1995-06-13	95 22ND ST & 3RD AVE	S 0 - 1/8 (0.077 mi.)	C29	66
GOWANUS BAY Spill Number/Closed Date: 9708594 / 2001-11-08 Spill Number/Closed Date: 9808774 / 2002-10-28 Site ID: 297345 Site ID: 297346	22ND ST & 3RD AVE	SSE 0 - 1/8 (0.080 mi.)	C30	68

EXECUTIVE SUMMARY

Spill Date: 1997-10-22 Spill Date: 1998-10-14				
MANHOLE 46454	OPPOSITE 82 18TH ST	NE 0 - 1/8 (0.094 mi.)	E40	85
Spill Number/Closed Date: 1311976 / 2014-03-24 Site ID: 492912 Spill Date: 2014-03-24				
MANHOLE 5580	3RD AVE IFO 702 22ND	S 0 - 1/8 (0.096 mi.)	C42	87
Spill Number/Closed Date: 0205502 / 2002-10-29 Site ID: 260360 Spill Date: 2002-08-26				
MANHOLE 5580	3RD AVE/22ND ST	S 0 - 1/8 (0.096 mi.)	C43	88
Spill Number/Closed Date: 9809002 / 2002-10-30 Spill Number/Closed Date: 9911863 / 2002-03-05 Site ID: 285391 Site ID: 285392 Spill Date: 1998-10-19 Spill Date: 2000-01-12				
SPILL NUMBER 9807662	3RD AVENUE & 22ND ST	S 0 - 1/8 (0.096 mi.)	C44	90
Spill Number/Closed Date: 9807662 / 2002-12-24 Site ID: 313922 Spill Date: 1998-09-23				
SB46706	133 20TH ST	ESE 0 - 1/8 (0.100 mi.)	H45	91
Spill Number/Closed Date: 0006685 / 2001-11-26 Site ID: 122446 Spill Date: 2000-09-06				
EDWARD T MINOR CO	133 22ND ST	SSE 0 - 1/8 (0.109 mi.)	G53	105
Spill Number/Closed Date: 0104859 / 2001-10-25 Site ID: 326265 Spill Date: 2001-08-06				
TRANSFORMER VAULT -	18TH ST & HAMILTON A	ENE 0 - 1/8 (0.110 mi.)	E54	106
Spill Number/Closed Date: 1702659 / 2017-09-06 Site ID: 552802 Spill Date: 2017-06-18				
SEWER	18TH ST AND HAMILTON	ENE 0 - 1/8 (0.110 mi.)	E55	107
Spill Number/Closed Date: 1311937 / 2014-03-24 Site ID: 492873 Spill Date: 2014-03-21				
SPILL NUMBER 0304223	HAMILTON AVE & 18TH	ENE 0 - 1/8 (0.110 mi.)	E56	109
Spill Number/Closed Date: 0304223 / 2003-08-27 Site ID: 210426 Spill Date: 2003-07-22				
POWER PLANT - JOSEPH	3RD AVE 23 ST	SSW 0 - 1/8 (0.115 mi.)	J59	117
Spill Number/Closed Date: 1504045 / 2015-07-15 Site ID: 510374 Spill Date: 2015-07-13				
MANHOLE #55605	3RD AVE & 18TH ST	ENE 0 - 1/8 (0.117 mi.)	L65	125
Spill Number/Closed Date: 0304282 / 2003-08-27 Site ID: 320223 Spill Date: 2003-07-22				
VS 6601 HAS 50 GAL D	3 AVENUE & 18 STREET	ENE 0 - 1/8 (0.117 mi.)	L66	126
Spill Number/Closed Date: 0705905 / 2007-09-20				

EXECUTIVE SUMMARY

Spill Number/Closed Date: 0706746 / 2007-11-08
 Site ID: 386318
 Site ID: 387320
 Spill Date: 2007-08-24
 Spill Date: 2007-09-18

ROADWAY 18TH ST AND 3RD AVE ENE 0 - 1/8 (0.117 mi.) L67 128
 Spill Number/Closed Date: 0910817 / 2010-01-06
 Site ID: 423587
 Spill Date: 2010-01-06

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
VERIZON Spill Number/Closed Date: 0211531 / 2003-02-21 Site ID: 74461 Spill Date: 2003-02-20	60 21ST	WSW 0 - 1/8 (0.017 mi.)	A6	29
KAMPCO SUPPLY Spill Number/Closed Date: 0700053 / 2007-04-03 Site ID: 379298 Spill Date: 2007-03-29	80 21ST STREET	SW 0 - 1/8 (0.020 mi.)	A8	33
SUNSET INDUSTRIAL PA Spill Number/Closed Date: 1810300 / Not Reported Site ID: 581187 Spill Date: 2018-06-12	50 20TH ST	NNW 0 - 1/8 (0.063 mi.)	F17	48
73 20TH ST Spill Number/Closed Date: 1503309 / 2017-02-14 Site ID: 509607 Spill Date: 2015-06-25	73 20TH ST	NW 0 - 1/8 (0.109 mi.)	I52	101

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/16/2019 has revealed that there are 47 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
NYSDOT GOWANUS EXPWY EPA ID:: NYR000030445	3RD AVE & HAMILTON	ENE 0 - 1/8 (0.060 mi.)	E16	45
3RD AVENUE AUTO PART EPA ID:: NYD091586040	694 3RD AVE	SSE 0 - 1/8 (0.064 mi.)	C19	50
SCRAP KING USA INC EPA ID:: NYR000207803	99 19TH ST	ENE 0 - 1/8 (0.072 mi.)	E24	59
CON EDISON EPA ID:: NYP004843179	64 21ST ST & 3RD AVE	SE 0 - 1/8 (0.083 mi.)	G31	70
CON EDISON MANHOLE:	19TH ST & 3RD AVE MH	E 0 - 1/8 (0.085 mi.)	E35	75

EXECUTIVE SUMMARY

EPA ID:: NYP004190864				
CON EDISON MANHOLE:	84 18 TH ST OPPOSITE	NE 0 - 1/8 (0.091 mi.)	E38	83
EPA ID:: NYP004297388				
CON EDISON	647 3 AVE	E 0 - 1/8 (0.101 mi.)	H46	93
EPA ID:: NYP004885154				
CON EDISON	18TH ST & HAMILTON A	ENE 0 - 1/8 (0.110 mi.)	E58	115
EPA ID:: NYP004190856				
CON EDISON SPLICE BO	709 3RD AVE	S 0 - 1/8 (0.117 mi.)	K62	121
EPA ID:: NYP004328290				
CON EDISON SERVICE B	137 22ND ST	SSE 0 - 1/8 (0.117 mi.)	G63	123
EPA ID:: NYP004557815				
NYSDOT	HAMILTON AVE & 16TH	S 0 - 1/8 (0.121 mi.)	K71	134
EPA ID:: NYR000017087				
NYSDOT D257588	3RD AVE & 18TH ST	NE 1/8 - 1/4 (0.126 mi.)	L72	136
EPA ID:: NYR000039123				
NYSDOT	3RD AVE & 19TH ST	E 1/8 - 1/4 (0.128 mi.)	L75	141
EPA ID:: NYD986899722				
SASUN JEWELRY INC	134 22ND ST	SSE 1/8 - 1/4 (0.130 mi.)	K76	143
EPA ID:: NYR000040857				
CON EDISON	637 3RD AVE	E 1/8 - 1/4 (0.131 mi.)	L79	148
EPA ID:: NYP004746996				
CON EDISON	3RD AVE & 23RD ST	S 1/8 - 1/4 (0.132 mi.)	J81	150
EPA ID:: NYP004197745				
CON EDISON	HAMILTON AVE & 17TH	NE 1/8 - 1/4 (0.147 mi.)	M91	181
EPA ID:: NYP004190914				
CON EDISON	123 18TH ST	E 1/8 - 1/4 (0.148 mi.)	L93	186
EPA ID:: NYP004845711				
CON EDISON	134 17TH ST	ENE 1/8 - 1/4 (0.172 mi.)	Q105	217
EPA ID:: NYP004444014				
COLONIAL MIRROR & GL	163 20TH ST	ESE 1/8 - 1/4 (0.173 mi.)	N107	221
EPA ID:: NYD987037785				
ADELE ROOTSTEIN USA	145 18TH ST	E 1/8 - 1/4 (0.173 mi.)	O108	225
EPA ID:: NYD986946796				
B B R CONTRACTING CO	163 22ND ST	SSE 1/8 - 1/4 (0.175 mi.)	S111	236
EPA ID:: NYR000064733				
CON EDISON SERVICE B	678 4TH AVE	SE 1/8 - 1/4 (0.187 mi.)	N116	248
EPA ID:: NYP004328316				
CON EDISON SERVICE B	668 4TH AVE	ESE 1/8 - 1/4 (0.188 mi.)	N117	250
EPA ID:: NYP004328324				
CON ED - MH 67496	F/O 117-119 25TH ST	SSW 1/8 - 1/4 (0.197 mi.)	T120	262
EPA ID:: NYP004012068				
CON ED - MH 46939	F/O #117 - 25 ST	SSW 1/8 - 1/4 (0.197 mi.)	T121	264
EPA ID:: NYP004012472				
CON EDISON SERVICE B	642 4TH AVE	ESE 1/8 - 1/4 (0.202 mi.)	U125	279
EPA ID:: NYP004329140				
CON EDISON SERVICE B	192 24TH ST	S 1/8 - 1/4 (0.203 mi.)	V126	282

EXECUTIVE SUMMARY

EPA ID:: NYP004538575				
CON EDISON SERVICE B	112-14 E 19TH ST & 4	ESE 1/8 - 1/4 (0.207 mi.)	U128	284
EPA ID:: NYP004511440				
CON EDISON SERVICE B	235-37 4TH AVE & 19T	ESE 1/8 - 1/4 (0.207 mi.)	U129	285
EPA ID:: NYP004511465				
NYNEX-MANHOLE	4TH AVE & 22ND ST	SSE 1/8 - 1/4 (0.210 mi.)	S132	291
EPA ID:: NYP000919563				
CON EDISON	162 23RD ST	SSE 1/8 - 1/4 (0.213 mi.)	P136	298
EPA ID:: NYP004758991				
NYC PARKS & REC - CO	30-26 W 25TH ST	SSW 1/8 - 1/4 (0.218 mi.)	137	300
EPA ID:: NYR000005652				
CON EDISON SERVICE B	683 4TH AVE	SE 1/8 - 1/4 (0.226 mi.)	W146	320
EPA ID:: NYP004313391				
SUNOCO SERVICE STATI	623 FOURTH AVE	ESE 1/8 - 1/4 (0.230 mi.)	U147	322
EPA ID:: NYD000816421				
NYSDEC/SPILLS	734 4TH AVE	SSE 1/8 - 1/4 (0.234 mi.)	X155	330
EPA ID:: NYP000958355				
NYSDOT	HAMILTON AVE & 16TH	NE 1/8 - 1/4 (0.237 mi.)	Z157	334
EPA ID:: NYR000017095				
CON EDISON SERVICE B	169 25TH ST	S 1/8 - 1/4 (0.237 mi.)	V158	337
EPA ID:: NYP004382230				
CON EDISON SERVICE B	115-17 E 23RD ST & 4	SSE 1/8 - 1/4 (0.238 mi.)	X160	340
EPA ID:: NYP004510004				
CON EDISON SERVICE B	127-29 E 23RD ST & 4	SSE 1/8 - 1/4 (0.238 mi.)	X161	341
EPA ID:: NYP004511606				
CON EDISON SERVICE B	104 E 23RD ST & 4TH	SSE 1/8 - 1/4 (0.238 mi.)	X162	342
EPA ID:: NYP004510020				
CON EDISON SERVICE B	313-21 4TH AVE & 23R	SSE 1/8 - 1/4 (0.238 mi.)	X163	343
EPA ID:: NYP004268629				
WHITE TOP	11-16 - 11-17	NE 1/8 - 1/4 (0.241 mi.)	Z165	347
EPA ID:: NYR000005710				
CON EDISON SERVICE B	60 16TH ST	ENE 1/8 - 1/4 (0.246 mi.)	AA169	353
EPA ID:: NYP004538997				
Lower Elevation	Address	Direction / Distance	Map ID	Page
DECORATIVE NOVELTY C	65 19TH ST	NNE 0 - 1/8 (0.068 mi.)	D20	52
EPA ID:: NYD987025038				
FEDERAL EXPRESS CORP	51 20TH ST	NW 1/8 - 1/4 (0.146 mi.)	I89	176
EPA ID:: NYD986904803				
CON EDISON - TRF 26	20 ST C32W 4TH AVE 2	NW 1/8 - 1/4 (0.155 mi.)	I100	211
EPA ID:: NYP004091849				

EXECUTIVE SUMMARY

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 11/12/2019 has revealed that there are 2 FUDS sites within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
MIL MED SUPPLY NO. 1		SSW 1/4 - 1/2 (0.448 mi.)	AT223	577
ROBINS DRYDOCK		NW 1/2 - 1 (0.672 mi.)	242	651

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there are 3 NY HSWDS sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
BUG, METROPOLITAN WO Facility Id: HS2014	2ND AVE & 12TH STREE	NNE 1/4 - 1/2 (0.423 mi.)	AQ218	556
US INFORMATION AGENC	830 3RD AVE	SSW 1/4 - 1/2 (0.435 mi.)	AP221	560
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HAMILTON AVE PIERS Facility Id: HS2031	19TH & 18TH STREETS	NNW 1/8 - 1/4 (0.225 mi.)	144	317

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 66 NY MANIFEST sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CON EDISON - SERVICE EPA ID: NYP005026945	690 3RD AVE	SSE 0 - 1/8 (0.058 mi.)	C13	41
CON EDISON EPA ID: NYP004498978	73-19 72 ST	NNE 0 - 1/8 (0.059 mi.)	D15	43
NYSDOT GOWANUS EXPWY EPA ID: NYR000030445	3RD AVE & HAMILTON	ENE 0 - 1/8 (0.060 mi.)	E16	45
CON EDISON EPA ID: NYP004476515	109 19 ST	ENE 0 - 1/8 (0.075 mi.)	E25	61
CON EDISON MANHOLE: EPA ID: NYP004190864	19TH ST & 3RD AVE MH	E 0 - 1/8 (0.085 mi.)	E35	75
CON EDISON	82 18TH ST	NE 0 - 1/8 (0.094 mi.)	E41	86

EXECUTIVE SUMMARY

EPA ID: NYP005106366				
CON EDISON	647 3 AVENUE	E 0 - 1/8 (0.101 mi.)	H47	94
EPA ID: NYP004333589				
CON ED	647 3RD AVE	E 0 - 1/8 (0.101 mi.)	H48	96
EPA ID: NYP004885154				
CON EDISON	100 18 ST	ENE 0 - 1/8 (0.108 mi.)	E51	100
EPA ID: NYP004675740				
CON EDISON - MANHOLE	HAMILTON AVE & 3RD A	ENE 0 - 1/8 (0.110 mi.)	E57	110
EPA ID: NYP004190906				
CON EDISON	18TH ST & HAMILTON A	ENE 0 - 1/8 (0.110 mi.)	E58	115
EPA ID: NYP004190856				
CON EDISON	123-19 ST	E 0 - 1/8 (0.115 mi.)	H60	118
EPA ID: NYP004584017				
NYCDEP	27 23 16TH ST	SSW 0 - 1/8 (0.116 mi.)	J61	119
EPA ID: NYP003661386				
CON EDISON SPLICE BO	709 3RD AVE	S 0 - 1/8 (0.117 mi.)	K62	121
EPA ID: NYP004328290				
CON EDISON	137 22ND ST	SSE 0 - 1/8 (0.117 mi.)	G64	124
EPA ID: NYP004557815				
NYSDOT	703-709 THIRD AVE	S 0 - 1/8 (0.121 mi.)	K70	133
EPA ID: NYR000017087				
NYCDEP	64 23RD AVE	S 1/8 - 1/4 (0.126 mi.)	J73	138
EPA ID: NYP010001717				
CON EDISON	146 20 ST	SE 1/8 - 1/4 (0.127 mi.)	H74	140
EPA ID: NYP004624169				
CON EDISON	134 22 ST	SSE 1/8 - 1/4 (0.130 mi.)	K77	145
EPA ID: NYP004623039				
CON EDISON	637 3RD AVE	E 1/8 - 1/4 (0.131 mi.)	L78	146
EPA ID: NYP004746996				
CON EDISON	3RD AVE & 23RD ST	S 1/8 - 1/4 (0.132 mi.)	J81	150
EPA ID: NYP004197745				
I & J FINISHING CORP	149 20TH ST	ESE 1/8 - 1/4 (0.137 mi.)	H84	162
EPA ID: NYD098843089				
CON EDISON	24-17 64 ST	NE 1/8 - 1/4 (0.145 mi.)	M86	168
EPA ID: NYP004541662				
CON EDISON	HAMILTON AVE & 17TH	NE 1/8 - 1/4 (0.147 mi.)	M91	181
EPA ID: NYP004190914				
CON EDISON	123 18TH ST	E 1/8 - 1/4 (0.148 mi.)	L94	187
EPA ID: NYP004845711				
CON EDISON	HAMILTON AVE & 17TH	NE 1/8 - 1/4 (0.162 mi.)	M101	212
EPA ID: NYP004733739				
CON EDISON	162 20 ST	SE 1/8 - 1/4 (0.164 mi.)	N102	213
EPA ID: NYP004624151				
CON EDISON	151 23 ST	SSE 1/8 - 1/4 (0.169 mi.)	P103	215
EPA ID: NYP004631081				
CON EDISON	134 17TH ST	ENE 1/8 - 1/4 (0.172 mi.)	Q105	217

EXECUTIVE SUMMARY

EPA ID: NYP004444014				
CONSOLIDATED EDISON	V4652 134 E 23RD ST	S 1/8 - 1/4 (0.173 mi.)	P106	220
EPA ID: NYP000927418				
COLONIAL MIRROR & GL	163 20TH ST	ESE 1/8 - 1/4 (0.173 mi.)	N107	221
EPA ID: NYD987037785				
ADELE ROOTSTEIN USA	145 18TH ST	E 1/8 - 1/4 (0.173 mi.)	O108	225
EPA ID: NYD986946796				
B B R CONTRACTING CO	163 22ND ST	SSE 1/8 - 1/4 (0.175 mi.)	S111	236
EPA ID: NYR000064733				
CON EDISON - SERVICE	144 23 ST	S 1/8 - 1/4 (0.184 mi.)	P112	240
EPA ID: NYP004399861				
CON EDISON SERVICE B	678 4TH AVE	SE 1/8 - 1/4 (0.187 mi.)	N116	248
EPA ID: NYP004328316				
CON EDISON SERVICE B	668 4TH AVE	ESE 1/8 - 1/4 (0.188 mi.)	N117	250
EPA ID: NYP004328324				
HOME DEPOT USA INC H	550 HAMILTON AVE	NNE 1/8 - 1/4 (0.192 mi.)	R119	255
EPA ID: NYR000077016				
CON ED - MH 67496	F/O 117-119 25TH ST	SSW 1/8 - 1/4 (0.197 mi.)	T120	262
EPA ID: NYP004012068				
CON ED - MH 46939	F/O #117 - 25 ST	SSW 1/8 - 1/4 (0.197 mi.)	T121	264
EPA ID: NYP004012472				
CON EDISON SERVICE B	642 4TH AVE	ESE 1/8 - 1/4 (0.202 mi.)	U125	279
EPA ID: NYP004329140				
CON EDISON	192 24TH ST	S 1/8 - 1/4 (0.203 mi.)	V127	283
EPA ID: NYP004538575				
CON EDISON - EXCAVAT	160 23RD ST	SSE 1/8 - 1/4 (0.209 mi.)	P130	286
EPA ID: NYP004324620				
NYNEX-MANHOLE	4TH AVE & 22ND ST	SSE 1/8 - 1/4 (0.210 mi.)	S132	291
EPA ID: NYP000919563				
CON EDISON	162 23RD ST	SSE 1/8 - 1/4 (0.213 mi.)	P135	297
EPA ID: NYP004758991				
NYC PARKS & REC - CO	30-26 W 25TH ST	SSW 1/8 - 1/4 (0.218 mi.)	137	300
EPA ID: NYR000005652				
CON EDISON	155 25 ST	S 1/8 - 1/4 (0.222 mi.)	V141	310
EPA ID: NYP004632295				
CONSOLIDATED EDISON	3RD AVE & 25TH ST EX	SSW 1/8 - 1/4 (0.224 mi.)	T142	311
EPA ID: NYP004142469				
CON EDISON	174-23 ST	SSE 1/8 - 1/4 (0.226 mi.)	X145	318
EPA ID: NYP004592648				
CON EDISON SERVICE B	683 4TH AVE	SE 1/8 - 1/4 (0.226 mi.)	W146	320
EPA ID: NYP004313391				
CON ED	614 4 AVE	E 1/8 - 1/4 (0.232 mi.)	Y152	327
EPA ID: NYP004860231				
CON EDISON	F/O 12 16 MCDONAL AV	NE 1/8 - 1/4 (0.233 mi.)	Z154	329
EPA ID: NYP004698064				
NYSDEC/SPILLS	734 4TH AVE	SSE 1/8 - 1/4 (0.234 mi.)	X155	330

EXECUTIVE SUMMARY

EPA ID: NYP000958355				
CON EDISON	139 PROSPECT AVE	ENE 1/8 - 1/4 (0.234 mi.)	AA156	333
EPA ID: NYP004620183				
NYSDOT	HAMILTON AVE & 16TH	NE 1/8 - 1/4 (0.237 mi.)	Z157	334
EPA ID: NYR000017095				
CON EDISON	F/O # 169 25TH STREE	S 1/8 - 1/4 (0.237 mi.)	V159	338
EPA ID: NYP004382248				
CON EDISON SERVICE B	313-21 4TH AVE & 23R	SSE 1/8 - 1/4 (0.238 mi.)	X163	343
EPA ID: NYP004268629				
NYC DEP HAZ MAT	HAMILTON & SECOND AV	NNE 1/8 - 1/4 (0.239 mi.)	AB164	346
EPA ID: NYP003662343				
NYCDEP	16TH & HAMILTON AVE	NNE 1/8 - 1/4 (0.241 mi.)	Z166	349
EPA ID: NYP000776542				
CONSOLIDATED EDISON	16TH ST & 3RD AVE	NE 1/8 - 1/4 (0.246 mi.)	167	351
EPA ID: NYP004060166				
CON EDISON	60 16TH ST	ENE 1/8 - 1/4 (0.246 mi.)	AA168	352
EPA ID: NYP004538997				
Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	27 21 ST	0 - 1/8 (0.000 mi.)	A3	23
EPA ID: NYP004588141				
VERIZON	60 21ST	WSW 0 - 1/8 (0.017 mi.)	A6	29
EPA ID: NYP000954289				
CON EDISON	64 21ST ST & 3RD AVE	WSW 0 - 1/8 (0.017 mi.)	A7	31
EPA ID: NYP004843179				
DECORATIVE NOVELTY C	65 19TH ST	NNE 0 - 1/8 (0.068 mi.)	D20	52
EPA ID: NYD987025038				
NORTHROP/US CUSTOMS	18 20TH ST	NW 1/8 - 1/4 (0.145 mi.)	I85	167
EPA ID: NYP000891168				
CONSOLIDATED EDISON	20 ST C32W 4TH AVE 2	NW 1/8 - 1/4 (0.155 mi.)	I99	209
EPA ID: NYP004091849				

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there is 1 PA MANIFEST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - 22ND ST	181 22ND STREET	SE 1/8 - 1/4 (0.233 mi.)	W153	328
Generator EPA Id: NYP005030812				

EXECUTIVE SUMMARY

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there is 1 RI MANIFEST site within approximately 0.25 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
FEDERAL EXPRESS CORP EPA Id: NYD986904803 Manifest Document Number: RIS0076689	51 20TH ST	NW 1/8 - 1/4 (0.146 mi.)	I89	176

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 12 NJ MANIFEST sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CON EDISON MANHOLE: EPA Id: NYP004190864	19TH ST & 3RD AVE MH	E 0 - 1/8 (0.085 mi.)	E35	75
CON EDISON - MANHOLE EPA Id: NYP004190898	19TH STREET & 3RD AV	E 0 - 1/8 (0.085 mi.)	E36	78
CON EDISON EPA Id: NYP004885154	647 3 AVE	E 0 - 1/8 (0.101 mi.)	H49	96
CON EDISON - MANHOLE EPA Id: NYP004190906	HAMILTON AVE & 3RD A	ENE 0 - 1/8 (0.110 mi.)	E57	110
CON EDISON EPA Id: NYP004746996	637 3RD AVE	E 1/8 - 1/4 (0.131 mi.)	L80	149
CON EDISON EPA Id: NYP004190914	HAMILTON AVE & 17TH	NE 1/8 - 1/4 (0.147 mi.)	M91	181
CON EDISON - SERVICE EPA Id: NYP004733747	HAMILTON AVE & 17 ST	NE 1/8 - 1/4 (0.147 mi.)	M92	185
CON EDISON EPA Id: NYP004845711	123 18TH ST	E 1/8 - 1/4 (0.148 mi.)	L95	189
CON EDISON EPA Id: NYP004444014	134 17TH ST	ENE 1/8 - 1/4 (0.172 mi.)	Q104	216
HOME DEPOT USA INC H EPA Id: NYR000077016	550 HAMILTON AVE	NNE 1/8 - 1/4 (0.192 mi.)	R119	255
CON EDISON EPA Id: NYP004758991	162 23RD ST	SSE 1/8 - 1/4 (0.213 mi.)	P134	296
CON EDISON - MANHOLE EPA Id: NYP004860231	614 4 AVE	E 1/8 - 1/4 (0.232 mi.)	Y151	326

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EXECUTIVE SUMMARY

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 3 EDR MGP sites within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
USPS GOWANUS SITE. F	2ND AVENUE AND 12TH	NNE 1/4 - 1/2 (0.402 mi.)	AQ213	524
BU-METROPOLITAN MGP	124-136 SECOND AVE	NNE 1/4 - 1/2 (0.492 mi.)	AV240	649
FORMER CITIZEN GAS W	5TH STREET AND SMITH	N 1/2 - 1 (0.772 mi.)	243	651

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 2 EDR Hist Auto sites within approximately 0.125 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
STARPOINT USA INC	668 3RD AVE	ESE 0 - 1/8 (0.044 mi.)	B10	35
LINSOM SERVICE CENTE	687 3RD AVE	SE 0 - 1/8 (0.084 mi.)	G33	73

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 12 records.


<u>Site Name</u>	<u>Database(s)</u>
BROOKLYN MILITARY OCEAN TERMINAL	NY SHWS
DAVIDSON PIPE SUPPLY COMPANY	NY SHWS
HAMILTON AVENUE PIERS/19TH & 18TH	NY SHWS
CARROL GARDEN	SEMS-ARCHIVE
NORTHEAST MARINE TERMINAL CO INC	CORRACTS, RCRA NonGen / NLR
NYCDOS @ 52ND ST. BROOKLYN	NY SWF/LF
BROOKLYN CONCRETE RECYCLING; INC./	NY SWF/LF, NY Spills
STAPLETON ANCHORAGE	NY LTANKS, NY Spills
20TH STREET	NY Spills
USPS GOWANUS SITE, FORMER MGP METR	NY VCP
455 SMITH STREET (VICHAR, INC.)	NY VCP
DANGMAN PARK	NY VCP

This map illustrates the sampling locations for the 2002-2003 sampling period in the Port of Los Angeles. The map shows the harbor area, surrounding streets, and various sampling points marked with letters and numbers. The sampling locations are categorized into three groups: 1) Sampling locations for the 2002-2003 sampling period, marked with letters (A, B, C, D, E, F, G, H, I, J, K, L, M, N, O, P, Q, R, S, T, U, V, W, X, Y, Z, AA, AB, AC, AD, AE, AF, AG, AH, AI, AJ, AK, AL, AM, AN, AO, AP, AQ, AR, AS, AT, AU, AV, AW, AX, AY, AZ, BA, BB, BC, BD, BE, BF, BG, BH, BI, BJ, BK, BL, BM, BN, BO, BP, BQ, BR, BS, BT, BU, BV, BW, BX, BY, BZ, CA, CB, CC, CD, CE, CF, CG, CH, CI, CJ, CK, CL, CM, CN, CO, CP, CQ, CR, CS, CT, CU, CV, CW, CX, CY, CZ, DA, DB, DC, DD, DE, DF, DG, DH, DI, DJ, DK, DL, DM, DN, DO, DP, DQ, DR, DS, DT, DU, DV, DW, DX, DY, DZ, EA, EB, EC, ED, EE, EF, EG, EH, EI, EJ, EK, EL, EM, EN, EO, EP, EQ, ER, ES, ET, EU, EV, EW, EX, EY, EZ, FA, FB, FC, FD, FE, FF, FG, FH, FI, FJ, FK, FL, FM, FN, FO, FP, FQ, FR, FS, FT, FU, FV, FW, FX, FY, FZ, GA, GB, GC, GD, GE, GF, GG, GH, GI, GJ, GK, GL, GM, GN, GO, GP, GQ, GR, GS, GT, GU, GV, GW, GX, GY, GZ, HA, HB, HC, HD, HE, HF, HG, HH, HI, HJ, HK, HL, HM, HN, HO, HP, HQ, HR, HS, HT, HU, HV, HW, HX, HY, HZ, IA, IB, IC, ID, IE, IF, IG, IH, II, IJ, IK, IL, IM, IN, IO, IP, IQ, IR, IS, IT, IU, IV, IW, IX, IY, IZ, JA, JB, JC, JD, JE, JF, JG, JH, JI, JJ, JK, JL, JM, JN, JO, JP, JQ, JR, JS, JT, JU, JV, JW, JX, JY, JZ, KA, KB, KC, KD, KE, KF, KG, KH, KI, KJ, KK, KL, KM, KN, KO, KP, KQ, KR, KS, KT, KU, KV, KW, KX, KY, KZ, LA, LB, LC, LD, LE, LF, LG, LH, LI, LJ, LK, LL, LM, LN, LO, LP, LQ, LR, LS, LT, LU, LV, LW, LX, LY, LZ, MA, MB, MC, MD, ME, MF, MG, MH, MI, MJ, MK, ML, MM, MN, MO, MP, MQ, MR, MS, MT, MU, MV, MW, MX, MY, MZ, NA, NB, NC, ND, NE, NF, NG, NH, NI, NJ, NK, NL, NM, NN, NO, NP, NQ, NR, NS, NT, NU, NV, NW, NX, NY, NZ, OA, OB, OC, OD, OE, OF, OG, OH, OI, OJ, OK, OL, OM, ON, OO, OP, OQ, OR, OS, OT, OU, OV, OW, OX, OY, OZ, PA, PB, PC, PD, PE, PF, PG, PH, PI, PJ, PK, PL, PM, PN, PO, PP, PQ, PR, PS, PT, PU, PV, PW, PX, PY, PZ, QA, QB, QC, QD, QE, QF, QG, QH, QI, QJ, QK, QL, QM, QN, QO, QP, QQ, QR, QS, QT, QU, QV, QW, QX, QY, QZ, RA, RB, RC, RD, RE, RF, RG, RH, RI, RJ, RK, RL, RM, RN, RO, RP, RQ, RR, RS, RT, RU, RV, RW, RX, RY, RZ, SA, SB, SC, SD, SE, SF, SG, SH, SI, SJ, SK, SL, SM, SN, SO, SP, SQ, SR, SS, ST, SU, SV, SW, SX, SY, SZ, TA, TB, TC, TD, TE, TF, TG, TH, TI, TJ, TK, TL, TM, TN, TO, TP, TQ, TR, TS, TT, TU, TV, TW, TX, TY, TZ, UA, UB, UC, UD, UE, UF, UG, UH, UI, UJ, UK, UL, UM, UN, UO, UP, UQ, UR, US, UT, UU, UV, UW, UX, UY, UZ, VA, VB, VC, VD, VE, VF, VG, VH, VI, VJ, VK, VL, VM, VN, VO, VP, VQ, VR, VS, VT, VU, VV, VW, VX, VY, VZ, WA, WB, WC, WD, WE, WF, WG, WH, WI, WJ, WK, WL, WM, WN, WO, WP, WQ, WR, WS, WT, WU, WV, WW, WX, WY, WZ, XA, XB, XC, XD, XE, XF, XG, XH, XI, XJ, XK, XL, XM, XN, XO, XP, XQ, XR, XS, XT, XU, XV, XW, XX, XY, XZ, YA, YB, YC, YD, YE, YF, YG, YH, YI, YJ, YK, YL, YM, YN, YO, YP, YQ, YR, YS, YT, YU, YV, YW, YX, YY, YZ, ZA, ZB, ZC, ZD, ZE, ZF, ZG, ZH, ZI, ZJ, ZK, ZL, ZM, ZN, ZO, ZP, ZQ, ZR, ZS, ZT, ZU, ZV, ZW, ZX, ZY, ZZ). 2) Sampling locations for the 2001-2002 sampling period, marked with numbers (1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503,

- This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

CLIENT: Roux Associates
CONTACT: Frank Cherena
INQUIRY #: 6012679.2s
DATE: March 17, 2020 2:01 pm

DETAIL MAP - 6012679.2S



- Legend:

 - Target Property
 - Sites at elevations higher than or equal to the target property
 - Sites at elevations lower than the target property
 - Manufactured Gas Plants
 - Sensitive Receptors
 - National Priority List Sites
 - Dept. Defense Sites
 - Indian Reservations BIA
 - Power transmission lines
 - Pipelines
 - Special Flood Hazard Area (1%)
 - 0.2% Annual Chance Flood Hazard
 - National Wetland Inventory
 - State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 74 20th Street
ADDRESS: 74 20th Street
Brooklyn NY 11232
LAT/LONG: 40.665057 / 73.998697

CLIENT: Roux Associates
CONTACT: Frank Cherena
INQUIRY #: 6012679.2s
DATE: March 17, 2020 2:02 pm

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
<i>Federal NPL site list</i>								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
<i>Federal Delisted NPL site list</i>								
Delisted NPL	1.000		0	0	0	0	NR	0
<i>Federal CERCLIS list</i>								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	1	NR	NR	1
<i>Federal CERCLIS NFRAP site list</i>								
SEMS-ARCHIVE	0.500		1	0	3	NR	NR	4
<i>Federal RCRA CORRACTS facilities list</i>								
CORRACTS	1.000	1	0	0	0	1	NR	2
<i>Federal RCRA non-CORRACTS TSD facilities list</i>								
RCRA-TSDF	0.500	1	0	0	0	NR	NR	1
<i>Federal RCRA generators list</i>								
RCRA-LQG	0.250		3	4	NR	NR	NR	7
RCRA-SQG	0.250		1	2	NR	NR	NR	3
RCRA-VSQG	0.250		0	1	NR	NR	NR	1
<i>Federal institutional controls / engineering controls registries</i>								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
<i>Federal ERNS list</i>								
ERNS	TP		NR	NR	NR	NR	NR	0
<i>State- and tribal - equivalent CERCLIS</i>								
NY SHWS	1.000		0	1	5	2	NR	8
<i>State and tribal landfill and/or solid waste disposal site lists</i>								
NY SWF/LF	0.500		2	0	3	NR	NR	5
<i>State and tribal leaking storage tank lists</i>								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500		1	4	40	NR	NR	45
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
<i>State and tribal registered storage tank lists</i>								
FEMA UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY UST	0.250		2	5	NR	NR	NR	7
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	1	NR	NR	1
NY MOSF	0.500		0	0	4	NR	NR	4
NY CBS	0.250		0	1	NR	NR	NR	1
NY AST	0.250		6	10	NR	NR	NR	16
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	1	NR	NR	1
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	1	NR	NR	NR	1
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	2	6	NR	NR	8
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		0	0	5	NR	NR	5
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	1	NR	NR	1
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	1	1	NR	2
US CDL	TP		NR	NR	NR	NR	NR	0
NY PFAS	0.500		0	0	0	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		25	NR	NR	NR	NR	25
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	2	12	35	NR	NR	NR	49
FUDS	1.000		0	0	1	1	NR	2
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP	1	NR	NR	NR	NR	NR	1
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP	2	NR	NR	NR	NR	NR	2
UXO	1.000		0	0	0	0	NR	0
ECHO	TP	2	NR	NR	NR	NR	NR	2
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	1	2	NR	NR	3
NY MANIFEST	0.250	1	20	46	NR	NR	NR	67
PA MANIFEST	0.250		0	1	NR	NR	NR	1
RI MANIFEST	0.250		0	1	NR	NR	NR	1
NJ MANIFEST	0.250		4	8	NR	NR	NR	12
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
MINES MRDS	TP		NR	NR	NR	NR	NR	0

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	1.000		0	0	2	1	NR	3
EDR Hist Auto	0.125		2	NR	NR	NR	NR	2
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0

- Totals --		10	79	124	76	6	0	295

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

A1
Target
Property

DEBEVOISE CO
74 20TH ST
BROOKLYN, NY 11232

Site 1 of 8 in cluster A

Actual:
7 ft.

CORRACTS
RCRA-TSDF
RCRA NonGen / NLR
ICIS
FINDS
ECHO
NY MANIFEST

1000224955
NYD091590471

CORRACTS:

EPA ID: NYD091590471
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 1994-04-05 00:00:00.0
Action: CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD091590471
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 1993-03-29 00:00:00.0
Action: CA050 - RFA Completed
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-TSDF:

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: DEBEVOISE CO
Facility address: 74 20TH ST
BROOKLYN, NY 11232-1101
EPA ID: NYD091590471
Mailing address: 20TH ST
BROOKLYN, NY 11232
Contact: Not reported
Contact address: 20TH ST
BROOKLYN, NY 11232
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: THE DEBEVOISE CO DIV-PLC INC
Owner/operator address: 74 20TH ST
BROOKLYN, NY 11232
Owner/operator country: US
Owner/operator telephone: 212-965-2700

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: THE DEBEVOISE CO DIV PLC INC
Owner/operator address: 74-20TH ST
OPERCITY, NY 99999

Owner/operator country: US
Owner/operator telephone: 212-965-2700
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: DEBEVOISE CO
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: DEBEVOISE CO
Classification: Not a generator, verified

Date form received by agency: 1980-11-19 00:00:00.0
Site name: DEBEVOISE CO
Classification: Not a generator, verified

Date form received by agency: 1980-08-13 00:00:00.0
Site name: DEBEVOISE CO
Classification: Large Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

Hazardous Waste Summary:

- . Waste code: D000
- . Waste name: Not Defined

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D003
- . Waste name: REACTIVE WASTE

- . Waste code: P092
- . Waste name: MERCURY, (ACETATO-O)PHENYL- (OR) PHENYLMERCURY ACETATE

- . Waste code: U002
- . Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

- . Waste code: U017
- . Waste name: BENZAL CHLORIDE (OR) BENZENE, (DICHLOROMETHYL)-

- . Waste code: U031
- . Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

- . Waste code: U069
- . Waste name: 1,2-BENZENEDICARBOXYLIC ACID, DIBUTYL ESTER (OR) DIBUTYL PHTHALATE

- . Waste code: U154
- . Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

- . Waste code: U159
- . Waste name: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

- . Waste code: U161
- . Waste name: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

- . Waste code: U220
- . Waste name: BENZENE, METHYL- (OR) TOLUENE

- . Waste code: U239
- . Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Corrective Action Summary:

- Event date: 1993-03-29 00:00:00.0
- Event: RFA COMPLETED

- Event date: 1994-04-05 00:00:00.0
- Event: CA PRIORITIZATION-MEDIUM CA PRIORITY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1985-01-03 00:00:00.0
Date achieved compliance: 1985-03-21 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE SCHEDULE EVALUATION
Enforcement action date: 1985-02-21 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Formal Enforcement Agreement or Order
Date violation determined: 1983-11-10 00:00:00.0
Date achieved compliance: 1983-12-10 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE SCHEDULE EVALUATION
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1983-11-10 00:00:00.0
Date achieved compliance: 1984-11-30 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE SCHEDULE EVALUATION
Enforcement action date: 1983-11-10 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 11500
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Formal Enforcement Agreement or Order
Date violation determined: 1983-11-10 00:00:00.0
Date achieved compliance: 1983-12-10 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE SCHEDULE EVALUATION
Enforcement action date: 1983-11-10 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 11500
Final penalty amount: Not reported
Paid penalty amount: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1983-11-10 00:00:00.0
Date achieved compliance: 1984-11-30 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE SCHEDULE EVALUATION
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 1982-06-15 00:00:00.0
Date achieved compliance: 1982-11-09 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: 1983-03-21 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 7500
Paid penalty amount: 7500

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 1982-06-15 00:00:00.0
Date achieved compliance: 1982-11-09 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: 1982-06-15 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 11500
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 1985-01-03 00:00:00.0
Evaluation: WRITTEN INFORMAL
Area of violation: Generators - General
Date achieved compliance: 1985-03-21 00:00:00.0
Evaluation lead agency: EPA

Evaluation date: 1983-11-10 00:00:00.0
Evaluation: INITIAL 3008(A) COMPLIANCE
Area of violation: Formal Enforcement Agreement or Order
Date achieved compliance: 1983-12-10 00:00:00.0
Evaluation lead agency: EPA

Evaluation date: 1983-11-10 00:00:00.0
Evaluation: INITIAL 3008(A) COMPLIANCE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

Area of violation: Generators - General
Date achieved compliance: 1984-11-30 00:00:00.0
Evaluation lead agency: EPA

Evaluation date: 1982-06-15 00:00:00.0
Evaluation: INITIAL 3008(A) COMPLIANCE
Area of violation: TSD - General
Date achieved compliance: 1982-11-09 00:00:00.0
Evaluation lead agency: EPA

Evaluation date: 1982-06-15 00:00:00.0
Evaluation: FINAL 3008(A) COMPLIANCE ORDER
Area of violation: TSD - General
Date achieved compliance: 1982-11-09 00:00:00.0
Evaluation lead agency: EPA

RCRA NonGen / NLR:

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: DEBEVOISE CO
Facility address: 74 20TH ST
BROOKLYN, NY 11232-1101
EPA ID: NYD091590471
Mailing address: 20TH ST
BROOKLYN, NY 11232
Contact: Not reported
Contact address: 20TH ST
BROOKLYN, NY 11232
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: THE DEBEVOISE CO DIV-PLC INC
Owner/operator address: 74 20TH ST
BROOKLYN, NY 11232
Owner/operator country: US
Owner/operator telephone: 212-965-2700
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: THE DEBEVOISE CO DIV PLC INC
Owner/operator address: 74-20TH ST
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: 212-965-2700

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: DEBEVOISE CO
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: DEBEVOISE CO
Classification: Not a generator, verified

Date form received by agency: 1980-11-19 00:00:00.0
Site name: DEBEVOISE CO
Classification: Not a generator, verified

Date form received by agency: 1980-08-13 00:00:00.0
Site name: DEBEVOISE CO
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

. Waste code:	P092
. Waste name:	MERCURY, (ACETATO-O)PHENYL- (OR) PHENYLMERCURY ACETATE
. Waste code:	U002
. Waste name:	2-PROPANONE (I) (OR) ACETONE (I)
. Waste code:	U017
. Waste name:	BENZAL CHLORIDE (OR) BENZENE, (DICHLOROMETHYL)-
. Waste code:	U031
. Waste name:	1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)
. Waste code:	U069
. Waste name:	1,2-BENZENEDICARBOXYLIC ACID, DIBUTYL ESTER (OR) DIBUTYL PHTHALATE
. Waste code:	U154
. Waste name:	METHANOL (I) (OR) METHYL ALCOHOL (I)
. Waste code:	U159
. Waste name:	2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)
. Waste code:	U161
. Waste name:	4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-
. Waste code:	U220
. Waste name:	BENZENE, METHYL- (OR) TOLUENE
. Waste code:	U239
. Waste name:	BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Corrective Action Summary:

Event date:	1993-03-29 00:00:00.0
Event:	RFA COMPLETED
Event date:	1994-04-05 00:00:00.0
Event:	CA PRIORITIZATION-MEDIUM CA PRIORITY

Facility Has Received Notices of Violations:

Regulation violated:	Not reported
Area of violation:	Generators - General
Date violation determined:	1985-01-03 00:00:00.0
Date achieved compliance:	1985-03-21 00:00:00.0
Violation lead agency:	EPA
Enforcement action:	COMPLIANCE SCHEDULE EVALUATION
Enforcement action date:	1985-02-21 00:00:00.0
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	EPA
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Regulation violated:	Not reported
Area of violation:	Formal Enforcement Agreement or Order
Date violation determined:	1983-11-10 00:00:00.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

Date achieved compliance: 1983-12-10 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE SCHEDULE EVALUATION
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1983-11-10 00:00:00.0
Date achieved compliance: 1984-11-30 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE SCHEDULE EVALUATION
Enforcement action date: 1983-11-10 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 11500
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Formal Enforcement Agreement or Order
Date violation determined: 1983-11-10 00:00:00.0
Date achieved compliance: 1983-12-10 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE SCHEDULE EVALUATION
Enforcement action date: 1983-11-10 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 11500
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1983-11-10 00:00:00.0
Date achieved compliance: 1984-11-30 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE SCHEDULE EVALUATION
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 1982-06-15 00:00:00.0
Date achieved compliance: 1982-11-09 00:00:00.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

Violation lead agency: EPA
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: 1983-03-21 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 7500
Paid penalty amount: 7500

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 1982-06-15 00:00:00.0
Date achieved compliance: 1982-11-09 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: 1982-06-15 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 11500
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 1985-01-03 00:00:00.0
Evaluation: WRITTEN INFORMAL
Area of violation: Generators - General
Date achieved compliance: 1985-03-21 00:00:00.0
Evaluation lead agency: EPA

Evaluation date: 1983-11-10 00:00:00.0
Evaluation: INITIAL 3008(A) COMPLIANCE
Area of violation: Formal Enforcement Agreement or Order
Date achieved compliance: 1983-12-10 00:00:00.0
Evaluation lead agency: EPA

Evaluation date: 1983-11-10 00:00:00.0
Evaluation: INITIAL 3008(A) COMPLIANCE
Area of violation: Generators - General
Date achieved compliance: 1984-11-30 00:00:00.0
Evaluation lead agency: EPA

Evaluation date: 1982-06-15 00:00:00.0
Evaluation: INITIAL 3008(A) COMPLIANCE
Area of violation: TSD - General
Date achieved compliance: 1982-11-09 00:00:00.0
Evaluation lead agency: EPA

Evaluation date: 1982-06-15 00:00:00.0
Evaluation: FINAL 3008(A) COMPLIANCE ORDER
Area of violation: TSD - General
Date achieved compliance: 1982-11-09 00:00:00.0
Evaluation lead agency: EPA

ICIS:

Enforcement Action ID: 02-1983-0015

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

FRS ID: 110004374114
Action Name: PLC ENTERPRISES, INC.
Facility Name: DEBEVOISE CO
Facility Address: 74 20TH ST
BROOKLYN, NY 112321101
Enforcement Action Type: Civil Judicial Action
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Judicial
EA Type Code: CIV
Facility SIC Code: 2851
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.665093
Longitude in Decimal Degrees: -73.997955
Permit Type Desc: Not reported
Program System Acronym: 27418
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: DEBEVOISE CO
Address: 74 20TH ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2851

Facility Name: DEBEVOISE CO
Address: 74 20TH ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2851

FINDS:

Registry ID: 110004374114
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004374114

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000224955
Registry ID: 110004374114
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004374114>
Name: DEBEVOISE CO
Address: 74 20TH ST
City,State,Zip: BROOKLYN, NY 11232

NY MANIFEST:

Name: DEBEVOISE PAINT-PR-ALL PAINT PRODUCTS
Address: 74 20TH ST
City,State,Zip: BROOKLYN, NY 11232-1101
Country: USA
EPA ID: NYD091590471
Facility Status: Not reported
Location Address 1: 74 20 ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: 1101

NY MANIFEST:

EPAID: NYD091590471
Mailing Name: DEBEVOISE PAINT-PR-ALL PAINT PRODUCTS
Mailing Contact: JOAN MANGIARANO
Mailing Address 1: 700 GOTHAM PARKWAY
Mailing Address 2: Not reported
Mailing City: CARLSTADT
Mailing State: NJ
Mailing Zip: 07072
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2129652700

NY MANIFEST:

Document ID: NYA6404031
Manifest Status: K
seq: Not reported
Year: 1987
Trans1 State ID: PLATE#
Trans2 State ID: Not reported
Generator Ship Date: 07/02/1987
Trans1 Recv Date: 07/02/1987
Trans2 Recv Date: / /
TSD Site Recv Date: 07/02/1987
Part A Recv Date: 08/17/1987
Part B Recv Date: 07/13/1987

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEBEVOISE CO (Continued)

1000224955

Generator EPA ID: NYD091590471
Trans1 EPA ID: NYD000824334
Trans2 EPA ID: Not reported
TSDF ID 1: NYD000824334
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F003 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

**A2
Target
Property**

**DECORATIVE NOVELTY
74 20TH ST - 1ST FLOOR
BROOKLYN, NY 11232**

**RCRA NonGen / NLR
FINDS
ECHO**

**1001493535
NYR000072587**

Site 2 of 8 in cluster A

**Actual:
7 ft.**

RCRA NonGen / NLR:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: DECORATIVE NOVELTY
Facility address: 74 20TH ST - 1ST FLOOR
BROOKLYN, NY 11232
EPA ID: NYR000072587
Mailing address: 20TH ST - 1ST FLOOR
BROOKLYN, NY 11232
Contact: MATTHEW NOTINE
Contact address: 20TH ST - 1ST FLOOR
BROOKLYN, NY 11232
Contact country: US
Contact telephone: 718-965-8600
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DECORATIVE NOVELTY (Continued)

1001493535

Owner/operator name: BOB NOTINE
Owner/operator address: 74 20TH ST
BROOKLYN, NY 11232
Owner/operator country: US
Owner/operator telephone: 718-965-8600
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BOB NOTINE
Owner/operator address: 74 20TH ST
BROOKLYN, NY 11232
Owner/operator country: US
Owner/operator telephone: 718-965-8600
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: DECORATIVE NOVELTY
Classification: Not a generator, verified

Date form received by agency: 1999-06-18 00:00:00.0
Site name: DECORATIVE NOVELTY
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DECORATIVE NOVELTY (Continued)

1001493535

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1999-06-03 00:00:00.0
Date achieved compliance: 1999-06-29 00:00:00.0
Violation lead agency: State
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: 1999-06-09 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 1999-06-03 00:00:00.0
Evaluation: WRITTEN INFORMAL
Area of violation: Generators - General
Date achieved compliance: 1999-06-29 00:00:00.0
Evaluation lead agency: State

FINDS:

Registry ID: 110004553849
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004553849

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1001493535
Registry ID: 110004553849
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004553849>
Name: DECORATIVE NOVELTY
Address: 74 20TH ST - 1ST FLOOR
City,State,Zip: BROOKLYN, NY 11232

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

A3
< 1/8
1 ft.

CON EDISON
27 21 ST
BROOKLYN, NY 11201
Site 3 of 8 in cluster A

NY MANIFEST
S117066187
N/A

Relative:
Lower

Actual:
6 ft.

NY MANIFEST:
Name: CON EDISON
Address: 27 21 ST
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004588141
Facility Status: Not reported
Location Address 1: 27 21 ST
Code: BP
Location Address 2: SB46825
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004588141
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/07/2014
Trans1 Recv Date: 07/07/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/07/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004588141
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002504220GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117066187

Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

**A4
ESE
< 1/8
0.012 mi.
62 ft.**

**INTERNATIONAL TRUCK STOP AND REPAIR CORP.
92 20TH STREET
BROOKLYN, NY 11232
Site 4 of 8 in cluster A**

**NY AST A100294489
N/A**

**Relative:
Higher
Actual:
10 ft.**

AST:
Name: INTERNATIONAL TRUCK STOP AND REPAIR CORP.
Address: 92 20TH STREET
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-609252
Program Type: PBS
UTM X: 584685.30821
UTM Y: 4502049.10697
Expiration Date: 05/08/2017
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 31097
Affiliation Type: Mail Contact
Company Name: INTERNATIONAL TRUCK STOP & REPAIR CORP.
Contact Type: Not reported
Contact Name: AMAR ELVAHVAH
Address1: 94 20TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

INTERNATIONAL TRUCK STOP AND REPAIR CORP. (Continued)

A100294489

Phone: (718) 832-8090
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-05-08

Site Id: 31097
Affiliation Type: Facility Operator
Company Name: INTERNATIONAL TRUCK STOP AND REPAIR CORP.
Contact Type: Not reported
Contact Name: AMAR ELVAHVAH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 832-8098
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-05-08

Site Id: 31097
Affiliation Type: Emergency Contact
Company Name: AMAR ELVAHVAH
Contact Type: Not reported
Contact Name: SHAFIK ELVAHVAH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 832-8098
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-05-08

Site Id: 31097
Affiliation Type: Facility Owner
Company Name: AMAR ELVAHVAH
Contact Type: PRES/TREAS/SEC'TY
Contact Name: AMAR ELVAHVAH
Address1: 8 ROCKULLE AVE
Address2: Not reported
City: STAEN ISLAND
State: NY
Zip Code: 11314
Country Code: 001
Phone: (718) 832-8098
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-03-19

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

INTERNATIONAL TRUCK STOP AND REPAIR CORP. (Continued)

A100294489

Tank Info:

Tank Number: 001
Tank Id: 66946
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/01/1996
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 04/14/2017
Material Name: lube oil

Tank Number: 002
Tank Id: 66947
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil,

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

INTERNATIONAL TRUCK STOP AND REPAIR CORP. (Continued)

A100294489

allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/01/1996
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 04/14/2017
Material Name: waste oil/used oil

A5
WSW
< 1/8
0.017 mi.
90 ft.

SUNSET INDUSTRIAL PARK
50 21ST STREET
BROOKLYN, NY 11232
Site 5 of 8 in cluster A

NY UST **U000411321**
N/A

Relative:
Lower

UST:

Actual:
3 ft.

Name: SUNSET INDUSTRIAL PARK
Address: 50 21ST STREET
City,State,Zip: BROOKLYN, NY 11232
Id/Status: 2-481327 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 587866.33509
UTM Y: 4500780.10985
Site Type: Unknown

Affiliation Records:

Site Id: 21517
Affiliation Type: Facility Owner
Company Name: AL FIGLIOLIA & JAMES MCKEON
Contact Type: Not reported
Contact Name: Not reported
Address1: 50 21ST STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 965-6000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 21517
Affiliation Type: Mail Contact
Company Name: AL FIGLIOLIA & JAMES MCKEON
Contact Type: Not reported
Contact Name: Not reported
Address1: 50 21ST STREET

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNSET INDUSTRIAL PARK (Continued)

U000411321

Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 965-6000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 21517
Affiliation Type: Facility Operator
Company Name: SUNSET INDUSTRIAL PARK
Contact Type: Not reported
Contact Name: CEASAR CHEVEZ (FOREMAN)
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-6000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 21517
Affiliation Type: Emergency Contact
Company Name: AL FIGLIOLIA & JAMES MCKEON
Contact Type: Not reported
Contact Name: CEASAR CHEVEZ (FOREMAN)
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-9665
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 39154
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 3000
Install Date: Not reported
Date Tank Closed: 12/01/1989
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNSET INDUSTRIAL PARK (Continued)

U000411321

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

A6
WSW
< 1/8
0.017 mi.
91 ft.
VERIZON
60 21ST
BROOKLYN, NY 11201
Site 6 of 8 in cluster A

NY Spills **1009235025**
NY MANIFEST **N/A**

Relative:
Lower
Actual:
3 ft.

SPILLS:
Name: SPILL NUMBER 0211531
Address: 60 21ST ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0211531 / 2003-02-21
Facility ID: 0211531
Facility Type: ER
DER Facility ID: 69863
Site ID: 74461
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2003-02-20
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 2003-02-20
CID: 195
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-02-20
Spill Record Last Update: 2003-02-21
Spiller Name: JOHN QUATRALE
Spiller Company: VERIZON

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VERIZON (Continued)

1009235025

Spiller Address: 199 FULTON AVE RM 409
Spiller Company: 001
Contact Name: JOHN QUATRALE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
KRIMGOLD "
Remarks: "GAS TANK LEAKING ON VAN - CLEAN UP IN PROGRESS"

All Materials:

Site ID: 74461
Operable Unit ID: 864868
Operable Unit: 01
Material ID: 565747
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: 5.00
Oxygenate: Not reported

NY MANIFEST:

Name: VERIZON
Address: 60 21ST
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP000954289
Facility Status: Not reported
Location Address 1: 60 21ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP000954289
Mailing Name: VERIZON
Mailing Contact: VERIZON
Mailing Address 1: 199 FULTON AVENUE RM 409
Mailing Address 2: Not reported
Mailing City: HEMPSTEAD
Mailing State: NY
Mailing Zip: 11550
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5162928166

NY MANIFEST:

Document ID: NJA4135866
Manifest Status: Not reported
seq: 01
Year: 2003
Trans1 State ID: 10376

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VERIZON (Continued)

1009235025

Trans2 State ID: Not reported
Generator Ship Date: 02/20/2003
Trans1 Recv Date: 02/20/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/28/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP000954289
Trans1 EPA ID: NJD003812047
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00800
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

A7
WSW
< 1/8
0.017 mi.
92 ft.

CON EDISON
64 21ST ST & 3RD AVE
BROOKLYN, NY 11215

NY MANIFEST **S118259970**
N/A

Site 7 of 8 in cluster A

Relative:
Lower
Actual:
3 ft.

NY MANIFEST:
Name: CON EDISON
Address: 64 21ST ST & 3RD AVE
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004843179
Facility Status: Not reported
Location Address 1: 64 21ST ST
Code: BP
Location Address 2: SB 51653
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S118259970

Location Zip 4:	Not reported
NY MANIFEST:	
EPAID:	NYP004843179
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770
NY MANIFEST:	
Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/23/2015
Trans1 Recv Date:	09/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/25/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004843179
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID 1:	NJD002200046
TSD ID 2:	Not reported
Manifest Tracking Number:	014460185JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S118259970

Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

A8
SW
< 1/8
0.020 mi.
107 ft.

KAMPCO SUPPLY
80 21ST STREET
BROOKLYN, NY

NY Spills S108635765
N/A

Site 8 of 8 in cluster A

Relative:
Lower

Actual:
3 ft.

SPILLS:

Name: KAMPCO SUPPLY
Address: 80 21ST STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0700053 / 2007-04-03
Facility ID: 0700053
Facility Type: ER
DER Facility ID: 328782
Site ID: 379298
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2007-03-29
Investigator: vszhune
Referred To: Not reported
Reported to Dept: 2007-04-02
CID: 408
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-04-02
Spill Record Last Update: 2007-04-03
Spiller Name: JEFFERY HARRIS
Spiller Company: KAMPCO SUPPLY
Spiller Address: 80 21ST STREET
Spiller Company: 001
Contact Name: JEFFERY HARRIS
DEC Memo: "04/03/07- zhune spoke to Robert venuti from Hop Energy
ph:(718)991-2106. He said the hose got a punch and leaked. Spill was
1 gallon of Diesel and has clean cleaned. No drain, No sewer, No soil
impacted "

Remarks: "HAS BEEN CLEANED;"

All Materials:

Site ID: 379298
Operable Unit ID: 1136788
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KAMPCO SUPPLY (Continued)

S108635765

Material ID: 2126741
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

**B9
ESE
< 1/8
0.043 mi.
229 ft.**

**MH 5578
3RD AVE/20TH ST
BROOKLYN, NY
Site 1 of 5 in cluster B**

**NY Spills S103937471
N/A**

**Relative:
Higher
Actual:
13 ft.**

SPILLS:
Name: MH 5578
Address: 3RD AVE/20TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9901948 / 1999-07-20
Facility ID: 9901948
Facility Type: ER
DER Facility ID: 93152
Site ID: 105607
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1999-05-20
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1999-05-20
CID: 270
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-05-20
Spill Record Last Update: 2000-06-13
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ENGELHARDT cON ED E2MIS NOTES: Found 5 gallons unknown oil on 200
gallons of waer in mh. Cleanup is completed. Incident is closed.
unknown oil 5 gal pcb 1ppm AROCLOR 1242 1ppm "
Remarks: "5GALS ON 200 GALS WATER 124986"

All Materials:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MH 5578 (Continued)

S103937471

Site ID: 105607
Operable Unit ID: 1080708
Operable Unit: 01
Material ID: 305475
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported

**B10
ESE
< 1/8
0.044 mi.
234 ft.**

**STARPOINT USA INC
668 3RD AVE
BROOKLYN, NY 11232**

**EDR Hist Auto 1020227973
N/A**

Site 2 of 5 in cluster B

**Relative:
Higher**

EDR Hist Auto

**Actual:
13 ft.**

Year:	Name:	Type:
1969	ROCKY SERVICE CENTER	Gasoline Service Stations
1970	ROCKY SERVICE CENTER	Gasoline Service Stations
1971	ROCKY SERVICE CENTER	Gasoline Service Stations
1972	ROCKY SERVICE CENTER	Gasoline Service Stations
1973	ROCKY SERVICE CENTER	Gasoline Service Stations
1974	ROCKY SERVICE CENTER	Gasoline Service Stations
1975	ROCKY SERVICE CENTER	Gasoline Service Stations
1986	WINDYS SERVICE STATION INC	General Automotive Repair Shops
1987	WINDYS SERVICE STATION INC	General Automotive Repair Shops
1988	WINDYS SERVICE STATION INC	General Automotive Repair Shops
1989	WINDYS SERVICE STATION INC	General Automotive Repair Shops
1990	WINDYS SERVICE STATION INC	General Automotive Repair Shops
1994	SUNOCO GAS STATION	Gasoline Service Stations
1995	STARPOINT USA INC	Gasoline Service Stations
1996	STARPOINT USA INC	Gasoline Service Stations
1997	STARPOINT USA INC	Gasoline Service Stations
1998	STARPOINT USA INC	Gasoline Service Stations
1999	STARPOINT USA INC	Gasoline Service Stations
2000	STARPOINT USA INC	Gasoline Service Stations
2001	STARPOINT USA INC	Gasoline Service Stations
2002	STARPOINT USA INC	Gasoline Service Stations
2003	STARPOINT USA INC	Gasoline Service Stations
2004	STARPOINT USA INC	Gasoline Service Stations
2005	SS AUTO CENTER INC	General Automotive Repair Shops
2005	STARPOINT USA INC	Gasoline Service Stations, NEC
2006	STARPOINT USA INC	Gasoline Service Stations, NEC
2006	SS AUTO CENTER INC	General Automotive Repair Shops
2007	SS AUTO CENTER INC	General Automotive Repair Shops
2007	STARPOINT USA INC	Gasoline Service Stations, NEC
2008	SS AUTO CENTER INC	General Automotive Repair Shops
2008	STARPOINT USA INC	Gasoline Service Stations, NEC
2009	STARPOINT USA INC	Gasoline Service Stations, NEC
2010	STARPOINT USA INC	Gasoline Service Stations, NEC
2011	STARPOINT USA INC	Gasoline Service Stations, NEC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

B11
ESE
< 1/8
0.044 mi.
234 ft.
SUNSET MANAGEMENT, LLC
668 THIRD AVENUE
BROOKLYN, NY 11232
Site 3 of 5 in cluster B

NY UST **U003128244**
N/A

Relative:
Higher

UST:

Actual:
13 ft.

Name: SUNSET MANAGEMENT, LLC
Address: 668 THIRD AVENUE
City,State,Zip: BROOKLYN, NY 11232
Id/Status: 2-601497 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/04/2021
UTM X: 584716.37397
UTM Y: 4502005.15413
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 23459
Affiliation Type: Mail Contact
Company Name: KAMAL SERVICE, LLC
Contact Type: Not reported
Contact Name: MRS. SURINDER KAUR SINGH
Address1: 668 THIRD AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 369-2072
EMail: SMSK0108@YAHOO.COM
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2016-12-23

Site Id: 23459
Affiliation Type: Facility Operator
Company Name: SUNSET MANAGEMENT, LLC
Contact Type: Not reported
Contact Name: JAGJEED SINGH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 369-2072
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2006-11-14

Site Id: 23459
Affiliation Type: Emergency Contact
Company Name: KAMAL SERVICE, LLC
Contact Type: Not reported
Contact Name: MANGAT SINGH
Address1: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNSET MANAGEMENT, LLC (Continued)

U003128244

Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 808-3446
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-01-30

Site Id: 23459
Affiliation Type: Facility Owner
Company Name: SMJK REALTY CORP
Contact Type: VICE PRESIDENT
Contact Name: SURINDER KAUR SINGH
Address1: 668 THIRD AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 369-2072
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2016-12-23

Tank Info:

Tank Number: 001
Tank ID: 46460
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY
Last Modified: 04/14/2017

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNSET MANAGEMENT, LLC (Continued)

U003128244

A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
H05 - Tank Leak Detection - In-Tank System (ATG)
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Tank Number: 002
Tank ID: 46461
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY
Last Modified: 04/14/2017

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
H05 - Tank Leak Detection - In-Tank System (ATG)
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Tank Number: 003
Tank ID: 46462
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNSET MANAGEMENT, LLC (Continued)

U003128244

Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY
Last Modified: 04/14/2017

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
H05 - Tank Leak Detection - In-Tank System (ATG)
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 004
Tank ID: 221443
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 6000
Install Date: 12/01/2006
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY
Last Modified: 04/14/2017

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNSET MANAGEMENT, LLC (Continued)

U003128244

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Tank Number: 005
Tank ID: 221444
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 6000
Install Date: 12/01/2006
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY
Last Modified: 04/14/2017

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

C12
South
< 1/8
0.054 mi.
286 ft.

NW CORNER OF
63RD ST AT 3RD AVE
BROOKLYN, NY
Site 1 of 10 in cluster C

NY Spills **S102401948**
N/A

Relative:
Higher
Actual:
10 ft.

SPILLS:
Name: NW CORNER OF
Address: 63RD ST AT 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9606647 / 1996-08-23
Facility ID: 9606647
Facility Type: ER
DER Facility ID: 150464
Site ID: 179247
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1996-08-23
Investigator: SMMARTIN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NW CORNER OF (Continued)

S102401948

Referred To: Not reported
Reported to Dept: 1996-08-23
CID: 322
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1996-08-23
Spill Record Last Update: 1996-09-20
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
MARTINKAT "
Remarks: "caller reported that resident noticed unk oil bubbling out of storm
drain "

All Materials:

Site ID: 179247
Operable Unit ID: 1037775
Operable Unit: 01
Material ID: 345915
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

C13
SSE
< 1/8
0.058 mi.
308 ft.

CON EDISON - SERVICE BOX 45016
690 3RD AVE
BROOKLYN, NY 11232
Site 2 of 10 in cluster C

NY MANIFEST **S121967610**
N/A

Relative:
Higher
Actual:
12 ft.

NY MANIFEST:
Name: CON EDISON - SERVICE BOX 45016
Address: 690 3RD AVE
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP005026945
Facility Status: Not reported
Location Address 1: 690 3RD AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - SERVICE BOX 45016 (Continued)

S121967610

Location Zip: 11232
Location Zip 4: Not reported
NY MANIFEST:
EPAID: NYP005026945
Mailing Name: CON EDISON - SERVICE BOX 45016
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

C14
SSE
< 1/8
0.058 mi.
308 ft.

CON EDISON - SERVICE BOX 45016
690 3RD AVE
BROOKLYN, NY 11232

RCRA-LQG

1024890702
NYP005026945

Site 3 of 10 in cluster C

Relative:
Higher

RCRA-LQG:

Actual:
12 ft.

Date form received by agency: 2018-04-10 00:00:00.0
Facility name: CON EDISON - SERVICE BOX 45016
Facility address: 690 3RD AVE
BROOKLYN, NY 11232
EPA ID: NYP005026945
Mailing address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact: ALYSSA SOTTO
Contact address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-2757
Contact email: SOTTOA@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: 212-460-2757

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - SERVICE BOX 45016 (Continued)

1024890702

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2017-02-01 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003

Owner/operator country: US
Owner/operator telephone: 212-460-2757
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2017-02-01 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

D15
NNE
< 1/8
0.059 mi.
311 ft.

CON EDISON
73-19 72 ST
BROOKLYN, NY 11201
Site 1 of 3 in cluster D

NY MANIFEST **S116551433**
N/A

Relative:
Higher

NY MANIFEST:
Name: CON EDISON
Address: 73-19 72 ST
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004498978
Facility Status: Not reported

Actual:
7 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S116551433

Location Address 1: 73-19 72 ST
Code: BP
Location Address 2: SB3955
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004498978
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 04/12/2014
Trans1 Recv Date: 04/12/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/14/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004498978
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002407796GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S116551433

Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

E16
ENE
< 1/8
0.060 mi.
317 ft.

NYSDOT GOWANUS EXPWY 6TH AVE BBT TUNNEL
3RD AVE & HAMILTON
BROOKLYN, NY 11220

RCRA NonGen / NLR 1001124768
NY MANIFEST NYR000030445

Site 1 of 16 in cluster E

Relative:
Higher

RCRA NonGen / NLR:

Actual:
12 ft.

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: NYSDOT GOWANUS EXPWY 6TH AVE BBT TUNNEL
Facility address: 3RD AVE & HAMILTON
BROOKLYN, NY 11220
EPA ID: NYR000030445
Mailing address: HUNTER POINT PLZ
LONG ISLAND CITY, NY 11101
Contact: Not reported
Contact address: HUNTER POINT PLZ
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NYSDOT
Owner/operator address: 1 HUNTERS POINT PLZ
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: 718-482-4806
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYSDOT
Owner/operator address: 1 HUNTERS POINT PLZ
LONG ISLAND CITY, NY 11101
Owner/operator country: US

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS DOT GOWANUS EXPWY 6TH AVE BBT TUNNEL (Continued)

1001124768

Owner/operator telephone: 718-482-4806
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: NYS DOT GOWANUS EXPWY 6TH AVE BBT TUNNEL
Classification: Not a generator, verified

Date form received by agency: 1999-07-14 00:00:00.0
Site name: NYS DOT GOWANUS EXPWY 6TH AVE BBT TUNNEL
Classification: Small Quantity Generator

Date form received by agency: 1996-10-08 00:00:00.0
Site name: NYS DOT GOWANUS EXPWY 6TH AVE BBT TUNNEL
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:

Name: NYS DOT GOWANUS EXPWY 6TH AVE
Address: 3RD AVE & HAMILTON
City,State,Zip: BROOKLYN, NY 11220
Country: USA
EPA ID: NYR000030445
Facility Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT GOWANUS EXPWY 6TH AVE BBT TUNNEL (Continued)

1001124768

Location Address 1: 3RD AVE & HAMILTON
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11220
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYR000030445
Mailing Name: NYSDOT GOWANUS EXPWY 6TH AVE
Mailing Contact: JOHN ELIAS
Mailing Address 1: 1 HUNTER POINT PLZ
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7185679260

NY MANIFEST:

Document ID: MIA4500821
Manifest Status: K
seq: Not reported
Year: 1997
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 09/19/1997
Trans1 Recv Date: 09/19/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 09/24/1997
Part A Recv Date: / /
Part B Recv Date: 10/29/1997
Generator EPA ID: NYR000030445
Trans1 EPA ID: NYD046765574
Trans2 EPA ID: Not reported
TSDF ID 1: MID096963194
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS DOT GOWANUS EXPWY 6TH AVE BBT TUNNEL (Continued)

1001124768

Waste Code: Not reported
Quantity: 03000
Units: P - Pounds
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100

**F17
NNW
< 1/8
0.063 mi.
333 ft.**

**SUNSET INDUSTRIAL PARK
50 20TH ST
BROOKLYN, NY
Site 1 of 2 in cluster F**

**NY Spills S123660011
N/A**

**Relative:
Lower**

SPILLS:

**Actual:
2 ft.**

Name: SUNSET INDUSTRIAL PARK
Address: 50 20TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1810300 / Not Reported
Facility ID: 1810300
Facility Type: ER
DER Facility ID: 533763
Site ID: 581187
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2018-06-12
Investigator: RMP/PIPER
Referred To: Not reported
Reported to Dept: 2019-01-08
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 1
Date Entered In Computer: 2019-01-08
Spill Record Last Update: 2019-09-12
Spiller Name: Not reported
Spiller Company: S L INDUSTIRAL II LLC & A M SUNSET PARK II LLC
Spiller Address: Not reported
Spiller Company: 999
Contact Name: CHRIS MCMAHON
DEC Memo: "01/08/19 - Lakhani Langan's client (DH Holdings) is closing on the property. The client was performing due diligence, so a Phase II was completed in June 2018. Free petroleum product was found on the groundwater. 0.10 of product was found on the groundwater. Fingerprint analysis of the product revealed that it was hydraulic oil. Langan contact: Chris McMahon 973-560-4900 PBS# 2-481327 A 3000 gallon #2 fuel oil UST was closed in 1989. 5/13-19- DEC Piper left message for Chris. 8-15-19- DEC Piper received closure report. Report documents: ? Closure in-place of three 550-gallon gasoline USTs and

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNSET INDUSTRIAL PARK (Continued)

S123660011

Remarks: one 5,000-gallon fuel oil UST beneath the floor slab of a building (1) in the northern portion of the site and, ? Closure in-place of one 4,000-gallon fuel oil UST beneath the floor slab of a garage adjacent to Building C in the southern portion of the site. "
"cleanup pending"

All Materials:

Site ID: 581187
Operable Unit ID: 1328892
Operable Unit: 01
Material ID: 2337926
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

C18
SSE
< 1/8
0.064 mi.
338 ft.

PARTS EXPRESS INC
694-696 3RD AVE
BROOKLYN, NY 11232
Site 4 of 10 in cluster C

NY SWF/LF S108146049
N/A

Relative:
Higher
Actual:
13 ft.

SWF/LF:
Name: PARTS EXPRESS INC
Address: 694-696 3RD AVE
City,State,Zip: BROOKLYN, NY 11232
Flag: INACTIVE
Region Code: 2
Phone Number: Not reported
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: Not reported
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: Vehicle Dismantling Facility
Activity Number: Not reported
Active: No
East Coordinate: 584777
North Coordinate: 4502064
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARTS EXPRESS INC (Continued)

S108146049

Operator Name: Not reported
Operator Type: Not reported
Last Date: Not reported

C19
SSE
< 1/8
0.064 mi.
338 ft.

3RD AVENUE AUTO PARTS
694 3RD AVE
BROOKLYN, NY 11232
Site 5 of 10 in cluster C

RCRA NonGen / NLR
FINDS
ECHO

1000103439
NYD091586040

Relative:
Higher

Actual:
13 ft.

RCRA NonGen / NLR:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: 3RD AVENUE AUTO PARTS
Facility address: 694 3RD AVE
BROOKLYN, NY 11232-1114
EPA ID: NYD091586040
Mailing address: 3RD AVE
BROOKLYN, NY 11232
Contact: Not reported
Contact address: 3RD AVE
BROOKLYN, NY 11232
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: EDDIE BERNARDO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: EDDIE BERNARDO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

3RD AVENUE AUTO PARTS (Continued)

1000103439

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: 3RD AVENUE AUTO PARTS
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: 3RD AVENUE AUTO PARTS
Classification: Not a generator, verified

Date form received by agency: 1986-12-12 00:00:00.0
Site name: 3RD AVENUE AUTO PARTS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004374098
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004374098

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000103439
Registry ID: 110004374098
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004374098>

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

3RD AVENUE AUTO PARTS (Continued)

1000103439

Name: 3RD AVENUE AUTO PARTS
Address: 694 3RD AVE
City,State,Zip: BROOKLYN, NY 11232

D20
NNE
< 1/8
0.068 mi.
358 ft.

DECORATIVE NOVELTY CO INC
65 19TH ST
BROOKLYN, NY 11232

RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

1000791007
NYD987025038

Site 2 of 3 in cluster D

Relative:
Lower

RCRA NonGen / NLR:

Actual:
6 ft.

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: DECORATIVE NOVELTY CO INC
Facility address: 65 19TH ST
BROOKLYN, NY 11232-1011
EPA ID: NYD987025038
Mailing address: 20TH ST
BROOKLYN, NY 11232
Contact: Not reported
Contact address: 20TH ST
BROOKLYN, NY 11232
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: 19 STREET REALTY
Owner/operator address: 65 19TH ST
BROOKLYN, NY 11232
Owner/operator country: US
Owner/operator telephone: 718-965-8600
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: 19 STREET REALTY
Owner/operator address: 65 19TH ST
BROOKLYN, NY 11232
Owner/operator country: US
Owner/operator telephone: 718-965-8600
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DECORATIVE NOVELTY CO INC (Continued)

1000791007

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: DECORATIVE NOVELTY CO INC
Classification: Not a generator, verified

Date form received by agency: 2002-03-25 00:00:00.0
Site name: DECORATIVE NOVELTY CO INC
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: DECORATIVE NOVELTY CO INC
Classification: Not a generator, verified

Date form received by agency: 1992-12-24 00:00:00.0
Site name: DECORATIVE NOVELTY CO INC
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DECORATIVE NOVELTY CO INC (Continued)

1000791007

SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004499338
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004499338

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000791007
Registry ID: 110004499338
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004499338>
Name: DECORATIVE NOVELTY CO INC
Address: 65 19TH ST
City,State,Zip: BROOKLYN, NY 11232

NY MANIFEST:

Name: DECORATIVE NOVELTY CO INC
Address: 65 19TH ST
City,State,Zip: BROOKLYN, NY 11232-1011
Country: USA
EPA ID: NYD987025038
Facility Status: Not reported
Location Address 1: 65-19TH ST 3D FLOOR
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD987025038
Mailing Name: DECORATIVE NOVELTY CO INC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DECORATIVE NOVELTY CO INC (Continued)

1000791007

Mailing Contact: S GARCEAU
Mailing Address 1: 65-19TH ST 3D FLOOR
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11232
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7189659742

NY MANIFEST:

Document ID: NJA1359565
Manifest Status: C
seq: Not reported
Year: 1993
Trans1 State ID: NJDEPS869
Trans2 State ID: NJDEPS869
Generator Ship Date: 03/17/1993
Trans1 Recv Date: 03/17/1993
Trans2 Recv Date: 03/20/1993
TSD Site Recv Date: 03/22/1993
Part A Recv Date: / /
Part B Recv Date: 04/02/1993
Generator EPA ID: NYD987025038
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: ILD051060408
TSDF ID 1: NJD002182897
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F001 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00398
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

B21
ESE
< 1/8
0.069 mi.
363 ft.

ATLAS GAS STATION
20TH ST & 3RD AVE
BROOKLYN, NY

Site 4 of 5 in cluster B

NY Spills **S105056922**
N/A

Relative:
Higher

Actual:
16 ft.

SPILLS:

Name: ATLAS GAS STATION
Address: 20TH ST & 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0101052 / 2003-11-17
Facility ID: 0101052
Facility Type: ER
DER Facility ID: 195262
Site ID: 237012
DEC Region: 2
Spill Cause: Unknown
Spill Class: B3
SWIS: 2401
Spill Date: 2001-04-27
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2001-04-27
CID: 404
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-04-27
Spill Record Last Update: 2003-11-17
Spiller Name: Not reported
Spiller Company: ATLAS GAS STATION
Spiller Address: 20TH ST & 3RD AVE
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 11/17/03 TJD Overfill impacting surface only. FDNY responded and flushed product to sewer. Product not recoverable. Spill closed."
Remarks: "caller stated gas was running down the street. caller thought it was water but further investigated and said it was gas. caller unsure if it going into sewers. caller is requesting a responder to the scene."

All Materials:

Site ID: 237012
Operable Unit ID: 839831
Operable Unit: 01
Material ID: 536759
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

F22
NNW
< 1/8
0.070 mi.
371 ft.
SHAMROCK CONTRACTING CORP.
95-99 19TH STREET
BROOKLYN, NY 11231
Site 2 of 2 in cluster F

NY SWF/LF **S105841754**
N/A

Relative: SWF/LF:
Lower Name: SHAMROCK CONTRACTING CORP.
Address: 95-99 19TH STREET
Actual: City,State,Zip: BROOKLYN, NY 11231
2 ft. Flag: INACTIVE
Region Code: 2
Phone Number: 7188756264
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: STEVE BARRANCA; PRESIDENT
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: Transfer station - permit
Activity Number: [24T28]
Active: No
East Coordinate: 584400
North Coordinate: 4503000
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: 2-6102-00046
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Last Date: Not reported

B23
East
< 1/8
0.071 mi.
376 ft.
GOWANUS EXPWY/65TH STREET
GOWANUS EXPWY/65TH STREET
BROOKLYN, NY
Site 5 of 5 in cluster B

NY Spills **S102149807**
N/A

Relative: SPILLS:
Higher Name: GOWANUS EXPWY/65TH STREET
Address: GOWANUS EXPWY/65TH STREET
Actual: City,State,Zip: BROOKLYN, NY
15 ft. Spill Number/Closed Date: 9416534 / 1995-03-22
Facility ID: 9416534
Facility Type: ER
DER Facility ID: 114119
Site ID: 132556
DEC Region: 2
Spill Cause: Traffic Accident
Spill Class: B2
SWIS: 2401

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANUS EXPWY/65TH STREET (Continued)

S102149807

Spill Date: 1995-03-22
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1995-03-22
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Fire Department
Cleanup Ceased: 1995-03-22
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-03-22
Spill Record Last Update: 1995-03-23
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: ""
Remarks: "ACCIDENT (ROLL OVER) SPILL ON GROUND GOING TOWARDS SEWER HOLE. FIRE DEPT. ON SCENE (NOT CONTAINED), DEC RESPONDED-200 GALLONS WENT DOWN SEWER, DEP WILL MONITOR IMPACT TO TREATMENT PLANT, SANITATION C"

All Materials:

Site ID: 132556
Operable Unit ID: 1013701
Operable Unit: 01
Material ID: 371689
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 150.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS EXPWY/65TH STREET
Address: GOWANUS EXPWY/65TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9416541 / 1995-03-22
Facility ID: 9416541
Facility Type: ER
DER Facility ID: 114119
Site ID: 132557
DEC Region: 2
Spill Cause: Traffic Accident
Spill Class: B1
SWIS: 2401
Spill Date: 1995-03-22
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1995-03-22
CID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANUS EXPWY/65TH STREET (Continued)

S102149807

Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Fire Department
Cleanup Ceased: 1995-03-22
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-03-22
Spill Record Last Update: 2002-10-28
Spiller Name: Not reported
Spiller Company: SCHNEIDER NATL. CARRIER
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "JACK KNIFES TRACTOR TRAILER, SURFACE SANDED BUT MAJORITY OF PRODUCT SPILLED INTO SEWER SYSTEM. DEC RESPONDED DEP WILL MONITOR TREATMENT PLANT. SANITATION CLEANED UP."

All Materials:

Site ID: 132557
Operable Unit ID: 1013703
Operable Unit: 01
Material ID: 371695
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 150.00
Units: G
Recovered: .00
Oxygenate: Not reported

E24
ENE
< 1/8
0.072 mi.
380 ft.

SCRAP KING USA INC
99 19TH ST
BROOKLYN, NY 11232

Site 2 of 16 in cluster E

RCRA NonGen / NLR
FINDS
ECHO

1016455675
NYR000207803

Relative:
Higher
Actual:
13 ft.

RCRA NonGen / NLR:
Date form received by agency: 2015-04-13 00:00:00.0
Facility name: SCRAP KING USA INC
Facility address: 99 19TH ST
BROOKLYN, NY 11232
EPA ID: NYR000207803
Mailing address: 19TH ST
BROOKLYN, NY 11232
Contact: MICHELLE CHANG
Contact address: COLLEGE POINT BLVD
FLUSHING, NY 11354
Contact country: US
Contact telephone: 718-888-9087
Contact email: MICHELLEC@SCRAPKINGUSA.COM
EPA Region: 02
Classification: Non-Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SCRAP KING USA INC (Continued)

1016455675

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: YILI TENG
Owner/operator address: 19TH ST
BROOKLYN, NY 11232
Owner/operator country: US
Owner/operator telephone: 718-788-8876
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2013-10-28 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: MICHELLE CHANG
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2014-01-01 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:

Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Historical Generators:

Date form received by agency: 2014-03-03 00:00:00.0
Site name: SCRAP KING USA INC
Classification: Not a generator, verified

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SCRAP KING USA INC (Continued)

1016455675

Violation Status: No violations found

FINDS:

Registry ID: 110058880037
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110058880037

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1016455675
Registry ID: 110058880037
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110058880037>
Name: SCRAP KING USA INC
Address: 99 19TH ST
City,State,Zip: BROOKLYN, NY 11232

**E25
ENE
< 1/8
0.075 mi.
395 ft.**

**CON EDISON
109 19 ST
BROOKLYN, NY 11215**

**NY MANIFEST S116296371
N/A**

Site 3 of 16 in cluster E

**Relative:
Higher**

NY MANIFEST:
Name: CON EDISON
Address: 109 19 ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004476515
Facility Status: Not reported
Location Address 1: 109 19 ST
Code: BP
Location Address 2: SB46464
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

**Actual:
14 ft.**

NY MANIFEST:
EPAID: NYP004476515
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

G26
SE
< 1/8
0.075 mi.
398 ft.

SPILL NUMBER 0306006
3RD AVE & 21ST ST
BROOKLYN, NY
Site 1 of 9 in cluster G

NY Spills S106017880
N/A

Relative:
Higher

Actual:
16 ft.

SPILLS:

Name: SPILL NUMBER 0306006
Address: 3RD AVE & 21ST ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0306006 / 2003-10-03
Facility ID: 0306006
Facility Type: ER
DER Facility ID: 73101
Site ID: 78565
DEC Region: 2
Spill Cause: Abandoned Drums
Spill Class: D4
SWIS: 2401
Spill Date: 2003-09-06
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2003-09-06
CID: 297
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-09-06
Spill Record Last Update: 2003-10-03
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: WAIMAN WONG
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 9/6/03. J. Krimgold visited the site and found abandoned 150 gal AST at the median (parking area) under BQE. No leak from this tank was observed. Neighbors complained to DOS but nobody wants to pick it up. 10/3/03 TJD No container(s) found at location during drum run on 10/1/03. Spill closed. See also spill #9930008."

Remarks: "A LARGE CONTAINER OF WASTE OIL WAS FOUND IN THE MEDIAN AT THE ABOVE LOCATION - NO CONTAMINATION FOUND AROUND THE CONTAINER"

All Materials:

Site ID: 78565
Operable Unit ID: 872582
Operable Unit: 01
Material ID: 503244
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 150.00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0306006 (Continued)

S106017880

Recovered: .00
Oxygenate: Not reported

**G27
SE
< 1/8
0.075 mi.
398 ft.**

**UNDER TRESSEL
21ST & 3RD AVE
BROOKLYN, NY
Site 2 of 9 in cluster G**

**NY Spills S106469770
N/A**

**Relative:
Higher**

**Actual:
16 ft.**

SPILLS:

Name: UNDER TRESSEL
Address: 21ST & 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0402503 / 2004-06-09
Facility ID: 0402503
Facility Type: ER
DER Facility ID: 215155
Site ID: 263962
DEC Region: 2
Spill Cause: Abandoned Drums
Spill Class: D4
SWIS: 2401
Spill Date: 2004-06-08
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2004-06-08
CID: 444
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-06-08
Spill Record Last Update: 2004-06-09
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: FIREFIGHTER FINKLE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND sangesland forwarded this spill to DEP (Enzo) for DEP to inspect. If it requires DEC action, DEP will call in another spill number"

Remarks: "near the 3rd ave Junk Scrap Metal Business: NOT leaking"

All Materials:

Site ID: 263962
Operable Unit ID: 884182
Operable Unit: 01
Material ID: 490116
Material Code: 0009
Material Name: gasoline
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNDER TRESSEL (Continued)

S106469770

Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

D28
North
< 1/8
0.076 mi.
401 ft.
18TH-19TH RELATY CO
79 19TH STREET
BROOKLYN, NY 11232
Site 3 of 3 in cluster D

NY AST **U003392425**
N/A

Relative:
Lower
Actual:
4 ft.

AST:
Name: 18TH-19TH RELATY CO
Address: 79 19TH STREET
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-366013
Program Type: PBS
UTM X: 584748.90010
UTM Y: 4502097.49360
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 18609
Affiliation Type: Facility Owner
Company Name: 18TH-19TH REALTY LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 4706-18TH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (718) 972-7878
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 18609
Affiliation Type: Mail Contact
Company Name: 18TH -19TH REALTY LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 4706 18TH AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (718) 972-7878
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

18TH-19TH RELATY CO (Continued)

U003392425

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 18609
Affiliation Type: Facility Operator
Company Name: 18TH-19TH RELATY CO
Contact Type: Not reported
Contact Name: BONNETT ESTEBAN SUPER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 832-7469
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 18609
Affiliation Type: Emergency Contact
Company Name: 18TH-19TH REALTY LLC
Contact Type: Not reported
Contact Name: ROBERT WOLF
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 972-7878
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 24556
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G04 - Tank Secondary Containment - Double-Walled (Underground)
I04 - Overfill - Product Level Gauge (A/G)
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

18TH-19TH RELATY CO (Continued)

U003392425

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1973
Capacity Gallons: 7500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/10/2007
Register: True
Modified By: LXZIELIN
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 002
Tank Id: 24557
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G04 - Tank Secondary Containment - Double-Walled (Underground)
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1962
Capacity Gallons: 2400
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/20/2005
Register: True
Modified By: LXZIELIN
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

C29
South
< 1/8
0.077 mi.
409 ft.

95 22ND STREET
95 22ND ST & 3RD AVE
BROOKLYN, NY
Site 6 of 10 in cluster C

NY Spills S102150308
N/A

Relative:
Higher

Actual:
12 ft.

SPILLS:
Name: 95 22ND STREET
Address: 95 22ND ST & 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9503163 / 1995-06-13
Facility ID: 9503163

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

95 22ND STREET (Continued)

S102150308

Facility Type: ER
DER Facility ID: 217229
Site ID: 266690
DEC Region: 2
Spill Cause: Deliberate
Spill Class: C4
SWIS: 2401
Spill Date: 1995-06-13
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 1995-06-13
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Police Department
Cleanup Ceased: 1995-06-13
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-06-19
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported
Spiller Company: RAYMOND ACOSTA
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
MARTINKAT "
Remarks: "UNKNOWN AMOUNT SPILLED - SPOKE TO RAYMOND, HE WAS CHANGING A
TRANSMISSION TODAY, SOME OIL SPILLED , WAS CLEANED UP."

All Materials:

Site ID: 266690
Operable Unit ID: 1014401
Operable Unit: 01
Material ID: 368215
Material Code: 0016A
Material Name: non PCB oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 266690
Operable Unit ID: 1014401
Operable Unit: 01
Material ID: 368214
Material Code: 0013
Material Name: lube oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

95 22ND STREET (Continued)

S102150308

Oxygenate: Not reported

C30
SSE
< 1/8
0.080 mi.
422 ft.

GOWANUS BAY
22ND ST & 3RD AVE
BROOKLYN, NY
Site 7 of 10 in cluster C

NY Spills S102961689
N/A

Relative:
Higher

Actual:
15 ft.

SPILLS:

Name: GOWANUS BAY
Address: 22ND ST & 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9708594 / 2001-11-08
Facility ID: 9708594
Facility Type: ER
DER Facility ID: 240585
Site ID: 297345
DEC Region: 2
Spill Cause: Unknown
Spill Class: E6
SWIS: 2401
Spill Date: 1997-10-22
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 1997-10-22
CID: 211
Water Affected: GOWANAS BAY
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: 2001-11-08
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1997-10-22
Spill Record Last Update: 2003-11-03
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: MICHAEL KOWALSKI
DEC Memo: ""
Remarks: "RAW SEWAGE FOUND IN BAY WHICH IS UPPER NEW YORK HARBOR / INVESTIGATION HAS STATRTED RE CAUSE"

All Materials:

Site ID: 297345
Operable Unit ID: 1051734
Operable Unit: 01
Material ID: 330554
Material Code: 0062A
Material Name: raw sewage
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANUS BAY (Continued)

S102961689

Recovered: .00
Oxygenate: Not reported

Name: MANHOLE 62008
Address: 22ND ST & 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9808774 / 2002-10-28
Facility ID: 9808774
Facility Type: ER
DER Facility ID: 240585
Site ID: 297346
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1998-10-14
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1998-10-14
CID: 246
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-10-14
Spill Record Last Update: 2002-10-28
Spiller Name: FRANK MASSERIA
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: MIKE CESARE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks: "OIL SHEEN FOUND ON WATER IN MANHOLE - ATTEMPTING TO ABSORB WITH PADS AT THIS TIME - IF NOT SUCCESSFUL SAMPLE WILL BE TAKEN AND MANHOLE WILL BE FLUSHED"

All Materials:
Site ID: 297346
Operable Unit ID: 1069966

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANUS BAY (Continued)

S102961689

Operable Unit: 01
Material ID: 316259
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

**G31
SE
< 1/8
0.083 mi.
437 ft.**

**CON EDISON
64 21ST ST & 3RD AVE
BROOKLYN, NY 11215**

**RCRA NonGen / NLR
FINDS
ECHO**

**1019908207
NYP004843179**

Site 3 of 9 in cluster G

**Relative:
Higher**

RCRA NonGen / NLR:

**Actual:
17 ft.**

Date form received by agency: 2015-09-23 00:00:00.0
Facility name: CON EDISON
Facility address: 64 21ST ST & 3RD AVE
BROOKLYN, NY 11215
EPA ID: NYP004843179
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2015-09-23 00:00:00.0
Site name: CON EDISON
Classification: Large Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1019908207

Violation Status: No violations found

FINDS:

Registry ID: 110069660272
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110069660272

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1019908207
Registry ID: 110069660272
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110069660272>
Name: CON EDISON
Address: 64 21ST ST & 3RD AVE
City,State,Zip: BROOKLYN, NY 11215

G32
SE
< 1/8
0.084 mi.
445 ft.

LINSOM SERVICE CENTER, INC.
687 3RD AVENUE
BROOKLYN, NY 11232
Site 4 of 9 in cluster G

NY AST A100294852
N/A

Relative:
Higher
Actual:
17 ft.

AST:
Name: LINSOM SERVICE CENTER, INC.
Address: 687 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-610184
Program Type: PBS
UTM X: 584732.28118
UTM Y: 4501888.95605
Expiration Date: 04/13/2016
Site Type: Other

Affiliation Records:

Site Id: 362521
Affiliation Type: Facility Owner
Company Name: LINSOM SERVICE CENTER, INC.
Contact Type: PRES.
Contact Name: PANNERRAL SOHAN
Address1: 687 3RD AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 768-5727
Email: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC. (Continued)

A100294852

Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2006-04-13

Site Id: 362521
Affiliation Type: Mail Contact
Company Name: LINSOM SERVICE CENTER, INC.
Contact Type: Not reported
Contact Name: JESSIE PAPIA
Address1: 687 3RD AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 768-5727
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2006-04-13

Site Id: 362521
Affiliation Type: Facility Operator
Company Name: LINSOM SERVICE CENTER, INC.
Contact Type: Not reported
Contact Name: PANNERRAL SOHAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 768-5727
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2006-04-13

Site Id: 362521
Affiliation Type: Emergency Contact
Company Name: LINSOM SERVICE CENTER, INC.
Contact Type: Not reported
Contact Name: JESSIE PAPIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 499-7681
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2006-04-13

Tank Info:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC. (Continued)

A100294852

Tank Number: 001
Tank Id: 211082
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
I01 - Overfill - Float Vent Valve
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/23/2005
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: waste oil/used oil

G33
SE
< 1/8
0.084 mi.
445 ft.

LINSOM SERVICE CENTER INC
687 3RD AVE
BROOKLYN, NY 11232

EDR Hist Auto 1020897041
N/A

Site 5 of 9 in cluster G

Relative:
Higher

EDR Hist Auto

Actual:
17 ft.

Year:	Name:	Type:
2003	LINSOM SERVICE CENTER INC	Gasoline Service Stations
2004	LINSOM SERVICE CENTER INC	Gasoline Service Stations
2005	LINSOM SERVICE CENTER INC	Gasoline Service Stations
2006	LINSOM SERVICE CENTER INC	Gasoline Service Stations
2007	LINSOM SERVICE CENTER INC	Gasoline Service Stations
2008	LINSOM SERVICE CENTER INC	Gasoline Service Stations
2010	LINSOM SERVICE CENTER INC	Gasoline Service Stations
2011	LINSOM SERVICE CENTER INC	Gasoline Service Stations
2012	LINSOM SERVICE CENTER INC	Gasoline Service Stations
2013	LINSOM SERVICE CENTER INC	Gasoline Service Stations

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

G34
SE
< 1/8
0.084 mi.
446 ft.

21 ST OFF 3RD AVENUE
21 ST OFF 3RD AVENUE
BROOKLYN, NY
Site 6 of 9 in cluster G

NY LTANKS S102672354
N/A

Relative:
Higher

Actual:
17 ft.

LTANKS:

Name: 21 ST OFF 3RD AVENUE
Address: 21 ST OFF 3RD AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9312696 / 1994-01-28
Facility ID: 9312696
Site ID: 125518
Spill Date: 1994-01-28
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: E4
Cleanup Ceased: 1994-01-28
SWIS: 2401
Investigator: CAMMISA
Referred To: Not reported
Reported to Dept: 1994-01-28
CID: Not reported
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-01-31
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 108561
DEC Memo: ""
Remarks: "NO CLEAN UP ACTION ONGOING FOR ~ 1 1/2 YRS. NO CONTACT AT THE GIVEN PHONE #."

All Materials:

Site ID: 125518
Operable Unit ID: 991322
Operable Unit: 01
Material ID: 388112
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

E35
East
< 1/8
0.085 mi.
449 ft.

CON EDISON MANHOLE: 74920
19TH ST & 3RD AVE MH 74920
BROOKLYN, NY 11232

RCRA NonGen / NLR
NJ MANIFEST
NY MANIFEST

1014396771
NYP004190864

Site 4 of 16 in cluster E

Relative:
Higher

RCRA NonGen / NLR:

Actual:
16 ft.

Date form received by agency: 2016-06-01 00:00:00.0
Facility name: CON EDISON MANHOLE: 74920
Facility address: 19TH ST & 3RD AVE MH 74920
BROOKLYN, NY 11232
EPA ID: NYP004190864
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: CAROLINE ISKANDER
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2009-08-13 00:00:00.0
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:

EPA Id: NYP004190864
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: CAROLINE ISKANDER
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 74920 (Continued)

1014396771

Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:

Manifest Number: 000894941GBF
EPA ID: NYP004190864
Date Shipped: 08/21/2009
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 08/21/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 08/25/2009
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:

Manifest Year: Not reported
Waste Code: D008
Hand Code: H141
Quantity: 150 G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 74920 (Continued)

1014396771

NY MANIFEST:

Name: CONSOLIDATED EDISON
Address: 19TH ST & 3RD AVE MH 74920
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004190864
Facility Status: Not reported
Location Address 1: 19th ST & 3rd AVE - MH 74925
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004190864
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/21/2009
Trans1 Recv Date: 08/21/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/25/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004190864
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 000894941GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 74920 (Continued)

1014396771

Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 150.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

E36
East
< 1/8
0.085 mi.
449 ft.

CON EDISON - MANHOLE 9285
19TH STREET & 3RD AVE
BROOKLYN, NY 11232
Site 5 of 16 in cluster E

RCRA-LQG **1014396774**
NJ MANIFEST **NYP004190898**

Relative:
Higher
Actual:
16 ft.

RCRA-LQG:
Date form received by agency: 2010-03-23 00:00:00.0
Facility name: CON EDISON - MANHOLE 9285
Facility address: 19TH STREET & 3RD AVE
BROOKLYN, NY 11232
EPA ID: NYP004190898
Mailing address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact: FRANKLYN MURRAY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-2808
Contact email: MURRAYFR@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 9285 (Continued)

1014396774

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2009-08-13 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2009-08-13 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2009-08-13 00:00:00.0
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 9285 (Continued)

1014396774

NJ MANIFEST:

EPA Id: NYP004190898
Mail Address: 4 IRVING PLACE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: FRANKLYN MURRAY
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:

Manifest Number: 000894902GBF
EPA ID: NYP004190898
Date Shipped: 08/17/2009
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 08/17/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 08/18/2009
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 9285 (Continued)

1014396774

Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:

Manifest Year: Not reported
Waste Code: D008
Hand Code: H141
Quantity: 300 G

E37
NE
< 1/8
0.091 mi.
481 ft.

TRI-STATE TRUCK & TRAILER REPAIR INC.
84 18TH STREET
BROOKLYN, NY 11232
Site 6 of 16 in cluster E

NY AST A100395517
N/A

Relative:
Higher
Actual:
11 ft.

AST:

Name: TRI-STATE TRUCK & TRAILER REPAIR INC.
Address: 84 18TH STREET
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-612335
Program Type: PBS
UTM X: 584776.54746
UTM Y: 4502179.38194
Expiration Date: 06/21/2019
Site Type: Other

Affiliation Records:

Site Id: 502718
Affiliation Type: Facility Owner
Company Name: SALVATORE CALABRESE
Contact Type: MANAGER
Contact Name: FRANK SCIRE
Address1: 84 18TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (646) 701-1692
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2014-12-09

Site Id: 502718
Affiliation Type: Mail Contact
Company Name: TRI-STATE TRUCK & TRAILER REPAIR INC.
Contact Type: Not reported
Contact Name: FRANK SCIRE
Address1: 84 18TH STREET
Address2: Not reported
City: BROOKLYN
State: NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TRI-STATE TRUCK & TRAILER REPAIR INC. (Continued)

A100395517

Zip Code: 11232
Country Code: 001
Phone: (718) 832-4911
EMail: TRISTATETRUCKREPAIR@GMAIL.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2014-12-09

Site Id: 502718
Affiliation Type: Facility Operator
Company Name: TRI-STATE TRUCK & TRAILER REPAIR INC.
Contact Type: Not reported
Contact Name: FRANK SCIRE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 832-4911
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2014-12-09

Site Id: 502718
Affiliation Type: Emergency Contact
Company Name: SALVATORE CALABRESE
Contact Type: Not reported
Contact Name: FRANK SCIRE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 701-1692
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2014-12-09

Tank Info:

Tank Number: 001
Tank Id: 253841

Equipment Records:

J02 - Dispenser - Suction Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
K00 - Spill Prevention - None
G09 - Tank Secondary Containment - Modified Double-Walled
(Aboveground)
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TRI-STATE TRUCK & TRAILER REPAIR INC. (Continued)

A100395517

C00 - Pipe Location - No Piping
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Fiberglass Reinforced Plastic
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/21/2014
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: LSZINOMA
Last Modified: 04/14/2017
Material Name: waste oil/used oil

E38
NE
< 1/8
0.091 mi.
481 ft.

CON EDISON MANHOLE: 46454
84 18 TH ST OPPOSITE
BROOKLYN, NY 11232

RCRA NonGen / NLR

1016450711
NYP004297388

Site 7 of 16 in cluster E

Relative:
Higher
Actual:
11 ft.

RCRA NonGen / NLR:
Date form received by agency: 2013-04-29 00:00:00.0
Facility name: CON EDISON MANHOLE: 46454
Facility address: 84 18 TH ST OPPOSITE
BROOKLYN, NY 11232
EPA ID: NYP004297388
Contact: ANTHONY SIGNORE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 46454 (Continued)

1016450711

Used oil transporter: No

Historical Generators:

Date form received by agency: 2013-03-29 00:00:00.0

Site name: CON EDISON MANHOLE: 46454

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

E39
NE
< 1/8
0.094 mi.
495 ft.

CON EDISON - VAULT 6524
82 18TH ST
BROOKLYN, NY 11232
Site 8 of 16 in cluster E

RCRA-SQG 1024891396
NYP005106366

Relative:
Higher

Actual:
11 ft.

RCRA-SQG:

Date form received by agency: 2018-04-10 00:00:00.0

Facility name: CON EDISON - VAULT 6524

Facility address: 82 18TH ST
BROOKLYN, NY 11232

EPA ID: NYP005106366

Mailing address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003

Contact: ALYSSA SOTTO

Contact address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003

Contact country: US

Contact telephone: 212-460-2757

Contact email: SOTTOA@CONED.COM

EPA Region: 02

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.

Owner/operator address: IRVING PLACE
NEW YORK, NY 10003

Owner/operator country: US

Owner/operator telephone: 212-460-2757

Owner/operator email: Not reported

Owner/operator fax: Not reported

Owner/operator extension: Not reported

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: 2017-07-05 00:00:00.

Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.

Owner/operator address: IRVING PLACE
NEW YORK, NY 10003

Owner/operator country: US

Owner/operator telephone: 212-460-2757

Owner/operator email: Not reported

Owner/operator fax: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - VAULT 6524 (Continued)

1024891396

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2017-07-05 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: B002
. Waste name: Petroleum oil or other liquid containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs. This includes oil from electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

**E40
NE
< 1/8
0.094 mi.
495 ft.**

**MANHOLE 46454
OPPOSITE 82 18TH ST
BROOKLYN, NY**

**NY Spills S116553780
N/A**

Site 9 of 16 in cluster E

**Relative:
Higher**

SPILLS:

**Actual:
11 ft.**

Name: MANHOLE 46454
Address: OPPOSITE 82 18TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1311976 / 2014-03-24
Facility ID: 1311976
Facility Type: ER
DER Facility ID: 447811
Site ID: 492912
DEC Region: 2
Spill Cause: Human Error
Spill Class: Not reported
SWIS: 2401
Spill Date: 2014-03-24
Investigator: HRPATEL
Referred To: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE 46454 (Continued)

S116553780

Reported to Dept: 2014-03-24
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2014-03-24
Spill Record Last Update: 2014-03-24
Spiller Name: ERT
Spiller Company: CONEDISON
Spiller Address: 4 IRVING PL
Spiller Company: 999
Contact Name: ERT
DEC Memo: "Emis # 236380 3/24/14-Zhune spoke to ERT- Dennis Michaelides. He said third party spill. approximately 15 gallons of waste oil was found in Con-Ed- manhole. This spill is related with spill # 1311937. Con-Ed in process to clean the spill. 03/24/14-Hiralkumar Patel. case closed. refer to spill #: 1311937."

Remarks: "Third party company spilled motor to the street 50 made it to the manhole. Clean up is pending resources."

All Materials:

Site ID: 492912
Operable Unit ID: 1242423
Operable Unit: 01
Material ID: 2242979
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

**E41
NE
< 1/8
0.094 mi.
495 ft.**

**CON EDISON
82 18TH ST
BROOKLYN, NY 11232

Site 10 of 16 in cluster E**

**NY MANIFEST S121968320
N/A**

**Relative:
Higher

Actual:
11 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 82 18TH ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP005106366
Facility Status: Not reported
Location Address 1: 82 18TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S121968320

Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported
NY MANIFEST:
EPAID: NYP005106366
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

C42
South
< 1/8
0.096 mi.
508 ft.

MANHOLE 5580
3RD AVE IFO 702 22ND ST
BROOKLYN, NY

NY Spills **S106006903**
N/A

Site 8 of 10 in cluster C

Relative:
Higher
Actual:
16 ft.

SPILLS:
Name: MANHOLE 5580
Address: 3RD AVE IFO 702 22ND ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0205502 / 2002-10-29
Facility ID: 0205502
Facility Type: ER
DER Facility ID: 212737
Site ID: 260360
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 2002-08-26
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2002-08-26
CID: 365
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-08-26
Spill Record Last Update: 2002-10-29
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE 5580 (Continued)

S106006903

Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 144-710: 8-26-02 0050 HRS B. LEWIS # 07854 CREW CHIEF CABLE REPORTS WHILE GETTING READY TO PULL PRIMARY CABLE (ROUTINE WORK) FOR FUTURE FDR 8B82 IN MH5580 F/O # 700 3 AVE 16' S/O 22 ST HE FOUND APPROX 1 PINT UNKNOWN OIL ON 60 GALLONS WATER. THERE WAS NO FIRE OR SMOKE AT THIS LOCATION. NO PRIVATE PROPERTY AFFECTED. NO INJURIES DUE TO THIS OIL. HE SEE A SUMP IN STRUCTURE, CAN NOT TELL WHAT TYPE OF SUMP IT IS AT THIS TIME. HE DOES NOT SEE A SEWER CONNECTION , LIQUID SEEMS CONTAINED NO SEWERS OR WATERWAYS AFFECTED. HE TOOK A LIQUID SAMPLE AND REQUESTED EMERG PRIORITY FOR PCB SAMPLE RESULTS. CLEANUP PENDING SAMPLE RESULTS. 8/26/02=0650hrs LAB RESULTS RETURNED 4PPM LSN- 02-07947-001 UPDATE: 26-AUG-2002 5HRS ROSENKING ENVIROMENTAL OPS REPORTS DOUBLE WASHED STRUCTURE WITH BIO GEN 70. REMOVED ALL LIQUIDS IN STRUCTURE. FOUND SUMP SEALED. REMOVED E/S TAG # 21698. JOB COMPLETE 100% "

Remarks: "car parked in top of the manhole so it can't be cleaned up in the 24 hour diminimous - 1 pint unk oil on 60 gallons of water - clean up pending vehicle being moved - samples = 4 ppm - ref #144710"

All Materials:

Site ID: 260360
Operable Unit ID: 856951
Operable Unit: 01
Material ID: 519702
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

C43
South
< 1/8
0.096 mi.
508 ft.

MANHOLE 5580
3RD AVE/22ND ST
BROOKLYN, NY

NY Spills S103573162
N/A

Site 9 of 10 in cluster C

Relative:
Higher
Actual:
16 ft.

SPILLS:

Name: MANHOLE 5580
Address: 3RD AVE/22ND ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9809002 / 2002-10-30
Facility ID: 9809002
Facility Type: ER
DER Facility ID: 231417
Site ID: 285391
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 1998-10-19
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1998-10-19

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE 5580 (Continued)

S103573162

CID: 370
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-10-19
Spill Record Last Update: 2002-10-30
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ABOVE CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT Con Ed e2mis #120632: D.MUSSILLO #37381 O.S UNDERGROUND REPORTS WHILE INSPECTING LOCATION MH5580 FOR FEEDER WORK FOUND APPROX 4 OUNCES OF CABLE OIL LEAKED FROM 3C CABLE ENDS. HE CAPPED ENDS LEAKED STOPPED. TREATING AS 50-499 WILL PROCEED WITH CLEANUP. MH DRY NO SEWERS OR WATERWAYS AFFECTED NO SAMPLE TAKEN. #12255 . @ 2006 HRS CLEANUP COMPLETED DOUBLE WASHED WITH SLIX, ABSORBANT AND DIAPERS BY D.MUSSILLO."

Remarks: "4 ounce spill in electrical manhole spill contained and cleanup in progress - con ed#120632"

All Materials:

Site ID: 285391
Operable Unit ID: 1070191
Operable Unit: 01
Material ID: 556129
Material Code: 0020B
Material Name: cable oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: MANHOLE 5580
Address: 3RD AVE/22ND ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9911863 / 2002-03-05
Facility ID: 9911863
Facility Type: ER
DER Facility ID: 231417
Site ID: 285392
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2000-01-12
Investigator: COMENALE
Referred To: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE 5580 (Continued)

S103573162

Reported to Dept: 2000-01-12
CID: 382
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-01-12
Spill Record Last Update: 2002-03-05
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ABOVE CALLER
DEC Memo: ""
Remarks: "7 gals of oil on 3000 gals of water contained in manhole. clean up pending. con ed 129-574"

All Materials:

Site ID: 285392
Operable Unit ID: 1086415
Operable Unit: 01
Material ID: 297303
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 7.00
Units: G
Recovered: .00
Oxygenate: Not reported

C44
South
< 1/8
0.096 mi.
508 ft.

SPILL NUMBER 9807662
3RD AVENUE & 22ND STREET
BROOKLYN, NY

NY Spills S107409948
N/A

Site 10 of 10 in cluster C

Relative:
Higher
Actual:
16 ft.

SPILLS:
Name: SPILL NUMBER 9807662
Address: 3RD AVENUE & 22ND STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9807662 / 2002-12-24
Facility ID: 9807662
Facility Type: ER
DER Facility ID: 253130
Site ID: 313922
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1998-09-23
Investigator: JMROMMEL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 9807662 (Continued)

S107409948

Referred To: Not reported
Reported to Dept: 1998-09-23
CID: 266
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-09-23
Spill Record Last Update: 2002-12-24
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMELL Rommel responded, on site 15:15 on 9/23/98 no one from Con Ed on site. 17:52: Celestino Fernandez, Operating Supervisor for Con Ed, showed up and opened manhole cover to expose vault 14' by 5' with approximately 4 of water. No evidence of oil, no visible discharge point, climbed into manhole and confirmed that water was contained within vault. Con Ed sampled water for PCBs earlier in the day. They will pump it out within 48 hours. Spill reported after 2 hours. Con Ed indicated to Spills Hotline that the spill was cleaned up, however upon arrival, it was not cleaned out yet. "
Remarks: "MANHOLE 5580. LEAKING CABLE. INTO CONCRETE VAULT. CABLE REPAIRED. CLEANED UP."
All Materials:
Site ID: 313922
Operable Unit ID: 1068732
Operable Unit: 01
Material ID: 315220
Material Code: 0020B
Material Name: cable oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: 1.00
Oxygenate: Not reported

H45
ESE
< 1/8
0.100 mi.
526 ft.

SB46706
133 20TH ST
BROOKLYN, NY

Site 1 of 9 in cluster H

Relative:
Higher

Actual:
19 ft.

SPILLS:
Name: SB46706
Address: 133 20TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0006685 / 2001-11-26

NY Spills S104789222
N/A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SB46706 (Continued)

S104789222

Facility ID: 0006685
Facility Type: ER
DER Facility ID: 106159
Site ID: 122446
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2000-09-06
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2000-09-06
CID: 312
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-09-06
Spill Record Last Update: 2001-11-26
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #133220 Notes: 9-6-00 1qt unknown oil on 2gal water. Only oil filled equipment in hole is cable. Took a liquid sample and returned <1ppm PCB. 9-7-00 Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump."

Remarks: "1QT UNK PETROLEUM ON 2GAL WATER - CONTAINED - CASE #133220"

All Materials:
Site ID: 122446
Operable Unit ID: 827663
Operable Unit: 01
Material ID: 547791
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

H46
East
< 1/8
0.101 mi.
535 ft.

CON EDISON
647 3 AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR

1019326088
NYP004885154

Relative:
Higher

Actual:
18 ft.

RCRA NonGen / NLR:

Date form received by agency: 2016-02-26 00:00:00.0

Facility name: CON EDISON

Site name: CON EDISON - MANHOLE MH55605

Facility address: 647 3 AVE

BROOKLYN, NY 11215

EPA ID: NYP004885154

Mailing address: IRVING PLACE, 15TH FL NE

NEW YORK, NY 10003

Contact: THERESA BURKARD

Contact address: IRVING PLACE, 15TH FL NE

NEW YORK, NY 10003

Contact country: US

Contact telephone: 212-460-2262

Contact email: BURKARDT@CONED.COM

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.

Owner/operator address: IRVING PLACE
NEW YORK, NY 10003

Owner/operator country: US

Owner/operator telephone: Not reported

Owner/operator email: Not reported

Owner/operator fax: Not reported

Owner/operator extension: Not reported

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: 2015-12-30 00:00:00.

Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.

Owner/operator address: IRVING PLACE
NEW YORK, NY 10003

Owner/operator country: US

Owner/operator telephone: Not reported

Owner/operator email: Not reported

Owner/operator fax: Not reported

Owner/operator extension: Not reported

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: 2015-12-30 00:00:00.

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1019326088

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2015-12-30 00:00:00.0

Site name: CON EDISON

Classification: Not a generator, verified

Date form received by agency: 2015-12-30 00:00:00.0

Site name: CON EDISON

Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code: D008
Waste name: LEAD
Amount (Lbs): 3000

Violation Status: No violations found

H47
East
< 1/8
0.101 mi.
535 ft.

CON EDISON
647 3 AVENUE
BROOKLYN, NY 11232

NY MANIFEST **S113816792**
N/A

Site 3 of 9 in cluster H

Relative:
Higher

NY MANIFEST:

Actual:
18 ft.

Name: CON EDISON
Address: 647 3 AVENUE
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004333589
Facility Status: Not reported
Location Address 1: 647 3 AVENUE
Code: BP
Location Address 2: SERVICE BOX # 55767
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S113816792

NY MANIFEST:

EPAID: NYP004333589
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/23/2013
Trans1 Recv Date: 07/23/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/25/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004333589
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002085861GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 80
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S113816792

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

H48
East
< 1/8
0.101 mi.
535 ft.

CON ED
647 3RD AVE
BROOKLYN, NY 11215

NY MANIFEST

S119078276
N/A

Site 4 of 9 in cluster H

Relative:
Higher
Actual:
18 ft.

NY MANIFEST:
Name: CON ED
Address: 647 3RD AVE
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004885154
Facility Status: Not reported
Location Address 1: 647 3 AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004885154
Mailing Name: CON ED
Mailing Contact: CON ED
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

H49
East
< 1/8
0.101 mi.
535 ft.

CON EDISON
647 3 AVE
BROOKLYN, NY 11215

NJ MANIFEST

S120678612
N/A

Site 5 of 9 in cluster H

Relative:
Higher
Actual:
18 ft.

NJ MANIFEST:
EPA Id: NYP004885154
Mail Address: IRVING PLACE, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THERESA BURKARD
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S120678612

SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDf Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported
Manifest:	
Manifest Number:	002621935GBF
EPA ID:	NYP004885154
Date Shipped:	12/30/2015
TSDf EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDf Received Waste:	Not reported
TSDf EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

H50
ESE
< 1/8
0.104 mi.
551 ft.

20TH STREET COLLISION & AUTO REPAIR INC.
135 20TH STREET
BROOKLYN, NY 11232
Site 6 of 9 in cluster H

Database(s)

NY AST

A100386218
N/A

Relative:
Higher

Actual:
20 ft.

AST:

Name: 20TH STREET COLLISION & AUTO REPAIR INC.
Address: 135 20TH STREET
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-612181
Program Type: PBS
UTM X: 584821.08382
UTM Y: 4501972.18728
Expiration Date: 03/14/2024
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 491809
Affiliation Type: Facility Owner
Company Name: 135 20TH STREET CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 135 20TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (917) 921-8012
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-01-30

Site Id: 491809
Affiliation Type: Mail Contact
Company Name: 20TH STREET COLLISION & AUTO REPAIR INC.
Contact Type: Not reported
Contact Name: GHASSAN AMIN
Address1: 135 20TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 965-7000
EMail: GHASSANAMIN1@GMAIL.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-03-14

Site Id: 491809
Affiliation Type: Facility Operator
Company Name: 20TH STREET COLLISION & AUTO REPAIR INC.
Contact Type: Not reported
Contact Name: KHALED F. SALEH

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

20TH STREET COLLISION & AUTO REPAIR INC. (Continued)

A100386218

Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-7000
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-02-19

Site Id: 491809
Affiliation Type: Emergency Contact
Company Name: 135 20TH STREET CORP.
Contact Type: Not reported
Contact Name: GHASSAN AMIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 324-7397
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-02-19

Tank Info:

Tank Number: 001
Tank Id: 251163

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/07/2014
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

20TH STREET COLLISION & AUTO REPAIR INC. (Continued)

A100386218

Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: waste oil/used oil

E51
ENE
< 1/8
0.108 mi.
572 ft.

CON EDISON
100 18 ST
BROOKLYN, NY 11215
Site 11 of 16 in cluster E

NY MANIFEST **S117737750**
N/A

Relative:
Higher
Actual:
14 ft.

NY MANIFEST:
Name: CON EDISON
Address: 100 18 ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004675740
Facility Status: Not reported
Location Address 1: 100 18 ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004675740
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/09/2014
Trans1 Recv Date: 10/09/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/10/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004675740
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117737750

TSD ID 1: NJD002200046
TSD ID 2: Not reported
Manifest Tracking Number: 012774613JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 800
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

I52
NW
< 1/8
0.109 mi.
574 ft.

73 20TH ST
73 20TH ST
BROOKLYN, NY
Site 1 of 7 in cluster I

NY Spills S117974852
N/A

Relative:
Lower
Actual:
0 ft.

SPILLS:
Name: 73 20TH ST
Address: 73 20TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1503309 / 2017-02-14
Facility ID: 1503309
Facility Type: ER
DER Facility ID: 464228
Site ID: 509607
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2015-06-25
Investigator: PXLAKHAN
Referred To: Not reported
Reported to Dept: 2015-06-25
CID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

73 20TH ST (Continued)

S117974852

Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2015-06-25
Spill Record Last Update: 2017-02-14
Spiller Name: Not reported
Spiller Company: OTW GROUP
Spiller Address: Not reported
Spiller Company: 999
Contact Name: TOM
DEC Memo: "6/25/2015 - Feng - Duty Desk. Talked to Thomas Melia of PW Grosser (631-589-6353, 516-315-6002, ThomasM@PWGrosser.com). PW Grosser is working for the interested buyer. They did a Phase 2 investigation. A GPR survey has identified an anomaly possibly UST. Soil borings were then installed around the UST. One boring hit high PID reading, one boring with high SVOCs and one boring with high VOCs. He is not aware of any future development plan. DEC required the Phase 1, Phase 2 and the contact information of the owner and the buyer. sent email to Thomas Melia for the submitting the Phase 1 and 2 rpts and the contact info of the owner and buyer. 9/28/15: Mahat DEC Mahat talked to Tom (PWG) and he will forward the Phase II report on the site. Future action on remediation on the site in still unknown. No plans for remediation yet. 12/23/2015: Rashad Spill reassigned from Mahat to Omar as per DeMeo. 12/24/2015: Rashad 73 20th Street does not have an alternate address. No additional spills or PBS registration found for site. No documents found in D2. 12/30/2015: Rashad Sent email to Tom: Spill#1503309 for 73 20th Street, Brooklyn NY 11232 has been reassigned to me. The previous notes in this case indicate that a Phase 2 investigation was conducted on the site. Would you be able to send me the Phase 2 document as well as any other documents/information you have? 5/20/2016: Rashad Sent email to Tom: Just following up on the email I sent you back in December seen below. Are you still involved in this project and can you send me the relevant reports? It is greatly appreciated. Thank you. 1/13/2017 Austin This spill report is being transferred from Rashad Omar to Pratik Lakhani end. 01/30/17 - Lakhani 10:35 AM: Called to PWG Thomas Melia. He informed that the Phase II report was not released due to lack of permission from the interested buyer. He said he would reach out to the interested buyer to determine whether the deal had fallen through and if the report can be released to the DEC. DEC Lakhani gave PWG Melia his contact. PWG Melia emailed the following: Just to follow up on our call earlier today, I reached out to our client to request permission to release the Phase II ESA to DEC. I have not heard back, but will let you know when I do. Also, after reviewing our file, it looks like the deal did in fact go through, and our client closed on the property in mid-August 2015. Let me know if there s anything else I can do to help. 73 20th Street aka 73-18 20th Street aka 96-104 19th Street. File Review: Limited Phase II Environmental Site Assessment (PWG Thomas Melia, 06/15) - The building contains an import and export company on the main and second floors and a storage company and labor union office on the main

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

73 20TH ST (Continued)

S117974852

floor. Historical maps show three (3) USTs inside the warehouse at 96-104 19th Street. Three (3) fill ports/vent pipes in the warehouse area of 96-104 19th Street were identified. Three (3) soil borings [SB001, SB002, SB003] were taken and one (1) groundwater sample [GW001]. Soil samples were field screened for the presence of VOCs with a PID. Groundwater was encountered at the site 8'-10'bg. Maximum PID responses were 11.7 ppm in SB002 and 1406 ppm in SB003. To determine if the historic usage of the property is causing soil vapor intrusion within the building, two (2) soil vapor samples and two (2) indoor air samples and one (1) ambient air sample were collected. VOCs were detected at concentrations exceeding their respective unrestricted use SCOs in soils collected from boring SB003. Results show: 1,2,4 trimethylbenzene 320ppm (SB003, 6-8'bg), 1,3,5 trimethylbenzene 94ppm (SB003, 6-8'bg), benzene 7.4ppm (SB003, 6-8'bg), ethylbenzene 120ppm (SB003, 6-8'bg), toluene 7.7ppm (SB003, 6-8'bg), xylene 110ppm (SB003, 6-8'bg), MTBE 8.4ppm (SB003, 6-8'bg), naphthalene 45ppm (SB003, 6-8'bg). SVOCs were detected at concentrations exceeding their respective unrestricted use SCOs in soils collected from soil boring SB002. Based on groundwater sampling results, it does not appear that the historic presence of USTs at the site has impacted groundwater at the subject property. Indoor air and sub slab vapor concentrations detected for PCE fell within the no further action category at each of the sample locations. With the exception of location IA002/SV002, TCE concentrations in indoor air and soil vapor fell within the no further action category. At location IA002/SV002, concentrations fell in the take reasonable and practical actions to identify source(s) and reduce exposures category. 01/31/17 - Lakhani DEC Lakhani sent the following email to NYSDOH Nathan Walz: I was recently assigned a case for the property at 73 20th Street in Brooklyn (aka 96-104 19th Street), referred to as the Site here forth, that has concerns with respect to the SVI study that was performed at the site as part of a Phase II ESA. As such I am seeking NYSDOH s review and comment on the soil vapor intrusion study of the report to determine what further action by the responsible party is needed. Attached to this email is a detailed site plan and the Phase II ESA report from June 2015. The property is occupied by a single-story commercial building which contains an import and export company on the main and second floors and a storage company and a labor union office on the main floor. A Phase I ESA dated May 18, 2015 prepared by Middleton Environmental, Inc. (MEI) identified the property to have been previously occupied by a paint manufacturer and garage company, both of which with the potential to have impacted the subsurface. Historical maps show three (3) USTs inside the warehouse at the Site. Based on the findings of the Phase I ESA, MEI recommended a Phase II ESA be performed. The Phase II ESA was completed by P. W. Grosser Consulting on June 16, 2015 which included a geophysical survey to identify potential USTs at the Site, a subsurface investigation, and a soil vapor intrusion evaluation. Five (5) soil borings were installed and three (3) groundwater samples were collected. All groundwater samples met CP-51 limits. One of the soil boring (SB003) on the Site showed concentrations of VOCs that exceeded CP-51 limits. Nevertheless, the Department has no further concerns with respect to soil or groundwater contamination. In addition, four (4) soil vapor samples and four (4) indoor air samples were taken. The soil vapor samples and some indoor air samples showed exceedances of VOC concentrations as per the average levels determined by the NYSDOH study (see detailed site plan for

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

73 20TH ST (Continued)

S117974852

concentrations). With maximum concentrations of TCE and PCE in soil vapor at the Site to be 1.49 ug/m3 and 1.07 ug/m3 respectively and in indoor air at the Site to be 1.36 ug/m3 for PCE. However, both TCE and PCE do not require any further action at the Site as per the NYSDOH matrices. I would appreciate any assistance or guidance that you may provide so that I can potentially close this case. I also wanted to bring to your attention that there are VOCs present, in addition to PCE and TCE, in the soil vapor samples at the Site. The concentrations are as follow: benzene 7.64 ug/m3 (SV003), ethylbenzene 8.21 ug/m3 (SV003), toluene 28.9 ug/m3 (SV003), o-xylene 7.95 ug/m3 (SV003), p/m-xylene 23 ug/m3 (SV003), benzene 8.82 ug/m3 (SV004), ethylbenzene 15.2 ug/m3 (SV004), toluene 25.8 ug/m3 (SV004), o-xylene 11.4 ug/m3 (SV004), and p/m-xylene 23.8 ug/m3 (SV004). NYSDOH responded: Based on my review of the report, I understand that that additional excavation of soil around the UST to get to clean end points will occur. Also, there are minimal concentrations of contaminants of concern in soil vapor and indoor air results indicated background concentrations are present. Based on the above information, I have no further comments or recommendations for this site. PWG Thomas Melia informed that their client on the Phase II ESA (who was purchasing the property) was: David Blumberg The 601W Companies 601 West 26th St. Suite 1275 New York, NY 10001 Email: dblumberg@601west.com The following email was sent to David Blumberg: My name is Pratik Lakhani and I work at the New York State Department of Environmental Protection. I was recently assigned the spill for your property at 73 20th Street, also known as 96-104 19th Street, in Brooklyn. I understand you hired P.W. Grosser Consulting to conduct a Phase II Environmental Site Assessment in 2015. I ve spoken to the P.W.G project manager, Thomas Melia about the site and he sent me the Phase II study. After inquiring with NYS Department of Health regarding the soil vapor intrusion study in the Phase II ESA, I have decided to close the spill case on the property. However, before I do so I wanted to get more information about the property. P.W.G recommended in their Phase II ESA to remove the UST and all impacted soils. Were these recommendations accepted and was this work completed at the site? If so, do you have any reports for the work? I was also wondering what the current use of the property is or will be? Please let me know as I would like to close this spill as soon as possible. 02/03/17 - Lakhani DEC Lakhani called 601W Companies (2124144603) twice, both times the call was busy and so no message could be left. 02/14/17 - Lakhani DEC Lakhani called 601W Companies and the call was busy. Spill closure with residual soil contamination letter sent to 601W David Blumberg. As per Vought, spill closed." "Caller states that during the Phase II investigation they determined soil to be affected by an unknown petroleum spill with unknown quantity."

Remarks:

All Materials:

Site ID: 509607
Operable Unit ID: 1258888
Operable Unit: 01
Material ID: 2262117
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

73 20TH ST (Continued)

S117974852

Recovered: Not reported
Oxygenate: Not reported

G53
SSE
< 1/8
0.109 mi.
577 ft.

EDWARD T MINOR CO
133 22ND ST
BROOKLYN, NY
Site 7 of 9 in cluster G

NY Spills S105141254
N/A

Relative:
Higher

Actual:
18 ft.

SPILLS:

Name: EDWARD T MINOR CO
Address: 133 22ND ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0104859 / 2001-10-25
Facility ID: 0104859
Facility Type: ER
DER Facility ID: 262835
Site ID: 326265
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2001-08-06
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2001-08-06
CID: 405
Water Affected: Not reported
Spill Source: Tank Truck
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-08-06
Spill Record Last Update: 2001-10-25
Spiller Name: MARY
Spiller Company: EDWARD T MINOR CO
Spiller Address: 133 22ND ST
Spiller Company: 001
Contact Name: MARY
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 15 GALLON STREET SPILL CAUSED BY MALFUNCTIONING VALVE ON TANK TRUCK. MECHANICS FROM OIL COMPANY STOPPED LEAK AND APPLIED ABSORBENTS TO SPILL FOR CONTAINMENT PURPOSES. CATCH BASINS IMPACTED FROM RELEASE. DEC NOTIFIED DEP FOR POSSIBLE SEWER IMPACTS. RP NOTIFIED RESPONSE ENVIRONMENTAL FOR CLEANUP. VAC TRUCK MOBILIZED TO PUMP CATCH BASINS AND CREW TO CLEAN STREET IMPACTS. 10/25/01 ROBERT CROSSEN/FILE. RECEIVED REPORT FROM RESPONSE ENVIRONMENTAL, SPILL CLEANED UP, DEP INSPECTED SITE AND APPROVED, THREE DRUMS OF SPILL DEBRIS DISPOSED OF AND DOCUMENTED, NO FURTHER ACTION REQUIRED. CLOSE OUT "

Remarks:

"caller states thier tank truck had a bad valve and approx 15 gallons spilled - also into 2 sewer drains - have a dispatched a vac truck"

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EDWARD T MINOR CO (Continued)

S105141254

All Materials:

Site ID: 326265
Operable Unit ID: 841611
Operable Unit: 01
Material ID: 533339
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15.00
Units: G
Recovered: 15.00
Oxygenate: Not reported

E54
ENE
< 1/8
0.110 mi.
580 ft.

TRANSFORMER VAULT - MANHOLE # 6524
18TH ST & HAMILTON AVE
BROOKLYN, NY

NY Spills S121099739
N/A

Site 12 of 16 in cluster E

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name: TRANSFORMER VAULT - MANHOLE # 6524
Address: 18TH ST & HAMILTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1702659 / 2017-09-06
Facility ID: 1702659
Facility Type: ER
DER Facility ID: 506420
Site ID: 552802
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: D4
SWIS: 2401
Spill Date: 2017-06-18
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 2017-06-18
CID: Not reported
Water Affected: Not reported
Spill Source: Transformer
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2017-06-18
Spill Record Last Update: 2017-09-06
Spiller Name: CON EDISON
Spiller Company: CON EDISON
Spiller Address: 18TH ST & HAMILTON AVE
Spiller Company: 999
Contact Name: CON EDISON
DEC Memo: "emis_258610 9/6/17 - Austin - 1 pint dielectric fluid atop 60 gals
water in vault - Con Ed contained and cleaned up the spill, and

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TRANSFORMER VAULT - MANHOLE # 6524 (Continued)

S121099739

Remarks: replaced the defective transformer - See document files for further information - Spill closed - end"
"1 pint oil on 60 Gals of water in a Tidal Manhole. Cleanup is pending sample results."

All Materials:

Site ID: 552802
Operable Unit ID: 1300886
Operable Unit: 01
Material ID: 2307157
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .13
Units: G
Recovered: .13
Oxygenate: Not reported

**E55
ENE
< 1/8
0.110 mi.
580 ft.**

**SEWER
18TH ST AND HAMILTON AVE
BROOKLYN, NY**

**NY Spills S116553746
N/A**

Site 13 of 16 in cluster E

**Relative:
Higher
Actual:
14 ft.**

SPILLS:

Name: SEWER
Address: 18TH ST AND HAMILTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1311937 / 2014-03-24
Facility ID: 1311937
Facility Type: ER
DER Facility ID: 447780
Site ID: 492873
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2014-03-21
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 2014-03-21
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2014-03-21
Spill Record Last Update: 2014-03-24
Spiller Name: Not reported
Spiller Company: COBRA CITY OIL
Spiller Address: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SEWER (Continued)

S116553746

Spiller Company:
Contact Name:
DEC Memo:

999
ANDREW WILSON
"03/21/14-Hiralkumar Patel. 10:05 PM:- visited site. met Andrew Wilson, truck driver. Andrew works for Cobra City Oil Recycling. he mentioned that truck had about 100 gal waste oil this morning. then he pumped about 200 gal more waste oil from repair shops in bronx. his truck broke down in Bronx and was being towed to Tri-State Truck Repair (718-832-4911), located at 84 18th Street, Brooklyn. just before intersection of Hamilton Ave and 17th Street (about 0.2 miles from the repair shop), drive shaft on the truck broke and it punctured tank holding waste oil. all of the amount spilled onto street. some of the oil got into catch basin located in southwest corner of the intersection of 17th Street and Hamilton Ave. leaking truck was parked along north sidewalk of 18th Street, across the street from the repair shop. found pool of oil underneath the leaking truck and other broke down vehicles located along same side of the street. Skyway Environmental Services was doing cleanup. minor petroleum odors were noted in area. Andres Cobra City Oil Recycling PH. (347) 706-9528 Harry Cobra City Oil Recycling PH. (347) 742-2175 Franklin Bonilla Skyway environmental services Ph. (718) 220-3081 03/22/14-Hiralkumar Patel. 5:25 PM:- received call from Skyway Env. person mentioned that while cleaning up the area under the parked leaking truck, they noted a ConEd structure that was fully covered with oil. informed Skyway not to enter ConEd structure and ConEd will do cleanup. 03/24/14-Hiralkumar Patel. 9:10 AM:- visited site. inspected areas which were impacted by the spill. spill on street and catch basin was cleaned up. no soil impact noted. noted a ConEd manhole (with rectangular cover), on north side of 18th St. 9:19 AM:- spoke with ConEd ERT and reported possible spill into their structure. ConEd will inspect the area. received a spill report (# 1311976) from ConEd. 50 gal oil spilled into manhole. based on observations during site visits, case closed after discussing with DEC Austin."

Remarks:

"Caller advised driveshaft on truck broke and punctured the tank. All the oil spilled onto the street and FDNY have the sewers dyked. Clean up is pending."

All Materials:

Site ID: 492873
Operable Unit ID: 1242384
Operable Unit: 01
Material ID: 2242940
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 500.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

E56
ENE
< 1/8
0.110 mi.
580 ft.

SPILL NUMBER 0304223
HAMILTON AVE & 18TH ST
BROOKLYN, NY

NY Spills S106016341
N/A

Site 14 of 16 in cluster E

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name: SPILL NUMBER 0304223
Address: HAMILTON AVE & 18TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0304223 / 2003-08-27
Facility ID: 0304223
Facility Type: ER
DER Facility ID: 174433
Site ID: 210426
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2003-07-22
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2003-07-22
CID: 205
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-07-22
Spill Record Last Update: 2003-08-27
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 149-417: 7/22/03 08:30HRS FOUND TWO QUARTS OF UNKNOWN OIL ON 200 GALLONS OF WATER. AT THIS TIME OIL APPEARS TO BE CONTAINED. NO FIRE SMOKE OR PRIVATE PROPERTY INVOLVED. UNABLE TO DETERMINE AT THIS TIME IF ANY SEWER CONNECTIONS OR SUMPS ARE INVOLVED BECAUSE OF THE AMOUNT OF WATER IN STRUCTURE. LIQUID SAMPLE WAS TAKEN. HISTORICAL RECORDS INDICATE THAT ITS A G.E TRANSFORMER 500KVA INSTALLED DATE 01/01/1976 AND HAS APPROX 290 GALLONS OF OIL. AT THIS TIME NETWORKS WILL BE GOING TO LOCATION TO PRESSURE TEST T.M. THIS JOB WILL BE TREATED AS A 50-499 CLEANUP. 7/22/03 09:16HRS ENG RECORDS INDICATE THAT STRCTURE HAS A SOIL DRAIN. 7/22/03 15:07 HRS. -- PCB RESULTS: LAB SEQ # 03-06023, <1.0 PPM. A. WALKER, O.S. BROOKLYN ENV. OPS. IS ON LOCATION AND WAS NOTIFIED. 7/22/03 15:35 HRS. -- G. PALLADINO, O.S. WITH BROOKLYN/QUEENS EQUIPMENT GROUP REPORTS TRANSFORMER WAS CONDEMNED AND WILL BE REPLACED. UNABLE TO PRESSURE EARLIER DUE TO UNDERGROUND PREPARING LIVE END CAP IN VAULT. FEEDER IS NOW IN PROCESS OF BEING RESTORED -- EQUIP. GROUP WILL PRESSURE-TEST THE TRANSFORMER AFTER FEEDER RESTORED. -- W.W. #17344 -- Update - 7/22/03 1600hrs A. Walker, env. ops OS reports due to severe weather

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0304223 (Continued)

S106016341

conditions the rain is causing a tremendous amount of water entering the structure. 22-JUL-2003 23:20 HRS. NETWORKS DEPT. SPLICER. V.DINEEN EMP# 41974 REPORTS: UNIT PRESSURE TESTED AND FAILED. UNIT LEAKED PRESSURE FROM THE A-B PHASE. NO OIL LEAKED FROM UNIT. OIL LEVEL IS 25+. THIS UNIT HAS BEEN CONDEMNED. PRELIMINARY CLEANUP TO PROCEED. ENVIR. TAG WILL REMAIN IN PLACE PENDING UNIT REPLACEMENT. UPDATE : 23-JUL-2003 04:00 HRS. ENVIR. FLUSH DEPT. MECH-A J.IOCCO EMP# 56611 REPORTS : ASTORIA TANKER REMOVED ALL LIQUIDS FROM STRUCTURE. STRUCTURE THEN DBL. WASHED WITH BIO-GEN 760. ALL SOLID DEBRIS REMOVED FROM STRUCTURE WITH VACTOR. ENVIR. TAG WILL REMAIN IN PLACE PENDING UNIT REMOVAL. SUMP FOUND SEALED IN STRUCTURE. Update - 7/23/03 1350hrs R. Cilentro # 44214, Networks reports old transformer was removed. Structure is ready to be cleaned. UPDATE - 7/23/03 1525HRS A. WALKER OS ENV. OPS REPORTS STRUCTURE IS STILL MAKING WATER. WILL COMPLETE JOB AS A TM MEET. 7/24/03 13:10 HRS. -- J. LIPORI OF BROOKLYN ENV. OPS. REPORTS THAT AFTER NETWORKS REMOVED TRANSFORMER HE & S.KARTELL DOUBLE WASHED STRUCTURE WITH SLIX, FOUND SUMP ALREADY SEALED AND REMOVED ENV. STOP TAG # 04562. NETWORKS IS ON LOCATION TO INSTALL NEW TRANSFORMER. CLEANUP 100% COMPLETE. -- W.W. #17344 -- 7/24/03 13:24 HRS. -- M. ADAMO OF NETWORKS REPORTS HOLE CLEANED BY FLUSH DEPT AND NETWORKS INSTALLED NEW TRANSFORMER." "2qt's oil on 200 gallons water. con ed 149417. samples taken."

Remarks:

All Materials:

Site ID: 210426
Operable Unit ID: 872478
Operable Unit: 01
Material ID: 505080
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

E57
ENE
< 1/8
0.110 mi.
580 ft.

CON EDISON - MANHOLE 55571
HAMILTON AVE & 3RD AVE
BROOKLYN, NY 11232

RCRA-LQG 1014396775
NJ MANIFEST NYP004190906
NY MANIFEST

Site 15 of 16 in cluster E

Relative:
Higher

RCRA-LQG:

Actual:
14 ft.

Date form received by agency: 2010-03-23 00:00:00.0
Facility name: CON EDISON - MANHOLE 55571
Facility address: HAMILTON AVE & 3RD AVE
BROOKLYN, NY 11232
EPA ID: NYP004190906
Mailing address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact: FRANKLYN MURRAY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-2808
Contact email: MURRAYFR@CONED.COM

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 55571 (Continued)

1014396775

EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2009-08-13 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2009-08-13 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 55571 (Continued)

1014396775

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2009-08-13 00:00:00.0
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NJ MANIFEST:

EPA Id: NYP004190906
Mail Address: 4 IRVING PLACE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: FRANKLYN MURRAY
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:

Manifest Number: 000894337GBF
EPA ID: NYP004190906
Date Shipped: 08/25/2009
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 08/25/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 55571 (Continued)

1014396775

Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 08/25/2009
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:

Manifest Year: Not reported
Waste Code: D008
Hand Code: H141
Quantity: 1200 G

NY MANIFEST:

Name: CONSOLIDATED EDISON
Address: HAMILTON AVE & 3RD AVE
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004190906
Facility Status: Not reported
Location Address 1: HAMILTON AVE & 3RD AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004190906
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 55571 (Continued)

1014396775

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/25/2009
Trans1 Recv Date: 08/25/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/25/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004190906
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 000894337GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1200.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

E58
ENE
< 1/8
0.110 mi.
580 ft.

CON EDISON
18TH ST & HAMILTON AVE
BROOKLYN, NY 11232

RCRA NonGen / NLR
NY MANIFEST

1014396770
NYP004190856

Site 16 of 16 in cluster E

Relative:
Higher

RCRA NonGen / NLR:

Actual:
14 ft.

Date form received by agency: 2016-06-01 00:00:00.0
Facility name: CON EDISON
Facility address: 18TH ST & HAMILTON AVE
BROOKLYN, NY 11232
EPA ID: NYP004190856
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: CAROLINE ISKANDER
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2009-08-13 00:00:00.0
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Name: CONSOLIDATED EDISON
Address: 18TH ST & HAMILTON AVE
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004190856
Facility Status: Not reported
Location Address 1: 18th ST & HAMILTON AVE - MH 46453
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1014396770

Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004190856
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/21/2009
Trans1 Recv Date: 08/21/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/25/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004190856
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 000894940GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1014396770

Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

J59
SSW
< 1/8
0.115 mi.
606 ft.

POWER PLANT - JOSEPH J SEYMOUR
3RD AVE 23 ST
BROOKLYN, NY

NY Spills S117975521
N/A

Site 1 of 6 in cluster J

Relative:
Higher
Actual:
12 ft.

SPILLS:
Name: POWER PLANT - JOSEPH J SEYMOUR
Address: 3RD AVE 23 ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1504045 / 2015-07-15
Facility ID: 1504045
Facility Type: ER
DER Facility ID: 464946
Site ID: 510374
DEC Region: 2
Spill Cause: Human Error
Spill Class: Not reported
SWIS: 2401
Spill Date: 2015-07-13
Investigator: RJFENG
Referred To: Not reported
Reported to Dept: 2015-07-15
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2015-07-15
Spill Record Last Update: 2015-07-16
Spiller Name: WALTER SOTO
Spiller Company: POWER PLANT
Spiller Address: 3RD AVE 23 ST
Spiller Company: 999
Contact Name: WALTER SOTO
DEC Memo: "7/15/2015 - Feng - Duty Desk. Forward a spill report to Sam Liablich in Division of Air. It is not petroleum discharge and it is to the air. Spill closed. "
Remarks: "1 lb. over limit to air"
All Materials:
Site ID: 510374

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

POWER PLANT - JOSEPH J SEYMOUR (Continued)

S117975521

Operable Unit ID: 1259640
Operable Unit: 01
Material ID: 2262970
Material Code: 2692A
Material Name: nitrogen dioxide
Case No.: 10102440
Material FA: Hazardous Material
Quantity: 1.00
Units: L
Recovered: Not reported
Oxygenate: Not reported

**H60
East
< 1/8
0.115 mi.
608 ft.**

**CON EDISON
123-19 ST
BROOKLYN, NY 11201
Site 7 of 9 in cluster H**

**NY MANIFEST S117065808
N/A**

**Relative:
Higher**

NY MANIFEST:

Name: CON EDISON
Address: 123-19 ST
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004584017
Facility Status: Not reported
Location Address 1: 123-19 ST
Code: BP
Location Address 2: SB46592
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

**Actual:
19 ft.**

NY MANIFEST:

EPAID: NYP004584017
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/02/2014
Trans1 Recv Date: 07/02/2014
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117065808

TSD Site Recv Date: 07/02/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004584017
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID 1: NJD991291105
TSD ID 2: Not reported
Manifest Tracking Number: 002503913GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

J61
SSW
< 1/8
0.116 mi.
614 ft.

NYCDEP
27 23 16TH ST
BROOKLYN, NY 11201
Site 2 of 6 in cluster J

NY MANIFEST 1009235664
N/A

Relative:
Higher
Actual:
12 ft.

NY MANIFEST:
Name: NYCDEP
Address: 27 23 16TH ST
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP003661386
Facility Status: Not reported
Location Address 1: 27 23 16TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCDEP (Continued)

1009235664

Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP003661386
Mailing Name: NYCDEP
Mailing Contact: ROSS POLONETSKY
Mailing Address 1: 96 05 HORACE HARDING EXPWY
Mailing Address 2: Not reported
Mailing City: CORONA
Mailing State: NY
Mailing Zip: 11368
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7185954658

NY MANIFEST:

Document ID: NYG2938941
Manifest Status: Not reported
seq: 01
Year: 2002
Trans1 State ID: PD3678
Trans2 State ID: Not reported
Generator Ship Date: 03/18/2002
Trans1 Recv Date: 03/18/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/18/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP003661386
Trans1 EPA ID: NYD986908085
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00020
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCDEP (Continued)

1009235664

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

K62
South
< 1/8
0.117 mi.
616 ft.

CON EDISON SPLICE BOX: 45017
709 3RD AVE
BROOKLYN, NY 11220
Site 1 of 6 in cluster K

RCRA NonGen / NLR **1016960704**
NY MANIFEST **NYP004328290**

Relative:
Higher

RCRA NonGen / NLR:

Actual:
18 ft.

Date form received by agency: 2013-08-12 00:00:00.0
Facility name: CON EDISON SPLICE BOX: 45017
Facility address: 709 3RD AVE
BROOKLYN, NY 11220
EPA ID: NYP004328290
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: ANTHONY SIGNORE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2013-07-12 00:00:00.0
Site name: CON EDISON SPLICE BOX: 45017
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Name: CON EDISON
Address: 709 3RD AVE
City,State,Zip: BROOKLYN, NY 11220
Country: USA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SPLICE BOX: 45017 (Continued)

1016960704

EPA ID: NYP004328290
Facility Status: Not reported
Location Address 1: 709 3 AVE
Code: BP
Location Address 2: SB #45017
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004328290
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/12/2013
Trans1 Recv Date: 07/12/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/16/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004328290
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002084669GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SPLICE BOX: 45017 (Continued)

1016960704

Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 250
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

G63
SSE
< 1/8
0.117 mi.
617 ft.

CON EDISON SERVICE BOX: 46842
137 22ND ST
BROOKLYN, NY 11232
Site 8 of 9 in cluster G

RCRA NonGen / NLR **1017777876**
NYP004557815

Relative:
Higher
Actual:
20 ft.

RCRA NonGen / NLR:
Date form received by agency: 2014-07-09 00:00:00.0
Facility name: CON EDISON SERVICE BOX: 46842
Facility address: 137 22ND ST
BROOKLYN, NY 11232
EPA ID: NYP004557815
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 46842 (Continued)

1017777876

Historical Generators:

Date form received by agency: 2014-06-09 00:00:00.0

Site name: CON EDISON

Classification: Small Quantity Generator

Date form received by agency: 2014-06-09 00:00:00.0

Site name: CON EDISON

Classification: Not a generator, verified

Violation Status: No violations found

G64
SSE
< 1/8
0.117 mi.
617 ft.

CON EDISON
137 22ND ST
BROOKLYN, NY 11232

Site 9 of 9 in cluster G

NY MANIFEST **S117063365**
N/A

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:
Name: CON EDISON
Address: 137 22ND ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004557815
Facility Status: Not reported
Location Address 1: 137 22 ST
Code: BP
Location Address 2: SB46842
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004557815
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 06/09/2014
Trans1 Recv Date: 06/09/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/09/2014
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117063365

Part B Recv Date: Not reported
Generator EPA ID: NYP004557815
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002423141GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

L65
ENE
< 1/8
0.117 mi.
618 ft.

MANHOLE #55605
3RD AVE & 18TH ST
BROOKLYN, NY

Site 1 of 13 in cluster L

NY Spills S106016413
N/A

Relative:
Higher

Actual:
15 ft.

SPILLS:
Name: MANHOLE #55605
Address: 3RD AVE & 18TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0304282 / 2003-08-27
Facility ID: 0304282
Facility Type: ER
DER Facility ID: 258000
Site ID: 320223
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2003-07-22

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE #55605 (Continued)

S106016413

Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2003-07-23
CID: 297
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-07-23
Spill Record Last Update: 2003-08-27
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: ANDREW MORRIS
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #149420: 7/22/03 11:20 HRS. R. CALISE #14889, FIELD OPERATOR WITH F.O.D., REPORTS WHILE ON LOCATION TO MARK PHASES ON FEEDER 8B90 AT 11:15 HRS. FOUND APPROX. 2 PINTS UNKNOWN OIL ON APPROX. 300 GAL. WATER IN MH-55605. 7/22/03 20:04 HRS. -- LAB SEQ 03-06041, 3 PPM, AROCLOR 1254. UPDATE - 23-JUL-2003 11:56 HRS. ASTORIA TANKER REMOVED ALL LIQUIDS FROM STRUCTURE, ALL SOLID DEBRIS REMOVED FROM STRUCTURE WITH VACTOR. SUMP FOUND CEMENTED. ENVIR. TAG# 30404 REMOVED. CLEANUP COMPLETE 100%. "
Remarks: "SMALL AMOUNT OF OIL WAS FOUND FLOATING ON 300 GALS. OF WATER IN THE ABOVE MANHOLE / CON ED SPILL #149420"
All Materials:
Site ID: 320223
Operable Unit ID: 871148
Operable Unit: 01
Material ID: 505135
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

L66
ENE
< 1/8
0.117 mi.
618 ft.

**VS 6601 HAS 50 GAL DIELECTRIC FLUID
3 AVENUE & 18 STREET
BROOKLYN, NY**
Site 2 of 13 in cluster L

**NY Spills S108764618
N/A**

**Relative:
Higher
Actual:
15 ft.**

SPILLS:
Name: EIGHT GALLONS OIL IN VS6601
Address: 3 AVENUE & 18 STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0705905 / 2007-09-20

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VS 6601 HAS 50 GAL DIELECTRIC FLUID (Continued)

S108764618

Facility ID: 0705905
Facility Type: ER
DER Facility ID: 335700
Site ID: 386318
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2007-08-24
Investigator: gdbreen
Referred To: Not reported
Reported to Dept: 2007-08-24
CID: 78
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-08-24
Spill Record Last Update: 2007-09-20
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 999
Contact Name: ERTSDESK
DEC Memo: "09/20/07 - See eDocs for Con Ed report detailing cleanup and closure. 207704. see eDocs"
Remarks: "Fault Box VS6601.. 8 gallons of unk. oil on 1500 gallons of water. contained in manhole. Pending tests. 207704"

All Materials:

Site ID: 386318
Operable Unit ID: 1143559
Operable Unit: 01
Material ID: 2133834
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 8.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: VS 6601 HAS 50 GAL DIELECTRIC FLUID
Address: 3 AVENUE & 18 STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0706746 / 2007-11-08
Facility ID: 0706746
Facility Type: ER
DER Facility ID: 335700
Site ID: 387320
DEC Region: 2

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VS 6601 HAS 50 GAL DIELECTRIC FLUID (Continued)

S108764618

Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2007-09-18
Investigator: gdbreen
Referred To: Not reported
Reported to Dept: 2007-09-18
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-09-18
Spill Record Last Update: 2007-11-08
Spiller Name: ERTSDESK
Spiller Company: CON EDISON
Spiller Address: 3RD & 18TH AVE
Spiller Company: 999
Contact Name: ERTSDESK
DEC Memo: "11/08/07 - See eDocs for Con Ed report detailing cleanup and closure. 208111. see eDocs"
Remarks: "ON 100 GALLONS OF WATER: IS CONTAINED AND NO TO 5 QUESTIONS. 208111"
All Materials:
Site ID: 387320
Operable Unit ID: 1144529
Operable Unit: 01
Material ID: 2134836
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Oxygenate: Not reported

**L67
ENE
< 1/8
0.117 mi.
618 ft.**

**ROADWAY
18TH ST AND 3RD AVE
BROOKLYN, NY
Site 3 of 13 in cluster L**

**NY Spills S110139391
N/A**

**Relative:
Higher
Actual:
15 ft.**

SPILLS:
Name: ROADWAY
Address: 18TH ST AND 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0910817 / 2010-01-06
Facility ID: 0910817
Facility Type: ER
DER Facility ID: 372479
Site ID: 423587

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ROADWAY (Continued)

S110139391

DEC Region: 2
Spill Cause: Traffic Accident
Spill Class: C4
SWIS: 2401
Spill Date: 2010-01-06
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2010-01-06
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-01-06
Spill Record Last Update: 2010-01-06
Spiller Name: Not reported
Spiller Company: HALLS FAST MOTOR FREIGHT
Spiller Address: Not reported
Spiller Company: 999
Contact Name: SCOTT SARNELL
DEC Memo: "roadway spill due to traffic accident,all cleaned up by FD.(sr)"
Remarks: "spill to paved area/clean up complete"

All Materials:

Site ID: 423587
Operable Unit ID: 1179398
Operable Unit: 01
Material ID: 2173066
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

**I68
NNW
< 1/8
0.117 mi.
619 ft.**

**HAMILTON AVENUE PIERS
18TH-19TH STREETS
BROOKLYN, NY 11232**

**SEMS-ARCHIVE 1003864411
NYD986914554**

Site 2 of 7 in cluster I

**Relative:
Lower
Actual:
1 ft.**

SEMS Archive:
Site ID: 0203383
EPA ID: NYD986914554
Name: HAMILTON AVENUE PIERS
Address: 18TH-19TH STREETS
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Cong District: 10
FIPS Code: 36047

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAMILTON AVENUE PIERS (Continued)

1003864411

FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region: 02
Site ID: 0203383
EPA ID: NYD986914554
Site Name: HAMILTON AVENUE PIERS
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1990-09-27 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 02
Site ID: 0203383
EPA ID: NYD986914554
Site Name: HAMILTON AVENUE PIERS
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: 1990-05-03 04:00:00
Finish Date: 1990-09-27 04:00:00
Qual: L
Current Action Lead: St Perf

Region: 02
Site ID: 0203383
EPA ID: NYD986914554
Site Name: HAMILTON AVENUE PIERS
NPL: N
FF: N
OU: 00
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: 1990-05-03 04:00:00
Finish Date: 1990-09-27 04:00:00
Qual: N
Current Action Lead: St Perf

Region: 02
Site ID: 0203383
EPA ID: NYD986914554
Site Name: HAMILTON AVENUE PIERS
NPL: N
FF: N
OU: 00
Action Code: DS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAMILTON AVENUE PIERS (Continued)

1003864411

Action Name: DISCVRY
SEQ: 1
Start Date: 1990-05-03 04:00:00
Finish Date: 1990-05-03 04:00:00
Qual: Not reported
Current Action Lead: St Perf

K69
South
< 1/8
0.121 mi.
638 ft.
3RD AVE AUTO REPAIR INC
703 3RD AVE
BROOKLYN, NY 11232
Site 2 of 6 in cluster K

NY AST **A100356926**
N/A

Relative:
Higher
Actual:
18 ft.

AST:
Name: 3RD AVE AUTO REPAIR INC
Address: 703 3RD AVE
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-611566
Program Type: PBS
UTM X: 584681.63793
UTM Y: 4501833.13668
Expiration Date: 01/21/2021
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 447663
Affiliation Type: Mail Contact
Company Name: 3RD AVE AUTO REPAIR INC
Contact Type: Not reported
Contact Name: ABDULLAH SALIM
Address1: 703 3RD AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 369-0555
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2016-06-06

Site Id: 447663
Affiliation Type: Facility Operator
Company Name: 3RD AVE AUTO REPAIR INC
Contact Type: Not reported
Contact Name: ABDULLAH SALIM
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 369-0555

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

3RD AVE AUTO REPAIR INC (Continued)

A100356926

EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2011-04-08

Site Id: 447663
Affiliation Type: Emergency Contact
Company Name: ABDULLAH SALIM
Contact Type: Not reported
Contact Name: IMAD BAKER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 622-2424
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2011-04-08

Site Id: 447663
Affiliation Type: Facility Owner
Company Name: 703 3RD AVE LLC
Contact Type: OWNER
Contact Name: ABDULLAH SALIM
Address1: 144 21 STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 369-3434
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2016-06-06

Tank Info:

Tank Number: 001
Tank Id: 238730
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I01 - Overfill - Float Vent Valve

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

3RD AVE AUTO REPAIR INC (Continued)

A100356926

K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/19/2011
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MRBARROW
Last Modified: 04/14/2017
Material Name: waste oil/used oil

K70
South
< 1/8
0.121 mi.
638 ft.

NYSDOT
703-709 THIRD AVE
BROOKLYN, NY 11232

NY MANIFEST **S119078388**
N/A

Site 3 of 6 in cluster K

Relative:
Higher
Actual:
18 ft.

NY MANIFEST:

Name: NYSDOT
Address: 703-709 THIRD AVE
City,State,Zip: BROOKLYN, NY 11232-0000
Country: USA
EPA ID: NYR000017087
Facility Status: Not reported
Location Address 1: HAMILTON AVE AND 16TH ST E
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYR000017087
Mailing Name: NYSDOT
Mailing Contact: SURIEL ZAYAS
Mailing Address 1: 47-40 21ST STREET
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7187686880

NY MANIFEST:

Document ID: NJA2781645
Manifest Status: C
seq: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT (Continued)

S119078388

Year: 1997
Trans1 State ID: S6993
Trans2 State ID: Not reported
Generator Ship Date: 12/05/1997
Trans1 Recv Date: 12/05/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 12/05/1997
Part A Recv Date: / /
Part B Recv Date: 12/24/1997
Generator EPA ID: NYR000017087
Trans1 EPA ID: NJD980772768
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 05500
Units: P - Pounds
Number of Containers: 011
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100

K71
South
< 1/8
0.121 mi.
638 ft.

NYSDOT
HAMILTON AVE & 16TH ST E WING
BROOKLYN, NY 11232
Site 4 of 6 in cluster K

RCRA NonGen / NLR 1001080001
NYR000017087

Relative:
Higher
Actual:
18 ft.

RCRA NonGen / NLR:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: NYSDOT
Facility address: HAMILTON AVE & 16TH ST E WING
BROOKLYN, NY 11232
EPA ID: NYR000017087
Mailing address: 21ST ST
LONG ISLAND CITY, NY 11101
Contact: SURIEL ZAYAS
Contact address: 21ST ST
LONG ISLAND CITY, NY 11101
Contact country: US

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT (Continued)

1001080001

Contact telephone: 718-768-6880
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NYSDOT
Owner/operator address: 47-40 21ST ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: 718-768-6880
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYSDOT
Owner/operator address: 47-40 21ST ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: 718-768-6880
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: NYSDOT
Classification: Not a generator, verified

Date form received by agency: 1998-08-27 00:00:00.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT (Continued)

1001080001

Site name: NYS DEPT OF TRANSPORTATION
Classification: Large Quantity Generator

Date form received by agency: 1995-12-04 00:00:00.0

Site name: NYSDOT
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

**L72
NE
1/8-1/4
0.126 mi.
664 ft.**

**NYSDOT D257588
3RD AVE & 18TH ST
BROOKLYN, NY 11232**

RCRA NonGen / NLR

**1001197390
NYR000039123**

Site 4 of 13 in cluster L

**Relative:
Higher**

RCRA NonGen / NLR:

**Actual:
11 ft.**

Date form received by agency: 2007-01-01 00:00:00.0

Facility name: NYSDOT D257588
Facility address: 3RD AVE & 18TH ST
UNDER GOWANUS EXPWY
BROOKLYN, NY 11232

EPA ID: NYR000039123
Mailing address: HAMILTON AVE
BROOKLYN, NY 11231

Contact: STAN MALEK
Contact address: HAMILTON AVE
BROOKLYN, NY 11231

Contact country: US
Contact telephone: 718-246-5854
Contact email: Not reported
EPA Region: 02

Land type: State
Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NYSDOT
Owner/operator address: 47-40 21ST ST
LONG ISLAND CITY, NY 11101

Owner/operator country: US
Owner/operator telephone: 718-482-4390
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYSDOT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT D257588 (Continued)

1001197390

Owner/operator address: 47-40 21ST ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: 718-482-4390
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: NYSDOT D257588
Classification: Not a generator, verified

Date form received by agency: 2001-01-01 00:00:00.0
Site name: NYS DEPT OF TRANSPORTATION; REGION 11
Classification: Large Quantity Generator

Date form received by agency: 1998-07-23 00:00:00.0
Site name: NYS DEPT OF TRANSPORTATION
Classification: Large Quantity Generator

Date form received by agency: 1998-06-10 00:00:00.0
Site name: NYSDOT D257588
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Facility Has Received Notices of Violations:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT D257588 (Continued)

1001197390

Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 1997-09-23 00:00:00.0
Date achieved compliance: 1997-10-24 00:00:00.0
Violation lead agency: EPA
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

**J73
South
1/8-1/4
0.126 mi.
664 ft.**

**NYCDEP
64 23RD AVE
BROOKLYN, NY 11010**

**NY MANIFEST 1009244323
N/A**

Site 3 of 6 in cluster J

**Relative:
Higher**

NY MANIFEST:

**Actual:
12 ft.**

Name: NYCDEP
Address: 64 23RD AVE
City,State,Zip: BROOKLYN, NY 11010
Country: USA
EPA ID: NYP010001717
Facility Status: Not reported
Location Address 1: 64 23RD AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11010
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP010001717
Mailing Name: NYCDEP
Mailing Contact: KIM HANNA
Mailing Address 1: 59-17 JUNCTION BLVD
Mailing Address 2: Not reported
Mailing City: FRANKLIN SQUARE
Mailing State: NY
Mailing Zip: 11010
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7185954656

NY MANIFEST:

Document ID: NYB7837686
Manifest Status: C
seq: Not reported
Year: 1996
Trans1 State ID: PD4340NY
Trans2 State ID: Not reported
Generator Ship Date: 01/19/1996
Trans1 Recv Date: 01/19/1996
Trans2 Recv Date: / /

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCDEP (Continued)

1009244323

TSD Site Recv Date: 01/19/1996
Part A Recv Date: 03/25/1996
Part B Recv Date: 02/01/1996
Generator EPA ID: NYP010001717
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported
TSD ID 1: NYD049178296
TSD ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00160
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00900
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00040
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

H74
SE
1/8-1/4
0.127 mi.
668 ft.
CON EDISON
146 20 ST
BROOKLYN, NY 11232
Site 8 of 9 in cluster H

NY MANIFEST **S117315267**
N/A

Relative:
Higher

NY MANIFEST:

Actual:
24 ft.

Name: CON EDISON
Address: 146 20 ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004624169
Facility Status: Not reported
Location Address 1: 146 20 ST
Code: BP
Location Address 2: SB 46709
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004624169
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/11/2014
Trans1 Recv Date: 08/11/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/13/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004624169
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002616217GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117315267

Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

L75
East
1/8-1/4
0.128 mi.
676 ft.

NYSDOT
3RD AVE & 19TH ST
BROOKLYN, NY 11227

RCRA NonGen / NLR

1000191447
NYD986899722

Site 5 of 13 in cluster L

Relative:
Higher
Actual:
18 ft.

RCRA NonGen / NLR:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: NYSDOT
Facility address: 3RD AVE & 19TH ST
BROOKLYN, NY 11227
EPA ID: NYD986899722
Mailing address: HUNTERS POINT PLZ 47-40 21ST
LONG ISLAND CITY, NY 11101
Contact: SURIEL ZAYAS
Contact address: HUNTERS POINT PLZ 47-40 21ST
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: 718-492-9610
Contact email: Not reported
EPA Region: 02
Land type: State
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYSDOT
Owner/operator address: 1 HUNTERS POINT PLZ
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: 718-492-9610

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT (Continued)

1000191447

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYSDOT
Owner/operator address: 1 HUNTERS POINT PLZ
LONG ISLAND CITY, NY 11101

Owner/operator country: US
Owner/operator telephone: 718-492-9610
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: NYSDOT
Classification: Not a generator, verified

Date form received by agency: 1994-02-16 00:00:00.0
Site name: NYSDOT FIELD OFF
Classification: Large Quantity Generator

Date form received by agency: 1993-08-23 00:00:00.0
Site name: NYSDOT
Classification: Not a generator, verified

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT (Continued)

1000191447

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

**K76
SSE
1/8-1/4
0.130 mi.
685 ft.**

**SASUN JEWELRY INC
134 22ND ST
BROOKLYN, NY 11232

Site 5 of 6 in cluster K**

**RCRA NonGen / NLR
FINDS
ECHO**

**1004760334
NYR000040857**

**Relative:
Higher**

RCRA NonGen / NLR:

**Actual:
20 ft.**

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: SASUN JEWELRY INC
Facility address: 134 22ND ST
BROOKLYN, NY 11232
EPA ID: NYR000040857
Mailing address: 22ND ST
BROOKLYN, NY 11232
Contact: ROBERT MOORE
Contact address: 22ND ST
BROOKLYN, NY 11232
Contact country: US
Contact telephone: 718-832-7400
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: SASUN JEWELRY INC
Owner/operator address: 134 22ND ST
BROOKLYN, NY 11232
Owner/operator country: US
Owner/operator telephone: 718-832-7400
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: SASUN JEWELRY INC
Owner/operator address: 134 22ND ST
BROOKLYN, NY 11232
Owner/operator country: US
Owner/operator telephone: 718-832-7400
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SASUN JEWELRY INC (Continued)

1004760334

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: SASUN JEWELRY INC
Classification: Not a generator, verified

Date form received by agency: 1997-06-09 00:00:00.0
Site name: SASUN JEWELRY INC
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D006
. Waste name: CADMIUM

Violation Status: No violations found

FINDS:

Registry ID: 110004535094
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004535094

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1004760334
Registry ID: 110004535094
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004535094>
Name: SASUN JEWELRY INC
Address: 134 22ND ST
City,State,Zip: BROOKLYN, NY 11232

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

K77
SSE
1/8-1/4
0.130 mi.
685 ft.
CON EDISON
134 22 ST
BROOKLYN, NY 11201
Site 6 of 6 in cluster K

NY MANIFEST **S117315175**
N/A

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:
Name: CON EDISON
Address: 134 22 ST
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004623039
Facility Status: Not reported
Location Address 1: 134 22 ST
Code: BP
Location Address 2: SB46845
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004623039
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/08/2014
Trans1 Recv Date: 08/08/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/15/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004623039
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002616094GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117315175

Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 75
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

L78
East
1/8-1/4
0.131 mi.
693 ft.

CON EDISON
637 3RD AVE
BROOKLYN, NY 11235

Site 6 of 13 in cluster L

NY MANIFEST S117741469
N/A

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:
Name: CON EDISON
Address: 637 3RD AVE
City,State,Zip: BROOKLYN, NY 11235
Country: USA
EPA ID: NYP004746996
Facility Status: Not reported
Location Address 1: 637 3RD AVE
Code: BP
Location Address 2: SB 55767
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004746996
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117741469

Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2015
Trans1 Recv Date: 03/09/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004746996
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002618983GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

L79
East
1/8-1/4
0.131 mi.
693 ft.

CON EDISON
637 3RD AVE
BROOKLYN, NY 11235

Site 7 of 13 in cluster L

RCRA NonGen / NLR
FINDS
ECHO

1018279848
NYP004746996

Relative:
Higher

RCRA NonGen / NLR:

Actual:
18 ft.

Date form received by agency: 2015-03-09 00:00:00.0
Facility name: CON EDISON
Facility address: 637 3RD AVE
BROOKLYN, NY 11235
EPA ID: NYP004746996
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2015-03-09 00:00:00.0
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067697433
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110067697433

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1018279848

corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1018279848
Registry ID: 110067697433
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110067697433>
Name: CON EDISON
Address: 637 3RD AVE
City,State,Zip: BROOKLYN, NY 11235

L80
East
1/8-1/4
0.131 mi.
693 ft.

CON EDISON
637 3RD AVE
BROOKLYN, NY 11235

Site 8 of 13 in cluster L

NJ MANIFEST **S120668636**
N/A

Relative:
Higher

Actual:
18 ft.

NJ MANIFEST:
EPA Id: NYP004746996
Mail Address: IRVING PL, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:

Manifest Number: 002618983GBF
EPA ID: NYP004746996
Date Shipped: 3/9/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S120668636

Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

J81
South
1/8-1/4
0.132 mi.
699 ft.

CON EDISON
3RD AVE & 23RD ST
BROOKLYN, NY 11204
Site 4 of 6 in cluster J

RCRA NonGen / NLR 1014397452
NY MANIFEST NYP004197745

Relative:
Higher
Actual:
15 ft.

RCRA NonGen / NLR:
Date form received by agency: 2016-06-01 00:00:00.0
Facility name: CON EDISON
Facility address: 3RD AVE & 23RD ST
BROOKLYN, NY 11204
EPA ID: NYP004197745
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: MICHAEL BETO
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 917-337-5519
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1014397452

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2009-10-08 00:00:00.0
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Name: CONSOLIDATED EDISON
Address: 3RD AVE & 23RD ST
City,State,Zip: BROOKLYN, NY 11204
Country: USA
EPA ID: NYP004197745
Facility Status: Not reported
Location Address 1: 3RD AVE & 23RD ST
Code: BP
Location Address 2: MH# 67889
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004197745
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/09/2009
Trans1 Recv Date: 10/09/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/13/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004197745
Trans1 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1014397452

Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: 001440950FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100.0
Units: K - Kilograms (2.2 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Waste Code: D008
Waste Code 1_2: D007
Waste Code 1_3: D006
Waste Code 1_4: B007
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

J82
SSW
1/8-1/4
0.133 mi.
704 ft.

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS
730 3RD AVENUE
BROOKLYN, NY 12201

NY SHWS S110751210
NY Spills N/A

Site 5 of 6 in cluster J

Relative:
Lower

Actual:
6 ft.

SHWS:

Name: FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS
Address: 730 3RD AVENUE
City,State,Zip: BROOKLYN, NY 12201
Program: HW
Site Code: 439096
Classification: N
Region: 2
Acres: 18.539999999999999
HW Code: 224143
Record Add: 08/24/2010
Record Upd: 11/12/2010
Updated By: MOBARRIE
Site Description: The Site is located in the Gowanus section of Brooklyn in a zoned manufacturing area. The site was formerly used by Moore McCormack Lines, a steamship company (dates of occupancy unknown). Subsequently, Continental Terminals used the pier shed to store and

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued)

S110751210

distribute cocoa beans into the late 1990s. The shed was removed and the pier was then used by American Warehousing for vehicle storage. The Site also contains a garage that was used for vehicle maintenance. The Site was recently paved. The northern portion of the Site is used for storage of sea containers by the New York City Police Department, and a small electric power generating station operated by the New York Power Authority occupies the south part of the Site. Immediately northwest of the Site is Upper New York Bay/Gowanus Canal, immediately northeast is industrial/manufacturing, and immediately southeast are commercial and office buildings. The Site is approximately 98,010 square feet (2.2 acres) in size and is occupied by the NY Power Authority as well as the storage area for sea containers for NYPD. The nearest residential units are 0.12 miles (approx. 650 feet) to the east-southeast. There are no records of Petroleum Bulk Storage or Chemical Bulk Storage on the site. The site did not qualify for addition to the Registry of Inactive Hazardous Waste Disposal Sites.

Env Problem:

Based upon investigations conducted to date, the primary contaminants of concern at the site include mercury, lead and copper. In July 2009, following discovery of petroleum contaminated soil during excavation to support repairs to the Site's bulkhead, three test pits were excavated to determine the extent of the petroleum impacts. A total of seven sidewall soil samples and one grab groundwater sample were collected from the test pits. One sample was also collected for waste classification from the stockpiled soil excavated from the initial excavation and the test pits. Sidewall samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, PCBs, pesticides and Total Petroleum Hydrocarbons. The composite waste classification sample was analyzed for TCLP parameters as well. The following contaminants with maximum concentrations were observed in soil: 17 ppm mercury; 1,100 ppm lead; and 330 ppm copper. The Part 375 Industrial Use Soil Cleanup Objectives (SCOs) have been exceeded for mercury, and the Part 375 Commercial Use SCOs have been exceeded for lead and copper. Groundwater samples were all below applicable Groundwater Standards for VOCs and SVOCs, but were not analyzed for metals. Depth to groundwater is approximately 9-15' below grade and is likely influenced by tidal action due to the immediately adjacent Gowanus Bay. Site characterization is required to evaluate the presence or absence of hazardous waste on the site, and to collect data sufficient to determine if the site poses a significant threat to public health or the environment. The site did not qualify for addition to the Registry of Inactive Hazardous Waste Disposal Sites.

Health Problem:

Not reported

Dump:

Not reported

Structure:

Not reported

Lagoon:

Not reported

Landfill:

Not reported

Pond:

Not reported

Disp Start:

Not reported

Disp Term:

Not reported

Lat/Long:

Not reported

Dell:

Not reported

Record Add:

Not reported

Record Upd:

Not reported

Updated By:

Not reported

Own Op:

Owner

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued)

S110751210

Sub Type: NNN
Owner Name: Attn: Kay Zias
Owner Company: NYC Economic Development Corp.
Owner Address: 110 William Street, 16th Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10038-3940
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

SPILLS:

Name: NY POWER AUTHORITY
Address: 730 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1011757 / 2011-02-25
Facility ID: 1011757
Facility Type: ER
DER Facility ID: 398537
Site ID: 445647
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2011-02-24
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2011-02-25
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-02-25
Spill Record Last Update: 2011-02-25
Spiller Name: Not reported
Spiller Company: NY POWER AUTHORITY
Spiller Address: Not reported
Spiller Company: 999
Contact Name: JOSH RAMOS
DEC Memo: "Forwarded to DEC Air Unit"
Remarks: "0903 THE CALLER ADVISED DISPATCH THE SPILL WAS DUE TO AN ERROR INLET HEATER. THE AIR WAS IMPACTED. CLEAN UP NOT NECESSARY. NO CALL BACK IS NEEDED BY SPILLS REPRESENTATIVE."

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued)

S110751210

All Materials:

Site ID: 445647
Operable Unit ID: 1196029
Operable Unit: 01
Material ID: 2192217
Material Code: 0243A
Material Name: nitrogen dioxide
Case No.: 10544726
Material FA: Hazardous Material
Quantity: .10
Units: G
Recovered: Not reported
Oxygenate: Not reported

Name: NY POWER AUTHORITY/ GOWNAS POWER PLANT
Address: 730 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1010032 / 2010-12-29
Facility ID: 1010032
Facility Type: ER
DER Facility ID: 398537
Site ID: 443615
DEC Region: 2
Spill Cause: Human Error
Spill Class: C4
SWIS: 2401
Spill Date: 2010-12-20
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2010-12-21
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-12-21
Spill Record Last Update: 2010-12-29
Spiller Name: JOSH RAMOS
Spiller Company: NY POWER AUTHORITY/ GOWNAS POWER PLANT
Spiller Address: 730 3RD AVE
Spiller Company: 999
Contact Name: JOSH RAMOS
DEC Memo: ""
Remarks: "exceeded emissions, operator error- corrected"

All Materials:

Site ID: 443615
Operable Unit ID: 1194068
Operable Unit: 01
Material ID: 2189706
Material Code: 0025A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued)

S110751210

Material Name: ammonia
Case No.: 07664417
Material FA: Hazardous Material
Quantity: .05
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name: NY POWER AUTHORITY POWER PLANT
Address: 730 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1010412 / 2011-01-06
Facility ID: 1010412
Facility Type: ER
DER Facility ID: 398537
Site ID: 444015
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2011-01-05
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2011-01-06
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-01-06
Spill Record Last Update: 2011-01-06
Spiller Name: JOSH RAMOS
Spiller Company: NY POWER AUTHORITY
Spiller Address: 730 3RD AVE
Spiller Company: 999
Contact Name: JOSH RAMOS
DEC Memo: "minor issue."
Remarks: "equip failaure, immediate correction."

All Materials:

Site ID: 444015
Operable Unit ID: 1194460
Operable Unit: 01
Material ID: 2190286
Material Code: 0243A
Material Name: nitrogen dioxide
Case No.: 10544726
Material FA: Hazardous Material
Quantity: 3.80
Units: G
Recovered: Not reported
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued)

S110751210

Name: NYPA
Address: 730 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1010704 / 2011-01-21
Facility ID: 1010704
Facility Type: ER
DER Facility ID: 398537
Site ID: 444318
DEC Region: 2
Spill Cause: Other
Spill Class: D5
SWIS: 2401
Spill Date: 2011-01-14
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2011-01-18
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-01-18
Spill Record Last Update: 2011-01-21
Spiller Name: JOSHUA RAMAS
Spiller Company: NYPA
Spiller Address: 730 3RD AVE
Spiller Company: 999
Contact Name: JOSHUA RAMAS
DEC Memo: ""
Remarks: "Caller reporting a release"

All Materials:

Site ID: 444318
Operable Unit ID: 1194763
Operable Unit: 01
Material ID: 2190629
Material Code: 0283A
Material Name: carbon monoxide
Case No.: 00630080
Material FA: Other
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Site ID: 444318
Operable Unit ID: 1194763
Operable Unit: 01
Material ID: 2190630
Material Code: 0025A
Material Name: ammonia
Case No.: 07664417
Material FA: Hazardous Material

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued)

S110751210

Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name: AIR
Address: 730 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1101207 / 2011-05-03
Facility ID: 1101207
Facility Type: ER
DER Facility ID: 398537
Site ID: 448654
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: D5
SWIS: 2401
Spill Date: 2011-05-02
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2011-05-03
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-05-03
Spill Record Last Update: 2011-05-03
Spiller Name: JOSHUA
Spiller Company: NY POWER AUTHORITY
Spiller Address: 730 3RD AVE
Spiller Company: 999
Contact Name: JOSHUA
DEC Memo: "NOx exceedance - copy forwarded to DEC Air Group"
Remarks: ""

All Materials:
Site ID: 448654
Operable Unit ID: 1198884
Operable Unit: 01
Material ID: 2195216
Material Code: 0243A
Material Name: nitrogen dioxide
Case No.: 10544726
Material FA: Hazardous Material
Quantity: .10
Units: L
Recovered: Not reported
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

J83
SSW
1/8-1/4
0.133 mi.
704 ft.

NEW YORK POWER AUTHORITY-SEYMOUR
730 3RD AVE AND 23RD ST
BROOKLYN, NY 11232
Site 6 of 6 in cluster J

NY CBS
NY CBS AST
NY TANKS
NY Spills

S105052646
N/A

Relative:
Lower

CBS:

Actual:
6 ft.

Name: NEW YORK POWER AUTHORITY-SEYMOUR
Address: 730 3RD AVE AND 23RD ST
City,State,Zip: BROOKLYN, NY 11232
CBS Number: 2-000378
Program Type: CBS
Facility Status: Active
Expiration Date: 04/18/2021
Dec Region: 2
UTMX: 584575.85260
UTMY: 4501786.89565

CBS AST:

CBS Number: 2-000378
ICS Number: Not reported
PBS Number: Not reported
MOSF Number: Not reported
SPDES Number: Not reported
Facility Status: IN SERVICE
Facility Type: I
Telephone: (718) 626-8258
Facility Town: NEW YORK CITY
Region: STATE
Expiration Date: 04/18/2003
Total Capacity of All Active Tanks(gal): 10000
Operator: CONECTIV THERMAL SYSTEMS
Emergency Contact: DON SYTKOWSKI
Emergency Phone: (718) 626-8258
Owner Name: NEW YORK POWER AUTHORITY
Owner Address: 123 MAIN ST.
Owner City,St,Zip: WHITE PLAINS, NY 10601
Owner Telephone: (914) 681-6200
Owner Type: State Government
Owner Sub Type: NYS Power Authority
Mail Name: NEW YORK POWER AUTHORITY
Mail Contact Addr: 123 MAIN ST
Mail Contact Addr2: Not reported
Mail Contact Contact: NICHOLAS RELLEA
Mail Contact City,St,Zip: WHITE PLAINS, NY 10601
Mail Phone: (914) 681-6408

Tank Id: 001
CAS Number: 1336216
Federal ID: Not reported
Tank Status: In Service
Install Date: 05/01
Tank Closed: Not reported
Capacity (Gal): 10000
Chemical: Ammonium hydroxide
Tank Location: Indoors, Aboveground
Tank Type: Steel/carbon steel
Total Tanks: 1
Tank Secret: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK POWER AUTHORITY-SEYMOUR (Continued)

S105052646

Tank Secondary Containment: 01
Tank Error Status: No Missing Data
Date Entered: 04/18/2001
Certified Date: 04/18/2001
Substance: Single Hazardous Substance on DEC List
Internal Protection: Other
External Protection: None,Other
Pipe Location: Aboveground/Underground Combination
Pipe Type: Wrapped Steel
Pipe Internal: Other
Pipe External: 09
Pipe Flag: 09
Leak Detection: 16
Overfill Protection: 02
Haz Percent: 19
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6101
Lat/Long: Not reported
Is Updated: False
Renew Date: Not reported
Is It There: False
Delinquent: False
Date Expired: Not reported
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: False
Pre-Printed Renewal App Last Printed: / /

TANKS:

Name: NEW YORK POWER AUTHORITY
Address: NORTHWEST CORNER OF 3RD AVE & 24TH ST.
City,State,Zip: BROOKLYN, NY 11232
Facility Id: 2-610581
Region: STATE
DEC Region: 2
Site Status: Active
Program Type: PBS
Expiration Date: 05/01/2021
UTM X: 584587.61415
UTM Y: 4501737.17003

SPILLS:

Name: POWER PLANT SITE - JOSEPH J SEAMER
Address: 730 3RD AVE 23RD ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1205025 / 2012-08-27
Facility ID: 1205025
Facility Type: ER
DER Facility ID: 422235
Site ID: 467937
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK POWER AUTHORITY-SEYMOUR (Continued)

S105052646

Spill Date: 2012-08-17
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2012-08-17
CID: Not reported
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-08-17
Spill Record Last Update: 2012-08-27
Spiller Name: WALTER SOLO
Spiller Company: POWER PLANT
Spiller Address: 730 3RD AVE 23RD ST
Spiller Company: 999
Contact Name: WALTER SOLO
DEC Memo: " Loss was of Freon. Forwarded copy to NYSDEC Air Unit. "
Remarks: "leak was stopped - when discovered"

All Materials:

Site ID: 467937
Operable Unit ID: 1217875
Operable Unit: 01
Material ID: 2216220
Material Code: 0050A
Material Name: freon
Case No.: Not reported
Material FA: Other
Quantity: 300.00
Units: L
Recovered: Not reported
Oxygenate: Not reported

Name: GOWANUS GAS TURBINES
Address: 730 3RD AVE/23RD
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1215226 / 2013-02-01
Facility ID: 1215226
Facility Type: ER
DER Facility ID: 433783
Site ID: 478513
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2013-01-31
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 2013-02-01
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK POWER AUTHORITY-SEYMOUR (Continued)

S105052646

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-02-01
Spill Record Last Update: 2013-02-01
Spiller Name: Not reported
Spiller Company: NY POWER AUTHORITY
Spiller Address: Not reported
Spiller Company: 999
Contact Name: WALTER SOTO
DEC Memo: "referred to DEC Lieblich."
Remarks: "Communication equipment failure, led to release of about one pound released."

All Materials:
Site ID: 478513
Operable Unit ID: 1228285
Operable Unit: 01
Material ID: 2225863
Material Code: 0243A
Material Name: nitrogen dioxide
Case No.: 10544726
Material FA: Hazardous Material
Quantity: 1.00
Units: L
Recovered: Not reported
Oxygenate: Not reported

H84
ESE
1/8-1/4
0.137 mi.
722 ft.
I & J FINISHING CORP
149 20TH ST
BROOKLYN, NY 11232
Site 9 of 9 in cluster H

RCRA-VSQG
FINDS
ECHO
NY MANIFEST
1000141937
NYD098843089

Relative:
Higher
Actual:
26 ft.

RCRA-VSQG:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: I & J FINISHING CORP
Facility address: 149 20TH ST
BROOKLYN, NY 11232-1110
EPA ID: NYD098843089
Mailing address: 20TH ST
BROOKLYN, NY 11232-1110
Contact: BENJAMIN BENIAKEN
Contact address: 20TH ST
BROOKLYN, NY 11232-1110
Contact country: US
Contact telephone: 718-438-5100
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time;

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I & J FINISHING CORP (Continued)

1000141937

or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2000-02-02 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. Importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I & J FINISHING CORP (Continued)

1000141937

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: I & J FINISHING CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 2005-03-30 00:00:00.0
Site name: I & J FINISHING CORP
Classification: Small Quantity Generator

Date form received by agency: 1999-07-14 00:00:00.0
Site name: DYNA COTE IND INC
Classification: Small Quantity Generator

Date form received by agency: 1985-08-05 00:00:00.0
Site name: DYNA COTE IND INC
Classification: Large Quantity Generator

Hazardous Waste Summary:

- . Waste code: D040
- . Waste name: TRICHLOROETHYLENE

- . Waste code: F001
- . Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F002
- . Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: U228
- . Waste name: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1988-05-10 00:00:00.0
Date achieved compliance: 1988-06-23 00:00:00.0
Violation lead agency: State
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: 1988-06-08 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I & J FINISHING CORP (Continued)

1000141937

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 1988-05-10 00:00:00.0
Evaluation: WRITTEN INFORMAL
Area of violation: Generators - General
Date achieved compliance: 1988-06-23 00:00:00.0
Evaluation lead agency: State

FINDS:

Registry ID: 110001573609
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110001573609

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000141937
Registry ID: 110001573609
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110001573609>
Name: I & J FINISHING CORP
Address: 149 20TH STREET
City,State,Zip: BROOKLYN, NY 11232

NY MANIFEST:

Name: I AND J FINISHING
Address: 149 20TH ST
City,State,Zip: BROOKLYN, NY 11232-1110
Country: USA
EPA ID: NYD098843089
Facility Status: Not reported
Location Address 1: 149 20TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD098843089
Mailing Name: I AND J FINISHING

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I & J FINISHING CORP (Continued)

1000141937

Mailing Contact: RICHARD SIRIANO
Mailing Address 1: 149 20TH STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11232
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7184990291

NY MANIFEST:

Document ID: NYG3988431
Manifest Status: Not reported
seq: Not reported
Year: 2005
Trans1 State ID: NY0000182675
Trans2 State ID: Not reported
Generator Ship Date: 04/07/2005
Trans1 Recv Date: 04/07/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD098843089
Trans1 EPA ID: NY68492JR
Trans2 EPA ID: Not reported
TSDF ID 1: NYD082785429
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: U228 - TRICHLOROETHENE
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 01600
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.20

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

	Site	Database(s)	EPA ID Number
I85 NW 1/8-1/4 0.145 mi. 763 ft.	NORTHROP/US CUSTOMS GANNON TRUCKING CO 18 20TH ST BROOKLYN, NY 11230 Site 3 of 7 in cluster I	NY MANIFEST	1009232731 N/A

Relative:	NY MANIFEST:	
Lower	Name:	NORTHROP/US CUSTOMS GANNON TRUCKING CO
	Address:	18 20TH ST
Actual:	City,State,Zip:	BROOKLYN, NY 11230
1 ft.	Country:	USA
	EPA ID:	NYP000891168
	Facility Status:	Not reported
	Location Address 1:	18 20TH ST
	Code:	BP
	Location Address 2:	Not reported
	Total Tanks:	Not reported
	Location City:	BROOKLYN
	Location State:	NY
	Location Zip:	11230
	Location Zip 4:	Not reported

NY MANIFEST:	
EPAID:	NYP000891168
Mailing Name:	NORTHROP/US CUSTOMS GANNON TRUCKING CO
Mailing Contact:	NORTHROP/US CUSTOMS GANNON TRUCKING CO
Mailing Address 1:	111 WEST SIDE AVENUE
Mailing Address 2:	Not reported
Mailing City:	JERSEY CITY
Mailing State:	NJ
Mailing Zip:	07305
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2014353851

NY MANIFEST:	
Document ID:	NJA0653288
Manifest Status:	C
seq:	Not reported
Year:	1989
Trans1 State ID:	NJDEPS-58
Trans2 State ID:	Not reported
Generator Ship Date:	07/27/1989
Trans1 Recv Date:	07/27/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/27/1989
Part A Recv Date:	08/07/1989
Part B Recv Date:	08/04/1989
Generator EPA ID:	NYP000891168
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSD ID 1:	NJD002200046
TSD ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NORTHROP/US CUSTOMS GANNON TRUCKING CO (Continued)

1009232731

Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00198
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100

M86
NE
1/8-1/4
0.145 mi.
765 ft.
CON EDISON
24-17 64 ST
BROOKLYN, NY 11385
Site 1 of 5 in cluster M

NY MANIFEST **S117061844**
N/A

Relative:
Higher
Actual:
12 ft.

NY MANIFEST:
Name: CON EDISON
Address: 24-17 64 ST
City,State,Zip: BROOKLYN, NY 11385
Country: USA
EPA ID: NYP004541662
Facility Status: Not reported
Location Address 1: 24-17 64 ST
Code: BP
Location Address 2: STRUCTURE 52153
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11385
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004541662
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117061844

seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 05/23/2014
Trans1 Recv Date: 05/23/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/02/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004541662
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID 1: NJD991291105
TSD ID 2: Not reported
Manifest Tracking Number: 002423626GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

N87
SE
1/8-1/4
0.145 mi.
767 ft.

STEPHEN IMPORTS INC.
150 20TH STREET
BROOKLYN, NY 11232
Site 1 of 6 in cluster N

NY AST A100300718
N/A

Relative:
Higher
Actual:
28 ft.

AST:
Name: STEPHEN IMPORTS INC.
Address: 150 20TH STREET
City,State,Zip: BROOKLYN, NY 11232
Region: STATE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STEPHEN IMPORTS INC. (Continued)

A100300718

DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-283584
Program Type: PBS
UTM X: 584903.51727
UTM Y: 4501885.01961
Expiration Date: N/A
Site Type: Other Wholesale/Retail Sales

Affiliation Records:

Site Id: 12527
Affiliation Type: Facility Owner
Company Name: BRAN JANG KU
Contact Type: Not reported
Contact Name: Not reported
Address1: 2474 18TH AVENUE
Address2: Not reported
City: SAN FRANCISCO
State: CA
Zip Code: 94116
Country Code: 001
Phone: (415) 777-9996
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 12527
Affiliation Type: Mail Contact
Company Name: STEPHEN IMPORTS, INC.
Contact Type: Not reported
Contact Name: BRAN JANG KU
Address1: 2474 18TH AVENUE
Address2: Not reported
City: SAN FRANCISCO
State: CA
Zip Code: 94116
Country Code: 001
Phone: (415) 777-9996
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 12527
Affiliation Type: Facility Operator
Company Name: STEPHEN IMPORTS INC.
Contact Type: Not reported
Contact Name: BENJAMIN KU
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-1324
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STEPHEN IMPORTS INC. (Continued)

A100300718

Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 12527
Affiliation Type: Emergency Contact
Company Name: BRAN JANG KU
Contact Type: Not reported
Contact Name: BENJAMIN KU
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (415) 777-9996
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 14913
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/10/2003
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I88
NW
1/8-1/4
0.146 mi.
771 ft.
FEDERAL EXPRESS - FBTA
51 20TH STREET
BROOKLYN, NY 11232
Site 4 of 7 in cluster I

NY AST **A100321712**
N/A

Relative:
Lower

AST:

Actual:
1 ft.

Name: FEDERAL EXPRESS - FBTA
Address: 51 20TH STREET
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-610915
Program Type: PBS
UTM X: 584592.02246
UTM Y: 4502157.85996
Expiration Date: 08/21/2023
Site Type: Other

Affiliation Records:

Site Id: 403042
Affiliation Type: Facility Owner
Company Name: SUNSET INDUSTRIAL PARK ASSOC.
Contact Type: PROJ. ENG. SPECIALIST
Contact Name: JOE PIERONI
Address1: 51 20TH ST.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 965-6000
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-06-19

Site Id: 403042
Affiliation Type: Mail Contact
Company Name: FEDERAL EXPRESS
Contact Type: Not reported
Contact Name: JOE PIERONI
Address1: 3620 HACKS CROSS ROAD
Address2: BLDG. B - 3RD FLOOR
City: MEMPHIS
State: TN
Zip Code: 38125
Country Code: 001
Phone: (314) 768-6418
EMail: JMPIERONI@FEDEX.COM
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-06-19

Site Id: 403042
Affiliation Type: Facility Operator
Company Name: FEDERAL EXPRESS - FBTA
Contact Type: Not reported
Contact Name: JOSEPH LAROSA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS - FBTA (Continued)

A100321712

Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-6826
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-06-19

Site Id: 403042
Affiliation Type: Emergency Contact
Company Name: SUNSET INDUSTRIAL PARK ASSOC.
Contact Type: Not reported
Contact Name: JOE PIERONI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (314) 768-6418
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-06-19

Tank Info:

Tank Number: 001
Tank Id: 224813
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G12 - Tank Secondary Containment - Double-Walled (AG only)

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/1999
Capacity Gallons: 250

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS - FBTA (Continued)

A100321712

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 002
Tank Id: 276249

Equipment Records:

E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

G12 - Tank Secondary Containment - Double-Walled (AG only)
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/1999
Capacity Gallons: 250
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DAFRANCI
Last Modified: 06/19/2018
Material Name: motor oil

Tank Number: 003
Tank Id: 276250

Equipment Records:

E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS - FBTA (Continued)

A100321712

Tank Location:	G12 - Tank Secondary Containment - Double-Walled (AG only) Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1999
Capacity Gallons:	85
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	06/19/2018
Material Name:	transmission fluid
Tank Number:	004
Tank Id:	276251
Equipment Records:	E00 - Piping Secondary Containment - None B00 - Tank External Protection - None C00 - Pipe Location - No Piping F00 - Pipe External Protection - None H02 - Tank Leak Detection - Interstitial - Manual Monitoring A00 - Tank Internal Protection - None K00 - Spill Prevention - None D00 - Pipe Type - No Piping L00 - Piping Leak Detection - None I04 - Overfill - Product Level Gauge (A/G) J00 - Dispenser - None G12 - Tank Secondary Containment - Double-Walled (AG only) Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Location:	G12 - Tank Secondary Containment - Double-Walled (AG only) Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1999
Capacity Gallons:	85
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	06/19/2018
Material Name:	waste oil/used oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

189
NW
1/8-1/4
0.146 mi.
771 ft.

FEDERAL EXPRESS CORP
51 20TH ST
BROOKLYN, NY 11232

RCRA NonGen / NLR **1000446357**
RI MANIFEST **NYD986904803**

Site 5 of 7 in cluster I

Relative:
Lower

RCRA NonGen / NLR:

Actual:
1 ft.

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: FEDERAL EXPRESS CORP
Facility address: 51 20TH ST
BROOKLYN, NY 11232-1109
EPA ID: NYD986904803
Mailing address: 20TH ST
BROOKLYN, NY 11215
Contact: Not reported
Contact address: 20TH ST
BROOKLYN, NY 11215
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: FEDERAL EXPRESS CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: FEDERAL EXPRESS CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORP (Continued)

1000446357

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: FEDERAL EXPRESS CORP
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: FEDERAL EXPRESS CORP
Classification: Not a generator, verified

Date form received by agency: 1990-06-21 00:00:00.0
Site name: FEDERAL EXPRESS CORP
Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001
Waste name: IGNITABLE WASTE

Violation Status: No violations found

RI MANIFEST:

EPA Id: NYD986904803
GEN Cert Date: 7/17/2003
Manifest Document Number: RIS0076689
Waste Description: OILY SOLIDS/ DEBRIS/ SLUDGE
TSDF Id: rid040098352
TSDF Name: Northland Environmental Inc.
Qty: 700
WT/Vol Units: LBS
TSDF Date: Not reported
Transporter 2 Id: Not reported
Item Number: 13434
Transporter 2 Name: Not reported
Transporter Name 2: Consolidated Recycling Technologies
Transporter EPAID: n/a
Transporter Receipt Date: 7/17/2003
Number Of Containers: Not reported
Container Type: Not reported
Waste Code1: NONE
Waste Code2: Not reported
Waste Code3: Not reported
Waste Code4: Not reported
Waste Code5: Not reported
Waste Code6: Not reported
Fee Exempt Code: Not reported
Comment: Not reported
Transporter Name 2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORP (Continued)

1000446357

Company Permit Number: Not reported
Year: Not reported
Quarter: Not reported
Transporter Contact Name: Not reported
Transporter Contact Email: Not reported
Filing Date: Not reported
Total Fee: Not reported
Billing Name: Not reported
Paid Date: Not reported
Paid Time: Not reported
Facility Receipt Date: Not reported
Fee: Not reported
Manifest Created Date: Not reported
Manifest Updated Date: Not reported

RI MANIFEST:

Transporter Receipt Date: 7/17/2003
Number Of Containers: Not reported
Container Type: Not reported
Waste Code1: NONE
Waste Code2: Not reported
Waste Code3: Not reported
Waste Code4: Not reported
Waste Code5: Not reported
Waste Code6: Not reported
Comment: Not reported
Fee Exempt Code: Not reported
TSDF Name: Northland Environmental Inc.
TSDF Id: rid040098352
Transporter Name 2: Not reported
Company Permit Number: Not reported
Year: Not reported
EPA ID: NYD986904803
Manifest Docket Number: RIS0076689
Quarter: Not reported
Waste Description: OILY SOLIDS/ DEBRIS/ SLUDGE
Transporter Contact Name: Not reported
Quantity: 700
Transporter Contact Email: Not reported
WT/Vol Units: LBS
Filing Date: Not reported
Total Fee: Not reported
Item Number: 13434
Transporter Name: Consolidated Recycling Technologies
Billing Name: Not reported
Transporter EPA ID: n/a
Date Paid: Not reported
Time Paid: Not reported
GEN Cert Date: 7/17/2003
Facility Receipt Date: Not reported
Fee: Not reported
Transporter 2 Receipt Date: Not reported
Manifest Created Date: Not reported
TSDF Receipt Date: Not reported
Transporter 2 ID: Not reported
Manifest Updated Date: Not reported

Transporter Receipt Date: 7/17/2003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORP (Continued)

1000446357

Number Of Containers: Not reported
Container Type: Not reported
Waste Code1: NONE
Waste Code2: Not reported
Waste Code3: Not reported
Waste Code4: Not reported
Waste Code5: Not reported
Waste Code6: Not reported
Comment: Not reported
Fee Exempt Code: Not reported
TSDf Name: Northland Environmental Inc.
TSDf Id: rid040098352
Transporter Name 2: Not reported
Company Permit Number: Not reported
Year: Not reported
EPA ID: NYD986904803
Manifest Docket Number: RIS0076689
Quarter: Not reported
Waste Description: OILY SOLIDS/ DEBRIS/ SLUDGE
Transporter Contact Name: Not reported
Quantity: 700
Transporter Contact Email: Not reported
WT/Vol Units: LBS
Filing Date: Not reported
Total Fee: Not reported
Item Number: 13434
Transporter Name: Consolidated Recycling Technologies
Billing Name: Not reported
Transporter EPA ID: n/a
Date Paid: Not reported
Time Paid: Not reported
GEN Cert Date: 7/17/2003
Facility Receipt Date: Not reported
Fee: Not reported
Transporter 2 Receipt Date: Not reported
Manifest Created Date: Not reported
TSDf Receipt Date: Not reported
Transporter 2 ID: Not reported
Manifest Updated Date: Not reported

M90
NE
1/8-1/4
0.147 mi.
778 ft.

CON EDISON - SERVICE BOX 55777
HAMILTON AVE & 17 ST
BROOKLYN, NY 11232
Site 2 of 5 in cluster M

RCRA-LQG **1018278595**
NYP004733747

Relative:
Higher
Actual:
11 ft.

RCRA-LQG:
Date form received by agency: 2016-02-05 00:00:00.0
Facility name: CON EDISON - SERVICE BOX 55777
Facility address: HAMILTON AVE & 17 ST
BROOKLYN, NY 11232
EPA ID: NYP004733747
Mailing address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact: THERESA BURKARD
Contact address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - SERVICE BOX 55777 (Continued)

1018278595

Contact country: US
Contact telephone: 212-460-2262
Contact email: BURKARDT@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2015-02-18 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2015-02-18 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - SERVICE BOX 55777 (Continued)

1018278595

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2015-02-18 00:00:00.0
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 2015-02-18 00:00:00.0
Site name: CON EDISON
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code: D008
Waste name: LEAD
Amount (Lbs): 3000

Violation Status: No violations found

M91
NE
1/8-1/4
0.147 mi.
778 ft.

CON EDISON
HAMILTON AVE & 17TH ST
BROOKLYN, NY 11232

RCRA NonGen / NLR
NJ MANIFEST
NY MANIFEST

1014396776
NYP004190914

Site 3 of 5 in cluster M

Relative:
Higher

Actual:
11 ft.

RCRA NonGen / NLR:

Date form received by agency: 2016-06-01 00:00:00.0
Facility name: CON EDISON
Facility address: HAMILTON AVE & 17TH ST
BROOKLYN, NY 11232
EPA ID: NYP004190914
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: CAROLINE ISKANDER
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1014396776

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2009-08-13 00:00:00.0
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:

EPA Id: NYP004190914
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: CAROLINE ISKANDER
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:

Manifest Number: 000894575GBF
EPA ID: NYP004190914
Date Shipped: 08/28/2009
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 08/28/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1014396776

Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 08/31/2009
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:

Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 100 G

NY MANIFEST:

Name: CONSOLIDATED EDISON
Address: HAMILTON AVE & 17TH ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004190914
Facility Status: Not reported
Location Address 1: HAMILTON AVE & 17th ST - MH 74729
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004190914
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1014396776

Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/28/2009
Trans1 Recv Date: 08/28/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/31/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004190914
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 000894575GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

M92
NE
1/8-1/4
0.147 mi.
778 ft.
Site 4 of 5 in cluster M

NJ MANIFEST **S120667456**
N/A

Relative:
Higher

Actual:
11 ft.

NJ MANIFEST:
EPA Id: NYP004733747
Mail Address: IRVING PLACE, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THERESA BURKARD
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002621106GBF
EPA ID: NYP004733747
Date Shipped: 2/18/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - SERVICE BOX 55777 (Continued)

S120667456

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

L93
East
1/8-1/4
0.148 mi.
781 ft.

CON EDISON
123 18TH ST
BROOKLYN, NY 11215

RCRA NonGen / NLR

1019325657
NYP004845711

Site 9 of 13 in cluster L

Relative:
Higher
Actual:
19 ft.

RCRA NonGen / NLR:
Date form received by agency: 2016-02-05 00:00:00.0
Facility name: CON EDISON
Site name: CON EDISON - TRANSFORMER MANHOLE 256
Facility address: 123 18TH ST
BROOKLYN, NY 11215
EPA ID: NYP004845711
Mailing address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact: THERESA BURKARD
Contact address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-2262
Contact email: BURKARDT@CONED.COM
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2015-09-29 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1019325657

Owner/Op start date: 2015-09-29 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2015-09-29 00:00:00.0
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 2015-09-29 00:00:00.0
Site name: CON EDISON
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code: D008
Waste name: LEAD
Amount (Lbs): 10000

Violation Status: No violations found

L94
East
1/8-1/4
0.148 mi.
781 ft.

CON EDISON
123 18TH ST
BROOKLYN, NY 11215
Site 10 of 13 in cluster L

NY MANIFEST **S118463036**
N/A

Relative:
Higher
Actual:
19 ft.

NY MANIFEST:
Name: CON EDISON
Address: 123 18TH ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004845711

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S118463036

Facility Status: Not reported
Location Address 1: 123 18TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004845711
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 09/29/2015
Trans1 Recv Date: 09/29/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/30/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004845711
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014460463JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S118463036

Waste Code: Not reported
Waste Code: Not reported
Quantity: 10000
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

L95
East
1/8-1/4
0.148 mi.
781 ft.

CON EDISON
123 18TH ST
BROOKLYN, NY 11215
Site 11 of 13 in cluster L

NJ MANIFEST **S120677333**
N/A

Relative:
Higher

Actual:
19 ft.

NJ MANIFEST:
EPA Id: NYP004845711
Mail Address: IRVING PLACE, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THERESA BURKARD
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSD Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 014460463JJJK
EPA ID: NYP004845711
Date Shipped: 9/29/2015
TSD EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S120677333

Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

L96
ENE
1/8-1/4
0.150 mi.
790 ft.

LINSOM SERVICE CENTER, INC
629 3RD AVENUE
BROOKLYN, NY 11232

NY AST A100412089
N/A

Site 12 of 13 in cluster L

Relative:
Higher
Actual:
18 ft.

AST:
Name: LINSOM SERVICE CENTER, INC
Address: 629 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-157309
Program Type: PBS
UTM X: 586688.96632
UTM Y: 4502483.44740
Expiration Date: N/A
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 5200
Affiliation Type: Mail Contact
Company Name: 629 THIRD AVENUE LLC AND JOSEPH M. MATTONI, TIC
Contact Type: Not reported
Contact Name: KENNETH RAISCH
Address1: 1 EDGEWATER PLAZA
Address2: SUITE
City: STATEN ISLAND
State: NY
Zip Code: 10305
Country Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

A100412089

Phone: (718) 816-1131
EMail: KRAISCH@KIRLAW.COM
Fax Number: Not reported
Modified By: HDDUPIGN
Date Last Modified: 2015-08-04

Site Id: 5200
Affiliation Type: Facility Operator
Company Name: LINSOM SERVICE CENTER, INC
Contact Type: Not reported
Contact Name: SAM SOMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 768-5727
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-24

Site Id: 5200
Affiliation Type: Emergency Contact
Company Name: 629 THIRD AVENUE LLC AND JOSEPH M. MATTONE, TIC
Contact Type: Not reported
Contact Name: KENNETH RAISCH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 816-1131
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-24

Site Id: 5200
Affiliation Type: Facility Owner
Company Name: 629 THIRD AVENUE LLC AND JOSEPH M. MATTONE, TIC
Contact Type: Not reported
Contact Name: Not reported
Address1: 1 EDGEWATER PLAZA - SUITE 204
Address2: Not reported
City: STATEN ISLAND
State: NY
Zip Code: 10305
Country Code: 001
Phone: (718) 816-1131
EMail: Not reported
Fax Number: Not reported
Modified By: HDDUPIGN
Date Last Modified: 2015-08-07

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

A100412089

Tank Info:

Tank Number: 021
Tank Id: 50148
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
Aboveground - contact with impervious barrier... Tank bottom rests on
impervious barrier, allowing visual indication of leaks.

Tank Location:

Tank Type: Fiberglass Coated Steel
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1995
Capacity Gallons: 4000
Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/16/2015
Register: True
Modified By: HDDUPIGN
Last Modified: 04/14/2017
Material Name: gasoline

Tank Number: 022
Tank Id: 50149
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J00 - Dispenser - None
F02 - Pipe External Protection - Original Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
Aboveground - contact with impervious barrier... Tank bottom rests on
impervious barrier, allowing visual indication of leaks.

Tank Location:

Tank Type: Fiberglass Coated Steel
Tank Status: Closed - Removed
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

A100412089

Install Date: 10/01/1995
Capacity Gallons: 4000
Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/16/2015
Register: True
Modified By: HDDUPIGN
Last Modified: 04/14/2017
Material Name: gasoline

Tank Number: 023
Tank Id: 50150
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
Aboveground - contact with impervious barrier... Tank bottom rests on
impervious barrier, allowing visual indication of leaks.

Tank Location:

Tank Type: Fiberglass Coated Steel
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1995
Capacity Gallons: 4000
Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/16/2015
Register: True
Modified By: HDDUPIGN
Last Modified: 04/14/2017
Material Name: gasoline

Tank Number: 024
Tank Id: 50151
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

A100412089

Tank Location: D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
Aboveground - contact with impervious barrier... Tank bottom rests on
impervious barrier, allowing visual indication of leaks.
Tank Type: Fiberglass Coated Steel
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1995
Capacity Gallons: 4000
Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/16/2015
Register: True
Modified By: HDDUPIGN
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: 025
Tank Id: 255013

Equipment Records:

L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
C03 - Pipe Location - Aboveground/Underground Combination
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on
impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1995
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/16/2015
Register: True
Modified By: HDDUPIGN
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

L97
ENE
1/8-1/4
0.150 mi.
790 ft.
LINSOM SERVICE CENTER, INC
629 3RD AVENUE
BROOKLYN, NY 11232
Site 13 of 13 in cluster L

NY UST **U003297785**
N/A

Relative:
Higher

UST:

Actual:
18 ft.

Name: LINSOM SERVICE CENTER, INC
Address: 629 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11232
Id/Status: 2-157309 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 586688.96632
UTM Y: 4502483.44740
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 5200
Affiliation Type: Mail Contact
Company Name: 629 THIRD AVENUE LLC AND JOSEPH M. MATTONE, TIC
Contact Type: Not reported
Contact Name: KENNETH RAISCH
Address1: 1 EDGEWATER PLAZA
Address2: SUITE
City: STATEN ISLAND
State: NY
Zip Code: 10305
Country Code: 001
Phone: (718) 816-1131
EMail: KRAISCH@KIRLAW.COM
Fax Number: Not reported
Modified By: HDDUPIGN
Date Last Modified: 2015-08-04

Site Id: 5200
Affiliation Type: Facility Operator
Company Name: LINSOM SERVICE CENTER, INC
Contact Type: Not reported
Contact Name: SAM SOMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 768-5727
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-24

Site Id: 5200
Affiliation Type: Emergency Contact
Company Name: 629 THIRD AVENUE LLC AND JOSEPH M. MATTONE, TIC
Contact Type: Not reported
Contact Name: KENNETH RAISCH
Address1: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 816-1131
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-24

Site Id: 5200
Affiliation Type: Facility Owner
Company Name: 629 THIRD AVENUE LLC AND JOSEPH M. MATTONE, TIC
Contact Type: Not reported
Contact Name: Not reported
Address1: 1 EDGEWATER PLAZA - SUITE 204
Address2: Not reported
City: STATEN ISLAND
State: NY
Zip Code: 10305
Country Code: 001
Phone: (718) 816-1131
EMail: Not reported
Fax Number: Not reported
Modified By: HDDUPIGN
Date Last Modified: 2015-08-07

Tank Info:

Tank Number: 001
Tank ID: 29869
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 29870
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 29871
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004
Tank ID: 29872
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 29873
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 006
Tank ID: 29874
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 007
Tank ID: 29875
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 008
Tank ID: 29876
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 009
Tank ID: 29877
Tank Status: Closed - Removed

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 010
Tank ID: 29878
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

J02 - Dispenser - Suction Dispenser

Tank Number: 011
Tank ID: 29879
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 012
Tank ID: 29880
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 013
Tank ID: 29881
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 014
Tank ID: 29882
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 015
Tank ID: 29883
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 016
Tank ID: 29884
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 017
Tank ID: 29885
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 018
Tank ID: 29886
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 019
Tank ID: 29887
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINSOM SERVICE CENTER, INC (Continued)

U003297785

Tank Number: 020
Tank ID: 29888
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 10/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

O98
East
1/8-1/4
0.153 mi.
806 ft.
Relative:
Higher
Actual:
28 ft.

VELAZQUEZ AUTO REPAIR
134 18TH STREET
BROOKLYN, NY 11215
Site 1 of 3 in cluster O

NY AST **A100353070**
N/A

AST:
Name: VELAZQUEZ AUTO REPAIR
Address: 134 18TH STREET
City,State,Zip: BROOKLYN, NY 11215
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-611397
Program Type: PBS
UTM X: 584929.49682
UTM Y: 4502062.22420
Expiration Date: 07/28/2015
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 438104
Affiliation Type: Facility Owner
Company Name: CARLOS LOPEZ
Contact Type: Not reported
Contact Name: Not reported
Address1: 459 52ND ST
Address2: Not reported
City: BROOKLYN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VELAZQUEZ AUTO REPAIR (Continued)

A100353070

State: NY
Zip Code: 11220
Country Code: 001
Phone: (917) 501-7559
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-07-28

Site Id: 438104
Affiliation Type: Mail Contact
Company Name: VELAZQUEZ AUTO REPAIR
Contact Type: Not reported
Contact Name: CARLOS LOPEZ
Address1: 134 18TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11215
Country Code: 001
Phone: (917) 501-7559
EMail: LOPEZCATERPILAR@AOL.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-07-28

Site Id: 438104
Affiliation Type: Facility Operator
Company Name: VELAZQUEZ AUTO REPAIR
Contact Type: Not reported
Contact Name: MAX GOMEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 369-2992
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-07-28

Site Id: 438104
Affiliation Type: Emergency Contact
Company Name: CARLOS LOPEZ
Contact Type: Not reported
Contact Name: CARLOS LOPEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 501-7559
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VELAZQUEZ AUTO REPAIR (Continued)

A100353070

Modified By: NRLOMBAR
Date Last Modified: 2010-07-28

Tank Info:

Tank Number: 001
Tank Id: 235363
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
B99 - Tank External Protection - Other
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.

Tank Type: Steel Tank in Concrete
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/10/2005
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: waste oil/used oil

**I99
NW
1/8-1/4
0.155 mi.
817 ft.**

**CONSOLIDATED EDISON
20 ST C32W 4TH AVE 20 ST C32W
BROOKLYN, NY 10003
Site 6 of 7 in cluster I**

**NY MANIFEST S117564157
N/A**

**Relative:
Lower
Actual:
1 ft.**

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 20 ST C32W 4TH AVE 20 ST C32W
City,State,Zip: BROOKLYN, NY 10003
Country: USA
EPA ID: NYP004091849
Facility Status: Not reported
Location Address 1: 20 ST & 4 AVE TM263
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROKLYN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S117564157

Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004091849
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:

Document ID: NYE0623196
Manifest Status: Not reported
seq: 01
Year: 2001
Trans1 State ID: 20856AD
Trans2 State ID: Not reported
Generator Ship Date: 11/12/2001
Trans1 Recv Date: 11/12/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/12/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004091849
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 02164
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S117564157

Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

**I100
NW
1/8-1/4
0.155 mi.
817 ft.**

**CON EDISION - TRF 263
20 ST C32W 4TH AVE 20 ST C32W
BROOKLYN, NY 10003**

RCRA NonGen / NLR

**1007208526
NYP004091849**

Site 7 of 7 in cluster I

**Relative:
Lower**

RCRA NonGen / NLR:

**Actual:
1 ft.**

Date form received by agency: 2002-06-02 00:00:00.0
Facility name: CON EDISION - TRF 263
Facility address: 20 ST C32W 4TH AVE 20 ST C32W
BROOKLYN, NY 10003
EPA ID: NYP004091849
Mailing address: IRVING PLACE
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS
Contact address: IRVING PLACE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2002-06-01 00:00:00.0
Site name: CON EDISION - TRF 263
Classification: Not a generator, verified

Date form received by agency: 2002-05-31 00:00:00.0
Site name: CON EDISION - TRF 263
Classification: Large Quantity Generator

Violation Status: No violations found

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

M101
NE
1/8-1/4
0.162 mi.
855 ft.

CON EDISON
HAMILTON AVE & 17TH ST SB63665
BROOKLYN, NY 11232

NY MANIFEST

S117740214
N/A

Site 5 of 5 in cluster M

Relative:
Higher

NY MANIFEST:

Actual:
9 ft.

Name: CON EDISON
Address: HAMILTON AVE & 17TH ST SB63665
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004733739
Facility Status: Not reported
Location Address 1: 570 HAMILTON AVE
Code: BP
Location Address 2: SB 63665
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004733739
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 02/18/2015
Trans1 Recv Date: 02/18/2015
Trans2 Recv Date: 02/23/2015
TSD Site Recv Date: 02/23/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004733739
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002620734GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117740214

Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 400
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

N102
SE
1/8-1/4
0.164 mi.
867 ft.
CON EDISON
162 20 ST
BROOKLYN, NY 11232
Site 2 of 6 in cluster N

NY MANIFEST **S117315266**
N/A

Relative:
Higher
Actual:
32 ft.

NY MANIFEST:
Name: CON EDISON
Address: 162 20 ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004624151
Facility Status: Not reported
Location Address 1: 162 20 ST
Code: BP
Location Address 2: SB 46710
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004624151
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117315266

Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/11/2014
Trans1 Recv Date: 08/11/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/13/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004624151
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002616218GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 75
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

P103
SSE
1/8-1/4
0.169 mi.
891 ft.

CON EDISON
151 23 ST
BROOKLYN, NY 11232

Site 1 of 8 in cluster P

NY MANIFEST **S117315899**
N/A

Relative:
Higher

Actual:
24 ft.

NY MANIFEST:
Name: CON EDISON
Address: 151 23 ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004631081
Facility Status: Not reported
Location Address 1: 151 23 ST
Code: BP
Location Address 2: SB 46893
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004631081
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/18/2014
Trans1 Recv Date: 08/18/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004631081
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002616220GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117315899

Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Q104
ENE
1/8-1/4
0.172 mi.
909 ft.

CON EDISON
134 17TH ST
BROOKLYN, NY 11217
Site 1 of 2 in cluster Q

NJ MANIFEST S120666095
N/A

Relative:
Higher
Actual:
21 ft.

NJ MANIFEST:
EPA Id: NYP004444014
Mail Address: IRVING PL, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported
Manifest:
Manifest Number: 002621676GBF
EPA ID: NYP004444014
Date Shipped: 12/29/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S120666095

Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Q105
ENE
1/8-1/4
0.172 mi.
909 ft.

CON EDISON
134 17TH ST
BROOKLYN, NY 11217

RCRA NonGen / NLR 1016970681
NY MANIFEST NYP004444014

Site 2 of 2 in cluster Q

Relative:
Higher

RCRA NonGen / NLR:

Actual:
21 ft.

Date form received by agency: 2015-12-29 00:00:00.0
Facility name: CON EDISON
Facility address: 134 17TH ST
BROOKLYN, NY 11217
EPA ID: NYP004444014
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1016970681

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2015-12-29 00:00:00.0
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 2014-03-17 00:00:00.0
Site name: CON EDISON SERVICE BOX: 46281
Classification: Not a generator, verified

Violation Status: No violations found

NY MANIFEST:

Name: CON EDISON
Address: 134 17TH ST
City,State,Zip: BROOKLYN, NY 11217
Country: USA
EPA ID: NYP004444014
Facility Status: Not reported
Location Address 1: 134 17TH ST
Code: BP
Location Address 2: SB46281
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004444014
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1016970681

Mailing Phone: Not reported

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/18/2014
Trans1 Recv Date: 02/18/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/19/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004444014
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011697923JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

P106
South
1/8-1/4
0.173 mi.
913 ft.
Site 2 of 8 in cluster P

NY MANIFEST **1009234256**
N/A

Relative:
Higher

Actual:
21 ft.

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: V4652 134 E 23RD ST
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP000927418
Facility Status: Not reported
Location Address 1: V4652 134 E 23RD ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000927418
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYB7187229
Manifest Status: C
seq: Not reported
Year: 1996
Trans1 State ID: NYSM1708
Trans2 State ID: Not reported
Generator Ship Date: 08/15/1996
Trans1 Recv Date: 08/15/1996
Trans2 Recv Date: / /
TSD Site Recv Date: 08/16/1996
Part A Recv Date: 08/30/1996
Part B Recv Date: 08/29/1996
Generator EPA ID: NYP000927418
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

1009234256

Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00509
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100

N107
ESE
1/8-1/4
0.173 mi.
916 ft.

COLONIAL MIRROR & GLASS
163 20TH ST
BROOKLYN, NY 11232
Site 3 of 6 in cluster N

RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

1000872564
NYD987037785

Relative:
Higher
Actual:
33 ft.

RCRA NonGen / NLR:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: COLONIAL MIRROR & GLASS
Facility address: 163 20TH ST
BROOKLYN, NY 11232-1110
EPA ID: NYD987037785
Mailing address: KENT AVE
BROOKLYN, NY 11211
Contact: Not reported
Contact address: KENT AVE
BROOKLYN, NY 11211
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: COLONIAL MIRROR & GLASS
Owner/operator address: 35 KENT AVE
BROOKLYN, NY 11211
Owner/operator country: US
Owner/operator telephone: 718-388-7667
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COLONIAL MIRROR & GLASS (Continued)

1000872564

Owner/operator name: COLONIAL MIRROR & GLASS
Owner/operator address: 35 KENT AVE
BROOKLYN, NY 11211
Owner/operator country: US
Owner/operator telephone: 718-388-7667
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: COLONIAL MIRROR & GLASS
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: COLONIAL MIRROR & GLASS
Classification: Not a generator, verified

Date form received by agency: 1993-07-21 00:00:00.0
Site name: COLONIAL MIRROR & GLASS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COLONIAL MIRROR & GLASS (Continued)

1000872564

ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004506865
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004506865

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000872564
Registry ID: 110004506865
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004506865>
Name: COLONIAL MIRROR & GLASS
Address: 163 20TH ST
City,State,Zip: BROOKLYN, NY 11232

NY MANIFEST:

Name: COLONIAL MIRROR & GLASS
Address: 163 20TH ST
City,State,Zip: BROOKLYN, NY 11232-1110
Country: USA
EPA ID: NYD987037785
Facility Status: Not reported
Location Address 1: 163 20TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COLONIAL MIRROR & GLASS (Continued)

1000872564

Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD987037785
Mailing Name: COLONIAL MIRROR & GLASS
Mailing Contact: ANGELO VARRIANO
Mailing Address 1: 163 20TH ST
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11232
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7183887667

NY MANIFEST:

Document ID: NJA1736770
Manifest Status: C
seq: Not reported
Year: 1993
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 10/13/1993
Trans1 Recv Date: 10/13/1993
Trans2 Recv Date: / /
TSD Site Recv Date: 10/14/1993
Part A Recv Date: / /
Part B Recv Date: 10/28/1993
Generator EPA ID: NYD987037785
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002182897
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F003 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00576
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COLONIAL MIRROR & GLASS (Continued)

1000872564

Specific Gravity: 100

O108
East
1/8-1/4
0.173 mi.
916 ft.

ADELE ROOTSTEIN USA INC
145 18TH ST
BROOKLYN, NY 11215

Site 2 of 3 in cluster O

RCRA NonGen / NLR
US AIRS
FINDS
ECHO
NY MANIFEST

1000552283
NYD986946796

Relative:
Higher

Actual:
31 ft.

RCRA NonGen / NLR:
Date form received by agency: 2017-12-13 00:00:00.0
Facility name: ADELE ROOTSTEIN USA INC
Facility address: 145 18TH ST
BROOKLYN, NY 11215-5313
EPA ID: NYD986946796
Mailing address: 18TH ST
BROOKLYN, NY 11215
Contact: RON RAUGEL
Contact address: 18TH ST
BROOKLYN, NY 11215
Contact country: US
Contact telephone: 917-860-0731
Contact email: RON@ROOTSTEIN.COM
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: ADELE ROOTSTEIN
Owner/operator address: 205 W 19TH ST
NEW YORK, NY 10011
Owner/operator country: US
Owner/operator telephone: 212-645-2020
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ADELE ROOTSTEIN
Owner/operator address: 205 W 19TH ST
NEW YORK, NY 10011
Owner/operator country: Not reported
Owner/operator telephone: 212-645-2020
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ADELE ROOTSTEIN
Owner/operator address: 205 W 19TH ST
NEW YORK, NY 10011

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ADELE ROOTSTEIN USA INC (Continued)

1000552283

Owner/operator country: US
Owner/operator telephone: 212-645-2020
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ADELE ROOTSTEIN
Owner/operator address: 205 W 19TH ST
NEW YORK, NY 10011

Owner/operator country: Not reported
Owner/operator telephone: 212-645-2020
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2007-01-01 00:00:00.0
Site name: ADELE ROOTSTEIN USA INC
Classification: Not a generator, verified

Date form received by agency: 2006-01-01 00:00:00.0
Site name: ADELE ROOTSTEIN USA INC
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: ADELE ROOTSTEIN USA INC
Classification: Not a generator, verified

Date form received by agency: 1992-04-22 00:00:00.0
Site name: ADEL ROOTSTEIN
Classification: Large Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ADELE ROOTSTEIN USA INC (Continued)

1000552283

Date form received by agency: 1991-04-03 00:00:00.0
Site name: ADELE ROOTSTEIN USA INC
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING:
TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE,
1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED
FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING
CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF
ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED
IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE
SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

US AIRS MINOR:

Envid: 1000552283
Region Code: 02
Programmatic ID: AIR NY0000002610300136
Facility Registry ID: 110004463866
D and B Number: Not reported
Primary SIC Code: 3999
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:

Region Code: 02
Programmatic ID: AIR NY0000002610300136
Facility Registry ID: 110004463866
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-11-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:

Registry ID: 110004463866
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004463866

Environmental Interest/Information System:

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ADELE ROOTSTEIN USA INC (Continued)

1000552283

to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000552283
Registry ID: 110004463866
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004463866>
Name: ADEL ROOTSTEIN USA INC
Address: 145 18TH ST
City,State,Zip: BROOKLYN, NY 11215

NY MANIFEST:

Name: ADEL ROOTSTEIN
Address: 145 18TH ST
City,State,Zip: BROOKLYN, NY 11215-5313
Country: USA
EPA ID: NYD986946796
Facility Status: Not reported
Location Address 1: 145 18TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD986946796
Mailing Name: ADEL ROOTSTEIN
Mailing Contact: JOSPEH GARCIA JR.
Mailing Address 1: 145 18TH STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11215
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7184995650

NY MANIFEST:

Document ID: NJA1678456

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ADELE ROOTSTEIN USA INC (Continued)

1000552283

Manifest Status: C
seq: Not reported
Year: 1993
Trans1 State ID: NJS6348
Trans2 State ID: Not reported
Generator Ship Date: 05/11/1993
Trans1 Recv Date: 05/11/1993
Trans2 Recv Date: / /
TSD Site Recv Date: 05/11/1993
Part A Recv Date: 05/24/1993
Part B Recv Date: 05/26/1993
Generator EPA ID: NYD986946796
Trans1 EPA ID: NJD047318043
Trans2 EPA ID: Not reported
TSDF ID 1: NJD047318043
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F001 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00175
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100

N109
SE
1/8-1/4
0.174 mi.
920 ft.
HK AUTO REPAIR INC.
163 21ST STREET
BROOKLYN, NY 11232
Site 4 of 6 in cluster N

NY AST **A100350446**
N/A

Relative:
Higher

AST:

Actual:
33 ft.

Name: HK AUTO REPAIR INC.
Address: 163 21ST STREET
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-611323
Program Type: PBS
UTM X: 584863.03685

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HK AUTO REPAIR INC. (Continued)

A100350446

UTM Y: 4501839.49771
Expiration Date: 04/23/2015
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 433599
Affiliation Type: Facility Owner
Company Name: HK AUTO REPAIR INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 163 21ST STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 788-2279
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-04-23

Site Id: 433599
Affiliation Type: Mail Contact
Company Name: HK AUTO REPAIR INC.
Contact Type: Not reported
Contact Name: CHI YEE CHENG
Address1: 163 21ST STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 788-2279
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-04-23

Site Id: 433599
Affiliation Type: Facility Operator
Company Name: HK AUTO REPAIR INC.
Contact Type: Not reported
Contact Name: CHI YEE CHENG
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 788-2279
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-04-23

Site Id: 433599
Affiliation Type: Emergency Contact

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HK AUTO REPAIR INC. (Continued)

A100350446

Company Name: HK AUTO REPAIR INC.
Contact Type: Not reported
Contact Name: CHI YEE CHENG
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 788-2279
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-04-23

Tank Info:

Tank Number: 001
Tank Id: 233991
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

Tank Type: Steel/Carbon Steel/Iron

Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/01/2001
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

Database(s)

R110
NE
1/8-1/4
0.175 mi.
922 ft.
JETRO CASH & CARRY
566 HAMILTON AVENUE
BROOKLYN, NY 11232
Site 1 of 3 in cluster R

NY UST **U001841328**
N/A

Relative:
Higher

Actual:
8 ft.

UST:

Name: JETRO CASH & CARRY
Address: 566 HAMILTON AVENUE
City,State,Zip: BROOKLYN, NY 11232
Id/Status: 2-600166 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 584682.28832
UTM Y: 4502341.81219
Site Type: Other Wholesale/Retail Sales

Affiliation Records:

Site Id: 22151
Affiliation Type: Facility Owner
Company Name: JETRO MANAGEMENT & DEVELOPMENT CORP
Contact Type: PRES
Contact Name: JETHRO-RICHARD KIRSCHNER
Address1: 15-24 132ND STREET
Address2: Not reported
City: FLUSHING
State: NY
Zip Code: 11356
Country Code: 001
Phone: (718) 559-4203
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-04-12

Site Id: 22151
Affiliation Type: Mail Contact
Company Name: JETRO CASH & CARRY
Contact Type: Not reported
Contact Name: RICHARD KIRSHNER
Address1: 15-24 132ND STREET
Address2: Not reported
City: FLUSHING
State: NY
Zip Code: 11356
Country Code: 001
Phone: (718) 559-4203
EMail: RKIRSCHNER@JETROD.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-04-12

Site Id: 22151
Affiliation Type: Facility Operator
Company Name: JETRO CASH & CARRY
Contact Type: Not reported
Contact Name: BILL METZGER (MGR)
Address1: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

JETRO CASH & CARRY (Continued)

U001841328

Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 768-05555
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-04-12

Site Id: 22151
Affiliation Type: Emergency Contact
Company Name: JETRO MANAGEMENT & DEVELOPMENT CORP
Contact Type: Not reported
Contact Name: BILL METZGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 768-05555
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-04-12

Tank Info:

Tank Number: #1
Tank ID: 41393
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

JETRO CASH & CARRY (Continued)

U001841328

G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: #2
Tank ID: 41394
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: #3
Tank ID: 41395
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: 01/30/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

JETRO CASH & CARRY (Continued)

U001841328

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 004
Tank ID: 236444
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1080
Install Date: Not reported
Date Tank Closed: 08/27/2010
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination

Tank Number: 005
Tank ID: 236445
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1080
Install Date: Not reported
Date Tank Closed: 08/27/2010
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

JETRO CASH & CARRY (Continued)

U001841328

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination

S111
SSE
1/8-1/4
0.175 mi.
922 ft.

B B R CONTRACTING CORP
163 22ND ST
BROOKLYN, NY 11232

Site 1 of 3 in cluster S

RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

1001233292
NYR000064733

Relative:
Higher

Actual:
29 ft.

RCRA NonGen / NLR:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: B B R CONTRACTING CORP
Facility address: 163 22ND ST
BROOKLYN, NY 11232
EPA ID: NYR000064733
Mailing address: 22ND ST
BROOKLYN, NY 11232
Contact: EVAN ARDAVANIS
Contact address: 22ND ST
BROOKLYN, NY 11232
Contact country: US
Contact telephone: 718-788-5447
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: ARDAVANIS REALITY CORP
Owner/operator address: 526 OVHNGTON AVE
BROOKLYN, NY 11209
Owner/operator country: US
Owner/operator telephone: 917-731-3879
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ARDAVANIS REALITY CORP

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

B B R CONTRACTING CORP (Continued)

1001233292

Owner/operator address: 526 OVHNGTON AVE
BROOKLYN, NY 11209
Owner/operator country: US
Owner/operator telephone: 917-731-3879
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: B B R CONTRACTING CORP
Classification: Not a generator, verified

Date form received by agency: 1998-12-16 00:00:00.0
Site name: B B R CONTRACTING CORP
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING:
TETRACHLOROETHYLENE, TRICHTHLORETHYLENE, METHYLENE CHLORIDE,
1,1,1-TRICHTHLORETHANE, CARBON TETRACHLORIDE AND CHLORINATED
FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING
CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF
ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED
IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE
SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

B B R CONTRACTING CORP (Continued)

1001233292

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004549640
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004549640

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1001233292
Registry ID: 110004549640
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004549640>
Name: B B R CONTRACTING CORP
Address: 163 22ND ST
City,State,Zip: BROOKLYN, NY 11232

NY MANIFEST:

Name: BBR CONTRACTING CORP
Address: 163 22ND ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYR000064733
Facility Status: Not reported
Location Address 1: 163 22ND ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: 1105

NY MANIFEST:

EPAID: NYR000064733
Mailing Name: BBR CONTRACTING CORP
Mailing Contact: N/S
Mailing Address 1: 163 22ND ST
Mailing Address 2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

B B R CONTRACTING CORP (Continued)

1001233292

Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11232
Mailing Zip 4: 1105
Mailing Country: USA
Mailing Phone: 7182743339

NY MANIFEST:

Document ID: NYG1058481
Manifest Status: Not reported
seq: 01
Year: 1998
Trans1 State ID: PD1011NY
Trans2 State ID: Not reported
Generator Ship Date: 12/19/1998
Trans1 Recv Date: 12/19/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/21/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000064733
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F001 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 07600
Units: P - Pounds
Number of Containers: 019
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

P112 **CON EDISON - SERVICE BOX 46896**
South **144 23 ST**
1/8-1/4 **BROOKLYN, NY 11232**
0.184 mi.
970 ft. **Site 3 of 8 in cluster P**

RCRA-LQG **1016967061**
NY MANIFEST **NYP004399861**

Relative:
Higher

Actual:
23 ft.

RCRA-LQG:
Date form received by agency: 2014-03-27 00:00:00.0
Facility name: CON EDISON - SERVICE BOX 46896
Facility address: 144 23 ST
BROOKLYN, NY 11232
EPA ID: NYP004399861
Mailing address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact: DENNIS HUACON
Contact address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-2757
Contact email: HUACOND@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2013-12-04 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - SERVICE BOX 46896 (Continued)

1016967061

Owner/Op start date: 2013-12-04 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:

Name: CON EDISON
Address: 144 23 ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004399861
Facility Status: Not reported
Location Address 1: 144-23RD ST
Code: BP
Location Address 2: SB46896
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004399861
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - SERVICE BOX 46896 (Continued)

1016967061

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	11/04/2013
Trans1 Recv Date:	11/04/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/05/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004399861
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID 1:	NJD991291105
TSD ID 2:	Not reported
Manifest Tracking Number:	002299917GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

T113
SSW
1/8-1/4
0.184 mi.
971 ft.
MOORE MCCORMACK BUILDING
740 3RD AVE
BROOKLYN, NY 11232
Site 1 of 7 in cluster T

RCRA-SQG
1010329102
NYR000147249

Relative:
Higher

Actual:
13 ft.

RCRA-SQG:

Date form received by agency: 2007-05-29 00:00:00.0
Facility name: MOORE MCCORMACK BUILDING
Facility address: 740 3RD AVE
BROOKLYN, NY 11232
EPA ID: NYR000147249
Mailing address: WILLIAM ST 3RD FLOOR
NYC ECONOMIC DEVELOPMENT CORP
NEW YORK, NY 10038
Contact: KAY ZIAS
Contact address: WILLIAM ST 3RD FLOOR NYC ECONOMIC DEVELOPMENT CORP
NEW YORK, NY 10038
Contact country: US
Contact telephone: 212-312-3752
Contact email: KZIAS@NYCEDC.COM
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: CITY OF NEW YORK
Owner/operator address: WILLIAM ST
NEW YORK, NY 10017
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 1972-10-01 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: NYC ECONOMIC DEVELOP CORP
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 1991-04-01 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOORE MCCORMACK BUILDING (Continued)

1010329102

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2007-05-28 00:00:00.0
Site name: MOORE MCCORMACK BUILDING
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

Violation Status: No violations found

P114
SSE
1/8-1/4
0.184 mi.
972 ft.

SPILL NUMBER 0300252
160 22ND ST
BROOKLYN, NY
Site 4 of 8 in cluster P

NY LTANKS **S105998627**
N/A

Relative:
Higher

Actual:
29 ft.

LTANKS:
Name: SPILL NUMBER 0300252
Address: 160 22ND ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0300252 / 2003-04-08
Facility ID: 0300252
Site ID: 295284
Spill Date: 2003-04-07
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 2003-04-07
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0300252 (Continued)

S105998627

UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-04-07
Spill Record Last Update: 2003-04-08
Spiller Name: KENNY
Spiller Company: EMPIRE STATE FUEL
Spiller Address: 1640 MACDONALD AVE
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 238947
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD Called Rene Lewis from A.S. Eastman, who confirmed that spill was cleaned-up by them. Clean-up require the use of 3 bags of absorbent which was taken away for disposal. manifest Faxed. No soil was impacted. The NYC-DEP was informed about the sewer which was impacted. They responded. Called Kenny from Empire State Fuel, who confirmed that clean-up is completed. Discussed with Jake, who visited this site on OFF-HOURS, and he recommends closure. E.R."
Remarks: "caller reports tank failed and spilled to concrete. some entered drain area. tank being emptied. "

All Materials:
Site ID: 295284
Operable Unit ID: 868556
Operable Unit: 01
Material ID: 508338
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Oxygenate: Not reported

O115
East
1/8-1/4
0.185 mi.
978 ft.
GLADYS PEREZ
144 17TH STREET
BROOKLYN, NY 11215
Site 3 of 3 in cluster O

NY AST **A100354100**
N/A

Relative:
Higher
Actual:
30 ft.

AST:
Name: GLADYS PEREZ
Address: 144 17TH STREET
City,State,Zip: BROOKLYN, NY 11215
Region: STATE
DEC Region: 2
Site Status: Inactive
Facility Id: 2-611458
Program Type: PBS
UTM X: 584975.08775
UTM Y: 4502126.77986
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GLADYS PEREZ (Continued)

A100354100

Affiliation Records:

Site Id:	441803
Affiliation Type:	Facility Owner
Company Name:	GLADYS PEREZ
Contact Type:	AGENT
Contact Name:	PAUL MARTINEZ
Address1:	87-14 116TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	11418
Country Code:	001
Phone:	(718) 463-1200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2010-11-08
Site Id:	441803
Affiliation Type:	Mail Contact
Company Name:	WAVECREST MANAGEMENT TEAM
Contact Type:	Not reported
Contact Name:	PAUL MARTINEZ
Address1:	87-14 116TH STREET
Address2:	Not reported
City:	RICHMOND HILL
State:	NY
Zip Code:	11418
Country Code:	001
Phone:	(718) 463-1200
EMail:	PMARTINEZ@TWM.T.NET
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-05
Site Id:	441803
Affiliation Type:	Facility Operator
Company Name:	GLADYS PEREZ
Contact Type:	Not reported
Contact Name:	FRANCISCO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 445-7191
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2010-11-08
Site Id:	441803
Affiliation Type:	Emergency Contact
Company Name:	GLADYS PEREZ
Contact Type:	Not reported
Contact Name:	LETICIA PEREZ

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GLADYS PEREZ (Continued)

A100354100

Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 262-3669
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2010-11-08

Tank Info:

Tank Number: 001
Tank Id: 236726
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G03 - Tank Secondary Containment - Vault (w/o access)
E09 - Piping Secondary Containment - Modified Double-Walled
(Aboveground)
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 02/14/1977
Capacity Gallons: 1080
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BVCAMPBE
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

N116
SE
1/8-1/4
0.187 mi.
985 ft.

CON EDISON SERVICE BOX: 68241
678 4TH AVE
BROOKLYN, NY 11220

RCRA NonGen / NLR
NY MANIFEST

1016960705
NYP004328316

Relative:
Higher

RCRA NonGen / NLR:

Actual:
37 ft.

Date form received by agency: 2013-08-12 00:00:00.0
Facility name: CON EDISON SERVICE BOX: 68241
Facility address: 678 4TH AVE
BROOKLYN, NY 11220
EPA ID: NYP004328316
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: ANTHONY SIGNORE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2013-07-12 00:00:00.0
Site name: CON EDISON SERVICE BOX: 68241
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Name: CON EDISON
Address: 678 4TH AVE
City,State,Zip: BROOKLYN, NY 11220
Country: USA
EPA ID: NYP004328316
Facility Status: Not reported
Location Address 1: 678 4 AVE
Code: BP
Location Address 2: SB #68241
Total Tanks: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 68241 (Continued)

1016960705

Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004328316
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/12/2013
Trans1 Recv Date: 07/12/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/16/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004328316
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002084675GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 60
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 68241 (Continued)

1016960705

Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

**N117
ESE
1/8-1/4
0.188 mi.
995 ft.**

**CON EDISON SERVICE BOX: 72515
668 4TH AVE
BROOKLYN, NY 11220**

**RCRA NonGen / NLR 1016960706
NY MANIFEST NYP004328324**

Site 6 of 6 in cluster N

**Relative:
Higher
Actual:
37 ft.**

RCRA NonGen / NLR:
Date form received by agency: 2013-08-12 00:00:00.0
Facility name: CON EDISON SERVICE BOX: 72515
Facility address: 668 4TH AVE
BROOKLYN, NY 11220
EPA ID: NYP004328324
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: ANTHONY SIGNORE
Contact address: Not reported
Contact country: Not reported
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2013-07-12 00:00:00.0
Site name: CON EDISON SERVICE BOX: 72515
Classification: Conditionally Exempt Small Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 72515 (Continued)

1016960706

Violation Status: No violations found

NY MANIFEST:

Name: CON EDISON
Address: 668 4TH AVE
City,State,Zip: BROOKLYN, NY 11220
Country: USA
EPA ID: NYP004328324
Facility Status: Not reported
Location Address 1: 668 4 AVE
Code: BP
Location Address 2: SB #72515
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004328324
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/12/2013
Trans1 Recv Date: 07/14/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/16/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004328324
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID 1: NJD991291105
TSD ID 2: Not reported
Manifest Tracking Number: 002084673GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 72515 (Continued)

1016960706

Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 60
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

R118
NNE
1/8-1/4
0.192 mi.
1016 ft.

HOME DEPOT U.S.A., INC.
550 HAMILTON AVENUE
BROOKLYN, NY 11232

NY UST **U003178498**
N/A

Site 2 of 3 in cluster R

Relative:
Higher

UST:

Actual:
8 ft.

Name: HOME DEPOT U.S.A., INC.
Address: 550 HAMILTON AVENUE
City,State,Zip: BROOKLYN, NY 11232
Id/Status: 2-010898 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 584749.32442
UTM Y: 4502350.62620
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id: 94
Affiliation Type: Facility Owner
Company Name: HOME DEPOT U.S.A., INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: ONE CRAGWOOD BOULEVARD
Address2: Not reported
City: SOUTH PLAINFIELD
State: NJ
Zip Code: 07080
Country Code: 001
Phone: (908) 424-2663
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOME DEPOT U.S.A., INC. (Continued)

U003178498

Date Last Modified: 2004-03-04

Site Id: 94
Affiliation Type: Mail Contact
Company Name: HOME DEPOT U.S.A., INC.
Contact Type: Not reported
Contact Name: MIKE MARUSEVICH
Address1: ONE CRAGWOOD ROAD
Address2: Not reported
City: SOUTH PLAINFIELD
State: NJ
Zip Code: 07080
Country Code: 001
Phone: (908) 424-2663
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 94
Affiliation Type: Facility Operator
Company Name: HOME DEPOT U.S.A., INC.
Contact Type: Not reported
Contact Name: RAMENDO TSONER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 832-8448
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 94
Affiliation Type: Emergency Contact
Company Name: HOME DEPOT U.S.A., INC.
Contact Type: Not reported
Contact Name: JOE RECHICHI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (201) 461-5550
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 30735

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOME DEPOT U.S.A., INC. (Continued)

U003178498

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 03/01/1997
Date Tank Closed: 03/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 09/01/1989
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 30736
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 03/01/1997
Date Tank Closed: 03/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 09/01/1989
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOME DEPOT U.S.A., INC. (Continued)

U003178498

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 003
Tank ID: 30737
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 03/01/1997
Date Tank Closed: 03/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 01
Date Test: 09/01/1989
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

R119 HOME DEPOT USA INC HD1225
NNE 550 HAMILTON AVE
1/8-1/4 BROOKLYN, NY 11232
0.192 mi.
1016 ft. Site 3 of 3 in cluster R

RCRA-SQG 1001818194
FINDS NYR000077016
ECHO
NY MANIFEST
NJ MANIFEST

Relative: RCRA-SQG:
Higher Date form received by agency: 2007-11-23 00:00:00.0
Actual: Facility name: HOME DEPOT USA INC HD1225
8 ft. Facility address: 550 HAMILTON AVE
BROOKLYN, NY 11232
EPA ID: NYR000077016
Mailing address: ASTON AVE - SUITE 100
CARLSBAD, CA 92008
Contact: BECKY WILBANKS
Contact address: ASTON AVE - SUITE 100
CARLSBAD, CA 92008
Contact country: US
Contact telephone: 760-602-7600
Contact email: BWILBANKS@3ECOMPANY.COM
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOME DEPOT USA INC HD1225 (Continued)

1001818194

Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: HOME DEPOT USA INC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 1998-03-05 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: HOME DEPOT USA INC
Owner/operator address: PACES FERRY RD
ATLANTA, GA 30339
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 1998-03-05 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2007-11-22 00:00:00.0
Site name: HOME DEPOT USA INC HD1225
Classification: Small Quantity Generator

Date form received by agency: 2006-01-01 00:00:00.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOME DEPOT USA INC HD1225 (Continued)

1001818194

Site name: HOME DEPOT USA INC HD1225
Classification: Small Quantity Generator

Date form received by agency: 2005-06-28 00:00:00.0
Site name: HOME DEPOT USA INC HD1225
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 1999-09-27 00:00:00.0
Site name: HOME DEPOT THE 1225
Classification: Small Quantity Generator

Hazardous Waste Summary:

- . Waste code: D001
- . Waste name: IGNITABLE WASTE

- . Waste code: D002
- . Waste name: CORROSIVE WASTE

- . Waste code: D006
- . Waste name: CADMIUM

- . Waste code: D009
- . Waste name: MERCURY

- . Waste code: D016
- . Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

- . Waste code: D018
- . Waste name: BENZENE

- . Waste code: D035
- . Waste name: METHYL ETHYL KETONE

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOME DEPOT USA INC HD1225 (Continued)

1001818194

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 2007-12-28 00:00:00.0
Date achieved compliance: 2008-03-14 00:00:00.0
Violation lead agency: State
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: 2008-01-07 00:00:00.0
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 2008-04-07 00:00:00.0
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 2007-12-28 00:00:00.0
Date achieved compliance: 2008-03-14 00:00:00.0
Violation lead agency: State
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: 2008-01-07 00:00:00.0
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 2008-04-07 00:00:00.0
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 2007-12-28 00:00:00.0
Date achieved compliance: 2008-03-14 00:00:00.0
Violation lead agency: State
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: 2008-01-07 00:00:00.0
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 2008-04-07 00:00:00.0
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 2007-12-28 00:00:00.0
Date achieved compliance: 2008-03-14 00:00:00.0
Violation lead agency: State
Enforcement action: COMPLIANCE EVALUATION INSPECTION ON-SITE
Enforcement action date: 2008-01-07 00:00:00.0
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 2008-04-07 00:00:00.0
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOME DEPOT USA INC HD1225 (Continued)

1001818194

Evaluation Action Summary:

Evaluation date: 2007-12-28 00:00:00.0
Evaluation: WRITTEN INFORMAL
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 2008-03-14 00:00:00.0
Evaluation lead agency: State

Evaluation date: 2007-12-28 00:00:00.0
Evaluation: WRITTEN INFORMAL
Area of violation: Generators - Pre-transport
Date achieved compliance: 2008-03-14 00:00:00.0
Evaluation lead agency: State

Evaluation date: 2007-12-28 00:00:00.0
Evaluation: WRITTEN INFORMAL
Area of violation: TSD IS-Preparedness and Prevention
Date achieved compliance: 2008-03-14 00:00:00.0
Evaluation lead agency: State

Evaluation date: 2007-12-28 00:00:00.0
Evaluation: WRITTEN INFORMAL
Area of violation: State Statute or Regulation
Date achieved compliance: 2008-03-14 00:00:00.0
Evaluation lead agency: State

FINDS:

Registry ID: 110004556579
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004556579

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1001818194
Registry ID: 110004556579
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004556579>
Name: HOME DEPOT USA INC HD1225
Address: 550 HAMILTON AVE
City,State,Zip: BROOKLYN, NY 11232

NY MANIFEST:

Name: HOME DEPOT - #1225
Address: 550 HAMILTON AVE
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYR000077016
Facility Status: Not reported
Location Address 1: 550 HAMILTON AVE
Code: BP

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOME DEPOT USA INC HD1225 (Continued)

1001818194

Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYR000077016
Mailing Name: HOME DEPOT - #1225
Mailing Contact: PETER KRUCKER - EXT 8620
Mailing Address 1: 1905 ASTON AVE - SUITE 100
Mailing Address 2: Not reported
Mailing City: CARLSBAD
Mailing State: CA
Mailing Zip: 92008
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7606028700

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: PAD982661381
Trans2 State ID: NJD071629976
Generator Ship Date: 06/20/2018
Trans1 Recv Date: 06/20/2018
Trans2 Recv Date: 06/28/2018
TSD Site Recv Date: 06/28/2018
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077016
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID 1: RID040098352
TSD ID 2: Not reported
Manifest Tracking Number: 001890138PSC
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 32

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOME DEPOT USA INC HD1225 (Continued)

1001818194

Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Waste Code: Not reported
Waste Code 1_2: D001
Waste Code 1_3: D005
Waste Code 1_4: D007
Waste Code 1_5: D008
Waste Code 1_6: D016

NJ MANIFEST:

EPA Id: NYR000077016
Mail Address: 550 HAMILTON AVENUE
Mail City/State/Zip: BROOKLYN 11232
Facility Phone: 7188328553
Emergency Phone: Not reported
Contact: ALONZO BANNISTER
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:

Manifest Number: NJA5288048
EPA ID: NYR000077016
Date Shipped: 03/22/2006
TSDF EPA ID: NJD002200046
Transporter EPA ID: VTR000500090
Transporter 2 EPA ID: NYD980761191
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 03/22/2006
Date Trans2 Transported Waste: 04/04/2006
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 04/04/2006

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOME DEPOT USA INC HD1225 (Continued)

1001818194

TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 06130625
Was Load Rejected: BROOKLYN 11232
Reason Load Was Rejected: Not reported

T120
SSW
1/8-1/4
0.197 mi.
1038 ft.

CON ED - MH 67496
F/O 117-119 25TH ST
BROOKLYN, NY 11232

RCRA NonGen / NLR
NY MANIFEST

1007206561
NYP004012068

Site 2 of 7 in cluster T

Relative:
Higher

RCRA NonGen / NLR:

Actual:
8 ft.

Date form received by agency: 1998-02-28 00:00:00.0
Facility name: CON ED - MH 67496
Facility address: F/O 117-119 25TH ST
BROOKLYN, NY 11232-0000
EPA ID: NYP004012068
Mailing address: CONSOLIDATED EDISON INC
4 IRVING PL RM 300
NEW YORK, NY 10003-0000
Contact: ANTHONY DRUMMINGS
Contact address: CONSOLIDATED EDISON INC
NEW YORK, NY 10003-0000
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - MH 67496 (Continued)

1007206561

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 1998-02-27 00:00:00.0
Site name: CON ED - MH 67496
Classification: Not a generator, verified

Date form received by agency: 1998-02-26 00:00:00.0
Site name: CON ED - MH 67496
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Name: CONSOLIDATED EDISON
Address: F/O 117-119 25TH ST
City,State,Zip: BROOKLYN, NY 11232-0000
Country: USA
EPA ID: NYP004012068
Facility Status: Not reported
Location Address 1: MH 67496-117 25TH ST & 3RD AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004012068
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:

Document ID: NYE0005688
Manifest Status: C
seq: Not reported
Year: 1997
Trans1 State ID: 20854AD
Trans2 State ID: Not reported
Generator Ship Date: 09/27/1997
Trans1 Recv Date: 09/27/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 09/29/1997
Part A Recv Date: 10/15/1997
Part B Recv Date: 10/16/1997
Generator EPA ID: NYP004012068

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - MH 67496 (Continued)

1007206561

Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 08309
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100

T121
SSW
1/8-1/4
0.197 mi.
1038 ft.

CON ED - MH 46939
F/O #117 - 25 ST
BROOKLYN, NY 11232

RCRA NonGen / NLR 1007206584
NY MANIFEST NYP004012472

Site 3 of 7 in cluster T

Relative:
Higher

RCRA NonGen / NLR:

Actual:
8 ft.

Date form received by agency: 1998-02-28 00:00:00.0
Facility name: CON ED - MH 46939
Facility address: F/O #117 - 25 ST
BROOKLYN, NY 11232-0000
EPA ID: NYP004012472
Mailing address: CONSOLIDATED EDISON INC
4 IRVING PL RM 300
NEW YORK, NY 10003-0000
Contact: ANTHONY DRUMMINGS
Contact address: CONSOLIDATED EDISON INC
NEW YORK, NY 10003-0000
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - MH 46939 (Continued)

1007206584

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 1998-02-27 00:00:00.0
Site name: CON ED - MH 46939
Classification: Not a generator, verified

Date form received by agency: 1998-02-26 00:00:00.0
Site name: CON ED - MH 46939
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Name: CONSOLIDATED EDISON
Address: F/O #117 - 25 ST
City,State,Zip: BROOKLYN, NY 11232-0000
Country: USA
EPA ID: NYP004012472
Facility Status: Not reported
Location Address 1: MH 46939 - F/O 117 & 25 ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004012472
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:

Document ID: NYE0005121

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - MH 46939 (Continued)

1007206584

Manifest Status: C
seq: Not reported
Year: 1997
Trans1 State ID: SM1860
Trans2 State ID: Not reported
Generator Ship Date: 10/04/1997
Trans1 Recv Date: 10/04/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 10/06/1997
Part A Recv Date: 10/24/1997
Part B Recv Date: 10/24/1997
Generator EPA ID: NYP004012472
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00227
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100

U122
ESE
1/8-1/4
0.197 mi.
1042 ft.

652 4TH AVE
652 4TH AVE
BROOKLYN, NY

Site 1 of 8 in cluster U

Relative:
Higher

Actual:
39 ft.

LTANKS:
Name: 652 4TH AVE
Address: 652 4TH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0803553 / 2008-10-09
Facility ID: 0803553
Site ID: 400313
Spill Date: 2008-06-25
Spill Cause: Tank Test Failure
Spill Source: Unknown

NY LTANKS S109208729
N/A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

652 4TH AVE (Continued)

S109208729

Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: vszhune
Referred To: Not reported
Reported to Dept: 2008-06-25
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: Not reported
Remediation Phase: 0
Date Entered In Computer: 2008-06-25
Spill Record Last Update: 2008-10-09
Spiller Name: BOB URBAN
Spiller Company: Not reported
Spiller Address: 652 4TH AVE
Spiller County: 001
Spiller Contact: BOB URBAN
Spiller Phone: (631) 321-4670
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 349607
DEC Memo: "7/15/2008 TTF sent to: District 2 Meba Building Corp. 652 4th Ave, Brooklyn, NY 11232 see eDocs 10/08/08- Protest sent the report. the Report included a closure letter and the results of the tightness test. On June 26,2008 Protest performed a tightness test on the above subject tank system and it failed with a wet leak. On september 26, 2008 Pro Test technicians broke the concrete floor above tank, excavated to the tank to isolate lines from the tank. Attached to the top of the tsnk was an old suction and return connection(8 inches of line still attached to the tank), with drop tubes, which was the cause of the wet leak indication. Our technicians removed the old suction and return partial lines and drop tubes and plugged the connections. We Re-tested the tank and system and the system passed. During the excavation our technicians found no visible evidence of contamination. Spill Closed "

Remarks:

All TTF:

Facility ID: 0803553
Spill Number: 0803553
Spill Tank Test: 2486374
Site ID: 400313
Tank Number: Not reported
Tank Size: 550
Material: 0001
EPA UST: Not reported
UST: True
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

652 4TH AVE (Continued)

S109208729

Last Modified Date: Not reported

All Materials:

Site ID: 400313
Operable Unit ID: 1157137
Operable Unit: 01
Material ID: 2148155
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

T123
South
1/8-1/4
0.200 mi.
1055 ft.

LOPEZ BYWAY SERVICE STATION
739 3RD AVENUE
BROOKLYN, NY 11232
Site 4 of 7 in cluster T

NY UST **U004114963**
N/A

Relative:
Higher

Actual:
18 ft.

UST:
Name: LOPEZ BYWAY SERVICE STATION
Address: 739 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11232
Id/Status: 2-610177 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 03/31/2016
UTM X: 584577.54530
UTM Y: 4501698.35708
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 361872
Affiliation Type: Facility Owner
Company Name: LOPEZ BYWAY SERVICE STATION
Contact Type: OWNER
Contact Name: SERGIO LOPEZ
Address1: 739 3RD AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-10-22

Site Id: 361872
Affiliation Type: Mail Contact
Company Name: LOPEZ BYWAY SERVICE STATION
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

U004114963

Contact Name: EDDIE LOPEZ
Address1: 739 THIRD AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-10-22

Site Id: 361872
Affiliation Type: Facility Operator
Company Name: LOPEZ BYWAY SERVICE STATION
Contact Type: Not reported
Contact Name: EDDIE LOPEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-10-22

Site Id: 361872
Affiliation Type: Emergency Contact
Company Name: LOPEZ BYWAY SERVICE STATION
Contact Type: Not reported
Contact Name: SERGIO LOPEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-10-22

Tank Info:

Tank Number: 0001
Tank ID: 219964
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/03/2007
Registered: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

U004114963

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 0002
Tank ID: 219965
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/03/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

U004114963

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 0003
Tank ID: 219966
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/03/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 0004
Tank ID: 219967
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/03/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

U004114963

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 0005
Tank ID: 219968
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/03/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 0006
Tank ID: 219969
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/03/2007

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

U004114963

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 0007
Tank ID: 219970
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/03/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

U004114963

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 0008
Tank ID: 219971
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/03/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

T124
South
1/8-1/4
0.200 mi.
1055 ft.
LOPEZ BYWAY SERVICE STATION
739 3RD AVENUE
BROOKLYN, NY 11232
Site 5 of 7 in cluster T

NY AST **A100294869**
N/A

Relative:
Higher
Actual:
18 ft.

AST:
Name: LOPEZ BYWAY SERVICE STATION
Address: 739 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-610177
Program Type: PBS
UTM X: 584577.54530
UTM Y: 4501698.35708
Expiration Date: 03/31/2016
Site Type: Auto Service/Repair (No Gasoline Sales)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

A100294869

Affiliation Records:

Site Id: 361872
Affiliation Type: Facility Owner
Company Name: LOPEZ BYWAY SERVICE STATION
Contact Type: OWNER
Contact Name: SERGIO LOPEZ
Address1: 739 3RD AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-10-22

Site Id: 361872
Affiliation Type: Mail Contact
Company Name: LOPEZ BYWAY SERVICE STATION
Contact Type: Not reported
Contact Name: EDDIE LOPEZ
Address1: 739 THIRD AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-10-22

Site Id: 361872
Affiliation Type: Facility Operator
Company Name: LOPEZ BYWAY SERVICE STATION
Contact Type: Not reported
Contact Name: EDDIE LOPEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-10-22

Site Id: 361872
Affiliation Type: Emergency Contact
Company Name: LOPEZ BYWAY SERVICE STATION
Contact Type: Not reported
Contact Name: SERGIO LOPEZ

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

A100294869

Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-10-22

Tank Info:

Tank Number: 001
Tank Id: 64854
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 001
Tank Id: 210787
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

A100294869

H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on
impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2004
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Affiliation Records:

Site Id: 30039
Affiliation Type: Facility Owner
Company Name: EDDIE LOPEZ
Contact Type: Not reported
Contact Name: Not reported
Address1: 739 3RD AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 492-5730
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 30039
Affiliation Type: Mail Contact
Company Name: LOPEZ BYWAY
Contact Type: Not reported
Contact Name: Not reported
Address1: 739 3RD AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

A100294869

Site Id: 30039
Affiliation Type: Facility Operator
Company Name: LOPEZ BYWAY
Contact Type: Not reported
Contact Name: EDDIE LOPEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 30039
Affiliation Type: Emergency Contact
Company Name: EDDIE LOPEZ
Contact Type: Not reported
Contact Name: EDDIE LOPEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 768-5291
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 64854
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOPEZ BYWAY SERVICE STATION (Continued)

A100294869

Install Date: Not reported
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 001
Tank Id: 210787
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.

Tank Type: Steel/Carbon Steel/Iron

Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2004
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 04/14/2017
Material Name: waste oil/used oil

U125
ESE
1/8-1/4
0.202 mi.
1068 ft.

CON EDISON SERVICE BOX: 45446
642 4TH AVE
BROOKLYN, NY 11220

Site 2 of 8 in cluster U

RCRA NonGen / NLR 1016960762
NY MANIFEST NYP004329140

Relative:
Higher

RCRA NonGen / NLR:

Actual:
40 ft.

Date form received by agency: 2013-08-15 00:00:00.0
Facility name: CON EDISON SERVICE BOX: 45446
Facility address: 642 4TH AVE
BROOKLYN, NY 11220
EPA ID: NYP004329140
Mailing address: IRVING PL, RM 828

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 45446 (Continued)

1016960762

NEW YORK, NY 10003
Contact: ANTHONY SIGNORE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2013-07-15 00:00:00.0
Site name: CON EDISON SERVICE BOX: 45446
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Name: CON EDISON
Address: 642 4TH AVE
City,State,Zip: BROOKLYN, NY 11220
Country: USA
EPA ID: NYP004329140
Facility Status: Not reported
Location Address 1: 642 4TH AVE
Code: BP
Location Address 2: SB #45446
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004329140
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 45446 (Continued)

1016960762

Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/15/2013
Trans1 Recv Date: 07/15/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/18/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004329140
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002084708GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

V126 CON EDISON SERVICE BOX: 46922 RCRA NonGen / NLR 1017776008
South 192 24TH ST
1/8-1/4 BROOKLYN, NY 11232
0.203 mi.
1071 ft. Site 1 of 5 in cluster V
NYP004538575

Relative:
Higher

Actual:
19 ft.

RCRA NonGen / NLR:
Date form received by agency: 2014-06-21 00:00:00.0
Facility name: CON EDISON SERVICE BOX: 46922
Facility address: 192 24TH ST
BROOKLYN, NY 11232
EPA ID: NYP004538575
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2014-05-21 00:00:00.0
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 2014-05-21 00:00:00.0
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

V127
South
1/8-1/4
0.203 mi.
1071 ft.
CON EDISON
192 24TH ST
BROOKLYN, NY 11232
Site 2 of 5 in cluster V

NY MANIFEST **S117061545**
N/A

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:
Name: CON EDISON
Address: 192 24TH ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004538575
Facility Status: Not reported
Location Address 1: 192 24TH ST
Code: BP
Location Address 2: SB 46922
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004538575
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 05/21/2014
Trans1 Recv Date: 05/21/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/23/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004538575
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 013246424JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117061545

Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

U128
ESE
1/8-1/4
0.207 mi.
1093 ft.

CON EDISON SERVICE BOX: 3517
112-14 E 19TH ST & 4TH AVE E OF
NEW YORK, NY 10003

RCRA NonGen / NLR **1017773364**
FINDS **NYP004511440**

Site 3 of 8 in cluster U

Relative:
Higher
Actual:
42 ft.

RCRA NonGen / NLR:
Date form received by agency: 2014-05-24 00:00:00.0
Facility name: CON EDISON SERVICE BOX: 3517
Facility address: 112-14 E 19TH ST & 4TH AVE E OF
NEW YORK, NY 10003
EPA ID: NYP004511440
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 3517 (Continued)

1017773364

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2014-04-24 00:00:00.0
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 2014-04-24 00:00:00.0
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063772859
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110063772859

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

U129
ESE
1/8-1/4
0.207 mi.
1093 ft.

CON EDISON SERVICE BOX: 35024
235-37 4TH AVE & 19TH ST N OF
NEW YORK, NY 10003

RCRA NonGen / NLR **1017773366**
FINDS **NYP004511465**

Site 4 of 8 in cluster U

Relative:
Higher
Actual:
42 ft.

RCRA NonGen / NLR:
Date form received by agency: 2014-05-24 00:00:00.0
Facility name: CON EDISON SERVICE BOX: 35024
Facility address: 235-37 4TH AVE & 19TH ST N OF
NEW YORK, NY 10003
EPA ID: NYP004511465
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 35024 (Continued)

1017773366

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2014-04-24 00:00:00.0
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 2014-04-24 00:00:00.0
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063774562
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110063774562

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P130
SSE
1/8-1/4
0.209 mi.
1104 ft.

CON EDISON - EXCAVATION FRONT OF #160
160 23RD ST
BROOKLYN, NY 11232
Site 5 of 8 in cluster P

RCRA-LQG 1016960479
NY MANIFEST NYP004324620

Relative:
Higher

RCRA-LQG:

Actual:
28 ft.

Date form received by agency: 2014-03-27 00:00:00.0
Facility name: CON EDISON - EXCAVATION FRONT OF #160
Facility address: 160 23RD ST
BROOKLYN, NY 11232
EPA ID: NYP004324620
Mailing address: IRVING PL 15TH FL NE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - EXCAVATION FRONT OF #160 (Continued)

1016960479

Contact: NEW YORK, NY 10003
Contact address: DENNIS HUACON
IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-2757
Contact email: HUACOND@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON CO OF NY INC
Owner/operator address: IRVING PL
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2013-07-02 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON CO OF NY INC
Owner/operator address: IRVING PL
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2013-07-02 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - EXCAVATION FRONT OF #160 (Continued)

1016960479

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2013-08-03 00:00:00.0
Site name: CON EDISON EXCAVATION: FRONT~OF~#160
Classification: Not a generator, verified

Date form received by agency: 2013-07-03 00:00:00.0
Site name: CON EDISON EXCAVATION: FRONT~OF~#160
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

Waste code: B002
Waste name: Petroleum oil or other liquid containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs. This includes oil from electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

Violation Status: No violations found

NY MANIFEST:

Name: CON EDISON
Address: 160 23RD ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004324620
Facility Status: Not reported
Location Address 1: 160 23RD STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004324620
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - EXCAVATION FRONT OF #160 (Continued)

1016960479

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	07/03/2013
Trans1 Recv Date:	07/03/2013
Trans2 Recv Date:	07/09/2013
TSD Site Recv Date:	07/10/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004324620
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID 1:	NYD049836679
TSD ID 2:	Not reported
Manifest Tracking Number:	002016854GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	17191
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	B002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

Map ID	Direction	Distance	Elevation	Site	Database(s)	EDR ID Number	EPA ID Number
S131				PRIVATE HOME			
SSE				720 4TH AVE			
1/8-1/4				BROOKLYN, NY	NY LTANKS	S108765406	N/A
0.209 mi.							
1106 ft.				Site 2 of 3 in cluster S			
Relative:				LTANKS:			
Higher				Name:	PRIVATE HOME		
				Address:	720 4TH AVE		
Actual:				City,State,Zip:	BROOKLYN, NY		
33 ft.				Spill Number/Closed Date:	0704596 / 2013-07-31		
				Facility ID:	0704596		
				Site ID:	384784		
				Spill Date:	2007-07-24		
				Spill Cause:	Tank Test Failure		
				Spill Source:	Private Dwelling		
				Spill Class:	C4		
				Cleanup Ceased:	Not reported		
				SWIS:	2401		
				Investigator:	VXBREVD0		
				Referred To:	Not reported		
				Reported to Dept:	2007-07-24		
				CID:	444		
				Water Affected:	Not reported		
				Spill Notifier:	Tank Tester		
				Last Inspection:	Not reported		
				Recommended Penalty:	False		
				Meets Standard:	False		
				UST Involvement:	Not reported		
				Remediation Phase:	0		
				Date Entered In Computer:	2007-07-24		
				Spill Record Last Update:	2013-07-31		
				Spiller Name:	MARLIN JOSEPH		
				Spiller Company:	PRIVATE HOME		
				Spiller Address:	720 4TH AVE		
				Spiller County:	001		
				Spiller Contact:	MARLIN JOSEPH		
				Spiller Phone:	(718) 624-4842		
				Spiller Extention:	112		
				DEC Region:	2		
				DER Facility ID:	334183		
				DEC Memo:	"07/16/13 - Spill Case is transferred from Brian Falvey (PBS Unit) to V. Brevdo (Section B) as per DER Region 2 decision - Tank Test Failure Spill Case. VB 07/31/2013 - V. Brevdo This TTF spill in unconfirmed. No information is available in DEC file to pursue this case. Spill Case Closure is appropriate. Spill case is closed effective July 31, 2013. V. Brevdo"		
				Remarks:	"ABOVE LIQUID LEAK"		
				All TTF:			
				Facility ID:	0704596		
				Spill Number:	0704596		
				Spill Tank Test:	1551019		
				Site ID:	384784		
				Tank Number:	1		
				Tank Size:	4000		
				Material:	0001		
				EPA UST:	Not reported		
				UST:	Not reported		
				Cause:	Not reported		

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIVATE HOME (Continued)

S108765406

Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:

Site ID: 384784
Operable Unit ID: 1142075
Operable Unit: 01
Material ID: 2132294
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

S132
SSE
1/8-1/4
0.210 mi.
1110 ft.

NYNEX-MANHOLE
4TH AVE & 22ND ST
BROOKLYN, NY 11232

Site 3 of 3 in cluster S

RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

1007205189
NYP000919563

Relative:
Higher

RCRA NonGen / NLR:

Actual:
38 ft.

Date form received by agency: 1996-03-27 00:00:00.0
Facility name: NYNEX-MANHOLE
Facility address: 4TH AVE & 22ND ST
BROOKLYN, NY 11232-0000
EPA ID: NYP000919563
Mailing address: 221 E 37TH ST 4TH FL
NEW YORK, NY 10016-0000
Contact: JOHN QUATRALE
Contact address: 221 E 37TH ST 4TH FL
NEW YORK, NY 10016-0000
Contact country: US
Contact telephone: 212-338-7141
Telephone ext.: 9999
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYNEX-MANHOLE (Continued)

1007205189

Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 1996-03-26 00:00:00.0
Site name: NYNEX-MANHOLE
Classification: Not a generator, verified

Date form received by agency: 1996-03-25 00:00:00.0
Site name: NYNEX-MANHOLE
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110064229589
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110064229589

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1007205189
Registry ID: 110064229589
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110064229589>
Name: NYNEX-MANHOLE
Address: 4TH AVE & 22ND ST
City,State,Zip: BROOKLYN, NY 11232

NY MANIFEST:

Name: NYNEX
Address: 4TH AVE & 22ND ST
City,State,Zip: BROOKLYN, NY 11232-0000
Country: USA
EPA ID: NYP000919563
Facility Status: Not reported
Location Address 1: 4TH AVE & 22ND ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYNEX-MANHOLE (Continued)

1007205189

NY MANIFEST:

EPAID: NYP000919563
Mailing Name: NYNEX
Mailing Contact: STEVE YUEN
Mailing Address 1: 1095 AVE OF AMER
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10036
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2123956040

NY MANIFEST:

Document ID: NJA2029830
Manifest Status: C
seq: Not reported
Year: 1995
Trans1 State ID: 50060
Trans2 State ID: Not reported
Generator Ship Date: 03/27/1995
Trans1 Recv Date: 03/27/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 03/29/1995
Part A Recv Date: 04/28/1995
Part B Recv Date: 04/06/1995
Generator EPA ID: NYP000919563
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W133
SE
1/8-1/4
0.212 mi.
1119 ft.

BROOKLYN CULTURAL CENTER OF NEW YORK
675 4TH AVENUE
BROOKLYN, NY 11232

NY AST

U004076197
N/A

Site 1 of 4 in cluster W

Relative:
Higher

AST:

Actual:
41 ft.

Name: BROOKLYN CULTURAL CENTER OF NEW YORK
Address: 675 4TH AVENUE
City,State,Zip: BROOKLYN, NY 11232-1299
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-054666
Program Type: PBS
UTM X: 584919.40575
UTM Y: 4501775.05072
Expiration Date: N/A
Site Type: School

Affiliation Records:

Site Id: 768
Affiliation Type: Facility Owner
Company Name: B.C.C.
Contact Type: Not reported
Contact Name: AINCIFAL
Address1: 675 - 4TH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 768-7181
EMail: Not reported
Fax Number: Not reported
Modified By: kxtang
Date Last Modified: 2004-06-22

Site Id: 768
Affiliation Type: Mail Contact
Company Name: B.C.C.
Contact Type: Not reported
Contact Name: ABUASI
Address1: 675 - 4TH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 768-7181
EMail: Not reported
Fax Number: Not reported
Modified By: kxtang
Date Last Modified: 2004-06-22

Site Id: 768
Affiliation Type: Facility Operator
Company Name: BROOKLYN CULTURAL CENTER OF NEW YORK
Contact Type: Not reported
Contact Name: B.C.C.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN CULTURAL CENTER OF NEW YORK (Continued)

U004076197

Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 768-7181
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 768
Affiliation Type: Emergency Contact
Company Name: B.C.C.
Contact Type: Not reported
Contact Name: NIDAL. ABUASI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 770-4865
EMail: Not reported
Fax Number: Not reported
Modified By: kxtang
Date Last Modified: 2004-06-22

Tank Info:

Tank Number: 001
Tank Id: 1690
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 5000
Tightness Test Method: -
Date Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN CULTURAL CENTER OF NEW YORK (Continued)

U004076197

Next Test Date: Not reported
Date Tank Closed: 06/16/2008
Register: True
Modified By: LXZIELIN
Last Modified: 06/23/2017
Material Name: #2 fuel oil (on-site consumption)

P134
SSE
1/8-1/4
0.213 mi.
1123 ft.
CON EDISON
162 23RD ST
BROOKLYN, NY 11215
Site 6 of 8 in cluster P

NJ MANIFEST **S120669688**
N/A

Relative:
Higher
Actual:
29 ft.

NJ MANIFEST:
EPA Id: NYP004758991
Mail Address: IRVING PL, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDf Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002619030GBF
EPA ID: NYP004758991
Date Shipped: 3/27/2015
TSDf EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: Not reported
TSDf EPA Facility Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S120669688

QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

P135
SSE
1/8-1/4
0.213 mi.
1123 ft.

CON EDISON
162 23RD ST
BROOKLYN, NY 11215
Site 7 of 8 in cluster P

NY MANIFEST S118088342
N/A

Relative:
Higher
Actual:
29 ft.

NY MANIFEST:
Name: CON EDISON
Address: 162 23RD ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004758991
Facility Status: Not reported
Location Address 1: 162 23RD ST
Code: BP
Location Address 2: 46897
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004758991
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S118088342

Trans2 State ID: NJD003812047
Generator Ship Date: 03/27/2015
Trans1 Recv Date: 03/27/2015
Trans2 Recv Date: 03/31/2015
TSD Site Recv Date: 03/31/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004758991
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002619030GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

P136
SSE
1/8-1/4
0.213 mi.
1123 ft.
CON EDISON
162 23RD ST
BROOKLYN, NY 11215
Site 8 of 8 in cluster P

RCRA NonGen / NLR
FINDS
ECHO
1018280980
NYP004758991

Relative:
Higher
Actual:
29 ft.
RCRA NonGen / NLR:
Date form received by agency: 2015-03-27 00:00:00.0
Facility name: CON EDISON
Facility address: 162 23RD ST
BROOKLYN, NY 11215
EPA ID: NYP004758991
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1018280980

Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2015-03-27 00:00:00.0
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067684946
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110067684946

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1018280980
Registry ID: 110067684946
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110067684946>
Name: CON EDISON
Address: 162 23RD ST
City,State,Zip: BROOKLYN, NY 11215

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

137
SSW
1/8-1/4
0.218 mi.
1152 ft.

NYC PARKS & REC - CONEY ISLAND GARAGE
30-26 W 25TH ST
BROOKLYN, NY 11224

RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

1001028333
NYR000005652

Relative:
Higher

RCRA NonGen / NLR:

Actual:
8 ft.

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: NYC PARKS & REC - CONEY ISLAND GARAGE
Facility address: 30-26 W 25TH ST
BROOKLYN, NY 11224-1907
EPA ID: NYR000005652
Mailing address: BOROUGH SHOPS
RANDALLS ISLAND, NY 10035
Contact: Not reported
Contact address: BOROUGH SHOPS
RANDALLS ISLAND, NY 10035
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Municipal
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: CITY OF NEW YORK PARKS & REC
Owner/operator address: FIVE BOROUGH SHOPS
RANDALLS ISLAND, NY 10035
Owner/operator country: US
Owner/operator telephone: 212-410-8905
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CITY OF NEW YORK PARKS & REC
Owner/operator address: FIVE BOROUGH SHOPS
RANDALLS ISLAND, NY 10035
Owner/operator country: US
Owner/operator telephone: 212-410-8905
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC PARKS & REC - CONEY ISLAND GARAGE (Continued)

1001028333

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: NYC PARKS & REC - CONEY ISLAND GARAGE
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: NYC PARKS & REC - CONEY ISLAND GARAGE
Classification: Not a generator, verified

Date form received by agency: 1996-11-20 00:00:00.0
Site name: CITY OF NEW YORK DEPARTMENT OF
Classification: Large Quantity Generator

Date form received by agency: 1995-05-27 00:00:00.0
Site name: NYC PARKS & REC - CONEY ISLAND GARAGE
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 1996-10-07 00:00:00.0
Date achieved compliance: 1996-11-18 00:00:00.0
Violation lead agency: State
Enforcement action: NON-FINANCIAL RECORD REVIEW
Enforcement action date: 1996-10-07 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 1996-01-01 00:00:00.0
Evaluation: WRITTEN INFORMAL
Area of violation: Generators - Records/Reporting
Date achieved compliance: 1996-11-18 00:00:00.0
Evaluation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC PARKS & REC - CONEY ISLAND GARAGE (Continued)

1001028333

FINDS:

Registry ID: 110004514044
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004514044

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1001028333
Registry ID: 110004514044
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004514044>
Name: NYC PARKS & REC - CONEY ISLAND GARAGE
Address: 30-26 W 25TH ST
City,State,Zip: BROOKLYN, NY 11224

NY MANIFEST:

Name: NYC DEPT OF PARKS & RECREATION
Address: 30-26 W 25TH ST
City,State,Zip: BROOKLYN, NY 11224-1907
Country: USA
EPA ID: NYR000005652
Facility Status: Not reported
Location Address 1: CONEY ISLAND GAR/30-26 25TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYR000005652
Mailing Name: NYC DEPT OF PARKS & RECREATION
Mailing Contact: MARK MARAIA
Mailing Address 1: 24-16 BRIDGE PLAZA S/SUITE 502
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7189373286

NY MANIFEST:

Document ID: NYB7554033
Manifest Status: C
seq: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC PARKS & REC - CONEY ISLAND GARAGE (Continued)

1001028333

Year: 1995
Trans1 State ID: Not reported
Trans2 State ID: NYD980769
Generator Ship Date: 09/28/1995
Trans1 Recv Date: 09/28/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 10/02/1995
Part A Recv Date: 10/10/1995
Part B Recv Date: 10/19/1995
Generator EPA ID: NYR000005652
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSD ID 1: NYD057770109
TSD ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00500
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00330
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

U138
ESE
1/8-1/4
0.219 mi.
1154 ft.

SLOPE ON 4TH LLC
647 4TH AVENUE
BROOKLYN, NY 11232

Site 5 of 8 in cluster U

NY AST **U003390314**
N/A

Relative:
Higher

Actual:
46 ft.

AST:

Name: SLOPE ON 4TH LLC
Address: 647 4TH AVENUE
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-212962
Program Type: PBS
UTM X: 584990.64402
UTM Y: 4501859.60417
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 7835
Affiliation Type: Mail Contact
Company Name: SLOPE ON 4TH LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: PO BOX 249
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (718) 837-2400
EMail: MARK@STERLINGGROUP.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2015-05-13

Site Id: 7835
Affiliation Type: Facility Operator
Company Name: SLOPE ON 4TH LLC
Contact Type: Not reported
Contact Name: MARK WEINBERGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 837-2500
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2015-05-13

Site Id: 7835
Affiliation Type: Emergency Contact
Company Name: SLOPE ON 4TH LLC
Contact Type: Not reported
Contact Name: MARK WEINBERGER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SLOPE ON 4TH LLC (Continued)

U003390314

Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 837-2500
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2015-05-13

Site Id: 7835
Affiliation Type: Facility Owner
Company Name: SLOPE ON 4TH LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: PO BOX 249
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (718) 837-2400
EMail: MARK@STERLINGGROUP.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2015-05-13

Tank Info:

Tank Number: 001
Tank Id: 18804
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1998
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SLOPE ON 4TH LLC (Continued)

U003390314

Next Test Date: Not reported
Date Tank Closed: 04/09/2012
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

T139
SSW
1/8-1/4
0.220 mi.
1161 ft.

25TH ST STATION/R TRAIN
25TH ST STATION
NEW YORK CITY, NY
Site 6 of 7 in cluster T

NY LTANKS **S102671402**
N/A

Relative:
Higher
Actual:
16 ft.

LTANKS:
Name: 25TH ST STATION/R TRAIN
Address: 25TH ST STATION
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 8902919 / 2003-02-12
Facility ID: 8902919
Site ID: 149988
Spill Date: 1989-06-21
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SULLIVAN
Referred To: Not reported
Reported to Dept: 1989-06-21
CID: Not reported
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1989-06-23
Spill Record Last Update: 2003-02-12
Spiller Name: Not reported
Spiller Company: APT COMPLEX
Spiller Address: 279 27TH STREET
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 127557
DEC Memo: ""
Remarks: "OIL WAS DISCOVERED, DID NOT BELONG TO NYCTA, CALLER BELIEVES COMPLEX HAD OVERFILL, PRESENCE OF OIL UNDER TRAIN PLATFORM, COMPLEX HAS HAD OVERFILLS IN PAST."

All Materials:
Site ID: 149988
Operable Unit ID: 928482
Operable Unit: 01
Material ID: 450595

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

25TH ST STATION/R TRAIN (Continued)

S102671402

Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

**140
ESE
1/8-1/4
0.220 mi.
1164 ft.**

**PARK SLOPE AUTO CENTER INC.
651 4TH AVENUE
BROOKLYN, NY 11232**

**NY AST A100178069
N/A**

**Relative:
Higher**

AST:

**Actual:
46 ft.**

Name: PARK SLOPE AUTO CENTER INC.
Address: 651 4TH AVENUE
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-605798
Program Type: PBS
UTM X: 584986.32029
UTM Y: 4501852.84552
Expiration Date: 04/27/2016
Site Type: Other

Affiliation Records:

Site Id: 27665
Affiliation Type: Facility Owner
Company Name: PARK SLOPE AUTO CENTER INC.
Contact Type: PRES.
Contact Name: KNEIFATI HAYEK
Address1: 651 4TH AVE.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 499-9726
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2011-02-07

Site Id: 27665
Affiliation Type: Mail Contact
Company Name: PARK SLOPE AUTO CENTER INC.
Contact Type: Not reported
Contact Name: JAMAL KNEIFATI HAYEK
Address1: 651 4TH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARK SLOPE AUTO CENTER INC. (Continued)

A100178069

Country Code: 001
Phone: (718) 499-9726
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2011-02-07

Site Id: 27665
Affiliation Type: Facility Operator
Company Name: PARK SLOPE AUTO CENTER INC.
Contact Type: Not reported
Contact Name: JAMAL KNEIFAIT HAYEK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 499-9726
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 27665
Affiliation Type: Emergency Contact
Company Name: PARK SLOPE AUTO CENTER INC.
Contact Type: Not reported
Contact Name: JAMAL KNEIFAIT HAYEK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 499-9726
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 01
Tank Id: 60483
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARK SLOPE AUTO CENTER INC. (Continued)

A100178069

K00 - Spill Prevention - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil,
allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/18/2009
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 02
Tank Id: 231155
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
G05 - Tank Secondary Containment - Synthetic Liner
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on
impervious barrier, allowing visual indication of leaks.
Tank Type: Fiberglass Reinforced Plastic
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/18/2009
Capacity Gallons: 150
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

V141
South
1/8-1/4
0.222 mi.
1170 ft.

CON EDISON
155 25 ST
BROOKLYN, NY 11232

Site 3 of 5 in cluster V

NY MANIFEST **S117316005**
N/A

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:
Name: CON EDISON
Address: 155 25 ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004632295
Facility Status: Not reported
Location Address 1: 155 25 ST
Code: BP
Location Address 2: SB 46940
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004632295
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/19/2014
Trans1 Recv Date: 08/19/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/21/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004632295
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002616441GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117316005

Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 60
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

T142
SSW
1/8-1/4
0.224 mi.
1181 ft.

CONSOLIDATED EDISON
3RD AVE & 25TH ST EXCAV
BROOKLYN, NY 11201

NY MANIFEST

S108933212
N/A

Site 7 of 7 in cluster T

Relative:
Higher
Actual:
16 ft.

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 3RD AVE & 25TH ST EXCAV
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004142469
Facility Status: Not reported
Location Address 1: 3RD AVE & 25TH ST EXCAV
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004142469
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRONKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S108933212

Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:

Document ID: NYE1321569
Manifest Status: Not reported
seq: 01
Year: 2006
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/27/2006
Trans1 Recv Date: 05/27/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/30/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004142469
Trans1 EPA ID: 18887JU
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00029
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 00.08

U143 639 4TH AVENUE
ESE 639 4TH AVENUE
1/8-1/4 BROOKLYN, NY 11232
0.224 mi.
1184 ft. Site 6 of 8 in cluster U

NY UST U004045702
N/A

Relative: UST:
Higher Name: 639 4TH AVENUE
Actual: Address: 639 4TH AVENUE
48 ft. City,State,Zip: BROOKLYN, NY 11232

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

639 4TH AVENUE (Continued)

U004045702

Id/Status: 2-609859 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 584990.61055
UTM Y: 4501908.74188
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 337982
Affiliation Type: Facility Owner
Company Name: 639 4TH AVENUE LLC
Contact Type: PARTNER
Contact Name: B TULI
Address1: 64 WESTWOOD CIRCLE
Address2: Not reported
City: EAST HILLS
State: NY
Zip Code: 11577
Country Code: 001
Phone: (516) 984-5751
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-02-24

Site Id: 337982
Affiliation Type: Mail Contact
Company Name: 639 4TH AVENUE LLC
Contact Type: PARTNER
Contact Name: B TULI
Address1: 64 WESTWOOD CIRCLE
Address2: Not reported
City: EAST HILLS
State: NY
Zip Code: 11577
Country Code: 001
Phone: (516) 984-5751
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-02-24

Site Id: 337982
Affiliation Type: Facility Operator
Company Name: 639 4TH AVENUE
Contact Type: Not reported
Contact Name: NONE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: NONE
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

639 4TH AVENUE (Continued)

U004045702

Modified By: KXTANG
Date Last Modified: 2005-02-24

Site Id: 337982
Affiliation Type: Emergency Contact
Company Name: 639 4TH AVENUE LLC
Contact Type: Not reported
Contact Name: NONE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: NONE
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-02-24

Tank Info:

Tank Number: 1
Tank ID: 182161
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/14/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
B02 - Tank External Protection - Original Sacrificial Anode
G00 - Tank Secondary Containment - None

Tank Number: 2
Tank ID: 182162
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/14/2004
Registered: True
Tank Location: Underground

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

639 4TH AVENUE (Continued)

U004045702

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
B02 - Tank External Protection - Original Sacrificial Anode
G00 - Tank Secondary Containment - None

Tank Number: 3
Tank ID: 182163
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/14/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
B02 - Tank External Protection - Original Sacrificial Anode
G00 - Tank Secondary Containment - None

Tank Number: 4
Tank ID: 182164
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/14/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

639 4TH AVENUE (Continued)

U004045702

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
B02 - Tank External Protection - Original Sacrificial Anode
G00 - Tank Secondary Containment - None

Tank Number: 5
Tank ID: 182165
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/14/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
B02 - Tank External Protection - Original Sacrificial Anode
G00 - Tank Secondary Containment - None

Tank Number: 6
Tank ID: 182166
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/14/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

639 4TH AVENUE (Continued)

U004045702

B02 - Tank External Protection - Original Sacrificial Anode
G00 - Tank Secondary Containment - None

**144
NNW
1/8-1/4
0.225 mi.
1189 ft.**

**HAMILTON AVE PIERS
19TH & 18TH STREETS
BROOKLYN, NY 11232**

**NY HSWDS S108146265
N/A**

**Relative:
Lower**

HSWDS:

**Actual:
0 ft.**

Facility ID: HS2031
Region: 2
Facility Status: Unknown
Owner Type: U
Owner: Strober Realty
Owner Address: 550 Hamilton Ave
Owner Phone: Unknown
Operator Type: Unknown
Operator: Same
Operator: Same
Operator Phone: Same
EPA ID: NYD980768733
Registry: Is or was on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID: 224007
RCRA Permitted: Unknown
Site Code: Leaking tanks, drums, lagoons, other containers
Owner City State: Brooklyn
Operator City State: Not reported
Quadrangle: Brooklyn
Latitude: 40 40 06 N
Longitude: 74 00 04 W
Acres: 0.00
Operator Date: 1967
Close Date: 1979
Completed: Phase 2
Active: No
PCB's Disposed: No
Pesticides Disposed: No
Metals Disposed: Yes
Asbestos Disposed: No
Volatile Organic Compounds Disposed: Yes
Semi Volatile Organic Compounds Disposed: Yes
Analytical Info Exists for Air: Not reported
Analytical Info Exists for Ground: Groundwater
Analytical Info Exists for Surface: Not reported
Analytical Info Exists for Sediments: Not reported
Analytical Info Exists for Surface: Surface Soil
Analytical Info Exists for Substance: Subsurface Soil
Analytical Info Exists for Waste: Not reported
Analytical Info Exists for Leachate: Not reported
Analytical Info Exists for EP Toxicity: EPTox
Analytical Info Exists for TCLP: Not reported
Threat to Environment/Public Health: Environmental
Surface Water Contamination: Yes
Surface Water Body Class: Unknown
Groundwater Contamination: Yes
Groundwater Classification: Unknown
Drinking Water Contamination: Unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAMILTON AVE PIERS (Continued)

S108146265

Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Yes
Site Has Controlled Access:	Yes
Ambient Air Contamination:	Unknown
Direct Contact:	Yes
EPA Hazardous Ranking System Score:	5.80
Inventory:	F
Nefrap:	T
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

X145
SSE
1/8-1/4
0.226 mi.
1193 ft.

CON EDISON
174-23 ST
BROOKLYN, NY 11232

Site 1 of 6 in cluster X

NY MANIFEST **S117066596**
N/A

Relative: NY MANIFEST:
Higher Name: CON EDISON
Address: 174-23 ST
Actual: City,State,Zip: BROOKLYN, NY 11232
32 ft. Country: USA
EPA ID: NYP004592648
Facility Status: Not reported
Location Address 1: 174-23 ST
Code: BP
Location Address 2: STRUCTURE 46901
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117066596

EPAID: NYP004592648
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/10/2014
Trans1 Recv Date: 07/10/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/11/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004592648
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID 1: NJD991291105
TSD ID 2: Not reported
Manifest Tracking Number: 002504204GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117066596

Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

**W146
SE
1/8-1/4
0.226 mi.
1194 ft.**

**CON EDISON SERVICE BOX: S/B~45448
683 4TH AVE
BROOKLYN, NY 11217**

**RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST**

**1016677670
NYP004313391**

Site 2 of 4 in cluster W

**Relative:
Higher**

RCRA NonGen / NLR:

**Actual:
44 ft.**

Date form received by agency: 2013-06-15 00:00:00.0
Facility name: CON EDISON SERVICE BOX: S/B~45448
Facility address: 683 4TH AVE
BROOKLYN, NY 11217
EPA ID: NYP004313391
Mailing address: VING PL, RM 828
NEW YORK, NY 10003
Contact: KYLE ANDERSON
Contact address: Not reported
Contact country: Not reported
Contact telephone: 718-666-4596
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2013-05-15 00:00:00.0
Site name: CON EDISON SERVICE BOX: S/B~45448
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058877256
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110058877256

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: S/B~45448 (Continued)

1016677670

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1016677670
Registry ID: 110058877256
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110058877256>
Name: CON EDISON SERVICE BOX: S/B~45448
Address: 683 4TH AVE
City,State,Zip: BROOKLYN, NY 11217

NY MANIFEST:

Name: CON EDISON
Address: 683 4TH AVE
City,State,Zip: BROOKLYN, NY 11217
Country: USA
EPA ID: NYP004313391
Facility Status: Not reported
Location Address 1: 683 4TH AVE
Code: BP
Location Address 2: SERVICE BOX # 45448
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004313391
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 05/15/2013
Trans1 Recv Date: 05/15/2013

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: S/B-45448 (Continued)

1016677670

Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/16/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004313391
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID 1: NJD991291105
TSD ID 2: Not reported
Manifest Tracking Number: 002017481GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

U147
ESE
1/8-1/4
0.230 mi.
1217 ft.

SUNOCO SERVICE STATION
623 FOURTH AVE
BROOKLYN, NY 11232

Site 7 of 8 in cluster U

RCRA NonGen / NLR 1000328910
NYD000816421

Relative:
Higher

Actual:
46 ft.

RCRA NonGen / NLR:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: SUNOCO SERVICE STATION
Facility address: 623 FOURTH AVE
BROOKLYN, NY 11232
EPA ID: NYD000816421
Mailing address: FOURTH AVE
BROOKLYN, NY 11232
Contact: HOWARD ALGEO
Contact address: FOURTH AVE
BROOKLYN, NY 11232

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNOCO SERVICE STATION (Continued)

1000328910

Contact country: US
Contact telephone: 215-688-8200
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: SUN OIL COMPANY OF PENNSYLVANIA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: SUN OIL COMPANY OF PENNSYLVANIA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. Importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: SUNOCO SERVICE STATION
Classification: Not a generator, verified

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNOCO SERVICE STATION (Continued)

1000328910

Date form received by agency: 1980-08-18 00:00:00.0
Site name: SUNOCO SERVICE STATION
Classification: Not a generator, verified

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

U148
ESE
1/8-1/4
0.231 mi.
1219 ft.

635 4TH AVENUE
635 4TH AVENUE
NEW YORK CITY, NY
Site 8 of 8 in cluster U

NY VCP S118943363
N/A

Relative:
Higher
Actual:
47 ft.

VCP NYC:
Project ID: 14TMP0369K, 14EHAZ369K, 14CVCP228K
Name: 635 4TH AVENUE
Address: 635 4TH AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn

W149
SE
1/8-1/4
0.231 mi.
1222 ft.

691 4TH AVENUE
691 4TH AVENUE
NEW YORK CITY, NY
Site 3 of 4 in cluster W

NY VCP S125317185
N/A

Relative:
Higher
Actual:
42 ft.

VCP NYC:
Project ID: 18TMP0017K, 18EHAZ047K
Name: 691 4TH AVENUE
Address: 691 4TH AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn

Y150
East
1/8-1/4
0.232 mi.
1227 ft.

CON EDISON - MANHOLE 5613
614 4 AVE
BROOKLYN, NY 11215
Site 1 of 4 in cluster Y

RCRA-LQG 1019325803
NYP004860231

Relative:
Higher
Actual:
45 ft.

RCRA-LQG:
Date form received by agency: 2016-02-26 00:00:00.0
Facility name: CON EDISON - MANHOLE 5613
Facility address: 614 4 AVE
BROOKLYN, NY 11215
EPA ID: NYP004860231
Mailing address: IRVING PL15TH FL NE
NEW YORK, NY 10003
Contact: THERESA BURKARD

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 5613 (Continued)

1019325803

Contact address: IRVING PL15TH FL NE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-2262
Contact email: BURKARDT@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2015-10-26 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2015-10-26 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 5613 (Continued)

1019325803

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code: D008
Waste name: LEAD
Amount (Lbs): 3320

Violation Status: No violations found

**Y151
East
1/8-1/4
0.232 mi.
1227 ft.**

**CON EDISON - MANHOLE 5613
614 4 AVE
BROOKLYN, NY 11215
Site 2 of 4 in cluster Y**

**NJ MANIFEST S120677763
N/A**

**Relative:
Higher**

NJ MANIFEST:
EPA Id: NYP004860231
Mail Address: IRVING PL15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THERESA BURKARD
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSD Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:

Manifest Number: 002622622GBF
EPA ID: NYP004860231
Date Shipped: 10/26/2015
TSD EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 5613 (Continued)

S120677763

Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Y152
East
1/8-1/4
0.232 mi.
1227 ft.

CON ED
614 4 AVE
BROOKLYN, NY 11215
Site 3 of 4 in cluster Y

NY MANIFEST **S118563590**
N/A

Relative:
Higher
Actual:
45 ft.

NY MANIFEST:
Name: CON ED
Address: 614 4 AVE
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004860231
Facility Status: Not reported
Location Address 1: 614 4 AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004860231

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED (Continued)

S118563590

Mailing Name: CON ED
Mailing Contact: CON ED
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

W153
SE
1/8-1/4
0.233 mi.
1232 ft.
CON EDISON - 22ND STREET
181 22ND STREET
BROOKLYN, NY 11232
Site 4 of 4 in cluster W

PA MANIFEST S123093054
N/A

Relative:
Higher

Actual:
43 ft.

Manifest Details:

Year: 2017
Manifest Number: 009438921FLE
Manifest Type: TSD Copy
Generator EPA Id: NYP005030812
Generator Date: 02/10/2017
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: Not reported
TSD Date: Not reported
TSD Facility Name: Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address: 2869 Sandstone Dr
TSD Facility City: Hatfield
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: 5
Container Number: 1
Container Type: Cargo tanks (tank trucks)
Waste Quantity: 800
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: PAD085690592
Date TSP Sig: Not reported

Year: 2017
Manifest Number: 009438921FLE
Manifest Type: TSD Copy
Generator EPA Id: NYP005030812
Generator Date: 02/10/2017
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: Not reported
TSD Date: Not reported
TSD Facility Name: Republic Environmental Systems (Pennsylvania) LLC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - 22ND STREET (Continued)

S123093054

TSD Facility Address: 2869 Sandstone Dr
TSD Facility City: Hatfield
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: D008
Container Number: 1
Container Type: Cargo tanks (tank trucks)
Waste Quantity: 800
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: PAD085690592
Date TSP Sig: Not reported

Z154
NE
1/8-1/4
0.233 mi.
1232 ft.

CON EDISON
F/O 12 16 MCDONAL AV
BROOKLYN, NY 11230

NY MANIFEST **S117537266**
N/A

Site 1 of 4 in cluster Z

Relative:
Higher

NY MANIFEST:
Name: CON EDISON
Address: F/O 12 16 MCDONAL AV
City,State,Zip: BROOKLYN, NY 11230
Country: USA
EPA ID: NYP004698064
Facility Status: Not reported
Location Address 1: F/O 12 16 MCDONAL AV
Code: BP
Location Address 2: M66849
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11230
Location Zip 4: Not reported

Actual:
12 ft.

NY MANIFEST:
EPAID: NYP004698064
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

X155
SSE
1/8-1/4
0.234 mi.
1236 ft.

NYSDEC/SPILLS
734 4TH AVE
BROOKLYN, NY 11101

Site 2 of 6 in cluster X

RCRA NonGen / NLR
NY MANIFEST

1010325297
NYP000958355

Relative:
Higher

Actual:
31 ft.

RCRA NonGen / NLR:
Date form received by agency: 2006-03-08 00:00:00.0
Facility name: NYSDEC/SPILLS
Facility address: 734 4TH AVE
BROOKLYN, NY 11101
EPA ID: NYP000958355
Mailing address: 625 B'WAY
ALBANY, NY 12233-7250
Contact: REPORTING SECTION
Contact address: 625 B'WAY
ALBANY, NY 12233-7250
Contact country: US
Contact telephone: 518-402-8730
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: UNKNOWN
Owner/operator address: UNKNOWN
UNKNOWN, NY 11111
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 1979-12-31 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: 2005-02-10 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDEC/SPILLS (Continued)

1010325297

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-03-07 00:00:00.0
Site name: NYSDEC/SPILLS
Classification: Not a generator, verified

Date form received by agency: 2006-03-06 00:00:00.0
Site name: NYSDEC/SPILLS
Classification: Not a generator, verified

Violation Status: No violations found

NY MANIFEST:

Name: NYS DEC BUREAU OF SPILLS
Address: 734 4TH AVE
City,State,Zip: BROOKLYN, NY 11101
Country: USA
EPA ID: NYP000958355
Facility Status: Not reported
Location Address 1: 737 4TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP000958355
Mailing Name: NYS DEC BUREAU OF SPILLS
Mailing Contact: MARK TIBBE
Mailing Address 1: 47 40 21ST STREET
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 8004577362

NY MANIFEST:

Document ID: NYG1627362
Manifest Status: Not reported
seq: Not reported
Year: 2005
Trans1 State ID: NYD064743263
Trans2 State ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDEC/SPILLS (Continued)

1010325297

Generator Ship Date: 02/10/2005
Trans1 Recv Date: 02/10/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/10/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP000958355
Trans1 EPA ID: 66832JR
Trans2 EPA ID: Not reported
TSDF ID 1: NYD082785429
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00495
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDEC/SPILLS (Continued)

1010325297

Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: Not reported

AA156
ENE
1/8-1/4
0.234 mi.
1238 ft.

CON EDISON
139 PROSPECT AVE
BROOKLYN, NY 11215
Site 1 of 3 in cluster AA

NY MANIFEST **S117314923**
N/A

Relative:
Higher

NY MANIFEST:

Actual:
28 ft.

Name: CON EDISON
Address: 139 PROSPECT AVE
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004620183
Facility Status: Not reported
Location Address 1: 139 PROSPECT AVE
Code: BP
Location Address 2: SB 31815
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004620183
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/06/2014
Trans1 Recv Date: 08/06/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/13/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004620183

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117314923

Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002616174GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 30
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Z157
NE
1/8-1/4
0.237 mi.
1252 ft.

NYSDOT
HAMILTON AVE & 16TH ST W WING
BROOKLYN, NY 11232

RCRA NonGen / NLR 1001080002
NY MANIFEST NYR000017095

Site 2 of 4 in cluster Z

Relative:
Higher

RCRA NonGen / NLR:

Actual:
12 ft.

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: NYSDOT
Facility address: HAMILTON AVE & 16TH ST W WING
BROOKLYN, NY 11232
EPA ID: NYR000017095
Mailing address: 21ST ST
LONG ISLAND CITY, NY 11101
Contact: SURIEL ZAYAS
Contact address: 21ST ST
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: 718-768-6880
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS DOT (Continued)

1001080002

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NYSDOT
Owner/operator address: 47-40 21ST ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: 718-768-6880
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYSDOT
Owner/operator address: 47-40 21ST ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: 718-768-6880
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: NYSDOT
Classification: Not a generator, verified

Date form received by agency: 1995-12-04 00:00:00.0
Site name: NYSDOT
Classification: Not a generator, verified

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS DOT (Continued)

1001080002

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 1997-08-26 00:00:00.0
Date achieved compliance: 1997-09-08 00:00:00.0
Violation lead agency: State
Enforcement action: NON-FINANCIAL RECORD REVIEW
Enforcement action date: 1997-08-26 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 1997-03-01 00:00:00.0
Evaluation: WRITTEN INFORMAL
Area of violation: Generators - Records/Reporting
Date achieved compliance: 1997-09-08 00:00:00.0
Evaluation lead agency: State

NY MANIFEST:

Name: NYS DOT
Address: HAMILTON AVE & 16TH ST W WING
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYR000017095
Facility Status: Not reported
Location Address 1: 3RD & HAMILTON
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYR000017095
Mailing Name: NYS DOT
Mailing Contact: DAMETRE LYTROCAPIS
Mailing Address 1: 703-709 3RD AVENUE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11232
Mailing Zip 4: Not reported
Mailing Country: USA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT (Continued)

1001080002

Mailing Phone: 7187686880

NY MANIFEST:

Document ID: PAE4314741
Manifest Status: C
seq: Not reported
Year: 1996
Trans1 State ID: PAAH0042
Trans2 State ID: Not reported
Generator Ship Date: 01/02/1996
Trans1 Recv Date: 01/02/1996
Trans2 Recv Date: / /
TSD Site Recv Date: 01/03/1996
Part A Recv Date: / /
Part B Recv Date: 01/17/1996
Generator EPA ID: NYR000017095
Trans1 EPA ID: PAD008781072
Trans2 EPA ID: Not reported
TSDF ID 1: PAD004835146
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 21180
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100

V158
South
1/8-1/4
0.237 mi.
1252 ft.
CON EDISON SERVICE BOX: 46943
169 25TH ST
BROOKLYN, NY 11232
Site 4 of 5 in cluster V

RCRA NonGen / NLR **1016965336**
NYP004382230

Relative: RCRA NonGen / NLR:
Higher Date form received by agency: 2013-11-29 00:00:00.0
Actual: Facility name: CON EDISON SERVICE BOX: 46943
20 ft. Facility address: 169 25TH ST
BROOKLYN, NY 11232

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 46943 (Continued)

1016965336

EPA ID: NYP004382230
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2013-10-29 00:00:00.0
Site name: CON EDISON SERVICE BOX: 46943
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

V159
South
1/8-1/4
0.237 mi.
1252 ft.

**CON EDISON
F/O # 169 25TH STREET
BROOKLYN, NY 11220**

**NY MANIFEST S116041909
N/A**

Site 5 of 5 in cluster V

**Relative:
Higher
Actual:
20 ft.**

NY MANIFEST:
Name: CON EDISON
Address: F/O # 169 25TH STREET
City,State,Zip: BROOKLYN, NY 11220
Country: USA
EPA ID: NYP004382248
Facility Status: Not reported
Location Address 1: F/O # 169 25TH STREET
Code: BP
Location Address 2: SERVICE BOX # 46943
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11220
Location Zip 4: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S116041909

NY MANIFEST:

EPAID: NYP004382248
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 10/29/2013
Trans1 Recv Date: 10/29/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/01/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004382248
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002237364GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 200
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S116041909

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

X160
SSE
1/8-1/4
0.238 mi.
1256 ft.

CON EDISON SERVICE BOX: 4320
115-17 E 23RD ST & 4TH AVE E OF
NEW YORK, NY 10011

RCRA NonGen / NLR
FINDS

1017773220
NYP004510004

Site 3 of 6 in cluster X

Relative:
Higher

RCRA NonGen / NLR:

Actual:
35 ft.

Date form received by agency: 2014-05-24 00:00:00.0
Facility name: CON EDISON SERVICE BOX: 4320
Facility address: 115-17 E 23RD ST & 4TH AVE E OF
NEW YORK, NY 10011
EPA ID: NYP004510004
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2014-04-24 00:00:00.0
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 2014-04-24 00:00:00.0
Site name: CON EDISON
Classification: Not a generator, verified

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 4320 (Continued)

1017773220

Violation Status: No violations found

FINDS:

Registry ID: 110063769783
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110063769783

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

**X161
SSE
1/8-1/4
0.238 mi.
1256 ft.**

**CON EDISON SERVICE BOX: 4324
127-29 E 23RD ST & 4TH AVE E OF
NEW YORK, NY 10010**

**RCRA NonGen / NLR
FINDS**

**1017773380
NYP004511606**

Site 4 of 6 in cluster X

**Relative:
Higher**

RCRA NonGen / NLR:

**Actual:
35 ft.**

Date form received by agency: 2014-05-25 00:00:00.0
Facility name: CON EDISON SERVICE BOX: 4324
Facility address: 127-29 E 23RD ST & 4TH AVE E OF
NEW YORK, NY 10010
EPA ID: NYP004511606
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 4324 (Continued)

1017773380

Historical Generators:

Date form received by agency: 2014-04-25 00:00:00.0

Site name: CON EDISON

Classification: Small Quantity Generator

Date form received by agency: 2014-04-25 00:00:00.0

Site name: CON EDISON

Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063774704

Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110063774704

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

X162
SSE
1/8-1/4
0.238 mi.
1256 ft.

CON EDISON SERVICE BOX: 4317
104 E 23RD ST & 4TH AVE E OF
NEW YORK, NY 10011

RCRA NonGen / NLR
FINDS

1017773222
NYP004510020

Site 5 of 6 in cluster X

Relative:
Higher

RCRA NonGen / NLR:

Actual:
35 ft.

Date form received by agency: 2014-05-24 00:00:00.0

Facility name: CON EDISON SERVICE BOX: 4317

Facility address: 104 E 23RD ST & 4TH AVE E OF
NEW YORK, NY 10011

EPA ID: NYP004510020

Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003

Contact: THOMAS TEELING

Contact address: Not reported

Contact address: Not reported

Contact country: Not reported

Contact telephone: 212-460-3770

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 4317 (Continued)

1017773222

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2014-04-24 00:00:00.0

Site name: CON EDISON

Classification: Small Quantity Generator

Date form received by agency: 2014-04-24 00:00:00.0

Site name: CON EDISON

Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063769809

Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110063769809

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

X163
SSE
1/8-1/4
0.238 mi.
1256 ft.

CON EDISON SERVICE BOX: 35058
313-21 4TH AVE & 23RD ST
NEW YORK, NY 10010

Site 6 of 6 in cluster X

RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

1016144075
NYP004268629

Relative:
Higher

RCRA NonGen / NLR:

Date form received by agency: 2017-07-28 00:00:00.0

Facility name: CON EDISON SERVICE BOX: 35058

Facility address: 313-21 4TH AVE & 23RD ST
NEW YORK, NY 10010

EPA ID: NYP004268629

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: RICARDO CARTY

Contact address: Not reported
Not reported

Contact country: Not reported

Contact telephone: 212-643-3044

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 35058 (Continued)

1016144075

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2012-09-14 00:00:00.0
Site name: CON EDISON SERVICE BOX: 35058
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055459980
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110055459980

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1016144075
Registry ID: 110055459980
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110055459980>
Name: CON EDISON SERVICE BOX: 35058
Address: 313-21 4TH AVE & 23RD ST
City,State,Zip: NEW YORK, NY 10010

NY MANIFEST:

Name: CON EDISON
Address: 313-21 4TH AVE & 23RD ST
City,State,Zip: NEW YORK, NY 10010
Country: USA
EPA ID: NYP004268629
Facility Status: Not reported
Location Address 1: FO 313 S PARK AVE
Code: BP

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 35058 (Continued)

1016144075

Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10010
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP004268629
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 09/14/2012
Trans1 Recv Date: 09/14/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/17/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268629
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010464478JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 35058 (Continued)

1016144075

Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AB164
NNE
1/8-1/4
0.239 mi.
1263 ft.

NYC DEP HAZ MAT
HAMILTON & SECOND AVE
BROOKLYN, NY 11232

NY MANIFEST **1009235748**
N/A

Site 1 of 2 in cluster AB

Relative:
Higher

NY MANIFEST:

Actual:
12 ft.

Name: NYC DEP HAZ MAT
Address: HAMILTON & SECOND AVE
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP003662343
Facility Status: Not reported
Location Address 1: HAMILTON & SECOND AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP003662343
Mailing Name: NYC DEP HAZ MAT
Mailing Contact: NICK LOAKNAUTH
Mailing Address 1: HAMILTON & SECOND AVE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11232
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

Document ID: NYG4658526
Manifest Status: Not reported
seq: Not reported
Year: 2005
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 05/17/2005
Trans1 Recv Date: 05/17/2005
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DEP HAZ MAT (Continued)

1009235748

TSD Site Recv Date: 05/19/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP003662343
Trans1 EPA ID: NY62758JS
Trans2 EPA ID: Not reported
TSD ID 1: NYD077444263
TSD ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00387
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

Z165
NE
1/8-1/4
0.241 mi.
1272 ft.

WHITE TOP
11-16 - 11-17
BROOKLYN, NY 11213
Site 3 of 4 in cluster Z

RCRA NonGen / NLR 1001028339
FINDS NYR000005710
ECHO

Relative:
Higher
Actual:
13 ft.

RCRA NonGen / NLR:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: WHITE TOP
Facility address: 11-16 - 11-17
BROOKLYN, NY 11213
EPA ID: NYR000005710
Contact: Not reported
Contact address: Not reported
NY
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WHITE TOP (Continued)

1001028339

Owner/Operator Summary:

Owner/operator name: VICIY DELINCE - NON-NOTIFIER
Owner/operator address: NOT REQUIRED
NOT REQUIRED, NY 99999
Owner/operator country: US
Owner/operator telephone: 718-774-6660
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: VICIY DELINCE - NON-NOTIFIER
Owner/operator address: NOT REQUIRED
NOT REQUIRED, NY 99999
Owner/operator country: US
Owner/operator telephone: 718-774-6660
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: WHITE TOP
Classification: Not a generator, verified

Date form received by agency: 1995-05-31 00:00:00.0
Site name: WHITE TOP
Classification: Not a generator, verified

Hazardous Waste Summary:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WHITE TOP (Continued)

1001028339

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

FINDS:

Registry ID: 110004514062
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004514062

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1001028339
Registry ID: 110004514062
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004514062>
Name: WHITE TOP
Address: 11-16 - 11-17
City,State,Zip: BROOKLYN, NY 11213

**Z166
NNE
1/8-1/4
0.241 mi.
1274 ft.**

**NYCDEP
16TH & HAMILTON AVE
BROOKLYN, NY 11201**

**NY MANIFEST 1009231588
N/A**

Site 4 of 4 in cluster Z

**Relative:
Higher**

NY MANIFEST:
Name: NYCDEP
Address: 16TH & HAMILTON AVE
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP000776542
Facility Status: Not reported
Location Address 1: 16TH & HAMILTON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

**Actual:
12 ft.**

NY MANIFEST:
EPAID: NYP000776542
Mailing Name: NYCDEP
Mailing Contact: CHARLES SMITH
Mailing Address 1: 16TH ST & HAMILTON AVE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11201

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCDEP (Continued)

1009231588

Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2125668977

NY MANIFEST:

Document ID: NYO2964609
Manifest Status: C
seq: Not reported
Year: 1983
Trans1 State ID: NY9A090
Trans2 State ID: Not reported
Generator Ship Date: 06/23/1983
Trans1 Recv Date: 06/23/1983
Trans2 Recv Date: / /
TSD Site Recv Date: 07/01/1983
Part A Recv Date: 07/11/2003
Part B Recv Date: 07/11/2003
Generator EPA ID: NYP000776542
Trans1 EPA ID: NYD080336241
Trans2 EPA ID: Not reported
TSDF ID 1: NYD080336241
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F001 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 01450
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

167
NE
1/8-1/4
0.246 mi.
1298 ft.

CONSOLIDATED EDISON
16TH ST & 3RD AVE
BROOKLYN, NY 11215

NY MANIFEST **1009239340**
N/A

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 16TH ST & 3RD AVE
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004060166
Facility Status: Not reported
Location Address 1: 16TH ST & 3RD AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004060166
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE0416448
Manifest Status: Not reported
seq: 01
Year: 2000
Trans1 State ID: 31877AJ
Trans2 State ID: Not reported
Generator Ship Date: 09/12/2000
Trans1 Recv Date: 09/12/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/13/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004060166
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

1009239340

Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00398
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

AA168
ENE
1/8-1/4
0.246 mi.
1301 ft.

CON EDISON
60 16TH ST
BROOKLYN, NY 11215
Site 2 of 3 in cluster AA

NY MANIFEST **S117061585**
N/A

Relative:
Higher
Actual:
27 ft.

NY MANIFEST:
Name: CON EDISON
Address: 60 16TH ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004538997
Facility Status: Not reported
Location Address 1: 60 16TH ST
Code: BP
Location Address 2: SB 46114
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004538997
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S117061585

seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 05/21/2014
Trans1 Recv Date: 05/21/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/23/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004538997
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID 1: NJD002200046
TSD ID 2: Not reported
Manifest Tracking Number: 013245598JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AA169
ENE
1/8-1/4
0.246 mi.
1301 ft.

CON EDISON SERVICE BOX: 46114
60 16TH ST
BROOKLYN, NY 11215
Site 3 of 3 in cluster AA

RCRA NonGen / NLR 1017776050
NYP004538997

Relative:
Higher

RCRA NonGen / NLR:

Actual:
27 ft.

Date form received by agency: 2014-06-21 00:00:00.0
Facility name: CON EDISON SERVICE BOX: 46114
Facility address: 60 16TH ST
BROOKLYN, NY 11215

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 46114 (Continued)

1017776050

EPA ID: NYP004538997
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2014-05-21 00:00:00.0
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 2014-05-21 00:00:00.0
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

Y170
East
1/4-1/2
0.258 mi.
1360 ft.

**609-619 4TH AVENUE
609 4TH AVENUE
NEW YORK CITY, NY**

Site 4 of 4 in cluster Y

**NY VCP S125317172
N/A**

**Relative:
Higher
Actual:
52 ft.**

VCP NYC:
Project ID: 16TMP0131M, 16EHAN126K, 17CVCP054K
Name: 609-619 4TH AVENUE
Address: 609 4TH AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AB171
NNE
1/4-1/2
0.267 mi.
1411 ft.
HAMILTON AVENUE INCINERATOR
555 HAMILTON AVE
BROOKLYN, NY 11232
Site 2 of 2 in cluster AB

SEMS-ARCHIVE
NY SWF/LF
NY Spills
NY MANIFEST
1000254641
NYD980768733

Relative:
Higher
Actual:
12 ft.

SEMS Archive:
Site ID: 0202241
EPA ID: NYD980768733
Name: HAMILTON AVENUE INCINERATOR
Address: 555 HAMILTON AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Cong District: 13
FIPS Code: 36047
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region: 02
Site ID: 0202241
EPA ID: NYD980768733
Site Name: HAMILTON AVENUE INCINERATOR
NPL: N
FF: N
OU: 00
Action Code: RS
Action Name: RV ASSESS
SEQ: 1
Start Date: Not reported
Finish Date: 2009-05-14 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 02
Site ID: 0202241
EPA ID: NYD980768733
Site Name: HAMILTON AVENUE INCINERATOR
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 2009-05-14 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 02
Site ID: 0202241
EPA ID: NYD980768733
Site Name: HAMILTON AVENUE INCINERATOR
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAMILTON AVENUE INCINERATOR (Continued)

1000254641

Start Date:	Not reported
Finish Date:	1983-10-01 04:00:00
Qual:	L
Current Action Lead:	St Perf
Region:	02
Site ID:	0202241
EPA ID:	NYD980768733
Site Name:	HAMILTON AVENUE INCINERATOR
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1983-09-01 04:00:00
Finish Date:	1983-09-01 04:00:00
Qual:	Not reported
Current Action Lead:	St Perf
Region:	02
Site ID:	0202241
EPA ID:	NYD980768733
Site Name:	HAMILTON AVENUE INCINERATOR
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1983-09-01 04:00:00
Finish Date:	1983-10-01 04:00:00
Qual:	H
Current Action Lead:	St Perf

SWF/LF:

Name:	NYCDOS MTS @ HAMILTON AVE.
Address:	500 HAMILTON AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Flag:	ACTIVE
Region Code:	2
Phone Number:	2128378030
Owner Name:	New York City Department of Sanitation
Owner Type:	Not reported
Owner Address:	125 Worth Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York City, NY 10013
Owner Email:	Not reported
Owner Phone:	6468854693
Contact Name:	Marshah-Reaff Barett
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	mabarett@dsny.nyc.gov
Contact Phone:	2124374516
Activity Desc:	Transfer station - permit

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAMILTON AVENUE INCINERATOR (Continued)

1000254641

Activity Number: [24T11]
Active: Yes
East Coordinate: 584605
North Coordinate: 4502526
Accuracy Code: Not reported
Regulatory Status: Permit
Waste Type: Not reported
Authorization #: 2-6102-00010/00013
Authorization Date: 10/13/2015
Expiration Date: 11/15/2018
Operator Name: Not reported
Operator Type: Not reported
Last Date: Not reported

SPILLS:

Name: NYC SANITATION CONSTRUCTION SITE
Address: 500 HAMILTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1102783 / 2011-06-24
Facility ID: 1102783
Facility Type: ER
DER Facility ID: 229863
Site ID: 450312
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2011-06-09
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2011-06-10
CID: Not reported
Water Affected: GOWANAS CANAL
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-06-10
Spill Record Last Update: 2011-06-24
Spiller Name: GREG BOROVSIS
Spiller Company: JH REID CONTRACTOR
Spiller Address: Not reported
Spiller Company: 999
Contact Name: GREG BOROVSIS
DEC Memo: "Spill of Hydraulic Oil from crane equipment into Gowanas Canal. Boom and pads put down. Cleanup complete."
Remarks: "spill into canal - cleanup done -"

All Materials:

Site ID: 450312
Operable Unit ID: 1200518
Operable Unit: 01
Material ID: 2196929

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAMILTON AVENUE INCINERATOR (Continued)

1000254641

Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Name: GOWONUS CANAL
Address: 500 HAMILTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1106759 / 2011-09-01
Facility ID: 1106759
Facility Type: ER
DER Facility ID: 229863
Site ID: 454444
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2011-09-01
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2011-09-01
CID: Not reported
Water Affected: GOWONUS CANAL
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-09-01
Spill Record Last Update: 2011-09-01
Spiller Name: JH REID CG
Spiller Company: JH REID CG
Spiller Address: 500 HAMILTON AVE
Spiller Company: 999
Contact Name: JH REID CG
DEC Memo: "1 gal spilled from excavator onto barge deck then dripped into water of canal. Booms were deployed and absorbants were put out on the water. Clean up is now completed. City DEP rep was on site and witnessed spill and cleanup."

Remarks: "Line failed and spilled into canal. Cleanup is in prgress."

All Materials:
Site ID: 454444
Operable Unit ID: 1204597
Operable Unit: 01
Material ID: 2201391
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAMILTON AVENUE INCINERATOR (Continued)

1000254641

Quantity: 1.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Name: TRANSFER STATION
Address: 500 HAMILTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9711052 / 2003-02-12
Facility ID: 9711052
Facility Type: ER
DER Facility ID: 229863
Site ID: 283400
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 1998-01-02
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 1998-01-02
CID: 369
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-01-02
Spill Record Last Update: 2003-02-12
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: VINCE MACDOUNNAH
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN Coast Guard On Scene. About 200 Gallons In Water02/12/2003-Closed Due To The Nature / Extent Of The Spill Report."

Remarks: "red liquid possibly transformer oil on premises of transfer station origin unknown-contained by sanitation co booms. "

All Materials:
Site ID: 283400
Operable Unit ID: 1057431
Operable Unit: 01
Material ID: 329317
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAMILTON AVENUE INCINERATOR (Continued)

1000254641

Oxygenate: Not reported

Name: GOWANUS CANAL
Address: 500 HAMILTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9711063 / 1997-12-02
Facility ID: 9711063
Facility Type: ER
DER Facility ID: 229863
Site ID: 283401
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 1998-01-02
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 1998-01-02
CID: 205
Water Affected: GOWANUS CANAL
Spill Source: Unknown
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-01-02
Spill Record Last Update: 1998-01-16
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: CALLER\\
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
MULQUEEN REF TO SPILL 97-11037"
Remarks: "unk petrol. on ground flowing to waterway. req call back a.s.a.p."

All Materials:

Site ID: 283401
Operable Unit ID: 1057441
Operable Unit: 01
Material ID: 329327
Material Code: 9999
Material Name: other -
Case No.: Not reported
Material FA: Other
Quantity: 200.00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:

Name: NYC DEPT SANITATION C/O SAFEWAY ENV

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAMILTON AVENUE INCINERATOR (Continued)

1000254641

Address: 500 HAMILTON AVE
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYD980768733
Facility Status: Not reported
Location Address 1: 500 HAMILTON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD980768733
Mailing Name: NYC DEPT SANITATION C/O SAFEWAY ENV
Mailing Contact: SCOTT WICKERS
Mailing Address 1: 1379 COMMERCE AVE
Mailing Address 2: Not reported
Mailing City: BRONX
Mailing State: NY
Mailing Zip: 10461
Mailing Zip 4: 3607
Mailing Country: USA
Mailing Phone: 7187944300

NY MANIFEST:

Document ID: NYH1478844
Manifest Status: Not reported
seq: Not reported
Year: 2005
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 09/13/2005
Trans1 Recv Date: 09/30/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/03/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980768733
Trans1 EPA ID: XS83704PA
Trans2 EPA ID: Not reported
TSDF ID 1: NYD049836679
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAMILTON AVENUE INCINERATOR (Continued)

1000254641

Waste Code: D008 - LEAD 5.0 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 07160
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

AC172
SSW
1/4-1/2
0.285 mi.
1503 ft.

ANTON JUNCIC ENTERPRISES, INC.
776 3RD AVENUE
BROOKLYN, NY 11232

NY SWF/LF
NY CBS
NY Spills

S105057939
N/A

Site 1 of 2 in cluster AC

Relative:
Higher
Actual:
11 ft.

SWF/LF:
Name: ANTON JUNCIC ENTERPRISES INC
Address: 776 3RD AVE
City,State,Zip: BROOKLYN, NY 11232
Flag: ACTIVE
Region Code: 2
Phone Number: 7187688884
Owner Name: Bernardo Juncic
Owner Type: Private
Owner Address: 776 3rd Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11232
Owner Email: junkman024@aol.com
Owner Phone: 7187688884
Contact Name: Bernardo Juncic
Contact Address: 776 3rd Avenue
Contact Addr2: Not reported
Contact City,St,Zip: Brooklyn, NY 11232
Contact Email: junkman024@aol.com
Contact Phone: 7187688884
Activity Desc: Vehicle Dismantling Facility
Activity Number: [7085636]
Active: Yes
East Coordinate: 584518
North Coordinate: 4501564
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Bernardo Juncic
Operator Type: Not reported
Laste Date: Not reported

CBS:

Name: ANTON JUNCIC ENTERPRISES, INC.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ANTON JUNCIC ENTERPRISES, INC. (Continued)

S105057939

Address: 776 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11232
CBS Number: 2-000433
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: 584456.52455
UTMY: 4501622.43894

SPILLS:

Name: ANTON JUNCIC ENTERPRISES (JUNK YARD)
Address: 776 3RD AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0102524 / 2014-06-04
Facility ID: 0102524
Facility Type: ER
DER Facility ID: 441158
Site ID: 167016
DEC Region: 2
Spill Cause: Deliberate
Spill Class: C3
SWIS: 2401
Spill Date: 2001-06-06
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 2001-06-06
CID: 211
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-06-06
Spill Record Last Update: 2014-06-04
Spiller Name: LT PARIS
Spiller Company: ANTON JUNCIC ENTERPRISES
Spiller Address: 776 3RD AV
Spiller Company: 001
Contact Name: LT PARIS
DEC Memo: "7/22/05: Closed out 9614390. Will clean up under this spill number.

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND PRIOR SPILL NUMBERS HERE - 9416269 9614390 6/7/2001 - Sangesland visited the site: Anton Juncic Ent. inc. (junk yard) with ECO Anthony Panipinto. The ground around the car dismantling area showed signs of petroleum pooling and saturation into the soil. Owners (brothers) Bernardo and Anton Jr. Juncic - 718-768-8884 Mr. Juncic presented drawings showing an oil/water separator which had been installed on the site in 1999. It is a buried unit with 2 stormwater drains leading into it. The water discharge goes into the NYC DEP sewer system. Oil is periodically pumped out of this unit and disposed of. Because the surface of the yard is soil (owner says it is cement 1' to 2' down) the rainwater had never been properly

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ANTON JUNICIC ENTERPRISES, INC. (Continued)

S105057939

directed into the 2 drains. DEC wrote a DO WORK letter (6/8/2001) directing Mr. Junicic to: 1) Excavate the site (soil/gravel) down to either clean soil or a solid barrier (old cement floor). Contact DEC for a site inspection. 2) If DEC inspection goes well, regrade the property and pour a new cement floor. Contour this floor so rainwater from the whole property flows to the proper drains. 3) Reconfirm that the water discharge from the oil/water separator is properly hooked up to the city sewer system in accordance with the regulations of the NYCDEP. 4) Design the property layout to allow access to the Blue Cover on the separator unit. 5) Maintain a log book for the drainage of the oil out of the separator unit. On future inspections, this information will be requested to provide that the separator system has been maintained. Submit a written plan and schedule of how this work will be performed. This plan is due to DEC by July 31, 2001. 7/11/2001 Sangesland went back to the site. Mr. Junicic is completing the required work in phases. Today the north 1/3 of the site had been cleared and excavated. Sangesland saw one hot spot which was removed while there. After today's inspection, an 8 to 10 reinforced cement slab was going to be poured and contoured over the full north 1/3 of the property. 8/14/2001 Sangesland (from the street) could see that the north 1/3 of the lot had been cemented and Mr. Junicic had redeployed much of his equipment over this area. It appears that he is clearing out the south west 1/3 of the site. I assume this will be done soon. 4/15/2002 Sangesland could see that 2/3 of the site had been paved over. Mr. Junicic said he would move the container boxes (used for storage) and would pave the remainder of the site soon. 3/30/2006 Requires a site visit to confirm that the whole lot has been paved over with cement. 8/26/08 - Raphael Ketani. I made a site visit at the request of Steve Sangesland, case manager. I met one of the workers who told me that the boss and the supervisor were both away from the shop. The worker called his boss who told him that it would be alright for me to look around. The shop is very overcrowded with car parts. I inspected the northern part of the site first. There was a small pile of soil and fill under a few cars. A spot of bare concrete was visible next to the pile of material and I had the impression that there actually was concrete under the material. Next, I viewed the back of the site. There was concrete everywhere in plain sight. Lastly, I viewed the southern part of the site. Here there was a depressed area with a sharp border, but which had a historical fill base. The entrance to this part of the shop had bare historical fill and comprised an area of about 800 to 1000 square feet. The worker I had met told me that they ordered the concrete, but they are waiting on a contractor to install it. After this, I left. 8/21/2013 Someone from spills needs to make a final visit to this site. It's a junk yard on Third Ave under the elevated hwy. It's an open lot between 2 buildings. Steve worked with the owners back in the 2001-2004 time frame to scrape up most of the lot and pour a cement base. They did 1 quarter of the lot at a time. They have completed 3/4 of the work. I never saw the rear/southern quarter completed. They have been inspected several times, but this final quarter has not been done. 05/27/14-Hiralkumar Patel. with approval from DEC DeMeo, case transferred from DEC Sangesland to DEC Patel. alternate address: 776-778 3rd Ave PBS #: 2-610070. as per PBS record, the site has one 275 gal waste oil AST in contact with impervious barrier. the tank was installed in July 2001. other spills : 9416269, 9614390 spill # 9416269 was reported on 03/6/1995 due to possible contamination at the site. case was closed and merged with 9614390. spill # 9614390

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ANTON JUNICIC ENTERPRISES, INC. (Continued)

S105057939

was reported on 03/12/1997 by NYPD due to petroleum contamination at the site. case closed and merged with 0102524. 06/04/14-Hiralkumar Patel. 10:30 AM:- visited site. found new concrete in visible areas in most of the site, except southwest corner, where broken asphalt was noted. found petroleum stains on concrete surface. site was full of auto parts. Anton Junicic Ent. Inc. Attn.: Bernardo 776 3rd Avenue Brooklyn, NY 11232 PH. (718) 768-8884 based on observations during site visit earlier today and information available to date, no further action needed and case closed."

Remarks:

""

All Materials:

Site ID: 167016
Operable Unit ID: 839240
Operable Unit: 01
Material ID: 534642
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 167016
Operable Unit ID: 839240
Operable Unit: 01
Material ID: 534644
Material Code: 0043A
Material Name: antifreeze
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 167016
Operable Unit ID: 839240
Operable Unit: 01
Material ID: 534643
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: JUNICIC
Address: 776 3RD AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9614390 / 2005-07-22
Facility ID: 9614390
Facility Type: ER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ANTON JUNICIC ENTERPRISES, INC. (Continued)

S105057939

DER Facility ID: 175143
Site ID: 118059
DEC Region: 2
Spill Cause: Deliberate
Spill Class: C3
SWIS: 2401
Spill Date: 1997-03-12
Investigator: JLDYBER
Referred To: Not reported
Reported to Dept: 1997-03-12
CID: 252
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Police Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1997-03-12
Spill Record Last Update: 2005-07-22
Spiller Name: SGT JOHN PAO
Spiller Company: JUNICIC
Spiller Address: 776 3RD AVE
Spiller Company: 001
Contact Name: SGT JOHN PAO
DEC Memo: "7/22/05, Dyber: Will clean up under spill 0102524. 7/19/05, Dyber: Steve Sangesland is managing another open spill (9614390) at this site. Left message for him to see if we can combine the spills. 7/13/05: Called precinct - Sgt. John Pao does not work there and they don't know him. Called the property owner, Bernardo Junicic (718-768-8884). He said that stained soil has been cleaned up and the junk yard is being paved. He will e-mail pictures and fax phone number of DEC person who witnessed construction if he can find card. Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE ECOs wrote tickets."

Remarks: "BUSINESS TAKES CARS APART-DURING AN INSPECTION BY THE PD IT WAS DISCOVERED THAT ABOVE PRODUCT HAD SATURATED THE GROUND REQ CALL BACK FROM DEC REP TO EITHER ABOVE # FOR SGT PAO OR #965-6341*****"

All Materials:

Site ID: 118059
Operable Unit ID: 1041814
Operable Unit: 01
Material ID: 339499
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 118059
Operable Unit ID: 1041814

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ANTON JUNICIC ENTERPRISES, INC. (Continued)

S105057939

Operable Unit: 01
Material ID: 339500
Material Code: 0021
Material Name: transmission fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: 776 3RD AVENUE
Address: 776 3RD AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9416269 / 1997-05-06
Facility ID: 9416269
Facility Type: ER
DER Facility ID: 175143
Site ID: 211293
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 1995-03-03
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1995-03-16
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-05-01
Spill Record Last Update: 2004-07-20
Spiller Name: Not reported
Spiller Company: ANTON JUNICIC ENTERPRISES
Spiller Address: 776 3RD AVENUE
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was M
TIBBE refer to 9614390."
Remarks: "GROUND OF FACILITY MAY BE CONTAMINATED WITH UNKNOWN OIL."

All Materials:
Site ID: 211293
Operable Unit ID: 1013538
Operable Unit: 01
Material ID: 371433
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ANTON JUNICIC ENTERPRISES, INC. (Continued)

S105057939

Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

AD173
South
1/4-1/2
0.294 mi.
1551 ft.

NYS DEC BUREAU OF SPILLS
737 4TH AVE
BROOKLYN, NY 11201

NY LTANKS
NY MANIFEST

S102672513
N/A

Site 1 of 5 in cluster AD

Relative:
Higher

Actual:
35 ft.

LTANKS:

Name: 737 4TH AVE
Address: 737 4TH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9402784 / 1994-05-26
Facility ID: 9402784
Site ID: 315150
Spill Date: 1994-05-26
Spill Cause: Tank Overfill
Spill Source: Gasoline Station or other PBS Facility
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 1994-05-26
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1994-06-08
Spill Record Last Update: 1999-09-30
Spiller Name: Not reported
Spiller Company: CITY GAS STATION
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 254075
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT 11/10/95 Original spill report looked up. (Caller remarks are blank) FD was on scene and spill cleaned."
""

Remarks:

All Materials:

Site ID: 315150
Operable Unit ID: 996589
Operable Unit: 01
Material ID: 382961
Material Code: 0009

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS DEC BUREAU OF SPILLS (Continued)

S102672513

Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:

Name: NYS DEC BUREAU OF SPILLS
Address: 737 4TH AVE
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP000955641
Facility Status: Not reported
Location Address 1: 737 4TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYP000955641
Mailing Name: NYS DEC BUREAU OF SPILLS
Mailing Contact: MARK TIBBS
Mailing Address 1: 47 40 21ST STREET
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7184824097

NY MANIFEST:

Document ID: NYG1626696
Manifest Status: Not reported
seq: 01
Year: 2003
Trans1 State ID: RK3196
Trans2 State ID: Not reported
Generator Ship Date: 09/10/2003
Trans1 Recv Date: 09/10/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/10/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP000955641
Trans1 EPA ID: NYD064743263
Trans2 EPA ID: Not reported
TSDF ID 1: NYD082785429
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS DEC BUREAU OF SPILLS (Continued)

S102672513

Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 00.99

AD174
South
1/4-1/2
0.295 mi.
1556 ft.

CITGO STATION
4TH AV & 25TH ST
SUNSET PARK, NY

Site 2 of 5 in cluster AD

NY LTANKS **S105054480**
N/A

Relative:
Higher

Actual:
30 ft.

LTANKS:
Name: CITGO STATION
Address: 4TH AV & 25TH ST
City,State,Zip: SUNSET PARK, NY
Spill Number/Closed Date: 9607556 / 2003-03-03
Facility ID: 9607556
Site ID: 279274
Spill Date: 1996-09-16
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 1996-09-16
CID: 349
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1996-09-16
Spill Record Last Update: 2003-03-03
Spiller Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CITGO STATION (Continued)

S105054480

Spiller Company: CITGO STATION
Spiller Address: 4TH AV & 25TH ST
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 226771
DEC Memo: ""
Remarks: "wouldnt fill to grade - ordered by dec chris tomesello "

All TTF:

Facility ID: 9607556
Spill Number: 9607556
Spill Tank Test: 1544756
Site ID: 279274
Tank Number: Not reported
Tank Size: 550
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 279274
Operable Unit ID: 1035657
Operable Unit: 01
Material ID: 346812
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AE175
East
1/4-1/2
0.295 mi.
1560 ft.
MOBIL R/S #11775
586 4TH AVENUE
BROOKLYN, NY 11215
Site 1 of 2 in cluster AE

NY LTANKS
NY UST
NY AST
NY Spills
U001838918
N/A

Relative:
Higher
Actual:
48 ft.
LTANKS:
Name: EXXONMOBIL
Address: 586 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8900734 / 1991-05-06
Facility ID: 8900734
Site ID: 77275

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Spill Date: 1989-04-24
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: B3
Cleanup Ceased: 1991-05-06
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1989-04-24
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1989-04-24
Spill Record Last Update: 2003-10-02
Spiller Name: MELISSA WINSOR
Spiller Company: EXXONMOBIL CORPORATION
Spiller Address: 3225 GALLOWES ROAD
Spiller County: 001
Spiller Contact: MELISSA WINSOR
Spiller Phone: (908) 474-3613
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 72133
DEC Memo: ""
Remarks: "550 GAL TANK NORMALLY USED FOR GAS. REMOVED GAS PRIOR TO TANK REPLACEMENT AND FILLED WITH WATER. WHILE EXCAVATING TANK DURING REPLACEMENT OPERATION CONTRACTOR POKED A HOLE IN THE TANK."

All TTF:

Facility ID: 8900734
Spill Number: 8900734
Spill Tank Test: 1535383
Site ID: 77275
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 77275
Operable Unit ID: 927305
Operable Unit: 01
Material ID: 452061

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: EXXONMOBIL
Address: 586 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9210276 / 1993-08-02
Facility ID: 9210276
Site ID: 77277
Spill Date: 1992-12-04
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: A3
Cleanup Ceased: 1993-08-02
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1992-12-04
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1992-12-08
Spill Record Last Update: 2003-10-02
Spiller Name: MELISSA WINSOR
Spiller Company: EXXONMOBIL CORPORATION
Spiller Address: 3225 GALLOWES ROAD
Spiller County: 001
Spiller Contact: MELISSA WINSOR
Spiller Phone: (908) 474-3613
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 72133
DEC Memo: ""
Remarks: "CHECKED OBVIOUS SIGNS ALSO CONTACTED ENVIRONMENTAL ENG TONY KAHOURY FROM MOBIL NO ONE CAN LOCATE SOURCE OF VAPORS"

All Materials:
Site ID: 77277
Operable Unit ID: 974515
Operable Unit: 01
Material ID: 403744
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Units: G
Recovered: .00
Oxygenate: Not reported

Name: MOBIL #17-E63
Address: 586 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0301750 / 2003-10-02
Facility ID: 0301750
Site ID: 154867
Spill Date: 2003-05-19
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2003-05-19
CID: 390
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-05-19
Spill Record Last Update: 2003-10-02
Spiller Name: MELISSA WINDSOR
Spiller Company: MOBIL #17-E63
Spiller Address: 3225 GALLOWS ROAD
Spiller County: 001
Spiller Contact: MELISSA WINDSOR
Spiller Phone: (908) 474-3613
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 72133
DEC Memo: ""
Remarks: "Caller reporting return of test results from a waste oil tank removed on 5/2/03 and there is ground contamination"

All Materials:

Site ID: 154867
Operable Unit ID: 869771
Operable Unit: 01
Material ID: 506238
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

UST:

Name: MOBIL R/S #11775
Address: 586 4TH AVENUE
City,State,Zip: BROOKLYN, NY 11215-5307
Id/Status: 2-157678 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585190.03919
UTM Y: 4502116.75609
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 5233
Affiliation Type: Facility Owner
Company Name: EXXONMOBIL OIL CORP
Contact Type: PERMITTING MANAGER
Contact Name: ERIC M. MCPHEE
Address1: 3225 GALLOWES RD.
Address2: Not reported
City: FAIRFAX
State: VA
Zip Code: 22037-0001
Country Code: 001
Phone: (703) 846-3000
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-06-05

Site Id: 5233
Affiliation Type: Mail Contact
Company Name: EXXONMOBIL OIL CORP
Contact Type: Not reported
Contact Name: ERIC M. MCPHEE
Address1: % VEEDER-ROOT CMS
Address2: 12265 W. BAYAUD AVE. #300
City: LAKEWOOD
State: CO
Zip Code: 80228
Country Code: 001
Phone: (303) 986-8011
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 5233
Affiliation Type: Facility Operator
Company Name: MOBIL R/S #11775
Contact Type: Not reported
Contact Name: STATION MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Zip Code: Not reported
Country Code: 001
Phone: (978) 465-9001
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 5233
Affiliation Type: Emergency Contact
Company Name: Not reported
Contact Type: Not reported
Contact Name: ENVIRONMENTAL HELP DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (800) 662-4567
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-08-06

Tank Info:

Tank Number: 001
Tank ID: 27650
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/2002
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Tank Number: 002
Tank ID: 27651
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1974
Date Tank Closed: 06/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 27652
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1974
Date Tank Closed: 06/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: 004
Tank ID: 27653
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1972
Date Tank Closed: 06/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 27654
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1957
Date Tank Closed: 06/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: 021
Tank ID: 27665
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 05/01/1989
Date Tank Closed: 02/01/2003
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 06/01/1999
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 022
Tank ID: 27666
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 05/01/1989
Date Tank Closed: 02/01/2003
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 06/01/1999

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 023
Tank ID: 27667
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 05/01/1989
Date Tank Closed: 02/01/2003
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 06/01/1999
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 024
Tank ID: 27668
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 05/01/1989
Date Tank Closed: 02/01/2003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 06/01/1999
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 025
Tank ID: 27669
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 05/01/1989
Date Tank Closed: 02/01/2003
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 06/01/1999
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
G04 - Tank Secondary Containment - Double-Walled (Underground)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Tank Number: 026
Tank ID: 27670
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 05/01/1989
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H04 - Tank Leak Detection - Groundwater Well
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 027
Tank ID: 27671
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 05/01/1989
Date Tank Closed: 02/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B04 - Tank External Protection - Fiberglass
D02 - Pipe Type - Galvanized Steel
H04 - Tank Leak Detection - Groundwater Well
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

I01 - Overfill - Float Vent Valve
F02 - Pipe External Protection - Original Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 028
Tank ID: 55996
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 05/01/1989
Date Tank Closed: 02/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: 14
Date Test: 07/01/1999
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B04 - Tank External Protection - Fiberglass
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
D00 - Pipe Type - No Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 030
Tank ID: 66052
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 05/02/2003
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

AST:

Name: MOBIL R/S #11775
Address: 586 4TH AVENUE
City,State,Zip: BROOKLYN, NY 11215-5307
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-157678
Program Type: PBS
UTM X: 585190.03919
UTM Y: 4502116.75609
Expiration Date: N/A
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 5233
Affiliation Type: Facility Owner
Company Name: EXXONMOBIL OIL CORP
Contact Type: PERMITTING MANAGER
Contact Name: ERIC M. MCPHEE
Address1: 3225 GALLOWS RD.
Address2: Not reported
City: FAIRFAX
State: VA
Zip Code: 22037-0001
Country Code: 001
Phone: (703) 846-3000
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-06-05

Site Id: 5233
Affiliation Type: Mail Contact
Company Name: EXXONMOBIL OIL CORP
Contact Type: Not reported
Contact Name: ERIC M. MCPHEE
Address1: % VEEDER-ROOT CMS
Address2: 12265 W. BAYAUD AVE. #300
City: LAKEWOOD
State: CO
Zip Code: 80228
Country Code: 001
Phone: (303) 986-8011
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 5233
Affiliation Type: Facility Operator
Company Name: MOBIL R/S #11775
Contact Type: Not reported
Contact Name: STATION MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (978) 465-9001
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 5233
Affiliation Type: Emergency Contact
Company Name: Not reported
Contact Type: Not reported
Contact Name: ENVIRONMENTAL HELP DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (800) 662-4567
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-08-06

Tank Info:

Tank Number: 006
Tank Id: 27655
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/01/2002
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 007
Tank Id: 27656
Material Code: 2642
Common Name of Substance: Used Oil (Heating, On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/01/2002
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: used oil (heating, on-site consumption)

Tank Number: 008
Tank Id: 27657
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed Prior to Micro Conversion, 03/91
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: other

Tank Number: 009
Tank Id: 27658
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed Prior to Micro Conversion, 03/91
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: other

Tank Number: 010
Tank Id: 27659

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Material Code: 9999
Common Name of Substance: Other

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed Prior to Micro Conversion, 03/91
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: other

Tank Number: 011
Tank Id: 27660
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed Prior to Micro Conversion, 03/91
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: other

Tank Number: 012
Tank Id: 27661
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed Prior to Micro Conversion, 03/91
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: other

Tank Number: 013
Tank Id: 27662
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.

Tank Type: Steel/Carbon Steel/Iron

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Tank Status: Closed Prior to Micro Conversion, 03/91
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: other

Tank Number: 014
Tank Id: 27663
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed Prior to Micro Conversion, 03/91
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: other

Tank Number: 015
Tank Id: 27664
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

Tank Location: I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed Prior to Micro Conversion, 03/91
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

SPILLS:

Name: EXXONMOBIL
Address: 586 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9006424 / 2014-09-16
Facility ID: 9006424
Facility Type: ER
DER Facility ID: 72133
Site ID: 77276
DEC Region: 2
Spill Cause: Unknown
Spill Class: A3
SWIS: 2401
Spill Date: 1990-09-11
Investigator: JXPerezM
Referred To: RA, ACT END DATE, 09/16/2014
Reported to Dept: 1990-09-12
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1990-09-12
Spill Record Last Update: 2014-09-17
Spiller Name: MELISSA WINSOR
Spiller Company: EXXONMOBIL OIL CO
Spiller Address: 3225 GALLOWES ROAD
Spiller Company: 001
Contact Name: MELISSA WINSOR
DEC Memo: "Spill Comments: 1. This spill case was reassigned from Rommel (DEC) to Perez (DEC) on 04/21/2005. 2. Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL . 3. This spill case was

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

reassigned from DEC (Sigona) to Rommel on 02/10/2004. 4. This spill site cleanup has been consolidated under Spill No. 9006424. 5. Reassigned from sullivan to sigona on 11/6/00. 6. PBS records indicate that 3 x 4,000 gallon and 11 x 550 gallon and 1 x 1,000 gallon USTs were closed or removed. 7. This spill case was reassigned from Sigona (DEC) to Perez (DEC) on 04/21/05. 08/30/2006 - RP's consultant sample the on-site soil gas points as outlined in the Feasibility Study (FS) the Investigation Work Plan A second round of soil gas samples will be taken by the end of the month (August 2006). RP continues to gauge and sample the on-site monitoring wells on a quarterly basis. By J. Perez. 11/10/2006 - RP submitted a Feasibility Study Report (FSR) and a supplemental subsurface investigation report. The FSR concluded that additional data would be required to assess the feasibility of implementing a full-scale system. By J. Perez. 01/15/2007 - DEC approved the Feasibility Study (FS) Report. The report recommends collection of additional data to develop full scale design or consider chemical oxidation as a remedial alternative. ExxonMobil will submit a supplemental FS work plan by early April. By J. Perez. 01/19/2007 - ExxonMobil submitted a site status update report and there is no major change in the concentration and distribution of the contaminants at the site. By J. Perez. 04/13/2007 - Exxonmobil submitted a Supplemental Feasibility Study & Investigation Report (SFSIR). (Perez) 04/19/2007 - ExxonMobil submitted a quarterly site status update report and there is no major change in the concentrations and the distribution of contaminants at the site. (Perez) 07/06/2007 - DEC approved the SFSIR. The report recommends collection of additional data in order to further evaluate the proposed system and consider other alternatives (i.e. chemical oxidation, ORC). (Perez) 03/10/2008 - Exxonmobil is conducting a subsurface investigation at the site and continues to gauge and sample the on-site monitoring wells on a quarterly basis. Exxonmobil's consultant were able to install one monitoring well and one monitoring point when an MTA inspector shut them down. Apparently they have new insurance requirements for 2008 and consultant, their subcontractor and the property owner did not have the right insurance. They have been working with the MTA and our insurance agent to make sure that everything is the way they want. (Perez) 06/04/2008 - Feasibility Study Report approved. ExxonMobil will submit a revised Remedial Action Plan (RAP) early July 2008. (Perez) 07/28/2008 - DEC approved the revised RAP. Implementation of RAP is scheduled to commence on October 2008. (Perez) 10/20/2008 - Consent Order (CO) was sent out to ExxonMobil for signature and should be returned by the end of the month. The CO will be necessary in order to commence with the implementation of the RAP. (Perez) 11/25/2008 - ExxonMobil sent the signed CO to the Department. MTA drilling issues were resolved, however, Exxonmobil is trying to resolve issues with the property owner. (Perez) 01/29/2009 - CO was executed by the Department. Exxonmobil is trying to resolve access issues with the property owner. (Perez) 03/26/2009 - This project was transfer to a new Klienfelder PM. ExxonMobil is trying to resolve access issues with the property owner. (Perez) 07/07/2009 - Delay is occurring while ExxonMobil tries to resolve access issues with the property owner. (Perez) 04/16/2010 - Construction of air sparge/extraction points on hold. During installation of points in the Western portion of the site consultant hit multiple refusals. ExxonMobil to change drilling technology, MTA has requested that EM monitor for vibration on the adjacent subway line. ExxonMobil is currently preparing a

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

vibration monitoring plan for MTA review and Approval. ExxonMobil continues to gauge and sample the on-site/off-site monitoring wells on a quarterly basis. (Perez) 05/24/2010 - Subway Vibration Monitoring plan approved by MTA. Construction of air sparge/extraction points to commence the week of May 23, 2010. ExxonMobil continues to gauge and sample the on-site/off-site monitoring wells on a quarterly basis. (Perez) 06/24/2010 - Construction of air sparge/soil vapor extraction system completed. System startup scheduled for June 25, 2010. ExxonMobil continues to gauge and sample the on-site/off-site monitoring wells on a quarterly basis. (Perez) 07/27/2010 - AS/SVE system is operational and being monitored for effectiveness. ExxonMobil continues to gauge and sample the on-site/off-site monitoring wells on a quarterly basis. (Perez) 08/26/2010 - AS/SVE system is operational(since June 2010) and being monitored for effectiveness. System performance/effectiveness will be reported on a quarterly basis. ExxonMobil continues to gauge and sample the on-site/off-site monitoring wells on a quarterly basis. (Perez) 11/30/2010 - Site update report results are consistent with historical data for the site. ExxonMobil continues to gauge and sample monitoring wells and report system performance/effectiveness on a quarterly basis. (Perez) 05/25/2011 - AS/SVE system is operational(since June 2010) and being monitored for effectiveness. Site update report revealed dissolved phase concentrations of benzene, toluene, ethylbenzene, and total xylenes (total BTEX) are generally consistent with prior quarters, showing a gradual decrease over time. ExxonMobil continues to gauge and sample monitoring wells and report system performance/effectiveness on a quarterly basis. (Perez) 07/26/2011 - AS/SVE system is operational. July 2011-Site Update Report revealed dissolved phase concentrations of total BTEX are generally consistent with prior quarters, showing a gradual decrease over time. Concentrations of MTBE have decreased compared to prior quarters. ExxonMobil continues to gauge and sample monitoring wells and report system performance/effectiveness on a quarterly basis. Next report to be submitted by October 2011.(Perez) 11/28/2011 - AS/SVE system is operational. October 2011 - Site Update Report revealed dissolved phase concentrations of total BTEX are the lowest (max. 2500 ppb) since sampling was initiated in the site. Concentrations of MTBE have decreased compared to prior quarters. ExxonMobil continues to gauge and sample monitoring wells and report system performance/effectiveness on a quarterly basis. Next report to be submitted by January 2012.(Perez) 02/23/2012 - Site transfer to Groundwater and Environmental (GES) consulting firm. GES will assume the role of remedial consultant for this spill. Awaiting for GES to discuss the Project. (Perez) 04/24/2012 - AS/SVE system is operational. October 2011 to December 2011- Site Update Report revealed dissolved phase concentrations of total BTEX are generally consistent with prior quarters, showing a gradual decrease over time. Concentrations of MTBE have decreased compared to prior quarters. ExxonMobil continues to gauge and sample monitoring wells and report system performance/effectiveness on a quarterly basis. Next report to be submitted by the end of April 2012. (Perez) 05/23/2012 - AS/SVE system is operational. January 2012 to March 2012- Site Update Report revealed dissolved phase concentrations of total BTEX are generally consistent with prior quarters, showing a gradual decrease over time. Concentrations of MTBE have decreased compared to prior quarters. ExxonMobil continues to gauge and sample monitoring wells and report system performance/effectiveness on a quarterly basis. Next report to

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

be submitted by the end of July 2012. (Perez) 08/13/2012 - AS/SVE system optimized to focus within the dissolved-phase plume area. Few air sparge wells were shut down to increase flow rate in certain wells. Additional adjustments may be made throughout the next reporting period to continue to focus on sparging near this area and GES will continue to monitor this sparging strategy to maximize hydrocarbon mass removal. (Perez) RP will to operate the system for a total of (6) six months on pulsing mode. After this time, a decision will be made whether to continue to operate the system or take further action. GES will continue to monitor this system to maximize hydrocarbon mass removal. (11-27-2012) AS/SVE system is operational (pulsing mode). October 2012 through December 2012 - Site Update Report revealed dissolved phase concentrations of total BTEX are generally consistent with prior quarters, showing a gradual decrease over time. RP will continue to monitor the system to maximize hydrocarbon mass removal. (01-28-2013) AS/SVE system is operational (pulsing mode). January 2013 through March 2013 - Site Update Report revealed dissolved phase concentrations of total BTEX are consistently decreasing (Max. 311.28PPB BTEX). RP consultant submitted a Site Investigation Work Plan for NYSDEC approval to determine the extent of residual soil impacts at the Site. Work plan is currently under review. RP will continue to monitor the system to maximize hydrocarbon mass removal. (04-25-2013) Fieldwork activities completed per approved site investigation work plan. RP submitted a site investigation report and it s currently under review. The investigation results reported concentrations of VOCs contaminated soils above soil cleanup guidance values between 10 and 30 feet below ground surface. No impacts reported in the groundwater interface. The RP recommendation in the report is to shutdown existing system and excavation of impacted soils. RP continues to gauge and sample monitoring wells and report system performance/effectiveness on a quarterly basis. (07-25-13) The Site Investigation Report and the request to shut down the AS/SVE system has been approved. The RP will submit a Remedial Action Plan (RAP) addendum to remove the AS/SVE system and a RAP for the excavation of impacted soils. After the approval of the RAP, the RP will initiate the system decommission and excavation activities. Upon the completion of the implementation of the approved RAP, groundwater will be monitored for a minimum of two quarters to ensure that groundwater contamination trends continues to decrease and rebound is not occurring at the site. After this time, a decision will be made whether to continue to monitoring the site or take further action. (08-28-13) The RP submitted a Remedial Action Plan Addendum and is currently under review by the Department. (09-26-13) DEC approved the Remedial Action Plan. The plan proposes excavation of remaining soil impacts at the site, between 10 and 30 feet below ground surface. ExxonMobil has been working on the permitting with NYCDOB, NYCDOT and MTA, but has encountered some setbacks as this is an E-Designated site. A permit has been filed with the NYCDOB, but since this is an E-Designated site, it appears that the permit will be processed through NYC Office of Environmental Remediation. (11-15-13) Fieldwork on hold pending to final approval of MTA permit. (12-19-13) RP still waiting on the MTA permit for this job. They have been backlogged and have taken a while to review RP s submittals. Late last week, they received comments on their last submittal and they are asking for revisions. They are planning on delivering the revisions this week. It s expected that they will be ready to proceed with the work early March; however, that is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL R/S #11775 (Continued)

U001838918

dependent on how quickly the MTA will review their latest submission. (02-25-14) Fieldwork activities completed per approved RAP. RP submitted a Closure Report and is under review by the Department. (08-13-2014) Comments on the Closure Report forwarded to the RP. (08-21-2014) The RP submitted a revised Closure Report and is currently under review by the Department. (09-11-2014) Spill closed on 09/16/2014. Groundwater analytical data collected over the past two years reveals that the concentration of the contaminants of concern in groundwater continues to naturally attenuate. During the source removal activities a total of approximately 2,010 tons of soil was removed from the excavation and disposed of off-site. Post-excavation soil samples reveals minor exceedances of NYSDEC RSCOs in 3 samples of 21 soil samples collected. However, the area above of the impacted soils was backfilled with clean material. Impact to groundwater is considered unlikely. There are no pathways considered complete or potential exposure to any identified sensitive receptors. Based on available documents, case closed. No further action letter sent to ExxonMobil. (09-17-14)"

Remarks:

"CONTAMINATED SOIL DISCOVERED DURING SITE ASSESSMENT, WILL COMPLETE ASSESSMENT."

All Materials:

Site ID: 77276
Operable Unit ID: 943922
Operable Unit: 01
Material ID: 433883
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

176
SW
1/4-1/2
0.298 mi.
1571 ft.

**BARGE: ELECTRA II/GOWANUS GAS TURBINES
THIRD AVENUE & 27TH STREET
BROOKLYN, NY 11232**

**NY MOSF S108413399
N/A**

**Relative:
Lower
Actual:
0 ft.**

MOSF:

Name: BARGE: ELECTRA II/GOWANUS GAS TURBINES
Address: THIRD AVENUE & 27TH STREET
City,State,Zip: BROOKLYN, NY 11232
Facility ID: 0-0772
Program Type: MOSF
Tank Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: Not reported
UTMY: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AF177
NW
1/4-1/2
0.304 mi.
1605 ft.
BUCKEYE TERMINALS, LLC - BROOKLYN TERMINAL
722 COURT STREET
BROOKLYN, NY 11231
Site 1 of 8 in cluster AF

NY MOSF
S108413283
N/A

Relative:
Lower

MOSF:

Actual:
3 ft.

Name: BUCKEYE TERMINALS, LLC - BROOKLYN TERMINAL
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY 11231
Facility ID: 2-1520
Program Type: MOSF
Tank Status: Active
Expiration Date: 03/31/2020
Dec Region: 2
UTMX: 584288.27645
UTMY: 4502485.63182

AF178
NW
1/4-1/2
0.304 mi.
1605 ft.
AMERADA HESS
722 COURT STREET
BROOKLYN, NY
Site 2 of 8 in cluster AF

NY LTANKS
NY Spills
S102147293
N/A

Relative:
Lower

LTANKS:

Actual:
3 ft.

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9500858 / 2003-08-11
Facility ID: 9500858
Site ID: 246738
Spill Date: 1995-04-20
Spill Cause: Tank Failure
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1995-04-20
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1995-05-12
Spill Record Last Update: 2003-08-11
Spiller Name: PETER HAID
Spiller Company: AMERADA HESS
Spiller Address: 1 HESS PLAZA
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 202598
DEC Memo: ""

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMERADA HESS (Continued)

S102147293

Remarks: "OLD PRODUCT FOUND IN WeLL DURING SAMPLING - NOT SAME AS PRODUCT IN ADJACENT TANKS - TANK O/S - REQUEST CALL BACK."

All Materials:

Site ID: 246738
Operable Unit ID: 1014983
Operable Unit: 01
Material ID: 369471
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9309813 / 1993-11-15
Facility ID: 9309813
Facility Type: ER
DER Facility ID: 202598
Site ID: 246734
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1993-11-12
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1993-11-12
CID: Not reported
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: 1993-11-15
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1993-11-19
Spill Record Last Update: 2004-04-07
Spiller Name: Not reported
Spiller Company: AMERADA HESS
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks: "CRACKED FITTING ON 275 GAL TANK. THEY DRAINED TANK INTO DRUMS. DIGGING UP CONTAMINATED SOIL - REPLACING FITTING."

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMERADA HESS (Continued)

S102147293

All Materials:

Site ID: 246734
Operable Unit ID: 991529
Operable Unit: 01
Material ID: 392464
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9812839 / 2003-08-11
Facility ID: 9812839
Facility Type: ER
DER Facility ID: 202598
Site ID: 138984
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1999-01-19
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1999-01-19
CID: 205
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-01-19
Spill Record Last Update: 2003-08-11
Spiller Name: CALLER
Spiller Company: AMERADA HESS
Spiller Address: 764 COURT ST
Spiller Company: 001
Contact Name: CALLER
DEC Memo: ""
Remarks: "CALLER REPORTED BROKEN FITTING ON TANK."

All Materials:

Site ID: 138984
Operable Unit ID: 1073288
Operable Unit: 01
Material ID: 313118
Material Code: 0001A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMERADA HESS (Continued)

S102147293

Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 30.00
Units: G
Recovered: .00
Oxygenate: Not reported

**AF179
NW
1/4-1/2
0.304 mi.
1605 ft.

Relative:
Lower**

**BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL
722 COURT ST
BROOKLYN, NY 11231

Site 3 of 8 in cluster AF**

**RCRA-SQG
NY LTANKS
NY MOSF UST
NY MOSF AST
NY Spills
NJ MANIFEST
NY MANIFEST**

**1000352824
NYD980651756**

**Actual:
3 ft.**

RCRA-SQG:
Date form received by agency: 2013-11-29 00:00:00.0
Facility name: BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL
Facility address: 722 COURT ST
BROOKLYN, NY 11231
EPA ID: NYD980651756
Mailing address: COURT ST
BROOKLYN, NY 11231
Contact: ADAM GADRA
Contact address: BUCKEYE RD
MACUNGIE, PA 18049
Contact country: US
Contact telephone: 610-904-4977
Contact email: AGADRA@BUCKEYE.COM
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: BUCKEYE TERMINALS LLC - BROOKLYN TERMINA
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2013-12-11 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2006-08-01 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: AMERADA HESS CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BUCKEYE TERMINALS LLC
Owner/operator address: HAMILTON BLVD
BREINIGSVILLE, PA 18031

Owner/operator country: US
Owner/operator telephone: 610-904-4000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2013-12-11 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2007-01-01 00:00:00.0
Site name: HESS CORPORATION

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Classification: Small Quantity Generator

Date form received by agency: 2006-08-01 00:00:00.0

Site name: HESS CORPORATION

Classification: Large Quantity Generator

Date form received by agency: 2006-07-31 00:00:00.0

Site name: HESS CORPORATION

Classification: Small Quantity Generator

Date form received by agency: 2004-04-19 00:00:00.0

Site name: AMERADA HESS BROOKLYN TERMINAL

Classification: Large Quantity Generator

Date form received by agency: 1999-07-08 00:00:00.0

Site name: AMERADA HESS CORP

Classification: Not a generator, verified

Date form received by agency: 1992-02-11 00:00:00.0

Site name: AMERADA HESS

Classification: Large Quantity Generator

Date form received by agency: 1982-11-29 00:00:00.0

Site name: AMERADA HESS CORP

Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: B001

. Waste name: PCB oil (concentrated) from transformers, capacitors, etc.

. Waste code: B006

. Waste name: PCB transformers. PCB transformers means any transformer that contains 500 ppm PCB or greater.

. Waste code: D001

. Waste name: IGNITABLE WASTE

. Waste code: D002

. Waste name: CORROSIVE WASTE

. Waste code: D006

. Waste name: CADMIUM

. Waste code: D007

. Waste name: CHROMIUM

. Waste code: D008

. Waste name: LEAD

. Waste code: D018

. Waste name: BENZENE

. Waste code: D035

. Waste name: METHYL ETHYL KETONE

. Waste code: F003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005

. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

LTANKS:

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0107145 / 2003-08-11
Facility ID: 0107145
Site ID: 138969
Spill Date: 2001-10-10
Spill Cause: Tank Failure
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2001-10-10
CID: 233
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-10-10
Spill Record Last Update: 2003-08-11
Spiller Name: PETER HAID
Spiller Company: AMERADA HESS '
Spiller Address: 722 COURT ST
Spiller County: 001
Spiller Contact: PETER HAID
Spiller Phone: (732) 750-7088
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 202598
DEC Memo: ""

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Remarks: "Caller was advised by DEC to report that staining was found near a large above ground storage tank No. 9414. "

All Materials:

Site ID: 138969
Operable Unit ID: 844211
Operable Unit: 01
Material ID: 531979
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0109487 / 2003-08-11
Facility ID: 0109487
Site ID: 138971
Spill Date: 2001-12-27
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2001-12-27
CID: 397
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-12-27
Spill Record Last Update: 2003-08-11
Spiller Name: HOWARD GOLDMAN
Spiller Company: AMERADA HESS
Spiller Address: 1 HESS PLAZA
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 202598
DEC Memo: ""
Remarks: "Discovered holes in tank. was originally discovered last friday adn additional holes have been found #0109349"

All Materials:

Site ID: 138971

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Operable Unit ID: 846754
Operable Unit: 01
Material ID: 527145
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0109620 / 2003-08-11
Facility ID: 0109620
Site ID: 138972
Spill Date: 2002-01-03
Spill Cause: Tank Failure
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2002-01-03
CID: 365
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-01-03
Spill Record Last Update: 2004-04-07
Spiller Name: HOWARD GOLDMAN
Spiller Company: AMERADA HESS
Spiller Address: 1 HESS PLAZA
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 202598
DEC Memo: ""
Remarks: "Identified 2 addition holes in the floor & they will further investigate"

All Materials:
Site ID: 138972
Operable Unit ID: 847971
Operable Unit: 01
Material ID: 527270
Material Code: 0003A
Material Name: #6 fuel oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: HESS STORAGE TERMINAL
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0207992 / 2003-07-17
Facility ID: 0207992
Site ID: 138978
Spill Date: 2002-11-01
Spill Cause: Tank Overfill
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2002-11-01
CID: 211
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-11-01
Spill Record Last Update: 2003-07-17
Spiller Name: Not reported
Spiller Company: HESS
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: PAUL MARINO
Spiller Phone: (732) 750-7105
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 202598
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
OD/SANGESLAND TERMINAL HAS A DRAIN FOR SPILL RECOVERY. DIESEL WENT TO
THE DRAIN AND THEN IT WAS CLEANED USING SPEEDY DRY. PAUL MARINO -
732-750-7105. ARS"

Remarks: "TYANK OVERFILLED AT LOADING RACK - SPILL CLEANED UP"

All Materials:
Site ID: 138978
Operable Unit ID: 860995
Operable Unit: 01
Material ID: 514995
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 59.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Units: G
Recovered: 59.00
Oxygenate: Not reported

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9102797 / 2003-08-11
Facility ID: 9102797
Site ID: 138981
Spill Date: 1991-06-10
Spill Cause: Tank Failure
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1991-06-10
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1991-07-01
Spill Record Last Update: 2003-08-11
Spiller Name: Not reported
Spiller Company: AMERADA HESS
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 202598
DEC Memo: ""
Remarks: "Product found in monitoring well at this site"

All Materials:

Site ID: 138981
Operable Unit ID: 953623
Operable Unit: 01
Material ID: 425284
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

MOSF UST:

Id/Status: 2-1520 / ACTIVE FACILITY
SWIS Code: 61
Facility Town: NEW YORK CITY
Contact Phone: (718) 330-1468
Emergency Contact: MIKE BROUGHAM
Emergency Telephone: (718) 330-1468
CBS Number: 2-000355
SPDES Num: 0-110001
Total Tanks: 10
Total Capacity: 29191558
Avg Throughput: 583000
License Stat: 1
Facility Type: STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Prod Xfer Options: AC
Expiration Date: 03/31/2002
Applic Rcvd: 01/05/2001
Operator: MIKE BROUGHAM
Owner Name: AMERADA HESS CORPORATION
Owner Address: 1 HESS PLAZA
Owner City,St,Zip: WOODBRIDGE, NJ 07095-
Owner Telephone: (732) 750-6000
Owner Type: Corporate/Commercial
Owner Status: 1
Owner Mark: First Owner
Mail To Name: AMERADA HESS CORPORATION
Mail To Address: 1 HESS PLAZA
Mail To Address 2: Not reported
Mail City,St,Zip: WOODBRIDGE, NJ 07095-
Mail To Contact: PETER HAID
Mail To Telephone: (732) 750-6000
Legal Agent Name: C.T. CORPORATION SYSTEM
Legal Agent Address: 277 PARK AVENUE
Legal Agent City,St,Zip: NEW YORK, NY 10017-
Date Filed: 02/20
Latitude: 40|40|1
Longitude: 74|00|2

Tank ID: 0P
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 72000
Product: EMPTY
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: None
Pipe Type: NONE
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: None
Dispenser: Not reported
Test Date: Not reported
Date Closed: 06/92

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Status of Data: Minor Errors
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 9401
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 179256
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner
Tank External: None
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: 24
Dispenser: Suction
Test Date: 10/84
Date Closed: 00/00
Status of Data: Complete
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 9402
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 250068
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner
Tank External: None
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: 24
Dispenser: Suction
Test Date: 10/84
Date Closed: 00/00
Status of Data: Complete
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 9403
Tank Location: UNDERGROUND
Install Date: 10/40
Capacity (Gal): 1378020
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: Groundwater Well
Overfill Protection: 24
Dispenser: Suction
Test Date: 12/00
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 9404
Tank Location: UNDERGROUND
Install Date: 10/40
Capacity (Gal): 1059366
Product: NOS 1,2, OR 4 FUEL OIL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: Groundwater Well
Overfill Protection: 24
Dispenser: Suction
Test Date: 12/00
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 9405
Tank Location: UNDERGROUND
Install Date: 10/40
Capacity (Gal): 1380372
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: Groundwater Well
Overfill Protection: 24
Dispenser: Suction
Test Date: 10/94
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Tank ID: 9409
Tank Location: UNDERGROUND
Install Date: 01/53
Capacity (Gal): 2281272
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: Groundwater Well
Overfill Protection: 24
Dispenser: Submersible
Test Date: 09/01
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 9410
Tank Location: UNDERGROUND
Install Date: 01/53
Capacity (Gal): 2281314
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: Groundwater Well
Overfill Protection: 24
Dispenser: Submersible
Test Date: 09/01
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 9416
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 5000
Product: NOS 5 OR 6 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: Other
Overfill Protection: None
Dispenser: Submersible
Test Date: Not reported
Date Closed: 00/00
Status of Data: Complete
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 9417
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 5000
Product: NOS 5 OR 6 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: Other
Overfill Protection: None
Dispenser: Submersible
Test Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Date Closed: 00/00
Status of Data: Complete
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 9516
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 5000
Product: NOS 5 OR 6 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: None
Dispenser: Suction
Test Date: Not reported
Date Closed: UNKWN
Status of Data: Complete
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 9517
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 5000
Product: NOS 5 OR 6 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Underground
Pipe Type: STEEL/IRON

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: None
Dispenser: Not reported
Test Date: Not reported
Date Closed: UNKWN
Status of Data: Minor Errors
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: A
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 54000
Product: EMPTY
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: None
Pipe Type: NONE
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: None
Dispenser: Not reported
Test Date: Not reported
Date Closed: 06/92
Status of Data: Minor Errors
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: B
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 54000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Product: EMPTY
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: None
Pipe Type: NONE
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: None
Dispenser: Not reported
Test Date: Not reported
Date Closed: 06/92
Status of Data: Minor Errors
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: C
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 54000
Product: EMPTY
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: None
Pipe Type: NONE
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: None
Dispenser: Not reported
Test Date: Not reported
Date Closed: 06/92
Status of Data: Minor Errors
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

COI Date: / /

Tank ID: D
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 54000
Product: EMPTY
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: None
Pipe Type: NONE
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: None
Dispenser: Not reported
Test Date: Not reported
Date Closed: 06/92
Status of Data: Minor Errors
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: E
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 54000
Product: UNKNOWN
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: None
Dispenser: Not reported
Test Date: Not reported
Date Closed: 12/91
Status of Data: Minor Errors
Inspected Date: 07/29/1997
Inspector Initials: AS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: F
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 54000
Product: UNKNOWN
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: None
Dispenser: Not reported
Test Date: Not reported
Date Closed: 12/91
Status of Data: Minor Errors
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: QR
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 72000
Product: EMPTY
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: None
Pipe Type: NONE
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Overfill Protection: None
Dispenser: Not reported
Test Date: Not reported
Date Closed: 06/92
Status of Data: Minor Errors
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: S
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 90000
Product: EMPTY
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: None
Pipe Type: NONE
Pipe Internal: None
Pipe External: None
Second Contain: None
Leak Detection: None
Overfill Protection: None
Dispenser: Not reported
Test Date: Not reported
Date Closed: 12/91
Status of Data: Minor Errors
Inspected Date: 07/29/1997
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/06/2001
Federal Id No: Not reported
COI Date: / /

MOSF AST:

MOSF Number: 2-1520
SWIS Code: 61
Facility Town: NEW YORK CITY
Facility Phone: (718) 330-1468
Emergency Contact Name: MIKE BROUGHAM
Emergency Contact Phone: (718) 330-1468
Total Tanks: 10
Total Capacity: 29191558

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Daily Throughput: 583000
License Status: 1
Facility Type: STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Product Transfer Operation: AC
Facility Status: IN SERVICE
Operator Name: MIKE BROUGHAM
Owner Name: AMERADA HESS CORPORATION
Owner Address: 1 HESS PLAZA
Owner City,St,Zip: WOODBRIDGE, NJ 07095-
Owner Phone: (732) 750-6000
Owner Type: Corporate/Commercial
Owner Status: 1
Owner Mark: First Owner
Mailing Name: AMERADA HESS CORPORATION
Mailing Address: 1 HESS PLAZA
Mailing Address 2: Not reported
Mailing City,St,Zip: WOODBRIDGE, NJ 07095-
Mailing Contact: PETER HAID
Mailing Phone: (732) 750-6000
Legal Agent Name: C.T. CORPORATION SYSTEM
Legal Agent Address: 277 PARK AVENUE
Legal Agent City,St,Zip: NEW YORK, NY 10017-
LIC Expires: 03/31/2002

Tank ID: 9411
Tank Location: ABOVEGROUND
Install Date: 01/69
Product: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: CATHODIC PROTECTION
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Secondary Containment: Prefabricated Steel Dike
Leak Detection: None
Overfill Protection: 24
Dispensing Mthd: Suction
Test Date: 07/98
Date Closed: Not reported
Status of Data: Complete
Capacity (gal): 4331880
Lat/Long: 40|40|1 / 74|00|2
Federal ID: Not reported
Inspected Date: 07/29/1997
Inspector: AS
Renew Date: 11/06/2001
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: In Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000355

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Pollution Discharge Elimination System Num: 0-110001
Date Legal Agent Filed with Secretary of State: 02/20

Tank ID: 9412
Tank Location: ABOVEGROUND
Install Date: 01/72
Product: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: CATHODIC PROTECTION
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Secondary Containment: Prefabricated Steel Dike
Leak Detection: None
Overfill Protection: 24
Dispensing Mthd: Suction
Test Date: 08/89
Date Closed: Not reported
Status of Data: Complete
Capacity (gal): 5988024
Lat/Long: 40|40|1 / 74|00|2
Federal ID: Not reported
Inspected Date: 07/29/1997
Inspector: AS
Renew Date: 11/06/2001
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: In Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000355
Pollution Discharge Elimination System Num: 0-110001
Date Legal Agent Filed with Secretary of State: 02/20

Tank ID: 9413
Tank Location: ABOVEGROUND
Install Date: 01/74
Product: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: CATHODIC PROTECTION
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Secondary Containment: Prefabricated Steel Dike
Leak Detection: None
Overfill Protection: 24
Dispensing Mthd: Suction
Test Date: 07/91

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Date Closed: Not reported
Status of Data: Complete
Capacity (gal): 4536210
Lat/Long: 40|40|1 / 74|00|2
Federal ID: Not reported
Inspected Date: 07/29/1997
Inspector: AS
Renew Date: 11/06/2001
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: In Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000355
Pollution Discharge Elimination System Num: 0-110001
Date Legal Agent Filed with Secretary of State: 02/20

Tank ID: 9414
Tank Location: ABOVEGROUND
Install Date: 00/77
Product: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: CATHODIC PROTECTION
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Secondary Containment: Prefabricated Steel Dike
Leak Detection: Double Bottom
Overfill Protection: 24
Dispensing Mthd: Suction
Test Date: 08/00
Date Closed: Not reported
Status of Data: Complete
Capacity (gal): 5945100
Lat/Long: 40|40|1 / 74|00|2
Federal ID: Not reported
Inspected Date: 07/29/1997
Inspector: AS
Renew Date: 11/06/2001
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: In Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000355
Pollution Discharge Elimination System Num: 0-110001
Date Legal Agent Filed with Secretary of State: 02/20

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Tank ID: 9415
Tank Location: ABOVEGROUND
Install Date: 00/00
Product: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: NONE
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: None
Secondary Containment: None
Leak Detection: None
Overfill Protection: 24
Dispensing Mthd: Suction
Test Date: Not reported
Date Closed: 00/00
Status of Data: Complete
Capacity (gal): 1080
Lat/Long: 40|40|1 / 74|00|2
Federal ID: Not reported
Inspected Date: 07/29/1997
Inspector: AS
Renew Date: 11/06/2001
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: In Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000355
Pollution Discharge Elimination System Num: 0-110001
Date Legal Agent Filed with Secretary of State: 02/20

Tank ID: 9418
Tank Location: ABOVEGROUND
Install Date: 07/90
Product: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 15
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: Jacketed
Secondary Containment: Concrete Dike
Leak Detection: None
Overfill Protection: 24
Dispensing Mthd: Gravity
Test Date: 07/90
Date Closed: Not reported
Status of Data: Complete
Capacity (gal): 10000
Lat/Long: 40|40|1 / 74|00|2

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Federal ID: Not reported
Inspected Date: 07/29/1997
Inspector: AS
Renew Date: 11/06/2001
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: In Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000355
Pollution Discharge Elimination System Num: 0-110001
Date Legal Agent Filed with Secretary of State: 02/20

SPILLS:

Name: AMERADA HESS BROOKLYN TER
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0104967 / 2001-08-10
Facility ID: 0104967
Facility Type: ER
DER Facility ID: 202598
Site ID: 246720
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2001-08-08
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 2001-08-08
CID: 204
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-08-08
Spill Record Last Update: 2004-04-07
Spiller Name: Not reported
Spiller Company: AMERADA HESS
Spiller Address: Not reported
Spiller Company: 999
Contact Name: HOWARD GOLDMAN
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
TIPPLE 08/10/2001 a line from a truck cleaning a tank at the terminal
was inadvertently disconnected while still full of oil. the spill
occured inside a bearmed area."

Remarks: "SPILL IS CONTAINED ON CONCRETE AND PLASTIC "

All Materials:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Site ID: 246720
Operable Unit ID: 843468
Operable Unit: 01
Material ID: 533448
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0304922 / 2003-08-11
Facility ID: 0304922
Facility Type: ER
DER Facility ID: 202598
Site ID: 246721
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: A3
SWIS: 2401
Spill Date: 2003-08-08
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2003-08-08
CID: 282
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-08-08
Spill Record Last Update: 2004-04-07
Spiller Name: PETE HAID
Spiller Company: AMERADA HESS
Spiller Address: 1 HESS PLAZA
Spiller Company: 001
Contact Name: PETE HAID
DEC Memo: ""
Remarks: "TANK No. 9412 has problem with secondary containment. The sheeting and bulkhead has begun to bow out. "

All Materials:

Site ID: 246721
Operable Unit ID: 873258
Operable Unit: 01
Material ID: 505767
Material Code: 0003A
Material Name: #6 fuel oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9008229 / 1990-10-31
Facility ID: 9008229
Facility Type: ER
DER Facility ID: 202598
Site ID: 246730
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 1990-10-29
Investigator: WILSON
Referred To: Not reported
Reported to Dept: 1990-10-29
CID: Not reported
Water Affected: GOWANUS BAY
Spill Source: Unknown
Spill Notifier: Federal Government
Cleanup Ceased: 1990-10-31
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1990-11-06
Spill Record Last Update: 2004-04-07
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "TUG CREW DISCOVERED SHEEN, USCG CALLED HESS, RETURNED CALL SAW NO SHEEN."

All Materials:
Site ID: 246730
Operable Unit ID: 948872
Operable Unit: 01
Material ID: 432063
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9100064 / 2003-08-11
Facility ID: 9100064
Facility Type: ER
DER Facility ID: 202598
Site ID: 246732
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 1991-04-02
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1991-04-02
CID: Not reported
Water Affected: GOWANUS BAY
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1991-04-16
Spill Record Last Update: 2003-08-11
Spiller Name: PETER HAID
Spiller Company: HESS
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "DURING TEST OF CARGO TRANSFER LINE FLANGE GASKET FAILED,FUEL SPRAYED INTO BAY,WILL APPLY 3M SWEEP."

All Materials:

Site ID: 246732
Operable Unit ID: 953590
Operable Unit: 01
Material ID: 426279
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9110635 / 1992-01-13
Facility ID: 9110635
Facility Type: ER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

DER Facility ID: 202598
Site ID: 246733
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 1992-01-13
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 1992-01-13
CID: Not reported
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: 1992-01-13
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1992-02-03
Spill Record Last Update: 2004-04-07
Spiller Name: Not reported
Spiller Company: AMERADA HESS
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks: "FUEL LEAKED ONTO TRUCK AND AND LOADING RACK DRAIN SYSTEM. CLEANUP COMPLETE."

All Materials:

Site ID: 246733
Operable Unit ID: 960643
Operable Unit: 01
Material ID: 419152
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 70.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0109732 / 2003-08-11
Facility ID: 0109732
Facility Type: ER
DER Facility ID: 202598
Site ID: 138973
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

SWIS: 2401
Spill Date: 2002-01-08
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2002-01-08
CID: 205
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-01-08
Spill Record Last Update: 2003-08-11
Spiller Name: Not reported
Spiller Company: ENTERPRIZE TRUCKING
Spiller Address: Not reported
Spiller Company: 001
Contact Name: CALLER
DEC Memo: ""
Remarks: "Driver failed to control filling chute. cleanup in progress."

All Materials:

Site ID: 138973
Operable Unit ID: 848093
Operable Unit: 01
Material ID: 527382
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 30.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS CORP
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0204594 / 2002-08-01
Facility ID: 0204594
Facility Type: ER
DER Facility ID: 202598
Site ID: 138974
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2002-07-31
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 2002-07-31
CID: 233
Water Affected: GOWANUS CANAL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-07-31
Spill Record Last Update: 2004-04-07
Spiller Name: HOWARD
Spiller Company: AMERADA HESS CORP --
Spiller Address: 1 HESS PLAZA
Spiller Company: 001
Contact Name: MICHAEL BROUGHAM
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
VOUGHT 8/1/02-VOUGHT-Spill is unrecoverable sheen. Source has been
stopped. Spill closed by Vought."

Remarks: "caller had replaced the bottom of a tank after the work was
completed the filled the tank w/ water from the canal to test it tank
passed the test they then tested the water to confirm it was not
contaminated water passed that test water started to be discharged to
the canal and a small sheen was noticed at this poit they are not
sure where the material is from the plan to test the water again and
replace the hose and try again tomorrow spill at this poit does not
seem to be recoverable "

All Materials:

Site ID: 138974
Operable Unit ID: 857336
Operable Unit: 01
Material ID: 518839
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS CORP
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0206505 / 2003-08-11
Facility ID: 0206505
Facility Type: ER
DER Facility ID: 202598
Site ID: 138975
DEC Region: 2
Spill Cause: Other
Spill Class: C3
SWIS: 2401
Spill Date: 2002-09-23
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2002-09-23

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

CID: 281
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-09-23
Spill Record Last Update: 2003-08-11
Spiller Name: HOWARD GOLDMAN
Spiller Company: AMERADA HESS CORP
Spiller Address: 1 HESS PLAZA
Spiller Company: 001
Contact Name: HOWARD GOLDMAN
DEC Memo: ""
Remarks: "TEST OF FIRE SUPPRESSION SYSTEM WAS PERFORMED AT ABOVE LOCATION TODAY AS REQUIRED BY LAW. FOAM THAT IS USED CONTAINS THE ABOVE MATERIAL. "

All Materials:

Site ID: 138975
Operable Unit ID: 859157
Operable Unit: 01
Material ID: 517111
Material Code: 0028A
Material Name: ethylene glycol
Case No.: 00107211
Material FA: Hazardous Material
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: HESS OIL TERMINAL
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0207382 / 2002-10-17
Facility ID: 0207382
Facility Type: ER
DER Facility ID: 202598
Site ID: 138976
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2002-10-17
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2002-10-17
CID: 211
Water Affected: GOWANUS CANAL
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-10-17
Spill Record Last Update: 2004-04-07
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: HOWARD GOLDMAN
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO/OD Notes: Called Howald Goldman of Amerada Hess Corporation (732-750-7004) on 10/17/2002. The terminal is constructing a new bulkhead for the oil terminal. While driving sheet metal piles into the gowanus bay, a sheen started to appear(Grey and very light). The construction has a DEC and Army Corp. permit. work has being done over a month and is first time noticed. NRC case number is 626479. The station deployed a boom on the water and threw out absorbents however the they are not working. Spill appears to be contained within boom. Station contact is Michael Broughm at 718 330 1468. ARS 10/17/02 TJD Demeo inspected site. Driving of sheet piles has disturbed contaminated sediment in canal. No spill has occurred."
Remarks: "DURING DRILLING FOR BULKHEAD A SHEEN WAS NOTICED ON WATER SURFACE - APPEARS PRODUCT WAS DISTURBED FROM BOTTOM OF WATER"

All Materials:

Site ID: 138976
Operable Unit ID: 858975
Operable Unit: 01
Material ID: 517975
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: HESS FACILITY
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0208217 / 2002-12-20
Facility ID: 0208217
Facility Type: ER
DER Facility ID: 202598
Site ID: 138979
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: A1
SWIS: 2401
Spill Date: 2002-11-07
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2002-11-07
CID: 390

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Water Affected: GOWANAS BAY
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-11-07
Spill Record Last Update: 2003-08-11
Spiller Name: PETER HAID
Spiller Company: AMERADA HESS
Spiller Address: HESS PLAZA
Spiller Company: 001
Contact Name: PETER HAID
DEC Memo: ""
Remarks: "Platform Adjacent to Bulkhead Construction at Tank No. 9412 Failed under Weight of 60 Ton Komatsu 410 Excavator."

All Materials:

Site ID: 138979
Operable Unit ID: 859741
Operable Unit: 01
Material ID: 565788
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8601539 / 1986-06-05
Facility ID: 8601539
Facility Type: ER
DER Facility ID: 202598
Site ID: 138980
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 1986-06-04
Investigator: SJMILLER
Referred To: Not reported
Reported to Dept: 1986-06-04
CID: Not reported
Water Affected: NONE POSS. GW
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: 1986-06-05
Cleanup Meets Std: True
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1986-07-02
Spill Record Last Update: 2004-04-07
Spiller Name: Not reported
Spiller Company: AMERADA HESS
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER 6/4/86: NO IMPACT TO WATER. DEC WILL INVESTIGATE."
Remarks: "SEAL BLEW ON PUMP DURING TRANSFER TO TANK TRUCK; PETRO TANK CLEANERS CLEANED UP SPILL WITH VAC TRUCK; SURFACE SOIL TO BE EXCAVATED."

All Materials:

Site ID: 138980
Operable Unit ID: 897816
Operable Unit: 01
Material ID: 478045
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 150.00
Units: L
Recovered: .00
Oxygenate: Not reported

[Click this hyperlink](#) while viewing on your computer to access
1 additional NY SPILL: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA Id: NYD980651756
Mail Address: 1 HESS PLAZA
Mail City/State/Zip: WOODBRIDGE 07095
Facility Phone: 2017506000
Emergency Phone: Not reported
Contact: Not reported
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: 000000

Manifest:

Manifest Number: NJA5288195
EPA ID: NYD980651756
Date Shipped: 01/31/2006
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/31/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDf Received Waste:	01/31/2006
TSDf EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03200621
Was Load Rejected:	WOODBIDGE 07095
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5244319
EPA ID:	NYD980651756
Date Shipped:	06/30/2005
TSDf EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/30/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 06/30/2005
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 07280525
Was Load Rejected: WOODBRIDGE 07095
Reason Load Was Rejected: Not reported

Manifest Number: NJA5114633
EPA ID: NYD980651756
Date Shipped: 11/12/2004
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 11/12/2004
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 11/12/2004
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 01110521

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Was Load Rejected: WOODBRIDGE 07095
Reason Load Was Rejected: Not reported

Manifest Number: 008921262JJK
EPA ID: NYD980651756
Date Shipped: 8/24/2012
TSDf EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: WOODBRIDGE 07095
Reason Load Was Rejected: Not reported

Waste:

Manifest Year: Not reported
Waste Code: D001
Hand Code: Not reported
Quantity: 110.00 gallons

Manifest Number: 003635401JJK
EPA ID: NYD980651756
Date Shipped: 4/20/2012
TSDf EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: WOODBRIDGE 07095
Reason Load Was Rejected: Not reported

Waste:

Manifest Year: Not reported
Waste Code: D001 F003 F005 D035
Hand Code: Not reported
Quantity: 300.00 Pounds

Manifest Number: 010406658JJK
EPA ID: NYD980651756
Date Shipped: 1/28/2013
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: WOODBRIDGE 07095
Reason Load Was Rejected: Not reported

Waste:

Manifest Year: Not reported
Waste Code: D001 F003 F005
Hand Code: Not reported
Quantity: 800.00 Pounds

Manifest Year: Not reported
Waste Code: D001 F003 F005 D035
Hand Code: Not reported
Quantity: 300.00 Pounds

Manifest Year: Not reported
Waste Code: D001
Hand Code: Not reported
Quantity: 20.00 Pounds

Manifest Year: Not reported
Waste Code: D001
Hand Code: Not reported
Quantity: 15.00 Pounds

NY MANIFEST:

Name: AMERADA HESS CORP
Address: 722 COURT ST
City,State,Zip: BROOKLYN, NY 11231-2119
Country: USA
EPA ID: NYD980651756
Facility Status: Not reported
Location Address 1: 722 COURT ST
Code: BP

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11231
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD980651756
Mailing Name: AMERADA HESS CORP
Mailing Contact: PAUL MARINO
Mailing Address 1: 1 HESS PLAZA
Mailing Address 2: Not reported
Mailing City: WOODBRIDGE
Mailing State: NJ
Mailing Zip: 07095
Mailing Zip 4: 0961
Mailing Country: USA
Mailing Phone: 7327507105

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 01/28/2013
Trans1 Recv Date: 01/28/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/28/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980651756
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010406658JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H061
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 800

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUCKEYE TERMINALS LLC - BROOKLYN TERMINAL (Continued)

1000352824

Units: P - Pounds
Number of Containers: 1
Container Type: CW - Wooden boxes
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Waste Code: D001
Waste Code 1_2: F003
Waste Code 1_3: F005
Waste Code 1_4: D035
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AF180 HESS BROOKLYN TERMINAL
NW 722 COURT ST
1/4-1/2 BROOKLYN, NY 11231
0.304 mi.
1605 ft. Site 4 of 8 in cluster AF

NY LTANKS S102141580
NY Spills N/A

Relative:
Lower

Actual:
3 ft.

LTANKS:
Name: HESS TERMINAL
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0310372 / 2003-12-10
Facility ID: 0310372
Site ID: 246722
Spill Date: 2003-12-08
Spill Cause: Tank Overfill
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2003-12-08
CID: 444
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-12-08
Spill Record Last Update: 2004-04-07
Spiller Name: HOWARD GOLDMAN
Spiller Company: HESS TERMINAL
Spiller Address: 722 COURT STREET
Spiller County: 001
Spiller Contact: HOWARD GOLDMAN
Spiller Phone: (732) 750-7004
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 202598
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Spill at Terminal Rack All Cleaned up on site"
Remarks: "Customer overfilled a compartment in the truck, and it is being cleaned up right now, it was contained in the loading rack area."

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

All Materials:

Site ID: 246722
Operable Unit ID: 878033
Operable Unit: 01
Material ID: 499232
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 30.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: BROOKLYN TERM.
Address: 722 COURT ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0910815 / 2010-01-06
Facility ID: 0910815
Facility Type: ER
DER Facility ID: 365444
Site ID: 423585
DEC Region: 2
Spill Cause: Human Error
Spill Class: C4
SWIS: 2401
Spill Date: 2010-01-06
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2010-01-06
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-01-06
Spill Record Last Update: 2010-01-06
Spiller Name: Not reported
Spiller Company: HESS
Spiller Address: Not reported
Spiller Company: 999
Contact Name: MIKE MATRI
DEC Memo: "Minor spill, contained and cleaned up.(sr)"
Remarks: "spill at loading rack/contained and cleaned"

All Materials:

Site ID: 423585
Operable Unit ID: 1179396
Operable Unit: 01
Material ID: 2173064

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Name: HESS TERMINAL
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9002896 / Not Reported
Facility ID: 9002896
Facility Type: ER
DER Facility ID: 202598
Site ID: 246729
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 1990-06-12
Investigator: MSHOQUE
Referred To: Not reported
Reported to Dept: 1990-06-13
CID: Not reported
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 5
Date Entered In Computer: 1990-06-13
Spill Record Last Update: 2019-09-17
Spiller Name: PETER HAID
Spiller Company: AMERADA HESS COMPANY
Spiller Address: 1 HESS PLAZA
Spiller Company: 001
Contact Name: Not reported
DEC Memo:

"02/29/13 - LZ The 01/26/12 report by EnviroTrac Ltd.(eDocs) notes that from October to December 2011, 0.86 gallon of LNAPL was recovered. Hess to continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. The next update report, which will summarize site activities from January 2012 through March 2012, will be submitted to NYSDEC in April 2012. 12/16/11 - LZ The October 2011 Report by EnviroTrac Ltd.(eDocs) notes that in July 2011 September 2011 30 monitoring wells were gauged and enhanced fluid recovery conducted on select wells. LNAPL (max): July: 0.29 feet (MW-13); August: 0.26 feet (RW-1); September: 1.01 feet (MW-13) LNAPL Recovered: 1.61 gallons (this monitoring period) LNAPL Recovered: 2,614 gallons (to date).Hess will to continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. The next update

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

report, which will summarize site activities from October 2011 through December 2011, will be submitted to NYSDEC in January 2012.

09-19-11- LZ The April - June 2011 Report in eDocs. The next report in October 30, 2011. 05/03/11 - LZ The Update Report, dated April 29, 2011 by EnvironTrac, summarizes remedial activities from January to March 2011(eDocs). Twenty nine monitoring wells and one recovery well were gauged monthly. Enhanced fluid recovery was performed weekly on selected wells. Total of 0.31 gallon of free product was recovered. Hess will continue monthly well gauging and weekly enhanced fluid recovery. In addition, Hess will explore other options of free product recovery. The next report will be submitted in July 2011.

01/20/11 - LZ The January 17, 2011 quarterly report (eDocs) shows that the facility conducts weekly vacuum enhanced fluid recovery. Slightly more than 1 gallon of free product was recovered. The next report will be submitted in April 2011. 11/2/10 - LZ The October 25, 2010 quarterly report (eDocs) shows that the facility conducts weekly vacuum enhanced fluid recovery. Slightly more than 0.2 gallon of free product was recovered. The highest thickness of free product was noted in MW-13 (0.25 foot). 11-2-10 - LZ The Update Report, dated July 30, 2010, by EnvironTrac, summarizes remedial activities from April through June 2010 (eDocs). Twenty nine monitoring wells and one recovery well were gauged monthly. Enhanced fluid recovery was performed weekly on selected wells. Total of 2,175 gallons of fluids were recovered, and 0.21 gallon of free product were recovered. Hess will continue monthly well gauging and weekly enhanced fluid recovery

05/12/10 - LZ The April 30th quarterly report (eDocs) shows that the facility conducts weekly vacuum enhanced fluid recovery. The highest thickness of free product was noted in RW-1 (0.93 foot). 01/28/10 - LZ Reviewed the EnviroTrac Ltd January 28, 2010 quarterly report (eDocs) containing recovery data from October 2009 through December 2009. The report shows that 1.79 gallons of free product were recovered during this period. The highest thickness of free product was in RW-1 (0.9 foot) and 10 wells of 30 total monitoring wells exhibited the presence of free product. 02/18/10 - LZ Reviewed the January 28, 2010 Remedial Action Plan (RAP)(eDocs) prepared by EnviroTrac Ltd. The RAP provides the status of remediation at the site and evaluates four methods that might be used to expedite the remedial process; excavation, chemical injection, groundwater treatment, and enhanced fluid recovery are assessed by their feasibilities and associated risks. Approved your recommendation that enhanced fluid recovery be continued since EnviroTrac Ltd asserts that only this remedial option does not compromise the integrity of storage tanks. NYSDEC requires that the frequency of enhanced fluid recovery be increased temporarily from twice a month to weekly. Starting March 1, 2010, the weekly events must be performed for at least six months. After this period, recovery data will be evaluated, and a future configuration of enhanced fluid recovery will be determined. 01/28/10 - LZ I received the January 28, 2010 quarterly report 9eDocs) containing recovery data. It is under review. 10/29/09 - LZ As a result of today's meeting between DEC and Ed Russo of Environtrac and Donald Bull of Hess-Woodbridge, by February 1, 2010, NYSDEC will receive a report on the extent of contamination and the evaluation of feasible options to expedite remediation in the area south of Tanks 9409 and 9410. 10/08/09 - LZ EnviroTrac e-mailed missing information about volume of recovered LNAPL (eDocs). 09/25/09 - LZ The September 16, 2009, Envirotrac report (eDocs) provides the results of monthly gauging of 29 monitoring wells and 1 recovery

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

well. Eleven wells exhibited LNAPL. in January, the maximum thickness was 0.55 foot (MW-8a); February - 2.16 feet (MW-13); March - 0.32 (RW-1); April - 0.56 foot (RW-1); May - 0.59 foot (MW-13); June - 0.84 foot (RW-1); July - 0.26 foot (MW-13); August - 1.15 feet (MW-13); and September - 0.31 foot (RW-1). No information about volume of recovered free-phase product (I e-mailed them requesting this information and a meeting on October 29th). The report was received with a delay because miscommunication between Hess and Envirotrac (this consultant replaced Delta Consultants, Inc). The next report before January 31, 2010. 03/10/08 - LZ During November 2007 - January 2008, 6,25 gallons of LNAPL were recovered, a Delta Consultants, Inc. quarterly report informs. Enhanced fluid recovery events were conducted twice a month at a number of monitoring wells that reveal the presence of free product. On November 13, 2007, the highest thickness of LNAPL was in MW-13 (0.67 feet) and in RW-1 (0.38 feet). On November 11, 2007, MW-13 revealed 0.77 feet of LNAPL and RW-1 0.33 feet. On January 9, 2008, MW-13 had 0.88 feet of free product and RW-1 had 0.29 feet of free product. Delta Consultants, Inc., propose continuation of bi-monthly recovery activities. 12/12/07 - Zielinski Delta Environmental Consultants' report covers August-October 2007 free product recovery activities. According to the report, 6.61 gallons of LNAPL were removed in this period. Since June 1998, when recovery system was installed, 2,518 gallons of LNAPL were recovered. Free product was detected in a number of wells: MW-8 (0.01 feet), MW-8A (0.14 feet), MW-13 (0.5 feet), RW-1 (0.26 feet), MW-15 (0.32 feet), MW-19 (0.05 feet), MW-17 (0.27 feet), and MW-20 (0.13 feet). Delta, on behalf of Hess, intends to continue twice-a-month operations using the enhanced fluid recovery system. 08/31/07 - Zielinski Delta Environmental Consultants, Inc., provides a report on remedial activities for May - July 2007. Total 5.56 gallons of LNAPL were recovered. In May, LNAPL was recovered from wells MW-8A 0.07 MW-13 0.08 feet, MW-17 0.17 feet, MW-20, 0.08 feet, RW-1 0.08 feet. In June, LNAPL was recovered from MW-8 0.07 feet, MW-8A 0.05 feet, MW-13 0.03 feet, MW-17 0.06 feet, MW-19 0.06 feet, MW-20, 0.07 feet, RW-1 0.40 feet. In July, LNAPL was recovered from MW-8 0.07 feet, MW-8A 0.12 feet, MW-11 0.11 feet, MW-13 0.39 feet, MW-14 0.28 feet, MW-15 0.08 feet, MW-20 0.16 feet, RW-1 0.15 feet. since 1990, 2,5411 gallons of free product were recovered. The next progress report will be submitted on December 8, 2007. 06/22/07 - Zielinski Delta Environmental Consultants, Inc., in its report of June 8, 2007, provides information on the quantity of LNAPL recovered during February- April 2007. Total of 5.36 gallons of LNAPL was pumped out from wells MW-8A, MW-13, MW-14, MW-20, and RW-1. Since June 1999, 2,506 gallons of free product have been recovered. The next progress report will be submitted on September 8, 2007. 03/21/07 - Zielinski A site status report, prepared by Delta Environmental Consultants, Inc., includes data collected during November 2006 to January 2007. LNAPL was recovered from wells MW-13, MW-17, RW-1. Free product was also found in MW-8, MW-8a, MW-11, MW-12, MW-13, MW-14, MW-19, MW-20. The next progress report will be submitted on June 8, 2007. 12/15/06 - Zielinski The Fourth Quarter STIP Agreement Progress Report, prepared by Hess Corporation, indicates that free product exists in Wells MW-13 and MW-8(RW1). The facility uses an enhanced fluid recovery system to remove LPH. Prior to Sept, 2004 data translation this spill Lead DEC Field was ZHAO This spill site has been consolidated under spill No. 9002896. 4/21/04 - This project is re-assigned to Zhao from Sigona. 06/29/12 - THIS SPILL CASE HAS BEEN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

TRANSFERRED TO SECTION B ON 06/29/12 AS DISCUSSED WITH RANDY AUSTIN 08/01/2012 V. Brevdo Received Update Report from Envirotrac covering period from April through June 2012 monitoring period. Report is dated July 31, 2012. Reviewed report. Brevdo 07/31/2013 V. Brevdo Received Update Report from Envirotrac covering period from April through June 2013 monitoring period. Report is dated July 31, 2013. Reviewed Report. E-mail from Joseph Rennie of Envirotrac: Dear Mr. Brevdo, Attached please find the Update Report for the above referenced Hess terminal. This report contains data collected from the April through June 2013 monitoring period. As per your earlier request, I will be compiling a CD with all the 2013 quarterly reports for this site later this year. If you have any questions regarding this report, please do not hesitate to contact Matt Butler (Hess) at (732) 750-6624. Sincerely, Joseph Rennie Project Manager Joseph Rennie - Project Manager - EnviroTrac Ltd. - 5 Old Dock Road, Yaphank NY 11980 631.924.3001 (Office) - 631.924.5001 (Fax) - joer@envirotrac.com 02/24/2014 - EnviroTrac submitted Update Report dated February 6, 2014. This report contains data collected from October through December 2013. The next update report, summarizing activities conducted from January through March 2014 will be submitted to NYSDEC in April 2014. VB 02/25/2014 - V. Brevdo Project Status: Hess Terminal, 722 Court Street, Brooklyn (Spill No. 9002896) This is active Hess Terminal and Major Oil Storage Facility (MOSF) with the storage capacity of more than 400,000 gallons of petroleum products. The facility is located on the northern bank of Gowanus Canal estuary, opposite to the Hamilton Avenue Marine Transfer Station, which is on the southern bank of canal. The spill case was opened due to an equipment failure: during construction a free product was found on the groundwater table on the site. Initial response included pumping of water/petroleum mixture into a tank track. Remediation of the site is implemented under the Stipulation Agreement executed on September 8, 1998. On February 24, 2014, EnviroTrac submitted Site Status Update Report for the Fourth Quarter of 2013 which contains remediation information and data collected from October through December 2013. On October 24 and November 19, 2013, EnviroTrac gauged 30 monitoring wells and conducted enhanced fluid recovery (EFR) events on three wells to recover detected free product LNAPL. A total volume of fluids recovered during fourth quarter of 2013 was 9,000 gallons, and total volume recovered to date is 628,839 gallons. Maximum thickness of LNAPL product varied from 0.18 feet in October 2013 to 0.66 feet in November 2013. Hess will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. The next update report, which will summarize site activities from January 2014 through March 2014 will be submitted to the Department in April 2014. 02/25/2014 - V. Brevdo Sent e-mail to Joseph Rennie of Envirotrack containing five (5) Comments-Questions on February 6, 2014 Site Status Update Report. VB. 03/03/2015 - V. Brevdo EnviroTrack submitted Update Reports dated 4/30/14; 07/31/14; 11/28/14; and 02/25/15. VB 03/10/2015 - V. Brevdo Project Status Update: Hess Terminal, 722 Court Street, Brooklyn (Spill No. 9002896) This is active Hess Terminal and Major Oil Storage Facility (MOSF) with the storage capacity of more than 400,000 gallons of petroleum products. The facility is located on the northern bank of Gowanus Canal estuary, opposite to the Hamilton Avenue Marine Transfer Station, which is on the southern bank of canal. The spill case was opened due to an equipment failure: during construction a free product - No. 6

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

fuel oil - was found on the groundwater table on the site. Initial response included pumping of water/petroleum mixture into a tank track. Remediation of the site is implemented under the Stipulation Agreement executed on September 8, 1998. On March 3, 2015, EnviroTrac submitted Site Status Update Report for the Fourth Quarter of 2014 which contains remediation information and data collected from October through December 2014. On October 30, November 18, and December 17, 2014, EnviroTrac gauged 30 monitoring wells and conducted enhanced fluid recovery (EFR) events on selected wells to recover detected free product LNAPL. A total volume of fluids recovered during fourth quarter of 2014 was 1,820 gallons, and total volume recovered to date is 655,545 gallons. Maximum thickness of LNAPL product varied from 0.42 feet in October 2014 to 1.85 feet in November 2014 and to 0.61 feet in December 2014. Hess will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. On March 10, 2015, the Department requested Hess and EnviroTrac to provide an estimated volume of LNAPL remaining in the subsurface as well as estimated time frame for the completion of LNAPL removal in the next April 2015 project update report. VB 05-01-2015 - V. Brevdo Hess Terminal, 722 Court Street, Brooklyn (Spill No. 9002896) This is active Hess Terminal and Major Oil Storage Facility (MOSF) with the storage capacity of more than 400,000 gallons of petroleum products. The facility is located on the northern bank of Gowanus Canal estuary, opposite to the Hamilton Avenue Marine Transfer Station, which is on the southern bank of canal. The spill case was opened due to an equipment failure: during construction a free product - No. 6 fuel oil - was found on the groundwater table on the site. Initial response included pumping of water/petroleum mixture into a tank track. Remediation of the site is implemented under the Stipulation Agreement executed on September 8, 1998. On April 30, 2015, EnviroTrac submitted Site Status Update Report for the First Quarter of 2015 which contains remediation information and data collected from January 2015 through March 2015. On January 26, February 23, and March 30, 2015, EnviroTrac gauged 30 monitoring wells and conducted enhanced fluid recovery (EFR) events on selected wells to recover detected free product LNAPL. A total volume of fluids recovered during first quarter of 2015 was 2,075 gallons, and total volume recovered to date is 657,620 gallons. Maximum thickness of LNAPL product varied from 0.25 feet in January 2015 to 0.21 feet in February 2015 and to 0.47 feet in March 2015. Hess and EnviroTrac will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. EnviroTrac will submit the update report for the second quarter of 2015 in July 2015. The Department communicated to EnviroTrac that shall they believe they can accomplish further reduction of the free product thickness at the site, they shall provide estimate and evaluation for methodology and time frame to complete the remedy. If it is not feasible to further reduce product thickness within reasonable time frame (one to two years from now), EnviroTrac shall evaluate whether environmental conditions accomplished so far are protective of the human health and the environment for the contemplated use of this property, in which case it may not be environmentally beneficial to continue keeping this spill case open. The Department is focused on completing the remedy and bringing this long term spill case to a closure status. VB 11-17-2015 - V. Brevdo Hess Terminal, 722 Court Street, Brooklyn (Spill No. 9002896) This is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

active Hess Terminal and Major Oil Storage Facility (MOSF) with the storage capacity of more than 400,000 gallons of petroleum products. The facility is located on the northern bank of Gowanus Canal estuary, opposite to the Hamilton Avenue Marine Transfer Station, which is on the southern bank of canal. The spill case was opened due to an equipment failure: during construction a free product - No. 6 fuel oil - was found on the groundwater table on the site. Initial response included pumping of water/petroleum mixture into a tank track. Remediation of the site is implemented under the Stipulation Agreement executed on September 8, 1998. On November 16, 2015, EnviroTrac submitted Site Status Update Report for the Third Quarter of 2015 which contains remediation information and data collected from July 2015 through September 2015. On July 23, August 25, and September 23, 2015, EnviroTrac gauged 30 monitoring wells and conducted enhanced fluid recovery (EFR) events on selected wells to recover detected free product LNAPL. A total volume of fluids recovered during third quarter of 2015 was 1,605 gallons, and total volume recovered to date is 660,245 gallons. Maximum thickness of LNAPL product varied from 0.57 feet in July 2015 to 0.44 feet in August 2015 and to 0.51 feet in September 2015. Hess and EnviroTrac will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. EnviroTrac will submit the update report for the fourth quarter of 2015 in January 2016. VB 02-12-2016 - V. Brevdo On February 12, 2016, EnviroTrac submitted Site Status Update Report for the Fourth Quarter of 2015 which contains remediation information and data collected from October 2015 through December 2015. On October 28, November 24, and December 16, 2015, EnviroTrac gauged 27 monitoring wells and conducted enhanced fluid recovery (EFR) events on selected wells to recover detected free product LNAPL. A total volume of fluids recovered during fourth quarter of 2015 was 3,038 gallons, and total volume recovered to date is 663,283 gallons. Maximum thickness of LNAPL product varied from 0.78 feet in December 2015 to 0.51 feet in October 2015 and to 0.46 feet in November 2015. Hess and EnviroTrac will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. EnviroTrac will submit the update report for the first quarter of 2016 in April 2016. 05-31-2016 - V. Brevdo On May 31, 2016, EnviroTrac submitted Site Status Update Report for the First Quarter of 2016 which contains remediation information and data collected from January 2016 through March 2016. On January 29, February 22, and March 18, 2016, EnviroTrac gauged 20 to 30 monitoring wells and conducted enhanced fluid recovery (EFR) events on selected wells to recover detected free product LNAPL. A total volume of fluids recovered during first quarter of 2016 was 2,621 gallons, and total volume recovered to date is 665,904 gallons. Maximum thickness of LNAPL product varied from 0.35 feet in January 2016 to 0.65 feet in February 2016 and to 0.19 feet in March 2016. Hess and EnviroTrac will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. VB 08-03-2016 - V. Brevdo On August 3, 2016, EnviroTrac submitted Site Status Update Report for the Second Quarter of 2016 which contains remediation information and data collected from April 2016 through June 2016. On April 18, May 18, and June 29, 2016, EnviroTrac gauged 20 to 30 monitoring wells and conducted enhanced fluid recovery (EFR) events on selected wells to recover detected free product LNAPL. A total volume of fluids recovered during second quarter of 2016 was

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

1,470 gallons, and total volume recovered to date is 667,374 gallons. Maximum thickness of LNAPL product varied from 0.20 feet in April 2016 to 0.22 feet in May 2016 and to 0.33 feet in June 2016. Hess and EnviroTrac will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. VB 11-17-2016 - V. Brevdo Former Hess Terminal Active Buckeye Terminal, 722 Court Street, Brooklyn (Spill No. 9002896) This is active Buckeye Terminal and Major Oil Storage Facility (MOSF) with the storage capacity of more than 400,000 gallons of petroleum products. The facility is located on the northern bank of Gowanus Canal estuary, opposite to the Hamilton Avenue Marine Transfer Station, which is on the southern bank of canal. The spill case was opened due to an equipment failure: during construction a free product - No. 6 fuel oil - was found on the groundwater table on the site. Initial response included pumping of water/petroleum mixture into a tank track. Remediation of the site is implemented under the Stipulation Agreement executed on September 8, 1998. As of September 2016, Rubicon Environmental, LLC (Rubicon) has taken over project management responsibilities for this project from EnviroTrac. On November 16, 2016, Rubicon submitted Site Status Update Report for the Third Quarter of 2016 which contains remediation information and data collected from July 2016 through September 2016. On July 14, August 22, and September 20, 2016, EnviroTrac gauged 28 monitoring wells and conducted enhanced fluid recovery (EFR) events on selected wells to recover detected free product LNAPL. A total volume of fluids recovered during third quarter of 2016 was 2,128 gallons, and total volume recovered to date is 669,502 gallons. Maximum thickness of LNAPL product varied from 1.09 feet in July 2016 to 0.40 feet in August 2016 and to 0.13 feet in September 2016. Hess and Rubicon will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. VB 02-28-2017 - V. Brevdo On February 24, 2017, Rubicon submitted Site Status Update Report for the Fourth Quarter of 2016 which contains remediation information and data collected from October 2016 through December 2016. On October 17, November 15, and December 16, 2016, Rubicon gauged 29 monitoring wells and conducted enhanced fluid recovery (EFR) events on selected wells to recover detected free product LNAPL. A total volume of fluids recovered during fourth quarter of 2016 was 2,909 gallons, and total volume recovered to date is 672,411 gallons. Maximum thickness of LNAPL product varied from 0.10 feet in October 2016 to 0.10 feet in November 2016 and to 0.35 feet in December 2016. Hess and Rubicon will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. VB 05-09-2017 - V. Brevdo On May 8, 2017, Rubicon submitted Site Status Update Report for the First Quarter of 2017 which contains remediation information and data collected from January 2017 through March 2017. On January 12, February 27, and March 22, 2017, Rubicon gauged 29 monitoring wells and conducted enhanced fluid recovery (EFR) events on one well to recover detected free product LNAPL. A total volume of fluids recovered during first quarter of 2017 was 3,853 gallons, and total volume recovered to date is 676,264 gallons. Maximum thickness of LNAPL product varied from 0.28 of a foot in January 2017 to 0.03 of a foot in February 2017 and to 0.05 of a foot in March 2017. Hess and Rubicon will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. VB 07-27-2017 - V. Brevdo On July 27, 2017, Rubicon submitted Site Status Update Report

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

for the Second Quarter of 2017 which contains remediation information and data collected from April 2017 through June 2017. On April 19, May 18, and June 21, 2017. Rubicon gauged 29 monitoring wells and conducted enhanced fluid recovery (EFR) events on selected wells to recover detected free product LNAPL. A total volume of fluids recovered during second quarter of 2017 was 5,458 gallons, and total volume recovered to date is 681,722 gallons. Maximum thickness of LNAPL product varied from 0.22 of a foot in April 2017 to 0.04 of a foot in May 2017 and to 0.08 of a foot in June 2017. Hess and Rubicon will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. VB 10-26-2017 - V. Brevdo On October 25, 2017, Rubicon submitted Site Status Update Report for the Third Quarter of 2017 which contains remediation information and data collected from July 2017 through September 2017. On July 19, August 23, and September 12, 2017, Rubicon gauged 29 monitoring wells and conducted enhanced fluid recovery (EFR) events on selected wells to recover detected free product LNAPL. A total volume of fluids recovered during third quarter of 2017 was 4,635 gallons, and total volume recovered to date is 686,357 gallons. Maximum thickness of LNAPL product varied from 0.22 of a foot in July 2017 to 0.07 of a foot in August 2017 and to 0.12 of a foot in September 2017. Hess and Rubicon will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. VB 02-21-2018 - V. Brevdo Former Hess Terminal Active Buckeye Terminal, 722 Court Street, Brooklyn (Spill No. 9002896) This is active Buckeye Terminal and Major Oil Storage Facility (MOSF) with the storage capacity of more than 400,000 gallons of petroleum products. The facility is located on the northern bank of Gowanus Canal estuary, opposite to the Hamilton Avenue Marine Transfer Station, which is on the southern bank of canal. The spill case was opened due to an equipment failure: during construction a free product - No. 6 fuel oil - was found on the groundwater table on the site. Initial response included pumping of water/petroleum mixture into a tank track. Remediation of the site is implemented under the Stipulation Agreement executed on September 8, 1998. As of September 2016, Rubicon Environmental, LLC (Rubicon) has taken over project management responsibilities for this project from EnviroTrac. On February 15, 2017, Rubicon submitted Site Status Update Report for the Fourth Quarter of 2017. Rubicon gauged monitoring wells and conducted enhanced fluid recovery (EFR) events to recover free product LNAPL - on October 18, 2017, November 21, 2017 and December 11, 2017. A total volume of fluids recovered during 4th quarter of 2017 was 3,685 gallons, and total volume recovered to date is 690,042 gallons. Maximum thickness of LNAPL product varied from 0.04 ft. to 0.06 ft. Hess and Rubicon will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain product. VB 05-09-2018 - V. Brevdo Former Hess Terminal Active Buckeye Terminal, 722 Court Street, Brooklyn (Spill No. 9002896) On May 3, 2017, Rubicon submitted Site Status Update Report for the First Quarter of 2018. Rubicon gauged monitoring wells and conducted enhanced fluid recovery (EFR) events to recover free product LNAPL - on January 25, 2018, February 20, 2018 and March 27, 2018. A total volume of fluids recovered during 1st quarter of 2018 was 5,818 gallons, and total volume recovered to date is 695,860 gallons. Maximum thickness of LNAPL product varied from 0.08 ft. to 0.35 ft. Hess and Rubicon will continue monthly well gauging and EFR events with the installation of absorbent socks in wells that contain

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

product. VB 11/6/2018-M.Hoque: 3rd quarter 2018 GW monitoring report received on 11/6/2018. The report is being reviewed. MDH 12/04/2018-M.Hoque: Report review completed. On November 6, 2018, Rubicon submitted a Site Status Update Report for the Third Quarter of 2018. Rubicon gauged 29 monitoring wells and one recovery well, and conducted enhanced fluid recovery (EFR) events in July, August and September 2018 to recover free product. During this period, they replaced sorbent socks in three wells. A total 5,538 gallons of fluids were recovered during the third quarter of 2018, bringing the total volume of fluids recovered to date to 706,253 gallons. The maximum product thickness varied from 0.07 to 0.11 foot. Hess and Rubicon will continue monthly well gauging and EFR events, with installation and maintenance of absorbent socks in wells with free product. The next well gauging and VEFR events are scheduled for October through December 2018, with the results submitted to DEC in the upcoming months. MDH 2/5/2019-M.Hoque: The 4th 2018 Quarter gauging/monitoring report received and is being reviewed. MDH 3/11/2019-M.Hoque: Report review completed. On February 5, 2019, Rubicon submitted a Site Status Update Report for the 4th Quarter of 2018. Rubicon gauged 29 monitoring wells and one recovery well, and conducted vacuum-enhanced fluid recovery (VEFR) in October, November and December 2018. Rubicon replaced absorbent socks in one well. A total of 5,582 gallons of fluids were recovered during the quarter, bringing the total volume recovered to date to 711,835 gallons. Maximum product thicknesses varied from 0.05 foot to 0.22 foot. Hess and Rubicon will continue monthly well gauging and VEFR, with the next events scheduled for January through March 2019. MDH 5/24/2019-M.Hoque: 1st Quarter 2019 monitoring report received and is being reviewed. (MDH) 6/18/2019-M.Hoque: Report review completed. On June 18, DEC reviewed a 1st Quarter of 2019 Site Status Update Report. Rubicon gauged 29 monitoring wells and conducted vacuum-enhanced fluid recovery (VEFR) on three wells(RW-1, MW-13 and MW-14) in January through March of 2019. Rubicon replaced absorbent socks in three wells(RW-1, MW-13, and MW-14). A total of 4,297 gallons of fluids were recovered during this quarter, bringing the total volume recovered to date to 716,132 gallons. Product thicknesses ranged from sheen to 0.28 foot(MW-13). Hess and Rubicon will continue monthly well gauging and VEFR, with the next events scheduled for April through June 2019. (MDH) 8/6/2019-M.Hoque: 2nd Quarter 2019 well gauging and monitoring report received and is being reviewed. -MDH 8/20/2019-M.Hoque: 2nd quarter 2019 well gauging and monitoring report review completed. On August 20, 2019, I reviewed a 2nd Quarter 2019 Site Status Update Report. Rubicon gauged 29 monitoring wells(MW-1 through MW-26, MW-8a through MW-8c and RW-1)and conducted vacuum-enhanced fluid recovery (VEFR) on three wells(RW-1, MW-13 and MW-14) from April through June of 2019. Rubicon replaced absorbent socks in two wells(RW-1 and MW-13). A total of 4,267 gallons of fluids (oil and water) were recovered during this quarter, bringing the total volume recovered to date to 720,399 gallons. At about 480.3 gallons of product recovered to date. Product thicknesses ranged from a sheen to 0.97 foot. Hess and Rubicon will continue monthly well gauging and VEFR, with the next events scheduled for July through September 2019.(MDH)"

Remarks: "DURING CONSTRUCTION FREE PRODUCT ON GROUNDWATER ON SITE PUMPING WATER/PETROLEUM PRODUCT IN TANK TRUCK"

All Materials:
Site ID:

246729

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

Operable Unit ID: 943016
Operable Unit: 01
Material ID: 437621
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERADA HESS TERMINAL
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9414375 / 2003-08-11
Facility ID: 9414375
Facility Type: ER
DER Facility ID: 202598
Site ID: 246737
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 1995-01-31
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1995-01-31
CID: Not reported
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-02-03
Spill Record Last Update: 2004-04-07
Spiller Name: PETE HAID
Spiller Company: HESS CORPORATION
Spiller Address: ONE HESS PLAZA
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "DIGGING ON PROPERTY, FOUND CONTAMINATION, UNDERGROUND LINE LEAK, LINE TAKEN O/S CONTINUING SITE INVESTIGATION."

All Materials:
Site ID: 246737
Operable Unit ID: 1011777
Operable Unit: 01
Material ID: 373119
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: HESS TERMINAL
Address: 722 COURT ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0904224 / 2009-07-13
Facility ID: 0904224
Facility Type: ER
DER Facility ID: 365444
Site ID: 416369
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2009-07-11
Investigator: jbvought
Referred To: Not reported
Reported to Dept: 2009-07-11
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2009-07-11
Spill Record Last Update: 2009-07-13
Spiller Name: Not reported
Spiller Company: GASKET
Spiller Address: Not reported
Spiller Company: 999
Contact Name: SAME AS ABOVE
DEC Memo: "07/13/09-Vought-Primary off-hours responder. Vought called and spoke to John Geitner (908-358-3436) and spill of approximately 1 gallon spray caused by failed gasket on a piping manifold resulting into oil spray on barge containment and on dock. One gallon total estimate of spill. Kens Marine onsite to clean dock and barge pan. Sheen observed in Gowanus as a result. Spill closed by Vought due to insignificant spill amount to surface water and immediate response by Hess."

Remarks: "# 6 oil sprayed while bardge transfer. Kens marine will be responding for clean up at this time."

All Materials:
Site ID: 416369
Operable Unit ID: 1172681
Operable Unit: 01
Material ID: 2164552
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name: HESS TERMINAL
Address: 722 COURT ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1206274 / 2012-09-28
Facility ID: 1206274
Facility Type: ER
DER Facility ID: 365444
Site ID: 469268
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401
Spill Date: 2012-09-25
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2012-09-25
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-09-25
Spill Record Last Update: 2012-09-28
Spiller Name: PAUL MARINO
Spiller Company: HESS CORP
Spiller Address: 722 COURT ST
Spiller Company: 999
Contact Name: PAUL MARINO
DEC Memo: "Sangesland spoke to Paul at Hess. He says spill was contained to cement area, no drains. Cleanup complete."
Remarks: "Spilled during testing into contained area. FD on scene during testing. Cleanup is underway."

All Materials:
Site ID: 469268
Operable Unit ID: 1219162
Operable Unit: 01
Material ID: 2217632
Material Code: 0028A
Material Name: ethylene glycol
Case No.: 00107211
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

Name: HESS BROOKLYN TERMINAL
Address: 722 COURT ST
City,State,Zip: BROOKLYN, NY 11231
Spill Number/Closed Date: 0900939 / 2009-05-12
Facility ID: 0900939
Facility Type: ER
DER Facility ID: 362065
Site ID: 412899
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2009-04-23
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2009-04-23
CID: Not reported
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2009-04-23
Spill Record Last Update: 2009-05-12
Spiller Name: OPERATOR
Spiller Company: HESS
Spiller Address: 722 COURT ST
Spiller Company: 999
Contact Name: OPERATOR
DEC Memo: "05/12/09 Left a messege for John Geitner to follow up on the spill.(sr) ** Rec'd a letter that states spill clean up was completed.Ken's Marine was contracted to clean up the spill. Spill was caused by a hose burst during a product transfer from a tanker truck to tank.Product released onto asphalt and a soil area covered by gravel, 15x15' in size.All liquid was removed from the pump containment,impacted gravel and soil was excavated and drummed for dispoal.Affected area was restored using clean gravel.No ground water was impacted, according to Hess.No end point sample was taken.I spoke with John Geitner of Hess Oil and he indicated that most of the spill was on the surface and it was recovered. Therefore, no sample was taken.(sr)**"
Remarks: "Diesel went onto asphalt and gravel; spill is contain; soil responder en route"

All Materials:
Site ID: 412899
Operable Unit ID: 1169353
Operable Unit: 01
Material ID: 2161005
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 15.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

Units: G
Recovered: Not reported
Oxygenate: Not reported

Name: HESS TERMINAL
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0408742 / 2004-12-03
Facility ID: 0408742
Facility Type: ER
DER Facility ID: 202598
Site ID: 333479
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2004-11-08
Investigator: JXZHAO
Referred To: Not reported
Reported to Dept: 2004-11-08
CID: 407
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-11-08
Spill Record Last Update: 2004-12-03
Spiller Name: Not reported
Spiller Company: PETROLUEM TANK CLEANERS
Spiller Address: Not reported
Spiller Company: 001
Contact Name: ED THERIAULT
DEC Memo: "site visit conducted by zhao PTC is the RP and took care of it's responsibility."
Remarks: "Contained in the tank field, tank 11, cleanup has begun."

All Materials:
Site ID: 333479
Operable Unit ID: 1095634
Operable Unit: 01
Material ID: 575755
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 333479
Operable Unit ID: 1095634

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

Operable Unit: 01
Material ID: 575772
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: HESS TERMINAL
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0103140 / 2003-08-11
Facility ID: 0103140
Facility Type: ER
DER Facility ID: 202598
Site ID: 138967
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2001-06-21
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2001-06-21
CID: 207
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-06-21
Spill Record Last Update: 2003-08-11
Spiller Name: DAVID LEE
Spiller Company: HESS TERMINAL
Spiller Address: 722 COURT ST
Spiller Company: 001
Contact Name: DAVID LEE
DEC Memo: ""
Remarks: "Spill on to blue stone - all cleaned up."

All Materials:
Site ID: 138967
Operable Unit ID: 841840
Operable Unit: 01
Material ID: 535236
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

Units: G
Recovered: 5.00
Oxygenate: Not reported

Name: AMERADA HESS TERMINAL
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0105995 / 2003-06-30
Facility ID: 0105995
Facility Type: ER
DER Facility ID: 202598
Site ID: 138968
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2001-09-05
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2001-09-05
CID: 257
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-09-05
Spill Record Last Update: 2004-04-07
Spiller Name: Not reported
Spiller Company: MAERADA HESS
Spiller Address: 722 COURT ST
Spiller Company: 001
Contact Name: HOWARD GOLDMAN
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND "
Remarks: "vac truck was filled to high and a mist sprayed out cleanup is in progress"

All Materials:
Site ID: 138968
Operable Unit ID: 843036
Operable Unit: 01
Material ID: 563126
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

Name: HESS TERMINAL
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0207681 / 2003-08-11
Facility ID: 0207681
Facility Type: ER
DER Facility ID: 202598
Site ID: 138977
DEC Region: 2
Spill Cause: Housekeeping
Spill Class: B3
SWIS: 2401
Spill Date: 2002-10-24
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2002-10-24
CID: 211
Water Affected: GOWANUS CREEK
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-10-24
Spill Record Last Update: 2003-08-11
Spiller Name: Not reported
Spiller Company: HESS
Spiller Address: Not reported
Spiller Company: 999
Contact Name: HOWARD GOLDMAN
DEC Memo: ""
Remarks: "DURING INSTALLATION OF NEW BULKHEAD BOTTOM SOIL WAS AGITATED CAUSED OILY MATERIAL TO GO TO SURFACE - BOOM APPLIED TO CONTAIN SPILL"

All Materials:

Site ID: 138977
Operable Unit ID: 860552
Operable Unit: 01
Material ID: 514692
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: AMERDA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9711037 / 2003-08-11
Facility ID: 9711037
Facility Type: ER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS BROOKLYN TERMINAL (Continued)

S102141580

DER Facility ID: 202598
Site ID: 138983
DEC Region: 2
Spill Cause: Unknown
Spill Class: A1
SWIS: 2401
Spill Date: 1998-01-02
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1998-01-02
CID: 322
Water Affected: GOWANUS CANAL/NY HAR
Spill Source: Unknown
Spill Notifier: Federal Government
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: 1997-01-02
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-01-02
Spill Record Last Update: 2003-08-11
Spiller Name: Not reported
Spiller Company: UNKNOWN VESSEL
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: ""
Remarks: "Unknown green liquid float on water - "

All Materials:

Site ID: 138983
Operable Unit ID: 1053912
Operable Unit: 01
Material ID: 329304
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

[Click this hyperlink](#) while viewing on your computer to access
1 additional NY SPILL: record(s) in the EDR Site Report.

**AF181
NW
1/4-1/2
0.304 mi.
1605 ft.**

**AMERADA HESS
722 COURT STREET
BROOKLYN, NY

Site 5 of 8 in cluster AF**

**NY LTANKS S103560371
N/A**

**Relative:
Lower

Actual:
3 ft.**

**LTANKS:
Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMERADA HESS (Continued)

S103560371

Spill Number/Closed Date: 9111290 / 1992-02-26
Facility ID: 9111290
Site ID: 138982
Spill Date: 1992-02-01
Spill Cause: Tank Overfill
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Class: A3
Cleanup Ceased: 1992-02-26
SWIS: 2401
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1992-02-01
CID: Not reported
Water Affected: GOWANUS CANAL/NY BAY
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1992-02-10
Spill Record Last Update: 2004-04-07
Spiller Name: Not reported
Spiller Company: HESS
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 202598
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "

Remarks: "USCG APPLIED TRIPLE BOOMS - HARD, SOFT & SNARES."

All Materials:

Site ID: 138982
Operable Unit ID: 961413
Operable Unit: 01
Material ID: 416333
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 300.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AF182
NW
1/4-1/2
0.304 mi.
1605 ft.

AMERADA HESS
722 COURT STREET
BROOKLYN, NY
Site 6 of 8 in cluster AF

NY LTANKS

S105230578
N/A

Relative:
Lower

LTANKS:

Actual:
3 ft.

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0109349 / 2003-08-11
Facility ID: 0109349
Site ID: 138970
Spill Date: 2001-12-21
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2001-12-21
CID: 390
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-12-21
Spill Record Last Update: 2004-04-07
Spiller Name: HOWARD GOLDMAN
Spiller Company: AMERADA HESS
Spiller Address: 1 HESS PLAZA
Spiller County: 001
Spiller Contact: HOWARD GOLDMAN
Spiller Phone: (732) 750-7004
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 202598
DEC Memo: ""
Remarks: "A hole in a Tank - No. 9412"

All Materials:

Site ID: 138970
Operable Unit ID: 846687
Operable Unit: 01
Material ID: 530554
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AF183
NW
1/4-1/2
0.304 mi.
1605 ft.

AMERADA HESS
722 COURT STREET
BROOKLYN, NY
Site 7 of 8 in cluster AF

NY LTANKS S106385307
N/A

Relative:
Lower

Actual:
3 ft.

LTANKS:

Name: AMERADA HESS
Address: 722 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0312168 / 2004-04-08
Facility ID: 0312168
Site ID: 246724
Spill Date: 2004-02-02
Spill Cause: Tank Overfill
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2004-02-02
CID: 444
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-02-02
Spill Record Last Update: 2004-04-08
Spiller Name: PAUL MARINO
Spiller Company: AMERADA HESS
Spiller Address: 1-HESS PLAZA
Spiller County: 001
Spiller Contact: PAUL MARINO
Spiller Phone: (732) 750-7105
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 202598
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO Demeo responded to the site. All State Power Vac will come to the site for cleanup 4/8/03 tjd Spill was cleaned by ABC Tank. Closure documentation submitted. Spill closed. No further action required."
Remarks: "DRIVER FAILED TO WATCH THE SPILLER, CLEAN UP IN PROGRESS."

All Materials:

Site ID: 246724
Operable Unit ID: 879627
Operable Unit: 01
Material ID: 497394
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMERADA HESS (Continued)

S106385307

Oxygenate: Not reported

AE184
East
1/4-1/2
0.305 mi.
1612 ft.
573-581 4TH AVENUE
581 4TH AVENUE
NEW YORK CITY, NY
Site 2 of 2 in cluster AE

NY VCP **S118943640**
N/A

Relative: VCP NYC:
Higher Project ID: 15TMP0003K, 15EHAN003K, 17CVCP030K
Name: 573-581 4TH AVENUE
Address: 581 4TH AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn

AD185
SSE
1/4-1/2
0.310 mi.
1637 ft.
GOLDEN MILLION
276-280 24TH ST
BROOKLYN, NY
Site 3 of 5 in cluster AD

NY LTANKS **S105997870**
NY Spills **N/A**

Relative: LTANKS:
Higher Name: GOLDEN MILLION
Address: 276-280 24TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0210214 / 2006-03-02
Facility ID: 0210214
Site ID: 242528
Spill Date: 2003-01-09
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: rmpiper
Referred To: Not reported
Reported to Dept: 2003-01-09
CID: 322
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-01-09
Spill Record Last Update: 2006-03-02
Spiller Name: MR LIM
Spiller Company: Not reported
Spiller Address: 276-280 24TH ST
Spiller County: 001
Spiller Contact: MR LIM
Spiller Phone: (718) 788-2760
Spiller Extention: Not reported
DEC Region: 2

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOLDEN MILLION (Continued)

S105997870

DER Facility ID: 199304
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER Rommel Office Duty 1/13/02 Tank Test failure letter sent to Mr. Lim at Golden Million at 276-280 24th Street, Brooklyn, NY 11215 as well as PBS application to register 10K gallon tank. 02/04/04-Transferred from Vought to Sawyer 11/28/05- ttf letter sent via fax 718.788.2759. Spoke w/ Mrs Lim. She said work was done and provided receipts though she has not provided soil analytical. She will contact PTC. 2/10/06- DEC Piper spoke w/ Mrs. Lim requesting info for a second time. 3/2/06- DEC Piper received soil analytical results. As per analytical and abandonment... Waiting for two other boring results. As per soil analytical, no gross contamination. Minor hits below TAGM. Closed."
Remarks: "tank test failure - tank has been abandoned since 1999 and is currently empty"

All TTF:

Facility ID: 0210214
Spill Number: 0210214
Spill Tank Test: 1527924
Site ID: 242528
Tank Number: 1
Tank Size: 10000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 242528
Operable Unit ID: 861471
Operable Unit: 01
Material ID: 513608
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: DRUM RUN
Address: 276-280 24TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0805570 / 2008-08-20
Facility ID: 0805570
Facility Type: ER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOLDEN MILLION (Continued)

S105997870

DER Facility ID: 199304
Site ID: 402689
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 2008-08-13
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2008-08-13
CID: 76
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2008-08-14
Spill Record Last Update: 2008-08-20
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: MARCIN STECKIEWICZ
DEC Memo: "drum run. 08/20/08 Drum was found today, was pumped out and list was sent to NYC Sanitation to pick up the empty drums.(sr)"
Remarks: "spill betw 4 and 5th aves. spill is in 55 gallon drum 3/4 filled and 7-5 gallon buckets which have been cleaned in garbage bag. contents of buckets packed into 55 gallon drum. spill was onto sidewalk and street. spill has been contained and cleaned up. spill was originally in buckets. spill less than 55 gallons."

All Materials:

Site ID: 402689
Operable Unit ID: 1159440
Operable Unit: 01
Material ID: 2150558
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

	Site	Database(s)	EDR ID Number EPA ID Number
AD186 SSE 1/4-1/2 0.310 mi. 1639 ft.	207 25TH STREET 207 25TH STREET BROOKLYN, NY Site 4 of 5 in cluster AD	NY LTANKS	S120702900 N/A

Relative:
Higher

Actual:
37 ft.

LTANKS:

Name:	207 25TH STREET
Address:	207 25TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1610374 / Not Reported
Facility ID:	1610374
Site ID:	541194
Spill Date:	1993-09-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	AAOBLIGA
Referred To:	Not reported
Reported to Dept:	2017-02-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	Not reported
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	1
Date Entered In Computer:	2017-02-16
Spill Record Last Update:	2019-07-30
Spiller Name:	Not reported
Spiller Company:	PHONG KINH HUA
Spiller Address:	5744 157TH STREET
Spiller County:	999
Spiller Contact:	SANDI FUNG
Spiller Phone:	(212) 810-0932
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	494958
DEC Memo:	"2/16/17 - Obligado - As part of an off-site investigation into 4th and 25th Spill cases #9305122, I conducted a complete file review and identified a tank test failure report for 207 25th street. According to the file, this site had a 550 gallon #2 diesel UST which failed a tightness test on 9/10/1993. As a result of this file review, the DEC under PIN # 93256 conducted a subsurface investigation around the former suspected tank with the current owner's permission. 4 borings were advanced, 2 within the building, 1 in the sidewalk adjacent to the fill port and 1 down gradient on the 737 4th Avenue Duncan donuts property. Soil and groundwater contamination was identified in all 4 soil borings. Contamination was found as shallow as 8 ft bgs. The soil data and groundwater confirm that the 1993 tank test failure resulted in a petroleum discharge to soil and groundwater. 3/21/17 - Obligado - Final Phase II report received from Envirotrac. The report documents investigations at 3 properties - 207 25th Street, 213 25th Street, and 276 24th Street. The report concludes that the former UST system at the 207 25th Street property was a contributing source to the over all Spill. However, based upon prior investigations, prior

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

207 25TH STREET (Continued)

S120702900

laboratory analysis of product samples, the overall extent of the impacted area and the volume of free product observed in the wells over the years, it is EnviroTrac's professional opinion that the property at 207 25th Street was not the sole source for the petroleum release. 4/4/17 - Obligado - I sent a letter to Sandi Fung of PSJC LLC, cc to DEC Vought, Austin, Urda and AOG Judith Karpen, requiring a UST assessment (via either geophysical or intrusive methods) in the vicinity of the suspected UST to determine if the source tank was still present beneath the site and acting as a continued source for soil and groundwater contamination. I required the report be submitted within 90 days of receipt of the correspondence. 4/5/17 - Obligado - I spoke with Sandi Fung. I provided her a list of tank contractors and the tank closure document from 1994. 5/19/17 - Obligado - Tom Gallanger, GEM (914) 382 8673. He has been hired by Sandi Fung to investigate the tank. 6/12/17 - Obligado - I got an email from Sandi requesting additional time to due the investigation as her contractor was not responsive. I told her that was fine. 8/21/17 - Obligado - I reviewed the UST Investigation Findings submitted by Gallinger Environmental on behalf of PSJC LLC. GEM installed three soil borings in the utility closet, using a jackhammer, shovel, and portable electroc hammer driven Geoprobe Soil sampler. The soil borings were targeted in the approximate location of the suspected former fuel oil access port observed in the 1993 photograph and immediately surrounding areas. Elevated field screening readings were detected in the soils collected from soil boring S2 starting at a depth of 7-9 feet below the surface. GEM found what appeared to be a UL listing tank tag and other debris (i.e. rags, paper and plastic) in the hand excavated soils at the location S3. The presence of these backfilled materials confirms past excavation work at this location that may be related to a previous tank removal. GEM concluded they did not encounter a UST beneath the site. Elevated field screenings and odors were observed at 7-9 ft, at a depth consisted with a tank grave for a small fuel oil UST. Evidence of possible former tank removal activities were observed. Based on the GEM report it appears the LUST at 207 25th St was previously removed by others. 7/2/18 - Obligado - After Project Review conference call with RSE Randall Austin and Kevin Hale, Chief of Spill Response and Coordination Section in Central Office on 6/26/18, it was determined that former LUST at 207 25th Street is a more likely source for the oil observed in the 4th and 25th Street Site monitoring wells. As such PIN #07960 has been opened and O&M activities will continue under this PIN/Spill number. Call out number 134930 has been issued to EAR. 1/28/19 - Obligado - I sent a letter of responsibility to Phong Kinh Hua and a Stipulation Agreement for signature within 30 days. CC to Robinson & Associates, P.C., Sandi Fung, and OAG. 4/30/19 - Obligado - Stipulation Agreement has been received on 4/12/19 and executed on 4/29/19. 7/30/19 - Obligado - RAWP submitted by Seacliff for continued gauging and product recovery approved."

Remarks:

"Subsurface investigation identified soil and groundwater contamination."

All TTF:

Facility ID: 1610374
Spill Number: 1610374
Spill Tank Test: 2503800
Site ID: 541194
Tank Number: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

207 25TH STREET (Continued)

S120702900

Tank Size: 550
Material: 0001
EPA UST: False
UST: True
Cause: 00
Source: 01
Test Method: 76
Test Method 2: VacuTect
Leak Rate: .00
Gross Fail: Not reported
Modified By: AAOBLIGA
Last Modified Date: Not reported

All Materials:
Site ID: 541194
Operable Unit ID: 1289763
Operable Unit: 01
Material ID: 2295545
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

AG187
NNW
1/4-1/2
0.314 mi.
1658 ft.

FORMER BARRETT MANUFACTURING CO.
627 SMITH ST.
BROOKLYN, NY 11231

Site 1 of 2 in cluster AG

NY SHWS
NY BROWNFIELDS

S112818546
N/A

Relative:
Lower
Actual:
1 ft.

SHWS:
Name: FORMER BARRETT MANUFACTURING CO.
Address: 627 SMITH ST.
City,State,Zip: BROOKLYN, NY 11231
Program: HW
Site Code: 466165
Classification: N
Region: 2
Acres: 1.04
HW Code: 224163
Record Add: 07/06/2012
Record Upd: 05/24/2013
Updated By: BXANDERS
Site Description: See site C224163 Location: The 45,400 square foot site is located at 627-641 Smith Street in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site currently consists of a vacant 1-story warehouse and an asphalt-paved parking lot. The site warehouse is connected to the warehouse on the lot to the south. Current Zoning/Use(s): The site is currently zoned as M3-1 (manufacturing). Historical Use(s): The Site was occupied by Barrett Manufacturing Company, Storage and Shipping in the early 1900s. Later, Colonial Sand and Stone Company occupied the site in the 1950s. Black Diamond Cargo Line and Pittston Stevedoring Storage

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER BARRETT MANUFACTURING CO. (Continued)

S112818546

occupied the Site from the early 1960's to the 1990s. The original occupant, Barrett Manufacturing, utilized nine coal tar storage tanks and two gasoline underground storage tanks (USTs) as part of their production of coal tar and roofing material. Additionally, Barrett Manufacturing operations occupied the entire city block west of the site (Block 492). Block 492 currently consists of three Lots: Lot 1, Lot 15, Lot 20. Block 492, Lot 1 is a State Superfund Site: Chemtura 633 Court Street ID No. 224146. Site Geology and Hydrogeology: Soil borings conducted between 2005 and 2012 indicate there are alternating layers of sand and dense clay. Two to four separate aquifers are present at the site, separated by clay confining layers. Groundwater is present at a depth of 2 ? 4 feet below grade.

Env Problem: See site C224163 Nature and Extent of Contamination: Soil ? Coal tar related VOCs and SVOCs are present above Unrestricted Use SCOs. These include naphthalene (7,700 mg/kg), benzo(a)anthracene (280 mg/kg), benzo(a)pyrene (250 mg/kg), and benzo(b)fluoranthene (190 mg/kg). Contaminated soil is present on-site in the vicinity of the former tar storage tanks, and extends to the eastern property boundary, which is bordered by the Gowanus Canal. Additionally, the area of contaminated soil extends off-site to the south, and upgradient to the west. High soil VOCs and SVOCs upgradient and adjacent to Block 492 indicate that Block 492 may be a source of coal tar related VOCs and SVOCs. Groundwater ? VOCs and SVOCs are present above Class GA Standard in twenty monitoring wells. The groundwater plume has not been delineated to the south or to the west. VOC and SVOC contamination extends to the eastern property boundary, which is bordered by the Gowanus Canal. Napthalene is present at a concentration of up to 17,000 ug/l. Benzene is present at a maximum concentration of 11,000 ug/l. Toluene is present at a concentration of up to 7,300 ug/l. Soil Vapor ? Soil vapor samples have not been collected. Significant Threat: No evaluation has been made thus far to determine if the contaminants represent an environmental significant threat.

Health Problem: Not reported

Dump: Not reported

Structure: Not reported

Lagoon: Not reported

Landfill: Not reported

Pond: Not reported

Disp Start: Not reported

Disp Term: Not reported

Lat/Long: Not reported

Dell: Not reported

Record Add: Not reported

Record Upd: Not reported

Updated By: Not reported

Own Op: Owner

Sub Type: E

Owner Name: c/o Crown Acquisitions, Inc.

Owner Company: Red Hook Developers Holdings, LLC

Owner Address: 362 Fifth Avenue

Owner Addr2: Suite 1201

Owner City,St,Zip: New York, NY 10001

Owner Country: United States of America

Own Op: Owner

Sub Type: E

Owner Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER BARRETT MANUFACTURING CO. (Continued)

S112818546

Owner Company: CF Smith, LLC
Owner Address: 404 Fifth Avenue
Owner Addr2: 5th Floor
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

BROWNFIELDS:

Name: RED HOOK SMITH STREET
Address: 627 SMITH ST.
City,State,Zip: BROOKLYN, NY 11231
Program: BCP
Site Code: 476652
Acres: 1.96
HW Code: C224163
SWIS: 2401
Town: New York City
Record Added Date: 12/12/2012
Record Updated Date: 10/11/2019
Update By: GWBURKE
Site Description:

Location: The Red Hook Smith Street site is located in Brooklyn, in an urban area. The site is bounded by Smith Street to the west, the Gowanus Canal to the east and south, and an industrial property to the north. Site Features: The site encompasses two tax parcels (Block 493, Lot 1 and Block 495, Lot 1) and occupies approximately 85,400 square feet. Block 493 (the northern part of the site) is occupied by a vacant one-story warehouse and an asphalt-paved parking lot. The warehouse is connected to the warehouse on the lot to the south (Block 495, Lot 1). Block 495 is occupied by an approximate 40,000-square-foot vacant one-story warehouse. Current Zoning/Use(s): The site is zoned heavy manufacturing; M-3. M-3 zoning also allow certain retail and commercial uses. Currently the site is vacant. Past Uses of the Site: Barrett Manufacturing occupied Block 493 from circa 1900 to 1940 and utilized nine coal tar storage tanks as part of their production of coal tar and roofing material. After Barrett Manufacturing sold the property in the 1950's two gasoline underground storage tanks (USTs) were installed on the property. Barrett's manufacturing facility also extended to the west of the site (hydraulically up-gradient). Various manufacturing and storage companies occupied Block 495 (the southern part of the site). American Ice Company occupied Block 495 in the early 1900 s and Smith Street Dock Corporation and Seaboard Storage occupied lock 495 from around 1930 to 1950. Black Diamond Cargo Line and Pittston Stevedoring Cargo Storage occupied Block 495 from the late 1960 s to the 1990 s. Site Geology and Hydrogeology: The topography is relatively flat, gently sloping to the east-southeast towards the Gowanus Canal. The site is underlain by a discontinuous layer of historic urban fill that extends to approximately 12 feet below grade

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER BARRETT MANUFACTURING CO. (Continued)

S112818546

Env Problem:

surface (bgs). The historic fill generally consisted of sand, silt, clay, gravel, cobbles, wood and brick fragments, cinder, and ash. The historic fill is underlain by fine sands and silts from 2 to 47 feet bgs. Discontinuous stiff clays lens and organic material were identified at varying depths (8 to 35 feet bgs). Bedrock was not encountered as part of this investigation, however, the Hartland Formation would be anticipated based on local investigations. The depth to groundwater is approximately five-feet below the ground surface and flows to the east-southeast towards the Gowanus Canal. Several environmental investigations and reports have been generated for this site; most recently the Department received a Draft Supplemental Investigation Report in February 2016. Observation described in the report detail the presence of tar-like material in the soil and floating on the groundwater in portions of the site and immediately upgradient of the site. Groundwater is approximately five-feet below the ground surface (bgs). The tar-like material was encountered from near the ground surface to a maximum depth of 47 feet bgs. Sorbed and aqueous phase VOCs and SVOCs are present onsite and upgradient of the site at concentrations above the applicable SCGs. The VOCs identified as contaminants of concern include BTEX compounds with soil concentrations up to 361mg/kg and dissolved phase concentrations up to 1,210 ug/l. The most prevalent SVOC was naphthalene with the maximum soil concentration of 7,500 ug/kg and groundwater concentration of 17,000 ug/l.

Health Problem:

Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with a building and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The inhalation of site-related contaminants due to soil vapor intrusion does not represent a current concern because the site is vacant. Additional evaluation is needed to determine whether actions are needed off-site.

Dump:

False

Structure:

True

Lagoon:

False

Landfill:

False

Pond:

False

Disp Start:

unknown

Disp Term:

unknown

Lat/Long:

Not reported

Dell:

Not reported

Record Add:

2013-10-25 15:30:00

Record Upd:

2016-08-18 15:11:00

Updated By:

CHPOST

Own Op:

Applicant/Requestor

Sub Type:

P03

Owner Name:

Emzon Shung

Owner Company:

Red Hook Developers Holdings, LLC

Owner Address:

1400 Broadway, 15th Floor

Owner Addr2:

Not reported

Owner City,St,Zip:

New York, NY 10018

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER BARRETT MANUFACTURING CO. (Continued)

S112818546

Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library
Owner Address:	10 Grand Army Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Emzon Shung
Owner Company:	Red Hook Developers Holdings, LLC
Owner Address:	1400 Broadway
Owner Addr2:	15th Floor
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	CF Smith, LLC
Owner Address:	404 Fifth Avenue
Owner Addr2:	5th Floor
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
HW Code:	C224163
Waste Type:	coal tar
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	0500510
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2012-12-12 16:08:00
Record Updated:	2012-12-12 16:08:00
Updated By:	BXANDERS
Crossref ID:	224197
Cross Ref Type Code:	09

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER BARRETT MANUFACTURING CO. (Continued)

S112818546

Cross Ref Type: DEC Case No.
Record Added Date: 2015-04-17 11:52:00
Record Updated: 2015-04-17 11:52:00
Updated By: CHPOST
Crossref ID: C224215
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2015-05-11 11:00:00
Record Updated: 2015-05-11 11:00:00
Updated By: CHPOST

AC188
SSW
1/4-1/2
0.317 mi.
1673 ft.

HI-VOLTAGE TEST SET
3RD AVE YARD
BROOKLYN, NY

NY LTANKS **S102240204**
NY Spills **N/A**

Site 2 of 2 in cluster AC

Relative:
Higher
Actual:
12 ft.

LTANKS:

Name: BETWEEN 18TH & 23RD ST
Address: 3RD AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0303210 / 2003-07-03
Facility ID: 0303210
Site ID: 148976
Spill Date: 2003-06-26
Spill Cause: Tank Failure
Spill Source: Commercial Vehicle
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2003-06-26
CID: 297
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-06-26
Spill Record Last Update: 2003-07-03
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: DISP #477
Spiller Phone: (718) 622-6900
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 264333
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO NYCFD left a drum on the side of the road for DEC pick up. Drum Run 7/3/03 TJD Drum emptied as part of Drum Run . No further action required. "

Remarks: "FDNY CALLED TO A TRUCK THAT WAS LEAKING FUEL ONTO THE ROADWAY - FD STILL ON SCENE"

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HI-VOLTAGE TEST SET (Continued)

S102240204

All Materials:

Site ID: 148976
Operable Unit ID: 871234
Operable Unit: 01
Material ID: 504081
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 40.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: HI-VOLTAGE TEST SET
Address: 3RD AVE YARD
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9606638 / 2005-02-09
Facility ID: 9606638
Facility Type: ER
DER Facility ID: 228767
Site ID: 148977
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1996-08-23
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1996-08-23
CID: 365
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1996-08-23
Spill Record Last Update: 2005-02-09
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 128 WEST END AVENUE
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 2/9/05: Con Ed injected test set: Site visit was performed to confirm cleanup - Test truck was always parked in North garage and found no evidence of oil there. Close out. (JHO)"
Remarks: "equipment failure caused spill of 2 pints of slating oil onto the concrete "

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HI-VOLTAGE TEST SET (Continued)

S102240204

All Materials:

Site ID: 148977
Operable Unit ID: 1037765
Operable Unit: 01
Material ID: 345906
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

AH189 643 COURT ST.
NNW 643 COURT ST.
1/4-1/2 BROOKLYN, NY 11231
0.322 mi.
1699 ft. Site 1 of 2 in cluster AH

NY SHWS S117269718
N/A

Relative:
Lower

SHWS:

Actual:
5 ft.

Name: 643 COURT ST.
Address: 643 COURT ST.
City,State,Zip: BROOKLYN, NY 11231
Program: HW
Site Code: 498440
Classification: P
Region: 2
Acres: 1.377
HW Code: 224196
Record Add: 08/08/2014
Record Upd: 04/05/2016
Updated By: GWCROSS

Site Description:

Location: The site is located in the Red Hook section of Brooklyn, in the City of New York. The site is listed as Block 494, Lot 1 and is located on the south east corner of Court St. and Halleck St. in close proximity to the Gowanus Canal. Site Features: The site is currently a parking lot with a small building near the middle of the site occupying approximately 1/8th of the property acreage. Current Use: The site is currently leased from Red Hook Realty Co. by National Grid who is using the site as a parking lot for their service vehicles. Historical Use: The property was used for tar paper manufacturing as depicted in the 1886 Sanborn map which shows tar pitch storage areas on the corners of Smith St./Halleck St. and Court St./Halleck St. Site Geology and Hydrogeology: Based on geological information at an adjacent site, the groundwater at this property is anticipated to be less than 5 feet bgs. Groundwater flow is anticipated to flow radially from the Gowanus Canal traveling north, northwest, west, southwest, and south. To the south and west of the site, the coastline is lined with sheet piling and to the east of the site, where groundwater enters, the coastline is lined with rip rap. The groundwater is likely saline due to its proximity to the canal. Much of this area is reclaimed water front property with fill material anticipated to exist from 0 to 12 feet bgs. A gray colored, low permeability clayey layer (former base of the Gowanus Canal) is also anticipated to exist beneath the fill material with a thickness

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

643 COURT ST. (Continued)

S117269718

of approximately 8 feet.

Env Problem: This site has had several instances over the last decade of tar seeping out of the ground, getting cleaned up, and reappearing some time later. Further investigation is required to determine the nature and extent of tar beneath the surface.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: Richard Schmitz
Owner Company: National Grid
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: David Weinberger
Owner Company: Red Hook Realty Co. (LLC)
Owner Address: 88 Mineola Ave.
Owner Addr2: PO Box 1356
Owner City,St,Zip: Roslyn Heights, NY 11577
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

AI190
NW
1/4-1/2
0.322 mi.
1701 ft.

HESS TERMINAL RACK 12
764 COURT STREET
BROOKLYN, NY
Site 1 of 2 in cluster AI

NY LTANKS S102147764
N/A

Relative:
Lower
Actual:
4 ft.

LTANKS:
Name: HESS TERMINAL RACK 12
Address: 764 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0110576 / 2002-03-04

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS TERMINAL RACK 12 (Continued)

S102147764

Facility ID: 0110576
Site ID: 253896
Spill Date: 2002-02-05
Spill Cause: Tank Overfill
Spill Source: Gasoline Station or other PBS Facility
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JBVUGHT
Referred To: Not reported
Reported to Dept: 2002-02-05
CID: 397
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-02-05
Spill Record Last Update: 2002-03-04
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: UNK
Spiller County: 999
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 321927
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 3/4/2002-VOUGHT-Spoke with Scott Douglas (Hess) who stated that the spill was cleaned by Allstate Power and Vacuuming using Speedy Dry. The spill was on concrete and no sewers or drains were affected. Spill closed by Vought."

Remarks: "caller states that one of the drivers was filling his tank truck and overfilled truck spilling some oil. clean up crew is en route"

All Materials:

Site ID: 253896
Operable Unit ID: 849049
Operable Unit: 01
Material ID: 528196
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AI191
NW
1/4-1/2
0.322 mi.
1701 ft.
Site 2 of 2 in cluster AI

NY LTANKS
S108765362
N/A

Relative:
Lower

LTANKS:

Actual:
4 ft.

Name: HESS LOADING RACK
Address: 764 COURT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0704424 / 2007-07-19
Facility ID: 0704424
Site ID: 384569
Spill Date: 2007-07-19
Spill Cause: Tank Overfill
Spill Source: Commercial Vehicle
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2007-07-19
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: Not reported
Meets Standard: False
UST Involvement: Not reported
Remediation Phase: 0
Date Entered In Computer: 2007-07-19
Spill Record Last Update: 2007-07-19
Spiller Name: Not reported
Spiller Company: BORO FUEL OIL INC
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: TAMARA SONGER
Spiller Phone: (732) 750-6000
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 321927
DEC Memo: "minor spill at Hess Depot loading ramp - spill cleaned"
Remarks: "TRUCK OVERFILLED WHILE FUELING AND CONTAINED AND IN PROCESS OF CLEANING UP"

All Materials:

Site ID: 384569
Operable Unit ID: 1141866
Operable Unit: 01
Material ID: 2132081
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 8.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

	Site	Database(s)	EDR ID Number EPA ID Number
AF192 NW 1/4-1/2 0.323 mi. 1707 ft.	713 COURT STREET 713 COURT STREET KINGS, NY Site 8 of 8 in cluster AF	NY LTANKS	S102671951 N/A
Relative: Lower Actual: 4 ft.	LTANKS: Name: 713 COURT STREET Address: 713 COURT STREET City,State,Zip: KINGS, NY Spill Number/Closed Date: 9207990 / 1995-03-22 Facility ID: 9207990 Site ID: 280278 Spill Date: 1992-10-10 Spill Cause: Tank Overfill Spill Source: Major Facility (MOSF) > 400,000 gal Spill Class: C4 Cleanup Ceased: 1995-03-22 SWIS: 2401 Investigator: O'DOWD Referred To: Not reported Reported to Dept: 1992-10-10 CID: Not reported Water Affected: GOWANUS CANAL Spill Notifier: Responsible Party Last Inspection: Not reported Recommended Penalty: False Meets Standard: True UST Involvement: False Remediation Phase: 0 Date Entered In Computer: 1992-10-15 Spill Record Last Update: 1995-03-22 Spiller Name: Not reported Spiller Company: Not reported Spiller Address: Not reported Spiller County: 001 Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported DEC Region: 2 DER Facility ID: 227565 DEC Memo: "" Remarks: "DURING UNLOADING OF BARGE TO TANK THEY OVERFILLED TANK CALLED KEN MARINE TO CLEAN IT UP TRYING TO CONTAIN IT NRC NOTIFIED NOTES ATTACHED" All Materials: Site ID: 280278 Operable Unit ID: 971634 Operable Unit: 01 Material ID: 408598 Material Code: 0002A Material Name: #4 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: 6000.00 Units: G Recovered: .00 Oxygenate: Not reported		

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

	Site	Database(s)	
AD193 SSE 1/4-1/2 0.334 mi. 1763 ft.	25TH ST - 4TH AVE SUB-STA 25TH ST - 4TH AVE SUB-STA BROOKLYN, NY Site 5 of 5 in cluster AD	NY LTANKS	S101658424 N/A
Relative: Higher Actual: 40 ft.	LTANKS: Name: 25TH ST - 4TH AVE SUB-STA Address: 25TH ST - 4TH AVE SUB-STA City,State,Zip: BROOKLYN, NY Spill Number/Closed Date: 9505109 / 1995-08-11 Facility ID: 9505109 Site ID: 213768 Spill Date: 1995-02-01 Spill Cause: Tank Failure Spill Source: Commercial/Industrial Spill Class: C3 Cleanup Ceased: Not reported SWIS: 2401 Investigator: TOMASELLO Referred To: Not reported Reported to Dept: 1995-07-26 CID: Not reported Water Affected: Not reported Spill Notifier: Citizen Last Inspection: Not reported Recommended Penalty: False Meets Standard: False UST Involvement: False Remediation Phase: 0 Date Entered In Computer: 1995-08-07 Spill Record Last Update: 2006-03-07 Spiller Name: Not reported Spiller Company: UNKNOWN Spiller Address: Not reported Spiller County: 999 Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported DEC Region: 2 DER Facility ID: 177106 DEC Memo: "refer to 9305122." Remarks: "BEEN LEAKING LAST 5-6 MONTHS - PEOPLE FROM SUBWAY CLEAN-UP PERIODICALLY - BELIEVED TO BE COMING FROM SERVICE STATION OVERHEAD." All Materials: Site ID: 213768 Operable Unit ID: 1019872 Operable Unit: 01 Material ID: 366637 Material Code: 0001A Material Name: #2 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: 5.00 Units: G Recovered: .00 Oxygenate: Not reported		

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AJ194
NE
1/4-1/2
0.340 mi.
1793 ft.

SPILL NUMBER 0207372
3RD AVE/14TH ST
BROOKLYN, NY
Site 1 of 2 in cluster AJ

NY LTANKS **S105997026**
N/A

Relative:
Higher

Actual:
26 ft.

LTANKS:

Name: SPILL NUMBER 0207372
Address: 3RD AVE/14TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0207372 / 2003-02-05
Facility ID: 0207372
Site ID: 124766
Spill Date: 2002-10-17
Spill Cause: Tank Failure
Spill Source: Commercial Vehicle
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2002-10-17
CID: 312
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-10-17
Spill Record Last Update: 2003-02-05
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 108018
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was
FOLEY Con Ed e2mis #145594: PAGANO #51764 ENVIROMENTAL OPS MANHATTAN
REPORTS THAT V.VAVALLIO #57666 OF MANHATTAN EQUIPMENT REPORTED THAT A
STEEL PLATE ON STREET AT THE S/E/C 3RD AVE & 14 STSHIFTED WHEN A CAR
IN FRONT OF HIM STOPPED SHORT. HIS COMPANY VEHICLE #24288 WAS HIT
UNDER IT CAUSING THE GAS TANK TO BE PUNCTURED, SPILLING APPROX 2
GALLONS OF GASOLINE TO SPILL ONTO THE STREET. LEAK STOPPED ONCE
ENGINE WAS TURNED OFF. HE NOTIFIED MANHATTAN ENVIROMENTAL PAGANO. MAN
SHIFT MANAGER ARRANGER FOR MATERIALS TO BE DELIVERED TO LOCATION TO
CONTAIN SPILL. NO SEWERS OR WATERWAYS AFFECTED, NO FIRE OR SMOKE
INVOLVED, NO INJURIES OR PRIVATE PROPERTY INVOLVED. UPDATE @ 0627 HRS
L.COSTA NOTIFIED. "

Remarks: "veh #24288 - metal plate shifted and made the fuel tank fail - being
cleaned up now - case #145594 - contained"

All Materials:

Site ID: 124766
Operable Unit ID: 858967
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0207372 (Continued)

S105997026

Material ID: 517965
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: 2.00
Oxygenate: Not reported

195
ESE
1/4-1/2
0.346 mi.
1829 ft.

**GRESCHLER HARDWARE STORE
660 5TH AVE
BROOKLYN, NY**

**NY LTANKS S102233323
N/A**

**Relative:
Higher
Actual:
74 ft.**

LTANKS:
Name: GRESCHLER HARDWARE STORE
Address: 660 5TH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9602471 / 1996-05-21
Facility ID: 9602471
Site ID: 102393
Spill Date: 1996-05-21
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 1996-05-21
CID: 282
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1996-05-21
Spill Record Last Update: 2001-06-13
Spiller Name: SAME
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: MR KEVIN BOYD
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 90670
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT 4:05pm FD WAS ON SCENE - SPILL CONTAINED - 275 GALLON TANK - 35 GALLON SPILLED - REST PUMPED OFF 6/13/01 STEVE SOBSTYL 516-576-8844 WORKING FOR POTENTIAL BUYER OF PROPERTY CALLED TO CONFIRM THAT SITE STATUS IS CLOSED/INACTIVE. ADDITIONAL INFORMATION: TANKS (2-275) WERE REMOVED AND REPLACED (USTS WITH ALARM SYSTEMS)"

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GRESCHLER HARDWARE STORE (Continued)

S102233323

Remarks: "they had a leak in the tank.appears to be a small spill yet they have not determined the size of the spill yet spill is in the process of being cleaned up. "

All Materials:

Site ID: 102393
Operable Unit ID: 1033941
Operable Unit: 01
Material ID: 352289
Material Code: 0012A
Material Name: kerosene
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AG196
NNW
1/4-1/2
0.354 mi.
1867 ft.

610 SMITH STREET
610 SMITH STREET
BROOKLYN, NY 11231

NY AST
NY BROWNFIELDS
NY Spills

U003393757
N/A

Site 2 of 2 in cluster AG

Relative:
Lower

Actual:
3 ft.

AST:
Name: 610 SMITH STREET
Address: 610 SMITH STREET
City,State,Zip: BROOKLYN, NY 11231
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-483109
Program Type: PBS
UTM X: 584467.49457
UTM Y: 4502596.11833
Expiration Date: 11/19/2020
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id: 21673
Affiliation Type: Facility Owner
Company Name: 610 SMITH ST LLC
Contact Type: VICE PRES.
Contact Name: HERBERT H. CHAVES
Address1: 111 JOHN STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 349-5618
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-10-07

Site Id: 21673
Affiliation Type: Mail Contact

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

610 SMITH STREET (Continued)

U003393757

Company Name: 610 SMITH ST LLC
Contact Type: Not reported
Contact Name: HERBERT H. CHAVES, V.P.
Address1: 111 JOHN STREET-ROOM 312
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 349-5618
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-10-07

Site Id: 21673
Affiliation Type: Facility Operator
Company Name: 610 SMITH STREET
Contact Type: Not reported
Contact Name: JOSE RODRIGUEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 349-5618
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-10-07

Site Id: 21673
Affiliation Type: Emergency Contact
Company Name: 610 SMITH ST CORP
Contact Type: Not reported
Contact Name: HERBERT CHAVES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 349-5618
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 32324
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

610 SMITH STREET (Continued)

U003393757

Equipment Records:

E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
Aboveground - contact with soil.... Tank bottom rests on soil,
allowing no visual inspection.
Steel/Carbon Steel/Iron
In Service
Not reported
08/26/1947
5000
NN
Not reported
Not reported
Not reported
True
NTFREEMA
04/14/2017
#2 fuel oil (on-site consumption)

Tank Location:

Tank Type:

Tank Status:

Pipe Model:

Install Date:

Capacity Gallons:

Tightness Test Method:

Date Test:

Next Test Date:

Date Tank Closed:

Register:

Modified By:

Last Modified:

Material Name:

BROWNFIELDS:

Name: 610 SMITH STREET
Address: 610 SMITH STREET
City,State,Zip: BROOKLYN, NY 11231
Program: BCP
Site Code: 507490
Acres: 0.46
HW Code: C224215
SWIS: 2401
Town: New York City
Record Added Date: 05/05/2015
Record Updated Date: 10/16/2019
Update By: GWBURKE
Site Description:

Location: The site is located in the Red Hook section of Brooklyn, in the City of New York at 610 Smith Street and is listed as Block 492, Lot 15 on NYC tax maps. The site is located at the intersections of Halleck Street, Smith Street and Sigourney Streets. The site is approximately 0.46 acres and is located 200 feet west of the Gowanus Canal. The site is a portion of P-site 224197 (Smith Street at Halleck Street). The site is bounded by NYSDEC BCP Site #C224163 (Red Hook Smith Street) to the east; #C224163 is downgradient of the site. To the south is NYSDEC P-site #224196 (643 Court Street). To the west and upgradient is NYSDEC Site 224146 (633 Court Street - a RCRA corrective action site). To the north is Sigourney Street which has been blocked off at both ends and is used as a storage area by others. Site Features: The site is primarily covered with a three-story brick building. Parking spaces along Smith Street and

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

610 SMITH STREET (Continued)

U003393757

Halleck Street are covered by asphalt. Contamination beneath these parking spaces is likely to be present. Current Zoning and Land Use: The current zoning is industrial M-3 for low-performing industrial use. The building is primarily used as artist's studios and art warehouse. Past Use of the Site: The site is a portion of a previous coal tar and tar-paper manufacturing facility operated by Barrett Manufacturing; a predecessor company of Honeywell International. A review of Sanborn maps identified the presence of coal-tar manufacturing facility at this site. Historic as-built drawings depict a tar well that extends to nearly the entire footprint of the building/site. The coal tar was manufactured for the production of tar-paper and has similar process vessels as have been found in typical manufactured gas plants (MGPs). A 1904 Sanborn Insurance Map depicts coal tar products, asphalt tanks and various oil tanks (including a 14,000-gallon underground tank). The area that was the location of the Barrett Manufacturing facility includes sites: 224197 (Smith Street at Halleck Street), site 224146 (633 Court Street) and site C224163 (Red Hook Smith Street). Site Geology and Hydrogeology: The area was previously part of the Gowanus Bay and was filled with anthropogenic material. Based on the geologic information at nearby sites, the base of the fill is typically identified by the presence of a native grey silt/clay layer at a depth of approximately 19 bgs. Groundwater at this property is approximately 5 feet bgs and is tidally influenced. Groundwater flow has been determined by others to be toward the Gowanus Canal traveling east and/or southeast. No environmental sampling has been performed to date within the boundaries of the site. Previous investigations by others at adjacent properties have identified NAPL, grossly contaminated soil, VOCs and SVOC as the primary contaminants of concern.

Env Problem:

Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available. No environmental sampling has been performed to date within the boundaries of the site. Previous investigations by others at adjacent properties have identified NAPL, grossly contaminated soil, VOCs and SVOC as the primary contaminants of concern.

Health Problem:

Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.

Dump:

False

Structure:

False

Lagoon:

False

Landfill:

False

Pond:

False

Disp Start:

Not reported

Disp Term:

Not reported

Lat/Long:

Not reported

Dell:

Not reported

Record Add:

2015-05-06 11:42:00

Record Upd:

2015-05-06 11:42:00

Updated By:

SRHEIGEL

Own Op:

Owner

Sub Type:

06

Owner Name:

Herbert Chaves

Owner Company:

610 Smith St., LLC

Owner Address:

111 John Street, Suite 312

Owner Addr2:

Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

610 SMITH STREET (Continued)

U003393757

Owner City,St,Zip:	New York, NY 10038
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Sandra Sutton
Owner Company:	Red Hook Library
Owner Address:	7 Wolcott Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Herbert Chaves
Owner Company:	610 Smith St., LLC
Owner Address:	111 John Street, Suite 312
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10038
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	224196
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2015-05-11 11:01:00
Record Updated:	2015-05-11 11:01:00
Updated By:	CHPOST
Crossref ID:	224146
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2015-05-11 11:02:00
Record Updated:	2015-05-11 11:02:00
Updated By:	CHPOST
Crossref ID:	224197
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2015-05-06 11:32:00
Record Updated:	2015-05-06 11:32:00
Updated By:	SRHEIGEL
Crossref ID:	C224163
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2015-05-11 11:00:00
Record Updated:	2015-05-11 11:00:00
Updated By:	CHPOST

SPILLS:

Name:	ROYAL INK
Address:	610 SMITH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1208781 / 2013-02-20
Facility ID:	1208781
Facility Type:	ER
DER Facility ID:	426109
Site ID:	471844
DEC Region:	2

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

610 SMITH STREET (Continued)

U003393757

Spill Cause: Storm
Spill Class: Not reported
SWIS: 2401
Spill Date: 2012-11-03
Investigator: HRAHMED
Referred To: Not reported
Reported to Dept: 2012-11-03
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-11-03
Spill Record Last Update: 2013-02-20
Spiller Name: Not reported
Spiller Company: HURRICANE SANDY
Spiller Address: Not reported
Spiller Company: 999
Contact Name: LIAM MCDERMOT
DEC Memo: "11/03/12-H.Ahmed-Spoke to Liam McDermot (718 928 5412). As per him, the storm flooded the basement and first floor. Now they have no flood water in first floor. The basement has flood water with little bit of oil sheen on it. Asked if we can help them to pump out flood water from the basement. Told him that, we are helping people who has flooded basement with oily water. 01/08/13-H.Ahmed-Spoke to Harbert Chaves the owner of the property. he said he converted to gas long ago and there is no indication of spill. I asked him to send some pictures on the boiler and floor. 02/20/13-H.AHMED- Received email with some pictures from Mr. Chaves showing there is no evidence of spill on the floor. Based on the info todote, the spill is closed. "

Remarks: "Caller advised boiler was flooded. CLean up is pending."

All Materials:

Site ID: 471844
Operable Unit ID: 1221700
Operable Unit: 01
Material ID: 2220360
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AH197
NNW
1/4-1/2
0.356 mi.
1879 ft.

CHEMTURA 633 COURT STREET
633 COURT STREET
BROOKLYN, NY 11231

Site 2 of 2 in cluster AH

NY SHWS **S113828311**
N/A

Relative:
Higher
Actual:
7 ft.

SHWS:

Name: CHEMTURA 633 COURT STREET
Address: 633 COURT STREET
City,State,Zip: BROOKLYN, NY 11231
Program: HW
Site Code: 443256
Classification: Significant threat to the public health or environment - action required.

Region: 2
Acres: 0.503
HW Code: 224146
Record Add: 12/10/2010
Record Upd: 10/09/2019
Updated By: GWBURKE

Site Description: Location: The site is located at 633 Court Street, Kings County, Brooklyn, New York within the Red Hook Industrial area of Brooklyn. The Site is located northeast of the Court Street and Halleck Street intersection. The site is immediately bordered to the south by Halleck Street and a National Grid truck facility, to the north by a paper street (Sigourney Street) and a petroleum cartage and storage (trucking) company. To the east there is small vacant lot and a warehouse. A recreational park (Red Hook Smith Recreational Park) is located directly across Court Street to the west of the site. Additionally, an oil terminal that is currently owned by Buckeye Partners, L.P. is located approximately one block to the south of the site. Site Features: The entire site is completely developed and covered with two connected adjoining buildings. The building's foundations are slab on grade concrete and there are no basements. These buildings were formerly used by Chemtura's predecessor companies for chemical manufacturing and chemical laboratory operations. Current Zoning and Land Use: The site is currently active, and is zoned M3-1 for industrial use, however this zoning designation allows for certain commercial uses. Several tenants occupy the site including a wholesale food and food product supply warehouse and offices. The M3-1 does not allow for residential use at this site. The surrounding parcels are currently used for a combination of commercial, light industrial and utility right-of-ways. The park located to the west is zoned residential and is used exclusively for recreational purposes. The nearest residential structure is approximately one-half miles to the north. Past Use of the Site: In 1904 the site was owned by Barrett Manufacturing and was used for the manufacturing of tar paper. Barrett Manufacturing Company is a predecessor company to Honeywell International, Inc. Tar tanks, storage tanks, stills, a pitch shed and an oil house were located on-site. In the 1940s Doran Manganese Bronze Company, Inc. Foundry & Machine Shop occupied the site. In the 1940s to 1950s, Argus Chemical Laboratory, a predecessor company to Chemtura, purchased and operated the site. Argus Chemical Laboratory was subsequently purchased by Witco (also a predecessor company to Chemtura) in the early 1960s. Under Argus and Witco ownership, the plant produced metallic-organic soaps and salts, barium stearates, phosphites and epoxy plasticizers. During the 1950s and 1960s, aluminum paste was produced in a process on the roof of one of the buildings. This

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEMTURA 633 COURT STREET (Continued)

S113828311

production ceased in the late 1950s to early 1960s and all plant operations were relocated to a parcel of land located to the southwest of the 688 Site. The laboratory and offices remained at the 633 Site until approximately 1990 when these functions were relocated to 688 Court Street. Site Geology and Hydrogeology: The Site is improved with impervious surfaces (concrete foundation of an active commercial building) which precluded extensive subsurface investigations. However, it is known that the Site and the surrounding area is reclaimed water front from what is now known as the Gowanus Canal. This historic fill material was observed from 0 to 12 ft below the ground surface (bgs). The fill material consisted primarily of fine to coarse sand-sized particles with varying amounts of silt and miscellaneous debris (ash, slag, coal, wood, brick, concrete, etc.). Underlying the fill materials, a silt-clay layer was encountered. This layer has a relatively low permeability and is believed to continue laterally across the site. This layer is gray in color and is believed to be about eight-feet thick. The Site is located approximately 400 feet west of the Gowanus Canal and ground water elevations ranges from approximately 3.5 to 6 feet bgs. Kings County lies within the Long Island aquifer system and overlies a sole-source aquifer.

Env Problem:

Nature and Extent of Contamination: Based on investigations conducted to date, the primary contaminants of concern at the site include toluene, ethylbenzene, xylene, semi-volatile organic compounds (SVOCs)/polycyclic aromatic hydrocarbons (PAHs), phenol, and metals. Soil: The VOCs toluene, ethylbenzene and xylene are found in soil from the surface to the water table. Benzene is found at 13 parts per million (ppm) at the center of the site and at 15 ppm at southern boundary of the site. This contamination is above the groundwater protection soil cleanup objective (SCO) of 0.06 parts per million (ppm) for benzene. PAHs are found throughout site soil. Benzo(a)pyrene is found in concentrations up to 62 ppm which is above the protection of groundwater SCO of 22 ppm. Metals are found throughout site soil. Lead was as high as 618 ppm, barium was found up to 590 ppm, cadmium was found up to 340 ppm, arsenic was found as high as 14.6 ppm and mercury was found as high as 2.4 ppm. Groundwater: Toluene, ethylbenzene, xylene, naphthalene and benzene are found in groundwater at concentrations up to 240, 300, 530, 3,000 and 48 parts per billion (ppb), respectively which are all above the groundwater standards of 5, 5, 5, 10 and 1 ppb, respectively. SVOCs pyrene and naphthalene are found in groundwater at concentrations up to 200 and 6,400 ppb, respectively, which are above the groundwater guidance values of 50 and 10 ppb, respectively. Soil Vapor: Two rounds of sub-slab soil vapor sampling were performed. Based on the results DOH indicated that no further sampling or mitigation would be required.

Health Problem:

Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sampling indicates soil vapor intrusion is not a

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEMTURA 633 COURT STREET (Continued)

S113828311

concern for existing on-site buildings. An evaluation of the potential for soil vapor intrusion is recommended for any future on-site buildings. Surrounding properties are in various cleanup programs and the potential for soil vapor intrusion at those sites will be evaluated separately.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-15 16:10:00
Record Upd: 2013-04-22 12:46:00
Updated By: KPSARNOW
Own Op: Owner
Sub Type: NNN
Owner Name: Alan Hertz
Owner Company: Alan B. Hertz, P.C.
Owner Address: 934 East 19th Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11230
Owner Country: United States of America
HW Code: 224146
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224146
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224146
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224146
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224146
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224146
Waste Type: ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224146
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224146
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEMTURA 633 COURT STREET (Continued)

S113828311

HW Code:	224146
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	ACETONE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	PHENOL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	V00249

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEMTURA 633 COURT STREET (Continued)

S113828311

Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2012-12-28 15:59:00
Record Updated: 2012-12-28 15:59:00
Updated By: KPSARNOW
Crossref ID: C224215
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2015-05-11 11:02:00
Record Updated: 2015-05-11 11:02:00
Updated By: CHPOST

AK198
SW
1/4-1/2
0.368 mi.
1942 ft.

GOWANUS QUICK ENERGY #1
420 SECOND AVENUE
BROOKLYN, NY 11232

NY MOSF
NY TANKS

S116349295
N/A

Site 1 of 4 in cluster AK

Relative:
Lower

MOSF:
Name: GOWANUS QUICK ENERGY #1
Address: 420 SECOND AVENUE
City,State,Zip: BROOKLYN, NY 11232
Facility ID: 0-1069
Program Type: MOSF
Tank Status: Active
Expiration Date: 03/31/2023
Dec Region: 2
UTMX: Not reported
UTMY: Not reported

Actual:
1 ft.

TANKS:

Name: GOWANUS GENERATING STATION
Address: 420 SECOND AVENUE
City,State,Zip: BROOKLYN, NY 11232
Facility Id: 2-603183
Region: STATE
DEC Region: 2
Site Status: Active
Program Type: PBS
Expiration Date: 07/27/2024
UTM X: 584169.05784
UTM Y: 4501643.68806

AJ199
NE
1/4-1/2
0.370 mi.
1956 ft.

SUNOCO
538 3RD AVE
BROOKLYN, NY

NY LTANKS

S123663795
N/A

Site 2 of 2 in cluster AJ

Relative:
Higher

LTANKS:
Name: SUNOCO
Address: 538 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1900028 / 2019-09-18
Facility ID: 1900028
Site ID: 585843

Actual:
25 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNOCO (Continued)

S123663795

Spill Date: 2019-04-01
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: Not reported
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: RHLIN
Referred To: Not reported
Reported to Dept: 2019-04-01
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2019-04-01
Spill Record Last Update: 2019-09-18
Spiller Name: Not reported
Spiller Company: SUNOCO
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: REID TUROFF
Spiller Phone: (718) 257-8470
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 537213
DEC Memo: "4/1 - Sekhon Notifier found annular sensor on alarm on super tank. Found water in annular space, pumped out water and reset sensor. Again the sensor went back into alarm on 4/1/19, they test the annular space it failed and primary tank passed, no loss of product. 4/3/19 - Sekhon Landlord: Shad LLC 150 east 58th street, suite 2400 New York, NY 10155 212-832-9100 shad@gmail.com ; Manny Shurka (manny@sigglobe.com) Tenant: Kurtuldu Huseyin 538 3rd Avenue, Brooklyn, NY 11215 718-414-7652 Huseyinkurtuld@hotmail.com Contractor: Energy Tank Inc. Energytankbklyn@aol.com Manager: Reid Turoff 516-524-9708 TTF letter send to the RP, Case assigned to DEC Lakhani for follow up. 04/17/19 - Lakhani Energy Fueling Systems (EFS) Reid Turoff submitted an update. EFS found the annular sensor in alarm on the Super Tank. Water was found in the annular space. The water was pumped out and the sensor was reset. The sensor went back into alarm at a later date on 04/01/19. EFS then tested the annular space. It failed, but the primary tank passed. There was no loss of product. EFS was instructed to take the tank out of service. 08/05/19 - Lakhani - Spill being transferred to Lin. 9/18/19-Lin-No spill occurred since primary tank passed. Tank is permanently taken out of service. Case closed. "
Remarks: "tank test failure on secondary tank- secondary part of tank is not holding"
All Materials:
Site ID: 585843
Operable Unit ID: 1333524
Operable Unit: 01
Material ID: 2342766
Material Code: 0009
Material Name: gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUNOCO (Continued)

S123663795

Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

AL200
NW
1/4-1/2
0.371 mi.
1958 ft.
CHEM TURA
688-700 COURT ST
BROOKLYN, NY 11231
Site 1 of 2 in cluster AL

NY CBS UST
NY CBS
NY DEL SHWS
RCRA NonGen / NLR
NY MANIFEST
1001485652
NY0001411404

Relative:
Higher
Actual:
9 ft.

CBS UST:
Id/Status: 2-000096 / CLOSED IN PLACE
Facility Type: D
Facility Tel: (718) 858-8694
Total Tanks: 0
Region: STATE
ICS No: 2-500035
PBS No: Not reported
MOSF No: Not reported
SPDES No: Not reported
Town: NEW YORK CITY
Operator: WITCO CORPORATION (POLYMER ADD
Emergency Contact: MARIE PITTIGNANO
Emergency Contact Phone: (203) 552-2477
Certification Date: 05/12/1999
Expiration Date: 07/07/2001
Owner Name: CK WITCO
Owner Address: ONE AMERICAN WAY
Owner City,State,Zip: BROOKLYN, NY 11231
Owner Phone: (203) 552-2477
Owner Type: 5
Owner Subtype: Not reported
Mailing Name: CK WITCO
Mailing Contact: MARIE PITTIGNANO
Mailing Address: ONE AMERICAN WAY
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11231
Mailing Telephone: (203) 552-2477
Tank Number: T5016
Date Entered: 07/07/1989
Capacity: 4000
Chemical: m-Xylene
Tank Closed: Not reported
Tank Status: Temporarily Out Of Service
Tank Type: Steel/carbon steel
Install Date: 08/70
CAS No: 108383
Substance: Not reported
Tank Location: 5
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Internal: Not reported
Pipe External: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEM TURA (Continued)

1001485652

Leak Detection:	Not reported
Secondary Containment:	Vault
Overfill Protection:	Not reported
Haz Percent:	0
Pipe Containment:	Not reported
Pipe Type:	STEEL/IRON
Tank Error Status:	Minor Data Missing
Tank Secret:	F
Date Entered:	12:04:21
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	40 40 10
Longitude:	74 00 13
Renew Date:	04/01/93
Deliquent:	F
Total Capacity:	0
Date Expired:	07/07/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T
Id/Status:	2-000096 / NO LONGER A MAJOR FACILITY
Facility Type:	D
Facility Tel:	(718) 858-8694
Total Tanks:	0
Region:	STATE
ICS No:	2-500035
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	WITCO CORPORATION (POLYMER ADD
Emergency Contact:	MARIE PITTIGNANO
Emergency Contact Phone:	(203) 552-2477
Certification Date:	05/12/1999
Expiration Date:	07/07/2001
Owner Name:	CK WITCO
Owner Address:	ONE AMERICAN WAY
Owner City,State,Zip:	BROOKLYN, NY 11231
Owner Phone:	(203) 552-2477
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	CK WITCO
Mailing Contact:	MARIE PITTIGNANO
Mailing Address:	ONE AMERICAN WAY
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11231
Mailing Telephone:	(203) 552-2477
Tank Number:	F203
Date Entered:	04/26/1995
Capacity:	4000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEM TURA (Continued)

1001485652

Chemical:	Benzene,1-methylethyl-
Tank Closed:	12/99
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Install Date:	06/93
CAS No:	98828
Substance:	Single Hazardous Substance on DEC List
Tank Location:	Outdoors, Belowground
Tank Internal:	Epoxy Liner
Tank External:	SACRIFICIAL ANODE
Pipe Location:	Aboveground/Underground Combination
Pipe Internal:	None
Pipe External:	None
Leak Detection:	Interstitial Monitoring
Secondary Containment:	Cut-off Walls
Overfill Protection:	High Level Alarm
Haz Percent:	100
Pipe Containment:	None
Pipe Type:	STEEL/IRON
Tank Error Status:	No Missing Data
Tank Secret:	F
Date Entered:	14:34:01
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	40 40 10
Longitude:	74 00 13
Renew Date:	04/01/93
Deliquent:	F
Total Capacity:	0
Date Expired:	07/07/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T

CBS:

Name:	WITCO CORPORATION (POLYMER ADDITIVES GROUP)
Address:	700 COURT STREET
City,State,Zip:	BROOKLYN, NY 11231
CBS Number:	2-000096
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	584344.69793
UTMY:	4502565.34770

DEL SHWS:

Name:	CHEMTURA 688-700 COURT STREET
Address:	688-700 COURT STREET
City,State,Zip:	BROOKLYN, NY 11231

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEM TURA (Continued)

1001485652

Year: Not reported
Site Code Id: Not reported
Site Classification: Not reported
Region: 2
Epa Id Number: Not reported
Site Type - Dump: No
Site Type - Structure: No
Site Type - Lagoon: No
Site Type - Landfill: No
Site Type - Treat Pond: No
Site Size (Acres): Not reported
Site Size Comment: Not reported
Period Assoc/HW Start: Not reported
Period Assoc/HW End: Not reported
Lat/Long: Not reported
Lat/Long Decimal: Not reported
Lat/Long (dms): Not reported
Hazardous Waste Code: 224145
Hazard Waste Disposed: Not reported
Quantity: Not reported
Air Data Available: No
SW Std Contravention: No
GW Std Contravention: No
Soil Type: Not reported
Sediment Data Available: No
GW Std Contravention: No
DW Std Contravention: No
SW Std Contravention: No
Air Stand Contraventions: No
Legal Action Type: Not reported
State Legal Action: No
Federal Legal Action: No
Enforce Status Code: Not reported
Remedial Act Proposed: No
Rem Act Under Design: No
Rem Act In Progress: No
Rem Act Completed: No
Remedial Action Type: Not reported
Soil Type: Not reported
Depth To Groundwater: Not reported
Owner Name: Not reported
Owner Address: Not reported
Owner City,St,Zip: Not reported
Owner Phone: Not reported
Owner Contact Name: Not reported
Owner During Disposal: Not reported
Owner During Use: Not reported
Operator Name: Not reported
Operator Address: Not reported
Operator City,St,Zip: Not reported
Operator Phone: Not reported
Operator Contact Name: Not reported
Oper During Disposal: Not reported
Site Type: Not reported
HW Disposal Period: Not reported
Analytical Data Available: Not reported
Applicable Std Exceeded: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEM TURA (Continued)

1001485652

Geotech Info:	Not reported
Depth To Groundwater:	Not reported
Status:	Not reported
Nature Of Action:	Not reported
Env Prob Assessment:	Not reported
Site Description:	Not reported
Confirmed HW:	Not reported
Environment Assesment:	Not reported
Health Assesment:	Not reported
Disposal Start Date:	Not reported
Disposal Term Date:	Not reported
Air Violation:	Not reported
Groundwater Violation:	Not reported
Drink Water Violation:	Not reported
Surface Water Violation:	Not reported
Legal New York State:	Not reported
Legal Federal:	Not reported
Legal State:	Not reported
Remedial Action Active:	Not reported
Remedial Action Done:	Not reported
NPL Status:	Not reported
Count Operator:	Not reported
Count Owner:	Not reported
NYTM X:	Not reported
NYTM Y:	Not reported
Co Name:	Not reported
Co Addr:	Not reported
Operator Addr:	Not reported
Operator Addr 2:	Not reported
Operator Addr 3:	Not reported
Operator Addr 4:	Not reported
HWDP From:	Not reported
From To:	Not reported
Assessment of Health:	Access to the site is restricted. However, persons who enter the site could contact contaminants in the soil by walking on the site, digging or otherwise disturbing the soil. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sampling indicates soil vapor intrusion is not occurring on-site and is not a concern for off-site buildings.
Description:	Location:The site is located at 688-700 Court Street within the Red Hook Industrial area of Brooklyn. The site is located southwest of the Court Street and Halleck Street intersection.Site Features:The site is relatively flat and mostly covered with blacktop and concrete. A small area in the southeast corner has a soil cover. Several previously decommissioned site buildings were either removed or rehabilitated without the Department's approval. The site is occupied by several tenants including a garbage hauling company, a motor coach repair facility, an electronics distribution warehouse, a commercial laundry repair business, a stone cutting business and a sheet metal fabricator. The dual-phase extraction remedial system is not operational. The site is surrounded with a concrete wall of

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEM TURA (Continued)

1001485652

varying height. Current Zoning and Land Use: The site is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial, light industrial and recreational uses. The site is bordered immediately to the east by Court Street, National Grid and Spentonbush Red Star Companies, to the west by Clinton Street and American Import Export Trucking and to the south by Bryant Street and a Buckeye, LLC oil terminal. A recreational park (Red Hook Recreational) is located immediately to the north of the site. Past Use of the Site: Milliken Brothers Iron Works occupied the southwestern portion of the site in 1904. In 1939 John F. McKenna, Inc. Lumber Yard, Marine Canvas Supply Corporation and John Menton Boiler Maker occupied the site. The site remained a lumberyard and marine canvas supply business until approximately 1958, when manufacturing at the site began. Historic manufacturing processes at the site include production of metallic-organic soaps and salts, phosphates and epoxy plasticizers. A hot-oil system, that used PCB containing oil, was part of the manufacturing process. Contamination at the site appears related to several historic operations, including materials handling from the chemical manufacturing processes, as well as releases to the environment from the hot oil system. Site Geology and Hydrogeology: The site was formed by backfilling the marsh and waterfront areas of the Gowanus Canal in the late 1800s through the early 1900s. Fill material consisting of fine to coarse sand-sized particles with varying amounts of silt and miscellaneous debris (ash, slag, coal, wood, brick, concrete, etc.) was observed across the site from ground surface to a depth of 12 ft. A clay layer of unknown thickness or continuity was encountered beneath the fill material. This layer is presumed to be the former base of the Gowanus Canal. The effectiveness of this layer as a low-permeability barrier between the overlying fill and the underlying water-bearing zone located within the glacial deposits beneath the site is unknown. Based on the manmade coastline (rip-rap, pile sheeting), well gauging data and the generalized hydrogeological cross-sections, a horizontal and somewhat radial (north, northwest, west, southwest, south) pathway for groundwater flow exists. Depth to water beneath the site has ranged from 2.0 ft to 9.0-ft bgs over the course of investigation. Groundwater beneath the site is minimally influenced by the tide. Groundwater flow is radial with a high point in the central part of the site.

Record Added Date: 12/03/2010
Record Updated Date: 01/05/2016
Env Assessment: Not reported
HW Disposed/Quantity: Not reported
Assess/Env Prog: Not reported
Assess/Health Prob: Not reported
Site Description: Not reported

RCRA NonGen / NLR:

Date form received by agency: 2012-10-15 00:00:00.0
Facility name: CHEM TURA
Facility address: 688-700 COURT ST
BROOKLYN, NY 11231
EPA ID: NY0001411404
Mailing address: BENSON RD
MIDDLEBURY, CT 06749
Contact: PAUL MEYER
Contact address: BENSON RD

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEM TURA (Continued)

1001485652

MIDDLEBURY, CT 06749
Contact country: US
Contact telephone: 203-573-3545
Contact email: PAUL.MEYER@CHEMTURA.COM
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: VIP BUILDERS LLC
Owner/operator address: REALTY LLC 400 BROOME ST
NEW YORK, NY 10013
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2004-03-23 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: VIP BUILDERS LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2004-03-23 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2012-07-18 00:00:00.0
Site name: CHEM TURA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEM TURA (Continued)

1001485652

Classification: Large Quantity Generator

Date form received by agency: 2007-01-01 00:00:00.0
Site name: WITCO CORP
Classification: Not a generator, verified

Date form received by agency: 2006-01-01 00:00:00.0
Site name: WITCO CORP
Classification: Not a generator, verified

Date form received by agency: 2001-01-01 00:00:00.0
Site name: CK WITCO CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 1998-11-27 00:00:00.0
Site name: WITCO CORP
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: B007
. Waste name: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D013
. Waste name: LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEM TURA (Continued)

1001485652

. Waste code: D031
. Waste name: HEPTACHLOR (AND ITS EPOXIDE)

Violation Status: No violations found

NY MANIFEST:

Name: CHEM TURA
Address: 688-700 COURT ST
City,State,Zip: BROOKLYN, NY 11231
Country: USA
EPA ID: NY0001411404
Facility Status: Not reported
Location Address 1: 688-700 COURT STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11231
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NY0001411404
Mailing Name: CHEM TURA
Mailing Contact: MARTIN DONAHUE
Mailing Address 1: 199 BENSON ROAD
Mailing Address 2: Not reported
Mailing City: MIDDLEBURY
Mailing State: CT
Mailing Zip: 06749
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 4356558110

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: MAD039322250
Trans2 State ID: NJD071629976
Generator Ship Date: 03/28/2018
Trans1 Recv Date: 03/28/2018
Trans2 Recv Date: 04/04/2018
TSD Site Recv Date: 04/05/2018
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0001411404
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: OHD000816629
TSDF ID 2: Not reported
Manifest Tracking Number: 011800335FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHEM TURA (Continued)

1001485652

Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 450
Units: P - Pounds
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Waste Code: Not reported
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: B003
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AL201
NW
1/4-1/2
0.371 mi.
1958 ft.

WITCO CORPORATION BROOKLYN PLANT
633 AND 688-700 COURT STREET
BROOKLYN, NY 11231

NY VCP S113922164
N/A

Site 2 of 2 in cluster AL

Relative:
Higher
Actual:
9 ft.

VCP:
Name: WITCO CORPORATION BROOKLYN PLANT
Address: 633 AND 688-700 COURT STREET
City,State,Zip: BROOKLYN, NY 11231
Program Type: VCP
Site Code: 58750
HW Code: V00249
Site Class: N
SWIS: 2401
Region: 2
Town: New York City
Acres: Not reported
Date Record Added: 11/30/2000
Date Record Updated: 07/14/2004
Updated By: VCPTRANS
Site Description: See projects 224145 and 224146
Env Problem: Not reported
Health Problem: Not reported
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WITCO CORPORATION BROOKLYN PLANT (Continued)

S113922164

Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Owner
Sub Type: ZZZ
Owner Name: Not reported
Owner Company: WITCO CORPORATION (FOR 688-700 SITE)
Owner Address: ONE AMERICAN LANE
Owner Addr2: Not reported
Owner City,St,Zip: GREENWICH, CT 06831-2559
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: ZZZ
Owner Name: Not reported
Owner Company: Witco Corporation
Owner Address: ONE AMERICAN LANE
Owner Addr2: Not reported
Owner City,St,Zip: GREENWICH, CT 06831-2559
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

202
WNW
1/4-1/2
0.375 mi.
1979 ft.

**GOUWANUS BAY
COURT ST- PIER 8
BROOKLYN, NY**

**NY LTANKS S102960154
N/A**

**Relative:
Lower**

LTANKS:

**Actual:
0 ft.**

Name: GOUWANUS BAY
Address: COURT ST- PIER 8
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9710375 / 1997-12-10
Facility ID: 9710375
Site ID: 71263
Spill Date: 1997-12-10
Spill Cause: Tank Failure
Spill Source: Vessel
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 1997-12-10
CID: 257
Water Affected: GOUWANUS BAY
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOUWANUS BAY (Continued)

S102960154

Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1997-12-10
Spill Record Last Update: 1997-12-15
Spiller Name: JOHN BOWIE
Spiller Company: SPENTONBUSH RED STAR
Spiller Address: 1185 AVE OF AMERICA'S
Spiller County: 001
Spiller Contact: PETER HACKETT
Spiller Phone: (718) 354-4136
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 67469
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
MARTINKAT "

Remarks: "leaking fuel tank driver is repairinf and leak is being cleaned up "

All Materials:

Site ID: 71263
Operable Unit ID: 1056747
Operable Unit: 01
Material ID: 328676
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: 2.00
Oxygenate: Not reported

203
SE
1/4-1/2
0.375 mi.
1982 ft.

**707 5TH AVENUE
707 5TH AVENUE
BROOKLYN, NY**

NY LTANKS

**S102672192
N/A**

**Relative:
Higher
Actual:
76 ft.**

LTANKS:
Name: 707 5TH AVENUE
Address: 707 5TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9304083 / 1993-06-30
Facility ID: 9304083
Site ID: 132567
Spill Date: 1993-06-30
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: D4
Cleanup Ceased: 1993-06-30
SWIS: 2401
Investigator: CAMMISA
Referred To: Not reported
Reported to Dept: 1993-06-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

707 5TH AVENUE (Continued)

S102672192

Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1993-07-01
Spill Record Last Update: 1993-07-20
Spiller Name: Not reported
Spiller Company: PETROLEUM HEAT & POWER
Spiller Address: 3616 19TH AVE ASTORIA
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 114127
DEC Memo: ""
Remarks: "AUTOMATIC DELIVERY - SPEEDI DRI WILL BE USED - CLEAN UP IS BEING COMPLETED - FDNY ON SCENE."

All Materials:

Site ID: 132567
Operable Unit ID: 985818
Operable Unit: 01
Material ID: 397610
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 12.00
Units: G
Recovered: .00
Oxygenate: Not reported

AM204
NNW
1/4-1/2
0.376 mi.
1986 ft.

**182 SIGOURNEY ST
182 SIGOURNEY ST
BROOKLYN, NY 11231**

**NY SHWS S117667764
N/A**

Site 1 of 2 in cluster AM

**Relative:
Higher
Actual:
8 ft.**

SHWS:

Name: 182 SIGOURNEY ST
Address: 182 SIGOURNEY ST
City,State,Zip: BROOKLYN, NY 11231
Program: HW
Site Code: 499845
Classification: P
Region: 2
Acres: 0.28999999999999998
HW Code: 224197
Record Add: 09/15/2014
Record Upd: 10/16/2019
Updated By: GWBURKE

Site Description: Location: The site is located in the Red Hook section of Brooklyn, in the City of New York. The site consists of two parcels listed as Block 492, Lot 20 (628 Smith Street) and Block 492, Lot 15 (182 Sigourney Street) on NYC tax maps. The site is at the intersections

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

182 SIGOURNEY ST (Continued)

S117667764

of Halleck Street, Smith Street and Sigourney Streets. The site is approximately 200-300 feet west of the Gowanus Canal. Site Features: The site is primarily covered with a multi-story brick building with courtyard parking accessible from Sigourney Street. Current Zoning and Land Use: The current site use is not known but appears to be occupied with commercial and/or industrial operations. Historical Use: The property was used for tar paper manufacturing. A 1904 Sanborn Insurance Map depicts coal tar products, asphalt tanks and various oil tanks (including a 14,000-gallon underground tank). The Sanborn Map indicates that this property was operated by Barrett Manufacturing Company. Site Geology and Hydrogeology: Based on geological information at an adjacent site, the groundwater at this property is anticipated to be approximately 5 feet bgs. Groundwater flow is anticipated to flow toward the Gowanus Canal traveling east and/or southeast. The groundwater is likely saline due to its proximity to the canal. Much of this area is reclaimed water front property with fill material anticipated to exist from 0 to 12 feet bgs. A gray colored, low permeability clayey layer (former base of the Gowanus Canal) is also anticipated beneath the fill material with a thickness varying up to eight feet.

Env Problem: Investigations at adjacent properties indicate tar-like source material, light non-aqueous phase liquid (LNAPL) and petroleum VOCs are present in the soil and at the soil/groundwater interface. Downgradient and to the east of this potential site is the Red Hook Smith Street Brownfield Cleanup Program (volunteer) site (C224163) where tar-like material, metals, VOCs and SVOCs were identified. West of this potential site is the 633 Court St. (Chemtura #224146) site and the Red Hook Smith Recreation Area; tar-like material has been identified in each of these locations. A portion of the Red Hook Smith Street BCP and the 633 Court Street (Chemtura) property were both previously part of the former Barrett Manufacturing property. To the south is a State Superfund P-site (224196) where tar boils have been identified on site, which was initially Mica Roofing Company. Investigation of this site is warranted.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Owner
Sub Type: NNN
Owner Name: Jerrold Lerner
Owner Company: Magrill Bros, Inc.
Owner Address: 247 W. 16th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011-6065
Owner Country: United States of America

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

182 SIGOURNEY ST (Continued)

S117667764

Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: 610 Smith St. Corp.
Owner Address: 111 John St. Rm 312
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10038-3135
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

AN205
SSE
1/4-1/2
0.388 mi.
2048 ft.

740 5TH AVE
740 5TH AVENUE
BROOKLYN, NY

NY LTANKS
NY Spills

S100144732
N/A

Site 1 of 2 in cluster AN

Relative:
Higher
Actual:
64 ft.

LTANKS:
Name: EXXONMOBIL
Address: 740 5TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8703559 / Not Reported
Facility ID: 8703559
Site ID: 126157
Spill Date: 1987-07-31
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: MJHAGGER
Referred To: Not reported
Reported to Dept: 1987-07-31
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 4
Date Entered In Computer: 1987-08-04
Spill Record Last Update: 2016-04-04
Spiller Name: MELISSA WINSOR
Spiller Company: EXXONMOBIL
Spiller Address: 3225 GALLOWES ROAD
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

740 5TH AVE (Continued)

S100144732

DEC Region:
DER Facility ID:
DEC Memo:

2
109106
"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill case was reassigned from DEC (Sigona) to Rommel on 02/10/2004. 04/27/05- Bureau B, unassigned, due to low priority. Transferred from R-2. 12/20/06- reassigned to Chris Milack, Central Office (Milack) 12/29/06- Groundwater investigation work plan approved. Plan calls for sampling of 3 wells on property that were previously installed for the investigation of spill #93-05122. (Milack) 5/24/07- GW investigation report was received 5/18/07. Two wells were sampled, one well was dry. Both wells had concentrations of MTBE that exceeded standards. Consultant will be submitting an additional investigation WP. Quarterly sampling will continue. 7/2/08 - Haggerty: assumed project management from Chris Milack 9/19/08 - Haggerty: approved SI workplan 11/25/08 - Haggerty: SI workplan altered due to the presence of oil-cooled high pressure gas mains along 24th Street. See email and revised figure in edocs 4/20/09 - Haggerty: approved SIR with the following comments: 1. Add Tertiary Butyl Alcohol (TBA) to the groundwater sampling protocol. 2. The 12 abandoned 550gal tanks must be removed as well as the former dispenser areas. Provide a UST Removal work plan within 60 days of the receipt of this email. 3. I agree with waiting 2 quarters before further groundwater delineation, if any, is performed. 6/19/09 - Haggerty: had conference call with Ken Drake from ExxonMobil and Kleinfelder. ExxonMobil states they are not willing to remove the tanks because there is an issue of who owns the tanks. They will gather more information and get back to me. PM forwarded this spill to Scott Owens (OGC) for follow-up May 2010 - Due to various underground utilities, off-site delineation is proving to be difficult. PM instructed Mobil to get access to a property across 24th Street to install a MW. This appears to be our only option of delineation at this time. Discontinued EFT events due to poor recovery, really tight soil July 2010 - EM granted access to off-site location to complete delineation August 2010 - Offsite well well installed 8/3 February 2011 - offsite well show high levels of gasoline contamination (20,000ppb BTEX) but little MTBE. On-site contamination predominately MTBE June 2011 - SSUR overdue July 2011 - reviewed SSUR. EM continues to only propose continued gw sampling when the site obviously needs active remediation. Left message with Jackie Fawcett, EM, to discuss August 2011 - sent email requiring ExxonMobil to submit a Pilot Test work plan to address both soil and groundwater contamination within 45 days (due 9/17/11) Sept. 2011 - approved Feasibility study work plan for SVE/AS January 2012 - EM switched consultant's to GES. SVE/AS pilot test failed, not viable. Heavy BTEX dissolved concentrations encountered in new wells (50,000+ppb) February 2012 - discussing the site on 2/28/12 when EM and GES come to Albany. My conceptual model changed since the new gw data came in April 2012 - EM's SVE pilot test was a complete failure based on the lithology. Tank/line removal, over-excavation is the only fiable solution to source removal. EM states they won't remove the tanks because some were sold to the owner. PM needs assistance from OGC August 2012 - With OGC's involvement, EM has agreed to drill through the tanks which will only prove that EM is responsible for removing the tanks December 2012 - Wells in the former tank area should have been installed at this point but I was unable to confirm with the GES PM. January 2, 2012 - according to GES Project Manager, installation of tank field wells was delayed. Installation will begin

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

740 5TH AVE (Continued)

S100144732

1/8/13 May 2013 - OGC and EM legal contacted regarding this site. The groundwater is grossly contaminated (80,000ppb of VOCs). Dept. required EM to excavate the source (old tanks and associated contaminated soil) but EM won't sign a Consent Order or perform the work. EM already performed an SVE/AS pilot test which failed. Now, EM wants to perform another SVE pilot test October 28 2013 - ExxonMobil has agreed to sign the Consent Order and remove the tanks and contaminated soil. Workplan due in 30 days December 2013 - PM sent comment letter to ExxonMobil. The work plan was revised and resubmitted. Currently under review January 6, 2014 - revised workplan approved April 2014 - Excavation work plan approved in January but we are still waiting on the access agreement with the property owner September 2014 - Haggerty: excavation per the RAP complete January 2015 - Haggerty: post-excavation MWs installed. PM required 4 quarters of performance groundwater monitoring."
"TANK-TEST FAILURE. ISOLATE, REPAIR, AND RE-TEST."

Remarks:

All TTF:

Facility ID: 8703559
Spill Number: 8703559
Spill Tank Test: 1531247
Site ID: 126157
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 126157
Operable Unit ID: 907446
Operable Unit: 01
Material ID: 469788
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: 740 5TH AVE
Address: 740 5TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9806222 / 2007-09-17
Facility ID: 9806222

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

740 5TH AVE (Continued)

S100144732

Facility Type: ER
DER Facility ID: 109106
Site ID: 72767
DEC Region: 2
Spill Cause: Other
Spill Class: C3
SWIS: 2401
Spill Date: 1998-08-19
Investigator: WXSUN
Referred To: SEE SPILL # 87-03559
Reported to Dept: 1998-08-19
CID: 257
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1998-08-19
Spill Record Last Update: 2013-12-06
Spiller Name: Not reported
Spiller Company: BATROUNI S/S
Spiller Address: Not reported
Spiller Company: 001
Contact Name: DAVID EKSTRAND
DEC Memo: "3/17/06 - Nathan - Another spill, 8703559, at the same location may be handled by a PRP. Next step, the owner at the time of this spill needs to be determined as it may be different from the '87 spill.
7/8/05 - Nathan - File review Site Assessment Report (8/27/98) 12X550 tanks closed in place. One waste oil tank remains in place passed test (6/23/98). Three Borings drilled, PID reading of 400 ppm in one. End points where below STARS. GW ~ 600 ppb Benzene. There are other gas stations in the area. Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL TRANSFERRED FROM TIBBE TO ROMMEL 04/12/04 11/02/06 Reassigned from Rommel to Sun.(MS) 8/1/07: C. Milack is DEC project manager for spill #87-03559. (JS/MS) 8/13/07: GW investigation report was received in May 2007 in which one well was dry and two indicated MTBE in concentrations exceeding GW standards. Consultant is to submit an additional work plan. (JS/MS) 9/18/07: This spill was closed on 9/17/07. The spill case will be tracked and remediated under spill number 87-03559, project manager C. Milack. (JS/MS)"

Remarks: "old gas station property and caller did some soil ssamples and found contaminated soil on property"

All Materials:
Site ID: 72767
Operable Unit ID: 1063870
Operable Unit: 01
Material ID: 317395
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

740 5TH AVE (Continued)

S100144732

Units: G
Recovered: .00
Oxygenate: Not reported

AO206
ENE
1/4-1/2
0.389 mi.
2056 ft.

535 4TH AVENUE
535 4TH AVENUE
NEW YORK CITY, NY

NY VCP

S125317142
N/A

Site 1 of 3 in cluster AO

Relative:
Higher

VCP NYC:
Project ID: 15TMP0451K, 15EHAZ451K
Name: 535 4TH AVENUE
Address: 535 4TH AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn

Actual:
53 ft.

AN207
SSE
1/4-1/2
0.391 mi.
2062 ft.

TEXACO SERVICE STATION - TTF
735 5TH AVENUE
BROOKLYN, NY

NY LTANKS

S102618896
N/A

Site 2 of 2 in cluster AN

Relative:
Higher

LTANKS:
Name: TEXACO SERVICE STATION - TTF
Address: 735 5TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9702464 / 2014-11-28
Facility ID: 9702464
Site ID: 161348
Spill Date: 1997-05-28
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 1997-05-28
CID: 204
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1997-05-28
Spill Record Last Update: 2014-11-28
Spiller Name: MICHAEL
Spiller Company: TEXACO SERVICE STATION
Spiller Address: 735 5TH AVENUE
Spiller County: 001
Spiller Contact: JERRY KASPAR
Spiller Phone: (800) 646-3161

Actual:
72 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO SERVICE STATION - TTF (Continued)

S102618896

Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 136233
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 1/2/2004 Reassigned from Tomasello to Sun. Austin - 3/3/10 - Reassigned from Sun to Krimgold for investigation of this TTF to ascertain the nature and status of this spil event - end 08/13/12 - LZ As Randy Austin requested, the spill has been reassigned to Tim DeMeo. 10/10/14-Hiralkumar Patel. reviewed available information for DEC DeMeo. alternate address for 735 5th Ave: 725-737 5th Avenue, 738 6th Avenue, 236-282 23rd Street, 333-415 24th Street the site is occupied by ConEd's Greenwood Substation. PBS #: 2-452769. as per PBS record, the site has/had following tanks: - one (1) 1,080 gal diesel UST, closed-in-place in Sep. 1998 - one (1) 550 gal diesel AST on legs, installed in Sep. 1998 - one (1) 50 gal diesel AST on legs, installed in Dec. 1981 the subject spill report was filed on 05/28/1997 for a Texaco Service Station, due to tank test failure of 4,000 gal tank. there is no information about material type in the spill report. the site is occupied by ConEd substation and not a service station. also as per PBS record, there is no record of 4,000 gal tank at 735 5th ave. information does not match. 10/6/14 TJD Site inspection - address not found (based upon reported address the site is either a Con Edison sub-station or a Cemetery). A Citgo S/S is operating at 745 5th Avenue, this location was inspected and onsite representative (Bernard Mays) was interviewed. He states station currently operating as a Citgo was formerly a Shell, Pronto & Texaco is reverse chronological order. The station operator states that no paperwork is available prior to changing to Citgo as the operator has changed multiple times. The onsite representqtative was able to provide passing tank tightness testing records for all (5) tanks in operation at site - dates of test reports available for review onsite were 7/23/13 and 7/7/14. A review of PBS records (EDOCS) reveal multiple passing tank test reports for the same (5) UST's are part of the PBS (2-332720) file. As the address is incorrect and current passing tightness tests are available - no further action is required. Spill is administratively closed."

Remarks: "TANK TEST FAILURE "

All TTF:

Facility ID: 9702464
Spill Number: 9702464
Spill Tank Test: 1545135
Site ID: 161348
Tank Number: 001
Tank Size: 4000
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 20
Test Method 2: USTest 2000/P/LL plus USTest 2000/U
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AK208
SW
1/4-1/2
0.393 mi.
2073 ft.

SIMS METAL MUNICIPAL RECYCLING LLC
472 2ND AVE
BROOKLYN, NY 11232

NY CBS **S117234141**
NY SWRCY **N/A**

Site 2 of 4 in cluster AK

Relative:
Lower

CBS:

Actual:
1 ft.

Name: SUNSET PARK MATERIAL RECOVERY FACILITY
Address: 472 2ND AVE
City,State,Zip: BROOKLYN, NY 11232
CBS Number: 2-000513
Program Type: CBS
Facility Status: Unregistered
Expiration Date: Not reported
Dec Region: 2
UTMX: 584143.44950
UTMY: 4501631.74512

SWRCY:

Name: SIMS METAL MUNICIPAL RECYCLING LLC
Address: 472 2ND AVE
City,State,Zip: BROOKLYN, NY 11232
Region: 2
Facility Address 2: Not reported
Phone Number: 3474298097
Owner Type: Private
Owner Name: Sims Metal Mangement
Owner Address: 1 Linden Ave East
Owner Address 2: Not reported
Owner City,St,Zip: Jersey City, NY 7305
Owner Email: Not reported
Owner Phone: 2015773218
Contact Name: Scott Quinn
Contact Address: Not reported
Contact Address 2: Not reported
Contact City,St,Zip: Not reported
Contact Email: scott.quinn@simsmm.com
Contact Phone: 3473913053
Activity Desc: RHRF - registration
Activity Number: [24MG0]
Active: Yes
East Coordinate: 584149
North Coordinate: 4501633
Accuracy Code: Not reported
Regulatory Status: Registration
Permit #: 24MG0
Auth. Date: Not reported
Expiration Date: Not reported
Waste Types: Source Separated Recyclables (Metal/Glass/Paper/Plastic);PET
Operator Name: Gary Osman
Operator Type: Private
Last Date: 1/5/2017

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AP209
SSW
1/4-1/2
0.395 mi.
2083 ft.
Site 1 of 2 in cluster AP

SEMS-ARCHIVE
RCRA NonGen / NLR
1000140475
NY4470000635

Relative:
Higher
Actual:
10 ft.

SEMS Archive:
Site ID: 0203254
EPA ID: NY4470000635
Name: U.S. INFORMATION AGENCY
Address: 29 TH STREET AND 3RD AVENUE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Cong District: 13
FIPS Code: 36047
FF: Y
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region: 02
Site ID: 0203254
EPA ID: NY4470000635
Site Name: U.S. INFORMATION AGENCY
NPL: N
FF: Y
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1989-12-31 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 02
Site ID: 0203254
EPA ID: NY4470000635
Site Name: U.S. INFORMATION AGENCY
NPL: N
FF: Y
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: Not reported
Finish Date: 1989-12-31 05:00:00
Qual: N
Current Action Lead: EPA Perf

Region: 02
Site ID: 0203254
EPA ID: NY4470000635
Site Name: U.S. INFORMATION AGENCY
NPL: N
FF: Y
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US INFORMATION AGENCY (Continued)

1000140475

Start Date: 1989-10-01 04:00:00
Finish Date: 1989-10-01 04:00:00
Qual: Not reported
Current Action Lead: Fed Fac

RCRA NonGen / NLR:

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: US INFORMATION AGENCY
Facility address: 29TH ST & 3RD AVE DOOR 15
BROOKLYN, NY 11232
EPA ID: NY4470000635
Mailing address: 3RD AVE
BROOKLYN, NY 11232
Contact: MICHAEL CARROLL
Contact address: 3RD AVE
BROOKLYN, NY 11232
Contact country: US
Contact telephone: 718-965-5747
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: US GOVERNMENT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Federal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: US GOVERNMENT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Federal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US INFORMATION AGENCY (Continued)

1000140475

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: US INFORMATION AGENCY
Classification: Not a generator, verified

Date form received by agency: 1986-03-28 00:00:00.0
Site name: US INFORMATION AGENCY
Classification: Not a generator, verified

Hazardous Waste Summary:

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

AM210
NNW
1/4-1/2
0.396 mi.
2090 ft.

FIRST BROOKLYN TRANSFER STA.
611 COURT ST.
BROOKLYN, NY 11231

NY SWF/LF S105841721
N/A

Site 2 of 2 in cluster AM

Relative:
Higher

Actual:
7 ft.

SWF/LF:
Name: FIRST BROOKLYN TRANSFER STA.
Address: 611 COURT ST.
City,State,Zip: BROOKLYN, NY 11231
Flag: INACTIVE
Region Code: 2
Phone Number: 7187970888
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: ANTHONY VITALE; V.P.
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: Transfer station - permit
Activity Number: [24T44]
Active: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FIRST BROOKLYN TRANSFER STA. (Continued)

S105841721

East Coordinate: 584300
North Coordinate: 4502800
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: 2-6102-00044
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Last Date: Not reported

**AO211
ENE
1/4-1/2
0.399 mi.
2105 ft.**

**FORMER STRAUSS AUTO - OFF-SITE
521-539 4TH AVENUE
BROOKLYN, NY 11215**

**NY BROWNFIELDS S118372392
N/A**

Site 2 of 3 in cluster AO

**Relative:
Higher**

BROWNFIELDS:

**Actual:
52 ft.**

Name:
Address:
City,State,Zip:
Program:
Site Code:
Acres:
HW Code:
SWIS:
Town:
Record Added Date:
Record Updated Date:
Update By:
Site Description:

FORMER STRAUSS AUTO - OFF-SITE

521-539 4TH AVENUE
BROOKLYN, NY 11215
BCP
517274
Not reported
C224189A
2401
New York City
11/23/2015
01/17/2019
MJKOMORO

The following description is for the associated BCP site: Site Location: The Former Strauss Auto site is located in an urban area at 521-539 4th Avenue in the Park Slope neighborhood of Brooklyn. The 18,200 square foot property is bounded by 14th Street to the north, 4th Avenue to the west, and 15th Street to the south. Multi-family residences are located to the east and an elementary school (PS 124) sits directly across 14th Street to the north. A subway line runs down 4th Avenue, a major commercial thoroughfare. Site Features: The site is currently vacant. A 14,640 square foot one-story automotive garage and attached sales building with partial basement previously occupied the site. The building included a vehicle service area, retail and stock areas, and administrative offices. An asphalt and concrete-paved parking lot was located on the western side of the property. The building was vacant from approximately June 2012 onward and was demolished in December 2014. The site is at an elevation of about 55 feet above sea level, and the site and the surrounding area slope toward the Gowanus Canal, which is approximately 2,500 feet northwest of the site. Current Zoning and Land Use: The site is zoned R8A residential with a C2-4 commercial overlay. Past Use of the Site: The site originally had two churches on it. Building records indicate the most recent structures were completed in 1944 with additions and/or alterations completed in 1946 and 1947. Automotive sales operations took place there since at least 1944. Automotive service operations started sometime between 1951 and 1965. Records indicate the most recent owner of the property, Strauss Auto Center, occupied the site from at least 1983 until 2012. Various underground storage tanks, sumps, floor drains, and pits are present from when the site

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER STRAUSS AUTO - OFF-SITE (Continued)

S118372392

	was used for automotive service operations, and the site was listed as a generator of tetrachloroethene waste from 1995 to 2002. Site Geology and Hydrogeology: Soil beneath the site consists of historic fill material, including predominately fine to coarse sand with varied amounts of brick fragments, gravel, milled and crushed asphalt, and ash. The fill extends to depths of up to 11 feet below ground surface. Historic fill is underlain primarily by glacial till, which in turn is underlain by a thick clay layer found at depths ranging between 40 and 60 feet below ground level. Bedrock was not encountered during investigations of the site, but the depth to bedrock in the vicinity of the site is reportedly 200 feet below ground level. The depth to groundwater across the site ranged from 31.5 to 37.7 feet and the groundwater flows to the north-northwest.
Env Problem:	Based on the work done for the on-site portion of this site, the potential exists for off-site contaminated groundwater and soil vapor, although the extent of this, if any, is not known at this time. It is entirely possible that the off-site contamination may be affected or addressed by the remediation occurring on-site.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AO212
ENE
1/4-1/2
0.399 mi.
2105 ft.

FORMER STRAUSS AUTO
521-539 4TH AVENUE
BROOKLYN, NY 11215

Site 3 of 3 in cluster AO

NY BROWNFIELDS **S116550040**
N/A

Relative:
Higher
Actual:
52 ft.

BROWNFIELDS:

Name: FORMER STRAUSS AUTO
Address: 521-539 4TH AVENUE
City,State,Zip: BROOKLYN, NY 11215
Program: BCP
Site Code: 493274
Acres: 0.418
HW Code: C224189
SWIS: 2401
Town: New York City
Record Added Date: 04/02/2014
Record Updated Date: 12/28/2018
Update By: MJKOMORO
Site Description:

Site Location: The Former Strauss Auto site is located in an urban area at 521-539 4th Avenue in the Park Slope neighborhood of Brooklyn. The 18,200 square foot property is bounded by 14th Street to the north, 4th Avenue to the west, and 15th Street to the south. Multi-family residences are located to the east and an elementary school (PS 124) sits directly across 14th Street to the north. A subway line runs down 4th Avenue, a major commercial thoroughfare. Site Features: A 14,640 square foot one-story automotive garage and attached sales building with partial basement previously occupied the site. The building included a vehicle service area, retail and stock areas, and administrative offices. An asphalt and concrete-paved parking lot was located on the western side of the property. The building was vacant from approximately June 2012 onward and was demolished in December 2014. The site is at an elevation of about 55 feet above sea level, and the site and the surrounding area slope toward the Gowanus Canal, which is approximately 2,500 feet northwest of the site. Current Zoning and Land Use: The site is zoned R8A residential with a C2-4 commercial overlay. Past Use of the Site: The site originally had two churches on it. Building records indicate the most recent structures were completed in 1944 with additions and/or alterations completed in 1946 and 1947. Automotive sales operations took place there since at least 1944. Automotive service operations started sometime between 1951 and 1965. Records indicate the most recent owner of the property, Strauss Auto Center, occupied the site from at least 1983 until 2012. Various underground storage tanks, sumps, floor drains, and pits were present when the site was used for automotive service operations, and the site was listed as a generator of tetrachloroethene waste from 1995 to 2002. Site Geology and Hydrogeology: Soil beneath the site consisted of historic fill material, including predominately fine to coarse sand with varied amounts of brick fragments, gravel, milled and crushed asphalt, and ash. The fill extended to depths of up to 11 feet below ground surface. Historic fill was underlain primarily by glacial till, which in turn is underlain by a thick clay layer found at depths ranging between 40 and 60 feet below ground level. Bedrock was not encountered during investigations of the site, but the depth to bedrock in the vicinity of the site is reportedly 200 feet below ground level. The depth to groundwater across the site ranged from 31.5 to 37.7 feet and the groundwater flows to the north-northwest. Nature and Extent of Contamination: Remediation at the site is

Env Problem:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER STRAUSS AUTO (Continued)

S116550040

complete. Prior to remediation, the primary contaminants of concern were PAHs, lead, copper, mercury, and zinc in a layer of historic fill beneath the site. PCE and its associated degradation products were found in groundwater. PCE and trichloroethylene were found in sub-slab soil vapor samples. Remedial actions have successfully achieved soil cleanup objectives for Unrestricted use. Remaining contamination in the groundwater is being managed under a Site Management Plan, and the new building will be evaluated for soil vapor intrusion. The evaluation will include a provision to implement actions to address exposures related to soil vapor intrusion, if necessary.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-04-09 12:14:00
Record Upd: 2016-10-12 08:24:00
Updated By: RJCOZZY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Park Slope Library
Owner Address: 431 6th Avenue at 9th Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11215
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Yvonne Lewis
Owner Company: XYZ Properties, Inc.
Owner Address: 101 Girard Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11235
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: David Schwartz
Owner Company: Partners VII / 535 Fourth Owner LLC
Owner Address: 38 E. 29th Street, 9th Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10016
Owner Country: United States of America
HW Code: C224189
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224189
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER STRAUSS AUTO (Continued)

S116550040

Waste Code:	Not reported
HW Code:	C224189
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224189
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1505072
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2015-08-11 15:01:00
Record Updated:	2015-08-11 15:01:00
Updated By:	RJFENG
Crossref ID:	c224189-06-14
Cross Ref Type Code:	23

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER STRAUSS AUTO (Continued)

S116550040

Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2016-11-28 15:00:00
Record Updated:	2016-11-28 15:00:00
Updated By:	ljalden
Crossref ID:	2016000413758
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2016-11-28 14:47:00
Record Updated:	2016-11-28 14:47:00
Updated By:	ljalden
Crossref ID:	2-508594
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2017-10-16 09:25:00
Record Updated:	2017-10-16 09:25:00
Updated By:	JAAVERSA

AQ213
NNE
1/4-1/2
0.402 mi.
2124 ft.

**USPS GOWANUS SITE. FORMER MGP METROPOLIT
2ND AVENUE AND 12TH STREET
BROOKLYN, NY 11215**

**EDR MGP 1008407902
N/A**

Site 1 of 3 in cluster AQ

**Relative:
Higher
Actual:
12 ft.**

Manufactured Gas Plants:
No additional information available

AK214
SW
1/4-1/2
0.402 mi.
2124 ft.

**BARGE: CLEAN ENERGY #1/GOWANUS GAS
SECOND AVENUE & 29TH STREET
BROOKLYN, NY 11232**

**NY MOSF S108413355
N/A**

Site 3 of 4 in cluster AK

**Relative:
Lower
Actual:
2 ft.**

MOSF:
Name: BARGE: CLEAN ENERGY #1/GOWANUS GAS
Address: SECOND AVENUE & 29TH STREET
City,State,Zip: BROOKLYN, NY 11232
Facility ID: 0-0538
Program Type: MOSF
Tank Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: Not reported
UTMY: Not reported

Name: BARGE: CLEAN ENERGY #2/GOWANUS GAS
Address: SECOND AVENUE & 29TH STREET
City,State,Zip: BROOKLYN, NY 11232
Facility ID: 0-0539
Program Type: MOSF
Tank Status: Inactive
Expiration Date: Not reported
Dec Region: 2
UTMX: Not reported
UTMY: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BARGE: CLEAN ENERGY #1/GOWANUS GAS (Continued)

S108413355

Name: BARGE: CLEAN ENERGY #4/GOWANUS GAS TURB.
Address: SECOND AVENUE & 29TH STREET
City,State,Zip: BROOKLYN, NY 11232
Facility ID: 0-0541
Program Type: MOSF
Tank Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: Not reported
UTMY: Not reported

AK215
SW
1/4-1/2
0.402 mi.
2124 ft.

GOWANES GAS TURBINE SITE
29TH STREET & 2ND AVENUE
BROOKLYN, NY

NY LTANKS
NY Spills

S102150803
N/A

Site 4 of 4 in cluster AK

Relative:
Lower

Actual:
2 ft.

LTANKS:

Name: GOWANES GAS TURBINE SITE
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9806837 / 1998-09-03
Facility ID: 9806837
Site ID: 119011
Spill Date: 1998-09-03
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1998-09-03
CID: 384
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1998-09-03
Spill Record Last Update: 2000-12-14
Spiller Name: WILLIAM MURPHY
Spiller Company: CON ED
Spiller Address: 29TH ST & SECOND AVE
Spiller County: 001
Spiller Contact: WILLIAM MURPHY
Spiller Phone: (212) 580-6763
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 223190
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis notes: Operator found fuel blowing out of drain line on unit 2-2. He then checked waste oil tank and found tank overflowing from vents. It is suspected that this is mostly rain water from last night's rain. Miller Environmental has been called to pump out the tank. Estimated approximately 50 gallons spilled. As of

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

Remarks: 1630 hrs MEG crew completed clean up."
"HEAVY RAINS CAUSED WASTE OIL TO OVERFLOW"

All Materials:

Site ID: 119011
Operable Unit ID: 1067963
Operable Unit: 01
Material ID: 317975
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS TURBINE SITE
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9705001 / 2002-03-21
Facility ID: 9705001
Site ID: 261797
Spill Date: 1997-07-25
Spill Cause: Tank Failure
Spill Source: Commercial Vehicle
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1997-07-25
CID: 322
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1997-07-25
Spill Record Last Update: 2002-03-21
Spiller Name: SCHAVONE
Spiller Company: GOWANUS TURBINE SITE
Spiller Address: 29TH ST AND 2ND AVE
Spiller County: 001
Spiller Contact: SCHAVONE
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 223190
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ENGELHARDT 3/2/02: Information submitted by Orion Power New York
indicate that this was a one-time release from a Con Ed vehicle onto
blacktop. The vehicle was repaired and the spill cleaned up. (JHO)"
Remarks: "LEAKING TANK IN VEHICLE - SPILL ON PAVEMENT BEING CLEANED UP"

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

All Materials:

Site ID: 261797
Operable Unit ID: 1050877
Operable Unit: 01
Material ID: 334231
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: 5.00
Oxygenate: Not reported

SPILLS:

Name: GOWANUS GAS TURBINES
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9614099 / 2000-11-30
Facility ID: 9614099
Facility Type: ER
DER Facility ID: 223190
Site ID: 219650
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1997-03-04
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1997-03-04
CID: 205
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1997-03-04
Spill Record Last Update: 2005-09-14
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ED ROACH
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL 3/20/97 (Katz notes): Al Fillipi - same as 3/4/97 report - sheen also found in water during inspection w/Brian Mitchell. Placed booms. Dissipated quickly. e2mis notes: Noticed sheen between dock and CE2 fuel barge. Absorbent boom placed by site personnel. The source was not from the site. Sample analysis did not match fuel oil." Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

Remarks: "CALLER FOUND SPILL OF OIL ON PROPERTY."

All Materials:

Site ID: 219650
Operable Unit ID: 1045533
Operable Unit: 01
Material ID: 339209
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS CANAL
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9512987 / 2002-03-21
Facility ID: 9512987
Facility Type: ER
DER Facility ID: 223190
Site ID: 274401
DEC Region: 2
Spill Cause: Unknown
Spill Class: B3
SWIS: 2401
Spill Date: 1996-01-18
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1996-01-18
CID: 266
Water Affected: GOWANUS CANAL
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1996-01-18
Spill Record Last Update: 2002-03-21
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL 1/18/96: Glen Katz spoke with Ron Santapaola, Con Ed - sheen between barges, boom in place. Sheen dissipated as of 1425 hrs. Divers are to investigate futher, will inspect barge for source. Divers en route as of 1425 hrs. UPDATE: divers found no source but collected sample for analysis possibly from sheen. 1/24/9, Engelhardt notes: Call from Lisa Primeggia, Con Ed - divers inspected bottom of canal, saw nothing. Avery Tom is Con Ed Environmental Affairs person

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

assigned to case. Note: this burping up of oil occurred last on 11/27/95 (see spill #9510745). Call Al Fillipi, Con ed to find out if this happens a lot. 3/21/02: Information provided by Orion Power New York indicates this storm drain was sealed on or about July1, 1996. No recurrences of sheen emanating from the storm drain have been noted since then. (JHO) "

Remarks: "LIGHT OIL BUBBLING UP FROM BOTTOM OF CANAL. DRIVERS ENROUTE TO INVESTIGATE FURTHER. 10'X10' SHEEN. ABSORBANT BOOM IN PLACE. NRC ALSO NOTIFIED. FURTHER TO FOLLOW."

All Materials:

Site ID: 274401
Operable Unit ID: 1023988
Operable Unit: 01
Material ID: 356721
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS GAS TURBINES
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9502938 / 2004-07-23
Facility ID: 9502938
Facility Type: ER
DER Facility ID: 223190
Site ID: 171303
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 1995-06-08
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1995-06-08
CID: Not reported
Water Affected: GOWANUS CANAL
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-06-19
Spill Record Last Update: 2004-07-23
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ENGELHARDT 7/23/04: Con Ed submitted copy of notification letter sent
to NYCDEP regarding the spill: Approximately 2 pints oil sheen.
Unknown Source, 50' x 20' on canal. Sheen was contained within
permanently deployed boom around Gas Turbine Barge No. 1. Oil pads
collected surface oil.: Close out. (JHO)"

Remarks: "OIL SHEEN IN GOWANUS CANAL - BOOMS DEPLOYED - SLICK CONTAINED"

All Materials:

Site ID: 171303
Operable Unit ID: 1017524
Operable Unit: 01
Material ID: 367992
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS CANNAL
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9706169 / 1997-08-21
Facility ID: 9706169
Facility Type: ER
DER Facility ID: 223190
Site ID: 176842
DEC Region: 2
Spill Cause: Other
Spill Class: C3
SWIS: 2401
Spill Date: 1997-08-21
Investigator: JHOCONNIE
Referred To: Not reported
Reported to Dept: 1997-08-21
CID: 205
Water Affected: GOWANUS
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1997-08-21
Spill Record Last Update: 2003-11-13
Spiller Name: RICHARD ROACH
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
O'CONNELL 8/21 - JHO RESPONDED WITH AVERY TOM OF CON ED. BILGE AREA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

OF TWO FLOATING GAS TURBINES OVERFLOWED DUE TO HEAVY RAINS. OIL/WATER SEPARATOR COULD NOT HANDLE THE VOLUME. BILGE WATER LEAKED FROM FOUR SPOTS: TWO ON EACH BARGE. COAST GUARD RESPONDED EARLY IN THE MORNING, ISSUED FINDINGS AND RECOMMENDATIONS TO MAKE REPAIRS TO FLANGE WELDS ON THE BARGES. ACCORDING TO CON ED, CONTRACTOR (S&D) TO PUMP DOWN WATER LEVEL IN BILGE TO ALLOW WELDERS TO WORK ON WELDS. SILVER SHEEN IS CONTAINED WITHIN BOOMED AREA, ALTHOUGH COAST GUARD REPORTED THAT A SHEEN WAS VISIBLE IN GOWANUS BAY - IT COULD BE ATTRIBUTED TO ANOTHER SOURCE. IMPACT TO WATER APPEARS MINIMAL. "

Remarks: "caller stated rain has washed oil from deck."

All Materials:

Site ID: 176842
Operable Unit ID: 1049546
Operable Unit: 01
Material ID: 331764
Material Code: 0013
Material Name: lube oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS GAS TURBINES
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9909657 / 2009-11-13
Facility ID: 9909657
Facility Type: ER
DER Facility ID: 223190
Site ID: 119012
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1999-11-09
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 1999-11-09
CID: 322
Water Affected: NY UPPER BAY
Spill Source: Vessel
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-11-09
Spill Record Last Update: 2009-11-13
Spiller Name: DIMITRI WOLKOFF
Spiller Company: ORION POWER NY
Spiller Address: 29TH ST & SECOND AVE
Spiller Company: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

Contact Name: DIMTRI WOLKOFF
DEC Memo: "11/13/2009. Spill in the rever about 10 years ago. Nothing to persue. Case closed. JK."
Remarks: "BARGE GGT3 - OIL WATER SEPERATER MALFUNTIONED RELEASING THE WATER/OIL MIXTURE INTO BAY - SAMPLE WAS 15.6 PPM - WATER RELEASED INTO A BOOMED AREA AND NO VISABLE SHEEN - LEAK WAS STOPPED ALSO"

All Materials:

Site ID: 119012
Operable Unit ID: 1084409
Operable Unit: 01
Material ID: 298735
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS SUBSTATION
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0104654 / 2005-05-20
Facility ID: 0104654
Facility Type: ER
DER Facility ID: 223190
Site ID: 246915
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2001-07-31
Investigator: JHOCONE
Referred To: Not reported
Reported to Dept: 2001-07-31
CID: 390
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-07-31
Spill Record Last Update: 2005-05-20
Spiller Name: CALLER
Spiller Company: CON ED
Spiller Address: 4 IRVING PL
Spiller Company: 001
Contact Name: MARK SCHLAGEL
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ 31-JUL-2001 14:40 HRS. REPORTS: WHILE P.SUDOL WAS ON LOCATION FOR INSPECTION WITH THE DEC HE FOUND: APPROX. 4 OZ OF TRANS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

FDR FLUID ON TO A SUPPORT BEAM THEN ON TO BLUE STONE IN CIRCULATION PLANT # C2 FROM OIL PUMP SEAL. EQUIPMENT IS DRIPPING APPROX. 1 DROP EVERY 10 MINUTES. SPILL IS NOT CONTAINED. NO SEWERS OR WATER WAYS AFFECTED. CLEANUP PENDING REPAIR. CONTAINER PLACED UNDER LEAK FILLED WITH OIL ABSORBENT UPDATE 31-JUL-2001 17:20 HRS. ASPER AN E-MAIL FROM M.ROSA : 13:48 hours During a DEC inspection of the Gowanus Substation, it revealed that within Cooling Plant C2, there was a minor oil leak from the Oil Motor / Pump #01 seals. Apparently through vibration of the motor the catch pan shifted slightly causing a leak of approximately four ounces of oil onto the bluestone. The pan was immediately reposition and consultations were in progress due to a previous E2MIS work order on that piece of equipment. 16:45 hours. Two catch pans placed beneath the Oil Motor/ Pump # 01. The support structure of the pump has been cleaned and the oily bluestone removed. A 5 gallon pail was created and labeled oily debris from CP 02. The drum identification number and the proper labels need to be applied. UPDATE 8/23/04 W.O.# 0000122854 has been complete by Michael Garcia#14564 and Nesbilt Santo # 14864. Pump needs to be repaired. Another Incident Report 140211 will capture the repairs on pump. This incident # will be closed because on inspection found two Incidents for the same problem."

Remarks:

"4 oz spilled - clean up pending crew arrival spilled to bluestone & a support beam - no smoke/fire/private property con ed none at this time - - - -this is a NON pcb spill"

All Materials:

Site ID: 246915
Operable Unit ID: 843037
Operable Unit: 01
Material ID: 533136
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS GAS TURBINE SITE
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9504650 / 1995-07-19
Facility ID: 9504650
Facility Type: ER
DER Facility ID: 223190
Site ID: 246916
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 1995-07-18
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1995-07-18
CID: Not reported
Water Affected: EAST RIVER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-08-03
Spill Record Last Update: 1998-02-17
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 7/19/95: Al Fillipi - due to heavy rainfall could not handle water and overflowed newly installed lip around barge. They are going to raise the lip from 3 to 6 . All oil contained within permanent boom. Used sorbent pads to try to remove sheen. MEg called in to do clean up. No PCB analysis performed. Transformer is non-PCB. Mike O'Donnell (Con Ed) - source of oil was residual dripping from dressing coupling on #3 and 4 units. 10/10/95: This is additional information about material spilled from the translation of the old spill file: OIL SHEEN."
Remarks: "SHEEN FOUND AROUND 2 BARGES AFTER RAIN - CONTAINED BY BOOMS."
All Materials:
Site ID: 246916
Operable Unit ID: 1015567
Operable Unit: 01
Material ID: 366159
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS GAS TURBINE FAC
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9516210 / 2002-03-21
Facility ID: 9516210
Facility Type: ER
DER Facility ID: 223190
Site ID: 246917
DEC Region: 2
Spill Cause: Unknown
Spill Class: B3
SWIS: 2401
Spill Date: 1996-03-18
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1996-03-18

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

CID: 275
Water Affected: EAST RIVER
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1996-03-18
Spill Record Last Update: 2002-03-21
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller Company: 999
Contact Name: STEVE ROMERO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL 3/21/02: Information provided by Orion Power New York indicates this storm drain was sealed on or about July1, 1996. No recurrences of sheen emanating from the storm drain have been noted since then. (JHO) "
Remarks: "unkn petro product coming from pipe - spill is conatined with oil booms by con ed - "

All Materials:

Site ID: 246917
Operable Unit ID: 1027184
Operable Unit: 01
Material ID: 352748
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS CANAL
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9603148 / 2002-03-21
Facility ID: 9603148
Facility Type: ER
DER Facility ID: 223190
Site ID: 246918
DEC Region: 2
Spill Cause: Unknown
Spill Class: B3
SWIS: 2401
Spill Date: 1996-06-06
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1996-06-06
CID: 205
Water Affected: GOWANUS CANAL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1996-06-06
Spill Record Last Update: 2002-03-21
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller Company: 999
Contact Name: JOE DEVOTI
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 3/21/02: Information provided by Orion Power New York indicates this storm drain was sealed on or about July1, 1996. No recurrences of sheen emanating from the storm drain have been noted since then. (JHO) "
Remarks: "sheen 30ft x 30ft, contained in a permanent boom. came from a drain line who's origin is unknown."

All Materials:

Site ID: 246918
Operable Unit ID: 1030701
Operable Unit: 01
Material ID: 349394
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: CON ED GOWANUS GAS TURBIN
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9704982 / 1998-06-24
Facility ID: 9704982
Facility Type: ER
DER Facility ID: 223190
Site ID: 246919
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401
Spill Date: 1997-07-25
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1997-07-25
CID: 252
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Federal Government

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1997-07-25
Spill Record Last Update: 2000-07-03
Spiller Name: TIM SOILCH
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: MISS LUKSHIRDES
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ENGELHARDT same as 9704993"
Remarks: "FIRE IN LINE CAUSED TRANSFORMER OIL TO SPILL ONTO GROUND-IN PROCESS
OF BEING CLEANED UP"

All Materials:

Site ID: 246919
Operable Unit ID: 1050857
Operable Unit: 01
Material ID: 334219
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS GAS TURBINES
Address: 29TH STREET & 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9800342 / 1998-05-19
Facility ID: 9800342
Facility Type: ER
DER Facility ID: 223190
Site ID: 246920
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 1998-04-08
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1998-04-08
CID: 252
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GOWANES GAS TURBINE SITE (Continued)

S102150803

Remediation Phase: 0
Date Entered In Computer: 1998-04-08
Spill Record Last Update: 1998-05-19
Spiller Name: MIKE CESARE
Spiller Company: CON ED
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: MIKE CESARE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 5/18/98 e-mail from Con Ed ERT Walker: On 4/8/98, 2 ounces of oil leaked onto bluestone/soil from a cable connection on Feeder 42422. The oil was tested (Con Ed Lab Seq # 980-4582) LT 1 PPM PCB. Spill was cleaned up (bluestone/soil) removed and the equipment was repaired (epoxy sealed cable connection) on 4/8/98."
Remarks: "POT HEAD TUBING FAULTY CAUSING 2 QTS OF DIE-ELECTRIC FLUID TO SPILL ONTO PAVEMENT-IN PROCESS OF BEING CLEANED UP."
All Materials:
Site ID: 246920
Operable Unit ID: 1060948
Operable Unit: 01
Material ID: 322321
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

[Click this hyperlink](#) while viewing on your computer to access 25 additional NY SPILL: record(s) in the EDR Site Report.

216
SSE
1/4-1/2
0.403 mi.
2129 ft.

CONSOLIDATED EDISON
258 23RD ST
BROOKLYN, NY 11215

NY LTANKS **S104880516**
NY Spills **N/A**
NY MANIFEST

Relative:
Higher
Actual:
80 ft.

LTANKS:
Name: GREENWOOD SUB STATION
Address: 258 23RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0312353 / 2009-08-18
Facility ID: 0312353
Site ID: 188149
Spill Date: 2004-02-05
Spill Cause: Tank Overfill
Spill Source: Unknown
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 2004-02-05
CID: 71

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-02-05
Spill Record Last Update: 2009-08-18
Spiller Name: SCHLAGEL, MARK
Spiller Company: CON EDISON 151710
Spiller Address: 258 23RD ST
Spiller County: 001
Spiller Contact: SCHLAGEL, MARK
Spiller Phone: (212) 580-8383
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 157200
DEC Memo: "08/18/09 - See eDocs for Con Ed report detailing cleanup and closure. 2/5/04 - 1902hrs - Leo Gerace # 37876 Sr. Station Operator, Central Station reports while Maintenance was performing work on Transformer # 2 Conservator Tank, the top blow-off overflowed 20 gallons of non-pcb dielectric oil onto side of transformer, concrete and bluestone underneath in Greenwood Station. No fire/smoke involved. No sewers or waterways were affected but bluestone was affected. Pigs and bolognies placed and clean up is in progress. Spill is contained at this time. Maintenance is on location and will be barreling clean up materials and affected bluestone along with washing down side of transformer. No sampling necessary. UPDATE 2/9/04 1500 Hours Mechanics Chang and Garzino were onsite to pickup affected bluestone. The cleanup was completed at 2100 hours the same day. UPDATE 8/12/04 T.Hunter #20132 notified me that the ELAN valve has been inverted on TR#2. I inspected TR#2 and found no leaking at this time. Leak Closed. - J. Suarez"
Remarks: "overflow of 20 gallons from conservator tank on transformer #2. Cleanup in progress. Note that this is NON-PCB oil."

All Materials:
Site ID: 188149
Operable Unit ID: 877593
Operable Unit: 01
Material ID: 555233
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: GREENWOOD SUB STATION
Address: 258 23RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0412106 / 2005-05-27

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Facility ID: 0412106
Facility Type: ER
DER Facility ID: 157200
Site ID: 337476
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2005-02-13
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 2005-02-13
CID: 41
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-02-14
Spill Record Last Update: 2005-05-27
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT DESK
DEC Memo: "#157209. 2/13/05 0750 HRS. LOVERO #86012 S.S.O REPORTS FOUND APPROX 1/2 PINT OF HYDRAULIC FLUID THAT SPILLED FROM VENDER'S FORKLIFT ONTO BLUE STONE. 6 BY 6 AREA AT NORTH YARD OF GREENWOOD SUBSTATION. NO SEWERS OR WATERWAYS AFFECTED. ENGINE OF FORK LIFT IS OFF (NOT LEAKING)AT THIS TIME. TRANSPORTATION WILL BE NOTIFIED. 0810HRS LOVERO REPORTS CLEANUP COMPLETED. PLACED MATL.IN 5-GALLON DRUM. UPDATE 1/14/05 Operator notified me that at 14:19 Blankley came and made repairs to fork lift. Forklift repairs completed incident closed. Clean up completed and all non-haz waste placed in a 5 gal drum."
Remarks: "1/2 pint - spilled from fork lift onto blue stone - ref 157209 - cleaned up - no to five questions. "

All Materials:

Site ID: 337476
Operable Unit ID: 1099426
Operable Unit: 01
Material ID: 579773
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GREENWOOD SUBSTATION
Address: 258 23RD STREET

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0008933 / 2001-04-12
Facility ID: 0008933
Facility Type: ER
DER Facility ID: 157200
Site ID: 273903
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2000-11-01
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2000-11-01
CID: 396
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-11-01
Spill Record Last Update: 2001-06-19
Spiller Name: SAME
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: BILL MURPHY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY DEC INSPECTOR'S NOTES CON ED E2MIS REPORT 11-01-00 2ozs. of dielectric oil spilled from transformer #2 oil fill valve of tap changer selector compartment on to blacktop and bluestone. A 1 x2 area of Bluestone has been affected and diapers have been placed. 1 liquid sample was taken. Update 14:00hrs. Don't need sample taken, because sample was just taken 6 months ago. Cleanup pending. Cleanup completed 11-01-00 14:30hrs. by tightening valve, removing/revocering liquid/solids and excavating contaminated soil and bluestone."
Remarks: "2 OZ SPILLED. SAMPLES TAKEN CLEAN UP PENDING. REF # 134208 OIL LEAKED FROM OIL FILL VALVE SELECTOR COMP. TRANS #2."
All Materials:
Site ID: 273903
Operable Unit ID: 831343
Operable Unit: 01
Material ID: 546434
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Name: GREENWOOD SUBSTATION
Address: 258 23RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0009443 / 2003-10-07
Facility ID: 0009443
Facility Type: ER
DER Facility ID: 157200
Site ID: 273904
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2000-11-16
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2000-11-16
CID: 323
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-11-16
Spill Record Last Update: 2003-10-07
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: RICHARD ROACH
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Correction: Substation is called Greenwood (not Greenwich) substation. Con Ed e2mis #134414: 1oz transformer oil had leaked onto concrete pad from flange fitting. Bucket and pads placed to contain leak. Transformer scheduled to be drained on 11/18/00. Historical records to be verified. Cleanup pending maintenance crew. LSN 300-09138 shows <1ppm PCBs. As per harscopy documentation provided by T. Kennison, cleanup completed on 11/16/00vat 1435hrs by tightening valve, placing drip pan and pads. Leak was slowed down. Unit TR#3 is being replaced. 4/18/03 Unit was replaced in January 2001, no repair required."
Remarks: "LEAKING FLANGES, TESTING FOR PCB. CON ED 134414"

All Materials:

Site ID: 273904
Operable Unit ID: 831736
Operable Unit: 01
Material ID: 543387
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: 1.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Oxygenate: Not reported

Name: GREENWOOD SUBSTATION

Address: 258 23RD ST

City,State,Zip: BROOKLYN, NY

Spill Number/Closed Date: 1506613 / 2016-10-24

Facility ID: 1506613

Facility Type: ER

DER Facility ID: 406682

Site ID: 514037

DEC Region: 2

Spill Cause: Equipment Failure

Spill Class: C4

SWIS: 2401

Spill Date: 2015-09-22

Investigator: RWAUSTIN

Referred To: Not reported

Reported to Dept: 2015-09-22

CID: Not reported

Water Affected: Not reported

Spill Source: Commercial/Industrial

Spill Notifier: Responsible Party

Cleanup Ceased: Not reported

Cleanup Meets Std: False

Last Inspection: Not reported

Recommended Penalty: False

UST Trust: False

Remediation Phase: 0

Date Entered In Computer: 2015-09-22

Spill Record Last Update: 2016-10-24

Spiller Name: ERT

Spiller Company: CON EDISON

Spiller Address: 4 IRVING PLACE

Spiller Company: 999

Contact Name: ERT

DEC Memo: "10/24/16 - Austin - Con Ed contained and cleaned up the spill the same day as the spill event; no source reported - See document files for further information - Spill closed - end"

Remarks: "Half a pint of oil spilled to blue stone. Clean up is in progress."

All Materials:

Site ID: 514037

Operable Unit ID: 1263246

Operable Unit: 01

Material ID: 2266928

Material Code: 0010

Material Name: hydraulic oil

Case No.: Not reported

Material FA: Petroleum

Quantity: .13

Units: G

Recovered: .13

Oxygenate: Not reported

Name: GREENWOOD SUBSTATION

Address: 258 23RD STREET

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0011131 / 2003-06-20
Facility ID: 0011131
Facility Type: ER
DER Facility ID: 157200
Site ID: 273905
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2001-01-12
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2001-01-12
CID: 281
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-01-12
Spill Record Last Update: 2003-10-07
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: PETE MCGUIRE
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #135074: 1/12/01 1044hrs Transformer #3 leaking approx 1gal non-PCB Transformer oil from (1) the intelligent transmitter flange between the bank and radiator (2) gate valve between the bank and radiator (3) sample valve on bank itself. Onto transformer pad and then into bluestone. Absorbant pads placed. Area roped off. Cleanup in progress as of 1050hrs. 1/12/01 1420hrs Cleanup completed 1230hrs. Pending repair on maximo WO# 94869. 1/18/01 1135hrs Cleanup completed on 1/12/01 1243hrs by placing drip pan diapers and marriage rolls. 1/19/01 2155hrs LSN 01-00486 PCBs <1ppm 2/15/01 1115hrs Containment device has been saturated and oil overflowed onto transformer pad and surrounding bluestone. 2/15/01 1155hrs 4oz leaked from transformer cooling fin to concrete pad. Drip rate is 2drops/hour. 2/15/01 1330hrs Existing oil leak from gas detector has increased in intensity to one drop/10 seconds. Leak has saturated the containment device and overflowed to bluestone. 16oz reached bluestone. There is a new leak associated with radiator fins. 4oz to concrete. Two drops/hour. Oil pads placed at both locations. Area Mgmt. notified for containment and cleanup at 1128hrs. 4/13/01 0935hrs As per hardcopy documentation provided by R. Betancourt. Cleanup completed on 4/9/01 at 1530hrs. Visible traces of oil were removed and stained areas were washed. Hydran was removed and replaced, gate valve packing was tightened, and sample valve was tightened. No leak found for cooling fin."

Remarks:

"ABOVE MATERIAL SPILLED AT ABOVE LOCATION. SPILL CAUSE IS UNDER INVESTIGATION AT TIME OF CALL. MATERIAL IS REPORTED AS NON-PCB. CON

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

ED # NOT AVAILABLE. NO CALL BACK REQUESTED."

All Materials:

Site ID: 273905
Operable Unit ID: 833194
Operable Unit: 01
Material ID: 541452
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GREENWOOD SUBSTATION
Address: 258 23RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0102581 / 2003-07-17
Facility ID: 0102581
Facility Type: ER
DER Facility ID: 157200
Site ID: 273906
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2001-06-06
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2001-06-07
CID: 211
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-06-07
Spill Record Last Update: 2003-07-17
Spiller Name: SAME
Spiller Company: CON ED
Spiller Address: 4 IRVING PL
Spiller Company: 001
Contact Name: JIMMY FOX
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
FOLEY Con Ed e2mis #137533: 6/7/01 - 1300 M. ROSA SUB STA OPS,
REPORTS A SPILL OF 1 DROP OF OIL FROM OIL SOAKED CLOTH WRAP THAT IS
WRAPPED AROUND THE C PHASE BUS INSULATOR ASSOCIATED WITH A POTENTIAL
TRANSFORMER ONTO A METAL PLATE. THIS SPILL WAS FOUND 6/6/01 AT 2035
HRS. SPILL IS CONTAINED. CLEANUP BEGAN 6/7/01 AT 0319 HRS USING OIL
ABSORB AND A DIAPER. CLEANUP ENDED AT 0530 HRS ON 6/7/01. 6/11/01 -
13:57 LSN 01-06304-001 indicates 19 ppm PCB. LSN 01-06304-002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Remarks: indicates 30 ppm PCB. 6/12/01 8:30 As per email notification cleanup was completed on 6/7/01 at 05:35hrs. Liquid and solids were both removed and recovered. 4/18/03 1515hrs Lab Sequence Number: 01-06304-001, SECT 4 PRIMARY COMP THRU BUSHING-C PHASE, 30ppm PCBs Lab Sequence Number: 01-06304-002, SECT 4 PRIMARY COMP THRU BUSHING-B PHASE, 19ppm PCBs 4/26/2003 12:31 As per Maximo # 0000116285 repairs were made on 10/04/2001."

"leak from insulator caused 1 drop of product to spill - spill cleaned up - con ed 137533"

All Materials:

Site ID: 273906
Operable Unit ID: 841282
Operable Unit: 01
Material ID: 534696
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: 1.00
Oxygenate: Not reported

Name: GREENWOOD SUBSTATION
Address: 258 23RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0103247 / 2017-08-01
Facility ID: 0103247
Facility Type: ER
DER Facility ID: 157200
Site ID: 273907
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2001-06-25
Investigator: RWAUSTIN
Referred To: SSO
Reported to Dept: 2001-06-25
CID: 397
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-06-25
Spill Record Last Update: 2017-08-01
Spiller Name: SAME
Spiller Company: CON ED
Spiller Address: 4 IRVING PL
Spiller Company: 001
Contact Name: CALLER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #137844: 6/25/01 1000hrs 6oz transformer oil from sampling valve of transformer #2 onto bleustone. 1sq ft of bluestone was dug up and disposed of. Cleanup completed 1005hrs. 4/25/03 1154hrs Maximo #205510 will capture all repair work on the oil sampling valve. 6/21/10 - changed Lead DEC to JMOCONN (JOC) 11/22/16 Austin This spill report is being transferred from Joe O Connell to Con Ed Unassigned - end 8/1/17 - Austin - Con Ed contained and cleaned up the spill, as indicated above, and as of 4/5/17, inspections have indicated that the leak has ceased with no further repairs needed - See document files for further information - Spill closed - end"

Remarks: "leak from sampling valve from transformer #2. con ed#137844 non pcb oil spill onto blue stone"

All Materials:

Site ID: 273907
Operable Unit ID: 840007
Operable Unit: 01
Material ID: 535341
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: 1.00
Oxygenate: Not reported

Name: GREENWOOD SUBSTATION
Address: 258 23RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0203551 / 2002-10-17
Facility ID: 0203551
Facility Type: ER
DER Facility ID: 157200
Site ID: 273908
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 2002-07-03
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2002-07-03
CID: 390
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-07-03
Spill Record Last Update: 2004-01-13

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller Company: 999
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #143763: 7-3-02 1710 HRS L. GIRACE # 37876 SSO GREENWOOD S.S. REPORTS WHILE TRYING TO COOL DOWN RING BUS TRANSF # 4 IN SUB STA HE FOUND IT LEAKED APPROX 150 GALLONS NON PCB TRANSF OIL FROM BOTTOM OF TRANSF ONTO BLUE STONE. LIQUID WAS CONTAINED TO BLUE STONE NO SEWERS OR WATERWAYS AFFECTED. APPROX 500 GALLONS WATER WAS MIXED (WATER COOLING OFF TRANSF) WITH OIL. TRANSF # 4 WAS TAKEN OUT OF SERV ON EMERG. THERE IS / WAS NO FIRE OR SMOKE AT THIS LOCATION. NO INJURIES DUE TO THIS SPILL. NO PRIVATE PROPERTY AFFECTED. THEY WILL START CLEANUP AS A NON PCB OIL CLEANUP. TRANSF STOPPED LEAKING WHEN TRANSF WAS TAKEN OUT OF SERV AND COOLED DOWN. NO SAMPLE TAKEN. HE PLACED E.S.TAG # 040-0085. CLEANUP IN PROGRESS. CIG M. SCHLAGEL NOTIFIED 1734 HRS. UPDATE 2400 hours 7/3/02 SSO management personnel arrived on scene 1815-2000 hours: GMs Aubrey Braz, Sanjay Bose AM Ralph Lasardo Supervisors T Hunter, M Watt ERT Sean Mahoney EHS Specialist P Sudol NYCDEP Celest Okoli All persons responded to an oil spill incident on TR #4. Operator estimated the amount of oil to be 150 gallons by visual estimate. Oil spilled to transformer pad and some surrounding bluestone. Source of the leak was the Conservator tank. Excess oil bled into the desiccant breather. Oil escaped through bottom of breather. Oil leak caused by expansion of oil due to excessive heat condition. Leak stopped after sufficient expansion allowed excess out of tank. Currently, there is no oil leaking. 55 gallon metal drum was placed under breather as future precaution. Maintenance Work Order will be created to install atmoseal bag inside conservator tank at a future date when outage is available. Operator placed pads on transformer pad as containment/ cleanup measure. NYCDEP Okoli on site at approximately 1950 hours. Requested lab result for Main Body of Tr #4. Lab report LSN 00-09138 faxed to NYCDEP office at 2150 hours. Lab result shows less than 1 ppm PCB. Also requested copy of updated E2MIS report when it becomes available. He left station at approximately 2030 hours. Allstate Power Vac reported on site at 2020 hours. Discussed work plan on cleanup. Allstate has picked up all oily pads and placed in drums. Vactor truck mobilized to take up affected bluestone/soil. This work is in progress. UPDATE 7/5/02 1300 hours Allstate Power Vac completed initial cleanup of TR#4 pad and bluestone. Approximately 8 cubic yards of bluestone and oily debris were removed. Waste was nonhazardous. Manifested to Clean Rock in Md (Manifest number 113865). Cleanup was done using a solids vactor truck. Initial cleanup completed 0200 hours 7/4/02. An inspection was conducted on 0900 hours on 7/5/02 by P Sudol and R LaSardo. Some stained areas were identified and contractor was called again to reclean areas. Job is in progress. Excavated area to be barricaded by station. Based on discussion with Transformer Group supervisor T Hunter, the spill amount should be revised. There is no practical way to determine how much oil was in the conservator before the incident, but if assumed full, it was estimated that there only may have been as much as an inch of expansion in the tank due to the high temperature. This would account for an estimated potential loss of 10-15% of the tank's contents, or 50-75 gallons of oil lost. NYSDEC K Foley scheduled to come on site to inspect on 7/9/02. UPDATE 7/9/02 1130 hours Allstate

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Power Vac on site on 7/5/02 to clean areas a second time. Approximately 12 yards of bluestone was removed by vactor truck. The waste was manifested to Clean Rock of PA on nonhazardous manifest No. 113828. Areas cleaned a second time were those surrounding the pad. This cleanup was completed 1430 hours on 7/5/02. UPDATE 7/10/02 1145 hours Site inspection was conducted by NYSDEC Kerry Foley on 7/9/02 at 1300 hours. Requested that some small, stained spots be recleaned, and that a composite post excavation sample be taken and analzed for TPH using Modified Method 8100. Arrangements made for chem lab and contractor within two days. UPDATE 7/17/02 1300 hours Allstate on site 7/11/02 to clean small area that exhibited staining. Two 55 gallon drums of oily soil/stone/debris were removed. Results of post excavation composite sample are indicated below. Awaiting instructions from the NYSDEC on how to proceed. Lab Sequence Number: 02-06376-001 Date Approved: 7/15/2002 Date Received: 7/10/2002 Chain of Custody ID: CC03337 Date Sampled: 7/10/2002 TPH - Dielectric/Diesel Fluid Range Organics Analysis by EPA 8100 (Modified) DiChevrol Fluid 100 Cable Oil < 49 mg/Kg EPA 8100 Mod DiChevrol Fluid 500 Cable Oil < 49 mg/Kg EPA 8100 Mod Silicone Base Transformer Oil < 49 mg/Kg EPA 8100 Mod High Visc. Polybutene Cable Oil < 49 mg/Kg EPA 8100 Mod Low Visc. Polybutene Cable Oil < 49 mg/Kg EPA 8100 Mod Sun #2 Base Transformer Oil < 49 mg/Kg EPA 8100 Mod Sun #4 Cable Oil < 49 mg/Kg EPA 8100 Mod Sun #6 Cable Oil < 49 mg/Kg EPA 8100 Mod Sun #8 II Base Transformer Oil < 49 mg/Kg EPA 8100 Mod Petroleum Base Transformer Oil < 49 mg/Kg EPA 8100 Mod Gasoline < 49 mg/Kg EPA 8100 Mod Kerosene < 49 mg/Kg EPA 8100 Mod #4 Fuel Oil < 49 mg/Kg EPA 8100 Mod #6 Fuel Oil < 49 mg/Kg EPA 8100 Mod THC by Method 8100 (Modified) 25293 mg/Kg EPA 8100 (MOD.) Univolt 60 Transformer Oil 25400 mg/Kg EPA 8100 Mod Diesel Fuel Oil < 49 mg/Kg EPA 8100 MOD #2 Fuel Oil < 49 mg/Kg EPA 8100 Mod Motor Oil < 49 mg/Kg EPA 8100 Mod JP4 (Aviation Fuel) < 49 mg/Kg EPA 8100 Mod DEC Inspector Notes: 7/9/02 During heat wave, oil leaked from dessicant breather of transformer #4 onto transformer pad and bluestone. 55gal drum was placed underneath breather as precaution. There is a work order to install a atmo seal bag inside conservator tank when outage is available. Historical PCB count <1ppm (LSN 00-09138). AllState PowerVac performed cleanup. There are a few stains which will be removed before taking composite samples for TPH via modified method 8100. Will either bring AllState back or will have Con Ed crews do it, whichever is available for tomorrow. 9/4/02 Met with Pete Sudol (SSO EH&S). Mechanics removed another 6 of soil from south side of transformer #4 to take samples for TPH via modified method 8100. (Results for this side were as high as 21,200ppm). Two samples were taken, one from north side of feeder pipe to the west of excavation and one from the south side of feeder pipe to the east of excavation. Will keep excavation open until results return. Told Con Ed that the north and west side of transformer could be backfilled based on last sample results. 9/10/02 Voicemail message received from Pete Sudol. Indicated that he received lab results from south side of excavation and they were approx 25,000-32,000ppm TPH via modified EPA method 8100. Engineering inspected situation and directed to stop excavation around transformer. Would like to discuss next step. Page 1 of 1 10/10/2002 Consolidated Edison Environment, Health and Safety ChemLab NELAP NY Lab ID No: 10380 Lab Sequence Number: 02-09383-001 Date Approved: 10/10/2002 Date Received: 10/07/2002 Chain of Custody ID: CC07847 Date Sampled: 10/04/2002 Submitter: PETER J SUDOL Job Site: GREENWOOD S/S Email To:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

SUDOLP@coned.com-EA-ChemLabReports-BQCHEMLABRESULTS TPH -
Dielectric/Diesel Fluid Range Organics Analysis by EPA 8100
(Modified) MATRIX: SOIL COMPOSITE DESCRIPTION: EXCAVATION BY TR # 4
LOCATION: GREENWOOD S/S EQUIPMENT: TRANSFORMER 4 TEST DESCRIPTION
RESULT UNIT METHOD DiChevrol Fluid 100 Cable Oil < 10.8ppm DOH
DiChevrol Fluid 500 Cable Oil < 10.8ppm DOH Silicone Base Transformer
Oil < 10.8ppm DOH High Visc. Polybutene Cable Oil < 10.8ppm DOH Low
Visc. Polybutene Cable Oil < 10.8ppm DOH Sun #2 Base Transformer Oil
< 10.8ppm DOH Sun #4 Cable Oil < 10.8ppm DOH Sun #6 Cable Oil <
10.8ppm DOH Sun #8 II Base Transformer Oil < 10.8ppm DOH Petroleum
Base Transformer Oil < 10.8ppm DOH Gasoline < 10.8ppm Modified 8100
Lubricating Oils < 10.8ppm Modified 8100 #2 Fuel Oil/Diesel < 10.8ppm
Modified 8100 #4 Fuel Oil < 10.8ppm Modified 8100 #6 Fuel Oil <
10.8ppm Modified 8100 THC by Method 8100 (Modified) 280ppm Modified
8100 Kerosene/Jet Fuel < 10.8ppm Modified 8100 % Solids 92.5% SM
2540B 10/11/02 Pete Sudol sent me the above results via email. Gave
him the OK to backfill. (KMF) "

Remarks: "40 gals unk oil - on bluestone - possible transformer oil "

All Materials:

Site ID: 273908
Operable Unit ID: 854402
Operable Unit: 01
Material ID: 521377
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 40.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GREENWOOD SUBSTATION
Address: 258 23RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0204749 / 2003-04-24
Facility ID: 0204749
Facility Type: ER
DER Facility ID: 157200
Site ID: 273909
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2002-08-05
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2002-08-05
CID: 198
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-08-05
Spill Record Last Update: 2003-04-28
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: TOM MARCINEK
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #144373: 8/5/02 - 0900 L. GIRACE - 37876 - SSO, REPORTS FINDING A SPILL OF APPROX 3 PTS OF NON PCB DIELECTRIC FLUID ONTO BLUESTONE FROM THE B PHASE POTHEAD BASE PLATE OF FDR 38B12. SPILL IS CONTAINED. MR. GIRACE PLACED DIAPERS ON THE SPILL. THE BASE PLATE IS LEAKING AT THE RATE OF APPROX 2 DROPS A MINUTE. MR. GIRACE PLACED A NOTICE OF DIEL FLUID RELEASE TAG - #0400073. CLEANUP IS PENDING FDR 38B12 BEING TAKEN OFF THE SYSTEM. UPDATE 11/4/02 1745 Hours Leak on B-Phase of Feeder 38B12 was reported repaired by Transmission Operations on 10/30/02. Vendors scheduled to bid cleanup of bluestone on 11/5/02. Bids were cancelled, field forces to cleanup dirt in sandbox. UPDATE 12/16/02 15:30 Information provided by SSO Supervisor Frank Kennedy indicates that cleanup was completed by field forces on 12/12/02 and completed at 2100 hours by shoveling out sand out of sandbox. Cleanup was completed by L Dryden #18081 and A Incorvaia #18472. A 55 gallon drum of waste was generated. This was determined to be nonhazardous by process knowledge."
Remarks: "LEAKING POTHEAD FROM A FEEDER LEAKED APPROX 3 PINTS OF PRODUCT. MATERIAL CONTAINED. LEAKAGE IS APPROX 2 DROPS A MINUTE. BEING TAKEN OFF SYSTEM FOR REPAIR. CON ED # 144373."

All Materials:

Site ID: 273909
Operable Unit ID: 856048
Operable Unit: 01
Material ID: 518982
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GREENWOOD SUBSTATION
Address: 258 23RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0300498 / 2008-08-04
Facility ID: 0300498
Facility Type: ER
DER Facility ID: 157200
Site ID: 273910
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2003-04-14

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2003-04-14
CID: 207
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-04-14
Spill Record Last Update: 2008-08-04
Spiller Name: LARRY COSTA
Spiller Company: CON EDISON
Spiller Address: 128 WEST END AVENUE
Spiller Company: 001
Contact Name: ZAMBRIO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ 8/4/08: Cleanup completed. As per 9/18/06 agreement between NYSDEC and Con Edison, approved engineering controls (valve bags, drip pans, absorbents, etc.) are in place and are being maintained for minor drips and small leaks. Repairs to be tracked and completed under Con Edison MAXIMO Work Order. See eDocs for final emis report. Close out. (JHO)"

Remarks: "12 oz total product - cleanup in progress"

All Materials:

Site ID: 273910
Operable Unit ID: 866577
Operable Unit: 01
Material ID: 508573
Material Code: 0016A
Material Name: non PCB oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GREENWOOD SUBSTATION
Address: 258 23RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9508354 / 2003-10-07
Facility ID: 9508354
Facility Type: ER
DER Facility ID: 157200
Site ID: 273911
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1995-10-08
Investigator: CAENGELH

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Referred To: Not reported
Reported to Dept: 1995-10-08
CID: 252
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-10-08
Spill Record Last Update: 2003-10-07
Spiller Name: ANDREW PETE
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: ANDREW PETE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 4/29/03 Inspected substation. Con Ed provided old tracking system report #961 which states the following: Transformer #3 oil pump #4 is leaking at a rate of 2drops/minute into a 5gal bucket which is almost full and should be changed before oil spills over or the bucket gets accidentally knocked over. Oil is all over transformer pad and need a good cleanup. Bluestone around pad is black from oil. During inspection, equipment was found repaired and area appeared clean. (KMF)"

Remarks: "TRANSFORMER NO 3 OIL PUMP NO 4 IS LEAKING AT A RATE OF TWO DROPS PER MINUTE-INTO A FIVE GALLON PAIL WHICH IS FULL- 1/2 GAL HAS LEAKED ONTO TRANSFORMER PAD WHICH IS CONCRETE AND ONTO BLUE STONE-CREWS ON WAY FOR CLEAN-UP"

All Materials:
Site ID: 273911
Operable Unit ID: 1022862
Operable Unit: 01
Material ID: 569831
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported

[Click this hyperlink](#) while viewing on your computer to access 49 additional NY SPILL: record(s) in the EDR Site Report.

NY MANIFEST:

Name: CONSOLIDATED EDISON
Address: 258 23RD ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004118931

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Facility Status: Not reported
Location Address 1: 258 23RD ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: 6506

NY MANIFEST:

EPAID: NYP004118931
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:

Document ID: NYE1556955
Manifest Status: Not reported
seq: Not reported
Year: 2004
Trans1 State ID: 46690JM
Trans2 State ID: Not reported
Generator Ship Date: 03/24/2004
Trans1 Recv Date: 03/24/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/25/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004118931
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Waste Code: Not reported
Waste Code: Not reported
Quantity: 00050
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

Name: GREENWOOD SS
Address: 258 23RD ST
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP000923789
Facility Status: Not reported
Location Address 1: 258 23RD ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000923789
Mailing Name: GREENWOOD SS
Mailing Contact: ANTHONY C LEONARDI
Mailing Address 1: 258 23RD ST
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11232
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7187683771

NY MANIFEST:
Document ID: NYB7575786
Manifest Status: C
seq: Not reported
Year: 1996
Trans1 State ID: Not reported
Trans2 State ID: HW5786
Generator Ship Date: 03/26/1996
Trans1 Recv Date: 03/27/1996
Trans2 Recv Date: / /
TSD Site Recv Date: 03/28/1996
Part A Recv Date: 05/13/1996
Part B Recv Date: 04/09/1996
Generator EPA ID: NYP000923789
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S104880516

Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00312
Units: K - Kilograms (2.2 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100

[Click this hyperlink](#) while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

217
East
1/4-1/2
0.419 mi.
2211 ft.

578 5TH AVENUE
578 5TH AVENUE
NEW YORK CITY, NY

NY VCP S121133136
N/A

Relative:
Higher
Actual:
81 ft.

VCP NYC:
Project ID: 16TMP0425K, 16EHAZ390K, 17CVCP055K
Name: 578 5TH AVENUE
Address: 578 5TH AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn

AQ218
NNE
1/4-1/2
0.423 mi.
2231 ft.

BUG, METROPOLITAN WORKS
2ND AVE & 12TH STREETS
BROOKLYN, NY 11215
Site 2 of 3 in cluster AQ

NY HSWDS S108146253
N/A

Relative:
Higher
Actual:
14 ft.

HSWDS:
Facility ID: HS2014
Region: 2
Facility Status: Unknown
Owner Type: Publ Utlity
Owner: Bruno's Truck Sales
Owner Address: 435 Hamilton Ave.
Owner Phone: (718)965-2400
Operator Type: Publ Utlity

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUG, METROPOLITAN WORKS (Continued)

S108146253

Operator: Unknown
Operator: Unknown
Operator Phone: Unknown
EPA ID: NYD980532006
Registry: Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID: None
RCRA Permitted: Unknown
Site Code: Coal Gasification Plant
Owner City State: Brooklyn NY 11215
Operator City State: Not reported
Quadrangle: Unknown
Latitude: 40 40'15"N
Longitude: 73 59'45"W
Acres: 0.00
Operator Date: 1871
Close Date: 1948
Completed: PA
Active: Unknown
PCB's Disposed: No
Pesticides Disposed: No
Metals Disposed: No
Asbestos Disposed: No
Volatile Organic Compounds Disposed: No
Semi Volatile Organic Compounds Disposed: Unknown
Analytical Info Exists for Air: Not reported
Analytical Info Exists for Ground: None
Analytical Info Exists for Surface: Not reported
Analytical Info Exists for Sediments: Not reported
Analytical Info Exists for Surface: Not reported
Analytical Info Exists for Substance: Not reported
Analytical Info Exists for Waste: Not reported
Analytical Info Exists for Leachate: Not reported
Analytical Info Exists for EP Toxicity: Not reported
Analytical Info Exists for TCLP: Not reported
Threat to Environment/Public Health: Environmental
Surface Water Contamination: Unknown
Surface Water Body Class: Unknown
Groundwater Contamination: Unknown
Groundwater Classification: Unknown
Drinking Water Contamination: Unknown
Drinking Water Supply is Active: No
Any Known Fish or Wildlife: Unknown
Hazardous Exposure: Unknown
Site Has Controlled Access: Unknown
Ambient Air Contamination: Unknown
Direct Contact: Unknown
EPA Hazardous Ranking System Score: Unknown
Inventory: F
Nefrap: T
Mailing: Not reported
Tax Map No: Not reported
Qualify: 0
Next Action: Not reported
Agencies: Not reported
Air: Not reported
Building: Not reported
Site Desc: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUG, METROPOLITAN WORKS (Continued)

S108146253

Drink: Not reported
Eptox: Not reported
Fish: Not reported
Ground: Not reported
Ground Desc: Not reported
Hazardous Threat: Not reported
Haz Threat Desc: Not reported
Leachate: Not reported
Preparer: Not reported
Sediment: Not reported
Soil: Not reported
Surface: Not reported
Status: Not reported
Surface Soil: Not reported
Surface: Not reported
TCLP: Not reported
Waste: Not reported

AQ219
NNE
1/4-1/2
0.423 mi.
2231 ft.

BKLYN UNION GAS /METROPOLITAN WORKS
2ND AVE & 12 ST /GOWANUS CANAL
BROOKLYN, NY 11215

SEMS-ARCHIVE 1003863850
NYD980532006

Site 3 of 3 in cluster AQ

Relative:
Higher

Actual:
14 ft.

SEMS Archive:
Site ID: 0201976
EPA ID: NYD980532006
Name: BKLYN UNION GAS /METROPOLITAN WORKS
Address: 2ND AVE & 12 ST /GOWANUS CANAL
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11215
Cong District: 14
FIPS Code: 36047
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region: 02
Site ID: 0201976
EPA ID: NYD980532006
Site Name: BKLYN UNION GAS /METROPOLITAN WORKS
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1986-09-24 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 02
Site ID: 0201976
EPA ID: NYD980532006
Site Name: BKLYN UNION GAS /METROPOLITAN WORKS
NPL: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BKLYN UNION GAS /METROPOLITAN WORKS (Continued)

1003863850

FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1981-06-01 04:00:00
Finish Date: 1981-06-01 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0201976
EPA ID: NYD980532006
Site Name: BKLYN UNION GAS /METROPOLITAN WORKS
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: 1986-09-05 04:00:00
Finish Date: 1986-09-24 04:00:00
Qual: N
Current Action Lead: EPA Perf

AR220
East
1/4-1/2
0.435 mi.
2296 ft.

187 15TH ST
187 15TH ST
BROOKLYN, NY

Site 1 of 2 in cluster AR

NY LTANKS **S103239054**
N/A

Relative:
Higher
Actual:
71 ft.

LTANKS:
Name: 187 15TH ST
Address: 187 15TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9800504 / 1998-04-13
Facility ID: 9800504
Site ID: 173608
Spill Date: 1998-04-10
Spill Cause: Tank Overfill
Spill Source: Commercial Vehicle
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 1998-04-13
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1998-04-13
Spill Record Last Update: 1998-04-15

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

187 15TH ST (Continued)

S103239054

Spiller Name: CALLER
Spiller Company: WHALECO
Spiller Address: 5560 58TH ST
Spiller County: 001
Spiller Contact: ECONOMOS RESIDENCE
Spiller Phone: (718) 788-7729
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 146058
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks: "DRIVER OVERFILLED TANK."

All Materials:

Site ID: 173608
Operable Unit ID: 1057859
Operable Unit: 01
Material ID: 322470
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

AP221 US INFORMATION AGENCY
SSW 830 3RD AVE
1/4-1/2 BROOKLYN, NY 11232
0.435 mi.
2296 ft. Site 2 of 2 in cluster AP

NY HSWDS S108146423
N/A

Relative:
Higher
Actual:
11 ft.

HSWDS:

Facility ID: Not reported
Region: 2
Facility Status: Unknown
Owner Type: F
Owner: General Services Administratio
Owner Address: 26 Federal Plaza
Owner Phone: 212-264-3446
Operator Type: F
Operator: Same
Operator: Same
Operator Phone: Unknown
EPA ID: NY4470000635
Registry: Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID: Unknown
RCRA Permitted: Unknown
Site Code: 5-office
Owner City State: NY, NY 10278
Operator City State: Not reported
Quadrangle: Unknown
Latitude: Unknown
Longitude: Unknown
Acres: 0.00
Operator Date: Unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US INFORMATION AGENCY (Continued)

S108146423

Close Date:	Unknown
Completed:	PA/SI
Active:	Not reported
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	Unknown
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Access:	Unknown
Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US INFORMATION AGENCY (Continued)

S108146423

TCLP: Not reported
Waste: Not reported

AS222 BROOKLYN WEST 06 DOS -DDC
NNE 127 2ND AVENUE
1/4-1/2 BROOKLYN, NY
0.447 mi.
2362 ft. Site 1 of 4 in cluster AS

NY LTANKS S104790007
NY Spills N/A

Relative:
Higher

Actual:
15 ft.

LTANKS:
Name: BROOKLYN WEST 06 DOS -DDC
Address: 127 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0012497 / 2003-10-30
Facility ID: 0012497
Site ID: 154174
Spill Date: 2001-02-22
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 2001-02-22
CID: 403
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-02-22
Spill Record Last Update: 2004-12-20
Spiller Name: N/A
Spiller Company: NYC DEPT SANATATION
Spiller Address: 800 EAST 176TH ST
Spiller County: 001
Spiller Contact: ROBERT JOHNSON
Spiller Phone: (718) 768-5795
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 172748
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
KRIMGOLD "
Remarks: "WILL UNCOVER AND INSPECT. SAME AS SPILL # 0007546."

All TTF:

Facility ID: 0012497
Spill Number: 0012497
Spill Tank Test: 1526108
Site ID: 154174
Tank Number: 8
Tank Size: 6000
Material: 0001
EPA UST: Not reported
UST: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 154174
Operable Unit ID: 834021
Operable Unit: 01
Material ID: 542761
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: BROOKLYN WEST 06 DOS -DDC
Address: 127 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0007613 / 2000-09-29
Facility ID: 0007613
Facility Type: ER
DER Facility ID: 172748
Site ID: 240357
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 2000-09-28
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 2000-09-28
CID: 390
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-09-28
Spill Record Last Update: 2004-12-20
Spiller Name: UNK
Spiller Company: SANITATION GARAGE
Spiller Address: 138 11TH ST

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

Spiller Company: 001
Contact Name: LIRO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
KRIMGOLD SAME SITE AS 127 2ND AVE. SEE SPILL # 0007546."
Remarks: "poss leak into an underground hole"

All Materials:

Site ID: 240357
Operable Unit ID: 830197
Operable Unit: 01
Material ID: 545148
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: SOIL
Address: 127 2ND AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1202601 / Not Reported
Facility ID: 1202601
Facility Type: ER
DER Facility ID: 419745
Site ID: 465374
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2012-06-15
Investigator: adzhitom
Referred To: CORRECTED FIGURE SHOULD BE SUBMITTED
Reported to Dept: 2012-06-15
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 1
Date Entered In Computer: 2012-06-15
Spill Record Last Update: 2016-12-15
Spiller Name: Not reported
Spiller Company: NYC DEPT OF SANITATION
Spiller Address: Not reported
Spiller Company: 999
Contact Name: STEVE FRANK
DEC Memo: "6-15-2012 The following e-mail was received from S. Frank (LiRo):
Alex, The approved remedial excavation work at Brooklyn West 6 is in
progress and the diesel fill line in the sidewalk area appears to be
the contaminant source. We excavated the line earlier today and found

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

a hole in the line. We have excavated the area to a depth of five feet which is approximately one foot below the average water table depth. We are planning to install a Passive Product Collection Trench to aid in the recovery of any residual oil in the formation. Please advise if you would like to open a separate spill number based on the observations today. Thanks, Steve Frank LiRo Engineers, Inc. According to S. Frank it is a double wall fiberglass pipe. AZ 6-15-2012 The following e-mail was sent to S. Frank and DDC: Steve, A new spill should be called in. The tank must be IMMEDIATELY taken out of service. Please confirm that the tank is taken out of service. Thanks, Alex Alexander Zhitomirsky Engineering Geologist 2 NYSDEC Region 2 Division of Environmental Remediation 2-21-2013 Discussed the spill with S. Frank. The repaired the fill line, excavated soil around it and took end-point samples. The report dated 10-11-2012 contains some inaccurate info in figure 7. LiRo will rectify this info and resubmit the report. AZ 4-5-2014 Reviewed a monitoring report dated November 6-2013. The report stated that in June 2013, soil was excavated at the site. During the excavation LiRo observed free-phase product in the soil located around the diesel UST fill port and piping at the southern end of the remedial excavation. The spill occurred from a hole in the diesel fill line piping.. Contaminated soil was excavated from beneath the fill piping, and a passive product collection trench was installed in the area of the fill piping at 5' bgs. During excavation 17 soil samples were taken. Twelve soil samples were collected at 4'-6', with total VOC concentrations ranging from non-detect to 251,510 ppb in WS-05. At 3 sidewalls samples VOC exceedances were detected. Further excavation in the western direction was limited, due to the potential risk of undermining 2nd Avenue subway. AZ 12-13-2016 Left a message for S. Frank. AZ December 15, 2016 Reviewed semi-annual monitoring report dated March 29, 2016. Free-phase product is present in LMW-01. EFR will be continued in this well. I have contacted S. Frank and we discussed spill consolidation. It was decided that since this spill is caused by a fill line remediation will continue under a separate spill number. AZ"

Remarks:

"Caller advised unknown amount of diesel spilled into soil from historic spill. Clean up is pending."

All Materials:

Site ID: 465374
Operable Unit ID: 1215396
Operable Unit: 01
Material ID: 2213522
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name: BROOKLYN WEST 06 DOS -DDC
Address: 127 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0007546 / 2014-03-05
Facility ID: 0007546

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

Facility Type: ER
DER Facility ID: 172748
Site ID: 293781
DEC Region: 2
Spill Cause: Other
Spill Class: C3
SWIS: 2401
Spill Date: 2000-09-27
Investigator: ADZHITOM
Referred To: NFA
Reported to Dept: 2000-09-27
CID: 312
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-09-27
Spill Record Last Update: 2014-03-05
Spiller Name: TONY CAGGIANO
Spiller Company: BROOKLYN WEST 6TH SANITAT
Spiller Address: 127 2ND AV
Spiller Company: 001
Contact Name: TONY CAGGIANO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 09/29/05. The site has free phase contamination. AZ 1/12/2006 The site moved from Priority 1 category to Priority 2 category as per Jon Kolleeny request. AZ 6-8-2006 At the meeting with DDC/Greyhawk/Roux on 5/23/2006 DEC requested to investigate this spill which has not been investigated yet. AZ 12/22/2006 At the meeting with DDC/Greyhawk on 12/12/2006 the remedial progress was discussed. Greyhawk will address this site. Soil Sampling plan will be submitted. Some wells will be added at the heating oil tank location. AZ 2-7-2007 E-mail was sent to Brian Morrissey: In your quarterly monitoring report dated July 7, 2006, you have not recommended reduction of groundwater monitoring frequency for this site. You recommended continue quarterly groundwater sampling. Also, you recommended reduction of water level gauging frequency to quarterly. DEC concurs with this proposal. Groundwater sampling should be performed quarterly due to the presence of dissolved phase contamination in groundwater. AZ 5-7-2007 Reviewed Quarterly Report (July-December 2006) submitted by Roux on January 31, 2007. Elevated concentrations of VOCs were detected in 12 wells sampled and the total concentration of VOCs ranged from non detect to 771 ppb (MW-05). Significant VOCs concentrations were detected in 3 wells. Currently, soil and gw impacts are limited to the area along Second Avenue. The system has been off-line since July 25, 2006, due to the malfunction of the carbon unit and failure of the seal water tank floats. Vacuum to extraction wells was restricted. In the last three months of work MPE system was effective in removing VOC contaminants (significant increase in influent Air Concentrations about 95 ppbv). Roux suggested decommissioned and dismantle the MPE system, conduct a soil investigation, conduct a PermeOx Plus injection. DEC approved

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

soil investigation and PermeOX injection. Also, Roux recommended reduce frequency of the groundwater gauging to quarterly. This request has been previously approved by DEC on 2-7-2007. Groundwater sampling should be performed quarterly. MW-09 could be removed from the sampling program. SVOC sampling could be removed from the monitoring program. In conversation with Brian Morrissey I suggested converting MPE system into SVE system since MPE system was effective in treating soil contamination (based on MPE System Influent Air Concentration data). E-mail was sent to Roux/DDC/Greyhawk: I have reviewed Roux's proposals for this site. Roux suggested decommissioning and dismantling the MPE system, conducting a soil investigation and performing a PermeOx Plus injection. I approve soil investigation plan and PermeOX injection. The system has been off-line since July 25, 2006, due to the malfunction of the carbon unit and failure of the seal water tank floats. I suggest converting MPE system into SVE system to expedite soil remediation; since MPE system was effective in treating soil contamination (based on MPE System Influent Air Concentration data). The system should remain intact at the site. Also, Roux recommended reducing frequency of the groundwater gauging to quarterly. This request has been previously approved by DEC on 2-7-2007. Groundwater sampling should be performed quarterly. MW-09 could be removed from the sampling program. SVOC sampling could be removed from the monitoring program. AZ 10-11-2007 An e-mail was sent to Roux/DDC/Greyhawk/VB: I have reviewed report for this site covering the period of January - March 2007 and received on August 1, 2007. Total VOC concentrations ranging between 305 ppb and 1,214 ppb were detected in site wells. Roux listed as upcoming tasks completion of the soil investigation and PermeOx injection work which commenced on June 28, 2007. Roux recommended removing MW-09 from the sampling program since no VOC or SVOC have been detected in this well for the past two consecutive sampling rounds. Also, Roux recommended removing SVOCs from the sampling program, but continue to sample for VOC with naphthalene as a target compound. DEC concurred with these proposals. Roux recommended reducing frequency of the groundwater monitoring. Current contaminant concentrations at the site do not justify such reduction. AZ 3-26-2008 Soil sampling was performed in June/July 2007. Soil boring RXSB-01 had concentration 232,000 of total VOC AT 2' to 4'. MW-14 had total VOC concentration in gw of 1,239 ppb. An e-mail was sent to Roux/DDC/V.Brevdo/Greyhawk: I have reviewed a Monitoring Report for the above site for the period of April - September 2007, dated December 21, 2007. Roux recommends replacing MW-16. Also, Roux proposed removing monitoring well MW-11 from the quarterly groundwater sampling but continue to sample it annually. These proposals are approved. AZ 6-12-2008 As per DEC request to investigate the fuel oil spill, Roux submitted report dated June 2, 2008, addressing spill #0007546. Roux stated that the only tank containing #2 fuel oil on the site was a 6,000 gallon tank (Tank #8). Roux recommended closure of this spill. I contacted Brian Morrissey (Roux) and suggested that Roux submit a plan showing the heating oil tank (Tank#8) location as well as the tanks which caused the leak which is currently being remediated by DDC. Also, existing wells and borings should be shown on the plan. The report should show that Tank #8 caused no impact to soil and groundwater or that the area impacted by tank #8 is currently under remediation. If such information can not be provided, then an investigation should be performed to establish if there is an impact to the environment caused by the fuel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

oil tank. B. Morrissey concurred. AZ 1-30-2009 An e-mail was sent to Roux/Greyhawk/DDC/V.B.: As per DEC request to investigate this spill, Roux submitted report dated June 2, 2008, addressing spill #0007546. Roux stated that the only tank containing #2 fuel oil on the site was a 6,000 gallon tank (Tank #8). I contacted Roux in June 2008 and suggested that Roux submit a plan showing the heating oil tank (Tank#8) location as well as the tanks which caused the leak which is currently being remediated by NYCDDC. Also, existing wells and borings should be shown on the plan. The report should show that Tank #8 caused no impact to soil and groundwater or that the area impacted by tank #8 is currently under remediation. There are also closed and active motor oil/lube oil tanks listed at this facility. Spill report also indicated motor oil tank as a source of the spill. Tank which is related to this spill number should be identified and its location shown on the plan. After this information is provided and reviewed, this spill will be considered for closure. If the data provided indicate that this spill has not been addressed, the spill should be investigated and remediated. If the information regarding the tanks in question can not be provided, then an investigation should be performed to establish if there is an impact to the environment caused by the fuel oil tank. So far, this information has not been received by DEC. Please submit to DEC requested plan and narrative regarding this spill. AZ 12-07-09 An e-mail was sent to Brian Morrissey (Roux) and NYCDDC (Fatemeh Ashkan): This spill should be investigated as per DEC's e-mail dated 1-30-09. Roux should submit a plan showing the heating oil tank (Tank#8) location as well as the locations of tanks which caused the leak which is currently being remediated by NYCDDC. Existing wells and borings should be shown on the plan. The report should demonstrate if Tank #8 caused impact to soil and groundwater. Soil borings/wells should be advanced/installed in the areas of Tank#8 and motor oil/lube oil tanks in question. There are closed and active motor oil/lube oil tanks listed at this facility. Spill report also indicated motor oil tank as a source of the spill. Tanks which are related to this spill number should be identified and their locations shown on the plan. AZ 11-24-2010 LiRo took over this case. LiRo in their report dated August 31, 2010, recommended investigation of the 6,000 gal heating oil tank. This request was approved via e-mail. AZ 4-29-2011 This spill probably resulted from the 6,000 gal fuel oil UST. LiRo proposed advancing one soil boring downgradient of the existing 6,000 gal heating oil tank and two borings downgradient of the assumed location of the former 6,000 gal heating oil tank (northeast of the existing tank). DEC asked to install four boring around the tank, if feasible. AZ 9-12-2011 Discussed this spill with S. Frank. It seems that LiRo is unsure about the location of this tank. LiRo will try to locate the tank in question. AZ 5-29-2012 LiRo will implement the excavation of two hot spots along the exterior wall of the subject structure along 2nd Ave. S. Frank confirmed in a phone conversation that the excavation will take place in June 2012. AZ 2-20-2013 I contacted S. Frank of LiRo. LiRo doesn't know the exact location of the former 6,000 gal #2 fuel oil tank. It was located in the vicinity of the current 6,000 gal #2 oil tank. No borings were installed south of this tank. Three borings were installed along a straight line north of the tank. LiRo will install two additional borings south of the current tank to confirm absence of contamination. AZ 5-31-2013 Reviewed a report dated 1-31-2013. According to this report no borings were installed south of a possible location of the former

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

6,000 gallon #2 fuel oil tank. When borings south of this tank are advanced, petition for spill closure will be submitted. AZ 4-5-2014 The following e-mail was sent to S. Frank and V. Brevdo: Dear Steve, I have reviewed a Semi- Annual Monitoring Report for this site dated November 5, 2013. The report stated that in order to investigate Spill#0007546, LiRo advanced two soil borings on August 13, 2013. Analytical results of the two borings reported no VOCs or SVOCs concentrations exceeding CP-51. Based upon soil data collected from these borings and previously advanced borings LSB-03 and LSB-04, LiRo concludes that no petroleum impacts are present in the area of the Tank #8. As a result, LiRo is requesting closure of this spill. Based on the above information this spill is closed. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or remedial action the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was unknown at the time of this closure. II. Environmental conditions related to this spill case which were unknown to the Department at the time of this closure. III. Information received, in whole or part, after the Department's spill case closure, which indicates that corrective action was not sufficiently protective of human health and/or the environment. IV. Fraud in obtaining this spill case closure determination. As a precaution, we must bring your attention to our concerns for the future use of this site. If subsurface contamination is encountered while excavating for any construction activity, appropriate remedial and vapor mitigation efforts must be taken to fully prevent vapor intrusion into any site development and to ensure human health and safety. This spill closure does not exempt the Responsible Parties from compliance with any applicable laws and regulations. Please be advised that you should maintain a permanent file of all documentation and correspondence regarding this case for future use as the Department's files may not be maintained indefinitely. Sincerely, Alex Zhitomirsky"

Remarks: "POSS FROM FUEL OIL TANKS ON SITE. ALSO SEE SPILL # 0012497. "

All Materials:

Site ID: 293781
Operable Unit ID: 828323
Operable Unit: 01
Material ID: 545083
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 293781
Operable Unit ID: 828323
Operable Unit: 01
Material ID: 545082
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

Units: G
Recovered: .00
Oxygenate: Not reported

Name: BROOKLYN WEST 06 DOS -DDC
Address: 127 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9310764 / Not Reported
Facility ID: 9310764
Facility Type: ER
DER Facility ID: 172748
Site ID: 208201
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 1993-12-06
Investigator: ADZHITOM
Referred To: REPLACEMENT WELLS WILL BE INSTALLED
Reported to Dept: 1993-12-06
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 5
Date Entered In Computer: 1993-12-06
Spill Record Last Update: 2019-04-26
Spiller Name: Not reported
Spiller Company: NYC DEPT. SANIT.
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY 10/10/95: This is additional information about material spilled from the translation of the old spill file: CONTAM. SOIL. TRANSFERRED FROM Y.KRIMGOLD. 4-26-2004 Reviewed a Monitoring Report. The report presented remedial system performance and groundwater monitoring data. The report stated that based on the site monitoring data, the MPE system is effectively treating contamination. However, pressure monitoring wells exhibit persistently low vacuum measurements due to the shallow water conditions. It is possible that the dissolved hydrocarbon plume which is still present in the northeastern part of the site is due to the low vacuum within the system?s radius of influence. DEC recommended to modify MPE system to address this problem. LiRo recommended the advancement of five soil borings to assess the progress of soil remediation. The Department concured with this proposal.AZ 7-21-2005 Reviewed a Monitoring Report for January 2005-March 2005. The report presented remedial system performance and groundwater monitoring data. The report stated that based on the site monitoring data, the MPE system is effectively treating contamination. Five soil borings will be advanced to assess

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

the progress of soil remediation. One or more additional extraction wells may be warranted to speed the remediation. LiRo will determine if and where new extraction wells may be installed. The Department concurred with this proposal. AZ 11-15-2005 Reviewed a Monitoring Report April- June 2005. Free phase was found at the site - MW-1 - 0.2' MPE system is working at the site. Recent soil sampling showed elevated VOC concentrations at SBR-19 (512,000 ppb) and SBR-18 (21,000 ppb). Soil contamination has not been removed. GW results show persisting contamination. Data from hot spot suggesting not much reduction in contamination has taken place during last monitoring period (summer 2005). No NFA for the site. GW monitoring results total VOCs: 103ppb, 772 ppb, 330ppb, 855 ppb. LiRo recommended converting existing well MW-14 for use as an additional extraction point in the most contaminated portion of the site. The Department concurred with this proposal. Also, LiRo recommended shutting down several extraction wells. The Department approved shutting down extraction well EW-6. AZ 1-3-2005 Reviewed a Monitoring Report July - September 2005. Groundwater results show persisting contamination. MPE system is fully back on-line. AZ 4-10-2006 Reviewed a Monitoring Report October - December 2005. LiRo is no longer the environmental consultant for the site as of December 2005. LiRo states that there is persisting groundwater contamination. DEC approved conversion of MW-14 for extraction use but there was insufficient time for LiRo to conduct the conversion work before turning the site to the new DDC Consultant. AZ 6-8-2006 At the meeting with DDC/Greyhawk/Roux on 5/23/2006 CM informed DEC that the system is shut down. CM will implement ORC. No source removal was performed. Depth to gw is 2'-3'. AZ 7/31/2006 Reviewed Work Plan dated July 6, 2006, and received on July 10, 2006. The Work Plan was discussed with Jon K. The plan cannot be approved at this point since it lacks essential information. Existing soil data must accompany the plan and must be plotted on the site map. Soil and groundwater plume maps must be included in the Work Plan. A short description of the site status and groundwater flow direction should be shown on the plan. A brief description of the remediation system, if any, current contamination levels, performed remedial activities and status of the tanks at the site should be included in the work plan. Upon submission of hard copies with this information, this work plan will be reviewed again. The information listed above has been routinely submitted by other consultants in their work plans. An e-mail with these comments was sent to Wendy Shen (Roux). AZ 9/27/2006 Reviewed Quarterly Report (April-June 2006) submitted by Roux on July 13, 2006. Elevated concentrations of VOCs were detected in 12 wells sampled and the total concentration of VOCs ranged from 8 ppb to 2,430 ppb (MW-14). Currently, soil and gw impacts are limited to the area along Second Avenue. MPE System will be shut down (DEC concurred on 5/23/2006), implement enhanced bioremediation, soil vapor investigation will be conducted, continue gw monitoring, soil samples will be collected (Work Plan was rejected by DEC on 7/31/2006). AZ 2-7-2007 E-mail was sent to Brian Morrissey: In your quarterly monitoring report dated July 7, 2006, you have not recommended reduction of groundwater monitoring frequency for this site. You recommended continue quarterly groundwater sampling. Also, you recommended reduction of water level gauging frequency to quarterly. DEC concurs with this proposal. Groundwater sampling should be performed quarterly due to the presence of dissolved phase contamination in groundwater. AZ 5-7-2007 Reviewed Quarterly Report (July-December 2006) submitted by

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

Roux on January 31, 2007. Elevated concentrations of VOCs were detected in 12 wells sampled and the total concentration of VOCs ranged from non detect to 771 ppb (MW-05). Significant VOCs concentrations were detected in 3 wells. Currently, soil and gw impacts are limited to the area along Second Avenue. The system has been off-line since July 25, 2006, due to the malfunction of the carbon unit and failure of the seal water tank floats. Vacuum to extraction wells was restricted. In the last three months of work MPE system was effective in removing VOC contaminants (significant increase in influent Air Concentrations about 95 ppbv). Roux suggested decommissioned and dismantle the MPE system, conduct a soil investigation, conduct a PermeOx Plus injection. DEC approved soil investigation and PermeOX injection. Also, Roux recommended reduce frequency of the groundwater gauging to quarterly. This request has been previously approved by DEC on 2-7-2007. Groundwater sampling should be performed quarterly. MW-09 could be removed from the sampling program. SVOC sampling could be removed from the monitoring program. In conversation with Brian Morrissey I suggested converting MPE system into SVE system since MPE system was effective in treating soil contamination (based on MPE System Influent Air Concentration data). E-mail was sent to Roux/DDC/Greyhawk: I have reviewed Roux's proposals for this site. Roux suggested decommissioning and dismantling the MPE system, conducting a soil investigation and performing a PermeOx Plus injection. I approve soil investigation plan and PermeOX injection. The system has been off-line since July 25, 2006, due to the malfunction of the carbon unit and failure of the seal water tank floats. I suggest converting MPE system into SVE system to expedite soil remediation; since MPE system was effective in treating soil contamination (based on MPE System Influent Air Concentration data). The system should remain intact at the site. Also, Roux recommended reducing frequency of the groundwater gauging to quarterly. This request has been previously approved by DEC on 2-7-2007. Groundwater sampling should be performed quarterly. MW-09 could be removed from the sampling program. SVOC sampling could be removed from the monitoring program. AZ 10-11-2007 An e-mail was sent to Roux/DDC/Greyhawk/VB: I have reviewed report for this site covering the period of January - March 2007 and received on August 1, 2007. Total VOC concentrations ranging between 305 ppb and 1,214 ppb were detected in site wells. Roux listed as upcoming tasks completion of the soil investigation and PermeOx injection work which commenced on June 28, 2007. Roux recommended removing MW-09 from the sampling program since no VOC or SVOC have been detected in this well for the past two consecutive sampling rounds. Also, Roux recommended removing SVOCs from the sampling program, but continue to sample for VOC with naphthalene as a target compound. DEC concurred with these proposals. Roux recommended reducing frequency of the groundwater monitoring. Current contaminant concentrations at the site do not justify such reduction. AZ 3-26-2008 Soil sampling was performed in June/July 2007. Soil boring RXSB-01 had concentration 232,000 of total VOC AT 2' to 4'. MW-14 had total VOC concentration in gw of 1,239 ppb. An e-mail was sent to Roux/DDC/V.Brevdo/Greyhawk: I have reviewed a Monitoring Report for the above site for the period of April - September 2007, dated December 21, 2007. Roux recommends replacing MW-16. Also, Roux proposed removing monitoring well MW-11 from the quarterly groundwater sampling but continue to sample it annually. These proposals are approved. AZ 1-30-2009 Reviewed Quarterly report covering the period from October 2007 through June 2008. Soil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

sampling collected for VOC, SVOC, metals and bioremediation parameters in May 2008. Samples collected from 2'-4'. Total VOC concentrations in soil are up to 94,900 ppb. System is shut down. First round of PermeOX injection was performed. Total VOC concentrations in groundwater samples is up to 1,123 ppb. Second round of PermeOX injection will be performed. An e-mail was sent to Roux/DDC/Greyhawk/V.B.: I have reviewed Quarterly Monitoring Report covering the period from October 2007 through June 2008. Roux recommended conducting the second round of PermeOX Injection, continue quarterly groundwater monitoring and removing MW-11 from the quarterly sampling but continue to sample this well annually. These recommendations are approved. Wells MW-17R and MW-20R should be sampled quarterly as the downgradient wells. Soil contamination should be addressed by Roux and recommendations submitted to NYSDEC. AZ 12-08-09 Reviewed Quarterly report covering the period from July 2008 through December 2008 and submitted in May 2009. Total VOC concentrations in soil are up to 94,900 ppb. System is shut down. First round of PermeOX injection was performed. Total VOC concentrations in groundwater samples is ranging from 7 ppb to 622 ppb. Second round of PermeOX injection will be performed. An e-mail was sent to Roux/DDC/Greyhawk/V.B.: I have reviewed the latest Quarterly Monitoring Report covering the period from July 2008 through December 2008. Roux recommended conducting the second round of PermeOX Injection, continue quarterly groundwater monitoring and re-developing injection wells IP-01, IP-04 and IP-06. New injection point should be installed upgradient of MW-07. These recommendations are approved. High level VOC shallow soil contamination near MW-14 should be addressed by NYCDDC. A hot spot soil excavation should be performed. A plan for the hot spot excavation should be included in the next monitoring report. AZ 11/24/2010 LiRo recommended conducting further soil and groundwater sampling along 2nd Avenue. These recommendations were approved via e-mail. Shallow soil excavation might be a valid option for remediation of this spill. AZ 5-4-2011 An e-mail was sent to LiRo/DDC/V. Brevdo: I have reviewed a quarterly report/remedial work plan for the above site dated January 12, 2011. Also, we discussed this site on the phone. As per our discussion, suggested nutrient injection suggested by LiRo will not be the most effective remedial strategy since the soil in the area is heavily contaminated and the groundwater has relatively moderate levels of contamination. Instead, LiRo will study hot spot shallow soil excavation. This remedial approach will be used at the site, if feasible. Five soil borings proposed by LiRo are approved. LiRo recommended removing the MPE system from the site. This recommendation is approved. AZ 9-12-2011 Reviewed Soil Excavation Proposals dated April 8, 2011. The following e-mail was sent to S.Frank/V.Brevdo/F.Ashkan: Dear Steve, I have reviewed Soil Excavation Proposals dated April 8, 2011. The proposals stated that high level residual VOC soil contamination is present beneath the sidewalk along 2nd Ave. LiRo proposed an excavation of the contaminated area. This excavation plan is approved. If groundwater is encountered, several groundwater samples should be taken. MPE system, which has been offline since July 2006, is in a state of disrepair due to mechanical failures and mineral and silt buildup in piping. This system can not be repaired. LiRo recommended removal of the MPE system. This proposal is approved. Bio injection should be postponed until the soil excavation is performed and its results are evaluated. AZ 5-29-2012 Reviewed Monitoring report dated January 26,

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

2012. Groundwater sampling performed in October 2011 showed that VOC groundwater contamination still persists in six monitoring wells. LiRo will remove the MPE system as approved by DEC on May 4, 2011. MW-01 will be added to the monitoring well sampling plan. AZ 2-21-2013 The following e-mail was sent to S. Frank/V. brevdo/F. Ashkan: Dear Steve, We have discussed yesterday a monitoring report for this site dated October 11, 2012. I approved completion of three replacement wells. LiRo will modify Fig. 7 of the report, which has some discrepancies, and check all tables and figures. Sincerely, Alexander Zhitomirsky 6-4-2013 Reviewed Quarterly Monitoring Report dated 1-31-2013. Discussed the site with S. Frank over the phone. Apparently discrepancies in Fig. 7, which became Fig. 4 in the most recent report, were not fixed. Data and concentrations in this figure are different from the concentrations in the tables. LiRo will issue a new report which will correct discrepancies in Fig.4/Fig.7. Gasoline 4,000-gal tank was removed. Free phase was encountered in the area where the product collection trench is located. It is not clear where the diesel tank which caused this spill, was located. LiRo will clarify the location of this tank so spill consolidation could be considered. They will clarify all discrepancies in the upcoming monitoring report. AZ 4-5-2014 Reviewed quarterly monitoring report dated November 6, 2013. As a result of the free-phase product reported within LMW-01 AND PPCT-01, monthly EFR events were conducted on February 2, March 20, May 14 and July 25, 2013. A total of 1,614 gallons of groundwater mixture have been removed since February 2013. AZ 3-17-2014 Reviewed quarterly monitoring report dated July 30, 2014. The following e-mail was sent to S. Frank: Dear Steve, I have reviewed a monitoring report for this site for the period of November 2012 - April 2013. The report proposed a reduction in routine sampling from quarterly to semi-annual. I concur with this proposal. EFR should be continued on an as-needed basis. Free product measurements should be performed quarterly. Sincerely, Alexander Zhitomirsky Sept 17, 2014 Reviewed quarterly monitoring report dated July 30, 2014. As a result of the thin layer of free-phase product reported within LMW-01 and PPCT-01; monthly EFR events were conducted. A total of 2,165 gallons of groundwater/oil mixture have been removed. An increase in VOC concentrations was noted in well MW-11 in the data reported in December 2013. June 17, 2015 Reviewed a quarterly monitoring report dated August 7, 2014. A total of three EFR events were completed. In February 2014 VOC concentrations increased. ORC socks were installed in MW-05. Globules of free product were observed during well development in monitoring well LMW-01. AZ Aug. 4, 2015 Reviewed a semi-annual monitoring report dated February 27, 2015. As a result of performed EFR a cumulative total of 2,680 gallons of groundwater/oil mixture have been removed between February 2013 and December 2014. Free phase product thickness in well LMW-01 reported a slight increase during this monitoring period. AZ April 18, 2016 Reviewed a semi-annual monitoring report dated September 14, 2015. As a result of performed EFR a cumulative total of 3,365 gallons of groundwater/oil mixture have been removed between February 2013 and June 2015. Free phase product thickness in well LMW-01 reported an increase during this monitoring period. Free phase product in LMW-01 ranged from 0.02' to 0.55'. LiRo performed EFR at well MW-05 to reduce dissolved phase contamination. Five EFR events have been performed. AZ December 15, 2016 Reviewed a semi-annual monitoring report dated 3/29/2016. As a result of performed EFR a cumulative total of 4,301 gallons of groundwater/oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

mixture have been removed between February 2013 and December 2015. Free phase product thickness in well LMW-01 reported an increase during this monitoring period. Free phase product thickness in LMW-01 was 0.12' in July 2015, however, no measurable free-phase product was reported between August 2015 and December 2015. It should be noted that a petroleum absorbent sock was changed monthly in this well which may be masking measurable free-phase product. AZ March 16, 2017 Reviewed a semi-annual monitoring report dated 8/15/2016. As a result of performed EFR a cumulative total of 5,243 gallons of groundwater/oil mixture have been removed between January 2016 and June 2016. Free phase product thickness in LMW-01 was 0.07' in April 2016. EFR is performed monthly. It should be noted that a petroleum absorbent sock was changed monthly in this well which may be masking measurable free-phase product. AZ August 8, 2017 Reviewed a semi-annual report dated February 13, 2017. The report stated that after the petroleum absorbent sock was removed from LMW-01 in September 2016, measurable free phase product was found at 0.19' thick on October 31, 2016. After EFR in November 2016, no free phase product was measured on December 5, 2016. EFR will be continued on wells LMW-01 and PPCT-01 as needed. AZ October 23, 2017 Reviewed a semi-annual report dated August 10, 2017. The report stated that during sampling on March 14, 2017, some wells were inaccessible. The last time free-phase product was measured in LMW-01 was in October 2017. LiRo proposed to remove monitoring wells MW-11, MW-17R and MW-20R from the sampling program. AZ The following e-mail was sent to S. Frank: Dear Steve, I have reviewed a semi-annual report for this site dated August 10, 2017. LiRo proposed to remove monitoring wells MW-11, MW-17R and MW-20R from the sampling program. MW-11 could be removed from the sampling program. The other two wells are downgradient wells and should be sampled semi-annually in order to monitor plume migration. Sincerely, Alex Zhitomirsky July 10, 2018 Reviewed a semi-annual report dated January 23, 2018. The report stated that free-phase product was reported in well LMW-01 during September 2017 and October 2017 EFR events. ORC socks were changed in two wells. In addition, ORC socks were installed in wells LMW-02 and LMW-03. AZ April 26, 2019 Reviewed a semi-annual report dated August 28, 2018. The report stated that free-phase product was reported in well LMW-01 during June 2018 EFR events at a thickness of 0.11'. ORC socks are maintained in four wells. AZ "

Remarks: "TANK REMOVAL. TRYING TO DETER. THE SOURCE - DIESEL TANKS WILL BE TESTED. ALSO SEE SPILL # 9413174."

All Materials:

Site ID: 208201
Operable Unit ID: 989522
Operable Unit: 01
Material ID: 389842
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

Name: BROOKLYN WEST 06 DOS -DDC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN WEST 06 DOS -DDC (Continued)

S104790007

Address: 127 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9413174 / 2003-10-30
Facility ID: 9413174
Facility Type: ER
DER Facility ID: 172748
Site ID: 208202
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: E5
SWIS: 2401
Spill Date: 1994-12-14
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 1995-01-03
CID: Not reported
Water Affected: Not reported
Spill Source: Railroad Car
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-03-17
Spill Record Last Update: 2004-12-20
Spiller Name: Not reported
Spiller Company: DEPT OF SANITATION
Spiller Address: WEST 6TH STREET
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
KRIMGOLD "
Remarks: "VENT PIPE OVERFLOWED. SEE SPILL # 9310764."

All Materials:
Site ID: 208202
Operable Unit ID: 1010730
Operable Unit: 01
Material ID: 375452
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AT223
SSW
1/4-1/2
0.448 mi.
2367 ft.
MIL MED SUPPLY NO. 1
NO CITY, NY
Site 1 of 3 in cluster AT

FUDS
1024899196
N/A

Relative:
Higher

Actual:
10 ft.

FUDS:
EPA Region: 2
Installation ID: NY29799F760000
Congressional District Number: 7
Facility Name: MIL MED SUPPLY NO. 1
FUDS Number: C02NY0041
City: NO CITY
State: NY
County: Not reported
USACE District: New England District (NAE)
Status: Properties without projects
Current Owner: Other Federal Government
EMS Map Link: <https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=62684>
Eligibility: Eligible
Has Projects: No
NPL Status: Not Listed
X Coord: -74.003611109999895
Y Coord: 40.659444440000001
Latitude: 40.659444440000001
Longitude: -74.003611109999994

224
SSW
1/4-1/2
0.454 mi.
2396 ft.
72 PRECINCT NYPD -DDC
830 4TH AVENUE
BROOKLYN, NY

NY LTANKS
NY Spills
S102233280
N/A

Relative:
Higher

Actual:
25 ft.

LTANKS:
Name: 72 PRECINCT NYPD -DDC
Address: 830 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9514143 / 2003-10-31
Facility ID: 9514143
Site ID: 317853
Spill Date: 1996-02-05
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 1996-02-06
CID: 312
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1996-02-06
Spill Record Last Update: 2004-12-22
Spiller Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

Spiller Company: NYC
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 70709
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
KRIMGOLD "
Remarks: "gasoline odor in soil after tanks were removed. Same as spill #
9514143."

All Materials:

Site ID: 317853
Operable Unit ID: 1028675
Operable Unit: 01
Material ID: 354282
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: 72 PRECINCT NYPD -DDC
Address: 830 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9502759 / 2005-01-10
Facility ID: 9502759
Site ID: 95328
Spill Date: 1995-06-01
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: ADZHITOM
Referred To: Not reported
Reported to Dept: 1995-06-05
CID: Not reported
Water Affected: Not reported
Spill Notifier: DEC
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1995-06-13
Spill Record Last Update: 2005-01-10
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 70709
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY TRANSFERRED FROM Y.KRIMGOLD. This spill is referred to spill # 9515879 and is closed today by II (01/10/05). "
Remarks: "WATER FOUND IN TANK - POSSIBLE LEAK - TO BE REPAIRED 6/5/95. Also see spill #s 9514143 and 9604636."

All Materials:

Site ID: 95328
Operable Unit ID: 1017343
Operable Unit: 01
Material ID: 567025
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: 72 PRECINCT NYPD -DDC
Address: 830 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9515879 / Not Reported
Facility ID: 9515879
Facility Type: ER
DER Facility ID: 70709
Site ID: 75551
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 1996-03-11
Investigator: ADZHITOM
Referred To: REMEDIATION IS PENDING
Reported to Dept: 1996-03-12
CID: 349
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 5
Date Entered In Computer: 1996-03-12
Spill Record Last Update: 2019-08-21
Spiller Name: MIKE ENGLISH
Spiller Company: NYC POLICE DEPT 72 PCT
Spiller Address: 4TH AV & 29TH ST

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

Spiller Company:

001

Contact Name:

MIKE ENGLISH

DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY TRANSFERRED FROM Y.KRIMGOLD. 10-12-2005 SVE and pump and treat systems are operated at the site. SVE system is extracting significant concentrations from the vadose zone. AZ 1/13/2006 Reviewed system report. Analytical results showed total VOCs concentrations in air samples at 550 ppb and 44.7 ppb in 1st sampling events. AZ 4-17-2006 Reviewed system report received in November 2006. Analytical results showed total VOCs concentrations in air samples at 1,832 ppb suggesting that SVE system continues to extract contaminants. URS recommended continuation of the groundwater extraction and treatment system. Groundwater sampling was performed. All wells except one showed exceedances ranging from 127 ppb to 19,100 ppb. Contaminant concentrations increased in wells MW-6,7,8,11 and 12. The average total VOC concentration increased from 6,297 ppb to 7,417 ppb. AZ 12/08/2006 Reviewed monitoring report dated September 22, 2006 and received on September 27, 2006. This report covers April - June 2006. On January 1, 2006 Greyhawk was assigned responsibility for this site. The site has SVE and GWET systems. VOCs were detected in all nine monitoring wells with concentrations ranging from 30 ppb to 14,700 ppb in MW-06. concentrations increased in two monitoring wells MW-01 and MW-08. It appears that the SVE system is not functioning efficiently as evidenced by relatively low VOC mass removal and restricted wellhead vacuum- 0.001 to 0.052 water column. The carbon unit should be replaced. Relatively low pumping rate limits the capture zone of 3 pumping wells. An increase in pumping rates would expand the size of the capture zone and might improve effectiveness of the SVE system. Significant VOC contamination persist in 7 of the 9 monitoring wells. Roux suggested continue quarterly gw monitoring, verify depth and condition of the ventilation wells, collect samples from MW-3 which was previously removed from the sampling program but is located very close to two other wells with significant VOC concentrations. Evaluate methods to optimize SVE and GWET systems. DEC concurred. AZ 4/26/2007 Reviewed monitoring report for the period of July - September 2006, dated December 15, 2006, and received on December 21, 2006, and report for the period of October - December 2006, dated April 11, 2007, and received on April 26, 2007. October - December 2006 Report stated that the SVE system is approaching asymptotic levels. Vacuum levels in four observation wells are low - 0.01 -0.04 , GWET system has low pumping rate which limits the capture zone of of the three extraction wells. Roux stated that increase in pumping rates would expand the size of the capture zone and might also improve the effectiveness of the SVE system. The site has significant VOC concentrations ranging from 2,252 ppb to 71, 110 ppb. Significant increase in concentration was observed in MW-10 from 9,010 to 71,100 of total VOC. In the previous report dated December 21, 2006, Roux recommended investigation and evaluation of the extraction wells conditions, evaluation of the feasibility of improving GWET system and optimization of the SVE system operation. However, these recommendations were not fulfilled. In the report dated April 11, 2007, Roux listed as upcoming tasks evaluation of the conditions of extraction wells, SVE and GWET systems optimization. These tasks should be performed without delay. Pumping rates and vacuum levels in remedial systems must be increased. Performance of the SVE and GWET systems should be improved and systems modified, if necessary.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

Submitted work plan for the proposed soil sampling is approved. The following e-mail was sent to DDC/ROUX/Greyhawk: I have reviewed monitoring report for the period of October - December 2006, dated April 11, 2006, for this site. Vacuum levels in four observation wells of the SVE system are very low (0.01 -0.04). GWET system has low pumping rate which limits the capture zone of the three extraction wells. Roux stated that increase in pumping rates would expand the size of the capture zone and might also improve the effectiveness of the SVE system. The site has significant VOC concentrations in groundwater (up to 71, 100 ppb of total VOC in well MW-10). Significant increase in total VOC concentrations was observed in MW-10 (from 9,010 ppb to 71,100 ppb). In the previous report dated December 21, 2006, Roux recommended investigation and evaluation of the extraction wells conditions, evaluation of the feasibility of improving GWET system and optimization of the SVE system operation. However, these recommendations were not fulfilled. In the report dated April 11, 2007, Roux listed as upcoming tasks evaluation of the conditions of extraction wells, SVE and GWET systems optimization. These tasks should be performed without delay. Pumping rates and vacuum levels in remedial systems must be increased. Performance of the SVE and GWET systems should be improved and the systems modified, if necessary. Submitted work plan for the proposed soil sampling is approved. AZ 1-22-2008 Reviewed January - September 2007 Report submitted on November 13, 2007. GWET is ineffective due to the restricted pumping rates. The SVE and GWET systems are not operating efficiently. Sheen was detected in MW-04 and MW-06 in April 2007. Soil investigation was performed in July-August 2007. The highest VOC concentrations in soil were detected in RXSB-04 75,000 ppb at 0 to 2 feet bls. RXSB-01 - 49,400 ppb of total VOC at 23-25 feet bls. MW-06 contained 9,980 ppb of total VOCs, MW-10-5,220 ppb of total VOCs. MW-02 was destroyed. Roux proposed shutting down SVE and GWET systems, implement enhanced bioremediation. Contacted Brian Morrissey. The site requires hydraulic control over migrating groundwater plume. Proposals for a new groundwater treatment system are required ASAP. Brian will get back to me with a timetable. AZ 1-23-2008 Conference call with Brian Morrissey and Andy Leddins. Bioremediation as main remediation strategy is rejected by DEC since the plume must be hydraulically controlled. I requested plume delineation along 29th street and establishing of hydraulic control over the groundwater plume. Roux will install delineation wells within next two weeks, perform high vac test and confirmation studies of DPE system within next three to four weeks. After the studies are completed a DPE system will be installed. Permo OX Plus injection will be performed along Th Street as an IRM simultaneously with constructing a DPE system. Timely quarterly should be submitted for this site. AZ 7-22-2008 Reviewed January - October 2007 through March 2008 Report submitted on April 21, 2008. The quarterly report submittal was significantly delayed. The SVE and GWET systems are not operating efficiently and high level residual soil and groundwater (up to 11,790 ppb of the total VOCs) contamination remains at the site. DEC requested installation of two additional monitoring wells to delineate offsite extent of groundwater contamination in January 2008 but the wells have yet to be installed. DEC requested and Greyhawk/Roux concurred that high vac test and confirmation studies of DPE system should be performed. The test has not been conducted and the DPE system has not been installed. The remedial progress at the site is unsatisfactory.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

Quarterly Monitoring Reports should be submitted on time. DPE system should be installed, delineation wells and needed testing performed without delay. A timetable for the above activities should be submitted to DEC within a week. An e-mail describing the above requests was sent to DDC/Greyhawk/Roux/V.B. AZ 7-3-2008 Received an e-mail from Brian Morrissey/site update: 1.The 2 offsite wells (RXMW-01 and RXMW-02) were installed and developed in late June/early July. The well casings and building corners will be mapped by a licensed surveyor on Friday, July 25th. 2.Groundwater levels in on-site and off-site monitoring wells were gauged during the week on July 14th. 3.Groundwater samples were collected during the week on July 14th. We expect to see preliminary results during the first week of August. 4. We reviewed soil data from prior CMs and further evaluated subsurface conditions (contaminant levels in clay/silt areas). 5.We conducted a 2nd round of vacuum testing and vapor sampling on July 9th. 6.ADT installed 10 injection wells in late June/early July. Well development activities were completed during the week on July 7th. 7.PermeOx Plus injections commenced on July 21st (as an interim remedial measure). 8.Soil samples were collected for laboratory analyses during installation of the monitoring wells and injection wells. Samples at intervals with elevated PID readings were also sent for petroleum identification. Upon receipt of the results of the vapor sampling and soil analyses, Greyhawk and Roux Associates will develop the plan for modifying the existing remedial systems. Due to the priority status of this site, I will contact you at that time to discuss future remedial actions and a timetable. AZ 6-16-2009 I have reviewed a Monitoring Report dated March 19-2009 for the above site for the period of April 2008 through January 2009. According to the report, URS recommended excavating the isolated area of shallow soil contamination around MW-02. Apparently, this excavation has not been performed. In 2007 VOCs were detected in soil shallow zone (0'-2') at concentrations up to 75,000 ppb. The SVE and GWET systems are not operating efficiently. Groundwater and soil contamination remains at the site. Free phase product was detected on January 12, 2008 in RXMW-06 and identified as a mixture of gasoline and No.2 fuel (diesel). One round of bioremediation injection was performed on July 21, 2008. Post-injection monitoring has not been performed. The contamination has migrated off-site in a northerly direction to the other side of 29th Street. However, VOCs were non-detect in two off-site wells (MW-13 and MW-14) installed at DEC request. Roux proposed modification of the SVE system by applying full vacuum to one or two extraction wells and using packers. This proposal is approved. On-site 1,000 gallon emergency generator diesel UST and onsite heating oil tanks should be tested without delay in order to determine a source of contamination at the site. DEC has not received results of the post-injection monitoring. These results should be submitted to DEC without delay. GWET or DPE system modification/installation plans should be submitted to DEC. Remediation recovery system (GWET or DPE) should be capable of capturing the contaminant plume and preventing off-site migration. Working groundwater recovery system should be installed at the site. Additional bioremediation injection could be used only as interim remedial measure. AZ 10-21-2010 The site was discussed at October 19, 2010, meeting with DDC/LIRO. The SVE system has not been modified and currently shut off. 1,000 gal emergency generator tank was not located by Roux. 8,000 heating oil tank should be tested. Shallow excavation should performed as it was discussed at the meeting. LiRo

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

will develop low flow multi well groundwater remedial system. Geoprobe borings will be performed prior to the excavation. I called S. Frank on October 21, 2010, to confirm investigation details. Design report will be submitted in November 2010. AZ 10-25-2010 E-mail from S. Frank/ Liro: Alex, Thanks for your call on the 72nd precinct site status following up our discussion from the quarterly meeting on October 19, 2010. Just to make sure I didn't miss anything, we discussed the following: 1 You asked that the shallow excavation work near MW-02 that Roux/NYSDEC worked out, should be implemented. I advised you that we had recommended sampling at that location to confirm that contamination is still present. 2 You asked that we implement modifications to the SVE system (i.e., packers and applying full vacuum to 1 or 2 wells) that Roux had recommended. 3 You asked about the status 1,000-gallon diesel tank for the emergency generator. I advised you that Roux reported that they could not find the tank. 4 You requested the status of tank testing for the 8,000 gallon heating oil tank. I found the tank tightness test report from August 2009 and have attached it. AZ 10-4-2010 An e-mail was sent to LiRo/V.Brevdo/F.Ashkan: Dear Steve, I have reviewed Quarterly and Site Turn-Over Status Report with the proposals dated August 3, 2010. The report provides very detailed information and comprehensive analysis of the site status. According to the report, the SVE/GWET system is down since 2008. Roux conducted packer tests and recommended SVE system modifications. Groundwater contamination appears to have migrated off-site northeast across 29th Street. Roux performed two rounds of PermeOx injection after which VOC concentrations slightly decreased in groundwater. Heavy soil contamination and relatively high dissolved groundwater contamination exist at the site. There are four USTs closed in place. Based on the above, DEC requires the following: Actual USTs information should be reconciled with the Petroleum Bulk Storage (PBS) records and changes filed with the PBS section. I suggest that the tanks closed in place should be excavated, utilities and structures permitting. SVE/GWET system should be restarted. SVE portion of the system should be modified. Modifications should be based on the Roux's pilot test results. Hot spot excavation of soil should be performed around wells IP-09 and MW-02. Investigation of the piping associated with the former gasoline UST and the trench drain system should be performed. If additional soil investigation for the purpose of excavation is needed, it should be performed without delay. Additional rounds of in-situ chemical oxidation should be discontinued pending soil excavation and restart of the remedial system. The pump test is approved and should be performed if needed. Wells MW-05 and MW-15 should be added to the monitoring program. SVOC analysis of ground water could be performed, if LiRo considers it necessary. 600 gallon waste oil UST should be located. A detailed work plan with the implementation schedule should be submitted to DEC no later than in 30 days. AZ 3-1-2011 Remedial Action Plan submitted on Dec. 1, 2010 was reviewed. The following e-mail was sent to S. Frank/ F. Ashkan/ V. Brevdo: Dear Steve, I have reviewed the Remedial Action Plan for the above site. A proposed excavation is approved. The excavation should include area around MW-07. The area of the excavation should be extended north, if feasible, to cover the contaminant plume. Tanks closed in place and associated piping should be excavated. Post excavation samples should be taken. Proposed GWET system should be modified to encompass contamination migrated across 29th Street. Contamination should be remediated on-site and off-site. SVE pilot

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

test is approved. GWET system and SVE system should be developed after the excavation is performed and a monitoring round confirms the exact boundaries of contamination. The Responsible Party and Contractors are responsible for the safe execution of the Work Plan. AZ 3-29-2011 Reviewed quarterly monitoring report dated Dec. 14, 2011. Well RXMW-05 was converted to injection but, nevertheless, sampled. Total VOC concentrations ranged from 73 ppb to 16,213 ppb. The pump test was conducted but on Sept. 2010, and indicated a limited flow capacity. Bioremediation sample results do not indicate a reduction of contaminate concentrations due to the bio-injections that were completed by Roux in July 2008 and September 2009. The results of the packer test were inconclusive. Soil contamination is present along the northern portion of the building and along 2nd St. (north side) extending 8' below the water table. MW-07 exhibit a significant increase in total VOCs. AZ 6-30-2011 Reviewed quarterly monitoring report dated March 1, 2011. Excavation in the vicinity of IP-09 and a former fill port is planned. Installation of SVE wells is scheduled. I contacted S. Frank and requested to repeat GPR test to locate closed in place tanks. GWET is being designed. The site has gross dissolved petroleum contamination (up to 18,634 ppb of total VOCs). This is the LiRo's highest priority site. AZ 10-25-2011 At the meeting with LiRo in-situ chemical oxidation (ISCO) pilot test described in a report dated October 13, 2011, was approved. An ISCO pilot plan will be prepared and submitted to DEC for review. AZ 10-25-2011 The following email was sent to S. Frank/F. Ashkan/V. Brevdo: Steve, You can request a FOIL information for sp.#0907094 and Langan's report related to this spill. The report stated that the source of the contamination at the site is 72nd Precinct. AZ 1-30-2012 Reviewed QMR and in-situ chemical oxidation pilot test work plan dated November 14, 2011. Second GPR survey was scheduled for November 2012. ISCO Pilot Test approved by DEC approved by DEC at October 25, 2011, meeting will be implemented. Two additional monitoring wells will be installed west/northwest of destroyed well MW-02. This area was previously inaccessible due to the SVE/GWET system trailer. Wells RXMW-02, RXMW-04 and RXMW-05 will be replaced. AZ 11-15-2012 Reviewed a quarterly monitoring report (October 2011-April 2012). Dissolved contaminat concentration increased significantly in two wells MW-07 (from 6518 ppb to 12,930 ppb)and MW-10 (from 1677 ppb to 4973 ppb). Discussed the site with S. Frank. 11-16-2012 An email from S. Frank: Alex, Monitoring wells for the 72nd Pct work were replaced as follows: RXMW-02, replaced by RXMW-02R RXMW-04, replaced by RXMW-04R RXMW-05, replaced by RXMW-05R The wells were replaced in Feb-March 2012. The soil results from the well installations were reported in the previous quarterly report (dated 6-18-12). Groundwater results for the replacement wells are included in the latest quarterly report. AZ 11-16-2012 An email was sent to S. Frank/V. Brevdo/F.Ashkan: Dear Steve, I have reviewed a quarterly monitoring report (October 2011- April 2012). LiRo completed the first ISCO injection on April 10, 2012. Nevertheless, dissolved contaminant concentrations increased significantly in two wells MW-07 (from 6,518 ppb to 12,930 ppb) and MW-10 (from 1,677 ppb to 4,973 ppb). It seems that ISCO injections are not effective enough to treat existing offsite contamination. LiRo could proceed with the remaining ISCO injections. However, alternative plans for treatment of the offsite contamination should be developed and submitted to DEC. Sincerely, Alexander Zhitomirsky 4-3-2013 Reviewed a quarterly monitoring report dated 11-13-2013. Post injection groundwater

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

sampling indicates a reduction in total VOC concentrations in wells with the dissolved contaminant plume. Also, some total VOC spikes in post injection samples were recorded. The following e-mail was sent to S. Frank/V. brevdo/ F. Ashkan: Dear Steve, I have reviewed and discussed over the phone with you the above site. LiRo proposed to expand ISCO Pilot Test Program to the precinct side of 29th Street. This proposal is approved. If this remedial strategy is not effective, an alternative remedial strategy should be implemented. The Responsible Party and Contractors are responsible for the safe execution of the Work Plan. Sincerely, Alex Zhitomirsky 10-9-2013

Reviewed Quarterly Monitoring Report dated March 4, 2013. LiRo will perform additional injections following re-evaluation of the calculated quantities of hydrogen peroxide and catalyst. On January 3, 2013, in a Progress Summary Meeting, DEC agreed with LiRo's recommendation to complete an ISCO Pilot Test Program on the precinct side of 29th Street. AZ 10-18-2013 Reviewed Quarterly Monitoring Report dated June 4, 2013. A Work Plan for ISCO injection is included in the report. Additional injections offsite (east side of 29th Street) were previously approved by DEC. An ISCO injection bid package has been approved by the City and is pending available NYCDDC funding. AZ 5-20-2014 Reviewed Quarterly Monitoring Report dated October 9, 2013. Additional injections offsite (east side of 29th Street) were previously approved by DEC. An ISCO injection bid package has been approved by the City and is tentatively scheduled. Potential off-site sources include the property of 149 29th Street and 822 4th Avenue, both located directly across (east) of the 72nd Precinct. The total VOC concentrations on site ranged from 7 ppb to 18,056 ppb. The total off-site VOC concentrations in off-site wells ranged from 302 ppb to 18,596 ppb. AZ 11-18-2014 Reviewed Quarterly Monitoring Report dated March 7, 2014 (Sept. 2013- January 2014). Additional injections offsite (east side of 29th Street) were previously approved by DEC. An ISCO injection bid package has been approved by the City. Potential off-site sources include the property of 149 29th Street and 822 4th Avenue, both located directly across (east) of the 72nd Precinct. In December 2013, LiRo collected soil and GW samples and sent them to FMC, as part of the treatability study (Klosur). The total VOC concentrations on site ranged from 11 ppb to 11,056 ppb. The total off-site VOC concentrations in off-site wells ranged from 19 ppb to 12,460 ppb. Free phase product was reported in injection well LIP-02 in January 2014. According to LiRo, there is a possibility that this free phase product could be attributed to the business located at LIP-02 (Address 149 29th Street. It belongs to active beverage distributor with constant truck traffic and trucks parked on sidewalk). AZ 12-24-2014 The following email was sent to S. Frank and V. Brevdo: Dear Steve, I have reviewed a Quarterly Monitoring Report and Klosur Injection Work Plan for the above site, received on October 6, 2014. The Work Plan proposed injection of Klosur Persulfate. This Work Plan is approved. The Responsible Party and its contractors are solely responsible for the safe execution of all invasive work performed at the site, and in particular, are responsible for identifying subsurface utilities and safeguarding the structural integrity of any excavations, buildings, utilities, and other structures both on and off site that may be adversely affected by the work. The Responsible Party and its contractors must obtain any local, state or federal permits or approvals that may be required to perform the work necessary to address this spill. Furthermore, the Responsible Party and its

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

contractors are solely responsible for the implementation of all appropriate health and safety measures during the performance of this work. Alex Zhitomirsky - Engineering Geologist 2 2-26-2015 Reviewed a monitoring report dated 7/23/2014. The report stated that there is a possibility that an off-site source is present on the east side of 29th Street. LiRo has opened discussions with the 149 29th Street property owner (beverage center) and will attempt to reach an access agreement to complete an investigation within the building in the areas where previous investigation had identified petroleum impacts and a possible tank anomaly. AZ 5-05-2015 Reviewed a monitoring report dated 02/25/2015. The report stated that off-site investigation consisting of the advancement of two soil borings/wells within the 149 29th Street building is on hold due to access restrictions. The Kloxur Persulfate Injection Work Plan was approved by NYSDEC, however, implementation is delayed due to NYC DDC budget issues. Five ISCO have been completed. Some total VOC concentrations reported increases. AZ 1-06-2016 Reviewed a monitoring report dated 05/28/2015. The report stated that off-site investigation consisting of the advancement of two soil borings/wells within the 149 29th Street building is on hold due to access restrictions. The Legal representative of this property was contacted in the first quarter of 2015 and stated, he had not reviewed the Investigation Work Plan to date. The Kloxur Persulfate Injection first round was completed in April 2015. Five ISCO have been completed. Some total VOC concentrations reported increases. AZ 5-05-2016 Reviewed a monitoring report dated 09/16/2015. The report stated that off-site investigation consisting of the advancement of two soil borings/wells within the 149 29th Street building is on hold due to access restrictions. The Legal representative of this property was contacted in the first quarter of 2015 and stated, he had not reviewed the Investigation Work Plan to date. The Kloxur Persulfate Injection first round was completed in April 2015. Four rounds of ISCO are anticipated. Some total VOC concentrations in groundwater reported significant increases. Total VOCs concentrations in groundwater were up to 12,000 ppb. Perdufate liberated/broke down the VOC sorbed onto the soil particles AZ 4-19-2017 Reviewed a monitoring report dated 09/29/2016. Off-site investigation consisting of the advancement of two soil borings/wells within the 149 29th Street building is on hold due to access restrictions. In June 2016, the 149 29th Street property owner signed an access agreement. LiRo is scheduling a limited boring program. Additional off-site injections utilizing Kloxur Persulfate may be initiated following completion of the on-site treatment regime. In May 2016, damaged injection well LIP-05 was replaced. Total VOCs concentrations in groundwater were up to 4,100 ppb. AZ 6-6-2017 Reviewed a monitoring report dated 12/20/2016. On-site Post injection groundwater sampling results (August 2016) indicated the highest VOC concentrations in MW--06R2 (14,074 ppb). Off-site investigation consisting of the advancement of two soil borings/wells within the 149 29th Street building is on hold due to access restrictions. In June 2016, the 149 29th Street property owner signed an access agreement. LiRo is scheduling a limited boring program. Additional off-site injections utilizing Kloxur Persulfate may be initiated following completion of the on-site treatment regime. AZ 9-13-2017 I have reviewed a report dated 3-01-2017. In 2016 soil borings were advanced onsite. The soil sampling results were compared with the previous results. In seven borings VOC concentrations in soil decreased. In four borings VOC concentrations

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

increased up to 1,409,500 ppb. One soil boring was advanced off-site. Six soil samples were analyzed, none reported any VOCs exceedances. Groundwater samples reported no VOCs exceedances. LiRo will determine, based on the soil and groundwater data, the need for additional injections. AZ 12-8-2017 I have reviewed a report dated 6-09-2017. In October 2016 the fourth Klossur injection round was completed. Post-injection groundwater monitoring was completed on October 31, 2016. Soil sampling was performed in February 2017 - March 2017. 23 samples reported one or more VOCs at concentrations above CP-51 SCLs. Total VOCs concentrations ranged from 819 ppb to 1,334,300 ppb. Off-site investigation was performed in October 2016. A total of six samples analyzed, none reported any VOC exceedances. Two off-site groundwater samples were collected. VOCs and SVOCs concentrations were reported at 0.48-2 ppb. No petroleum contamination was identified in the soil and groundwater at the off-site property. AZ 2-15-2018 I have reviewed a report dated 8-22-2017. LiRo identified a possible UST (status unknown) at the off-site property, however, no petroleum contamination was identified in the soil and groundwater. PeroxyChem has revised the injection amounts and injection zones. A revised USEPA injection program was submitted on July 3, 2017. The highest total VOC concentration was 5,151 ppb in well MW-06R2. AZ 6-11-2018 Reviewed a report dated March 1, 2018, The following e-mail was sent to S. Frank and V. Brevdo: Dear Steve, I have reviewed a Work Plan for the above site. The plan proposed ISCO injections with Klossur in the sidewalk area of the 149 29th Street property. This proposal is approved. The Responsible Party and its contractors are solely responsible for the safe execution of all invasive work performed at the site, and in particular, are responsible for identifying subsurface utilities and safeguarding the structural integrity of any excavations, buildings, utilities, and other structures both on- and off-site that may be adversely affected by the work. The Responsible Party and its contractors must obtain any local, state or federal permits or approvals that may be required to perform the work necessary to address this spill. Furthermore, the Responsible Party and its contractors are solely responsible for the implementation of all appropriate health and safety measures during the performance of this work. Sincerely, Alex Zhitomirsky - Engineering Geologist 2 NYS Department of Environmental Conservation 47-40 21st Street, Long Island City, NY 11101 Phone: 718.482.6387 - Fax: 718.482.6390 Email: alexander.zhitomirsky@dec.ny.gov 10-22-2018 I have reviewed a report dated 11-3-2017. In September 2017, a fifth injection was completed. The highest total VOC concentration was 3,049 ppb in well BW-01R ON 8/21/2017. AZ 1-07-2018 I have reviewed a report dated 6-11-2018. In December 2017, seven soil borings were advanced in the sidewalk area in front of the 149 29th Street property. Petroleum-related impacts were identified in several soil borings. The highest groundwater total VOC concentrations were encountered in well BW-01R on 8/21/2017 (3,049 ppb). AZ 5-13-2019 I have reviewed a report dated 9-24-2018. The highest groundwater total VOC concentrations were encountered in well MW-06R2 located on sidewalk on 5/11/2018 (8,668 ppb). Injections were scheduled for off-site part of the plume. Because of the concrete work further injection on-site are suspended. The on-site area will phase into monitored natural attenuation. AZ 8-21-2019 I have reviewed a report dated 1-08-2019. The highest groundwater total VOC concentrations were encountered in well MW-06R2 located on the sidewalk sampled on 5/11/2018 (7,251

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

ppb). Another round of post-injection soil borings were advanced on-site in August 2018. Isolated pockets of soil contamination exist on-site in both Area 1 and Area 2. The first round of the off-site injections were completed in August 2018. The injections consisted of the injection of Klorur Persulfate and an activator (solution sodium hydroxide) into existing wells LIP2-LIP-09. The second stage of the injections was completed in October 2018 and post-injection samples were collected. AZ "

Remarks: "tank abandonment done there - while geo-probing found product believes it is the piping"

All Materials:

Site ID: 75551
Operable Unit ID: 1030540
Operable Unit: 01
Material ID: 2096801
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Site ID: 75551
Operable Unit ID: 1030540
Operable Unit: 01
Material ID: 355991
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: 75 PRECINCT NYPD -DDC
Address: 830 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9514695 / 1999-05-04
Facility ID: 9514695
Facility Type: ER
DER Facility ID: 70709
Site ID: 129870
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1995-01-14
Investigator: JAKOLLEE
Referred To: Not reported
Reported to Dept: 1996-02-16
CID: 311
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1996-02-16
Spill Record Last Update: 2005-07-07
Spiller Name: ANTHONY MARINO
Spiller Company: DEPT OF GENERAL SERVICES
Spiller Address: MUNICIPAL BLDG-15TH FLOOR
Spiller Company: 001
Contact Name: ANTHONY MARINO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY URS DID SITE INVESTIGATION; CONTAMINATION FOUND IN ONE WELL, WELL LATER DESTROYED DURING INSTALLATION OF NEW TANKS. REPLACEMENT WELL INSTALLED A FEW FEET AWAY. GROUNDWATER SAMPLING IN OCTOBER 1998 AND MARCH 1999 FOUND NO PETROLEUM-RELATED COMPOUNDS. JK APPROVED NO FURTHER ACTION MAY 4, 1999."

Remarks: "called by above agency stating they found contamination in ground water after doing a soil test at above site."

All Materials:

Site ID: 129870
Operable Unit ID: 1025807
Operable Unit: 01
Material ID: 354822
Material Code: 9999
Material Name: other -
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: 72 PRECINCT NYPD -DDC
Address: 830 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9604636 / 2003-10-31
Facility ID: 9604636
Facility Type: ER
DER Facility ID: 70709
Site ID: 317854
DEC Region: 2
Spill Cause: Abandoned Drums
Spill Class: B3
SWIS: 2401
Spill Date: 1996-07-03
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 1996-07-09
CID: 311
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: DEC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1996-07-09
Spill Record Last Update: 2004-12-22
Spiller Name: SAME
Spiller Company: NYC POLICE DEPT
Spiller Address: 830 4TH AVE
Spiller Company: 001
Contact Name: SGT TOM ZAPATA
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
KRIMGOLD "
Remarks: "4- 55 gallons drums leaking on the westside of the building outside
product is unk. Same site as spill # 9502759. "

All Materials:

Site ID: 317854
Operable Unit ID: 1032287
Operable Unit: 01
Material ID: 347388
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: 72 POLICE STATION
Address: 830 4TH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1407672 / 2016-09-16
Facility ID: 1407672
Facility Type: ER
DER Facility ID: 456197
Site ID: 501200
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2014-10-24
Investigator: ADZHITOM
Referred To: Not reported
Reported to Dept: 2014-10-24
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

Remediation Phase: 0
Date Entered In Computer: 2014-10-24
Spill Record Last Update: 2016-09-19
Spiller Name: STEVEN FRANK
Spiller Company: UNKNOWN
Spiller Address: 830 4TH AVE
Spiller Company: 999
Contact Name: STEVEN FRANK
DEC Memo: "10-24-2014 email from S. Frank: Dear Alex, We discovered material that has been identified as transmission fluid in well BW-1 at the 72nd Precinct site. The well location is shown on the attached site plan. The well is in the middle of the driveway area and there is no transmission fluid storage in this portion of the site so we suspect the fluid may have been introduced from the surface rather than migrating through the ground. We have a Vac Truck scheduled to evacuate the product next Wednesday. Let me know if you would like us to report a new spill for this finding. Sincerely, Steve Frank
5-4-2015 Reviewed a report dated 2/26/2015. EFR via vacuum truck was performed at BW-01 on October 2014 and the product thickness was 0.34' in BW-01. On November 6 2014, the product thickness was 0.02'. Approximately 8-gallons of oil groundwater mixture was removed from the well. On December 4 and December 19, 2014, no free phase was recorded. I called S. Frank and requested that more monitoring events needed in order to determine if all free phase product was removed from the well. AZ 1-6-2016 Reviewed a report dated 5/28/2015. No free-phase product was measured in BW-01 since November 2014. The free-phase product was identified as transmission fluid. AZ 9-16-2016 Reviewed a report dated 3/10/2016. Spill Number 1407672 was reported as a result of free-phase product in well BW-01 which was identified as transmission fluid. LiRo performed fluid removal and has continued to monitor this well. No free-phase product was measured in BW-01 since November 2014. Based upon the monitoring data LiRo requested closure of Spill Number 1407672. I concur with this proposal. The following letter email was sent to S. frank and V. Brevdo on 9-19-16: Dear Steve, I have reviewed a Spill Closure Report dated March 3, 2016. The report stated that that spill #1407672 was reported as a result of discovery of free-phase product in well BW-01 which was identified as transmission oil. LiRo performed product removal and has continued to monitor this well. No free-phase product has been reported in well BW-01 since November 2014. Based upon this monitoring data, LiRo requested closure of this spill. This request is approved and the spill is closed. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or remedial action the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was unknown at the time of this closure. II. Environmental conditions related to this spill case which were unknown to the Department at the time of this closure. III. Information received, in whole or part, after the Department's spill case closure, which indicates that corrective action was not sufficiently protective of human health and/or the environment. IV. Fraud in obtaining this spill case closure determination. As a precaution, we must bring your attention to our concerns for the future use of this site. If subsurface contamination is encountered while excavating for any construction activity, appropriate remedial and vapor mitigation efforts may need to be taken to fully prevent vapor intrusion into any site development and to ensure human health and safety. This

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

72 PRECINCT NYPD -DDC (Continued)

S102233280

spill closure does not exempt the Responsible Parties from compliance with any applicable laws and regulations. Please be advised that you should maintain a permanent file of all documentation and correspondence regarding this case for future use as the Department's files may not be maintained indefinitely. Sincerely, Alex Zhitomirsky
- Engineering Geologist 2 NYS Department of Environmental Conservation 47-40 21st Street, Long Island City, NY 11101 Phone: 718.482.6387 - Fax: 718.482.6390 Email: alexander.zhitomirsky@dec.ny.gov"

Remarks: "caller reporting that spill is caused by a unknown leak possibly from a vehicle. clean up is pending"

All Materials:

Site ID: 501200
Operable Unit ID: 1250601
Operable Unit: 01
Material ID: 2252372
Material Code: 0021
Material Name: transmission fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

AR225
East
1/4-1/2
0.467 mi.
2466 ft.

GTO HOLDING CORP
550 FIFTH AVENUE
BROOKLYN, NY 11215

NY LTANKS S103941215
N/A

Site 2 of 2 in cluster AR

Relative:
Higher
Actual:
80 ft.

LTANKS:

Name: GTO HOLDING CORP
Address: 550 FIFTH AVENUE
City,State,Zip: BROOKLYN, NY 11215
Spill Number/Closed Date: 9902100 / 2009-09-04
Facility ID: 9902100
Site ID: 60272
Spill Date: 1999-05-24
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: VSZHUNE
Referred To: Not reported
Reported to Dept: 1999-05-24
CID: 281
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-05-24

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GTO HOLDING CORP (Continued)

S103941215

Spill Record Last Update: 2009-09-04
Spiller Name: FRED SCHAFER
Spiller Company: GTO HOLDING CORP
Spiller Address: 2655 MAIN ST SUITE #240
Spiller County: 001
Spiller Contact: STEVE BRAUN
Spiller Phone: (718) 444-3400
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 25907
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 5/18/04 - AUSTIN - TRANSFERRED FROM TOMASELLO FOR REASSIGNMENT - END 09/13/06 This case was transferred from Albany to Region 2. Zhune tried to speak to Mr. Steve Braun. He was in the field. A TTF letter was sent to: Mr. Steve Braun 2125 Mill Ave Brooklyn, NY 11234 09/15/06 Steve called back. He asked me to send letter to Mr. George Smith. A TTF letter was sent to: Mr. George Smith 5205 Estates Drive Delray Beach FL 33445 08/28/08-Zhune spoke to Steve Braun from Aproved Oil. He said the owner sold the building and move to Florida. He never did any work. 10/21/2008- Zhune spoke sent a TTF to Fred Roerden, Property Owner from Endraws Building Corp. (212)529-5688 01/06/09- DEC received a letter from Fred Roerden. The letter is dated 12/31/2008 stated the fallwing: In response to your letter dated October 9, 2008, regarding the above captioned matter, I must inform you that two main points of information have changed since the original complaint on May 5,1999. First, Building in question has changed ownership and is now owned as a condominium by individual owners. GTO Holdings is longewr involved with this site. Second, the offending fuel oil tank is no longer in use at this site and in fact, has been removed from the building. I do not have dates and records to provide, but the GTO Holdings Corp. romoved the tank prior to selling the building and changing the ownership into a condominium. All heating is now done by individually meterded gas supply. "
Remarks: "TANK TEST FAILURE AT ABOVE LOCATION. TANK TO BE CLOSED DOWN. NO CALL BACK REQUESTED."

All TTF:

Facility ID: 9902100
Spill Number: 9902100
Spill Tank Test: 1547197
Site ID: 60272
Tank Number: Not reported
Tank Size: 1500
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 60272

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GTO HOLDING CORP (Continued)

S103941215

Operable Unit ID: 1076876
Operable Unit: 01
Material ID: 305614
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AU226 CITY OF NY PARKS DEPT TTF
NNW 155 BAY SY
1/4-1/2 BROOKLYN, NY
0.470 mi.
2480 ft. Site 1 of 2 in cluster AU

NY LTANKS S111836533
N/A

Relative:
Higher
Actual:
16 ft.

LTANKS:

Name: CITY OF NY PARKS DEPT TTF
Address: 155 BAY SY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1201097 / 2015-02-04
Facility ID: 1201097
Site ID: 463765
Spill Date: 2012-05-03
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: adzhitom
Referred To: NFA
Reported to Dept: 2012-05-03
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2012-05-03
Spill Record Last Update: 2015-02-04
Spiller Name: BILL KLEIN
Spiller Company: CITY OF NY PARKS DEPT/ REDHOOK REC CTR
Spiller Address: 155 BAY SY
Spiller County: 999
Spiller Contact: BILL KLEIN
Spiller Phone: 718762-5200
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 418160
DEC Memo: "4-1-2014 Reviewed SSIP plan dated 10-25-2013. An e-mail was sent to S. Frank/V. Brevdo: Dear Steve, I am reviewing a Site Specific Investigation Plan for this site. The plan proposed installation of three wells and two soil borings. However, the plan did not address

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CITY OF NY PARKS DEPT TTF (Continued)

S111836533

the tank piping and fill port. Generally borings/wells are installed along the piping and near fill ports. Please clarify this issue. Sincerely, Alexander Zhitomirsky 4-2-2014 E-mail from S. Frank: Alex, We will modify the boring location plan, moving points closer to the fill port and closer to the piping that goes to the building. Inside the building, the pipe is above ground in the basement, so we will add a detail to the drawing noting that the pipe is above ground. On another matter, we mailed a report pre-maturely for 123rd Pct. The pre-mature report should arrive at your office today or tomorrow. Please dispose of the report and we will re-transmit after all of our internal reviews are complete. Thanks Steve 4-4-2014 e-mail from S. Frank: Dear Alex, I have attached a revise boring location plan for you review. We moved LMW-01 closer to the piping run and vent line between the tank and building, moved LMW-03 closer to the fill port and added a boring LSB-03 along the piping between the fill port and the tank. Please note that this is a relatively small site and that LMW-03 and LSB-03 are within 10 feet of each other. Also note that the pipe run within the building is above ground in the basement level of the building. Please let me know if you would like us to re-submit the SSIP with the updated plan. Sincerely, Steve Frank 4-7-2014 The following e-mail was sent to S. Frank/V. Brevdo: Dear Steve, I have reviewed a revised boring location plan dated April 4, 2014. I concur with this plan. The Responsible Party and Contractors are responsible for the safe execution of the Work Plan. Sincerely, Alexander Zhitomirsky 2-4-2015 An e-mail was sent to S. Frank and V. Brevdo: Dear Steve, I have reviewed an Investigation Summary and Remedial Plan and Spill Closure Request dated 10/10/2015. Several tank test failures were recorded at this location. The report stated that three monitoring wells and three soil borings were completed to investigate the site. No VOCs were reported above the laboratory limit. SVOC were reported at concentrations exceeding CP-51 SCLs in six samples. Total SVOC concentrations in six samples ranged from 16,661 to 55,140 ppb. The SVOC constituents were attributed to urban fill. Groundwater samples were collected. MTBE was reported in well LMW-02 at 230 ppb in June 2014 and at 52 ppb in August 2014. According to the consultant, this impact is not likely related to the 7,500-gallon #2 fuel oil UST. Based upon results of the sampling, LiRo recommended closure of spills 1201097 and 0600249. I concur with this request. All wells should be checked for the presence of free phase product prior to decommissioning. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or remedial action the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was unknown at the time of this closure. II. Environmental conditions related to this spill case which were unknown to the Department at the time of this closure. III. Information received, in whole or part, after the Department's spill case closure, which indicates that corrective action was not sufficiently protective of human health and/or the environment. IV. Fraud in obtaining this spill case closure determination. As a precaution, we must bring your attention to our concerns for the future use of this site. If subsurface contamination is encountered while excavating for any construction activity, appropriate remedial and vapor mitigation efforts may need to be taken to fully prevent vapor intrusion into any site development and to ensure human health and safety. This spill closure does not exempt the Responsible Parties from compliance with any applicable laws and regulations.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CITY OF NY PARKS DEPT TTF (Continued)

S111836533

Please be advised that you should maintain a permanent file of all documentation and correspondence regarding this case for future use as the Department's files may not be maintained indefinitely. Also, according to the report, 7,500-gallon tank, which previously failed tank tightness test on several occasions, is scheduled for removal. End point samples should be taken when the tank removal is completed. If contamination is encountered NYSDEC should be notified, and a spill should be called in. Sincerely, Alex Zhitomirsky - Engineering Geologist 2 NYS Department of Environmental Conservation 47-40 21st Street, Long Island City, NY 11101 Phone: 718.482.6387 - Fax: 718.482.6390 Email: alexander.zhitomirsky@dec.ny.gov "

Remarks: "tank top leak, failed a couple of tests"

All Materials:

Site ID: 463765
Operable Unit ID: 1213858
Operable Unit: 01
Material ID: 2211869
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

AU227 RED HOOK PARK
NNW 155 BAY STREET
1/4-1/2 BROOKLYN, NY 11231
0.470 mi.
2480 ft. Site 2 of 2 in cluster AU

SEMS 1019328386
NYN000202712

Relative:
Higher
Actual:
16 ft.

SEMS:

Site ID: 0202712
EPA ID: NYN000202712
Name: RED HOOK PARK
Address: 155 BAY STREET
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11231
Cong District: 07
FIPS Code: 36047
Latitude: Not reported
Longitude: Not reported
FF: N
NPL: Not on the NPL
Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AS228
NNE
1/4-1/2
0.471 mi.
2487 ft.

US POSTAL SERVICE - VEH MAINT FAC
138 2ND AVE
BROOKLYN, NY 11215
Site 2 of 4 in cluster AS

RCRA-VSQG
NY LTANKS
NJ MANIFEST
NY MANIFEST

1000349038
NYD981871759

Relative:
Higher

Actual:
13 ft.

RCRA-VSQG:

Date form received by agency: 2007-01-01 00:00:00.0

Facility name: US POSTAL SERVICE - VEH MAINT FAC

Facility address: 138 2ND AVE

BROOKLYN, NY 11215-3812

EPA ID: NYD981871759

Mailing address: 2ND AVE

BROOKLYN, NY 11215

Contact: Not reported

Contact address: 2ND AVE

BROOKLYN, NY 11215

Contact country: US

Contact telephone: Not reported

Contact email: Not reported

EPA Region: 02

Land type: Facility is not located on Indian land. Additional information is not known.

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: US POSTAL SERVICE

Owner/operator address: NOT REQUIRED

NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: 212-555-1212

Owner/operator email: Not reported

Owner/operator fax: Not reported

Owner/operator extension: Not reported

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: US POSTAL SERVICE

Owner/operator address: NOT REQUIRED

NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: 212-555-1212

Owner/operator email: Not reported

Owner/operator fax: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE - VEH MAINT FAC (Continued)

1000349038

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: US POSTAL SERVICE - VEH MAINT FAC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 2003-07-30 00:00:00.0
Site name: US POSTAL SERVICE - VEH MAINT FAC
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: US POSTAL SERVICE - VEH MAINT FAC
Classification: Not a generator, verified

Date form received by agency: 1986-12-12 00:00:00.0
Site name: US POSTAL SERVICE - VEH MAINT FAC
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

LTANKS:

Name: 138 2ND AVENUE
Address: 138 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9201414 / 1992-05-20
Facility ID: 9201414

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE - VEH MAINT FAC (Continued)

1000349038

Site ID: 294178
Spill Date: 1992-05-05
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: C3
Cleanup Ceased: 1992-05-20
SWIS: 2401
Investigator: O'DOWD
Referred To: Not reported
Reported to Dept: 1992-05-05
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1992-05-06
Spill Record Last Update: 2002-11-26
Spiller Name: Not reported
Spiller Company: EMPIRE STATE FUEL
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 238068
DEC Memo: ""
Remarks: "SPILL CONTAINED ON ROOF; A.L EASTMOND CLEANED UP."

All Materials:

Site ID: 294178
Operable Unit ID: 968750
Operable Unit: 01
Material ID: 412728
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 200.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: US POSTAL SERVICE
Address: 138 2ND AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9111199 / 1992-01-31
Facility ID: 9111199
Site ID: 202256
Spill Date: 1992-01-29
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: C3
Cleanup Ceased: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE - VEH MAINT FAC (Continued)

1000349038

SWIS: 2401
Investigator: SJMILLER
Referred To: Not reported
Reported to Dept: 1992-01-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1992-02-07
Spill Record Last Update: 2002-12-23
Spiller Name: Not reported
Spiller Company: EMPIRE STATE FUEL
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 238068
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER 1/31/92, 0937HRS, MILLER INSPECTED CLEANUP AND CONFIRMED COMPLETE; NO DRAIN IMPACTS BUT ROOFING MATERIAL IS DAMAGED."
Remarks: "SPILL CONTAINED ON ROOF. AL EASTMOND CLKEANING."

All Materials:

Site ID: 202256
Operable Unit ID: 964928
Operable Unit: 01
Material ID: 416251
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 200.00
Units: G
Recovered: 200.00
Oxygenate: Not reported

NJ MANIFEST:

EPA Id: NYD981871759
Mail Address: 138 2ND AVE
Mail City/State/Zip: BROOKLYN 11215
Facility Phone: 7188345562
Emergency Phone: Not reported
Contact: Not reported
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE - VEH MAINT FAC (Continued)

1000349038

TSD Flag: Not reported
Name Change: Not reported
Date Change: Not reported
Manifest:
Manifest Number: NJA5086818
EPA ID: NYD981871759
Date Shipped: 05/07/2004
TSD EPA ID: NJD991291105
Transporter EPA ID: NJR000016279
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 05/07/2004
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSD Received Waste: 05/14/2004
TSD EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 05260425
Was Load Rejected: BROOKLYN 11215
Reason Load Was Rejected: Not reported

Manifest Number: NJA5086789
EPA ID: NYD981871759
Date Shipped: 01/21/2004
TSD EPA ID: NJD991291105
Transporter EPA ID: NJR000016279
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE - VEH MAINT FAC (Continued)

1000349038

Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/21/2004
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 01/27/2004
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 03090425
Was Load Rejected: BROOKLYN 11215
Reason Load Was Rejected: Not reported

Manifest Number: NJA5217591
EPA ID: NYD981871759
Date Shipped: 04/07/2005
TSDf EPA ID: NJD991291105
Transporter EPA ID: NJR000050617
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 04/07/2005
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 04/15/2005
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE - VEH MAINT FAC (Continued)

1000349038

Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 05270522
Was Load Rejected: BROOKLYN 11215
Reason Load Was Rejected: Not reported

NY MANIFEST:

Name: US POSTAL SERVICE GARAGE
Address: 138 2ND AVE
City,State,Zip: BROOKLYN, NY 11215-3812
Country: USA
EPA ID: NYD981871759
Facility Status: Not reported
Location Address 1: 138 2ND AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD981871759
Mailing Name: US POSTAL SERVICE GARAGE
Mailing Contact: MICHAEL SUAREZ
Mailing Address 1: 1050 FORBELL ST
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11256
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7183483375

NY MANIFEST:

Document ID: NJA5217591
Manifest Status: Not reported
seq: Not reported
Year: 2005
Trans1 State ID: NJR000050617
Trans2 State ID: Not reported
Generator Ship Date: 04/07/2005
Trans1 Recv Date: 04/07/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/15/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE - VEH MAINT FAC (Continued)

1000349038

Generator EPA ID: NYD981871759
Trans1 EPA ID: 50178
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

AS229 **BROOKLYN NORTH 2**
NNE **11 2ND AVE**
1/4-1/2 **BROOKLYN, NY**
0.472 mi.
2493 ft. **Site 3 of 4 in cluster AS**

NY LTANKS **S104650590**
NY Spills **N/A**

Relative:
Higher

LTANKS:

Actual:
14 ft.

Name: 11TH ST. & 2ND AVE.
Address: 11TH ST/2ND AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9214380 / 2003-09-01
Facility ID: 9214380
Site ID: 296990
Spill Date: 1993-03-30
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: ALKARWIE
Referred To: Not reported
Reported to Dept: 1992-03-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN NORTH 2 (Continued)

S104650590

Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1993-04-01
Spill Record Last Update: 2003-11-17
Spiller Name: Not reported
Spiller Company: US POST OFFICE
Spiller Address: 11TH ST.& 2ND AVE.
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 240324
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks:

KARWIEL 9/1/03 - AUSTIN - THIS SPILL IS BEING CLOSED IN THE DATABASE, BASED UPON THE REFERENCES PROVIDED BELOW BY ANTHONY KARWIEL OF THE DER/CENTRAL OFFICE. MR KARWIEL INDICATED THAT THESE DOCUMENTS SUPPORT THE CLOSURE OF THIS SPILL REPORT AND SPILL # 9704147. THE DOCUMENTS THAT SUPPORT CLOSURE OF THIS PROJECT ARE AS FOLLOWS: - DETACHED MAIL UNIT (DMU) SUBSURFACE INVESTIGATION RESULTS AND RECOMMENDATIONS (11/27/02) PREPARED BT ROUX ASSOCIATES; - DMU SUBSURFACE REMEDIATION RESULTS AND EVALUATION (2/24/03) PREPARED BY ROUX ASSOCIATES; - FINAL COMPLETION REPORT (3/18/03) PREPARED BY ROUX ASSOCIATES; - OPERATIONS, MAINTENANCE AND MONITORING PLAN (REVISED 8/13/03) - DECLARATION OF RESTRICTIONS (EXECUTED 7/1/03) FIRST AMENDMENT TO DECLARATION OF RESTRICTIONS (EXECUTED 7/31/03) DOCUMENTS ARE ON FILE WITH DEPARTMENT, SUBJECT TO ARCHIVING RULES - END "

"PULLING TANKS, DISCOVERED CONTAMINATED SOIL & HOLES IN TANK. STOCK-PILING SOIL, WILL SAMPLE & TEST & DISPOSE. TANKS WERE CLEANED BEFORE PULLING. WILL HOLD TANKS ON SIGHT UNTIL TOMORROW FOR DEC INSPEC SITE BEING HANDLED BY HAZ. WASTE SECTION."

All Materials:

Site ID: 296990
Operable Unit ID: 981659
Operable Unit: 01
Material ID: 400595
Material Code: 0013
Material Name: lube oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: BROOKLYN NORTH 2
Address: 11 2ND AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0000664 / 2010-11-09
Facility ID: 0000664
Facility Type: ER
DER Facility ID: 236315
Site ID: 291873

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN NORTH 2 (Continued)

S104650590

DEC Region: 2
Spill Cause: Unknown
Spill Class: B3
SWIS: 2401
Spill Date: 2000-04-17
Investigator: ADZHITOM
Referred To: Not reported
Reported to Dept: 2000-04-17
CID: 205
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-04-17
Spill Record Last Update: 2010-11-09
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY 4/10/03 transferred from tipple to Zhitomirsky, ddc project 10/06/05 Dual phase system is operating at the site. AZ 8-1-2007 Reviewed Monitoring Report for October 2006-March 2007 dated May 24, 2007. The report stated that the previous round of gw sampling conducted by LiRo on November 16, 2005, indicated that VOC soil contamination was successfully remediated and that SVOC soil contamination was removed to the residual levels. The residual low-level VOCs and SVOC remaining in MW-20 (less than 200 ppb) can likely be attributed to an offsite source as this well is located in the extreme southern corner of the site and is side-gradient. Free phase was detected only in MW-19 (separate phase of transmission oil). The source of transmission oil is most likely from the current tenant(a private bus company).The product first appeared after the bus company commenced operations at the site. At the meeting with Greyhawk on May 30, 2007, DEC requested from DDC a memo summarizing site activities and information obtained on the new contaminant (transmission fluid). AZ 11-9-2010 Based on the LiRo report and investigation it was concluded that NYCDDC successfully remediated this spill. However, there is a new spill at the same property which will be remediated by another responsible party (spill#0601840). After consultation with J. Urda spill #0000664 is closed and further remediation will be tracked under spill#0601840. the following e-mail was sent to V.Brevdo, J. Urda, Fatemeh Ashkan and S. Frank: Dear Steve, Based on the LiRo report dated May 2007 and DEC's investigation, it was concluded that NYCDDC successfully remediated spill #0000664. However, there is another spill (spill#0601840) associated with the same property which will be remediated by another responsible party. After consultation with J. Urda, spill #0000664 is closed and further remediation will be tracked under spill#0601840. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROOKLYN NORTH 2 (Continued)

S104650590

remedial action the Department deems necessary due to: I.The off-site migration of petroleum contaminants that was not addressed by this evaluation. II. Environmental conditions related to the Site which were unknown to the Department at the time of this approval. III.Information received, in whole or part, after the Department s approval for inactivation, which indicates that inactivation decision and/or corrective action is not sufficiently protective of human health for the reasonably anticipated use of the site. IV.Fraud in obtaining this approval for inactivation. Please be advised that you should maintain a permanent file of all documentation and correspondence regarding this case for future use. The Department s files regarding this release may not be maintained indefinitely. AZ "caller doing site work found contaminated soil."

Remarks:

All Materials:

Site ID: 291873
Operable Unit ID: 822394
Operable Unit: 01
Material ID: 288905
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

230
ENE
1/4-1/2
0.479 mi.
2528 ft.

244A 13TH STREET
244A 13TH STREET
BROOKLYN, NY

NY LTANKS S102672019
N/A

Relative:
Higher
Actual:
64 ft.

LTANKS:
Name: 244A 13TH STREET
Address: 244A 13TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9210439 / 1992-12-10
Facility ID: 9210439
Site ID: 131864
Spill Date: 1992-12-09
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: 1992-12-10
SWIS: 2401
Investigator: CAMMISA
Referred To: Not reported
Reported to Dept: 1992-12-10
CID: Not reported
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

244A 13TH STREET (Continued)

S102672019

Remediation Phase: 0
Date Entered In Computer: 1992-12-15
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 113611
DEC Memo: ""
Remarks: "OIL LEAKED FROM VENT TO COAL CHUTE AND FROM GAGE ON TANK TO CONCRETE FLOOR BERGEN OIL CO. APPLIED SPEEDI-DRI AND VINEGAR APPLIED CALLERS WIFE IS PREGNANT AND SICK"

All Materials:

Site ID: 131864
Operable Unit ID: 977062
Operable Unit: 01
Material ID: 403901
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported

AS231
NNE
1/4-1/2
0.483 mi.
2550 ft.
MCIZ CORP.
1-25 2ND AVENUE
BROOKLYN, NY 11215
Site 4 of 4 in cluster AS

NY LTANKS
NY Spills
S102619097
N/A

Relative:
Higher

Actual:
14 ft.

LTANKS:
Name: MCIZ CORP
Address: 1-25 2ND AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9603998 / 2013-07-30
Facility ID: 9603998
Site ID: 267560
Spill Date: 1996-06-24
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: adzhitom
Referred To: Not reported
Reported to Dept: 1996-06-24
CID: 297
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MCIZ CORP. (Continued)

S102619097

Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1996-06-24
Spill Record Last Update: 2013-07-30
Spiller Name: JACK MARMURSTEIN
Spiller Company: MCIZ CORP
Spiller Address: 1-25 2ND AV
Spiller County: 001
Spiller Contact: JACK MARMURSTEIN
Spiller Phone: (718) 875-8200
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 217964
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This Spill cleanup project has been reassigned from DEC (Sigona) to Rommel on 2/2/2004. 3/24/06 Diaz - Next steps required - review file, track down contacts. 9/21/06 sent ttf letter. bf 9/27/06 Mr. Braun of MCIZ called and left message. I called him back. No info on tank. not sure of which tank failed. Says he has no records. I tried calling Tone Tank and Pump (performed test) at (718)331-5003. Phone number not in service and no further info. bf 3/12/10 PBS inspection. NOV issued. bf 07/16/13 - Spill Case is transferred from Brian Falvey (PBS Unit) to V. Brevdo (Section B) as per DER Region 2 decision - Tank Test Failure Spill Case. VB 07/30/13 - Spill Case is reassigned to Alex Zhitomirsky. Alex had another spill at this facility that has been closed. Re-assignment of this spill case is discussed between Alex Zhitormirsky and Vadim Brevdo on 7/30/2013. VB. 7-30-2013 Discussed the spill with Kris Almskog (P.W. Grosser Phone:631.589.6353). He stated that based upon a review of available spill report files, it appears that there was an administrative overlap of this spill case and spill # 0601840, which was closed last month. PWGC is requesting that NYSDEC spill case # 9603998 be closed at this time as the site has been remediated in accordance with NYSDEC requirements. I concur with this request. All e-docs are stored under spill# 0601840. AZ"
Remarks: "CALLERS COMPANY HIRED FOR TANK TESTING AND DISCOVERED THE FAILURE - NO PRODUCT HAS LEAKED ONTO THE GROUND"

All Materials:

Site ID: 267560
Operable Unit ID: 1035122
Operable Unit: 01
Material ID: 553626
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: MCIZ CORP.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MCIZ CORP. (Continued)

S102619097

Address: 1-25 2ND AVENUE
City,State,Zip: BROOKLYN, NY 11215
Spill Number/Closed Date: 0601840 / 2013-06-12
Facility ID: 0601840
Facility Type: ER
DER Facility ID: 374189
Site ID: 364184
DEC Region: 2
Spill Cause: Housekeeping
Spill Class: C4
SWIS: 2401
Spill Date: 2006-05-19
Investigator: adzhitom
Referred To: NFA
Reported to Dept: 2006-05-19
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-19
Spill Record Last Update: 2013-06-12
Spiller Name: JACK MARMURSTEIN
Spiller Company: MCIZ CORP.
Spiller Address: 1-25 2ND AVE
Spiller Company: 999
Contact Name: JACK MARMURSTEIN
DEC Memo: "6/16/06 - Raphael Ketani. I tried calling Mr. Marmurstei (718) 875-8200, but could only leave a message with his secretary. I tried him at home (718) 438-0333, but he wasn't there. I called his cell (917) 217-6277 and spoke to him. I told him I needed to know whether the spill was cleaned up and, if so, when I will receive the cleanup report. He said he wasn't aware of a spill, but he will contact his foreman and find out what happened. At 12:49PM, Mr. Braun called me up and asked when the oil spill occurred and what spilled. I told him that it happened on May 19 and that it was waste oil and fuel oil. He said he wasn't aware of this and that usually his crews clean everything up every day. He said he will investigate the problem and make sure it's cleaned up. Mr Braun said he will send me a report.
6/19/06 - Raphael Ketani. Mr. Braun showed up at the DEC office and handed me pictures of the buse garage. The garage appeared to be reasonably clean. Mr. Braun explained that he was there yesterday, 6/18, and saw that the crew had cleaned up the spill. The pictures Mr. Braun gave me show that at least some amount of cleaning took place. This appears to be a house keeping issue. Based upon the pictures Mr. Braun gave me, I am closing the spill case. 2-12-2009 Spill was reopened after a meeting with V. Brevdo and J. Urda due to new information. Spill was previously managed by Raphael Ketani. Spill was transferred to Alex Zhitomirsky on 2-10-2009 as per Vadim Brevdo. According to the report received from Roux on February 4, 2009, NYC DOS leased 1-25 second Ave. Brooklyn from One Second Ave. Corp, c/c Howard Levine from Sept. 1957 until November 17, 1995. This

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MCIZ CORP. (Continued)

S102619097

property was owned by One Second Avenue Corporation until it was transferred or sold to a new entity, Fifteen Second Avenue LLC, on February 10, 1998. The site is currently leased by a private bus company and operated as a maintenance and repair garage. This site was included in NYC DDC Consent Order - sp.#9614826. The site was investigated and remediated in 1997-2006 as part of NYC DDC Consent Order. MPE system was shut down 6-20-2006. Soil samples were collected from MW-19 on July 18, 1998. No VOC exceedances were recorded. SVOC compounds which do not match transmission fluid were found in soil samples collected from this well. Groundwater data from March 5, 2000, indicates no product or sheen in MW-19. Gauging records indicate that a disabled bus had been parked over well MW-19 between July 15, 2005 up until after December 9, 2005. On March 15, 2006, Roux found 0.16 foot of separate-phase transmission fluid. This well did not historically exhibit product, including the last time it was gauged by LiRo on July 15, 2005. On August 7, 2008 Roux encountered 0.29 foot of the free phase product. AZ 2-25-2009 CSL approved by V. Brevdo and J. Urda was sent to Jack Marmurstein at 15 Second Avenue, Brooklyn, NY by certified mail. AZ 2-22-2011 Consent Order was signed by DEC on Feb.14, 2011. AZ 9-8-2011 An e-mail was received from M. Goddick AKRF ph.914.949.7559: Alexander, As a follow up to our discussion, the removal of the aboveground tanks is being scheduled to be completed within 30 days. Immediately following removal of the tanks, test pits will be excavated in the area of the tanks. If grossly contaminated soil is observed, it will be excavated to the extent practical for off-site disposal. No dewatering will occur during the soil removal activities; appropriate measures will be taken to protect the structural integrity of the building, including excavating in small sections and/or using a trench box, as warranted. If appropriate, observation/recovery wells will be installed in the excavation prior to backfilling. Endpoint samples will be collected in accordance with DER-10 requirements. The findings associated with the tank removal and investigation/remediation activities will be documented in the Remedial Investigation Work Plan (RIWP). The RIWP will also include a comprehensive investigation of the entire facility per the requirements of the consent order. The RIWP will be submitted to you within 60 days of today (November 4, 2011), as opposed to 30 days. As requested, the RIWP will be submitted in electronic format (pdf on CD-ROM). I will let you once the tank removal work is scheduled. In the meantime, please let me know if you have any questions or require additional information. AZ 9/9/2011 An e-mail was received from M. Goddick AKRF ph.914.949.7559: Alexander, To clarify, yes, we will provide a hard copy of the work plan along with the electronic copy. As discussed during the subsequent call today, we will send you a brief work plan next week outlining the protocols for the test pit investigation, soil remediation, and end-point sampling at the time of the tank removal. The field findings and end-point sampling results would be included in the RIWP and would provide a basis for the need for further delineation (as part of future investigation work defined in the RIWP). We have a pending FOIL request to gain any information related to past spill investigation work at the site. We have a partial report prepared by Roux on behalf of NYCDOS dated February 4, 2009. This report discusses NAPL in certain wells, but did not include a site plan. If you could please email a site plan showing the existing wells with NAPL and/or a more complete report showing historic NAPL gauging records, it would be very helpful. As

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MCIZ CORP. (Continued)

S102619097

you suggested, if there are wells in close proximity to the tanks that contain NAPL, I agree that it would be prudent to excavate the area as part of the tank investigation/remediation work described above. I forwarded a plan, made by LiRo with well locations dated March 2010, to M. Goddick. AZ 9-22-2011 An e-mail was received from M. Goddick: AKRF met with the tank removal contractor (Gemstar), tank design consultant (JD2), and client at the site today to review logistics related to the tank removal and soil remediation. Work at the site will start on this upcoming Monday (9/26) and is expected to be completed by the end of the week (Friday-9/30). A tentative schedule of the field work is as follows: - Mon & Tue Tank cleaning and removal, removal of the containment wall, saw cutting of concrete, set up of temporary drums with containment pallets for oil storage - Wed & Thur Contaminated soil removal - Fri Backfill excavation A brief scope of work describing procedures for the tank removal, soil excavation, end-point sampling, and reporting is attached. The attachment also includes a schematic depicting the targeted area for soil removal. Finally, the accessible wells were inspected and gauged today. Only one well, MW-19 (near the ASTs and historically contained product), contained product (0.2 feet). A table summarizing the well gauging results is included in the attachment. Liz Baird from my office (ebaird@akrf.com, cell: 917.613.5977) will be on-site to oversee and conduct the required sampling during the tank removal and soil remediation activities. AZ 12-6-2011 Contacted Marc Goddick. It was decided that the AKRF will sample newly installed monitoring wells (3), number them, sample existing monitoring wells, indicate location of the former MW-19, consider removing USTs closed in place. AKRF will submit a report with the results of the sampling and the site plan to DEC. AZ 2-16-2012 Received an ecopy of a report summarizing the groundwater sampling of the existing wells at the site. Feedback as to how the scope of RI WP should be modified in consideration of the findings of the sampling, which does not show significant groundwater contamination was requested. Report was edoc'ed. I requested a hard copy submittal. AZ 2-28-2012 Discussed the site with Marc Goddick. No exceedances of VOCs/SVOCs were detected. No free phase was detected. AKRF will submit a Work Plan containing the following info: report/document inspection of all floor drains, inspection of the oil/water separator, operation/maintenance plan which would specify any corrective measures and require inspection maintenance of the separator. An implementation schedule will be included. The WP will be submitted within 60 days. Email from M. Goddick: Alexander, As a follow up to our discussion earlier, based upon the findings of the Groundwater Sampling report along with the previous remediation activities documented in the Remedial Investigation Work Plan, additional subsurface investigation activities at the site are not warranted. However, it is our understanding that NYSDEC is requesting that the floor drains and oil/water separator be further investigated and an Operations & Maintenance (O&M) Plan be prepared. Within 60 days, a report will be prepared and submitted to NYSDEC, which documents the following: - Inspection of the floor drains and oil water separator, inclusive of dye testing, as appropriate, to document construction of the separator, to confirm discharge points of the drains and separator, etc. - O&M plan for future periodic inspection and maintenance of the drains and separator - Implementation schedule for any corrective actions and future inspection & maintenance We understand that you would prefer our

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MCIZ CORP. (Continued)

S102619097

submittals to consist of a hard (paper) copy along with an electronic copy on CD. In the meantime, please let me know if you have any questions or require additional information. Regards, Marc Marc S. Godick Sr. Vice President

..... AKRF Environmental, Planning, and Engineering Consultants 34 South Broadway, Suite 401 - White Plains, NY 10601 - F) 914.949.7559 440 Park Ave South - New York, NY 10016 - F) 212.726.0942 P) 914.922.2356 - Email mgodick@akrf.com www.akrf.com AZ 5-16-2012 Dave Ydelson(917-295-6449) contacted me and inquired about the status of the project. Marc Godick works for Dave Ydelson. I updated Dave Ydeslon on the project status. AZ 5-24-2013 Discussed the site from L. Oliva and D. Ydelson. The site no longer will be a bus depot. It will be demolished and become a correction facility. The floor drains and the oil separator were cleaned. P.W. Grossman will submit a report documenting it and requesting a spill closure. AZ 6-11-2013 Received a copy of a report by P.W. Grosser dated June 3, 2013. The report states that the property has most recently been used as a bus maintenance facility, but is currently vacant. The site is currently being prepared for a complete building renovation with a second floor expansion. The site will be leased to NYS Dept. of Correction and Community Supervision for offices. PWGC inspected the site on May 28,2013. PWGC confirmed the site building to be vacant. The floors, mechanic pits, drains, utility manholes and chamber are clean and free of petroleum debris and sludge. There were no tanks, petroleum products and/or chemicals observed at the site. No evidence of light non-aqueous phase liquid was observed. Photographs were attached to the report. Based upon PWGC's observations, the site has been thoroughly cleaned and is vacant, no petroleum or chemical products are being stored on the site, and no evidence of LNAPL was observed. PWGC requested closure of this spill. AZ 6-12-2013 Based on the submitted reports including a report dated February 10, 2012, this spill is closed. The following e-mail was sent to David Yudelson, V. Brevdo and L. Oliva: Dear Dave, I have reviewed a spill closure report dated June 3, 2013. The report stated that the floors, mechanic pits, drains, utility manholes and chamber are clean and free of petroleum debris and sludge. There were no tanks, petroleum products and/or chemicals observed at the site. No evidence of light non-aqueous phase liquid was observed. Photographs were attached to the report. Also, a report summarizing the results of groundwater sampling at the above site and dated February 10, 2012, was submitted to DEC. Based on this information, spill number 0601840 is closed. All wells associated with this spill should be properly abandoned. Prior to the abandonment, all wells should be checked for presence of free phase product. If free phase product is encountered, NYSDEC should be notified. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or remedial action the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was not addressed by this evaluation. II. Environmental conditions related to the Site which were unknown to the Department at the time of this approval. III. Information received, in whole or in part, after the Department's spill case closure, which indicates that the corrective action was not sufficiently protective of human health for the reasonably anticipated use(s) of the site; or IV. Fraud in obtaining this approval for inactivation. Please be advised that you should maintain a permanent file of all documentation and correspondence

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MCIZ CORP. (Continued)

S102619097

Remarks: regarding this case for future use. The Department's files regarding this release may not be maintained indefinitely. Sincerely, Alex Zhitomirsky "

"OIL ON FLOOR, : WASTE OIL IS OVERFILL, FLOODED AREA NO CLEAN UP"

All Materials:

Site ID: 364184
Operable Unit ID: 1122219
Operable Unit: 01
Material ID: 2111692
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 364184
Operable Unit ID: 1122219
Operable Unit: 01
Material ID: 2111691
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: BUS YARD
Address: 1-25 2ND AVE.
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0800421 / 2010-03-19
Facility ID: 0800421
Facility Type: ER
DER Facility ID: 345672
Site ID: 396173
DEC Region: 2
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 2401
Spill Date: 2008-04-10
Investigator: jbvought
Referred To: Not reported
Reported to Dept: 2008-04-10
CID: 406
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MCIZ CORP. (Continued)

S102619097

Remediation Phase: 0
Date Entered In Computer: 2008-04-10
Spill Record Last Update: 2010-04-20
Spiller Name: Not reported
Spiller Company: MCIZ CORP.
Spiller Address: 1-25 2ND AVENUE
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "04/11/08-Vought-Off hours responder. Called and spoke to spill notifier. Site is used for bus maintenance and parking and last night one of the buses was in accident with two cars on the lot releasing sewage, waste oil, and motor oil. FDNY was onsite night of 4/09 and again on 4/10. Sewers were affected and DEP was also onsite. Notifier also had prior conversations with DEC Selvin Southwell from Water Unit regarding continual problem of poor housekeeping and hence discharge to Gowanus Canal. Puddles of product and ribbons also present. Puddles are on asphalt, concrete and soil. Vought provided email address to notifier who will email pictures. Vought reviewed pictures and three puddles present of dark liquid, possibly concrete but no signs of spills requiring immediate DEC response. Also present in pictures is large AST. Vought called Mciz Corp and spoke to receptionist (Maria) and informed them of site visit and left message that DEC will performing a site visit this afternoon, and DEC would prefer to observe no violations. Site contact is: Mciz Corp 15 2nd Ave, Brooklyn, NY 11215-2711 Phone: (718) 875-8200 SIC: Bus Charter Service, Except Local Line of Business: Bus Charter Service-Nonlocal Contact Name: Jacob JACK Marmurstein Contact Title: President DEC requires: 1)site visit 2)cc and discussion with Selvin Southwell 3)possible contaminated soil letter upon DEC site visit 4)PBS Registration of aboveground tank. Vought sent email of above to notifier. 04/14/08-Hiralkumar Patel. visited site on 04/11/08. met notifier at site who showed bus repair company at 15 2nd ave, as source site. visited bus repair company and met James Carter. Mr. Carter mentioned that he owns the property with other people. found heavy sheen on water outside of repair shop, that was going into city sewer system. asked Mr. Carter to clean that area. Mr. Carter parked buses on open lot in front of his site. found one spot of soil contamination under a bus (see pics on e-docs) and a water pool with heavy sheen. found heavily contaminated soil near this water pool and that is under a backhoe. this backhoe owned by C&A Properties, who runs business at 110 5th St. spoke with Teddy (cell: 347-381-9811) at C&A Properties, asked him to remove contaminated soil from area under the backhoe. found three aboveground waste oil tanks at bus repair shop (PBS #: 2-456101). minor spills found inside repair shop on concrete. found monitoring well across the street from bus repair shop and in front of empty lot, which bus repair shop used to park their buses. James Carter MCIZ CORP. 15 2nd Avenue Brooklyn, NY 11215 PH. (917) 559-0491 Charlie Crystie **owner** C&A Properties II, Corp. 110 5th Street Brooklyn, NY 11215 PH. (718) 596-1151 Fax (718) 246-0148 requirements for MCIZ corp: 1) cleanup of bus depot entrance from where oil water coming out and going into city sewer, 2) cleanup under bus in parking lot requirement for C&A properties: 1) cleanup under and around backhoe 04/28/08-Vought-After further discussion with DEC Patel Vought changed address of this spill from original address of 31 2nd Ave to 3-25 2nd Avenue. Vought reviewed pictures and DEC requires:1)Opening new spill on 2-14 2nd Ave (lot across street from Bus yard where Bus was observed with contaminated soil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MCIZ CORP. (Continued)

S102619097

and one monitoring well was observed and also spill from backhoe and contaminated soil 2)collection of endpoint samples from bus spill excavation and also from backhoe excavation 3)CSL with repair of waste oil tanks and registration of tanks for 3-25 2nd ave (Bus repair building). Vought to send CSLs to: DEC requirements for 3-25 2nd ave are: 1)cleaning, repair and registration of waste oil AST (pictures taken by DEC Patel show open hole in top of tank) and excavation of soil and collection of endpoint samples from under bus (owner is) 2)cc to NYCDOS and DEC Southwell 3)Registration of waste oil tank: Fifteen Second Ave, LLC 5307 17th Avenue Brooklyn, NY 11204 and: James Carter MCIZ CORP. 15 2nd Avenue Brooklyn, NY 11215 PH. (917) 559-0491 Vought sent CSL with one month due date and above requirements to above addresses. DEC requirements for 2-14 2nd Ave are: 1)opening of new spill number due to soil contamination from bus leak and from backhoe leak observed by DEC Patel 2)excavation and collection of endpoint samples from bus spill and from backhoe spill and owner is 3)cc to NYCDOS and DEC Southwell. Letter to be sent to: Mr. Renzo Ferrari Chief of Operations 125 Worth Street Room 823 New York, NY 10013 Fax: (212) 442-8624 Ph: (646) 885-4540 Vought sent out letter with above requirements and one month due date under new spill #0850124. DEC Requirements for 110 South 5th Street (owner of backhoe) are: 1)excavation of contaminated soil under backhoe and collection of endpoint samples 2)cc to NYSDOS and DEC Southwell. Letter to be sent to: Charlie Crystie **owner** C&A Properties II, Corp. 110 5th STreet Brooklyn, NY 11215 PH. (718) 596-1151 Fax (718) 246-0148 Vought sent out above letter to Crystie under spill #0850124 with one month due date: 04/28/08-Vought-Spoke with NYSDOS Ferrari and he will send out Sanitation inspector to write violations for spill to bus company and backhoe company and will inform Vought of progress. See also spill #0800421 for spill at 3-25 2nd Avenue. 05/02/08-Vought-Received call from and spoke to NYSDOS Ferrari and he performed site visit and gave order to bus company to remove buses from lot. Ferrari will have his building maintenance manager call Vought to ask for soil excavation requirements. Vought received original letter sent to Charlie Crystie as returned and undeliverable. Vought called Charlie Crystie to confirm mailing address and Teddy Lewis confirmed that Crystie did receive DEC letter dated 4/28/08 via fax. 05/05/08-Vought-Received message from NYSDOS Al Mignone (cell:646-235-3183 office:718-334-9121 fax:718-334-9088). Vought called Mignone and left message to return call. Vought received call and spoke to Mignone and he will excavate soil and send in manifest. As NYCDOS will be performing excavation, no soil endpoint analyticals required due to relatively small areas of excavation however for spill closure, Department requires submission of waste manifest for soil. Vought faxed Mignone copy of pictures and Department letters. 07/07/08-Vought-Received call from and spoke to AL Mignon and soil was excavated and he sent in disposal manifests and small letter of explanation. Property was fenced in and bus company was evicted from site. 3/19/10-Vought-Reviewed notes and due to excavation of contaminated soil from lot across street from site as per discussion with DOS Mignone 5/5/08, spill closed by Vought. "Spill is coming from the house across the street. Home heating oil is on the sidewalk. No contact with the homeowner since this morning." Not reported

Remarks:

All Materials:

Site ID:

396173

Operable Unit ID:

1153120

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MCIZ CORP. (Continued)

S102619097

Operable Unit: 01
Material ID: 2143898
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

AT232
SSW
1/4-1/2
0.484 mi.
2553 ft.

850 3RD AVE
850 3RD AVENUE
BROOKLYN, NY

NY LTANKS
NY Spills

S104278460
N/A

Site 2 of 3 in cluster AT

Relative:
Higher

LTANKS:

Actual:
12 ft.

Name: 850 3RD AVENUE
Address: 850 3RD AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9312153 / 1994-01-15
Facility ID: 9312153
Site ID: 161674
Spill Date: 1994-01-15
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: 1994-01-15
SWIS: 2401
Investigator: O'DOWD
Referred To: Not reported
Reported to Dept: 1994-01-15
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-01-20
Spill Record Last Update: 2004-05-14
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 136486
DEC Memo: ""
Remarks: "SUPERVISOR GAVE WRONG TANK SIZE CAUSING OVEFILL - CREW ENROUTE TO CLEAN IT UP APPLY SPEEDY DRY - DEP CONTACTED - 1030/AM - 215/PM ARRIVED SITE (GSA) SAND APPLIED MET W/ PEDRO (ENG) HE SAID EMPIRE"

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

850 3RD AVE (Continued)

S104278460

All Materials:

Site ID: 161674
Operable Unit ID: 994177
Operable Unit: 01
Material ID: 391149
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 200.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: 850 3RD AVE
Address: 850 3RD AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9407229 / 1995-03-29
Facility ID: 9407229
Facility Type: ER
DER Facility ID: 136486
Site ID: 239333
DEC Region: 2
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 2401
Spill Date: 1994-08-25
Investigator: O'DOWD
Referred To: Not reported
Reported to Dept: 1994-08-25
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: 1995-03-29
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1994-10-21
Spill Record Last Update: 2004-05-14
Spiller Name: Not reported
Spiller Company: FEDERAL GOV'T FACILITY
Spiller Address: 850 THIRD AVE
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "BEING TRANSPORTED OFF SITE AS BEING EXCAVATED"

All Materials:

Site ID: 239333
Operable Unit ID: 1001478
Operable Unit: 01
Material ID: 380243

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

850 3RD AVE (Continued)

S104278460

Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

AT233
SSW
1/4-1/2
0.484 mi.
2553 ft.

US GSA
850 3RD AVENUE (29TH ST AND 3RD AVE)
BROOKLYN, NY 11232
Site 3 of 3 in cluster AT

NY LTANKS
NY Spills

U001842028
N/A

Relative:
Higher
Actual:
12 ft.

LTANKS:
Name: GENERAL SERVICES OF FEDS
Address: 850 3RD AVENUE (29TH ST AND 3RD AVE)
City,State,Zip: BROOKLYN, NY 11232
Spill Number/Closed Date: 9908767 / 2008-06-10
Facility ID: 9908767
Site ID: 239334
Spill Date: 1999-10-19
Spill Cause: Tank Test Failure
Spill Source: Non Major Facility > 1,100 gal
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 1999-10-19
CID: 371
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-10-19
Spill Record Last Update: 2008-06-10
Spiller Name: JOHN HARRIS
Spiller Company: GENERAL SERVICES ADMIN.
Spiller Address: 26 FEDERAL PLAZA, RM 1611
Spiller County: 001
Spiller Contact: STEVE FERMAN
Spiller Phone: (718) 340-5268
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 23550
DEC Memo: "3/30/07 - Austin - Trasferred to Rahman for further review no prior info in remarks - end 02/27/08 Rec'd call from Tom Burke, Office of General Services(federal)@(212)264.0800 asking status of the spill case.Tank failed tests(UST),no info on investigation around the tank.Other associated spill 9304694.(sr) 06/10/08 As per RSE's directives to consolidate duplicate spills for same site,this spill case is consolidated with Spill # 9304694 upon Rafael Ketani's

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US GSA (Continued)

U001842028

Remarks: consent.(sr)"
"three tanks failed 3-30,000 GALLON USTs. Federal facility has no response."

All TTF:

Facility ID: 9908767
Spill Number: 9908767
Spill Tank Test: 1547747
Site ID: 239334
Tank Number: 1, 2, 3
Tank Size: 20000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 239334
Operable Unit ID: 1087442
Operable Unit: 01
Material ID: 297869
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: US GSA
Address: 850 3RD AVENUE (29TH ST AND 3RD AVE)
City,State,Zip: BROOKLYN, NY 11232
Spill Number/Closed Date: 9304694 / 2010-01-06
Facility ID: 9304694
Facility Type: ER
DER Facility ID: 23550
Site ID: 265268
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1993-07-14
Investigator: HRAHMED
Referred To: Not reported
Reported to Dept: 1993-07-14
CID: Not reported
Water Affected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US GSA (Continued)

U001842028

Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1993-07-16
Spill Record Last Update: 2010-01-06
Spiller Name: Not reported
Spiller Company: FEDERAL POWER PLY GSA
Spiller Address: 26 FEDERAL PLAZA
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "also know as 850 3rd Ave. see also 93-12153 & 94-07229. unable to reach a GSA contact. Possible remediation under 94-07229. Previous note by RDDECAND on 3/15/06 Spill transferred back to R-2 3/5/08 - Austin - Assigned to Ketani for further investigation - end 3/13/08 - Raphael Ketani. I began working on the case. Spill number 93-12153 was monitored by a former spills worker, Kerri O'Dowd. She didn't put in any case notes into the database. The spill was a 200 gal. overfill. It happened because someone had the wrong tank size. DEP was contacted at 10:30AM and GSA arrived at 2:15PM. Sand and Speedi Dri were applied to the spill. The case was closed on 1/15/94. The site address is 850 3rd Avenue, Brklyn. (29 St. & 3rd Ave.). Case 94-07229 was managed by Kerri O'Dowd. There were no case notes. Contaminated soil was discovered and was being removed as it was being excavated. She closed the case on 3/29/95. 3/17/08 - Raphael Ketani. A copy of the original August 1993 Site Characterization Report was found in the file cabinet. It was produced by Woodward-Clyde Consultants, Inc. It was prepared for Rose, Beaton & Rose, Architects and Engineers, 81 Main Street, Brooklyn (212) 926-2878/(212) 594-2118. According to the soil analytical tables in the report, there was no significant contamination. Table 4-2 for the groundwater samples didn't list any significant contamination, either. There was a fold out site map which showed the locations of the six formerly active tanks. The PBS case is #2-601672. It shows that six tanks were closed in place on either 8/1/94 or 9/1/94. Four other tanks were installed on 9/1/94. Tank #7 is in service and tanks #8 to #10 are temporarily out of service. A note in the file that I did find said that there were records in the open file section of the storage area downstairs. I checked the file storage room, but found nothing. I also asked around in the Division of Environmental Remediation, but no one had heard of the case for the site. I checked the E-docs and found the following: The E-docs contained a transmittal letter dated 8/10/93 stating that this was the second revision of the Site Characterization Report. An estimated 2050 cu. yds of soil will be excavated and an additional 450 cu. yds. of oil contaminated soil. Tanks #3 and #4 are scheduled to be removed, along with an 1100 gal. tank. Two 20,000 gal. tanks will be abandoned in place. Groundwater remediation is not necessary based upon the analytical results. A second round of groundwater sampling will take place August 1993. The parties involved are: Woodward-Clyde Consultants (212) 594-2118 Roy Feinzig (914) 682-4895, Rose, Beaton & Rose, Architects and Engineers, 81 Main Street, White Plains, NY, 10601 Charles Evans (718) 330-7474, Federal Building Manager, General

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US GSA (Continued)

U001842028

Services Administration, Public Buildings Service, Contract Section, 26 Federal Plaza, rm. 1611, NY, 10278; GS0wP94CUC0055 A 10/4/93 E-doc note from Ms. O'Dowd states that they will install 3 new USTs. There are 6 USTs on site: 5 fuel oil (4 20,000 gal. tanks, 1 1100 gal. tank); 1 20,000 gal. gas tank. Groundwater is at 5.5' to 8.5' below grade. Nine soil borings will be done and 5 monitoring wells will be installed. MW-3G is in the area for the new UST. Groundwater is at 6' and dewatering will have to take place in order to install the new tank. USTs #3 and #4 are impacted. Fuel contaminated soil will have to be removed. A 8/9/93 E-doc note from Ms. O'Dowd states that MW-1 has no VOC hits MW-2 has less than 5 ppb MW-3G has hexane 5.8 ppb, ethylbenzene <50 ppb, xylene ,50 ppb MW-6 has 3 ppb of hexane MW-9 has no VOCs There was a 10/18/94 letter from Environmental Data Consultants to the GSA requesting well installation locations and regarding the NYCFD and NYC Building Department violations. Environmental Data Consultants, Inc., 55 Alder Street, Ste 2, South Yonkers, NY, 10701, (914) 968-1508. Dewatering took place to install the new tanks, but a SPDES permit wasn't needed as the discharge rate was below the permit lower limit and the water wasn't contaminated. Soil samples need to be taken at all of the closed tanks and the PBS record needs to be updated. The 9/6/94 E-doc note states that there is 2 to 3 of oil in MW-3G. USTs #3 to #5 are to be removed. Wells MW-3 and MW-6 need to be replaced as they were destroyed. Many of the hits in Table 1 of the analyses summary table also appear in the blanks. So these analytes can be negated. I tried to contact Charles Evans, but the phone number was not in service. I tried to reach Environmental Data Consultants, but the phone number was not in service. I tried to reach Rose, Beaton & Rose, but the phone number belonged to another company. I tried to reach Woodward-Clyde, but the phone number belonged to another company. 3/18/08 - Raphael Ketani. I found a later case from 1999 for the same site - #9908767. It involves the test failure of three 30,000 gal. tanks. Contact people were listed on the spill report. They are: Steve Ferman (718) 340-5268, at the site; John Harris (718) 965-5147 of the General Services Administration; and Tom Burke (212) 264-0800 of the General Services Administration, Technical Services, 26 Federal Plaza, rm. 1611, NY. I tried to contact Mr. Burke, but could only leave a message. I tried to contact Mr. Harris, but no one picked up. I tried to contact Mr. Ferman, but the number was no longer in service. William (Bill) De Nyse (de-nice), Senior Industrial Hygienist, (212) 264-0506 called to ask what DEC had in the way of reports and documentation for the spill case. I told him we had the August 1993 Site Characterization Report that was produced by Woodward-Clyde, a Second Revision SCR and some small letters. He asked that DEC provide him the reports as he doesn't have them. He added that he was the contact person at the GSA and that he will try to help get the case closed. Mr. De Nyse asked what should happen if he can't find the closure reports. I told him that DEC will ask that a new investigation take place. I made copies of the reports and sent them to him. 4/11/08 - Raphael Ketani. I tried to contact Mr. De Nyse, but could only leave a message. His phone greeting said that he will be out until 4/21/08. I will try him then. 6/10/08 - Raphael Ketani. I tried to contact Mr. De Nyse, but could only leave a message. I got ahold of Mr. Burke. He said that right now they are putting the contract out for bid. He said it will take some time in order to get a contractor lined up and get the investigation started. I told him to keep me updated. He added that Mr. De Nyse is the point of

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

US GSA (Continued)

U001842028

Remarks: contact. 6/12/08 - Raphael Ketani. Mr. De Nyse called back. He said he is the regional engineer and the project is now being handled by a field (local) engineer at the site. The person is Rashid Mattoo (718) 254-7141 at 10 Metro Tech, Brklyn. Mr. De Nyse said that Mr. Mattoo is the contact person from now on. He added that right now they are trying to get funding to do the investigation. They have a scope of work, also. 8/12/08 - Raphael Ketani. I tried to contact Mr. Mattoo regarding the site investigation, but could only leave a message. Mr. Burke called me back. He said that the contractor has been chosen and they expect to go to contract next week. He added that they will start in a week or two. 8/18/08 - Raphael Ketani. The case is being prepared for transfer due to a case realignment within the unit. The new case manager should probably call Mr. Mattoo or Mr. De Nyse in a week or two to find out the status of the investigation."

"SOIL SAMPLE SHOW ELEVATED T.P.H. - AUTHORITY ENGINEERS - MAIN CONTRACTOR (914)682-4850 ROY FONZING PRINCIPAL CONTACT - FEDERAL MANAGER BUILDING CHARLES EVANS (718)330-7474."

All Materials:

Site ID: 265268
Operable Unit ID: 986365
Operable Unit: 01
Material ID: 398180
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

234
East
1/4-1/2
0.486 mi.
2565 ft.

APARTMENT
555 5TH AVE
BROOKLYN, NY

NY LTANKS S106702423
N/A

Relative:
Higher
Actual:
84 ft.

LTANKS:
Name: APARTMENT
Address: 555 5TH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0404519 / 2004-08-04
Facility ID: 0404519
Site ID: 106219
Spill Date: 2004-07-27
Spill Cause: Tank Test Failure
Spill Source: Tank Truck
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2004-07-27
CID: 405
Water Affected: Not reported
Spill Notifier: Other

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APARTMENT (Continued)

S106702423

Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-07-27
Spill Record Last Update: 2004-08-04
Spiller Name: DAVE UDELSON
Spiller Company: APARTMENT
Spiller Address: 555 5TH AVE
Spiller County: 001
Spiller Contact: DAVE UDELSON
Spiller Phone: (212) 421-2150
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 93603
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO send TTF letter 8/4/04 TJD Inspection performed 8/2/04. Tradewinds environmental retested tank only - passed. System test failed - unable to hold pressure. Problem determined to be related to piping. Buried sections of piping were exposed, revealing an old petrometer line which was not connected. No evidence of a petroleum discharge was identified. No further action required. Spill closed."

Remarks:

All TTF:

Facility ID: 0404519
Spill Number: 0404519
Spill Tank Test: 1529471
Site ID: 106219
Tank Number: Not reported
Tank Size: 4000
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

235
North
1/4-1/2
0.488 mi.
2575 ft.

NYC DOT ASPHALT PLANT
448 HAMILTON AVE
BROOKLYN, NY

NY LTANKS S109063041
NY Spills N/A

Relative:
Higher

Actual:
11 ft.

LTANKS:
Name: HAMILTON AVE. YARD (ASPH. PLANT) DOT -DDC
Address: 448 HAMILTON AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0302574 / Not Reported
Facility ID: 0302574
Site ID: 209848

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Spill Date: 2003-06-10
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: adzhitom
Referred To: WORK PLAN
Reported to Dept: 2003-06-10
CID: 252
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 1
Date Entered In Computer: 2003-06-10
Spill Record Last Update: 2019-08-12
Spiller Name: VIVIAN MARCOVICI
Spiller Company: NYC DOT FACILITY MAINT.
Spiller Address: 69-46 SYBILLA STREET
Spiller County: 001
Spiller Contact: WILLIAM KLEIN
Spiller Phone: (718) 762-5200
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 271159
DEC Memo: "1/3/05- The case is transferred to I. Islam 9/8/05- The site's GW is being remediated by evacuating the free product with vac truck from the monitoring wells on monthly basis by URS Corp. in association with O.Brien-Kreitzberg. Reviewed the IRM data report through Jun/05. The report reveals that there is no data for the month of May/05. Absorbent sock has been installed in one well only and a total of 1,650 gallons of free product and water have been removed to date from the wells. Site visits with vac truck on monthly basis will continue until free product stops appearing. Then, it is advised for GW sampling for analyzing VOCs and SVOCs.- II 3/09/06: This spill transferred from I. Islam to Q.Abidi. 7/27/06: DEC case lead transferred from Q. Abidi to J.A. Maisonave. - JAM 8/22/06 Reviewed and responded in a letter to Semi-annual Monitoring Report dated July 28, 2006 submitted by Roux Associates. Only three wells remain (MW-10, MW-11 and MW-12) and are being gauged monthly. MW-11 and MW-12 contained measurable free product and MW-10 contained a sheen. An absorbent sock is used to collect product in MW-10. The product in MW-11 and MW-12 was not removed. Previously a vacuum truck was used to remove product from the three wells (enhanced fluid recovery [EFR]). Roux recommended reducing well gauging frequency from monthly to quarterly since the gauging events provide limited information and the high viscosity of the free product limits its potential for migration. The Department approved the gauging reduction provided Roux resume EFR in all three wells. The Department also requests Roux install more monitoring wells to replace the ones destroyed. A work plan will be submitted for the installation of replacement wells. - JAM 5/30/07 Meeting with NYCDDC, Greyhawk and Roux. We discussed re-installing on-site wells that were destroyed. This is a very active asphalt plant so it is difficult to maintain the wells.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Greyhawk recommends a site visit to discuss. Also, a waste oil tanks will be removed from this site sometime at the end of the summer. - JAM 01/08/08 Reviewed UST Closure Report for two waste oil USTs. After lab data was returned with levels of VOCs and SVOCs above regulatory limits, spill number 0707639 was called in. I called Brian Morrissey at Roux to discuss. I sent him a copy of the Closure Report and we will schedule a site visit. Refer to spill number 0707639 for the UST Closure Report. - JAM 02/07/08 Visited the site with associates from Roux and Greyhawk. Wendy Shen, Wendy Monterosa, and Alan Elias attended. Discussed locations for wells and ways to ensure the wells would not be destroyed. Roux has been conducting EFR at the three existing wells, MW-10, MW-11 and MW-12. Roux/Greyhawk will submit a summary data report for those EFR events and also a work plan with proposed well locations. - JAM 07/08/08 (DEC REMARKS ENTRY IN SPILL # 0707659) The tanks are associated with an Oil/Water Separator near the garage. I visited the site with representatives from Roux Associates and they will be responsible for any contamination associated with these tanks. This spill case (0707659) will be closed and remediation tracked under spill # 0302574. - JAM 9/5/08 Reviewed Hamilton Ave Additional Investigation Work Plan dated June 24, 2008 submitted by Roux. Roux proposes installing 10 monitoring wells throughout the site and advancing 3 soil borings near the former oil water separator tanks (removed by Shaw). DEC submitted a letter today approving the work plan with the following adjustments: 1) One monitoring well should be installed to the south of the gasoline and diesel dispenser islands located at the southern edge of the site. 2) If contaminated soil is encountered in the vicinity of the 2 former USTs then a monitoring well should be installed at that location. Letter is uploaded to eDocs. - JAM. 09/10/08-Vought-See also closed spill 0801979 at same location for asphalt spill. 7/28/10 On July 8, 2010, DEC met with NYCDOT, their consultants, and representatives from NYCDOT to discuss sites managed under the consent order. DDC has changed consultants and LiRo will perform remedial activities at sites in Brooklyn, Queens and Staten Island. DEC was notified that the work plan, which was approved on September 5, 2008, will be implemented. Additional wells were proposed by LiRo and verbally approved by the DEC at the meeting. The field work began on July 13, 2010. On July 14, 2010, DEC was notified that due to site constraints, some wells had to be relocated. - JAM 10/29/10: Related spill case 0812313 has been closed to consolidate with this spill case, under which investigation & remediation of this site are being tracked. - J. Kolleeny 11/8/2010 Sill was re-assigned to AZ from Joe Maisonave as per J. Kolleeny and V. Brevdo. Contacted S. Frank. They submitted Site-Turn-over report received 11-8-2010. Newly proposed wells/borings (5 wells and 3 borings) are approved. AZ 2-23-2011 An email was sent to DDC/V. Brevdo/S. Frank: Dear Steve, I have reviewed Site Turn-over Status Report and Supplemental Investigation. The Supplemental Investigation Plan is approved. EFR activities should be performed to address free phase product. A permanent groundwater and soil remediation system should be designed to address the existing contamination. Shallow soil excavation should be considered. UST closed in place should be located and, if feasible, excavated. AZ 3-2-2011 Reviewed additional investigation pplan dated February 15, 2011. The following e-mail was sent to S. Frank/F.Ashkan/V. Brevdo: Dear Steve, I have reviewed additional site investigation plan dated February 15, 2011. This plan has been approved. The Responsible Party and Contractors are responsible for

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

the safe execution of the Work Plan. AZ 11-17-2011 The following email was sent to S. Frank/V. Brevdo, F. Ashkan: Dear Steve, I have reviewed a quarterly monitoring report for the above site dated August 31, 2011. A free phase plume and gross soil contamination are encountered at this site. Excavation of grossly contaminated soil should be considered. Ground Penetrating Radar Survey proposed by LiRo is approved. Closed in-place tanks should be excavated, if feasible. A tank inventory should be compiled and compared with the PBS records. Discrepancies in the PBS records regarding the tank status should be corrected. LiRo proposed reduction of dissolved phase sampling to semi-annual. Additionally, LiRo proposed that wells MW-10 and RXMW-05, if product free, be sampled for dissolved phase impact. These proposals are approved. AZ 6-11-2012 Reviewed Quarterly Monitoring Report (August through December 2011) and dated February 24, 2012. LiRo will continue use of ORC socks. Removal/excavation of the three to four USTs identified in the Central Dispenser Area and associated contaminated soil. AZ 10-11-12 The following e-mail was sent to S. Frank/F. Ashkan/V. Brevco: Dear Steve, I have reviewed quarterly and semi-annual sampling report for this site. The report stated that free phase product is consistently present in three wells and is intermittent in five wells. LiRo stated that they are planning to remove/excavate the three to four USTs and associated contaminated soil. All associated piping and fill ports should be removed if feasible. LiRo is proposing to reduce EFR events from once a month to once every two months. This proposal is approved. Sincerely, Alexander Zhitomirsky - Engineering Geologist 2 New York State Department of Environmental Conservation 5-9-2013 Reviewed USTs closure reported submitted by LiRo and dated 12/6/2012. According to the report Empire removed and disposed of three previously closed in-place 1,100-gallon single wall gasoline USTs and associated single wall steel piping. One 1,100-gallon UST was not removed due to subsurface conflicts. During sampling, site inspector noticed moderate to strong odors of contamination at both east and west sidewalls. 5 soil samples were taken. Two samples of the three sidewall samples collected exhibited total VOC concentration ranging from 48,700 ppb to 80,650 ppb. Groundwater was encountered and a sample was collected. The sample exhibited a total VOC concentration of 723 ppb. Major site reconstruction activities are planned. AZ 8-24-2013 Reviewed a monitoring report dated 2-6-2013 In September 2012 3 out of four USTs were excavated. A total of 90.1 tons of petroleum impacted soil was removed. Visually impacted soil remained along the east and west sidewalls. Further excavation to the east and west could not be completed due to the presence of an active sewer drain and subsurface electrical utilities. Free-phase product was observed on the groundwater sample surface and analyzed for TPH which identified the material as weathered gasoline. Product is consistently present in three monitoring wells (MW-1, MW-12 and RXMW-03). As a result of pending site construction being completed by NYCDOT, all DDC wells with the exception of RXMW-11 were abandoned in October 2012. THE US EPA well clusters MW-17I/MW-17S, MW-18I/MW18S and MW-19I/MW-19S were not a part of the abandonment plan. AZ 6-29-2015 Reviewed a monitoring report for the period of April 2014 through September 2014. According to the report, the site has undergone extensive construction between 2012 and 2014. It is estimated that 5,000 tons of soil were removed for the construction purposes. As a result of construction, the Site monitoring wells were abandoned in October 2012. This monitoring report is the first post

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

construction report. EFR resumed in four wells in June 2014. Although free phase product was observed during drilling in well RXMW-01R, free phase product has not been measured in this well. Heavy sheen and staining was observed in replacement well LMW-07R. Well RXMW-03 has 0.28' of product. The total VOC concentrations in soil ranged from 16,000 ppb to 505,133 ppb. The total VOC concentrations in groundwater ranged from 30 ppb to 894 ppb. AZ 12-21-2015 Reviewed a monitoring report for the period of October 2014 through March 2015. According to the report, the site has undergone extensive construction between 2012 and 2014. It is estimated that 5,000 tons of soil were removed for the construction purposes. As a result of construction, the Site monitoring wells were abandoned in October 2012. EFR resumed in four wells in June 2014. No EFR was conducted between December 2014 and March 2015 due to the lack of funding. Removal of free-phase product during this time frame was completed via hand bailing. Dissolved SVOCs were reported in eight wells and ranged from 7 ppb to 272 ppb. Heavy sheen and staining was observed in replacement well LMW-07R. Well RXMW-03 has 0.28' of product. Well RXMW-03 has 0.28' of product. The total VOC concentrations in soil ranged from 16,000 ppb to 505,133 ppb. The total VOC concentrations in groundwater ranged from 30 ppb to 894 ppb. AZ 8-12-2016 Reviewed a monitoring report for the period of April 2014 through September 2015. According to the report, the site has undergone extensive construction between 2012 and 2014. It is estimated that 5,000 tons of soil were removed for the construction purposes. As a result of construction, the Site monitoring wells were abandoned in October 2012. EFR is performed in the wells. Removal of free-phase product during this time frame was completed via hand bailing. Dissolved SVOCs were reported in eight wells and ranged from 34 ppb to 184 ppb. Heavy sheen and staining was observed in replacement well LMW-07R. Well RXMW-01r has 0.71' of product. Well RXMW-03 has 0.28' of product. The total VOC concentrations in soil ranged from 16,000 ppb to 505,133 ppb. The total VOC concentrations in groundwater ranged from 18 ppb to 431 ppb. AZ 2-13-2017 Reviewed semi-annual monitoring report for the period of October 2015 through March 2016. According to the report, the site has undergone extensive construction between 2012 and 2014. It is estimated that 5,000 tons of soil were removed for the construction purposes. EFR is performed in wells. Six additional soil borings were advanced in September 2015. Free-phase product and/or petroleum odors were observed in borings/wells LSB-18/MW-9, LSB-12/LMW-12 and LSB-22/LMW-13. The total VOC concentrations in groundwater ranged up to 610 ppb. Thickness of free-phase product in RXMW-05R was 0.12'. AZ 5-1-2017 Reviewed semi-annual monitoring report for the period of April 2016 through September 2016. Free-phase product and/or petroleum odors were observed in borings/wells LSB-18/LMW-9 and LSB-22/LMW-13 (not measurable)in September 2016 gauging. The total VOC concentrations in groundwater ranged up to 377 ppb. AZ 12-4-2017 Reviewed semi-annual monitoring report for the period of October 2016 through March 2017. Free-phase product were observed in RXMW-05R. Product thickness was measured at 0.58' on 3/20/2017. Petroleum sheen was observed in several monitoring wells. AZ 4-11-2018 Reviewed semi-annual monitoring report for the period of April 2017 through September 2017. Free-phase product were observed in RXMW-05R. Product thickness was measured at 0.16' on 9/27/2017. Petroleum sheen was observed in several monitoring wells. EFR has been performed at the site. AZ 1-23-2019 Reviewed semi-annual monitoring report for the period of

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

April 2017 through September 2017. Free-phase product were observed in RXMW-05R. Product thickness ranged from sheen to 0.62' on 3/14/2018. Petroleum sheen was observed in several monitoring wells. EFR has been performed at the site. AZ 8-12-2019 Reviewed semi-annual monitoring report for the period of May 2018 through October 2018. Free-phase product were observed in RXMW-05R, RXMW-3R, RXMW-5R, LMW-07R. Product thickness ranged from sheen to 0.14' on 9/05/2018. EFR has been performed at the site. AZ "

Remarks:

"RECOMMEND THAT TANK BE TAKEN OUT OF SERVICE."

All TTF:

Facility ID: 0302574
Spill Number: 0302574
Spill Tank Test: 1528442
Site ID: 209848
Tank Number: 009
Tank Size: 1080
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 209848
Operable Unit ID: 870311
Operable Unit: 01
Material ID: 2148709
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Site ID: 209848
Operable Unit ID: 870311
Operable Unit: 01
Material ID: 507043
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Name: HAMILTON AVE. YARD (ASPH. PLANT) DOT -DDC
Address: 448 HAMILTON AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9109766 / 2005-01-13
Facility ID: 9109766
Site ID: 209849
Spill Date: 1991-12-11
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: A3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: Allslam
Referred To: 0302574
Reported to Dept: 1991-12-13
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1992-01-06
Spill Record Last Update: 2009-05-21
Spiller Name: Not reported
Spiller Company: NYCDOT HALMINTON YARD
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 271159
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY Tanks were removed. Extensive soil and GW contamination. YK. TRANSFERRED FROM Y.KRIMGOLD. This spill is referred to spill # 0302574 and is closed today as per discussion with Alex. - II (01/13/05)."

Remarks: "THREEM 550'S; WILL REPAIR & RETEST."

All TTF:

Facility ID: 9109766
Spill Number: 9109766
Spill Tank Test: 1539420
Site ID: 209849
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Last Modified Date: Not reported

All Materials:

Site ID: 209849
Operable Unit ID: 963522
Operable Unit: 01
Material ID: 418354
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: NYC DOT ASPHALT PLANT
Address: 448 HAMILTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1000297 / 2010-04-09
Facility ID: 1000297
Facility Type: ER
DER Facility ID: 337883
Site ID: 431459
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2010-04-07
Investigator: jbvought
Referred To: Not reported
Reported to Dept: 2010-04-07
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-04-07
Spill Record Last Update: 2010-04-09
Spiller Name: (917) 337-6234
Spiller Company: NYC DOT
Spiller Address: 448 HAMILTON AVE
Spiller Company: 999
Contact Name: (917) 337-6234
DEC Memo: "4/9/10-Vought-Off hours responder. Called NYCDOS Jon Santos ((917) 337-6234) and left message to return call with potential impact to sewers/drains. Vought received callback from and spoke to Santos and spill from leaking hydraulic line on crane. Line was repaired and spill cleaned using speedy dry and absorbent pads. Spill on concrete

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Remarks: and no sewers or drains affected. Spill closed by Vought."
"DUE TO A LINE BREAK ABOUT 3 GALLONS SPILLED TO PAVEMENT. CLEAN UP IN
PROGRESS."

All Materials:

Site ID: 431459
Operable Unit ID: 1182927
Operable Unit: 01
Material ID: 2177119
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 3.00
Units: G
Recovered: 3.00
Oxygenate: Not reported

Name: NYC DOT ASPHALT PLANT
Address: 448 HAMILTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0707639 / 2008-07-08
Facility ID: 0707639
Facility Type: ER
DER Facility ID: 337883
Site ID: 388368
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401
Spill Date: 2007-10-11
Investigator: jamaison
Referred To: Not reported
Reported to Dept: 2007-10-11
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2007-10-11
Spill Record Last Update: 2008-07-08
Spiller Name: ERICA COZZA
Spiller Company: NYC DOT ASPHALT PLANT
Spiller Address: 448 HAMILTON AVE
Spiller Company: 001
Contact Name: ERICA COZZA
DEC Memo: "2 tanks pulled in sept 2007 - lab results come back with some SVOC

hits. Cross Ref with Spill # 0302574 07/08/08 The tanks are
associated with an Oil/Water Separator near the garage. I visited the
site with representatives from Roux Associates and they will be
responsible for any contamination associated with these tanks. This
spill case will be closed and remediation tracked under spill #

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Remarks: 0302574. - JAM"
"600 AND A 1080 WERE REMOVED AND CONTAMINATED SOIL FROM LAB RESULTS"

All Materials:

Site ID: 388368
Operable Unit ID: 1145543
Operable Unit: 01
Material ID: 2135878
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

Name: NYC DOT ASPHALT PLANT
Address: 448 HAMILTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0812313 / 2010-10-29
Facility ID: 0812313
Facility Type: ER
DER Facility ID: 337883
Site ID: 409929
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401
Spill Date: 2009-02-11
Investigator: jamaison
Referred To: Not reported
Reported to Dept: 2009-02-11
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2009-02-11
Spill Record Last Update: 2010-10-29
Spiller Name: Not reported
Spiller Company: NYC DOT ASPHALT PLANT
Spiller Address: 448 HAMILTON AVE
Spiller Company: 999
Contact Name: ERICA COZZA
DEC Memo: "DDC Case manager: Jerry Aliberti DDC - Div of Structures - 5th Flr.
30-30 Thomson Ave LIC, NY 11101 10/29/10: This entire site, including
area of UST removal mentioned in this spill report, is being
addressed under NYC Vehicle Fueling Facility Order on Consent,
managed by NYC Dept of Design & Construction, with current envt'l
consultant LiRo Engineers, Inc. Investigation and remediation of site
is being tracked under open spill no. 0302574; this spill case is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Remarks: closed to consolidate with that spill. - J. Kolleeny"
"CALLER STATES THAT THEY REMOVED 3 TANKS (2) DIESEL EACH 2500 GALLON
UST AND (1) GASOLINE 1000 GALLON UST. THERE IS IMPACTED SOIL. CLEAN
UP STATUS IS UNK."

All Materials:

Site ID: 409929
Operable Unit ID: 1166421
Operable Unit: 01
Material ID: 2157879
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported

Site ID: 409929
Operable Unit ID: 1166421
Operable Unit: 01
Material ID: 2157880
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported

Name: NYC DOT HAMILTON AVE YARD
Address: 448 HAMILTON AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0506715 / 2005-09-21
Facility ID: 0506715
Facility Type: ER
DER Facility ID: 271159
Site ID: 351978
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2005-08-31
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2005-08-31
CID: 409
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Remediation Phase: 0
Date Entered In Computer: 2005-08-31
Spill Record Last Update: 2005-09-21
Spiller Name: DAVE STERMAN
Spiller Company: NYTA
Spiller Address: 448 HAMILTON AVE
Spiller Company: 999
Contact Name: DAVE STERMAN
DEC Memo: "Sangesland spoke to Tom at Metro Environmental 718-652-0200 He says the tank system failed an ullage test Tank was isolated and passed. Vent line was identified as the problem Franklin 718-762-5200 has been hired to fix the vent line. Sangesland spoke to Bob Laga at the Franklin company. He said the vent line was replaced, but the system still needs to be retested. 9/21/2005 Bob Laga sent an e-mail to Sangesland with new tank test results. Tank was retested and passed."
Remarks: "IT IS A TANK TEST FAILURE. THE VENT LINE ATTACHED TO THE TANK IS BROKEN. THE VENT LINE IS BEING FIXED MY FRANKLIN CONTRACT."

All Materials:

Site ID: 351978
Operable Unit ID: 1109479
Operable Unit: 01
Material ID: 2099504
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: NYCDOT HAMILTON ASPHALT PLANT
Address: 448 HAMILTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0801979 / 2008-09-10
Facility ID: 0801979
Facility Type: ER
DER Facility ID: 337883
Site ID: 398038
DEC Region: 2
Spill Cause: Human Error
Spill Class: Not reported
SWIS: 2401
Spill Date: 2008-05-20
Investigator: jbvought
Referred To: Not reported
Reported to Dept: 2008-05-20
CID: 408
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Remediation Phase: 0
Date Entered In Computer: 2008-05-20
Spill Record Last Update: 2008-09-10
Spiller Name: ANTHONY BORDENCA
Spiller Company: DOT FACILITY
Spiller Address: 448 HAMILTON AVE
Spiller Company: 001
Contact Name: ANTHONY BORDENCA
DEC Memo: "05/20/08-Vought-Off hours responder. Called and spoke to Anthony Bordenca and cause of spill was overfill during delivery by tank truck containing asphalt. As per Bordenca, representative from All Saints Limited (out of Arco Terminal) arrived on site, spoke with operating room and confirmed that delivery was to made to 30,000-gallon tank. Driver went to ASTs and truck and made delivery but purportedly switched the wrong valve so delivery was made to 10000-gallon AST. Spill came out of piping at base of AST and was released into underlying secondary containment basin consisting of concrete walls and gravel bottom. No sewers or drains affected and spill contained as per Bordenca. Vought notified DEC Austin who instructed Vought to notify USCG due to proximity to Gowanus Bay and to perform site visit. Vought notified USCG Command Center PO Huey of spill and noted spill was contained. PO Huey will send out boat on 5/21/08 to confirm no impact to Bay. Onsite was NYCDOT Anthony Bordenca-Plant Manager (Ph:718-369-4246;Fax:718-369-4211), NYCDOT Augustine Montalvo-Environmental Coordinator Ph:212-442-6810;Fax:212-487-8437), NYCDOT Jonathon Santos(Environmental Compliance Analyst Ph:212-513-0130;Fax:212-442-7733), and representatives from All Saints. Vought will return call on 5/21 to obtain information for All Saints. Vought explained to all parties that spill was responsibility of both delivery company and operator as both were onsite and knowledgeable of the the delivery. CSL with one month due date and requiring endpoint samples to be sent to both NYCDOT and All Saints. CSL sent to: Mr. Anthony Bordenca NYCDOT 448 Hamilton Avenue Brooklyn, NY 11232 Fax: (718) 369-4211 Vought called Bordenca and left message to return call with contact for All Saints and update: Vought received call from Bordenca and second address is: Mr Robert St. John All Saints Limited 28 Rolling Hills Drive Ridge, NY 11961 Ph: (516)903-4391 Fax: (631)924-8123 Bordenca stated that All Saints were performing site visits this week to determine scope of work which may begin on Tuesday 5/27. Vought sent letter to both above address with one month due date and faxed copies as well. 05/28/08-Vought-Received call from and spoke to Richard O'Niel (Ph:516-413-7862) who is hired by All Saints Limited and he is working with DOT, DOH and site managers and proposal for cleanup from rim to containment and excavation. Concerns that excavation will not result in clean endpoints due to prior spill. Proposal to excavate to gravel and DEC wil require installation of four soil borings and collection of four soil samples after gravel is reached. Vought also received call from NYCDOT Santos and work will begin on 5/31 and health and safety plan required as per DER-10 but not specifically by Vought. Permeability testing being submitted to DEC Albany as part SPCC and soil analyticals received. 06/16/08-Vought-Received call from and spoke to NYCDOT Santos and asphalt was removed from secondary containment and contractor still being sought for soil borings. Extension granted by Vought till 7/30/08. 07/11/08-Vought-Teleconference set to discuss sampling on 7/11/08 at

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

11:30am. Teleconference with NYCDOT Santos and MTL Labs John Hicks (516-938-7120). Discussion of endpoint samples and separation of containment into four quadrants and one boring will be performed in each quadrant. Samples will be analyzed for 8270 due to asphalt spill. If refusal is encountered borings will be placed between secondary containment and bay. Quote will be submitted to insurance company and email will be sent to DEC of investigation date. 7/31/08-Vought-Received call from and spoke to NYCDOT Santos and approval given for borings. Work scheduled for 8/2. Coordination difficult as vendor signed indemnification clause and oil company (All Saints) is choosing contractor. As per plant supervisor secondary containment consisted of half inch of stone, layer of corrugated steel and asphalt cement. DEC will consider case closure if documentation of secondary containment is submitted. If no documentation found then borings required to ensure no release to soil and or groundwater. 08/01/08-Vought-Teleconference with NYCDOT Santos and engineer Mirza from MTL Labs and excavation will be performed to clean gravel/or secondary containment or clean soil and work scheduled to be performed tomorrow. 08/05/08-Vought-Received proposal from MTL Labs for installation of three soil borings and DEC required: 1)submission of a scaled site plan with locations of borings and corrugated sheet metal. 09/08/08-Vought-Received call and spoke to NYCDOT Santos and MTL arrived onsite and were unprepared. MTL contracted by All Saints Insurance. All Saints brought in independent adjustor and Mike Baldwin wants to discuss site with DEC Vought. Initial asphalt was excavated out and portion of site is not covered and remaining asphalt has solidified after 5 months. As per Santos asphalt was excavated to extent possible due to structural limitations of AST support and walls of secondary containment. Vought reviewed spill with DEC Austin and NFA will be issued as long as well network surrounds asphalt spill to monitor the remote possibility of groundwater contamination increases from asphalt spill. Vought spoke with DEC Maisonave (manager of open spill 0302574) who recently approve installation of wells surrounding asphalt storage area due to BTEX delineation from diesel and fuel oil USTs. Due to high viscosity of asphalt and low leachability of spill and surrounding BTEX and oil plume this spill closed and referred to open spill #0302574. Vought called NYCDOT Santos and faxed spill report to 212-442-7072. "

Remarks: "ENTERED SECONDARY CONTAINMENT; OVERFILL/DRIVER ERROR; MAKING ARRANGEMENTS FOR CLEAN UP;"

All Materials:

Site ID: 398038
Operable Unit ID: 1154949
Operable Unit: 01
Material ID: 2145787
Material Code: 0004
Material Name: asphalt
Case No.: Not reported
Material FA: Petroleum
Quantity: 6331.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: HAMILTON AVE. YARD (ASPH. PLANT) DOT -DDC
Address: 448 HAMILTON AVENUE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9416686 / 2003-11-03
Facility ID: 9416686
Facility Type: ER
DER Facility ID: 271159
Site ID: 209850
DEC Region: 2
Spill Cause: Other
Spill Class: C3
SWIS: 2401
Spill Date: 1995-03-24
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 1995-03-24
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-04-27
Spill Record Last Update: 2005-01-03
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

KRIMGOLD 06/14/95: SPILL CAUSED BY DIESEL WASH DOWN OF ASPHALT PLANT INTO SOILS 0. Investigation and remediation undre spill #9109766. "

Remarks: "HISTORICAL SPILL, ATTN:STEVE MILLER"

All Materials:

Site ID: 209850
Operable Unit ID: 1013795
Operable Unit: 01
Material ID: 371833
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: HAMILTON AVE. YARD (ASPH. PLANT) DOT -DDC
Address: 448 HAMILTON AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9813984 / 2005-01-13
Facility ID: 9813984
Facility Type: ER
DER Facility ID: 271159

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Site ID: 209851
DEC Region: 2
Spill Cause: Unknown
Spill Class: A3
SWIS: 2401
Spill Date: 1999-02-18
Investigator: Allslam
Referred To: 0302574
Reported to Dept: 1999-02-18
CID: 366
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-02-18
Spill Record Last Update: 2009-05-21
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "This spill is referred to spill # 0302574 and is closed today as per discussion with with alex. - II (01/13/05)."
Remarks: "CALLER IS GETTING INFO THIRD PARTY THROUGH FIRE DEPT. A SPILL OF 1000 GALLONS OF GASOLINE FROM AN UNKNOWN VEHICLE. REQ TO CONTACT FIRE DEPT (718) 965-8265. CALLER SAID THEY MIGHT BE ABLE TO GIVE MORE INFO. Also see spill 0302574. "

All Materials:

Site ID: 209851
Operable Unit ID: 1074870
Operable Unit: 01
Material ID: 310692
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 1000.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GOWANUS CANAL
Address: 448 HAMILTON AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9904638 / 1999-07-22
Facility ID: 9904638
Facility Type: ER
DER Facility ID: 271159
Site ID: 209852
DEC Region: 2
Spill Cause: Unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Spill Class: C3
SWIS: 2401
Spill Date: 1999-07-19
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 1999-07-19
CID: 252
Water Affected: GOWANUS CANAL
Spill Source: Unknown
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-07-19
Spill Record Last Update: 1999-08-03
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller Company: 999
Contact Name: KERRI ANN ODOWD
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
KRIMGOLD FAED TO USCG, 718 354-4140. 7/19/99 12:00 HRS. WENT TO DOT
ASPHALT PLANT DUE TO PART OF INVESTIGATION FROM SPILL #9904613. COULD
SEE OIL SHEENING FROM HAMILTON AVE. BRIDGE, CLOSE TO ASPHALT PLANT.
WENT TO NYCDOT HAMILTON AVENUE ASPHALT PLANT AT 448 HAMILTON AVENUE &
14TH ST, BKLYN. WENT TO CANAL, COULD SEE OIL BY CANAL AND TRAPPED
BETWEEN TWO BARGES. 12:20 HRS. CALLED USCG POLLUTION RESPONSE AND
SPOKE TO P.O. SAMPSON AND GAVE THEM UPDATE. 12:25 HRS. CALLED SPILL
HOTLINE SPILL # 9904638. 13:00 HRS. USCG P.O. SUMMERS AND P.O. AVILA
ARRIVE ON SITE. JACOB KRIMGOLD/DEC ALSO ARRIVES ON-SITE. WENT TO
CANAL SAW OIL. IT'S MAINLY A WEATHERED SILVER SHEENING. USCG DEEMS IT
AS UNRECOVERABLE. THERE IS SOME FRESH RAINBOW SHEENING NEAR SOME OF
THE PIERS AT DOT PLANT SIDE (UNRECOVERABLE). POSSIBLE SEEPAGE PROBLEM
WITH DOT ASPHALT PLANT. JACOB HAS 1995 SITE PLAN. THERE WAS A TWO (2)
FOOT PRODUCT PLUME AT DOT ASPHALT PLANT. PRODUCT RECOVERY SYSTEM
INSTALLED, BUT HASN'T BEEN TURNED ON YET. MW-8 (MOST DOWNGRADIENT
WELL) MOST LIKELY DESTROYED, IT'S IN THE APPROXIMATE LOCATION OF
RECENT SEWERS CONSTRUCTION. MW-8 IS APPROX. 200 FT. FROM CANAL. OLD
USTS CLOSED IN PLACE, CLOSE TO OLD PUMP ISLAND, THAT'S STILL IN
PLACE. THERE ARE SANITARY SEWERS IN THE STREET (ALONG HAMILTON AVE.).
REMEDATION SYSTEM MAY HAVE TO BE DISCHARGED TO CITY SEWER, TO AVOID
A LONGER DELAY. WILL NEED MWs DOWNGRADIENT OF PUMP ISLAND AND USTS.
USCG TOOK SAMPLE FROM CANAL. JACOB WILL COORDINATE WITH URS AND USCG
TO SAMPLE MWs AND CANAL (PET. PRODUCT I.D.)/JACOB WILL DO FOLLOW-UP
WITH CITY."
Remarks: "SHEEN ON WATER- COAST GURAD NOTIFIED."
All Materials:
Site ID: 209852
Operable Unit ID: 1079061
Operable Unit: 01
Material ID: 300968
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYC DOT ASPHALT PLANT (Continued)

S109063041

Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

236
NE
1/4-1/2
0.492 mi.
2596 ft.

**498 3RD AVENUE
498 3RD AVENUE
BROOKLYN, NY 11215**

NY LTANKS

**S100167654
N/A**

**Relative:
Higher
Actual:
22 ft.**

LTANKS:

Name: 498 3RD AVENUE
Address: 498 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11215
Spill Number/Closed Date: 8809911 / Not Reported
Facility ID: 8809911
Site ID: 66897
Spill Date: 1989-03-14
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: EJKIM
Referred To: Not reported
Reported to Dept: 1989-03-14
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 1
Date Entered In Computer: 1989-03-29
Spill Record Last Update: 2019-08-30
Spiller Name: Not reported
Spiller Company: CARMELO AUTO REPAIR
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 20999
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill case was reassigned from DEC (Sigona) to Rommel on 01/07/2004. DEC Sigona sent a letter to RP on Jan 23, 1990 with requirements for spill investigation. On May 16, 2002, DEC (Austin) was contacted by Mr. Englemenan (917)747-7702 representative for the owner. He requested to pave over the monitoring wells at the site. DEC (Sigona) called Mr. Engleman on 5/17/02 and left message on answering machine to submit recent groundwater testing results to determine if the spill case could be closed. 3/17/06 This site had documented impacts to groundwater. A complete investigation was

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

498 3RD AVENUE (Continued)

S100167654

needed in 1989. The file does not reflect completion of an investigation. Available data indicates that remediation would have been necessary. Need to establish the current status and determine if site should be in one of the remedial programs. 9/12/2006 This case was transferred from Albany to Region #2. Zhune spoke to Mr. Engleman. He said as soon as he find documentation he will send it. 07/12/12- Zhune spoke to Mr. Englemenann he asked for two days to find the report and send it. 03/14/12-Zhune spoke to Mr. Englemenan. he said he is going to send the closure tank report next week. Mr. Englemenan email- e1462@aol.com ***** 08/16/13-David Engleman sent the following email: I got your e-mail and I am working on it. I will e-mail you the information within a few days G-D willing. 8/30/13-David Engleman sent the following email: As per your request I am attaching a copy of the affidavit for the property 498 3rd Avenue/tanks purged and filled with concrete in 1990 8/26/19 - Spill reassigned to Kim as per Obligado. 8/30/19 - Kim - Spill reclassified from B3 to C3."

Remarks: "(6) 550 GALLON TANKS WERE TESTED BY FIRE DEPT, TANKS ARE LEAKING, LEAK ORDER FOR INVESTIGATION ISSUED BY CITY."

All TTF:

Facility ID: 8809911
Spill Number: 8809911
Spill Tank Test: 1535283
Site ID: 66897
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 66897
Operable Unit ID: 926214
Operable Unit: 01
Material ID: 451084
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AV237
NNE
1/4-1/2
0.492 mi.
2600 ft.
SPILL NUMBER 0300314
124 2ND AVE
BROOKLYN, NY
Site 1 of 4 in cluster AV

NY LTANKS
NY Spills
S102619303
N/A

Relative:
Higher

Actual:
13 ft.

LTANKS:

Name: OLD POST OFFICE
Address: 124 2ND AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9704147 / 2003-09-01
Facility ID: 9704147
Site ID: 156078
Spill Date: 1997-07-02
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: ALKARWIE
Referred To: Not reported
Reported to Dept: 1997-07-08
CID: 297
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1997-07-08
Spill Record Last Update: 2003-09-02
Spiller Name: Not reported
Spiller Company: US GOV'T
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: THOMAS PINO
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 94209
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks:

KARWIEL 9/1/03 - AUSTIN - SPILL CLOSED, AS PER DIRECTIVE FROM ANTHONY KARWIEL IN DER/CENTRAL OFFICE. SEE RELATED SPILL # 9214380 FOR A LIST OF DOCUMENTS THAT SUPPORT CLOSURE FOR BOTH SPILL #S - END"
"THERE ARE 4 10000 GALLON INGROUND FUEL TANKS ON SITE , AT THIS POINT IT IS UNKNOWN WHICH TANK IS LEAKING, BUT SOIL CONTAMINATION HAS BEEN FOUND - KERRI-ANN O'DOWD FROM DEC WAS ON SITE LAST WEDNESDAY AND TOLD CALLER TO NOTIFY DEC SITE BEING HANDLED BY HAZ. WASTE SECTION."

All Materials:

Site ID: 156078
Operable Unit ID: 1050018
Operable Unit: 01
Material ID: 333404
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0300314 (Continued)

S102619303

Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: SPILL NUMBER 0300314
Address: 124 2ND AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0300314 / 2003-04-11
Facility ID: 0300314
Facility Type: ER
DER Facility ID: 94209
Site ID: 107096
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2003-04-09
Investigator: JMROMMEL
Referred To: Not reported
Reported to Dept: 2003-04-09
CID: 205
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-04-09
Spill Record Last Update: 2003-04-11
Spiller Name: Not reported
Spiller Company: 124 2ND AVE
Spiller Address: 124 2ND AVE
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL See 9704147 Site being handled by Haz Waste Section. Community Board directed to contact project manager with questions: Gardiner Cross Engineering Geologist 2 NYSDEC-Division of Environmental Remediation 625 Broadway Albany, NY 12233-7017 518.402.9662"

Remarks: "CONST ON SITE OF OLD GAS STATION, FOUND CONTAMINATED SOIL."

All Materials:

Site ID: 107096
Operable Unit ID: 866395
Operable Unit: 01
Material ID: 571436
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0300314 (Continued)

S102619303

Recovered: .00
Oxygenate: Not reported

AV238
NNE
1/4-1/2
0.492 mi.
2600 ft.

**K - METROPOLITAN MGP
124-136 SECOND AVE
BROOKLYN, NY 11215
Site 2 of 4 in cluster AV**

**NY SHWS
NY BROWNFIELDS**

**S108667326
N/A**

**Relative:
Higher
Actual:
13 ft.**

SHWS:

Name: K - METROPOLITAN MGP
Address: 124-136 SECOND AVE
City,State,Zip: BROOKLYN, NY 11215
Program: HW
Site Code: 372656
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 11
HW Code: 224046
Record Add: 10/27/2006
Record Upd: 04/10/2018
Updated By: GWCROSS

Site Description: Location: The Metropolitan Gas Works site is located at the intersection of 12th Street and Second Avenue in South Brooklyn. It is bounded on the west by the Gowanus Canal, on the north by 10th St., on the east by 2nd Avenue and on the south by 13th St. Site Features: The site is completely developed. The original plant footprint is occupied by a large home improvement center, a strip mall and parking lots that serve them. The surrounding neighborhood is primarily industrial and commercial, with some residential properties within a few blocks. Past use of the site: The site was occupied by a large manufactured gas plant (MGP) from the late 1800s to the late 1930s. The MGP converted coal and petroleum products to gas, which was used for heating, cooking, and lighting purposes in the surrounding areas. The process produced large amounts of coal tar wastes which have heavily contaminated the soils beneath the site. The southeastern portion of the plant was remediated in 2001 to 2003. The remediation consisted of the excavation of 3 gas holders and the installation of a DNAPL recovery system that is currently operating. The western third of the site (where the actual gas plant was located) is now occupied by a multi-story brick commercial building including a Pathmark grocery store. A Remedial Investigation was conducted in this area between 2009 and 2013. Site Geology and Hydrogeology: Soils on the site consist of fill that overlies a peat/silt/clay "meadow mat" marsh deposit that lies approximately 16 feet below ground surface (bgs). Beneath the meadow mat are sand and silt glacial outwash deposit. Bedrock is greater than 150 ft.bgs. Groundwater flow is southwest, toward the Gowanus Canal.

Env Problem: Contaminants of concern The principal waste disposed on the site was MGP tar, which is a dark, oily liquid that is slightly denser than water. Large amounts of this tar escaped from the foundation of the gas holders, and appear to have migrated off site to the south and west of the site. The tar contains high levels of BTEX and PAH compounds. Both groups of compounds have been found in site soils and groundwater. Impacted media Soils and groundwater at the site are

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

K - METROPOLITAN MGP (Continued)

S108667326

heavily impacted by BTEX and PAH compounds. The impacted soils are found at depths of 8-16 feet and greater beneath the Lowe s portion of the property; contaminated soils above this elevation were removed and replaced with clean backfill during the remedial action in 2002. No information is available on the Pathmark portion of the site. However, gross contamination was found within a few feet of the Pathmark foundation and it is likely that significant amounts of soil and groundwater contamination are present in this area also. Known SCG exceedances Soil and groundwater contain BTEX and PAH compounds at levels far in excess of SCGs. These exceedances represent a significant threat to the environment. Special Resources impacted No special resources identified. The adjacent portion of the Gowanus Canal is heavily contaminated from a variety of sources including other MGP sites nearby, but specific impacts from this particular MGP site have not been identified. The off site tar migration appears to be taking place at depths below the bottom of the canal.

Health Problem: Further investigation is needed to assess the nature and extent of site-related contamination and the potential for exposure to site contaminants. The site currently has several buildings and a paved parking lot, therefore, contact with subsurface contamination is unlikely. Exposure to site-related contaminants in groundwater is not expected because the area is served by public water. NYSDOH and NYSDEC will evaluate the need for additional investigations to determine the potential for soil vapor intrusion on the site.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2006-10-31 16:33:00
Record Upd: 2013-09-20 14:14:00
Updated By: Idennist
Own Op: Document Repository
Sub Type: C04
Owner Name: Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 12201-6401
Owner Country: United States of America
HW Code: 224046
Waste Type: BENZENE
Waste Quantity: 26.00
Waste Code: Not reported
HW Code: 224046
Waste Type: BENZENE
Waste Quantity: 26.00
Waste Code: Not reported
HW Code: 224046
Waste Type: BENZENE
Waste Quantity: 26.00
Waste Code: Not reported
HW Code: 224046

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

K - METROPOLITAN MGP (Continued)

S108667326

Waste Type: TOLUENE
Waste Quantity: 3000.00
Waste Code: Not reported
HW Code: 224046
Waste Type: NAPHTHALENE
Waste Quantity: 810.00
Waste Code: Not reported
HW Code: 224046
Waste Type: NAPHTHALENE
Waste Quantity: 810.00
Waste Code: Not reported
HW Code: 224046
Waste Type: NAPHTHALENE
Waste Quantity: 810.00
Waste Code: Not reported
HW Code: 224046
Waste Type: BENZO(A)PYRENE
Waste Quantity: 130.00
Waste Code: Not reported
HW Code: 224046
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: v00405
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2010-01-19 10:10:00
Record Updated: 2010-01-19 10:10:00
Updated By: SMWITHER

BROWNFIELDS:

Name: K - METROPOLITAN MGP
Address: 124-136 SECOND AVE
City,State,Zip: BROOKLYN, NY 11215
Program: BCP
Site Code: 57384
Acres: 7.8
HW Code: C224046
SWIS: 2401
Town: New York City
Record Added Date: 04/30/2004
Record Updated Date: 12/01/2009
Update By: MOBARRIE
Site Description: See Site 224046
Env Problem: Not reported
Health Problem: Not reported
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

K - METROPOLITAN MGP (Continued)

S108667326

Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AV239
NNE
1/4-1/2
0.492 mi.
2600 ft.

METROPOLITAN
124-136 SECOND AVE
BROOKLYN, NY 11215
Site 3 of 4 in cluster AV

NY VCP **S113922091**
N/A

Relative:
Higher
Actual:
13 ft.

VCP:

Name:	METROPOLITAN
Address:	124-136 SECOND AVE
City,State,Zip:	BROOKLYN, NY 11215
Program Type:	VCP
Site Code:	57308
HW Code:	V00695
Site Class:	N
SWIS:	2401
Region:	2
Town:	New York City
Acres:	Not reported
Date Record Added:	11/06/2003
Date Record Updated:	10/30/2006
Updated By:	DKMACNEA
Site Description:	See site 224046
Env Problem:	Not reported
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METROPOLITAN (Continued)

S113922091

Owner Name: Not reported
Owner Company: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Country: Not reported
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

AV240
NNE
1/4-1/2
0.492 mi.
2600 ft.

BU-METROPOLITAN MGP
124-136 SECOND AVE
BROOKLYN, NY 11215
Site 4 of 4 in cluster AV

EDR MGP 1008407883
N/A

Relative:
Higher
Actual:
13 ft.

Manufactured Gas Plants:
No additional information available

241
NNW
1/2-1
0.659 mi.
3479 ft.

FORMER COLUMBIA SMELTING
98 LORRAINE STREET
BROOKLYN, NY 11231

NY SHWS S121933837
N/A

Relative:
Higher
Actual:
14 ft.

SHWS:
Name: FORMER COLUMBIA SMELTING
Address: 98 LORRAINE STREET
City,State,Zip: BROOKLYN, NY 11231
Program: HW
Site Code: 520660
Classification: P
Region: 2
Acres: 4.1699999999999999
HW Code: 224231
Record Add: 01/07/2016
Record Upd: 02/27/2018
Updated By: JHOCONNE
Site Description: Location: The 4.17 acre site is located at 98 Lorraine Street in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site currently consists of a portion of a public park (Red Hook Park) operated by the NYC Department of Parks and Recreation. This portion of the park contains 4 baseball fields (fields 5 through 8). Current Zoning and Land Use: The site is currently zoned as park land and is surrounded by other sections of Red Hook Par, as well as a large public housing development (Red Hook Houses). The site is bounded on the north by Lorraine Street and Red

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER COLUMBIA SMELTING (Continued)

S121933837

Hook Houses, to the east by Henry Street and Red Hook Park, to the south by Bay Street and Red Hook Park, and to the west by Hicks Street and multi-family residential buildings. Past Use of the Site: The site was occupied by a secondary lead smelter operated initially by Delevan Smelting and Refining Works and later by Columbia Smelting and Refining Works from at least 1929 to the late 1930s. By 1939 the smelting building was demolished. The site was redeveloped as part of Red Hook Park some time before 1947. Site Geology and Hydrogeology: Soil sampling has only been performed in the upper 2 feet of soil. Generally the soil consists of fill material. No groundwater samples were collected as part of the investigations to date; therefore depth to groundwater and groundwater flow direction are unknown. The nearest water body (Gowanus Bay) is located approximately 1200 feet to the southeast of the site.

Env Problem: Nature and Extent of Contamination: In 2012 USA Today published an article documenting sampling conducted at the park which showed elevated concentrations of lead in surface soil. As a result of that finding, NYC Parks collected their own samples for analysis, which generally mirrored the results reported by USA Today. NYC Parks and NYC Department of Health and Mental Hygiene performed some limited remediation (soil excavation, import of clean soil over bare soil areas, and hydroseeding). In 2014, USEPA implemented an investigation in support of an emergency removal action. The data below is from the USEPA investigation. Soil In surface soil (0 to 1 below grade) the highest concentration of lead was 980 ppm as compared to the restricted residential soil cleanup objective (RRSCO) of 400 ppm. In the 1 to 6 interval, the highest concentration was 2400 ppm. At depth (6 to 24 below grade) the highest concentration was 5700 ppm on-site and 8300 ppm off-site to the south. Other metals including antimony, arsenic, iron, copper and tin were found in association with the lead. USEPA concluded that the ratios of the various metals to lead were indicative of the smelting process as opposed to exclusively being attributed to historic fill. Groundwater No groundwater samples have been collected. Soil Vapor No soil vapor samples have been collected.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Not reported
Sub Type: Not reported
Owner Name: Not reported
Owner Company: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER COLUMBIA SMELTING (Continued)

S121933837

Owner Country: Not reported
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

242
NW
1/2-1
0.672 mi.
3546 ft.

ROBINS DRYDOCK
NO CITY, NY

FUDS 1024899191
N/A

Relative:
Higher

Actual:
8 ft.

FUDS:
EPA Region: 2
Installation ID: NY29799F741400
Congressional District Number: 10
Facility Name: ROBINS DRYDOCK
FUDS Number: C02NY0027
City: NO CITY
State: NY
County: Not reported
USACE District: New England District (NAE)
Status: Properties without projects
Current Owner: Private Sector
EMS Map Link: <https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=56486>
Eligibility: Eligible
Has Projects: No
NPL Status: Not Listed
X Coord: -74.009444439999896
Y Coord: 40.671111109999998
Latitude: 40.671111109999998
Longitude: -74.009444439999996

243
North
1/2-1
0.772 mi.
4075 ft.

FORMER CITIZEN GAS WORKS MGP SITE (CAROL
5TH STREET AND SMITH STREET TO GOWANUS CANAL
BROOKLYN, NY 11215

EDR MGP 1008407888
N/A

Relative:
Higher

Actual:
22 ft.

Manufactured Gas Plants:
No additional information available

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

244
North
1/2-1
0.834 mi.
4403 ft.

**CARROLL GARDENS
CORNER OF 5TH STREET & SMITH STREET
BROOKLYN, NY**

**NY DEL SHWS S105972444
N/A**

**Relative:
Higher**

DEL SHWS:

**Actual:
37 ft.**

Name: CARROLL GARDENS
Address: CORNER OF 5TH STREET & SMITH STREET
City,State,Zip: BROOKLYN, NY
Year: Not reported
Site Code Id: 224012
Site Classification: D1
Region: 2
Epa Id Number: Not reported
Site Type - Dump: No
Site Type - Structure: No
Site Type - Lagoon: No
Site Type - Landfill: No
Site Type - Treat Pond: No
Site Size (Acres): 6 Acres
Site Size Comment: Not reported
Period Assoc/HW Start: Not reported
Period Assoc/HW End: Not reported
Lat/Long: 40 40' 33 / 73 59' 46
Lat/Long Decimal: 0.00000 / 0.00000
Lat/Long (dms): 0 0 0 / 0 0 0
Hazardous Waste Code: Not reported
Hazard Waste Disposed: Not reported
Quantity: Not reported
Air Data Available: No
SW Std Contravention: No
GW Std Contravention: No
Soil Type: Not reported
Sediment Data Available: No
GW Std Contravention: No
DW Std Contravention: No
SW Std Contravention: No
Air Stand Contraventions: No
Legal Action Type: Not reported
State Legal Action: No
Federal Legal Action: No
Enforce Status Code: Not reported
Remedial Act Proposed: No
Rem Act Under Design: No
Rem Act In Progress: No
Rem Act Completed: No
Remedial Action Type: Not reported
Soil Type: Not reported
Depth To Groundwater: Not reported
Owner Name: NYC Department of Real Property
Owner Address: 2 Lafayette Street
Owner City,St,Zip: New York, NY 10007
Owner Phone: Not reported
Owner Contact Name: Not reported
Owner During Disposal: Not reported
Owner During Use: Not reported
Operator Name: Not reported
Operator Address: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CARROLL GARDENS (Continued)

S105972444

Operator City,St,Zip:	Not reported
Operator Phone:	Not reported
Operator Contact Name:	Not reported
Oper During Disposal:	Not reported
Site Type:	Dump
HW Disposal Period:	From: unknown To:
Analytical Data Available:	Groundwater, Surface Water, Soil
Applicable Std Exceeded:	Groundwater, Surface Water
Geotech Info:	Sand and till.
Depth To Groundwater:	Range: 10 to 20 feet.
Status:	Not reported
Nature Of Action:	Not reported
Env Prob Assessment:	Not reported
Site Description:	This site was formerly owned by the Brooklyn Union Gas Company, which operated a coal gasification plant. It is believed that products from previous operations may have been disposed at this site. The site is currently vacant and located in a mixed industrial/residential area. Single family homes and a concrete product manufacturing plant are adjacent to the site. At one time, residential housing was proposed for construction at this location. The lot is littered with debris piles, cinder blocks, old lumber and at least fourteen 55-gallon drums embedded in concrete. The NYSDEC has received the final Phase II site investigation report, but is awaiting the analytical results of the sampling of the 55 gallon drums disposed on site. These drums were sampled separately in December 1990. Analytical data for the 3 drums sampled in 1990 revealed that the waste present in the drums originated from a petroleum hydrocarbon source and is not classified as hazardous waste.
Confirmed HW:	Methylene Chloride: unknown
Environment Assesment:	Environmental problems not established.
Health Assesment:	Not reported
Disposal Start Date:	Not reported
Disposal Term Date:	Not reported
Air Violation:	Not reported
Groundwater Violation:	Not reported
Drink Water Violation:	Not reported
Surface Water Violation:	Not reported
Legal New York State:	Not reported
Legal Federal:	Not reported
Legal State:	Not reported
Remedial Action Active:	Not reported
Remedial Action Done:	Not reported
NPL Status:	Not reported
Count Operator:	Not reported
Count Owner:	Not reported
NYTM X:	0
NYTM Y:	0
Co Name:	Not reported
Co Addr:	Not reported
Operator Addr:	Not reported
Operator Addr 2:	Not reported
Operator Addr 3:	Not reported
Operator Addr 4:	Not reported
HWD From:	Not reported
From To:	Not reported
Assessment of Health:	Not reported
Description:	Not reported
Record Added Date:	Not reported
Record Updated Date:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CARROLL GARDENS (Continued)

S105972444

Env Assessment: Not reported
HW Disposed/Quantity: Not reported
Assess/Env Prog: Not reported
Assess/Health Prob: Not reported
Site Description: Not reported

245
NNE
1/2-1
0.866 mi.
4572 ft.

PATTERSON CHEMICAL CO INC
102 3RD ST
BROOKLYN, NY 11231

CORRACTS
RCRA NonGen / NLR
FINDS
ECHO

1000403436
NYD980592471

Relative:
Higher

Actual:
17 ft.

CORRACTS:

EPA ID: NYD980592471
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 1994-09-20 00:00:00.0
Action: CA050 - RFA Completed
NAICS Code(s): 49311 48411
General Warehousing and Storage
General Freight Trucking, Local
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD980592471
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 1994-05-27 00:00:00.0
Action: CA075LO - CA Prioritization, Facility or area was assigned a low
corrective action priority
NAICS Code(s): 49311 48411
General Warehousing and Storage
General Freight Trucking, Local
Original schedule date: 1994-07-01 00:00:00.0
Schedule end date: Not reported

EPA ID: NYD980592471
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 1993-11-19 00:00:00.0
Action: CA010 - RFA Initiation
NAICS Code(s): 49311 48411
General Warehousing and Storage
General Freight Trucking, Local
Original schedule date: Not reported
Schedule end date: Not reported

RCRA NonGen / NLR:

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: PATTERSON CHEMICAL CO INC
Facility address: 102 3RD ST
BROOKLYN, NY 11231
EPA ID: NYD980592471
Mailing address: 3RD ST
BROOKLYN, NY 11231
Contact: MOE STONE
Contact address: 3RD ST

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PATTERSON CHEMICAL CO INC (Continued)

1000403436

BROOKLYN, NY 11231
Contact country: US
Contact telephone: 718-855-7676
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: ACE TERMINALS
Owner/operator address: 102 3RD ST
BROOKLYN, NY 11231
Owner/operator country: US
Owner/operator telephone: 212-855-7676
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PATTERSON CHEMICAL CO INC
Owner/operator address: 102 THIRD STREET
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: 212-855-7676
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: Yes
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: PATTERSON CHEMICAL CO INC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PATTERSON CHEMICAL CO INC (Continued)

1000403436

Classification: Not a generator, verified

Date form received by agency: 1980-11-19 00:00:00.0

Site name: PATTERSON CHEMICAL CO INC

Classification: Not a generator, verified

Date form received by agency: 1980-07-25 00:00:00.0

Site name: PATTERSON CHEMICAL CO INC

Classification: Not a generator, verified

Date form received by agency: 1979-12-31 00:00:00.0

Site name: PATTERSON CHEMICAL CO INC

Classification: Not a generator, verified

Hazardous Waste Summary:

. Waste code: D000

. Waste name: Not Defined

. Waste code: D001

. Waste name: IGNITABLE WASTE

. Waste code: D002

. Waste name: CORROSIVE WASTE

. Waste code: D003

. Waste name: REACTIVE WASTE

. Waste code: F001

. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002

. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003

. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PATTERSON CHEMICAL CO INC (Continued)

1000403436

MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F005
- . Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: F006
- . Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

- . Waste code: F007
- . Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

- . Waste code: F008
- . Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

- . Waste code: F009
- . Waste name: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

- . Waste code: F010
- . Waste name: QUENCHING BATH RESIDUES FROM OIL BATHS FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

- . Waste code: F012
- . Waste name: QUENCHING WASTEWATER TREATMENT SLUDGES FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

- . Waste code: F017
- . Waste name: Not Defined

- . Waste code: F018
- . Waste name: Not Defined

- . Waste code: K086
- . Waste name: SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.

- . Waste code: P030
- . Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

- . Waste code: U101

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PATTERSON CHEMICAL CO INC (Continued)

1000403436

Waste name: 2,4-DIMETHYLPHENOL (OR) PHENOL, 2,4-DIMETHYL-

Corrective Action Summary:

Event date: 1993-11-19 00:00:00.0

Event: RFA INITIATION

Event date: 1994-05-27 00:00:00.0

Event: CA PRIORITIZATION-LOW CA PRIORITY

Event date: 1994-09-20 00:00:00.0

Event: RFA COMPLETED

Violation Status: No violations found

FINDS:

Registry ID: 110004387814

Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110004387814

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000403436

Registry ID: 110004387814

DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110004387814>

Name: PATTERSON CHEMICAL CO INC

Address: 102 3RD ST

City,State,Zip: BROOKLYN, NY 11231

246
SE
1/2-1
0.901 mi.
4755 ft.

**EVER NU METAL
471 20TH STREET
BROOKLYN, NY 11215**

**NY SHWS S121933826
N/A**

**Relative:
Higher**

SHWS:

Name: EVER NU METAL
Address: 471 20TH STREET
City,State,Zip: BROOKLYN, NY 11215

Program: HW
Site Code: 492522
Classification: N
Region: 2
Acres: 0.31
HW Code: 224187
Record Add: 03/13/2014
Record Upd: 02/21/2018
Updated By: JXGRECO

Site Description: Location: The 13,700 square foot (0.31 acre) site is located at 471 20th Street in the Borough of Brooklyn in an urban area. The site is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EVER NU METAL (Continued)

S121933826

bordered by 20th Street and Greenwood Cemetery to the south, an institutional building (Diocese of Brooklyn) to the east and north, residential buildings to the north, and a parking lot and additional commercial/industrial uses to the west. Site transitioned to Brownfield Cleanup Program as Site #C224187. Please refer to that site number for accurate information.

Env Problem: Site transitioned to Brownfield Cleanup Program as Site #C224187. Please refer to that site number for accurate information.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported

Structure: Not reported

Lagoon: Not reported

Landfill: Not reported

Pond: Not reported

Disp Start: Not reported

Disp Term: Not reported

Lat/Long: Not reported

Dell: Not reported

Record Add: Not reported

Record Upd: Not reported

Updated By: Not reported

Own Op: On-Site Operator

Sub Type: E

Owner Name: Not reported

Owner Company: Ever Nu Metal Products Co., Inc.

Owner Address: 471 20th Street

Owner Addr2: Not reported

Owner City,St,Zip: Brooklyn, NY 11215

Owner Country: United States of America

Own Op: Owner

Sub Type: E

Owner Name: Rocco Gagliardi

Owner Company: EDCA Realty Corp

Owner Address: 417 20th Street

Owner Addr2: Not reported

Owner City,St,Zip: Brooklyn, NY 11215

Owner Country: United States of America

HW Code: Not reported

Waste Type: Not reported

Waste Quantity: Not reported

Waste Code: Not reported

Crossref ID: Not reported

Cross Ref Type Code: Not reported

Cross Ref Type: Not reported

Record Added Date: Not reported

Record Updated: Not reported

Updated By: Not reported

Count: 12 records.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S113917066	BROOKLYN MILITARY OCEAN TERMINAL	2ND AVE BTWN 57TH, 65TH STREET	11232	NY SHWS
BROOKLYN	S105003695	USPS GOWANUS SITE, FORMER MGP METR	2ND AVENUE AND 12TH STREET	11215	NY VCP
BROOKLYN	S113916585	DAVIDSON PIPE SUPPLY COMPANY	3RD AVE & 37TH STREET		NY SHWS
BROOKLYN	S105841746	NYCDOS @ 52ND ST. BROOKLYN	52ND STREET & N. Y. BAY	11232	NY SWF/LF
BROOKLYN	S113922111	455 SMITH STREET (VICHAR, INC.)	5TH STREET & SMITH STREET TO G	11231	NY VCP
BROOKLYN	1003864070	CARROL GARDEN	CORNER OF 5TH AND SMITH STREET	11231	SEMS-ARCHIVE
BROOKLYN	1000407436	NORTHEAST MARINE TERMINAL CO INC	FOOT OF 39TH ST	11232	CORRACTS, RCRA NonGen / NLR
BROOKLYN	S105972442	HAMILTON AVENUE PIERS/19TH & 18TH	REAR OF 566 HAMILTON AVENUE	11232	NY SHWS
BROOKLYN	S113922162	DANGMAN PARK	SHEEPSHEAD BAY ROAD & WEST 5TH	11215	NY VCP
BROOKLYN	S102143752	BROOKLYN CONCRETE RECYCLING; INC./	SMITH STREET	11231	NY SWF/LF, NY Spills
BROOKLYN	S102148323	20TH STREET	UNK. FAC. ON 20TH AVE		NY Spills
BROOKLYN	S102141358	STAPLETON ANCHORAGE	NY UPPER BAY		NY LTANKS, NY Spills

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 01/30/2020	Source: EPA
Date Data Arrived at EDR: 02/05/2020	Telephone: N/A
Date Made Active in Reports: 02/14/2020	Last EDR Contact: 03/04/2020
Number of Days to Update: 9	Next Scheduled EDR Contact: 04/13/2020
	Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 01/30/2020	Source: EPA
Date Data Arrived at EDR: 02/05/2020	Telephone: N/A
Date Made Active in Reports: 02/14/2020	Last EDR Contact: 03/04/2020
Number of Days to Update: 9	Next Scheduled EDR Contact: 04/13/2020
	Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 01/30/2020
Date Data Arrived at EDR: 02/05/2020
Date Made Active in Reports: 02/14/2020
Number of Days to Update: 9

Source: EPA
Telephone: N/A
Last EDR Contact: 03/04/2020
Next Scheduled EDR Contact: 04/13/2020
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 04/03/2019
Date Data Arrived at EDR: 04/05/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 01/03/2020
Next Scheduled EDR Contact: 04/13/2020
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly known as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 01/30/2020
Date Data Arrived at EDR: 02/05/2020
Date Made Active in Reports: 02/14/2020
Number of Days to Update: 9

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 02/05/2020
Next Scheduled EDR Contact: 04/27/2020
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 01/30/2020	Source: EPA
Date Data Arrived at EDR: 02/05/2020	Telephone: 800-424-9346
Date Made Active in Reports: 02/14/2020	Last EDR Contact: 03/04/2020
Number of Days to Update: 9	Next Scheduled EDR Contact: 04/27/2020
	Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/16/2019	Source: EPA
Date Data Arrived at EDR: 12/16/2019	Telephone: 800-424-9346
Date Made Active in Reports: 12/20/2019	Last EDR Contact: 02/27/2020
Number of Days to Update: 4	Next Scheduled EDR Contact: 04/06/2020
	Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/16/2019	Source: Environmental Protection Agency
Date Data Arrived at EDR: 12/16/2019	Telephone: (212) 637-3660
Date Made Active in Reports: 12/20/2019	Last EDR Contact: 02/27/2020
Number of Days to Update: 4	Next Scheduled EDR Contact: 04/06/2020
	Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/16/2019	Source: Environmental Protection Agency
Date Data Arrived at EDR: 12/16/2019	Telephone: (212) 637-3660
Date Made Active in Reports: 12/20/2019	Last EDR Contact: 02/27/2020
Number of Days to Update: 4	Next Scheduled EDR Contact: 04/06/2020
	Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/16/2019	Source: Environmental Protection Agency
Date Data Arrived at EDR: 12/16/2019	Telephone: (212) 637-3660
Date Made Active in Reports: 12/20/2019	Last EDR Contact: 02/27/2020
Number of Days to Update: 4	Next Scheduled EDR Contact: 04/06/2020
	Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/16/2019	Source: Environmental Protection Agency
Date Data Arrived at EDR: 12/16/2019	Telephone: (212) 637-3660
Date Made Active in Reports: 12/20/2019	Last EDR Contact: 02/27/2020
Number of Days to Update: 4	Next Scheduled EDR Contact: 04/06/2020
	Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 11/04/2019	Source: Department of the Navy
Date Data Arrived at EDR: 11/13/2019	Telephone: 843-820-7326
Date Made Active in Reports: 01/28/2020	Last EDR Contact: 02/10/2020
Number of Days to Update: 76	Next Scheduled EDR Contact: 05/25/2020
	Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 11/22/2019	Source: Environmental Protection Agency
Date Data Arrived at EDR: 11/22/2019	Telephone: 703-603-0695
Date Made Active in Reports: 01/28/2020	Last EDR Contact: 02/20/2020
Number of Days to Update: 67	Next Scheduled EDR Contact: 06/08/2020
	Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 11/22/2019	Source: Environmental Protection Agency
Date Data Arrived at EDR: 11/22/2019	Telephone: 703-603-0695
Date Made Active in Reports: 01/28/2020	Last EDR Contact: 02/20/2020
Number of Days to Update: 67	Next Scheduled EDR Contact: 06/08/2020
	Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/16/2019

Date Data Arrived at EDR: 12/19/2019

Date Made Active in Reports: 03/06/2020

Number of Days to Update: 78

Source: National Response Center, United States Coast Guard

Telephone: 202-267-2180

Last EDR Contact: 12/19/2019

Next Scheduled EDR Contact: 04/06/2020

Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 11/11/2019

Date Data Arrived at EDR: 11/12/2019

Date Made Active in Reports: 01/17/2020

Number of Days to Update: 66

Source: Department of Environmental Conservation

Telephone: 518-402-9622

Last EDR Contact: 02/12/2020

Next Scheduled EDR Contact: 05/25/2020

Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 10/09/2019

Date Data Arrived at EDR: 10/10/2019

Date Made Active in Reports: 12/18/2019

Number of Days to Update: 69

Source: Department of Environmental Conservation

Telephone: 518-402-8678

Last EDR Contact: 03/02/2021

Next Scheduled EDR Contact: 04/12/2020

Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/03/2019

Date Data Arrived at EDR: 12/04/2019

Date Made Active in Reports: 02/14/2020

Number of Days to Update: 72

Source: EPA Region 8

Telephone: 303-312-6271

Last EDR Contact: 01/24/2020

Next Scheduled EDR Contact: 05/04/2020

Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 10/11/2019

Date Data Arrived at EDR: 12/04/2019

Date Made Active in Reports: 02/10/2020

Number of Days to Update: 68

Source: EPA Region 10

Telephone: 206-553-2857

Last EDR Contact: 01/24/2020

Next Scheduled EDR Contact: 05/04/2020

Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/02/2019
Date Data Arrived at EDR: 12/04/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 68

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 01/24/2020
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 10/10/2019
Date Data Arrived at EDR: 12/05/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 67

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 01/24/2020
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 10/15/2019
Date Data Arrived at EDR: 12/17/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 55

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 12/16/2019
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/01/2019
Date Data Arrived at EDR: 12/04/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 68

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/24/2020
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 10/01/2019
Date Data Arrived at EDR: 12/04/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 68

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 01/24/2020
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 10/04/2019
Date Data Arrived at EDR: 12/04/2019
Date Made Active in Reports: 02/27/2020
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 01/24/2020
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: Varies

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 11/11/2019
Date Data Arrived at EDR: 11/11/2019
Date Made Active in Reports: 11/13/2019
Number of Days to Update: 2

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/07/2020
Next Scheduled EDR Contact: 05/25/2020
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 08/27/2019
Date Data Arrived at EDR: 08/28/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 75

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 01/21/2020
Next Scheduled EDR Contact: 04/20/2020
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 12/18/2019
Date Data Arrived at EDR: 12/19/2019
Date Made Active in Reports: 03/02/2020
Number of Days to Update: 74

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/19/2019
Next Scheduled EDR Contact: 04/06/2020
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 12/18/2019
Date Data Arrived at EDR: 12/19/2019
Date Made Active in Reports: 03/02/2020
Number of Days to Update: 74

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/19/2019
Next Scheduled EDR Contact: 04/06/2020
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 12/18/2019
Date Data Arrived at EDR: 12/19/2019
Date Made Active in Reports: 03/02/2020
Number of Days to Update: 74

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/19/2019
Next Scheduled EDR Contact: 04/06/2020
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 12/18/2019
Date Data Arrived at EDR: 12/19/2019
Date Made Active in Reports: 03/02/2020
Number of Days to Update: 74

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/19/2019
Next Scheduled EDR Contact: 04/06/2020
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 10/11/2019
Date Data Arrived at EDR: 12/04/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 68

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/24/2020
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/01/2019
Date Data Arrived at EDR: 12/04/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 68

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/24/2020
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 10/10/2019	Source: EPA Region 4
Date Data Arrived at EDR: 12/05/2019	Telephone: 404-562-9424
Date Made Active in Reports: 02/10/2020	Last EDR Contact: 01/24/2020
Number of Days to Update: 67	Next Scheduled EDR Contact: 05/04/2020
	Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 10/01/2019	Source: EPA Region 5
Date Data Arrived at EDR: 12/04/2019	Telephone: 312-886-6136
Date Made Active in Reports: 02/10/2020	Last EDR Contact: 01/24/2020
Number of Days to Update: 68	Next Scheduled EDR Contact: 05/04/2020
	Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 10/02/2019	Source: EPA Region 6
Date Data Arrived at EDR: 12/04/2019	Telephone: 214-665-7591
Date Made Active in Reports: 02/10/2020	Last EDR Contact: 01/24/2020
Number of Days to Update: 68	Next Scheduled EDR Contact: 05/04/2020
	Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 10/11/2019	Source: EPA Region 7
Date Data Arrived at EDR: 12/04/2019	Telephone: 913-551-7003
Date Made Active in Reports: 02/10/2020	Last EDR Contact: 01/24/2020
Number of Days to Update: 68	Next Scheduled EDR Contact: 05/04/2020
	Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/03/2019	Source: EPA Region 8
Date Data Arrived at EDR: 12/04/2019	Telephone: 303-312-6137
Date Made Active in Reports: 02/14/2020	Last EDR Contact: 01/24/2020
Number of Days to Update: 72	Next Scheduled EDR Contact: 05/04/2020
	Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/04/2019	Source: EPA Region 9
Date Data Arrived at EDR: 12/04/2019	Telephone: 415-972-3368
Date Made Active in Reports: 02/27/2020	Last EDR Contact: 01/24/2020
Number of Days to Update: 85	Next Scheduled EDR Contact: 05/04/2020
	Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TANKS: Storage Tank Facility Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 12/18/2019	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 12/19/2019	Telephone: 518-402-9543
Date Made Active in Reports: 03/02/2020	Last EDR Contact: 12/19/2019
Number of Days to Update: 74	Next Scheduled EDR Contact: 04/06/2020
	Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 12/16/2019	Source: New York City Department of City Planning
Date Data Arrived at EDR: 12/17/2019	Telephone: 212-720-3300
Date Made Active in Reports: 03/02/2020	Last EDR Contact: 12/16/2019
Number of Days to Update: 76	Next Scheduled EDR Contact: 03/30/2020
	Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 12/16/2019	Source: NYC Department of City Planning
Date Data Arrived at EDR: 12/16/2019	Telephone: 212-720-3401
Date Made Active in Reports: 03/02/2020	Last EDR Contact: 12/16/2019
Number of Days to Update: 77	Next Scheduled EDR Contact: 03/30/2020
	Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 11/11/2019	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 11/12/2019	Telephone: 518-402-9553
Date Made Active in Reports: 01/17/2020	Last EDR Contact: 02/12/2020
Number of Days to Update: 66	Next Scheduled EDR Contact: 05/25/2020
	Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 11/11/2019	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 11/12/2019	Telephone: 518-402-9553
Date Made Active in Reports: 01/17/2020	Last EDR Contact: 02/12/2020
Number of Days to Update: 66	Next Scheduled EDR Contact: 05/25/2020
	Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 11/11/2019
Date Data Arrived at EDR: 11/12/2019
Date Made Active in Reports: 01/17/2020
Number of Days to Update: 66

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 02/12/2020
Next Scheduled EDR Contact: 05/25/2020
Data Release Frequency: Semi-Annually

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 64

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 03/16/2020
Next Scheduled EDR Contact: 06/29/2020
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 12/17/2019
Next Scheduled EDR Contact: 04/06/2020
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 11/11/2019
Date Data Arrived at EDR: 11/12/2019
Date Made Active in Reports: 01/17/2020
Number of Days to Update: 66

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 02/12/2020
Next Scheduled EDR Contact: 05/25/2020
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a \$200 million Environmental Restoration or Brownfields Fund as part of the \$1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 11/11/2019
Date Data Arrived at EDR: 11/12/2019
Date Made Active in Reports: 01/17/2020
Number of Days to Update: 66

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/12/2020
Next Scheduled EDR Contact: 05/25/2020
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 12/02/2019	Source: Environmental Protection Agency
Date Data Arrived at EDR: 12/16/2019	Telephone: 202-566-2777
Date Made Active in Reports: 03/06/2020	Last EDR Contact: 12/16/2019
Number of Days to Update: 81	Next Scheduled EDR Contact: 03/30/2020
	Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 04/06/2018	Telephone: 518-402-8694
Date Made Active in Reports: 06/08/2018	Last EDR Contact: 03/09/2020
Number of Days to Update: 63	Next Scheduled EDR Contact: 06/22/2020
	Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 10/09/2019	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 10/10/2019	Telephone: 518-402-8678
Date Made Active in Reports: 12/18/2019	Last EDR Contact: 03/02/2020
Number of Days to Update: 69	Next Scheduled EDR Contact: 04/13/2020
	Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998	Source: Environmental Protection Agency
Date Data Arrived at EDR: 12/03/2007	Telephone: 703-308-8245
Date Made Active in Reports: 01/24/2008	Last EDR Contact: 01/27/2020
Number of Days to Update: 52	Next Scheduled EDR Contact: 05/11/2020
	Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985	Source: Environmental Protection Agency
Date Data Arrived at EDR: 08/09/2004	Telephone: 800-424-9346
Date Made Active in Reports: 09/17/2004	Last EDR Contact: 06/09/2004
Number of Days to Update: 39	Next Scheduled EDR Contact: N/A
	Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/17/2020
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Services, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 01/31/2020
Next Scheduled EDR Contact: 05/11/2020
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 06/11/2019
Date Data Arrived at EDR: 06/13/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/21/2020
Next Scheduled EDR Contact: 06/08/2020
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 11/11/2019
Date Data Arrived at EDR: 11/12/2019
Date Made Active in Reports: 01/17/2020
Number of Days to Update: 66

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/12/2020
Next Scheduled EDR Contact: 05/25/2020
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 06/11/2019
Date Data Arrived at EDR: 06/13/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/21/2020
Next Scheduled EDR Contact: 06/08/2020
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 02/07/2020
Next Scheduled EDR Contact: 05/18/2020
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Local Lists of Registered Storage Tanks

SUFFOLK CO TANKS: Storage Tank Database

Facilities that have no tank information

Date of Government Version: 06/28/2018

Date Data Arrived at EDR: 02/05/2019

Date Made Active in Reports: 03/08/2019

Number of Days to Update: 31

Source: Department of Health Services

Telephone: 631-854-2516

Last EDR Contact: 01/27/2020

Next Scheduled EDR Contact: 05/11/2020

Data Release Frequency: Varies

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002

Date Data Arrived at EDR: 06/02/2006

Date Made Active in Reports: 07/20/2006

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9549

Last EDR Contact: 10/23/2006

Next Scheduled EDR Contact: 01/22/2007

Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002

Date Data Arrived at EDR: 06/02/2006

Date Made Active in Reports: 07/20/2006

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9549

Last EDR Contact: 10/23/2006

Next Scheduled EDR Contact: 01/22/2007

Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 11/04/2019

Date Data Arrived at EDR: 11/05/2019

Date Made Active in Reports: 01/14/2020

Number of Days to Update: 70

Source: Office of the State Comptroller

Telephone: 518-474-9034

Last EDR Contact: 03/02/2020

Next Scheduled EDR Contact: 05/18/2020

Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 01/30/2020

Date Data Arrived at EDR: 02/05/2020

Date Made Active in Reports: 02/14/2020

Number of Days to Update: 9

Source: Environmental Protection Agency

Telephone: 202-564-6023

Last EDR Contact: 03/05/2020

Next Scheduled EDR Contact: 04/13/2020

Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/05/2019
Date Data Arrived at EDR: 12/06/2019
Date Made Active in Reports: 02/14/2020
Number of Days to Update: 70

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 12/06/2019
Next Scheduled EDR Contact: 04/06/2020
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 11/11/2019
Date Data Arrived at EDR: 11/11/2019
Date Made Active in Reports: 11/13/2019
Number of Days to Update: 2

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/07/2020
Next Scheduled EDR Contact: 05/25/2020
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/16/2019
Date Data Arrived at EDR: 12/16/2019
Date Made Active in Reports: 12/20/2019
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 02/27/2020
Next Scheduled EDR Contact: 04/06/2020
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 11/12/2019
Date Data Arrived at EDR: 11/19/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 70

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 02/19/2020
Next Scheduled EDR Contact: 06/01/2020
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 01/10/2020
Next Scheduled EDR Contact: 04/20/2020
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 01/09/2020
Next Scheduled EDR Contact: 04/20/2020
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 02/13/2020
Next Scheduled EDR Contact: 05/25/2020
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 12/16/2019
Date Data Arrived at EDR: 12/19/2019
Date Made Active in Reports: 02/27/2020
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 12/19/2019
Next Scheduled EDR Contact: 04/06/2020
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/21/2014	Telephone: 617-520-3000
Date Made Active in Reports: 06/17/2014	Last EDR Contact: 02/03/2020
Number of Days to Update: 88	Next Scheduled EDR Contact: 05/18/2020
	Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017	Source: Environmental Protection Agency
Date Data Arrived at EDR: 05/08/2018	Telephone: 703-308-4044
Date Made Active in Reports: 07/20/2018	Last EDR Contact: 02/07/2020
Number of Days to Update: 73	Next Scheduled EDR Contact: 05/18/2020
	Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016	Source: EPA
Date Data Arrived at EDR: 06/21/2017	Telephone: 202-260-5521
Date Made Active in Reports: 01/05/2018	Last EDR Contact: 12/20/2019
Number of Days to Update: 198	Next Scheduled EDR Contact: 03/30/2020
	Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2017	Source: EPA
Date Data Arrived at EDR: 11/16/2018	Telephone: 202-566-0250
Date Made Active in Reports: 11/21/2019	Last EDR Contact: 02/05/2020
Number of Days to Update: 370	Next Scheduled EDR Contact: 06/01/2020
	Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 05/01/2019	Source: EPA
Date Data Arrived at EDR: 10/23/2019	Telephone: 202-564-4203
Date Made Active in Reports: 01/15/2020	Last EDR Contact: 01/24/2020
Number of Days to Update: 84	Next Scheduled EDR Contact: 05/04/2020
	Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/30/2020	Source: EPA
Date Data Arrived at EDR: 02/05/2020	Telephone: 703-416-0223
Date Made Active in Reports: 02/14/2020	Last EDR Contact: 03/04/2020
Number of Days to Update: 9	Next Scheduled EDR Contact: 06/15/2020
	Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/25/2019	Source: Environmental Protection Agency
Date Data Arrived at EDR: 05/02/2019	Telephone: 202-564-8600
Date Made Active in Reports: 05/23/2019	Last EDR Contact: 01/21/2020
Number of Days to Update: 21	Next Scheduled EDR Contact: 05/04/2020
	Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995	Source: EPA
Date Data Arrived at EDR: 07/03/1995	Telephone: 202-564-4104
Date Made Active in Reports: 08/07/1995	Last EDR Contact: 06/02/2008
Number of Days to Update: 35	Next Scheduled EDR Contact: 09/01/2008
	Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 01/30/2020	Source: EPA
Date Data Arrived at EDR: 02/06/2020	Telephone: 202-564-6023
Date Made Active in Reports: 02/14/2020	Last EDR Contact: 03/04/2020
Number of Days to Update: 8	Next Scheduled EDR Contact: 05/18/2020
	Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 10/09/2019	Source: EPA
Date Data Arrived at EDR: 10/11/2019	Telephone: 202-566-0500
Date Made Active in Reports: 12/20/2019	Last EDR Contact: 01/10/2020
Number of Days to Update: 70	Next Scheduled EDR Contact: 04/20/2020
	Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016	Source: Environmental Protection Agency
Date Data Arrived at EDR: 11/23/2016	Telephone: 202-564-2501
Date Made Active in Reports: 02/10/2017	Last EDR Contact: 01/06/2020
Number of Days to Update: 79	Next Scheduled EDR Contact: 04/20/2020
	Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009	Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Date Data Arrived at EDR: 04/16/2009	Telephone: 202-566-1667
Date Made Active in Reports: 05/11/2009	Last EDR Contact: 08/18/2017
Number of Days to Update: 25	Next Scheduled EDR Contact: 12/04/2017
	Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009	Source: EPA
Date Data Arrived at EDR: 04/16/2009	Telephone: 202-566-1667
Date Made Active in Reports: 05/11/2009	Last EDR Contact: 08/18/2017
Number of Days to Update: 25	Next Scheduled EDR Contact: 12/04/2017
	Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 10/25/2019	Source: Nuclear Regulatory Commission
Date Data Arrived at EDR: 10/25/2019	Telephone: 301-415-7169
Date Made Active in Reports: 01/15/2020	Last EDR Contact: 01/21/2020
Number of Days to Update: 82	Next Scheduled EDR Contact: 05/04/2020
	Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2018	Source: Department of Energy
Date Data Arrived at EDR: 12/04/2019	Telephone: 202-586-8719
Date Made Active in Reports: 01/15/2020	Last EDR Contact: 03/06/2020
Number of Days to Update: 42	Next Scheduled EDR Contact: 06/15/2020
	Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/05/2019	Telephone: N/A
Date Made Active in Reports: 11/11/2019	Last EDR Contact: 02/27/2020
Number of Days to Update: 251	Next Scheduled EDR Contact: 06/15/2020
	Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019	Source: Environmental Protection Agency
Date Data Arrived at EDR: 11/06/2019	Telephone: 202-566-0517
Date Made Active in Reports: 02/10/2020	Last EDR Contact: 02/07/2020
Number of Days to Update: 96	Next Scheduled EDR Contact: 05/18/2020
	Data Release Frequency: Varies

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019	Source: Environmental Protection Agency
Date Data Arrived at EDR: 07/01/2019	Telephone: 202-343-9775
Date Made Active in Reports: 09/23/2019	Last EDR Contact: 12/20/2019
Number of Days to Update: 84	Next Scheduled EDR Contact: 04/13/2020
	Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/01/2007	Telephone: 202-564-2501
Date Made Active in Reports: 04/10/2007	Last EDR Contact: 12/17/2007
Number of Days to Update: 40	Next Scheduled EDR Contact: 03/17/2008
	Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/01/2007	Telephone: 202-564-2501
Date Made Active in Reports: 04/10/2007	Last EDR Contact: 12/17/2008
Number of Days to Update: 40	Next Scheduled EDR Contact: 03/17/2008
	Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transportation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 10/01/2019	Source: Department of Transportation, Office of Pipeline Safety
Date Data Arrived at EDR: 10/29/2019	Telephone: 202-366-4595
Date Made Active in Reports: 01/15/2020	Last EDR Contact: 01/28/2020
Number of Days to Update: 78	Next Scheduled EDR Contact: 05/11/2020
	Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 01/17/2020
Date Made Active in Reports: 03/06/2020
Number of Days to Update: 49

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/06/2020
Next Scheduled EDR Contact: 04/20/2020
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 02/27/2020
Next Scheduled EDR Contact: 04/06/2020
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/07/2020
Next Scheduled EDR Contact: 04/20/2020
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 01/31/2020
Next Scheduled EDR Contact: 05/18/2020
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 02/21/2020
Next Scheduled EDR Contact: 06/01/2020
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/30/2020
Date Data Arrived at EDR: 02/05/2020
Date Made Active in Reports: 02/14/2020
Number of Days to Update: 9

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 03/04/2020
Next Scheduled EDR Contact: 04/13/2020
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931 and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 12/03/2019
Date Data Arrived at EDR: 12/03/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 56

Source: DOL, Mine Safety & Health Admini
Telephone: 202-693-9424
Last EDR Contact: 03/02/2020
Next Scheduled EDR Contact: 06/15/2020
Data Release Frequency: Quarterly

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 11/06/2019
Date Data Arrived at EDR: 11/25/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 64

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 02/25/2020
Next Scheduled EDR Contact: 06/08/2020
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/28/2020
Next Scheduled EDR Contact: 06/08/2020
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011	Source: USGS
Date Data Arrived at EDR: 06/08/2011	Telephone: 703-648-7709
Date Made Active in Reports: 09/13/2011	Last EDR Contact: 02/28/2020
Number of Days to Update: 97	Next Scheduled EDR Contact: 06/08/2020
	Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 12/09/2019	Source: Department of Interior
Date Data Arrived at EDR: 12/11/2019	Telephone: 202-208-2609
Date Made Active in Reports: 02/27/2020	Last EDR Contact: 03/05/2020
Number of Days to Update: 78	Next Scheduled EDR Contact: 06/22/2020
	Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/22/2019	Source: EPA
Date Data Arrived at EDR: 12/04/2019	Telephone: (212) 637-3000
Date Made Active in Reports: 03/02/2020	Last EDR Contact: 03/03/2020
Number of Days to Update: 89	Next Scheduled EDR Contact: 06/15/2020
	Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2017	Source: Department of Defense
Date Data Arrived at EDR: 01/17/2019	Telephone: 703-704-1564
Date Made Active in Reports: 04/01/2019	Last EDR Contact: 01/13/2020
Number of Days to Update: 74	Next Scheduled EDR Contact: 04/27/2020
	Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 01/05/2020	Source: Environmental Protection Agency
Date Data Arrived at EDR: 01/07/2020	Telephone: 202-564-2280
Date Made Active in Reports: 03/06/2020	Last EDR Contact: 01/07/2020
Number of Days to Update: 59	Next Scheduled EDR Contact: 04/20/2020
	Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 07/26/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 02/21/2020
Next Scheduled EDR Contact: 06/08/2020
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 11/18/2019
Date Data Arrived at EDR: 11/19/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 70

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/19/2020
Next Scheduled EDR Contact: 06/01/2020
Data Release Frequency: Quarterly

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 08/14/2019
Date Data Arrived at EDR: 08/14/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 01/08/2020
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 10/09/2019
Date Data Arrived at EDR: 10/10/2019
Date Made Active in Reports: 12/18/2019
Number of Days to Update: 69

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 02/28/2020
Next Scheduled EDR Contact: 04/13/2020
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 07/12/2019
Date Data Arrived at EDR: 12/09/2019
Date Made Active in Reports: 02/06/2020
Number of Days to Update: 59

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 03/09/2020
Next Scheduled EDR Contact: 06/22/2020
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 08/05/2019
Date Data Arrived at EDR: 09/19/2019
Date Made Active in Reports: 11/22/2019
Number of Days to Update: 64

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 12/16/2019
Next Scheduled EDR Contact: 03/30/2020
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/02/2019
Date Made Active in Reports: 09/06/2019
Number of Days to Update: 66

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 02/06/2020
Next Scheduled EDR Contact: 04/13/2020
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 03/01/2019
Date Data Arrived at EDR: 03/19/2019
Date Made Active in Reports: 06/18/2019
Number of Days to Update: 91

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 03/09/2020
Next Scheduled EDR Contact: 06/22/2020
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 05/01/2019
Date Made Active in Reports: 06/21/2019
Number of Days to Update: 51

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 01/31/2020
Next Scheduled EDR Contact: 05/11/2020
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 11/14/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/17/2020
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 01/21/2020
Next Scheduled EDR Contact: 05/04/2020
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/01/2018
Date Data Arrived at EDR: 02/13/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 120

Source: Department of Environmental Conservation
Telephone: 518-402-9814
Last EDR Contact: 02/14/2020
Next Scheduled EDR Contact: 05/25/2020
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 12/02/2019
Date Data Arrived at EDR: 12/05/2019
Date Made Active in Reports: 02/06/2020
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 03/04/2020
Next Scheduled EDR Contact: 06/15/2020
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 10/15/2019
Date Data Arrived at EDR: 10/16/2019
Date Made Active in Reports: 12/20/2019
Number of Days to Update: 65

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 01/15/2020
Next Scheduled EDR Contact: 04/27/2020
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 02/28/2020
Next Scheduled EDR Contact: 06/08/2020
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/27/2020
Next Scheduled EDR Contact: 05/11/2020
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/27/2020
Next Scheduled EDR Contact: 05/11/2020
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/26/2020
Next Scheduled EDR Contact: 05/10/2020
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/27/2020
Next Scheduled EDR Contact: 05/11/2020
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County

A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 01/27/2020
Next Scheduled EDR Contact: 05/11/2020
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/26/2020
Next Scheduled EDR Contact: 05/10/2020
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/27/2020
Next Scheduled EDR Contact: 05/11/2020
Data Release Frequency: Varies

ROCKLAND COUNTY:

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AST - ROCKLAND: Petroleum Bulk Storage Database

A listing of aboveground storage tank sites located in Rockland County. Rockland County's Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017

Date Data Arrived at EDR: 03/17/2017

Date Made Active in Reports: 09/22/2017

Number of Days to Update: 189

Source: Rockland County Health Department

Telephone: 914-364-2605

Last EDR Contact: 03/02/2020

Next Scheduled EDR Contact: 06/15/2020

Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database

A listing of underground storage tank sites located in Rockland County. Rockland County's Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017

Date Data Arrived at EDR: 03/17/2017

Date Made Active in Reports: 09/22/2017

Number of Days to Update: 189

Source: Rockland County Health Department

Telephone: 914-364-2605

Last EDR Contact: 03/02/2020

Next Scheduled EDR Contact: 06/15/2020

Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database

A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018

Date Data Arrived at EDR: 12/06/2018

Date Made Active in Reports: 02/07/2019

Number of Days to Update: 63

Source: Suffolk County Department of Health Services

Telephone: 631-854-2521

Last EDR Contact: 01/27/2020

Next Scheduled EDR Contact: 05/11/2020

Data Release Frequency: No Update Planned

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018

Date Data Arrived at EDR: 12/06/2018

Date Made Active in Reports: 02/07/2019

Number of Days to Update: 63

Source: Suffolk County Department of Health Services

Telephone: 631-854-2521

Last EDR Contact: 01/27/2020

Next Scheduled EDR Contact: 05/11/2020

Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 01/31/2020

Date Data Arrived at EDR: 02/11/2020

Date Made Active in Reports: 02/14/2020

Number of Days to Update: 3

Source: Westchester County Department of Health

Telephone: 914-813-5161

Last EDR Contact: 01/27/2020

Next Scheduled EDR Contact: 05/11/2020

Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 01/31/2020

Date Data Arrived at EDR: 02/11/2020

Date Made Active in Reports: 02/14/2020

Number of Days to Update: 3

Source: Westchester County Department of Health

Telephone: 914-813-5161

Last EDR Contact: 01/27/2020

Next Scheduled EDR Contact: 05/11/2020

Data Release Frequency: Semi-Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 01/30/2020
Date Data Arrived at EDR: 01/30/2020
Date Made Active in Reports: 03/09/2020
Number of Days to Update: 39

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 01/30/2020
Next Scheduled EDR Contact: 05/25/2020
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 01/06/2020
Next Scheduled EDR Contact: 04/20/2020
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 01/14/2020
Next Scheduled EDR Contact: 04/07/2020
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 10/02/2019
Date Made Active in Reports: 12/10/2019
Number of Days to Update: 69

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 02/18/2020
Next Scheduled EDR Contact: 06/01/2020
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 01/13/2020
Next Scheduled EDR Contact: 04/27/2020
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/09/2020
Next Scheduled EDR Contact: 06/22/2020
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Oil/Gas Pipelines

Source: Endeavor Business Media

Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data

Source: Endeavor Business Media

This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers

Source: Department of Health

Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.

Source: FEMA

Telephone: 877-336-2627

Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands

Source: Department of Environmental Conservation

Telephone: 518-402-8961

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK[®] - PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

74 20TH STREET
74 20TH STREET
BROOKLYN, NY 11232

TARGET PROPERTY COORDINATES

Latitude (North):	40.665057 - 40° 39' 54.21"
Longitude (West):	73.998697 - 73° 59' 55.31"
Universal Transverse Mercator:	Zone 18
UTM X (Meters):	584638.9
UTM Y (Meters):	4501847.0
Elevation:	7 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5940597 BROOKLYN, NY
Version Date:	2013
Northwest Map:	6048959 JERSEY CITY, NJ
Version Date:	2014

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General WNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

<u>Flood Plain Panel at Target Property</u>	<u>FEMA Source Type</u>
3604970211F	FEMA FIRM Flood data
<u>Additional Panels in search area:</u>	<u>FEMA Source Type</u>
3604970192F	FEMA FIRM Flood data
3604970073B	FEMA Q3 Flood data
3604970194F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

<u>NWI Quad at Target Property</u>	<u>NWI Electronic Data Coverage</u>
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1 - 2 Miles NNE
Site Name:	Vidan Auto Salvage
Site EPA ID Number:	NYD986961167
Groundwater Flow Direction:	SW TOWARD THE NARROWS.
Inferred Depth to Water:	approximately 38 feet.
Hydraulic Connection:	The surficial aquifer and underlying aquifer are hydraulically connected.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information is inferred in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

<u>MAP ID</u>	<u>LOCATION FROM TP</u>	<u>GENERAL DIRECTION GROUNDWATER FLOW</u>
Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era: Mesozoic
System: Cretaceous
Series: Upper Cretaceous
Code: uK (decoded above as Era, System & Series)

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
Layer	Boundary		Soil Texture Class	Classification		Permeability Rate (in/hr)	Soil Reaction (pH)
	Upper	Lower		AASHTO Group	Unified Soil		
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

<u>DATABASE</u>	<u>SEARCH DISTANCE (miles)</u>
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

<u>MAP ID</u>	<u>WELL ID</u>	<u>LOCATION FROM TP</u>

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	USGS40000828020	1/4 - 1/2 Mile North
A2	USGS40000828021	1/4 - 1/2 Mile North
B3	USGS40000828019	1/4 - 1/2 Mile NE
B4	USGS40000828018	1/4 - 1/2 Mile NE
5	USGS40000827905	1/4 - 1/2 Mile East
6	USGS40000828002	1/4 - 1/2 Mile WNW
C7	USGS40000828124	1/2 - 1 Mile NNE
C8	USGS40000828125	1/2 - 1 Mile NNE
9	USGS40000828165	1/2 - 1 Mile NNE
D10	USGS40000828183	1/2 - 1 Mile NNW
11	USGS40000828092	1/2 - 1 Mile NE
12	USGS40000827412	1/2 - 1 Mile WSW
D13	USGS40000828193	1/2 - 1 Mile NNW
E14	USGS40000828115	1/2 - 1 Mile NE
E15	USGS40000828117	1/2 - 1 Mile NE
16	USGS40000828265	1/2 - 1 Mile North
F17	USGS40000828200	1/2 - 1 Mile NNW
F18	USGS40000828254	1/2 - 1 Mile NNW
19	USGS40000828114	1/2 - 1 Mile NE
20	USGS40000827039	1/2 - 1 Mile SSW
21	USGS40000828120	1/2 - 1 Mile NE
G22	USGS40000827036	1/2 - 1 Mile SW
23	USGS40000828297	1/2 - 1 Mile NNE
G24	USGS40000827028	1/2 - 1 Mile SW
25	USGS40000828275	1/2 - 1 Mile NNW
26	USGS40000828339	1/2 - 1 Mile NNW
27	USGS40000828070	1/2 - 1 Mile ENE
28	USGS40000827037	1/2 - 1 Mile SW
29	USGS40000827051	1/2 - 1 Mile SW
30	USGS40000828170	1/2 - 1 Mile NE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

PHYSICAL SETTING SOURCE MAP - 6012679.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons

- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME: 74 20th Street
 ADDRESS: 74 20th Street
 Brooklyn NY 11232
 LAT/LONG: 40.665057 / 73.998697

CLIENT: Roux Associates
 CONTACT: Frank Cherena
 INQUIRY #: 6012679.2s
 DATE: March 17, 2020 2:02 pm

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

A1
North
1/4 - 1/2 Mile
Higher

FED USGS USGS40000828020

Organization ID: USGS-NY
Monitor Location: K 2512. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 152

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

A2
North
1/4 - 1/2 Mile
Higher

FED USGS USGS40000828021

Organization ID: USGS-NY
Monitor Location: K 2513. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 130

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

B3
NE
1/4 - 1/2 Mile
Higher

FED USGS USGS40000828019

Organization ID: USGS-NY
Monitor Location: K 1010. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 181

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

B4
NE
1/4 - 1/2 Mile
Higher

FED USGS USGS40000828018

Organization ID: USGS-NY
Monitor Location: K 639. 1
Description: 4001
Drainage Area: Not Reported

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: 176
Well Hole Depth: 190

Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: ft
Well Hole Depth Units: ft

5 East 1/4 - 1/2 Mile Higher

FED USGS USGS40000827905

Organization ID: USGS-NY
Monitor Location: K 907. 1
Description: 2301
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Northern Atlantic Coastal Plain aquifer system
Formation Type: Glacial Aquifer, Upper
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 130

6 WNW 1/4 - 1/2 Mile Lower

FED USGS USGS40000828002

Organization ID: USGS-NY
Monitor Location: K 701. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 83

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

C7 NNE 1/2 - 1 Mile Higher

FED USGS USGS40000828124

Organization ID: USGS-NY
Monitor Location: K 638. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 175

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

C8
NNE
1/2 - 1 Mile
Higher

FED USGS USGS40000828125

Organization ID: USGS-NY
Monitor Location: K 1332. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 168

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

9
NNE
1/2 - 1 Mile
Lower

FED USGS USGS40000828165

Organization ID: USGS-NY
Monitor Location: K 9. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 159

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

D10
NNW
1/2 - 1 Mile
Higher

FED USGS USGS40000828183

Organization ID: USGS-NY
Monitor Location: K 720. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 103

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

11
NE
1/2 - 1 Mile
Higher

FED USGS USGS40000828092

Organization ID: USGS-NY
Monitor Location: K 650. 1
Description: Not Reported
Drainage Area: Not Reported

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 195

Contrib Drainage Area Units: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

12
WSW
1/2 - 1 Mile
Lower

FED USGS USGS40000827412

Organization ID: USGS-NY
Monitor Location: K 698. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 100

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Units: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

D13
NNW
1/2 - 1 Mile
Higher

FED USGS USGS40000828193

Organization ID: USGS-NY
Monitor Location: K 1091. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 124

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Units: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

E14
NE
1/2 - 1 Mile
Higher

FED USGS USGS40000828115

Organization ID: USGS-NY
Monitor Location: K 916. 1
Description: 2101
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 162

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Units: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

E15

NE
1/2 - 1 Mile
Higher

FED USGS USGS40000828117

Organization ID: USGS-NY
Monitor Location: K 920. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 164

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

16

North
1/2 - 1 Mile
Higher

FED USGS USGS40000828265

Organization ID: USGS-NY
Monitor Location: K 1536. 1
Description: 5001
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 156

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

F17

NNW
1/2 - 1 Mile
Higher

FED USGS USGS40000828200

Organization ID: USGS-NY
Monitor Location: K 700. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 116

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

F18

NNW
1/2 - 1 Mile
Higher

FED USGS USGS40000828254

Organization ID: USGS-NY
Monitor Location: K 1069. 1
Description: Not Reported
Drainage Area: Not Reported

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Units:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system	Aquifer Type:	Not Reported
Formation Type:	Glacial Aquifer, Upper	Well Depth:	60
Construction Date:	Not Reported	Well Hole Depth:	Not Reported
Well Depth Units:	ft		
Well Hole Depth Units:	Not Reported		

Ground water levels, Number of Measurements:	55	Level reading date:	1980-03-13
Feet below surface:	Not Reported	Feet to sea level:	1.31
Note:	Not Reported		
Level reading date:	1979-12-18	Feet below surface:	Not Reported
Feet to sea level:	2.00	Note:	Not Reported
Level reading date:	1979-09-17	Feet below surface:	Not Reported
Feet to sea level:	1.80	Note:	Not Reported
Level reading date:	1979-06-28	Feet below surface:	Not Reported
Feet to sea level:	2.50	Note:	Not Reported
Level reading date:	1979-03-26	Feet below surface:	Not Reported
Feet to sea level:	1.89	Note:	Not Reported
Level reading date:	1978-12-22	Feet below surface:	Not Reported
Feet to sea level:	1.49	Note:	Not Reported
Level reading date:	1978-10-02	Feet below surface:	Not Reported
Feet to sea level:	1.88	Note:	Not Reported
Level reading date:	1978-06-23	Feet below surface:	Not Reported
Feet to sea level:	2.80	Note:	Not Reported
Level reading date:	1978-04-04	Feet below surface:	Not Reported
Feet to sea level:	2.97	Note:	Not Reported
Level reading date:	1978-01-03	Feet below surface:	Not Reported
Feet to sea level:	2.73	Note:	Not Reported
Level reading date:	1977-10-13	Feet below surface:	Not Reported
Feet to sea level:	2.65	Note:	Not Reported
Level reading date:	1977-07-07	Feet below surface:	Not Reported
Feet to sea level:	2.34	Note:	Not Reported
Level reading date:	1977-03-28	Feet below surface:	Not Reported
Feet to sea level:	1.43	Note:	Not Reported
Level reading date:	1976-12-22	Feet below surface:	Not Reported
Feet to sea level:	1.84	Note:	Not Reported
Level reading date:	1976-09-23	Feet below surface:	Not Reported
Feet to sea level:	2.10	Note:	Not Reported
Level reading date:	1976-06-28	Feet below surface:	Not Reported
Feet to sea level:	2.40	Note:	Not Reported
Level reading date:	1976-03-23	Feet below surface:	Not Reported
Feet to sea level:	2.35	Note:	Not Reported
Level reading date:	1975-12-30	Feet below surface:	Not Reported
Feet to sea level:	2.33	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1975-10-08	Feet below surface:	Not Reported
Feet to sea level:	2.57	Note:	Not Reported
Level reading date:	1975-06-30	Feet below surface:	Not Reported
Feet to sea level:	2.29	Note:	Not Reported
Level reading date:	1975-03-26	Feet below surface:	Not Reported
Feet to sea level:	2.27	Note:	Not Reported
Level reading date:	1974-12-20	Feet below surface:	Not Reported
Feet to sea level:	2.38	Note:	Not Reported
Level reading date:	1974-09-05	Feet below surface:	Not Reported
Feet to sea level:	2.44	Note:	Not Reported
Level reading date:	1973-10-02	Feet below surface:	Not Reported
Feet to sea level:	2.57	Note:	Not Reported
Level reading date:	1973-07-09	Feet below surface:	Not Reported
Feet to sea level:	0.23	Note:	Not Reported
Level reading date:	1973-04-03	Feet below surface:	Not Reported
Feet to sea level:	0.56	Note:	Not Reported
Level reading date:	1972-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.07	Note:	Not Reported
Level reading date:	1972-10-03	Feet below surface:	Not Reported
Feet to sea level:	0.50	Note:	Not Reported
Level reading date:	1972-07-11	Feet below surface:	Not Reported
Feet to sea level:	0.30	Note:	Not Reported
Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	0.90	Note:	Not Reported
Level reading date:	1972-01-13	Feet below surface:	Not Reported
Feet to sea level:	1.86	Note:	Not Reported
Level reading date:	1971-09-27	Feet below surface:	Not Reported
Feet to sea level:	2.81	Note:	Not Reported
Level reading date:	1971-03-08	Feet below surface:	Not Reported
Feet to sea level:	2.01	Note:	Not Reported
Level reading date:	1970-10-30	Feet below surface:	Not Reported
Feet to sea level:	1.94	Note:	Not Reported
Level reading date:	1970-03-13	Feet below surface:	Not Reported
Feet to sea level:	1.75	Note:	Not Reported
Level reading date:	1969-11-10	Feet below surface:	Not Reported
Feet to sea level:	0.99	Note:	Not Reported
Level reading date:	1969-09-03	Feet below surface:	Not Reported
Feet to sea level:	1.05	Note:	Not Reported
Level reading date:	1968-11-06	Feet below surface:	Not Reported
Feet to sea level:	1.43	Note:	Not Reported
Level reading date:	1968-04-23	Feet below surface:	Not Reported
Feet to sea level:	1.43	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1967-10-23	Feet below surface:	Not Reported
Feet to sea level:	1.46	Note:	Not Reported
Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	1.61	Note:	Not Reported
Level reading date:	1966-10-25	Feet below surface:	Not Reported
Feet to sea level:	-0.78	Note:	Not Reported
Level reading date:	1966-05-04	Feet below surface:	Not Reported
Feet to sea level:	1.46	Note:	Not Reported
Level reading date:	1965-10-27	Feet below surface:	Not Reported
Feet to sea level:	1.59	Note:	Not Reported
Level reading date:	1965-09-14	Feet below surface:	Not Reported
Feet to sea level:	1.72	Note:	Not Reported
Level reading date:	1965-05-04	Feet below surface:	Not Reported
Feet to sea level:	1.88	Note:	Not Reported
Level reading date:	1964-11-02	Feet below surface:	Not Reported
Feet to sea level:	1.28	Note:	Not Reported
Level reading date:	1964-04-23	Feet below surface:	Not Reported
Feet to sea level:	1.32	Note:	Not Reported
Level reading date:	1963-04-25	Feet below surface:	Not Reported
Feet to sea level:	1.75	Note:	Not Reported
Level reading date:	1961-12-28	Feet below surface:	Not Reported
Feet to sea level:	1.76	Note:	Not Reported
Level reading date:	1960-09-09	Feet below surface:	Not Reported
Feet to sea level:	0.73	Note:	Not Reported
Level reading date:	1960-01-11	Feet below surface:	Not Reported
Feet to sea level:	0.82	Note:	Not Reported
Level reading date:	1954-12-17	Feet below surface:	Not Reported
Feet to sea level:	0.06	Note:	Not Reported
Level reading date:	1953-12-23	Feet below surface:	Not Reported
Feet to sea level:	-0.11	Note:	Not Reported
Level reading date:	1953-01-15	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported

**19
NE
1/2 - 1 Mile
Higher**

FED USGS USGS40000828114

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 648. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Well Hole Depth: 197

Well Hole Depth Units: ft

20
SSW
1/2 - 1 Mile
Higher

FED USGS USGS40000827039

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 922. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system	Formation Type:	Not Reported
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	150
Well Hole Depth Units:	ft		

21
NE
1/2 - 1 Mile
Higher

FED USGS USGS40000828120

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 646. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	194	Well Hole Depth Units:	ft

G22
SW
1/2 - 1 Mile
Higher

FED USGS USGS40000827036

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 167. 1	Type:	Well
Description:	3801	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	150	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

23
NNE
1/2 - 1 Mile
Higher

FED USGS USGS40000828297

Organization ID: USGS-NY
Monitor Location: K 10.1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: 75
Well Hole Depth: Not Reported

Organization Name: USGS New York Water Science Center
Type: Well
HUC: Not Reported
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: ft
Well Hole Depth Units: Not Reported

Ground water levels, Number of Measurements: 268
Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1943-02-27
Feet to sea level: -15.45

Level reading date: 1943-01-30
Feet to sea level: -16.47

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1943-01-02
Feet to sea level: -17.14

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-12-26
Feet to sea level: -16.81

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-12-19
Feet to sea level: -17.58

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-12-12
Feet to sea level: -17.11

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-12-05
Feet to sea level: -17.86

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-11-28
Feet to sea level: -17.51

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-11-21
Feet to sea level: -17.69

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-11-14
Feet to sea level: -17.74

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-11-07
Feet to sea level: -18.28

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-10-31
Feet to sea level: -17.56

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-10-24
Feet to sea level: -17.95

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-10-17
Feet to sea level: -18.01

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-10-10

Feet below surface: Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Feet to sea level:	-17.84	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-18.25	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-17.93	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-18.53	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-18.21	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-18.13	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-17.85	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-18.39	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-17.77	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-17.92	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-17.94	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-17.83	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-17.65	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-18.21	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-17.52	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-17.90	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-17.38	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-17.50	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-17.40	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-16.97	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-17.15	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-16.95	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-17.27	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-16.65	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-16.46	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-16.43	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-16.58	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-15.97	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-16.55	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-15.93	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-16.51	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-16.42	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-16.78	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-16.11	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-16.90	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-15.95	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-16.19	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-16.19	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-16.43	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-16.13	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-16.49	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-16.25	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-16.63	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-16.19	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-17.01	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-17.26	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-15.77	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-16.66	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-16.80	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-16.95	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-16.82	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-16.83	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-17.08	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-17.32	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-17.09	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-17.69	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-17.50	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-17.85	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-16.93	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-17.13	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-17.04	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-16.85	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-17.05	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-17.17	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-16.93	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-16.35	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-16.70	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-16.35	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-16.71	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-16.15	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-16.42	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-15.77	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-16.17	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-15.69	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-16.38	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-16.43	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-15.86	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-15.45	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-15.46	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-15.14	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-15.00	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-15.41	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-15.63	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-14.35	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-14.18	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-14.25	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-13.98	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-13.98	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-14.43	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-15.04	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-14.73	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-14.56	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-14.28	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-14.14	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-14.92	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-14.34	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-13.64	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-14.75	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-14.41	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-14.70	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-14.95	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-15.36	Note:	Not Reported
Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-14.90	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-15.09	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-15.24	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1940-10-05	Feet below surface:	Not Reported
Feet to sea level:	-15.31	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-16.60	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-15.69	Note:	Not Reported
Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-15.94	Note:	Not Reported
Level reading date:	1940-09-07	Feet below surface:	Not Reported
Feet to sea level:	-15.55	Note:	Not Reported
Level reading date:	1940-08-31	Feet below surface:	Not Reported
Feet to sea level:	-16.17	Note:	Not Reported
Level reading date:	1940-08-24	Feet below surface:	Not Reported
Feet to sea level:	-16.14	Note:	Not Reported
Level reading date:	1940-08-17	Feet below surface:	Not Reported
Feet to sea level:	-15.50	Note:	Not Reported
Level reading date:	1940-08-10	Feet below surface:	Not Reported
Feet to sea level:	-15.43	Note:	Not Reported
Level reading date:	1940-08-03	Feet below surface:	Not Reported
Feet to sea level:	-15.47	Note:	Not Reported
Level reading date:	1940-07-27	Feet below surface:	Not Reported
Feet to sea level:	-15.44	Note:	Not Reported
Level reading date:	1940-07-20	Feet below surface:	Not Reported
Feet to sea level:	-14.86	Note:	Not Reported
Level reading date:	1940-07-13	Feet below surface:	Not Reported
Feet to sea level:	-15.18	Note:	Not Reported
Level reading date:	1940-07-06	Feet below surface:	Not Reported
Feet to sea level:	-14.88	Note:	Not Reported
Level reading date:	1940-06-29	Feet below surface:	Not Reported
Feet to sea level:	-14.50	Note:	Not Reported
Level reading date:	1940-06-22	Feet below surface:	Not Reported
Feet to sea level:	-14.66	Note:	Not Reported
Level reading date:	1940-06-15	Feet below surface:	Not Reported
Feet to sea level:	-15.15	Note:	Not Reported
Level reading date:	1940-06-08	Feet below surface:	Not Reported
Feet to sea level:	-14.43	Note:	Not Reported
Level reading date:	1940-06-01	Feet below surface:	Not Reported
Feet to sea level:	-14.12	Note:	Not Reported
Level reading date:	1940-05-25	Feet below surface:	Not Reported
Feet to sea level:	-14.15	Note:	Not Reported
Level reading date:	1940-05-18	Feet below surface:	Not Reported
Feet to sea level:	-14.28	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1940-05-11	Feet below surface:	Not Reported
Feet to sea level:	-13.94	Note:	Not Reported
Level reading date:	1940-05-04	Feet below surface:	Not Reported
Feet to sea level:	-13.96	Note:	Not Reported
Level reading date:	1940-04-27	Feet below surface:	Not Reported
Feet to sea level:	-13.94	Note:	Not Reported
Level reading date:	1940-04-20	Feet below surface:	Not Reported
Feet to sea level:	-13.65	Note:	Not Reported
Level reading date:	1940-04-13	Feet below surface:	Not Reported
Feet to sea level:	-13.76	Note:	Not Reported
Level reading date:	1940-04-06	Feet below surface:	Not Reported
Feet to sea level:	-13.12	Note:	Not Reported
Level reading date:	1940-03-30	Feet below surface:	Not Reported
Feet to sea level:	-12.59	Note:	Not Reported
Level reading date:	1940-03-23	Feet below surface:	Not Reported
Feet to sea level:	-13.59	Note:	Not Reported
Level reading date:	1940-03-16	Feet below surface:	Not Reported
Feet to sea level:	-13.35	Note:	Not Reported
Level reading date:	1940-03-09	Feet below surface:	Not Reported
Feet to sea level:	-14.07	Note:	Not Reported
Level reading date:	1940-03-02	Feet below surface:	Not Reported
Feet to sea level:	-13.82	Note:	Not Reported
Level reading date:	1940-02-24	Feet below surface:	Not Reported
Feet to sea level:	-14.22	Note:	Not Reported
Level reading date:	1940-02-17	Feet below surface:	Not Reported
Feet to sea level:	-13.58	Note:	Not Reported
Level reading date:	1940-02-10	Feet below surface:	Not Reported
Feet to sea level:	-13.57	Note:	Not Reported
Level reading date:	1940-02-03	Feet below surface:	Not Reported
Feet to sea level:	-13.32	Note:	Not Reported
Level reading date:	1940-01-27	Feet below surface:	Not Reported
Feet to sea level:	-13.46	Note:	Not Reported
Level reading date:	1940-01-20	Feet below surface:	Not Reported
Feet to sea level:	-13.70	Note:	Not Reported
Level reading date:	1940-01-13	Feet below surface:	Not Reported
Feet to sea level:	-14.34	Note:	Not Reported
Level reading date:	1940-01-06	Feet below surface:	Not Reported
Feet to sea level:	-14.20	Note:	Not Reported
Level reading date:	1939-12-30	Feet below surface:	Not Reported
Feet to sea level:	-13.60	Note:	Not Reported
Level reading date:	1939-12-23	Feet below surface:	Not Reported
Feet to sea level:	-13.70	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1939-12-16	Feet below surface:	Not Reported
Feet to sea level:	-13.59	Note:	Not Reported
Level reading date:	1939-12-09	Feet below surface:	Not Reported
Feet to sea level:	-13.93	Note:	Not Reported
Level reading date:	1939-12-02	Feet below surface:	Not Reported
Feet to sea level:	-13.30	Note:	Not Reported
Level reading date:	1939-11-25	Feet below surface:	Not Reported
Feet to sea level:	-13.73	Note:	Not Reported
Level reading date:	1939-11-18	Feet below surface:	Not Reported
Feet to sea level:	-13.96	Note:	Not Reported
Level reading date:	1939-11-11	Feet below surface:	Not Reported
Feet to sea level:	-14.48	Note:	Not Reported
Level reading date:	1939-11-04	Feet below surface:	Not Reported
Feet to sea level:	-14.32	Note:	Not Reported
Level reading date:	1939-10-28	Feet below surface:	Not Reported
Feet to sea level:	-15.32	Note:	Not Reported
Level reading date:	1939-10-21	Feet below surface:	Not Reported
Feet to sea level:	-15.59	Note:	Not Reported
Level reading date:	1939-10-14	Feet below surface:	Not Reported
Feet to sea level:	-15.72	Note:	Not Reported
Level reading date:	1939-10-07	Feet below surface:	Not Reported
Feet to sea level:	-15.47	Note:	Not Reported
Level reading date:	1939-09-30	Feet below surface:	Not Reported
Feet to sea level:	-16.89	Note:	Not Reported
Level reading date:	1939-09-23	Feet below surface:	Not Reported
Feet to sea level:	-16.26	Note:	Not Reported
Level reading date:	1939-09-16	Feet below surface:	Not Reported
Feet to sea level:	-15.77	Note:	Not Reported
Level reading date:	1939-09-08	Feet below surface:	Not Reported
Feet to sea level:	-16.16	Note:	Not Reported
Level reading date:	1939-09-01	Feet below surface:	Not Reported
Feet to sea level:	-16.41	Note:	Not Reported
Level reading date:	1939-08-25	Feet below surface:	Not Reported
Feet to sea level:	-16.45	Note:	Not Reported
Level reading date:	1939-08-18	Feet below surface:	Not Reported
Feet to sea level:	-16.02	Note:	Not Reported
Level reading date:	1939-08-11	Feet below surface:	Not Reported
Feet to sea level:	-15.74	Note:	Not Reported
Level reading date:	1939-08-04	Feet below surface:	Not Reported
Feet to sea level:	-15.72	Note:	Not Reported
Level reading date:	1939-07-28	Feet below surface:	Not Reported
Feet to sea level:	-16.73	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1939-07-21	Feet below surface:	Not Reported
Feet to sea level:	-16.22	Note:	Not Reported
Level reading date:	1939-07-14	Feet below surface:	Not Reported
Feet to sea level:	-16.05	Note:	Not Reported
Level reading date:	1939-07-07	Feet below surface:	Not Reported
Feet to sea level:	-15.06	Note:	Not Reported
Level reading date:	1939-06-30	Feet below surface:	Not Reported
Feet to sea level:	-15.29	Note:	Not Reported
Level reading date:	1939-06-23	Feet below surface:	Not Reported
Feet to sea level:	-15.04	Note:	Not Reported
Level reading date:	1939-06-16	Feet below surface:	Not Reported
Feet to sea level:	-15.36	Note:	Not Reported
Level reading date:	1939-06-09	Feet below surface:	Not Reported
Feet to sea level:	-14.96	Note:	Not Reported
Level reading date:	1939-06-02	Feet below surface:	Not Reported
Feet to sea level:	-15.15	Note:	Not Reported
Level reading date:	1939-05-26	Feet below surface:	Not Reported
Feet to sea level:	-14.09	Note:	Not Reported
Level reading date:	1939-05-19	Feet below surface:	Not Reported
Feet to sea level:	-14.44	Note:	Not Reported
Level reading date:	1939-05-12	Feet below surface:	Not Reported
Feet to sea level:	-14.44	Note:	Not Reported
Level reading date:	1939-05-05	Feet below surface:	Not Reported
Feet to sea level:	-14.25	Note:	Not Reported
Level reading date:	1939-04-28	Feet below surface:	Not Reported
Feet to sea level:	-13.83	Note:	Not Reported
Level reading date:	1939-04-21	Feet below surface:	Not Reported
Feet to sea level:	-14.32	Note:	Not Reported
Level reading date:	1939-04-15	Feet below surface:	Not Reported
Feet to sea level:	-13.92	Note:	Not Reported
Level reading date:	1939-04-08	Feet below surface:	Not Reported
Feet to sea level:	-13.84	Note:	Not Reported
Level reading date:	1939-03-31	Feet below surface:	Not Reported
Feet to sea level:	-14.33	Note:	Not Reported
Level reading date:	1939-03-17	Feet below surface:	Not Reported
Feet to sea level:	-15.04	Note:	Not Reported
Level reading date:	1939-03-10	Feet below surface:	Not Reported
Feet to sea level:	-14.82	Note:	Not Reported
Level reading date:	1939-03-03	Feet below surface:	Not Reported
Feet to sea level:	-14.80	Note:	Not Reported
Level reading date:	1939-02-24	Feet below surface:	Not Reported
Feet to sea level:	-14.35	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1939-02-17	Feet below surface:	Not Reported
Feet to sea level:	-14.30	Note:	Not Reported
Level reading date:	1939-02-10	Feet below surface:	Not Reported
Feet to sea level:	-14.45	Note:	Not Reported
Level reading date:	1939-02-03	Feet below surface:	Not Reported
Feet to sea level:	-14.98	Note:	Not Reported
Level reading date:	1939-01-27	Feet below surface:	Not Reported
Feet to sea level:	-15.14	Note:	Not Reported
Level reading date:	1939-01-20	Feet below surface:	Not Reported
Feet to sea level:	-14.68	Note:	Not Reported
Level reading date:	1939-01-13	Feet below surface:	Not Reported
Feet to sea level:	-15.15	Note:	Not Reported
Level reading date:	1939-01-06	Feet below surface:	Not Reported
Feet to sea level:	-14.77	Note:	Not Reported
Level reading date:	1938-12-30	Feet below surface:	Not Reported
Feet to sea level:	-14.49	Note:	Not Reported
Level reading date:	1938-12-23	Feet below surface:	Not Reported
Feet to sea level:	-14.30	Note:	Not Reported
Level reading date:	1938-12-16	Feet below surface:	Not Reported
Feet to sea level:	-14.79	Note:	Not Reported
Level reading date:	1938-12-09	Feet below surface:	Not Reported
Feet to sea level:	-13.50	Note:	Not Reported
Level reading date:	1938-12-02	Feet below surface:	Not Reported
Feet to sea level:	-14.81	Note:	Not Reported
Level reading date:	1938-11-25	Feet below surface:	Not Reported
Feet to sea level:	-14.84	Note:	Not Reported
Level reading date:	1938-11-18	Feet below surface:	Not Reported
Feet to sea level:	-15.06	Note:	Not Reported
Level reading date:	1938-11-11	Feet below surface:	Not Reported
Feet to sea level:	-14.95	Note:	Not Reported
Level reading date:	1938-11-04	Feet below surface:	Not Reported
Feet to sea level:	-14.28	Note:	Not Reported
Level reading date:	1938-10-28	Feet below surface:	Not Reported
Feet to sea level:	-14.04	Note:	Not Reported
Level reading date:	1938-10-21	Feet below surface:	Not Reported
Feet to sea level:	-13.85	Note:	Not Reported
Level reading date:	1938-10-14	Feet below surface:	Not Reported
Feet to sea level:	-13.74	Note:	Not Reported
Level reading date:	1938-10-07	Feet below surface:	Not Reported
Feet to sea level:	-13.73	Note:	Not Reported
Level reading date:	1938-09-30	Feet below surface:	Not Reported
Feet to sea level:	-13.63	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1938-09-23	Feet below surface:	Not Reported
Feet to sea level:	-13.72	Note:	Not Reported
Level reading date:	1938-09-16	Feet below surface:	Not Reported
Feet to sea level:	-13.63	Note:	Not Reported
Level reading date:	1938-09-09	Feet below surface:	Not Reported
Feet to sea level:	-13.70	Note:	Not Reported
Level reading date:	1938-09-02	Feet below surface:	Not Reported
Feet to sea level:	-13.38	Note:	Not Reported
Level reading date:	1938-08-26	Feet below surface:	Not Reported
Feet to sea level:	-13.68	Note:	Not Reported
Level reading date:	1938-08-19	Feet below surface:	Not Reported
Feet to sea level:	-13.35	Note:	Not Reported
Level reading date:	1938-08-12	Feet below surface:	Not Reported
Feet to sea level:	-13.33	Note:	Not Reported
Level reading date:	1938-08-05	Feet below surface:	Not Reported
Feet to sea level:	-13.09	Note:	Not Reported
Level reading date:	1938-07-29	Feet below surface:	Not Reported
Feet to sea level:	-13.05	Note:	Not Reported
Level reading date:	1938-07-15	Feet below surface:	Not Reported
Feet to sea level:	-12.79	Note:	Not Reported
Level reading date:	1938-07-08	Feet below surface:	Not Reported
Feet to sea level:	-12.65	Note:	Not Reported
Level reading date:	1938-07-01	Feet below surface:	Not Reported
Feet to sea level:	-12.52	Note:	Not Reported
Level reading date:	1938-06-25	Feet below surface:	Not Reported
Feet to sea level:	-12.57	Note:	Not Reported
Level reading date:	1938-06-11	Feet below surface:	Not Reported
Feet to sea level:	-12.18	Note:	Not Reported
Level reading date:	1938-06-04	Feet below surface:	Not Reported
Feet to sea level:	-12.26	Note:	Not Reported
Level reading date:	1938-05-28	Feet below surface:	Not Reported
Feet to sea level:	-12.22	Note:	Not Reported
Level reading date:	1938-05-21	Feet below surface:	Not Reported
Feet to sea level:	-12.05	Note:	Not Reported
Level reading date:	1938-05-14	Feet below surface:	Not Reported
Feet to sea level:	-12.20	Note:	Not Reported
Level reading date:	1938-05-07	Feet below surface:	Not Reported
Feet to sea level:	-12.24	Note:	Not Reported
Level reading date:	1938-04-30	Feet below surface:	Not Reported
Feet to sea level:	-12.29	Note:	Not Reported
Level reading date:	1938-04-23	Feet below surface:	Not Reported
Feet to sea level:	-12.15	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1938-04-16	Feet below surface:	Not Reported
Feet to sea level:	-11.98	Note:	Not Reported
Level reading date:	1938-04-02	Feet below surface:	Not Reported
Feet to sea level:	-11.64	Note:	Not Reported
Level reading date:	1938-03-26	Feet below surface:	Not Reported
Feet to sea level:	-11.52	Note:	Not Reported
Level reading date:	1938-03-19	Feet below surface:	Not Reported
Feet to sea level:	-11.54	Note:	Not Reported
Level reading date:	1938-03-12	Feet below surface:	Not Reported
Feet to sea level:	-11.69	Note:	Not Reported
Level reading date:	1938-03-05	Feet below surface:	Not Reported
Feet to sea level:	-11.52	Note:	Not Reported
Level reading date:	1938-02-26	Feet below surface:	Not Reported
Feet to sea level:	-11.72	Note:	Not Reported
Level reading date:	1938-02-19	Feet below surface:	Not Reported
Feet to sea level:	-11.63	Note:	Not Reported
Level reading date:	1938-02-12	Feet below surface:	Not Reported
Feet to sea level:	-11.74	Note:	Not Reported
Level reading date:	1938-02-04	Feet below surface:	Not Reported
Feet to sea level:	-12.43	Note:	Not Reported
Level reading date:	1938-01-28	Feet below surface:	Not Reported
Feet to sea level:	-12.66	Note:	Not Reported
Level reading date:	1938-01-21	Feet below surface:	Not Reported
Feet to sea level:	-12.31	Note:	Not Reported
Level reading date:	1938-01-14	Feet below surface:	Not Reported
Feet to sea level:	-12.22	Note:	Not Reported
Level reading date:	1938-01-07	Feet below surface:	Not Reported
Feet to sea level:	-12.00	Note:	Not Reported
Level reading date:	1937-12-31	Feet below surface:	Not Reported
Feet to sea level:	-11.96	Note:	Not Reported
Level reading date:	1937-12-24	Feet below surface:	Not Reported
Feet to sea level:	-12.09	Note:	Not Reported
Level reading date:	1937-12-18	Feet below surface:	Not Reported
Feet to sea level:	-12.12	Note:	Not Reported
Level reading date:	1937-12-11	Feet below surface:	Not Reported
Feet to sea level:	-12.11	Note:	Not Reported
Level reading date:	1937-12-04	Feet below surface:	Not Reported
Feet to sea level:	-12.05	Note:	Not Reported
Level reading date:	1937-11-27	Feet below surface:	Not Reported
Feet to sea level:	-12.45	Note:	Not Reported
Level reading date:	1937-11-20	Feet below surface:	Not Reported
Feet to sea level:	-12.09	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date: 1937-11-13
Feet to sea level: -12.02

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1937-11-08
Feet to sea level: -12.50

Feet below surface: Not Reported
Note: Not Reported

G24
SW
1/2 - 1 Mile
Higher

FED USGS USGS40000827028

Organization ID: USGS-NY
Monitor Location: K 1148. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 150

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Units: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

25
NNW
1/2 - 1 Mile
Higher

FED USGS USGS40000828275

Organization ID: USGS-NY
Monitor Location: K 704. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 130

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Units: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

26
NNW
1/2 - 1 Mile
Higher

FED USGS USGS40000828339

Organization ID: USGS-NY
Monitor Location: K 703. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 138

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Units: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

27
ENE
1/2 - 1 Mile
Higher

FED USGS USGS40000828070

Organization ID: USGS-NY
Monitor Location: K 104. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: 102
Well Hole Depth: Not Reported

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Unts: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: ft
Well Hole Depth Units: Not Reported

Ground water levels,Number of Measurements: 129
Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1943-08-28
Feet to sea level: -25.72

Level reading date: 1943-07-31
Feet to sea level: -25.61

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1943-06-26
Feet to sea level: -25.43

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1943-05-29
Feet to sea level: -25.37

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1943-05-01
Feet to sea level: -25.43

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1943-03-27
Feet to sea level: -25.72

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1943-02-27
Feet to sea level: -25.91

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1943-01-30
Feet to sea level: -25.93

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1943-01-02
Feet to sea level: -26.33

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-12-26
Feet to sea level: -26.42

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-12-19
Feet to sea level: -26.47

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-12-12
Feet to sea level: -26.51

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-12-05
Feet to sea level: -26.53

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-11-28
Feet to sea level: -26.55

Feet below surface: Not Reported
Note: Not Reported

Level reading date: 1942-11-21

Feet below surface: Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Feet to sea level:	-26.59	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-26.62	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-26.65	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-26.68	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-26.69	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-26.68	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-26.66	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-26.62	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-26.59	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-26.58	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-26.56	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-26.53	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-26.53	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-26.51	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-26.49	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-26.49	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-26.48	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-26.45	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-26.43	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-26.44	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-26.39	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-26.37	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-26.35	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-26.31	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-26.32	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-26.35	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-26.34	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-26.34	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-26.34	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-26.36	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-26.36	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-26.40	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-26.43	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-26.44	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-26.45	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-26.48	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-26.51	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-26.55	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-26.61	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-26.67	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-26.72	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-26.76	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-26.78	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-26.80	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-26.81	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-26.84	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-26.87	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-26.87	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-26.87	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-26.84	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-26.80	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-26.74	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-26.68	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-26.62	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-26.45	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-26.40	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-26.35	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-26.30	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-26.22	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-26.16	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-26.13	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-26.10	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-26.07	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-26.05	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-26.01	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-25.92	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-25.85	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-25.80	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-25.75	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-25.72	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-25.68	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-25.63	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-25.60	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-25.56	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-25.53	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-25.51	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-25.52	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-25.51	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-25.50	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-25.49	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-25.51	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-25.56	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-25.58	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-25.56	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-25.56	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-25.58	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-25.60	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-25.62	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-25.65	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-25.69	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-25.74	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-25.78	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-25.81	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-25.87	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-25.91	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-25.99	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-26.03	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-26.07	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-26.09	Note:	Not Reported
Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-26.10	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-26.11	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-26.12	Note:	Not Reported
Level reading date:	1940-10-05	Feet below surface:	Not Reported
Feet to sea level:	-26.11	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-26.08	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-26.04	Note:	Not Reported
Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-26.04	Note:	Not Reported
Level reading date:	1940-08-27	Feet below surface:	Not Reported
Feet to sea level:	-25.89	Note:	Not Reported

28
SW
1/2 - 1 Mile
Higher

FED USGS USGS40000827037

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1189. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	144
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

29
SW
1/2 - 1 Mile
Higher

FED USGS USGS40000827051

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1271. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Well Hole Depth: 1503

Well Hole Depth Units: ft

30
NE
1/2 - 1 Mile
Higher

FED USGS USGS40000828170

Organization ID: USGS-NY
Monitor Location: K 917. 1
Description: Not Reported
Drainage Area: Not Reported
Contrib Drainage Area: Not Reported
Aquifer: Not Reported
Aquifer Type: Not Reported
Well Depth: Not Reported
Well Hole Depth: 106

Organization Name: USGS New York Water Science Center
Type: Well
HUC: 02030201
Drainage Area Units: Not Reported
Contrib Drainage Area Units: Not Reported
Formation Type: Not Reported
Construction Date: Not Reported
Well Depth Units: Not Reported
Well Hole Depth Units: ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.

: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.

: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

<u>Area</u>	<u>Average Activity</u>	<u>% <4 pCi/L</u>	<u>% 4-20 pCi/L</u>	<u>% >20 pCi/L</u>
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map

Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.

Source: FEMA

Telephone: 877-336-2627

Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands

Source: Department of Environmental Conservation

Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells

Source: New York Department of Health

Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database

Source: Department of Environmental Conservation

Telephone: 518-402-8072

These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon

Source: Department of Health

Telephone: 518-402-7556

Radon Test Results

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones

Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities

Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.