

HALEY & ALDRICH OF NEW YORK 237 West 35<sup>th</sup> Street 16<sup>th</sup> Floor New York, NY 10123 646.518.7735

10 March 2023 File No. 0202156

Via Email: Jolene.lozewski@dec.ny.gov New York State Department of Environmental Conservation Division of Environmental Remediation 625 Broadway Albany, New York 12233

Attention: Jolene Lozewski

Subject: Project Status Report

Former Carter Spray Finishing Corp. - NYSDEC BCP Site C224218

65 Eckford Street Brooklyn, New York

Dear Jolene Lozewski:

Haley & Aldrich of New York is pleased to present this Project Status Report on behalf of 65-73 Eckford Realty, LLC for the above referenced Site. Copies of this Project Status Report have also been provided to Scarlett McLaughlin and Arunesh Ghosh of the New York State Department of Health. The Project Status Report is for 1 February 2023 to 1 March 2023. If you have any questions, please contact us at 646-277-5688.

Sincerely yours,
HALEY & ALDRICH OF NEW YORK

Mari Cate Conlon

Associate

CC:

Bob Corcoran (NYSDEC) Email: bob.corcoran@dec.ny.gov

Scarlett McLaughlin (NYSDOH) Email: <a href="mailto:scarlett.mclaughlin@health.ny.gov">scarlett.mclaughlin@health.ny.gov</a>
Arunesh Ghosh (NYSDOH) Email: <a href="mailto:scarlett.mclaughlin@health.ny.gov">scarlett.mclaughlin@health.ny.gov</a>

65-73 Eckford Realty, LLC Email: <u>abe6991@gmail.com</u>

Jon Schuyler Brooks (Abramson Brooks LLP) Email: <a href="mailto:jbrooks@abramsonbrooks.com">jbrooks@abramsonbrooks.com</a>

Former Carter Spray Finishing Corp. - BCP Site C224218 10 March 2023 Page 2

This status report summarizes activities conducted at the Former Carter Spray Finishing Corp. Site (the Site) located at 65 Eckford Street, Brooklyn, NY from 1 February 2023 to 1 March 2023. Activities during this period were conducted by Haley & Aldrich of New York (Haley & Aldrich). A Site plan showing the current Site conditions is included as Attachment A.

#### **Corrective Action and Remedial Measure Activities**

No on-site activity has occurred during this reporting period. Disposal facilities are still being evaluated.

## **Sampling Results and Other Data**

None

# **Estimated Percentage of Project Completion**

The Site investigation and remedial design phase is 100% complete.

## **Delays Encountered**

Remedy implementation and construction will continue once disposal facility approvals have been obtained.

#### **Site Communication and Deliverable Submittals**

No daily reports or deliverables were submitted to New York State Department of Environmental Conservation (NYSDEC) and/or New York State Department of Health (NYSDOH) during this reporting period.

### **Anticipated Activities during Next Reporting Period**

Supplemental waste characterization sampling as requested by disposal facilities.

# **Anticipated Citizen Participation Activities**

**Current Period** 

None

**Anticipated Next Period** 

None

#### **Attachments**

Attachment A - Current Site Conditions Plan



# Attachment A

**Current Site Conditions Plan** 



