

DAILY FIELD REPORT

Project	8 Walworth Street	Report No.	12
BCP Site	BCP Site No. C224239	Date	8/1/2024
Location	8 Walworth Street, Brooklyn, NY	File No.	0134860
Client	Toldos Yehudah, LLC	Temperature	88-92°F
Contractor	Haley & Aldrich	Wind Direction	From E to W up to 2 mph
Weather	Sunny	Personnel on Site	S. Sotomayor, J. Mastro
Humidity	40%	Time on Site	08:00 to 15:00

Haley & Aldrich of New York (Haley & Aldrich) was present to document implementation of the NYSDECapproved July 2022 Remedial Action Work Plan (RAWP) and Decision Document for 8 Walworth Street Site C224239. Site Observations are summarized below.

Daily Observations:

- Haley & Aldrich mobilized to site to conduct well development of all on-site and off-site monitoring wells.
- Haley & Aldrich performed a round of synoptic gauging all on-site and off-site monitoring wells.

Activities Planned for Coming Week:

- Continued redevelopment of on-site and off-site monitoring wells.
- Site-wide groundwater sampling.



DAILY FIELD REPORT

Site Photographs:




Photo 1: View of the Site conditions, facing northwest.



Photo 2: View of the Site conditions, facing northeast.



DAILY FIELD REPORT

