

DAILY STATUS REPORT

Prepared By: C. Zaccheo

| | | | | | | | | | | |
|---------|------|--|-------|--|----------|--|---------------|---|------------|---|
| WEATHER | Snow | | Rain | | Overcast | | Partly Cloudy | | Bright Sun | X |
| TEMP. | < 32 | | 32-50 | | 50-70 | | 70-85 | X | >85 | |

BCP Site ID #:C224267

Date: 06/03/2024

Project Name: **3901-3913 8th Avenue – Brooklyn, NY**

Consultant:

Matthew Carroll, P.E.
Tenen Environmental

Safety Officer:

Claire Zaccheo
Tenen Environmental

General Contractor:

EarthTech Services, Inc.
222 William Street
Bronx, NY 10461

EarthTech Site Superintendent:

Sam Caller
(347) 907-4053

Work Activities Performed (Since Last Report):

The contractor was spreading and leveling the RCA in preparation for vapor barrier and rebar installation.

Working In Grid #: A1, A2 and A3

Samples Collected (Since Last Report): None

Air Monitoring (Since Last Report):

Background Conditions

Downwind: Dust: NA mg/m3 PID: NA ppm

Downwind: Dust: NA mg/m3 PID: NA ppm

Daily TWA

Downwind: Dust: NA mg/m3 PID: NA ppm

Downwind: Dust: NA mg/m3 PID: NA ppm

*CAMP stations were not utilized during the workday.

Problems Encountered: None.

Planned Activities for the Next Day/ Week:

The contractor will be installing the vapor barrier and preparing to pour concrete.

| | | |
|--------------------------------------|--|----------|
| Facility # Name/ Location | Bayshore Soil Management 75 Crows Mill Road Keasby, NJ 08832 | |
| (Trucks, CY) | Trucks | Cu. Yds. |
| Today | 0 | 0 |
| Total | 33 | 660 |




Photo Log

Photo 1 –
View of
RCA
backfill.



Photo 2 –
View of Site
conditions.



CAMP Data

| | |
|----------------|----|
| <u>DW CAMP</u> | NA |
| <u>UW CAMP</u> | NA |

DAILY STATUS REPORT

Prepared By: C. Zaccheo

| | | | | | | | | | | |
|---------|------|--|-------|--|----------|---|---------------|---|------------|--|
| WEATHER | Snow | | Rain | | Overcast | X | Partly Cloudy | X | Bright Sun | |
| TEMP. | < 32 | | 32-50 | | 50-70 | | 70-85 | X | >85 | |

BCP Site ID #:C224267

Date: 06/05/2024

Project Name: **3901-3913 8th Avenue – Brooklyn, NY**

Consultant:

Matthew Carroll, P.E.
Tenen Environmental

Safety Officer:

Claire Zaccheo
Tenen Environmental

General Contractor:

EarthTech Services, Inc.
222 William Street
Bronx, NY 10461

EarthTech Site Superintendent:

Sam Caller
(347) 907-4053

Work Activities Performed (Since Last Report):

Tenen completed the vapor barrier inspection prior to the contractor pouring concrete.

Working In Grid #: A1, A2 and A3

Samples Collected (Since Last Report): None

Air Monitoring (Since Last Report):

Background Conditions

Downwind: Dust: NA mg/m3 PID: NA ppm

Downwind: Dust: NA mg/m3 PID: NA ppm

Daily TWA

Downwind: Dust: NA mg/m3 PID: NA ppm

Downwind: Dust: NA mg/m3 PID: NA ppm

*CAMP stations were not utilized during the workday.

Problems Encountered: None.

Planned Activities for the Next Day/ Week:

The contractor will complete indoor renovations.

| Facility # Name/ Location | Bayshore Soil Management 75 Crows Mill Road Keasby, NJ 08832 | |
|------------------------------|--|----------|
| (Trucks, CY) | Trucks | Cu. Yds. |
| Today | 0 | 0 |
| Total | 33 | 660 |




Photo Log

Photo 1 –
View of
vapor barrier
installation.



Photo 2 –
View of
vapor barrier
installation.



CAMP Data

| | |
|----------------|----|
| <u>DW CAMP</u> | NA |
| <u>UW CAMP</u> | NA |