

DAILY STATUS REPORT

Prepared By: C. Zaccheo

WEATHER	Snow		Rain		Overcast	X	Partly Cloudy	X	Bright Sun	
TEMP.	< 32		32-50		50-70		70-85	X	>85	

BCP Site ID #:C224267

Date: 07/18/2024

Project Name: **3901-3913 8th Avenue – Brooklyn, NY**

Consultant:

Matthew Carroll, P.E.
Tenen Environmental

Safety Officer:

Claire Zaccheo
Tenen Environmental

General Contractor:

Pragmatic Developers Inc.
500 DeKalb Ave., Ste 408
Brooklyn, NY

Work Activities Performed (Since Last Report):

Tenen completed waste characterization sampling of concrete wash water in preparation for off-site disposal.

Working In Grid #: A1, A2 and A3

Samples Collected (Since Last Report): Drum-1

Air Monitoring (Since Last Report):

Background Conditions

Downwind: Dust: NA mg/m3 PID: NA ppm

Downwind: Dust: NA mg/m3 PID: NA ppm

Daily TWA

Downwind: Dust: NA mg/m3 PID: NA ppm

Downwind: Dust: NA mg/m3 PID: NA ppm

*CAMP stations were not utilized during the workday.

Problems Encountered: None.

Planned Activities for the Next Day/ Week:

The drums of wash water will be disposed of off-site.

Facility # Name/ Location	Bayshore Soil Management 75 Crows Mill Road Keasby, NJ 08832	
(Trucks, CY)	Trucks	Cu. Yds.
Today	0	0
Total	33	660




Photo Log

Photo 1 –
View of
containerized
wash water
for off-site
disposal.



Photo 2 –
View of
concrete
after
washing.



Photo 3 –
View of
concrete
after
washing.



CAMP Data

<u>DW CAMP</u>	NA
<u>UW CAMP</u>	NA