

DAILY STATUS REPORTPrepared By: M. Carroll

WEATHER	Snow		Rain		Overcast		Partly Cloudy	X	Bright Sun	
TEMP.	< 32		32-50		50-70	X	70-85		>85	

BCP Site ID #:C224267

Date: 03/31/2025

Project Name: **3901-3913 8th Avenue – Brooklyn, NY****Consultant:**Matthew Carroll, P.E.
Tenen Environmental**Safety Officer:**HP Lau
Tenen Environmental**Subcontractor:** N/A**Work Activities Performed (Since Last Report):**

Tenen collected indoor and ambient samples, see attached figure. As discussed, the sample layout was inadvertently not implemented per the work plan. We are proposing to analyze indoor air samples IA-1, IA-3/3D, IA-4 and IA-5, as well as both ambient air samples.

Working In Grid #: N/A**Samples Collected (Since Last Report):** None.**Air Monitoring (Since Last Report):** None.**Problems Encountered:** None.**Planned Activities for the Next Day/ Week:** None.

Site Layout

