

DAILY STATUS REPORTPrepared By: C. Zaccheo

WEATHER	Snow		Rain		Overcast		Partly Cloudy	X	Bright Sun	
TEMP.	< 32	X	32-50		50-70		70-85		>85	

BCP Site ID #:C224267

Date: 01/21/2026

Project Name: **3901-3913 8th Avenue – Brooklyn, NY****Consultant:**Matthew Carroll, P.E.
Tenen Environmental**Safety Officer:**HP Lau
Tenen Environmental**Subcontractor:** N/A**Work Activities Performed (Since Last Report):**

Tenen collected indoor and ambient samples, see attached figure. Five indoor air samples (including a duplicate) and two outdoor air samples were collected.

Working In Grid #: N/A**Samples Collected (Since Last Report):** None.**Air Monitoring (Since Last Report):** None.**Problems Encountered:** None.**Planned Activities for the Next Day/ Week:** None.

Site Layout




Photo 1 – View of the outdoor air sample along 8th Avenue



Jan 21, 2026 12:08:42 PM
40°38'49"N 73°59'51"W
801 40th Street
Brooklyn
Kings County
New York

Photo 2 – View of an indoor air sample location



Jan 21, 2026 12:02:04 PM
40°38'50"N 73°59'50"W
Brooklyn
Kings County
New York