

1



SOIL SAMPLES AT 1665 STILLWELL AVENUE BROOKLYN, NY PHOTOS TAKEN WEDS 10/26/2022



**SOIL SAMPLE SBO-5 IN FRONT OF
WORK-SITE ON STILLWELL AVENUE 2**



3

**SOIL SAMPLE SBO-5 IN FRONT OF
WORK-SITE ON
ON STILLWELL AVENUE**

SOIL SAMPLE SBO-5 IN FRONT OF WORK- SITE ON STILLWELL AVENUE







5

**SOIL SAMPLE SBO-5
IN FRONT OF WORK-
SITE ON STILLWELL
AVENUE**

SOIL SAMPLE SBO-5 IN FRONT OF
WORK-SITE ON STILLWELL AVENUE



6



**SOIL SAMPLE SBO-4 MIDDLE OF
BLOCK ON STILLWELL AVENUE**

7




**SOIL SAMPLE SBO-4 MIDDLE OF
BLOCK ON STILLWELL AVENUE**

8



**SOIL SAMPLE SBO-4 MIDDLE OF
BLOCK ON STILLWELL AVENUE**




10

**SOIL SAMPLE SBO-9 NEAR THE
BUS STOP AT CORNER OF STILLWELL
& KINGS HIGHWAY**

11



**SOIL SAMPLE SBO-9 NEAR THE
BUS STOP AT CORNER OF STILLWELL
& KINGS HIGHWAY**



12

**SOIL SAMPLE SBO-9 NEAR THE
BUS STOP AT CORNER OF STILLWELL
& KINGS HIGHWAY**



**SOIL SAMPLE
SBO-9**

13

14



**SOIL SAMPLE SBO-9 NEAR THE
BUS STOP AT CORNER OF STILLWELL
& KINGS HIGHWAY**

15

SAMPLING
SBO-9



SOIL SAMPLE SBO-8 NEAR THE CORNER OF WEST 13TH & KINGS HIGHWAY



16

LEARN + GROW

17



**SOIL SAMPLE
SBO-8 NEAR THE CORNER OF
WEST 13TH & KINGS HIGHWAY**

18

A black circular soil sampling device is embedded in a hole in the ground. The device has a white triangle on its top surface and four small circular indentations around its perimeter. A small metal tab is visible on the top edge. The surrounding ground is dark and appears to be soil or gravel. In the upper right corner, a portion of a red and black object, possibly a piece of machinery, is visible.

**SOIL SAMPLE
SBO-8 NEAR THE CORNER OF
WEST 13TH & KINGS HIGHWAY**