

**WEEKLY INSPECTION REPORT****Prepared By:**

Thomas Jensen

WEATHER	Snow		Rain		Overcast		Partly Cloudy	X	Bright Sun	X	Wind
TEMP.	< 32		32-50	X	50-70	X	70-85		>85		5 – SW mph

IEC Project No:	14729	NYSDEC BCP Site No:	C224329	Date:	11/2/23
Project:	585 Union Street, Brooklyn, NY				

Consultant:

Impact Environmental Engineering and Geology, PLLC (IEEG)

Time On: 7:30

Time Out: 7:45

Personnel On Site:IEEG (Environmental) – Thomas Jensen
Broadway Construction Group, Shannon Dowling**Scope of Work:**

- Weekly site inspection.

Site Activities:

- Interior framing up to the 7th floor;
- Electrical and Plumbing work up to the 7th floor;
- Exterior framing; and
- General super structure work.

Community Air Monitoring Program (CAMP):

- CAMP was not deployed as the purpose of the Site visit was for a weekly inspection.

Notable Site Conditions:

- A partial stop work order was issued due to a fall from a ladder, most trades are not on site, work will resume next week.

Planned for the Next Day/Week:

- Continued Superstructure work.

Photo 1 –
Representative
photo of the
building
exterior.



Photo 2 –
Representative
photo of
building interior
at the 2nd floor.



Photo 3 –
Representative
photo of the
first floor.

