



WEEKLY INSPECTION REPORT

Prepared By:

Thomas Jensen

WEATHER	Snow	Rain	Overcast	Partly Cloudy	<input checked="" type="checkbox"/>	Bright Sun	Wind
TEMP.	< 32	32-50	50-70	<input checked="" type="checkbox"/>	70-85	>85	

IEC Project No:	14729	NYSDEC BCP Site No:	C224329	Date:	11/15/23
Project:	585 Union Street, Brooklyn, NY				

<p>Consultant: Impact Environmental Engineering and Geology, PLLC (IEEG)</p> <p>Time On: 17:00 Time Out: 17:30</p>	<p>Personnel On Site: IEEG (Environmental) – Thomas Jensen Broadway Construction Group, Shannon Dowling</p>
---	--

<p><u>Scope of Work:</u></p> <ul style="list-style-type: none"> Weekly site inspection. <p><u>Site Activities:</u></p> <ul style="list-style-type: none"> Interior framing up to the 9th floor; Continued exterior framing up to the 4th floor; All trades working on all floors; and General super structure work. <p><u>Community Air Monitoring Program (CAMP):</u></p> <ul style="list-style-type: none"> CAMP was not deployed as the purpose of the Site visit was for a weekly inspection. <p><u>Notable Site Conditions:</u></p> <ul style="list-style-type: none"> None. <p><u>Planned for the Next Day/Week:</u></p> <ul style="list-style-type: none"> Continued superstructure work.

PHOTO LOG

585 Union Street, Brooklyn,
NY



Photo 1 –
Representative
photo of the
building
exterior.



Photo 2 –
Representative
photo of work
done on the
roof.



Photo 3 –
Representative
photo of the
third floor.

