

## Daily Status Report

Prepared by: HP Lau

Date: 8/22/2023

Weather: 80 deg F., Sunny

**Project: 340 Myrtle Avenue - Brooklyn, NY BCP Site# C224340**

Engineer: Matthew Carroll, P.E. Tenen Environmental, LLC	Safety Manager: HP Lau Tenen Environmental, LLC
Onsite Tenen Staff: Mark Accetturi	

### Work Activities Performed:

1) Collected soil samples PFAS-1, PFAS-2, PFAS-3, TB-1, TB-2 and Field Blank from the Site at 155 Carlton Avenue.


**Samples Collected (Since Last Report):** PFAS-1, PFAS-2, PFAS-3, TB-1, TB-2 and Field Blank for analysis of PFAS.

**Air Monitoring (Since Last Report):** Soil disturbance activities were not conducted today; therefore, CAMP was not deployed.

**Problems Encountered:** None.

**Planned Work Activities for Next Day/Week:** None.

# Site Map



References:  
NYC Department of City Planning, Information Technology Division  
Newmap Aerial 3/12/2021

**Photo 1:** View of the soil sample locations.



**Photo 2:** View of the soil sample location, TB-1.



**Downwind CAMP  
Data**

**Note:  
Teal = 15-min  
average  
concentration**

**Blue = 8-hr TWA**

**Upwind CAMP  
Data**

**Note:  
Teal = 15-min  
average  
concentration**

**Blue = 8-hr TWA**