

# IMPACT ENVIRONMENTAL | 170 Keyland Court | Bohemia | New York | 11716 | 631.269.8800

## **DAILY STATUS REPORT**

Prepared by: Alex Keenan

WEATHER	Snow	Rain	Overcast	Partly Cloudy	Bright Sun	х
TEMP.	< 32	32-50	50-70	70-85	> 85	

DEC BCP Project. No.	C224350	Date:	10/12/22
Project Name:	318 Nevins Street, Brooklyn, NY		

Environmental Consultant:	Environmental Safety Officer:
Impact Environmental Closures, Inc	Alex Keenan – Impact Environmental Closures, Inc.
170 Keyland Court	
Bohemia, NY 11716.	
General Contractor:	Site Manager/ Supervisor:
Broadway Construction Group, LLC	Site Super: Shannon Dowling- Broadway Construction
	Group, LLC
	Diana Posten– Impact Environmental Closures, Inc.

### **Work Activities Performed (Since Last Report)**

- Impact arrived on site at 0800;
- Impact Environmental purged GW-6 as well as collected a gw sample from the well using low-flow techniques; and
- Impact collected all sample location coordinated utilizing a handheld GPS.

#### **Working In Area:**

• Eastern portion of the Site.

#### **Samples Collected (Since Last Report):**

- GW-6
- \*All required QA/QC samples were collected.

### **Air Monitoring (Since Last Report):**

CAMP was not run as no subsurface intrusive work was occurring on this date.

### **Problems Encountered:**


None

#### Planned Activities for the Next Day/ Week:

• TBD if the bulkhead test pits will be completed, the client will advise. If this work is planed for a later date, Impact will notify the DEC and be present on-Site to run CAMP and screen soil.


<sup>\*</sup>It should be noted that since the start of this RI work (9/27/22), the portion of the Gowanus Canal adjacent to the Site has been getting dredged.

# Site Grid Map



# **Photo Log**

**Photo 1** – Representative photo of sampling set-up at GW-6.



**Photo 2** – Representative photo of dredging along the Gowanus Canal.

