

DAILY STATUS REPORT

Prepared By: Daniel Horvath

WEATHER	Snow	Rain	Overcast	X	Partly Cloudy		Bright Sun	
TEMP.	< 32	32-50	50-70		70-85	X	>85	

Langan Project No:	100688803	Project:	12074 Flatlands Avenue p/o Lot 1	Date:	06/17/2025
NYSDEC BCP Site No:	C224353	NYCOER Site No.:	Lot 1: 23TMP1319K / 23EHAN210K Lot 100: 25TMP1084K, 25EHAN206K	Time:	06:15 – 17:30

Consultant:

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.

PERSONNEL ON SITE:

Langan: Daniel Horvath (Environmental), Lakshman

Dontha (Geotechnical)

Monadnock: Seamus Lavin (Superintendent) **United Concrete:** Miguel Flores and laborers

RYC Turbos: Manuel and crew

Morris-Shea: Crew

American Dewatering & Grouting: Crew

EQUIPMENT ON SITE: Komatsu PC490 LC Excavator (2), Komatsu PC360 LC Excavator, Komatsu PC138US LC Excavator, Komatsu PC78US Excavator, Bobcat 740 Skid Steer, JLG 800AJ Boom Lift, ABI Mobilram TM18/22 HD Drill Rig (2), Caterpillar 335F L CR Excavator (2), STS Scheltzke MPS 510-D-C-AUT Mix-Pump-Unit, Delmag RH34 Drill Rig, Hutte HBR 605 Drill Rig, Woltman 90DR Drill Rig, Volvo ECR235EL Excavator, CASE TV450B Skid Steer, FL-126 Telehandler

Site Activities

BCP Site Activities

- Langan provided oversight during implementation of the 1 May 2024 RAWP.
- United Concrete (United) removed 32 truckloads of material for off-Site disposal to Clean Earth New Castle.
 - United removed material from stockpile ST-57, originally excavated from disposal grid WC40F in the southern portion of the Site, for off-Site disposal to Clean Earth New Castle. Stockpile ST-57 is no longer present on-Site.
 - United removed material from stockpile ST-60, originally excavated from disposal grid WC52 in the northwestern portion of the Site, for off-Site disposal to Clean Earth New Castle. Stockpile ST-60 is no longer present on-Site.
 - United excavated an approximately 140-foot-long area ranging between 20- and 40-feet-wide from between 9 to up to 11 feet below ground surface (bgs) in disposal grids WC52 and WC55.
 All excavated material was loaded for off-Site disposal to Clean Earth New Castle.
- United excavated an approximately 125-foot-long by 20-foot-wide area from between 11 to up to 13 feet bgs in disposal grids WC56 and WC59. All excavated material was staged as stockpile ST-61. Stockpile ST-61 was covered with polyethylene sheeting at the end of the day.
- United used an excavator to remove miscellaneous debris from stockpile ST-59 to meet disposal facility requirements. All separated debris was added to roll-off containers.
- United continued installing walers in the southeastern portion of the Site.
- American Dewatering Grouting (ADG) continued drilling dewatering wells in the southern portion of the Site. ADG placed the collected water and any cuttings in the filter-fabric lined collection basin. The accumulated water was left to evaporate overnight.
- RYC Turbos continued installing tiebacks along the western boundary of the Site for the construction of the SOE.
- Morris-Shea continued installing foundation piles in the northeastern portion of the Site. No cuttings were generated during pile installation.



Lot 100 Site Activities

None.

Dewatering Activities

- ADG continued dewatering in the northern portion of the Site.
- Langan will provide a summary of daily groundwater elevation measurements upon receipt from the dewatering contractor.

Samples Collected

None.

Community Air Monitoring Program (CAMP)

- Langan implemented the community air monitoring program (CAMP) during soil disturbance. CAMP equipment consisted of an Aeroqual AQS 1 Air Quality Monitor at dedicated locations on the downwind and upwind perimeter of the site, as well as a personal DataRam (pDR) an PID at a work zone monitoring station.
 - o No VOC or dust concentrations were detected in exceedance of the short-term exposure limit (STEL) at the downwind CAMP station.

Problems Encountered

None.

Activities Scheduled for Next Day

- United will export material from the Site.
- United will import material to the Site.
- United will continue to excavate in the western portion of the Site.
- Morris-Shea will continue installation of deep foundation elements in the northwestern portion of the Site
- ADG will continue installation of the dewatering wells in the southern portion of the Site.

Two Week Outlook

- United will excavate and export material from the southern portions of the Site.
- ADG will continue installation of the dewatering wells.
- Morris-Shea will continue installation of deep foundation elements.



Truck Count Log of Imported Material										
Facility/Material (BCP Site – NYSDEC Approved):	Tilcon New York Inc., Mount Hope Quarry (1.5-inch Clean Stone)		Tilcon New York Inc., Mount Hope Quarry (0.75-inch Clean Stone)		Braen Stone of Sparta Lafayette, New Jersey (1.5-inch Clean Stone)		Braen Stone of Sparta Lafayette, New Jersey (0.75-inch Clean Stone)		Braen Stone of Sparta Lafayette, New Jersey (Dense Graded Aggregate)	
Volume:	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yards	Trucks	Cu. Yards	Trucks	Cu. Yards
Today:	0	0	0	0	0	0	0	0	0	0
Total:	18	360	0	0	102	2,040	0	0	28	660
Approved Quantity (CY):		500		500		3,500		3,500		5,000
Facility/Material (Lot 100 – NYCOER Approved):	Lafayette, I	Braen Stone of Sparta Lafayette, New Jersey (1.5-inch Clean Stone)		Braen Stone of Sparta Lafayette, New Jersey (0.75-inch Clean Stone)				_	-	
Volume:	Trucks	Cu. Yards	Trucks	Cu. Yds.	Trucks	Cu. Yards	Trucks	Cu. Yards	Trucks	Cu. Yards
Today:	0	0	0	0						
Total:	10	200	1	20						
Approved Quantity (CY):		3,000		3,000						

Note: 20 cubic yards (CY) assumed per truckload



		Tru	ck Cou	nt Log of	Export	ed Materi	al			
Facility/Material (BCP Site):	Clean Earth Philadelphia Philadelphia, Pennsylvania Approval # 243100026 (7,000 tons)		Clean Earth Carteret Carteret, New Jersey Approval #243070587 (4,000 tons)		Clean Earth Carteret Carteret, New Jersey Approval #253070241 (cumulative 83,450 tons)		Clean Earth Carteret Carteret, New Jersey Approval #253070242 (cumulative 83,450 tons)		Clean Earth New Castle New Castle, Delaware Approval #253020014 (cumulative 96,400 tons)	
Volume:	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.
Today:	0	0	0	0	0	0	0	0	0	0
Total:	175	3,500	51	1,020	953	19,060	180	3,600	780	15,600
Facility/Material (BCP Site):	Clean Earth New Castle New Castle, Delaware Approval #253020015 (cumulative 96,400 tons)		Clean Earth North Jersey Kearny, New Jersey Approval #2530804874 (6,000 tons)		Clean Earth North Jersey Kearny, New Jersey Approval #2530804878 (5,250 tons)		Clean Earth North Jersey Kearny, New Jersey Approval #2530804888 (1,500 tons)		Clean Earth North Jersey Kearny, New Jersey Pre-Approval #2530804828 (2,000 tons)	
Volume:	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.
Today:	32	640	0	0	0	0	0	0	0	0
Total:	140	2,800	30	600	34	680	0	0	61	1,220
Facility/Material (BCP Site):	Kearny, I Approval #	North Jersey New Jersey \$2530804872 O tons)	Clean Earth North Jersey Kearny, New Jersey Pre-Approval #2530804884 (50 tons)		Clean Earth North Jersey Kearny, New Jersey Approval #2530804880 (3,750 tons)		Clean Earth Carteret Carteret, New Jersey Approval #253070475 (cumulative 83,450 tons)			
Volume:	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.
Today:	0	0	0	0	0	0	0	0		
Total:	2	40	0	0	0	0	141	2,820		
Facility/Material (Lot 100):	New Cast Approval	n New Castle, le, Delaware #253020014 e 96,400 tons)								
Volume:	Trucks	Cu. Yds.	Trucks	Trucks	Trucks	Trucks	Trucks	Trucks	Trucks	Trucks
Today:	0	0								
Total:	4	80								

Note: 20 cubic yards assumed per truckload

LANGAN

Photo Log

Photo 1 – United washing trucks at the truck wash station in the northern portion of the Site, facing northwest.



Photo 2 – United excavating in the northwestern portion of the Site, facing northeast.



LANGAN

Photo 3 – United removing miscellaneous debris from stockpile ST-59, facing south.



Photo 4 – ADG installing a dewatering well in the southern portion of the Site, facing southeast.



SITE MAP



Concrete Stockpile

Post-excavation Sample

Truck Ramp



LEGEND 12074 Flatlands Avenue Site Boundary (BCP Work Zone Air Monitoring Station Site No. C224353) Lot 100 Site Boundary (NYCOER Site No. Downwind Perimeter Air Monitoring 25TMP1084K) Station Disposal Grids Upwind Perimeter Air Monitoring Station **RAWP Hotspot Areas** Work Area **Excavation Completed Today Excavation Previously Completed** Soil Stockpile Concrete Clean Stone Stockpile Clean Stone Asphalt Stockpile


FODS Trackout

Metallic Structure

Settling Tank for Truck Wash Station

- Basemap from the "Support of Excavation Plan" drawing prepared by Langan dated 3/3/2025.
- 2. Waste characterization grids are shown as presented in the Draft Disposal Map prepared by Clean Earth.
 3. Truck Ramp TR-4 contains imported DGA from Braen Stone of Sparta in Lafayette,
- 3. Truck Ramp TR-4 contains imported DGA from Braen Stone of Sparta in Lafayette, NJ.
 4. Stockpile ST-54 contains non-hazardous drill cuttings from disposal grid WC61H in the southwestern portion of the Site for off-Site disposal to Clean Earth New Castle.
 5. Stockpile ST-59 contains non-hazardous material excavated from disposal grids WC61D and WC61E in the southern portion of the Site for off-Site disposal to Clean Earth Carteret.
 6. Stockpile ST-61 contains non-hazardous material excavated from disposal grids WC56 and WC59 for off-Site disposal to Clean Earth New Castle.

DEWATERING SITE MAP



12074 Flatlands Avenue Site Boundary (BCP Site No. C224353)

Lot 100 Site Boundary (NYCOER Site No. 25TMP1084K)



Deep Well Installed and Active

Deep Well Installed but not Active

Deep Well



Monitoring Well for Dewatering Monitoring and Sampling



Deep Well to be Installed

1. Basemap from the "Dewatering Plan" drawing prepared by Cichetti Engineering PLLC dated 5/5/2025.




Site Contribution Report - CCC Phase 1B - 1 Report


_								
100688803 - CCC - Phase 1B Report Period								
To:	6/17/2025 19:00							
PM10 Action Level:	150 μg/m³							
VOC Action Level:	5 ppm							

Daily Environmental Summary	Temp (°F)	Relative Humidity (%)	Barometer (inHg)	Wind Speed (mph)	Prevailing Wind Direction
06/17/2025	61.5 - 66.2	78.0 - 90.5	30.0 - 30.5	0.2 - 1.6	WSW


Daily Monitoring Summary	PM10 (µg/m³)	Time	VOC (ppm)	Time
Min Contribution (15 min avg.) - 6/17/2025	-30.6	07:45	-0.0273	09:45
Max Contribution (15 min avg.) - 6/17/2025	40.0	17:15	0.0467	10:00
Daily Avg. Contribution (15 min avg.) - 6/17/2025	-1.0	-	-0.0000	-




PM10 Average Contribution (µg/m³)



VOC Average Contribution (ppm)



Wind rose (mph)



Page 2 of 4

Date/Time	Average Upwind PM10 (µg/m³)	Average Downwind PM10 (µg/m³)	Average Contribution PM10 (µg/m³)	Average Upwind VOC (ppm)	Average Downwind VOC (ppm)	Average Contribution VOC (ppm)	Wind Speed 15 min Avg	Wind Direction 15 min Avg
6/17/2025 06:45:00	68.2	71.0	2.8	0.0000	0.0000	0.0000	0.2	W
6/17/2025 07:00:00	30.2	35.4	5.2	0.0000	0.0007	0.0007	0.2	NNW
6/17/2025 07:15:00	18.7	20.0	1.3	0.0000	0.0007	0.0007	0.3	NNW
6/17/2025 07:30:00	23.7	22.6	-1.1	0.0360	0.0347	-0.0013	0.3	WNW
6/17/2025 07:45:00	59.8	29.3	-30.6	0.0280	0.0120	-0.0160	0.4	NW
6/17/2025 08:00:00	34.3	42.0	7.8	0.0073	0.0047	-0.0027	0.4	WNW
6/17/2025 08:15:00	47.6	19.7	-27.9	0.0080	0.0033	-0.0047	0.5	NW
6/17/2025 08:30:00	56.6	30.4	-26.2	0.0160	0.0227	0.0067	0.5	NW
6/17/2025 08:45:00	46.4	22.7	-23.7	0.0067	0.0100	0.0033	1.0	N
6/17/2025 09:00:00	40.0	19.2	-20.8	0.0067	0.0120	0.0053	0.8	NNE
6/17/2025 09:15:00	16.5	16.8	0.3	0.0133	0.0100	-0.0033	0.4	WNW
6/17/2025 09:30:00	19.1	18.5	-0.6	0.0293	0.0107	-0.0187	0.5	NW
6/17/2025 09:45:00	12.6	12.5	-0.1	0.0407	0.0133	-0.0273	0.4	WSW
6/17/2025 10:00:00	9.8	11.8	2.0	0.0007	0.0473	0.0467	0.6	NW
6/17/2025 10:15:00	8.3	12.3	3.9	0.0000	0.0000	0.0000	0.5	WNW
6/17/2025 10:30:00	12.4	9.6	-2.8	0.0000	0.0027	0.0027	0.4	WNW
6/17/2025 10:45:00	13.0	11.8	-1.2	0.0027	0.0087	0.0060	0.6	WSW
6/17/2025 11:00:00	16.9	12.5	-4.4	0.0020	0.0007	-0.0013	0.5	WSW
6/17/2025 11:15:00	11.1	15.4	4.3	0.0013	0.0020	0.0007	0.4	W
6/17/2025 11:30:00	12.4	6.9	-5.5	0.0000	0.0000	0.0000	0.8	WSW
6/17/2025 11:45:00	16.5	8.3	-8.2	0.0000	0.0000	0.0000	0.8	SW
6/17/2025 12:00:00	14.8	8.6	-6.2	0.0000	0.0000	0.0000	0.9	SW
6/17/2025 12:15:00	12.7	38.8	26.2	0.0000	0.0000	0.0000	0.8	WSW
6/17/2025 12:30:00	9.4	7.1	-2.3	0.0000	0.0000	0.0000	0.5	WSW
6/17/2025 12:45:00	8.9	14.7	5.8	0.0080	0.0047	-0.0033	0.6	W
6/17/2025 13:00:00	11.2	12.1	0.9	0.0020	0.0000	-0.0020	0.4	W
6/17/2025 13:15:00	9.9	9.8	-0.1	0.0000	0.0000	0.0000	0.6	WSW
6/17/2025 13:30:00	18.0	12.1	-5.9	0.0000	0.0000	0.0000	0.8	SW
6/17/2025 13:45:00	8.2	8.0	-0.2	0.0000	0.0047	0.0047	0.8	SW
6/17/2025 14:00:00	9.9	10.2	0.2	0.0033	0.0000	-0.0033	0.8	SW
6/17/2025 14:15:00	11.7	6.9	-4.8	0.0000	0.0000	0.0000	0.8	SW
6/17/2025 14:30:00	16.0	13.3	-2.7	0.0000	0.0013	0.0013	0.6	SW

Date/Time	Average Upwind PM10 (µg/m³)	Average Downwind PM10 (µg/m³)	Average Contribution PM10 (µg/m³)	Average Upwind VOC (ppm)	Average Downwind VOC (ppm)	Average Contribution VOC (ppm)	Wind Speed 15 min Avg	Wind Direction 15 min Avg
6/17/2025 14:45:00	7.8	11.0	3.1	0.0000	0.0000	0.0000	0.7	SW
6/17/2025 15:00:00	9.6	14.6	5.1	0.0000	0.0000	0.0000	0.7	SW
6/17/2025 15:15:00	7.5	10.2	2.7	0.0000	0.0000	0.0000	0.8	SW
6/17/2025 15:30:00	8.2	8.7	0.5	0.0000	0.0000	0.0000	0.8	SSW
6/17/2025 15:45:00	8.3	9.2	1.0	0.0000	0.0000	0.0000	0.7	SW
6/17/2025 16:00:00	6.2	9.8	3.6	0.0000	0.0000	0.0000	0.7	SW
6/17/2025 16:15:00	8.3	12.3	3.9	0.0000	0.0047	0.0047	0.7	SW
6/17/2025 16:30:00	7.9	11.0	3.1	0.0000	0.0000	0.0000	0.7	WSW
6/17/2025 16:45:00	6.9	9.8	2.9	0.0000	0.0000	0.0000	0.7	SW
6/17/2025 17:00:00	8.4	15.0	6.5	0.0000	0.0000	0.0000	0.7	SW
6/17/2025 17:15:00	9.2	49.1	40.0	0.0000	0.0000	0.0000	0.6	WSW
6/17/2025 17:30:00							0.7	SW