

**WEEKLY INSPECTION REPORT****Prepared By:** Thomas Jensen

IEEG Project No:	13928	NYSDEC BCP Site No:	C224367	Date: 06/13/25
Project:	251 Douglass Street, Brooklyn, NY			

Consultant:

Impact Environmental Engineering and Geology, PLLC (IEEG)

Personnel On Site:IEEG (Environmental) – Thomas Jensen
Broadway Construction Group – Shannon Dowling/Tom Caporale
Concrete Courses**Scope of Work:** Weekly Site Inspection**Site Activities:**

- Concrete Courses completed the pour for the 11th story of the super structure (Phases 1, 2, and 3);
- Concrete Courses continued rebar work for the 12th story in Phases 2 and 3 of the superstructure; and
- Continued utility, plumbing and framing work inside of the northern and eastern portions of the Site (Phase 1, 2, and 3).

Community Air Monitoring Program (CAMP):

- CAMP was not deployed as the purpose of the Site visit was for a weekly inspection.

Notable Site Conditions:

- None.

Planned for the Next Day/Week:

- Concrete Courses will continue form and rebar for utilities; and
- Continued utility, plumbing and framing work inside of the building.

PHOTO LOG

251 DOUGLASS STREET, BROOKLYN, NY



Photo 1-
Representative
view of the Site
from on
Douglass Street.



Photo 2-
Representative
photo of the
completed 11th
story of the
superstructure.



Photo 3-

Representative view of rebar work for the 12th story of the superstructure.



Photo 4-

Representative photo of utility work inside of the building.



SITE PLAN

251 DOUGLASS STREET, BROOKLYN, NY





IMPACT ENVIRONMENTAL

welcome to solid ground...

170 Keyland Court | Bohemia | NY | 11716 | 631.269.8800

www.impactenvironmental.com

