

**WEEKLY INSPECTION REPORT****Prepared By:** Tyler Bistline

IEEG Project No:	13928	NYSDEC BCP Site No:	C224367	Date: 07/30/25
Project:	251 Douglass Street, Brooklyn, NY			

Consultant:

Impact Environmental Engineering and Geology, PLLC (IEEG)

Personnel On Site:IEEG (Environmental) – Tyler Bistline
Broadway Construction Group – Shannon Dowling/Tom Caporale
Concrete Courses
Skyline**Scope of Work:** Weekly Site Inspection**Site Activities:**

- Concrete Courses continues construction of roof access and stairs within staircases;
- Skyline continued adding scaffolding to the top floors; and
- Continued utility, window, plumbing, sheetrock, and framing work inside of the northern and eastern portions of the Site (Phase I, 2, and 3);

Community Air Monitoring Program (CAMP):

- CAMP was not deployed as the purpose of the Site visit was for a weekly inspection.

Notable Site Conditions:

- None.

Planned for the Next Day/Week:

- Concrete Courses will continue roof work; and
- Continued utility, window, plumbing and framing work inside of the building.

PHOTO LOG

251 DOUGLASS STREET, BROOKLYN, NY



Photo 1-
Representative
view of the Site
from Douglass
Street.



Photo 2-
Representative
photo of the
roof prepping
for masonry
work.



Photo 3-
Representative
view of
scaffolding
installation.



Photo 4-
Representative
photo of
electrical
installation on
the 10th floor.



Photo 5-
Representative
photo of the
courtyard with
windows
installed.



SITE PLAN

251 DOUGLASS STREET, BROOKLYN, NY





IMPACT ENVIRONMENTAL

welcome to solid ground...

170 Keyland Court | Bohemia | NY | 11716 | 631.269.8800

www.impactenvironmental.com

