

Project	Former A&A Brake Service Site	Report No.	12
BCP Site	NYSDEC BCP SITE C224372	Date	6/14/2023
Location	558 Sackett Street	File No.	0206384
Client	Sackett Heights LLC	Temperature	H:77 L: 63
Contractor	STAR Demolition	Wind Direction	NW to SE 9 mph
Weather	Sunny	Personnel on Site	Eddy Nunez
Humidity	63%	Time on Site	7:30-14:30

Haley & Aldrich of New York (Haley & Aldrich) was present to document implementation of the NYSDEC-Approved Remedial Investigation Work Plan (RIWP) dated March 2023. Site observations are summarized below.

Daily Observations:

- Contractor loaded three (3) loads of C&D debris for transport and disposal to Cooper Recycling Center in Brooklyn, NY.

CAMP Activities:

- Air monitoring was performed at one upwind and one downwind location during demolition activities. No 15-minute average concentration of volatiles organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.

Activities Planned for Coming Week:

- Continued demolition of the site.


Site Photographs:

Photo 1: View of site exterior and CAMP setup, facing east.





Photo 2: View of demolition, facing south.

Site Plan:



LEGEND:

-  Area of work
-  CAMP Station

558 Sackett Street, Brooklyn, NY
BCP Site C224372
Air Monitoring Log

Date: 6/14/2023
 Personnel: Eddy Nunez
 Weather: 62-78 deg F, Sunny
 Humidity: 80%
 Wind Direction: NW to SE 9 mph

Particulate Background (mcg/m3): 0.022
 PID Background (ppm): 0

Site Map:



N



Time	Particulate		VOCs		Notes	
	Upwind (mcg/m3)	Downwind (mcg/m3)	Upwind (ppm)	Downwind (ppm)	Odors (y/n)	Activities/Additional Monitoring
630						
645						
700						
715						
730						Site preparation/equipment organization - demolition work not implemented
745						
800						
815						
830						
845						
900	0.053	0.022	0	0	n	Demolition Work beings at site
915	0.058	0.045	0	0	n	
930	0.06	0.051	0	0	n	
945	0.061	0.053	0	0	n	
1000	0.065	0.057	0	0	n	
1015	0.064	0.043	0	0	n	
1030	0.039	0.035	0	0	n	
1045	0.029	0.03	0	0	n	

558 Sackett Street, Brooklyn, NY
BCP Site C224372
Air Monitoring Log

Time	Particulate		VOCs		Notes	
	Upwind (mcg/m3)	Downwind (mcg/m3)	Upwind (ppm)	Downwind (ppm)	Odors (y/n)	Activities/Additional Monitoring
1100	0.047	0.033	0	0	n	
1115	0.042	0.04	0	0	n	
1130	0.03	0.039	0	0	n	
1145	0.028	0.037	0	0	n	
1200	0.026	0.039	0	0	n	
1215	0.027	0.033	0	0	n	
1230	0.028	0.03	0	0	n	
1245	0.03	0.027	0	0	n	
1300	0.03	0.023	0	0	n	
1315	0.028	0.024	0	0	n	
1330	0.027	0.025	0	0	n	
1345	0.027	0.04	0	0	n	
1400	0.028	0.023	0	0	n	
1430	0.026	0.022	0	0	n	
1445						
1500						
1515						
1530						
1545						
1600						
1615						
1630						
1645						
1700						
1715						
1730						
1745						
1800						
1815						
1830						
1845						